E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

E&A - P2018.228.001 Bill SID as of 2/17/22 P2018 228 000

		Bill SID as of 2/17	7/22 P2018.228.000		
Inspector: Jason Brackett					Stage
		Seventy	Two Place		
			1		
Dreiest Name:		·			
Project Name:					
For Week Ending:					
Project Location:		12101 S 72nd St, Pa	pillion, Sarpy County, NE		68046
Grading:	75%				
Sanitary Sewer:	75%				
Storm Sewer:	30%				
Paving:	0%				
Seeding:	0%				
Utilities:	0%				
Overall Development:	25%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week
Sunday:	0.15"				
Monday:	0.00"				
Tuesday:	0.00"				
Wednesday:	0.70"	5/18/2022	Mostly Sunny 84/63	2:50 PM	•
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				

Complaints:

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Rough grading began (6/15/21). Excavation for sanitary installation (9/28/21). Grading ceased due to winter conditions (1/5/22). Excavation for utility connections along 72nd (2/8/22).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading began (6/15/21). Excavation for sanitary installation (9/28/21). Grading ceased due to winter conditions (1/5/22). Excavation for utility connections along 72nd (2/8/22).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (6/15/21).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

No, see Findings section.

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion

No

Create Corrective Action?

No, see Findings section.

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

Create Corrective Action?

No, see BMPs section.

Are construction entrances and adjacent streets being maintained adequately?

Yes

Create Corrective Action

N/A

Is dust associated with the	construction activity adequately controlled on the site?	
Yes		
Create Corrective Action?		
N/A		

omments: Comments:

The site was **inactive** during the most recent inspection.

Findings / Corrective Actions (Date):

- Findings / Corrective Actions (Date):

 1) Some maintenance is required in the BMP section of this report.
- 2) Sediment that has washed out beyond the property boundary at the Ponderosa Drive (East and West) culvert needs to be cleaned up and the upgradient area needs to be stabilized. DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21, 2/11/22, 3/24/22, 4/29/22, 5/5/22, **5/19/22.**
- 3) Off-site accumulation of sediment along the northeast side of the site should be cleaned up and the area restabilized (unless the area will be farmed). Gene Graves was informed to complete by 2/15/22. Not done as of the last inspection. Gene Graves was reminded on 3/24/22, 4/29/22, 5/5/22, 5/19/22.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance			
CE 1	Construction Entrance	Schram Road	7/8/2021	Active	No			
Current Condition:	Good Condition - 75% Eff	fective - An old farm entra	ance is in use on site as of the	7/8/21 inspection. D	EJ added rock to the			
	entrance prior to the 1/13	entrance prior to the 1/13/22 inspection. Sudbeck reinstalled the entrance prior to the 4/1/22 inspection.						
D 1	Diversion	E of SB C	11/12/2021	Active	Yes			
Current Condition:	Fair Condition - DEJ insta	alled the diversion prior to	the 11/12/21 inspection.					
	The diversion should be o	place and out/radafined						
	The diversion should be d	nearied out/redefined.						
			2/8/21. Not done as of the las	st inspection. DEJ/G	ene Graves were			
	reminded on 2/11/22, 3/2-	4/22, 5/5/22, 5/19/22.						
D 2	Diversion	S of SB D	5/31/2021	Pending	Yes			
Current Condition:	Pending -							
	1.) The diversion should be							
	2.) Additional diversions s	should be built in the area	with SB D to divert the water	along the contours to	the basin (while avo			
	the stockpiles on site).							
			by 11/2/21. Not done as of the	last inspection. DE	J/Gene Graves were			
	reminded on 12/2/21, 2/1							
			by 11/2/21. Not done as of the	last inspection. DE	J/Gene Graves were			
	reminded on 12/2/21, 2/1	1/22, 3/24/22, 5/5/22.						
D 3	Diversion	N of SB D	5/31/2021	Pending	Yes			
Current Condition:	Pending -							
	3							
			1/2/21. Not done as of the las	st inspection. DEJ/G	ene Graves were			
	reminded on 12/2/21, 2/1		0/7/0004	D :				
D 4	Diversion	E and SB B	9/7/2021	Pending	Yes			
Current Condition:	Pending -							
	The diversion should be installed.							
	DEJ was informed to complete by 9/7/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 10/15/21,							
	10/21/21, 10/29/21, 12/2/			23/Gene Graves wer	e reminded on 10/15/2			
D. F.			ZZ	Demond				
D 5	Diversion The diversion	Northwest Perimeter		Removed				
Current Condition:		is not needed due to exis	· C · · · · · · · · · · · · · · · · · ·					
D 6	Diversion	Mastana Daninastan	sting contours as of the 5/3/22		V			
Current Condition:		Western Perimeter	1/18/2022	Active	Yes			
Current Condition.	Fair Condition - A portion	of the diversion appears	1/18/2022 to have been installed in the r	Active northwest corner of the	ne site prior to the 1/1			
Current Condition.	Fair Condition - A portion	of the diversion appears	1/18/2022	Active corthwest corner of the	ne site prior to the 1/1			
Current Condition.	Fair Condition - A portion inspection. As of the 5/3/	of the diversion appears /22 inspection, D 6 will rep	1/18/2022 to have been installed in the r present the swale and dirt berr	Active northwest corner of the mat the western edg	ne site prior to the 1/18 e of future Schram Ro			
Current Condition.	Fair Condition - A portion inspection. As of the 5/3/	of the diversion appears /22 inspection, D 6 will rep	1/18/2022 to have been installed in the r	Active northwest corner of the mat the western edg	ne site prior to the 1/18 e of future Schram Ro			
Current Condition.	Fair Condition - A portion inspection. As of the 5/3/ The gap in the berm at the	of the diversion appears /22 inspection, D 6 will repart to Schram Road stub should be supported by the schram	1/18/2022 to have been installed in the roresent the swale and dirt berruld be redirected along the sw	Active northwest corner of the mat the western edg ale and not into the v	ne site prior to the 1/18 e of future Schram Ro			
current condition.	Fair Condition - A portion inspection. As of the 5/3/ The gap in the berm at the	of the diversion appears /22 inspection, D 6 will repart to Schram Road stub should be supported by the schram	1/18/2022 to have been installed in the r present the swale and dirt berr	Active northwest corner of the mat the western edg ale and not into the v	ne site prior to the 1/18 e of future Schram Ro			
	Fair Condition - A portion inspection. As of the 5/3/ The gap in the berm at th DEJ/Gene Graves were in	of the diversion appears /22 inspection, D 6 will repose Schram Road stub shown formed to complete by 5	1/18/2022 to have been installed in the roresent the swale and dirt berrulated be redirected along the swale. 1/10/22. Not done as of the last	Active northwest corner of the at the western edge ale and not into the vest inspection.	ne site prior to the 1/18 e of future Schram Ro vattles.			
ET 1	Fair Condition - A portion inspection. As of the 5/3/ The gap in the berm at th DEJ/Gene Graves were in Erosion Control Terrace	of the diversion appears /22 inspection, D 6 will repose Schram Road stub shown formed to complete by 5	1/18/2022 to have been installed in the roresent the swale and dirt berruld be redirected along the sw	Active northwest corner of the mat the western edg ale and not into the v	ne site prior to the 1/18 e of future Schram Ro			
	Fair Condition - A portion inspection. As of the 5/3/ The gap in the berm at th DEJ/Gene Graves were in	of the diversion appears /22 inspection, D 6 will repose Schram Road stub shown formed to complete by 5	1/18/2022 to have been installed in the roresent the swale and dirt berrulated be redirected along the swale. 1/10/22. Not done as of the last	Active northwest corner of the at the western edge ale and not into the vest inspection.	ne site prior to the 1/10 e of future Schram Ro vattles.			
ET 1	Fair Condition - A portion inspection. As of the 5/3/ The gap in the berm at the DEJ/Gene Graves were in Erosion Control Terrace Pending -	of the diversion appears /22 inspection, D 6 will rep le Schram Road stub shoot nformed to complete by 5 N of SB D	1/18/2022 to have been installed in the represent the swale and dirt bernuld be redirected along the swa/10/22. Not done as of the last	Active northwest corner of the mat the western edge ale and not into the vest inspection. Pending	ne site prior to the 1/18 e of future Schram Ro vattles. Yes			
ET 1	Fair Condition - A portion inspection. As of the 5/3/ The gap in the berm at the DEJ/Gene Graves were in Erosion Control Terrace Pending - The terrace should be ins	of the diversion appears /22 inspection, D 6 will replace Schram Road stub shounformed to complete by 5 N of SB D	1/18/2022 to have been installed in the roresent the swale and dirt berrulated be redirected along the swale. 1/10/22. Not done as of the last	Active northwest corner of the mat the western edge ale and not into the vest inspection. Pending	ne site prior to the 1/18 e of future Schram Ro vattles. Yes			
ET 1	Fair Condition - A portion inspection. As of the 5/3/ The gap in the berm at the DEJ/Gene Graves were in Erosion Control Terrace Pending -	of the diversion appears /22 inspection, D 6 will replace Schram Road stub shounformed to complete by 5 N of SB D	1/18/2022 to have been installed in the represent the swale and dirt bernuld be redirected along the swa/10/22. Not done as of the last	Active northwest corner of the mat the western edge ale and not into the vest inspection. Pending	ne site prior to the 1/18 e of future Schram Ro vattles. Yes			
ET 1	Fair Condition - A portion inspection. As of the 5/3/ The gap in the berm at the DEJ/Gene Graves were in Erosion Control Terrace Pending - The terrace should be instead to the toe of the adjoining	of the diversion appears /22 inspection, D 6 will replace Schram Road stub should be schram Road stub should be stalled when the area reach slope.	1/18/2022 to have been installed in the represent the swale and dirt bernuld be redirected along the swa/10/22. Not done as of the last 5/31/2021 these final grade. The terrace states are the swale and the swale are the swale	Active northwest corner of the mat the western edge ale and not into the vest inspection. Pending	e site prior to the 1/18 e of future Schram Ro wattles. Yes across future Schram			
ET 1	Fair Condition - A portion inspection. As of the 5/3/ The gap in the berm at the DEJ/Gene Graves were in Erosion Control Terrace Pending - The terrace should be instead to the toe of the adjoining DEJ/Gene Graves were in	of the diversion appears //22 inspection, D 6 will replace Schram Road stub shown formed to complete by 5 N of SB D stalled when the area react y slope. Informed to complete by 1	1/18/2022 to have been installed in the represent the swale and dirt bernuld be redirected along the swa/10/22. Not done as of the last	Active northwest corner of the mat the western edge ale and not into the vest inspection. Pending	e site prior to the 1/18 e of future Schram Ro wattles. Yes across future Schram			
ET 1	Fair Condition - A portion inspection. As of the 5/3/ The gap in the berm at the DEJ/Gene Graves were in Erosion Control Terrace Pending - The terrace should be instead to the toe of the adjoining	of the diversion appears //22 inspection, D 6 will replace Schram Road stub shown formed to complete by 5 N of SB D stalled when the area react y slope. Informed to complete by 1	1/18/2022 to have been installed in the represent the swale and dirt bernuld be redirected along the swa/10/22. Not done as of the last 5/31/2021 these final grade. The terrace states are the swale and the swale are the swale	Active northwest corner of the mat the western edge ale and not into the vest inspection. Pending	e site prior to the 1/18 e of future Schram Ro wattles. Yes across future Schram F			

		-					
ET 2	Erosion Control Terrace	N of SB E	5/31/2021	Pending	Yes		
Current Condition:	Pending -						
	The terrace should be installed when the area reaches final grade. The terrace should be extended across future Schram R						
	to the toe of the adjoining slope.						
		·					
	DEJ/Gene Graves were in	oformed to complete by	11/2/21. Not done as of the la	ast inspection. DEJ/G	ene Graves were		
	reminded on 12/2/21, 2/11		,_,	20100000	iono Gravos more		
ET 3	Erosion Control Terrace	N of SB B	5/31/2021	Pending	Yes		
Current Condition:		11 01 3B B	3/31/2021	rending	1 63		
Current Condition.	Pending -						
	The femore of the 14 has too	call and					
	The terrace should be inst	talled.					
	DEJ/Gene Graves were in	nformed to complete by	11/2/21. Not done as of the la	ast inspection. DEJ/G	ene Graves were		
	reminded on 12/2/21, 2/11	1/22, 3/24/22, 5/5/22.					
ET 4	Erosion Control Terrace	East Central	5/31/2021	Pending	Yes		
Current Condition:	Pending -	2121 22 121	2.5				
	The terrace should be inst	talled					
	The terrace should be ins	talica.					
	DE I/Cono Crayos ware in	oformed to complete by	11/2/21 Not done as of the la	act increation DE I/C	iono Crovos woro		
			11/2/21. Not done as of the la	ast mapermon. DEJ/G	elle Glaves Wele		
	reminded on 12/2/21, 2/11		F/0.1/0.00 :	F "			
EM 1	Erosion Control Matting	Northwest Side	5/31/2021	Pending	Yes		
Current Condition:	Pending -						
	The slope should be seed	led/matted when at final	grade.				
	Gene Graves/DEJ were in	nformed to complete by	5/10/22. Not done as of the la	ast inspection.			
EM 2	Erosion Control Matting	North-Central	5/31/2021	Pendina	Yes		
Current Condition:	Pending -	TTOTAL COLLEGE	6/01/2021	r onang	. 55		
Current Condition.	1 Origing						
	The slope should be seed	lad/mattad when at final	grada				
	The slope should be seed	led/matted when at illian	grade.				
	Cara Craves/DE Lucas is		5/40/00 Not do a o of the la				
			5/10/22. Not done as of the la				
EM 3	Erosion Control Matting	Northeast Side	5/31/2021	Pending	Yes		
Current Condition:	Pending -						
	The slope should be stabi	lized ASAP when work	allows.				
	Gene Graves/DEJ were in	nformed on 2/11/22. No	t done as of the last inspectio	n. Gene Graves/DEJ	was reminded on 3/24/22,		
	5/5/22.						
EM 4	Erosion Control Matting	Southwest Corner	5/31/2021	Pending	No		
Current Condition:			alled within the seeding windo				
			letion of the culvert work in th				
511.5			7				
EM 5	Erosion Control Matting	West Side	5/31/2021	Pending	No No		
Current Condition:			alled within the seeding windo				
	-	•	gin soon as of the 5/3/22 insp				
	in the area will be tempora	arily halted until work is	complete. Seeding of the slop	oe is still recommende	ed as of the 5/3/22		
	inspection.						
FT 1	Fuel Tank	SW Corner	5/18/2021	Active	Yes		
Current Condition:			rior to the 5/18/21 inspection.				
	the 9/7/21 inspection.				P.1.2. 13		
	the 9/7/21 inspection.						
	·	robuilt on the south side	of the fuel tank				
	1.) The berm needs to be						
	·						
	1.) The berm needs to be 2.) The stained soils and p	pallet need to be cleane	d up and removed.				
	1.) The berm needs to be 2.) The stained soils and p	pallet need to be cleane re informed to complete			J/Gene Graves were		
	1.) The berm needs to be 2.) The stained soils and p 1.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11	pallet need to be cleane re informed to complete 1/22, 3/24/22, 5/5/22.	d up and removed. by 11/2/21. Not done as of th	ne last inspection. DE			
	1.) The berm needs to be 2.) The stained soils and p 1.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 2.) DEJ/Gene Graves wer	ce informed to complete 1/22, 3/24/22, 5/5/22. The informed to complete to com	d up and removed.	ne last inspection. DE			
	1.) The berm needs to be 2.) The stained soils and p 1.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11	ce informed to complete 1/22, 3/24/22, 5/5/22. The informed to complete to com	d up and removed. by 11/2/21. Not done as of th	ne last inspection. DE			
FT 2	1.) The berm needs to be 2.) The stained soils and p 1.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 2.) DEJ/Gene Graves wer	ce informed to complete 1/22, 3/24/22, 5/5/22. The informed to complete to com	d up and removed. by 11/2/21. Not done as of th	ne last inspection. DE			
	1.) The berm needs to be 2.) The stained soils and p 1.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 2.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 Fuel Tank	re informed to complete 1/22, 3/24/22, 5/5/22. re informed to complete 1/22, 3/24/22, 5/5/22. Material Storage Area	d up and removed. by 11/2/21. Not done as of the by 11/2/21. Not done as of the	ne last inspection. DE			
Current Condition:	1.) The berm needs to be 2.) The stained soils and p 1.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 2.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 Fuel Tank Removed - TAB removed	re informed to complete 1/22, 3/24/22, 5/5/22. The informed to complete 1/22, 3/24/22, 5/5/22. Material Storage Area the fuel tank prior to the	by 11/2/21. Not done as of the by 11/2/21. Not done as of the by 11/2/21. Not done as of the by 11/2/21 inspection.	ne last inspection. DE ne last inspection. DE Removed	J/Gene Graves were		
Current Condition: FT 3	1.) The berm needs to be 2.) The stained soils and p 1.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 2.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 Fuel Tank Removed - TAB removed Fuel Tank	ce informed to complete 1/22, 3/24/22, 5/5/22. The informed to complete 1/22, 3/24/22, 5/5/22. The informed to complete 1/22, 3/24/22, 5/5/22. The fuel tank prior to the Material Storage Area Material Storage Area	by 11/2/21. Not done as of the by 11/2/21.	ne last inspection. DE ne last inspection. DE Removed			
Current Condition: FT 3 Current Condition:	1.) The berm needs to be 2.) The stained soils and p 1.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 2.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 Fuel Tank Removed - TAB removed Fuel Tank Good Condition - RPL ins	re informed to be cleane to informed to complete 1/22, 3/24/22, 5/5/22. The informed to complete 1/22, 3/24/22, 5/5/22. Material Storage Area the fuel tank prior to the Material Storage Area talled a double walled fu	by 11/2/21. Not done as of the by 11/2/21. Not done as of the by 11/2/21. Not done as of the by 11/2/21 inspection.	ne last inspection. DE ne last inspection. DE Removed Active 21/21 inspection.	J/Gene Graves were		
Current Condition: FT 3 Current Condition: FT 4	1.) The berm needs to be 2.) The stained soils and p 1.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 2.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 Fuel Tank Removed - TAB removed Fuel Tank Good Condition - RPL ins	callet need to be cleane re informed to complete 1/22, 3/24/22, 5/5/22. re informed to complete 1/22, 3/24/22, 5/5/22. Material Storage Area the fuel tank prior to the Material Storage Area talled a double walled fu	by 11/2/21. Not done as of the e4/7/22 inspection. 12/21/2021 let tank on site prior to the 12/21/2021	ne last inspection. DE ne last inspection. DE Removed	J/Gene Graves were		
Current Condition: FT 3 Current Condition: FT 4 Current Condition:	1.) The berm needs to be 2.) The stained soils and p 1.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 2.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 Fuel Tank Removed - TAB removed Fuel Tank Good Condition - RPL ins Fuel Tank Removed - The fuel tank	ce informed to complete 1/22, 3/24/22, 5/5/22. The informed	by 11/2/21. Not done as of the by 11/2/21. Not done as of the by 11/2/21. Not done as of the e 4/7/22 inspection. 12/21/2021 lel tank on site prior to the 12/10 the 5/18/22 inspection.	ne last inspection. DE ne last inspection. DE Removed Active 21/21 inspection. Removed	J/Gene Graves were		
Current Condition: FT 3 Current Condition: FT 4 Current Condition: MS 1	1.) The berm needs to be 2.) The stained soils and p 1.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 2.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 Fuel Tank Removed - TAB removed Fuel Tank Good Condition - RPL ins Fuel Tank Removed - The fuel tank Material Storage	ce informed to complete 1/22, 3/24/22, 5/5/22. The informed to complete 1/22,	by 11/2/21. Not done as of the 2/1/2/21 inspection. 12/21/2021 12/1/2021 14/1/2021 15/14/2021	ne last inspection. DE Removed Active 21/21 inspection. Removed Active	J/Gene Graves were No No		
Current Condition: FT 3 Current Condition: FT 4 Current Condition:	1.) The berm needs to be 2.) The stained soils and p 1.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 2.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 Fuel Tank Removed - TAB removed Fuel Tank Good Condition - RPL ins Fuel Tank Removed - The fuel tank Material Storage Good Condition - Material	ce informed to complete 1/22, 3/24/22, 5/5/22. The informed to complete 1/22, 5/5/22. The informed to	by 11/2/21. Not done as of the 2/1/2021 inspection. 12/21/2021 itel tank on site prior to the 12/1/2021 itel tank on site prior to the 12/1/2021 itel tank on site site of the 3/14/2021 ited along the west side of the	ne last inspection. DE Removed Active 21/21 inspection. Removed Active	J/Gene Graves were No No		
Current Condition: FT 3 Current Condition: FT 4 Current Condition: MS 1	1.) The berm needs to be 2.) The stained soils and p 1.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 2.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 Fuel Tank Removed - TAB removed Fuel Tank Good Condition - RPL ins Fuel Tank Removed - The fuel tank Material Storage	ce informed to complete 1/22, 3/24/22, 5/5/22. The informed to complete 1/22, 5/5/22. The informed to	by 11/2/21. Not done as of the 2/1/2021 inspection. 12/21/2021 itel tank on site prior to the 12/1/2021 itel tank on site prior to the 12/1/2021 itel tank on site site of the 3/14/2021 ited along the west side of the	ne last inspection. DE Removed Active 21/21 inspection. Removed Active	J/Gene Graves were No No		
Current Condition: FT 3 Current Condition: FT 4 Current Condition: MS 1	1.) The berm needs to be 2.) The stained soils and p 1.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 2.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 Fuel Tank Removed - TAB removed Fuel Tank Good Condition - RPL ins Fuel Tank Removed - The fuel tank Material Storage Good Condition - Material	ce informed to complete 1/22, 3/24/22, 5/5/22. The informed to complete 1/22, 5/5/22. The informed to	by 11/2/21. Not done as of the 2/1/2021 inspection. 12/21/2021 itel tank on site prior to the 12/1/2021 itel tank on site prior to the 12/1/2021 itel tank on site site of the 3/14/2021 ited along the west side of the	Removed Active 21/21 inspection. Removed Active 2stite as of the 9/14/2	J/Gene Graves were No No		
Current Condition: FT 3 Current Condition: FT 4 Current Condition: MS 1 Current Condition: PB X	1.) The berm needs to be 2.) The stained soils and p 1.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 2.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 Fuel Tank Removed - TAB removed Fuel Tank Good Condition - RPL ins Fuel Tank Removed - The fuel tank Material Storage Good Condition - Material up the stained soils prior t	callet need to be cleane the informed to complete 1/22, 3/24/22, 5/5/22. The informed to complete 1/22, 3/24/22, 5/5/22. Material Storage Area the fuel tank prior to the Material Storage Area talled a double walled fuel talled storage Area to was removed prior to the 9/28/21 inspection On Site	by 11/2/21. Not done as of the 4/7/22 inspection. 12/21/2021 12/21/2021 12/21/2021 14/2/2021 15/21/2021 16/21/2021 16/21/2021 16/21/2021 16/21/2021 16/21/2021 16/21/2021	ne last inspection. DE Removed Active 21/21 inspection. Removed Active e site as of the 9/14/24	J/Gene Graves were No No		
Current Condition: FT 3 Current Condition: FT 4 Current Condition: MS 1 Current Condition:	1.) The berm needs to be 2.) The stained soils and p 1.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 2.) DEJ/Gene Graves wer reminded on 12/2/21, 2/11 Fuel Tank Removed - TAB removed Fuel Tank Good Condition - RPL ins Fuel Tank Removed - The fuel tank Material Storage Good Condition - Material up the stained soils prior t	callet need to be cleane the informed to complete 1/22, 3/24/22, 5/5/22. The informed to complete 1/22, 3/24/22, 5/5/22. Material Storage Area the fuel tank prior to the Material Storage Area talled a double walled fuel talled storage Area to was removed prior to the 9/28/21 inspection On Site	by 11/2/21. Not done as of the 2/1/2021 inspection. 12/21/2021 itel tank on site prior to the 12/1/2021 itel tank on site prior to the 12/1/2021 itel tank on site site of the 3/14/2021 ited along the west side of the	ne last inspection. DE Removed Active 21/21 inspection. Removed Active e site as of the 9/14/24	J/Gene Graves were No No		

			out prior to the 12/1/21 inspection. The riser was in			
	The basin should be installed (baffle, cleanout mark, correct contours/depth).					
	DEJ was informed to com		ne as of the last inspection. [DEJ/Gene Graves we	re reminded on 10/15/21,	
SB B	Sediment Basin	O24	5/18/2022	Active	Yes	
Current Condition:		ed - The basin had beer	n partially dug out prior to the	9/14/21 inspection by	DEJ, the inspector will	
	was in the process of bein riser prior to the 5/18/22 The basin should be insta DEJ was informed to com	ng installed during the 4/2 inspection. Illed (baffle, cleanout manuplete by 9/7/21. Not dor	ne as of the last inspection. [g holes appear to ha	ave been installed in the	
CD C	10/21/21, 10/29/21, 12/2/2			Active	Vac	
SB C Current Condition:	Sediment Basin	H24	5/18/2022 out prior to the 11/12/21 insp	Active	Yes	
	4/21/22 inspection. Dewa The basin should be insta	atering holes appear to alled (baffle, cleanout ma aplete by 9/7/21. Not dor	ne as of the last inspection. [riser prior to the 5/1	8/22 inspection.	
SB D	Sediment Basin	H22	5/18/2022	Active	Yes	
Current Condition:			ne process of being dug out d			
SB E Current Condition:	DEJ/Gene Graves were in reminded on 12/2/21, 2/11 Sediment Basin	nformed to complete by 1 1/22, 3/24/22, 5/5/22. D19	should be installed (baffle, cle 11/2/21. Not done as of the land to the land	ast inspection. DEJ/G	Gene Graves were Yes	
	5/3/22 inspection. The cleanout mark needs				· ·	
	The E&A inspector or DE	J will complete when con	oditions allow as of 5/5/22. N	ot done as of the last	inspection.	
SF 1	Silt fence	J will complete when con Northern/Western Perimeter	nditions allow as of 5/5/22. N	Active	Yes	
SF 1 Current Condition:	Silt fence Fair Condition - The devel intentionally built in the no Sudbeck installed wattles maintenance prior to the 4 prior to the 4/7/22 inspection. 1.) Silt fence should be insected in the silt fence should be 3.) Additional silt fence should be 3.) Additional silt fence should be 3.) The silt fence needs 1.) DEJ/Gene Graves were reminded on 2/11/22, 3/24. Gene Graves was info 5/19/22.	J will complete when cornection Northern/Western Perimeter loper installed the silt fer orthern section of the run as an extension of the silt silt section. Suddetion. TAB repaired/reinstalled over the flared en be cleaned out southwest would be installed adjacer to be repaired along the recommendation of the silt silt silt silt silt silt silt silt	first to the solutions allow as of 5/5/22. Not done as of the last 0/22.	Active ction. A diversion ber on, extending the silt for the 2/2/22 inspection. the south along the n d Street prior to the 4. utfall west of SB D. section of the run. section entrance. he last inspection. DE	Yes m appears to have been ence is still recommended. Sudbeck began silt fence orth side of the entrance /7/22 inspection.	

Current Condition:	Fair Condition - The deve	loper installed the silt fe	nce prior to the 5/25/21 inspec	tion.			
	4.) The effective of the decision		and the first operation of				
	1.) The silt fence is damaged/full and Y12 and needs to be maintained. 2.) The silt fence is damaged at U12 and needs to be repaired.						
	2.) The sill felice is damag	ged at 012 and needs to	o be repaired.				
	1.) DEJ was informed to complete by 7/17/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on						
	8/27/21, 9/2/21, 10/15/21, 10/21/21, 10/29/21, 12/2/21, 2/11/22, 3/24/22, 4/29/22, 5/5/22, 5/19/22 .						
	2.) DEJ was informed to o	complete by 7/17/21. No	ot done as of the last inspection	n. DEJ/Gene Graves	were reminded on		
	8/27/21, 9/2/21, 10/15/21,	10/21/21, 10/29/21, 12/	<u>/2/21, 2/11/22, 3/24/22, 4/29/2</u>	2, 5/5/22 , 5/19/22.			
SF 3	Silt fence	Southeast Corner	5/25/2021	Active	Yes		
Current Condition:			nce prior to the 5/25/21 inspec	tion. The silt fence v	as partially removed for		
	installation of the SB C ou	ittall pipe prior to the 4/7	7/22 Inspection.				
	Silt fence needs to be repaired in multiple locations and extended over the SB A outfall pipe.						
	Citation of the control of	anda in maiapio iddaidi	io and oxionada over the C2 /	· outium pipoi			
			10/27/21. Not done as of the I	ast inspection. DEJ/	Gene Graves were		
	reminded on 10/29/21, 12						
SF 4	Silt fence	Southwest Perimeter		Active	Yes		
Current Condition:			nce prior to the 5/18/21 inspec				
			B/21 inspection. Excavation sp				
			silt fence prior to the 1/18/22 in and Ponderosa Drive appears t				
			Sudbeck began silt fence main				
			nstallation of the silt fence prior				
	, , ,		ne swale prior to the 4/7/22 ins	the state of the s			
			Street for storm sewer work				
	imminent paving, reinst	•		prior to the 3/10/22	inspection, due to		
	miniment paving, remst	anation will not be rec	ommended.				
	1.) The silt fence needs to	be backfilled, cleaned	out, and repaired in multiple lo	cations south and ea	st of SB C as well as		
	adjacent to the culvert cor		the state of the s				
	2.) The silt fence should b	e adjusted and addition	al silt fence checks installed up	ogradient of the box of	culvert once the temporary		
	pipe is removed.						
			SB C and SB B outfall to prev	rent inundating the rip	rap with silt.		
	4.) High porosity checks	s should be cleaned or	ut/repaired.				
	4.) DE 1/0 0		h 44/0/04 Not do a a a a file	. In the contract DE	1/0		
			by 11/2/21. Not done as of the	e last inspection. DE	J/Gene Graves were		
	reminded on 12/2/21, 2/11		one as of the last inspection. G	Sama Crayes was re-	minded on E/40/22		
			10/22. Not done as of the last				
	5/19/22.	imed to complete by 5/1	10/22. Not dolle as of the last	inspection. Gene Gi	aves was reminded on		
	4) Gene Graves was inf	ormed to complete by	5/25/22				
STR	Streets	S 72nd Street	5/18/2021	Active	No		
Current Condition:	Good Condition - The stre	ets were relatively clear	n during the most recent inspe	ction.			
SWPPP Sign	Misc/Other	S 72nd and Schram	5/18/2021	Active	No		
Current Condition:		A inspector installed the	SWPPP sign in the southwes	t corner of the proper	ty during the 5/18/21		
	inspection.						
WO 1	Concrete Washout	On Site	5/31/2021	Pending	No		
Current Condition:	Pending - A concrete was				1		
WS 1	Waste Storage	On Site	5/31/2021	Pending	No		
Current Condition:			proper containment vessels.				
	3,	*	and all attachments were prep	•	•		
	accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for						
Certification Statement:	,		,	•	, ,		
	-		ed is, to the best of my knowle ubmitting false information incl	-	-		
	for knowing violations."	igimicani penaliles i01 S	ubmitting raise initornation inc	idding the possibility (אוווופס מווע ווווףווסטווווופוונ		
	To Knowing Violations.		Т				
	On Co Mont						
In an auton Claus - tour	Cfr Ce Thoward			Daviewad De	South Sol		
Inspector Signature:				Reviewed By:			