E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

E&A - P2018.228.001 Bill SID as of 2/17/22 P2018 228 000

		Bill SID as of 2/1	7/22 P2018.228.000				
Inspector: Jason Brackett					Stage		
		Seventy	y Two Place				
		PAP-20200	0624-5346-GP1		1		
Project Name:		CSW-	202004796				
For Week Ending:		6/18/2022					
Project Location:		12101 S 72nd St, Pa	apillion, Sarpy County, NE		68046		
	·						
Grading:	75%						
Sanitary Sewer:	90%						
Storm Sewer:	65%						
Paving:	8%						
Seeding:	0%						
Utilities:	0%						
Overall Development:	30%						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time			
					Week		
Sunday:	0.00"						
Monday:	0.00"	6/13/2022	Mostly Sunny 100/78	1:40 PM			
	0.00"						
Tuesday:	0.00						
Tuesday: Wednesday:	1.20"	6/15/2022	Cloudy 77/62	2:05 PM			
•		6/15/2022	Cloudy 77/62	2:05 PM			
Wednesday:	1.20"	6/15/2022	Cloudy 77/62	2:05 PM			

Complaints:

A complaint was received from Mike Kleffner with the City of Papillion regarding silt getting into the culvert under 72nd Street. Members of the SWPPP team met on site on 6/10/22. SWPPP Maintenance will be addressed ASAP and not later than 14-days to prevent further discharge.

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Rough grading began (6/15/21). Excavation for sanitary installation (9/28/21). Grading ceased due to winter conditions (1/5/22). Excavation for utility connections along 72nd (2/8/22). Grading for roadways (6/9/22).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading began (6/15/21). Excavation for sanitary installation (9/28/21). Grading ceased due to winter conditions (1/5/22). Excavation for utility connections along 72nd (2/8/22). Grading for roadways (6/9/22).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (6/15/21).

Checklist Questions:

ers adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

No

Create Corrective Action?

No, see Findings section.

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

No

Create Corrective Action?

No, see Findings section.

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

Create Corrective Action?

No, see BMPs section

Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?

No, see BMPs section.
Is dust associated with the construction activity adequately controlled on the site?
Yes
Create Corrective Action?
N/A

Comments

Comments

The site was **inactive** during the most recent inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section of this report.
- 2) Sediment that has washed out beyond the property boundary at the Ponderosa Drive (East and West) culvert needs to be cleaned up and the upgradient area needs to be stabilized. DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21, 2/11/22, 3/24/22, 4/29/22, 5/5/22, 5/19/22, 6/10/22.
- 3) Off-site accumulation of sediment along the northeast side of the site should be cleaned up and the area restabilized (unless the area will be farmed). Gene Graves was informed to complete by 2/15/22. Not done as of the last inspection. Gene Graves was reminded on 3/24/22, 4/29/22, 5/5/22, 5/19/22, 6/10/22.
 4) Inactive areas of the site need to be stabilized. This is a secondary recommendation to the EM called out in the BMP section below. Gene Graves/DEJ were informed to complete by 5/10/22. Not done as of the last inspection. Gene Graves/DEJ were reminded on 5/27/22, 6/10/22.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance			
CE 1	Construction Entrance Schram Road 7/8/2021 Active Yes							
Current Condition:	Fair Condition - 50% Effective - An old farm entrance is in use on site as of the 7/8/21 inspection. DEJ added rock to the entrance prior to the 1/13/22 inspection. Sudbeck reinstalled the entrance prior to the 4/1/22 inspection. More rock is needed at the entrance.							
D 1	Gene Graves was informed to complete by 6/16/22. Not done as of the last inspection. Diversion E of SB C 11/12/2021 Active Yes							
Current Condition:				Active	res			
	Fair Condition - DEJ installed the diversion prior to the 11/12/21 inspection. The diversion should be cleaned out/redefined. DEJ/Gene Graves were informed to complete by 12/8/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 2/11/22, 3/24/22, 5/5/22, 5/19/22, 6/10/22.							
D 2	Diversion	S of SB D	5/26/2022	Active	Yes			
Current Condition:	Fair Condition - DEJ installed the diversion prior to the 5/26/22 inspection. Additional diversions should be built in the area with SB D to divert the water along the contours to the basin (while avoiding the stockpiles on site). DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21, 2/11/22, 3/24/22, 5/5/22, 6/10/22.							
D 3	Diversion	N of SB D	5/26/2022	Active	Yes			
Current Condition:	Fair Condition - DEJ partially installed the diversion prior to the 5/26/22 inspection. 1.) The diversion should be extended across future Schram Road to the toe of the adjoining slope. 2.) The diversion needs to be cleaned out and redefined. 1.) DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21, 2/11/22, 3/24/22, 5/5/22, 5/27/22, 6/10/22. 2.) DEJ/Gene Graves were informed to complete by 6/1/22. Not done as of the last inspection. DEJ/Gene Graves were reminded on 6/10/22.							
D 4	Diversion	E and SB B	9/7/2021	Pending	Yes			
Current Condition:	Pending - The diversion should be installed. DEJ was informed to complete by 9/7/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 10/15/21, 10/21/21, 10/29/21, 12/2/21, 2/11/22, 3/24/22, 5/5/22, 5/27/22, 6/10/22.							
D 5	Diversion	Northwest Perimeter		Removed				
Current Condition:	_		sisting contours as of the 5/3/2					
D 6	Diversion	Western Perimeter	1/18/2022	Active	No			
Current Condition:	Good Condition - A portion of the diversion appears to have been installed in the northwest corner of the site prior to the 1/18/22 inspection. As of the 5/3/22 inspection, D 6 will represent the swale and dirt berm at the western edge of future Schram Road. DEJ/Gene Graves redirected the gap in the diversion along the swale adjacent to 72nd Street prior to the 5/31/22 inspection.							
	inspection.							

Current Condition:	Pending -							
	The terrace should be ins	talled when the area rea	aches final grade. The terrac	e should be extended	across future Schram Road			
	The terrace should be installed when the area reaches final grade. The terrace should be extended across future Schram Roac to the toe of the adjoining slope. As of 6/9/22, the terrace will not be installed on the Vestara Apartments lot.							
	DEJ/Gene Graves were in	oformed to complete by	11/2/21. Not done as of the	last inspection DEJ/G	Sene Graves were			
	reminded on 12/2/21, 2/1			220/0				
ET 2	Erosion Control Terrace	N of SB E	5/31/2021	Pending	Yes			
Current Condition:	Pending -							
	The terrace should be ins	talled when the area rea	aches final grade. The terrac	e should be extended	across future Schram Roa			
			e terrace will not be installed					
	, ,							
			11/2/21. Not done as of the	last inspection. DEJ/G	Gene Graves were			
ET 3	reminded on 12/2/21, 2/1 Erosion Control Terrace	N of SB B	5/31/2021	Pending	Yes			
Current Condition:	Pending -		5.5	,				
	The terrace should be ins	talled.						
	DEJ/Gene Graves were in	nformed to complete by	11/2/21. Not done as of the	last inspection. DEJ/G	Gene Graves were			
	reminded on 12/2/21, 2/1	1/22, 3/24/22, 5/5/22, 5/2	27/22, 6/10/22.	·				
ET 4	Erosion Control Terrace	East Central	5/31/2021	Pending	Yes			
Current Condition:	Pending -							
	The terrace should be ins	talled *Due to naving a	s of the 6/9/22 inspection, the	e terrace is recommen	ded only on either side of			
	67th Avenue.	talled. Due to pavilig a	is of the 0/9/22 inspection, the	e terrace is recommen	ded only on either side of			
		DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21, 2/11/22, 3/24/22, 5/5/22, 5/27/22, 6/9/22.						
EM 1	Erosion Control Matting	Northwest Side	5/31/2021	Pending	Yes			
Current Condition:	Pending -	Northwest Side	3/31/2021	reliailig	165			
	. Straining							
	The slope should be seeded/matted when at final grade.							
	Gene Graves/DE Lwere in	Cons Crouse/DE Lyars informed to complete by E/40/22. Not done on of the last improving. Cons Crouse/DE Lyars						
	Gene Graves/DEJ were informed to complete by 5/10/22. Not done as of the last inspection. Gene Graves/DEJ were reminded on 5/27/22, 6/10/22.							
EM 2	Erosion Control Matting	North-Central	5/31/2021	Pending	Yes			
Current Condition:	Pending -							
	The slope should be seeded/matted when at final grade.							
	The slope should be seed	ied/matted when at imal	grade.					
		Gene Graves/DEJ were informed to complete by 5/10/22. Not done as of the last inspection. Gene Graves/DEJ were						
	reminded on 5/27/22, 6/10							
EM 3 Current Condition:	Erosion Control Matting Pending -	Northeast Side	5/31/2021	Pending	Yes			
Current Condition.	rending -							
	The slope should be stabilized ASAP when work allows.							
	Gene Graves/DEJ were informed on 2/11/22. Not done as of the last inspection. Gene Graves/DEJ was reminded on 3/24/22							
	Gene Graves/DEJ were ii 5/5/22, 5/27/22, 6/10/22.	nformed on 2/11/22. No	t done as of the last inspection	on. Gene Graves/DEJ	was reminded on 3/24/22			
EM 4	Erosion Control Matting	Southwest Corner	5/31/2021	Pending	No			
Current Condition:	Pending - The erosion co	ntrol matting will be insta	alled within the seeding windo	when the associate	d area reaches final grade			
	Stabilization will be recom	nmended following comp	letion of the culvert work in the	ne area as of the 5/3/2	2 inspection.			
EM 5	Erosion Control Matting	West Side	5/31/2021	Pending	No			
Current Condition:	<u> </u>	•	alled within the seeding windo		· ·			
		•	gin soon as of the 5/3/22 insp complete. Seeding of the slo		•			
	inspection.	arily ridited dritti Work to						
FT 1	·	SW Corner	5/18/2021	Active	Yes			
FT 1 Current Condition:	inspection. Fuel Tank Fair Condition - DEJ insta	SW Corner	rior to the 5/18/21 inspection	Active DEJ installed a bern	Yes n around the tank prior to			
	inspection. Fuel Tank Fair Condition - DEJ insta	SW Corner		Active DEJ installed a bern	Yes n around the tank prior to			
	inspection. Fuel Tank Fair Condition - DEJ instathe 9/7/21 inspection. DE	SW Corner Illed a fuel tank on-site p	or to the 5/18/21 inspection or to the 6/9/22 inspection, so	Active DEJ installed a bern	Yes n around the tank prior to			
	inspection. Fuel Tank Fair Condition - DEJ insta	SW Corner Illed a fuel tank on-site p Tremoved the pallet pri rebuilt on the south side	prior to the 5/18/21 inspection or to the 6/9/22 inspection, so	Active DEJ installed a bern	Yes n around the tank prior to			
	inspection. Fuel Tank Fair Condition - DEJ instathe 9/7/21 inspection. DE 1.) The berm needs to be 2.) The stained soils need	SW Corner Illed a fuel tank on-site p J removed the pallet pri rebuilt on the south side to be cleaned up and re	prior to the 5/18/21 inspection or to the 6/9/22 inspection, so of the fuel tank.	Active DEJ installed a bernoils still need to be clea	Yes n around the tank prior to aned up.			
	inspection. Fuel Tank Fair Condition - DEJ instathe 9/7/21 inspection. DE 1.) The berm needs to be 2.) The stained soils need 1.) DEJ/Gene Graves we	SW Corner Illed a fuel tank on-site p IJ removed the pallet pri rebuilt on the south side if to be cleaned up and re re informed to complete	prior to the 5/18/21 inspection or to the 6/9/22 inspection, so the of the fuel tank. emoved. by 11/2/21. Not done as of the	Active DEJ installed a bernoils still need to be clea	Yes n around the tank prior to aned up.			
	inspection. Fuel Tank Fair Condition - DEJ instathe 9/7/21 inspection. DE 1.) The berm needs to be 2.) The stained soils need 1.) DEJ/Gene Graves we reminded on 12/2/21, 2/1	SW Corner Illed a fuel tank on-site p IJ removed the pallet pri rebuilt on the south side if to be cleaned up and re re informed to complete 1/22, 3/24/22, 5/5/22, 5/5	prior to the 5/18/21 inspection or to the 6/9/22 inspection, so the fuel tank. emoved. by 11/2/21. Not done as of the 27/22, 6/10/22.	Active DEJ installed a bernoils still need to be clean	Yes n around the tank prior to aned up.			
	inspection. Fuel Tank Fair Condition - DEJ instathe 9/7/21 inspection. DE 1.) The berm needs to be 2.) The stained soils need 1.) DEJ/Gene Graves we reminded on 12/2/21, 2/1	SW Corner Illed a fuel tank on-site p IJ removed the pallet pri rebuilt on the south side if to be cleaned up and re re informed to complete 1/22, 3/24/22, 5/5/22, 5/5 re informed to complete	rior to the 5/18/21 inspection or to the 6/9/22 inspection, so so of the fuel tank. emoved. by 11/2/21. Not done as of the 27/22, 6/10/22. by 11/2/21. Not done as of the 27/22, 6/10/22.	Active DEJ installed a bernoils still need to be clean	Yes n around the tank prior to aned up.			
	inspection. Fuel Tank Fair Condition - DEJ instathe 9/7/21 inspection. DE 1.) The berm needs to be 2.) The stained soils need 1.) DEJ/Gene Graves wereminded on 12/2/21, 2/1. 2.) DEJ/Gene Graves wereminded on Graves were	SW Corner Illed a fuel tank on-site p IJ removed the pallet pri rebuilt on the south side if to be cleaned up and re re informed to complete 1/22, 3/24/22, 5/5/22, 5/5 re informed to complete	rior to the 5/18/21 inspection or to the 6/9/22 inspection, so so of the fuel tank. emoved. by 11/2/21. Not done as of the 27/22, 6/10/22. by 11/2/21. Not done as of the 27/22, 6/10/22.	Active DEJ installed a bernoils still need to be clean	Yes n around the tank prior to aned up.			
Current Condition:	inspection. Fuel Tank Fair Condition - DEJ instathe 9/7/21 inspection. DE 1.) The berm needs to be 2.) The stained soils need 1.) DEJ/Gene Graves wereminded on 12/2/21, 2/1 2.) DEJ/Gene Graves wereminded on 12/2/21, 2/1	SW Corner Illed a fuel tank on-site p IJ removed the pallet pri rebuilt on the south side If to be cleaned up and re re informed to complete 1/22, 3/24/22, 5/5/22, 5/5 re informed to complete 1/22, 3/24/22, 5/5/22, 5/5 Material Storage Area	prior to the 5/18/21 inspection or to the 6/9/22 inspection, so the fuel tank. emoved. by 11/2/21. Not done as of the 27/22, 6/10/22. by 11/2/21. Not done as of the 27/22, 6/10/22.	Active DEJ installed a bernoils still need to be cleaned to be cleaned to be last inspection. DE	Yes n around the tank prior to aned up.			

Current Condition:	Good Condition - RPL ins	talled a double walled for	uel tank on site prior to the 12	/21/21 inspection.				
FT 4	Fuel Tank	Material Storage Area		Removed				
Current Condition:	Removed - The fuel tank	was removed prior to th	e 5/18/22 inspection.					
FT 5	Fuel Tank	Material Storage Area	6/9/2022	Active	Yes			
Current Condition:	Fair Condition - An unidentified contractor installed a fuel tank on site prior to the 6/9/22 inspection. The fuel tank needs secondary containment.							
	The E&A construction obs	server was informed on	6/10/22. Not done as of the	last inspection.				
MS 1	Material Storage	On Site	9/14/2021	Active	No			
Current Condition:	Good Condition - Material	storage is primarily loc	ated along the west side of th	e site as of the 9/14/2	1 inspection. DEJ cleaned			
	up the stained soils prior to the 9/28/21 inspection. Material storage for paving is primarily located along the southeast side of the site as of the 6/9/22 inspection.							
PB X	Portable Bathroom	On Site	5/31/2022	Active	No			
Current Condition:	Good Condition - RPL rei	nstalled a portable toilet	on site prior to the 5/31/22 in	spection.				
SB A	Sediment Basin	X24	5/11/2022	Active	Yes			
Current Condition:	appears to have been ins was reshaped prior to the The basin should be insta	talled prior to the 4/13/2 5/26/22 inspection. That alled (baffle).	g out prior to the 12/1/21 insp 2 inspection. The riser was in e E&A inspector painted the of the as of the last inspection. In 5/22, 5/27/22, 6/10/22.	stalled prior to the 5/1 cleanout mark on 5/23,	1/22 inspection. The basin /22.			
SB B	Sediment Basin	O24	5/18/2022	Active	Yes			
Current Condition:			partially dug out prior to the 9					
	The basin should be insta	ulled (baffle). splete by 9/7/21. Not do	or painted the cleanout mark on the last inspection. In the last inspection in the last inspection. In the last inspection in the last inspection in the last inspection. In the last inspection in the last inspection in the last inspection in the last inspection. In the last inspection in the last inspection in the last inspection in the last inspection. In the last inspection in		re reminded on 10/15/21,			
SB C	Sediment Basin	H24	5/18/2022	Active	Yes			
Current Condition:	to have been installed pricinspection. Dewatering he painted the cleanout mark. The basin should be installed.	or to the 4/13/22 inspectoles appear to have been on 5/23/22. Alled (baffle). Applete by 9/7/21. Not do	out prior to the 11/12/21 inspetion. The riser was in the proen installed in the riser prior to the proen as of the last inspection. In the property of the property of the property of the property of the last inspection. In the property of the last inspection. In the property of the property of the last inspection. In the property of the last inspection. In the property of the last inspection. In the property of the last inspection.	cess of being installed the 5/18/22 inspectio	during the 4/21/22 n. The E&A inspector			
SB D	Sediment Basin	H22	5/18/2022	Active	Yes			
Current Condition:	Fair Condition - 46% Filled - The basin was in the process of being dug out during the 11/4/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. The old area inlet was removed prior to the 4/21/22 inspection. Dewatering holes appear to have been installed in the riser prior to the 5/18/22 inspection. Due to ground disturbance in the area, the basin should be installed (baffle, cleanout mark, correct contours/depth). DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21, 2/11/22, 3/24/22, 5/5/22, 5/27/22, 6/10/22. *Survey to check basin installation elevations as of 6/9/22.							
SB E	Sediment Basin	D19	5/3/2022	Active	No			
Current Condition:	Good Condition - 7% Fille	ed - The basin was partic	ally dug out prior to the 12/1/2 e cleanout mark on 5/23/22.					
SF 1	Silt fence	Northern/Western Perimeter	5/18/2021	Active	Yes			

Current Condition:	Fair Condition - The developer installed the silt fence prior to the 5/18/21 inspection. A diversion berm appears to have been intentionally built in the northern section of the run prior to the 1/18/22 inspection, extending the silt fence is still recommended. Sudbeck installed wattles as an extension of the silt fence to the north prior to the 2/2/22 inspection. Sudbeck began silt fence maintenance prior to the 4/1/22 inspection. Sudbeck extended the silt fence to the south along the north side of the entrance prior to the 4/7/22 inspection. TAB repaired/reinstalled the silt fence along 72nd Street prior to the 4/7/22 inspection. Gene Graves repaired the silt fence along the north side of the construction entrance prior to the 5/26/22 inspection. 1.) Silt fence should be installed over the flared end sections at the area inlet outfall west of SB D. 2.) The silt fence should be cleaned out southwest of SB D. 3.) Additional silt fence should be installed adjacent to the wattles in the north section of the run. 4.) The silt fence needs to be repaired adjacent to the construction entrance. 5.) The silt fence needs to be repaired NW of SB D. 6.) Eroded areas southwest of SB D should be repaired and stabilized and the silt fence should be maintained. 1.) DEJ/Gene Graves were informed to complete by 12/8/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 2/11/22, 3/24/22, 4/29/22, 5/5/22, 5/19/22, 6/10/22. 2.) Gene Graves was informed to complete by 5/10/22. Not done as of the last inspection. Gene Graves was reminded on 5/19/22, 6/10/22. 4.) Gene Graves was informed to complete by 6/16/22. Not done as of the last inspection. 6.) Gene Graves was informed to complete by 6/16/22. Not done as of the last inspection. 6.) Gene Graves was informed to complete by 6/16/22. Not done as of the last inspection.						
SF 2	Silt fence	Northeastern	5/25/2021	Active	Yes		
Current Condition:	Fair Condition - The deve	Perimeter eloper installed the silt fen	ce prior to the 5/25/21 in	spection.			
SF 3 Current Condition:	1.) DEJ was informed to complete by 7/17/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 8/27/21, 9/2/21, 10/15/21, 10/21/21, 10/29/21, 12/2/21, 2/11/22, 3/24/22, 4/29/22, 5/5/22, 5/19/22, 6/10/22. 2.) DEJ was informed to complete by 7/17/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 8/27/21, 9/2/21, 10/15/21, 10/21/21, 10/29/21, 12/2/21, 2/11/22, 3/24/22, 4/29/22, 5/5/22, 5/19/22, 6/10/22. Silt fence Southeast Corner 5/25/2021 Active Yes Fair Condition - The developer installed the silt fence prior to the 5/25/21 inspection. The silt fence was partially removed for installation of the SB A outfall pipe prior to the 4/7/22 inspection.						
	DEJ/Gene Graves were i	paired in multiple locations informed to complete by 1 2/2/21, 2/11/22, 3/24/22, 4	0/27/21. Not done as of	the last inspection. DEJ/	Gene Graves were		
SF 4	Silt fence	Southwest Perimeter	5/18/2021	Active	Yes		
Current Condition:	Fair Condition - The developer installed the silt fence prior to the 5/18/21 inspection. Gene Graves installed silt fence around the Ponderosa Drive connection prior to the 10/13/21 inspection. Excavation spoils from sanitary excavation in the area of Ponderosa Drive damaged a small portion of the silt fence prior to the 1/18/22 inspection, the inspector will recommend repair when work is complete. Sanitary excavation around Ponderosa Drive appears to be complete as of the 2/2/22 inspection, maintenance in the area is now included below. Sudbeck began silt fence maintenance prior to the 4/1/22 inspection. Sudbeck complete the majority of the maintenance and reinstallation of the silt fence prior to the 4/7/22 inspection. Sudbeck installed high porosity silt fence checks in the flow line of the swale prior to the 4/7/22 inspection. The silt fence was partially removed at the future Ponderosa entrance along 72nd Street for storm sewer work prior to the 5/18/22 inspection, due to imminent paving, reinstallation will not be recommended. 1.) The silt fence needs to be backfilled, cleaned out, and repaired in multiple locations south and east of SB C as well as adjacent to the culvert construction when work allows. 2.) The silt fence should be adjusted and additional silt fence checks installed upgradient of the box culvert once the temporary pipe is removed. 3.) Silt fence should be installed upgradient of the SB C and SB B outfall to prevent inundating the rip rap with silt. 4.) High porosity checks should be cleaned out/repaired. 1.) DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21, 2/11/22, 3/24/22, 4/29/22, 5/5/22, 5/19/22, 6/10/22. 2.) Gene Graves was informed to complete by 5/10/22. Not done as of the last inspection. Gene Graves was reminded on 5/19/22, 6/10/22. 3.) Gene Graves was informed to complete by 5/25/22. Not done as of the last inspection. Gene Graves was reminded on 6/10/22.						
STR	Streets	S 72nd Street	5/18/2021	Active	No		
Current Condition:	Good Condition - The str	eets were cleaned prior to	the 5/31/22 inspection.		n the curb line along 72nd		
OW/DDD C:		nspection, the inspector w					
SWPPP Sign Current Condition:	Misc/Other Good Condition - The F&	S 72nd and Schram A inspector installed the	5/18/2021 SWPPP sign in the south	Active nwest corner of the proper	No ty during the 5/18/21		
Canoni Condition.	inspection.		o i sigii ii tile souti	Jos John of the proper	., adming the 0/10/21		

WO 1	Concrete Washout	On Site	6/9/2022	Active	Yes		
Current Condition:	 A liner should be instal Concrete waste piles s The E&A construction 	lled in the pit. chould be cleaned up. cobserver was informed	on 6/10/22. Not done as of to 6/10/22. Not done as of to 6/10/22. Not done as of the first state of the firs				
WS 1	Waste Storage	On Site	5/31/2021	Pending	No		
Current Condition:	Pending - Waste will be co	ontained on site and in p	proper containment vessels.				
Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."						
Inspector Signature:	Jan Ca Start			Reviewed By:	Get Sel		