E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

E&A - P2018.228.001 Bill SID as of 2/17/22 P2018 228 000

		Bill SID as of 2/17/	22 P2018.228.000		
Inspector: Jason Brackett	on Brackett				
		Seventy '	Two Place		
			1		
Project Name:					
For Week Ending:					
Project Location:		12101 S 72nd St, Papillion, Sarpy County, NE			
Grading:	75%				
Sanitary Sewer:	100%				
Storm Sewer:	95%				
Paving:	75%				
Seeding:	50%				
Utilities:	25%				
Overall Development:	41%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week '
Sunday:	0.00"				

KAIN FALL AWOUNTS	Amount in tentis	Date inspected	vveatner Conditions	rime	
					Week 1
Sunday:	0.00"				
Monday:	0.01"				
Tuesday:	0.16"				
Wednesday:	0.00"				
Thursday:	0.00"	7/28/2022	Mostly Sunny 82/67	11:30 AM	
Friday:	0.00"				
Saturday:	0.00"				

Complaints:

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Rough grading began (6/15/21). Excavation for sanitary installation (9/28/21). Grading ceased due to winter conditions (1/5/22). Excavation for utility connections along 72nd (2/8/22). Grading for roadways (6/9/22).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading began (6/15/21). Excavation for sanitary installation (9/28/21). Grading ceased due to winter conditions (1/5/22). Excavation for utility connections along 72nd (2/8/22). Grading for roadways (6/9/22).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (6/15/21). Disking/seeding east side of site (7/8/22).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

No

Create Corrective Action?

No, see Findings section.

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

Create Corrective Action?

No, see BMPs section.

Are construction entrances and adjacent streets being maintained adequately?

Yes

Create Corrective Action?

N/A s dust a

Yes

N/A

The site was active during the most recent inspection.

Lot 5 and 6 Replat 1 have been removed from this SWPPP and are covered by PAP-20220310-6351-GP1.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section of this report.
- 2) Inactive areas of the site need to be stabilized. This is a secondary recommendation to the EM called out in the BMP section below. Gene Graves/DEJ were informed to complete by 5/10/22. Not done as of the last inspection. Gene Graves/DEJ were reminded on 5/27/22, 6/10/22. DEJ began seeding during the 7/8/22 inspection.
 3) CIR 17107/17120 were received and reviewed on 7/29/22. CIRs are consistent with E&A inspector's report.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
CE 1	Construction Entrance	Schram Road	7/8/2021	Active	No		
Current Condition:	Good Condition - 80% Eff	ective - An old farm entr	rance is in use on site as of th	e 7/8/21 inspection. I	DEJ added rock to the		
	entrance prior to the 1/13/	entrance prior to the 1/13/22 inspection. Sudbeck reinstalled the entrance prior to the 4/1/22 inspection. Sudbeck added roc					
	to the entrance prior to the	to the entrance prior to the 6/24/22 inspection.					
D 1	Diversion	E of SB C	11/12/2021	Active	No		
Current Condition:			to the 11/12/21 inspection.				
Carrotti Cortainotti		· ·	maintained the diversion prior		•		
D 2	Diversion	S of SB D	5/26/2022	Active	Yes		
Current Condition:				Active	162		
	stockpiles on site).	Fair Condition - DEJ installed the diversion prior to the 5/26/22 inspection. Additional diversions should be built in the area with SB D to divert the water along the contours to the basin (while avoiding stockpiles on site). DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were					
			10/22. Recommendations h				
	inspection due to active		10/22. Recommendations in	lave temporarily cea	ised as of the 1/20/22		
D 3	Diversion	N of SB D	5/26/2022	Active	Yes		
Current Condition:			on prior to the 5/26/22 inspect				
	DEJ/Gene Graves were informed to complete by 6/1/22. Not done as of the last inspection. DEJ/Gene Graves were reminded on 6/10/22. Recommendations have temporarily ceased as of the 7/28/22 inspection due to active grading in the area.						
				T	T		
D 4	Diversion	E and SB B	7/8/2022	Active	No		
Current Condition:			prior to the 7/8/22 inspection.	1	T		
D 5	Diversion	Northwest Perimeter		Removed			
Current Condition:			isting contours as of the 5/3/2		1		
D 6	Diversion	Western Perimeter	1/18/2022	Active	No No		
Current Condition:	1/18/22 inspection. As of	the 5/3/22 inspection, D	ars to have been installed in the control of will represent the swale and the diversion along the swale a	nd dirt berm at the we	stern edge of future So		
ET 1	Erosion Control Terrace	N of SB D		Removed			
Current Condition:			errace will no longer be instal		inspection.		
ET 2	Erosion Control Terrace	N of SB E		Removed			
Current Condition:			errace will no longer be instal		inspection.		
ET 3	Erosion Control Terrace	N of SB B		Removed			
Current Condition:			errace will no longer be instal		inspection.		
ET 4	Erosion Control Terrace	East Central		Removed			
Current Condition:			errace will no longer be instal				
EM 1	Erosion Control Matting	Northwest Side	7/15/2022	Active	No		
Current Condition:			ne matting prior to the 7/15/22				
EM 2	Erosion Control Matting	North-Central	7/15/2022	Active	No		
Current Condition:	Good Condition - Comme	rcial Seeding installed th	ne matting prior to the 7/15/22				
EM 3	Erosion Control Matting	Northeast Side	7/15/2022	Active			
Current Condition:	Good Condition - Comme	rcial Seeding installed th			No		
		roidi Goodii g iriolailoa li	ne matting prior to the 7/15/22	inspection.	No		
EM 4	Erosion Control Matting	Southwest Corner	5/31/2021	Pending	No		
EM 4 Current Condition:	Erosion Control Matting Pending - The erosion cor	Southwest Corner ntrol matting will be insta		Pending w when the associate	No No ed area reaches final gr		
	Erosion Control Matting Pending - The erosion cor	Southwest Corner ntrol matting will be insta	5/31/2021 alled within the seeding windo	Pending w when the associate	No No ed area reaches final gr		

Current Condition:	A water main extension p in the area will be temporalinspection.	roject in the area will be arily halted until work is	alled within the seeding wind gin soon as of the 5/3/22 ins complete. Seeding of the slo	pection, therefore, recoppe is still recommende	ommendations for matting	
FT 1	Fuel Tank	SW Corner		Removed		
Current Condition:	Removed - DEJ removed		7/15/22 inspection.			
FT 2	Fuel Tank	Material Storage Area		Removed		
Current Condition:	Removed - TAB removed	the fuel tank prior to the	e 4/7/22 inspection.			
FT 3	Fuel Tank	Material Storage Area	12/21/2021	Active	No	
Current Condition:	Good Condition - RPL ins	talled a double walled fu	el tank on site prior to the 12	2/21/21 inspection.		
FT 4	Fuel Tank	Material Storage Area		Removed		
Current Condition:	Removed - The fuel tank			•		
FT 5	Fuel Tank	Material Storage Area		Removed		
Current Condition:	Removed - The fuel tank	was removed prior to the On Site	e 7/8/22 inspection. 9/14/2021			
MS 1	Material Storage	Active	No			
Current Condition:	Good Condition - Material storage is primarily located along the west side of the site as of the 9/14/21 inspection. DEJ cleaned up the stained soils prior to the 9/28/21 inspection. Material storage for paving is primarily located along the southeast side of the site as of the 6/9/22 inspection.					
PB X	Portable Bathroom	On Site	5/31/2022	Active	No	
Current Condition:	Good Condition - RPL rei	nstalled a portable toilet	on site prior to the 5/31/22 in			
SB A	Sediment Basin	X24	5/11/2022	Active	Yes	
Current Condition:	Fair Condition - 41% - The basin was partially dug out prior to the 12/1/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was installed prior to the 5/11/22 inspection. The basin should be installed (baffle). The basin should be installed (baffle). DEJ was informed to complete by 9/7/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 10/15/2					
	10/21/21, 10/29/21, 12/2/2	21, 2/11/22, 3/24/22, 5/5	5/22, 5/27/22, 6/10/22.			
SB B	Sediment Basin	O24	5/18/2022	Active	Yes	
Current Condition:		d - The basin had been	partially dug out prior to the			
	prior to the 5/18/22 inspection. The E&A inspector painted the cleanout mark on 5/23/22. The basin should be installed (baffle). DEJ was informed to complete by 9/7/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 10/15/21, 10/21/21, 10/29/21, 12/2/21, 2/11/22, 3/24/22, 5/5/22, 5/27/22, 6/10/22.					
00.0		1		A office	V	
SB C Current Condition:	Sediment Basin	H24	5/18/2022 out prior to the 11/12/21 inspe	Active	Yes	
	inspection. Dewatering h painted the cleanout mark. The basin should be instance. DEJ was informed to com. 10/21/21, 10/29/21, 12/2/3	oles appear to have beek on 5/23/22. Illed (baffle). Iplete by 9/7/21. Not do 21, 2/11/22, 3/24/22, 5/5		o the 5/18/22 inspection DEJ/Gene Graves we	re reminded on 10/15/21,	
SB D	Sediment Basin	H22	5/18/2022	Active	Yes	
Current Condition:	pipe and rip rap appears to during the 4/21/22 inspect have been installed in the Due to ground disturbance DEJ/Gene Graves were in reminded on 12/2/21, 2/1.	Fair Condition - 46% Filled - The basin was in the process of being dug out during the 11/4/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. The old area inlet was removed prior to the 4/21/22 inspection. Dewatering holes appear to have been installed in the riser prior to the 5/18/22 inspection. Due to ground disturbance in the area, the basin should be installed (baffle, cleanout mark, correct contours/depth). DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21, 2/11/22, 3/24/22, 5/5/22, 5/27/22, 6/10/22. *Survey to check basin installation elevations as of 6/9/22. Basin elevations incorrect per E&A survey prior to the 7/28/22 inspection.				
CD F			-		No	
SB E Current Condition:		·	5/3/2022 Ally dug out prior to the 12/1/ c cleanout mark on 5/23/22.	Active 21 inspection. DEJ ins	No stalled the riser prior to the	
SF 1	Silt fence	Northern/Western Perimeter	5/18/2021	Active	Yes	

	intentionally built in the no Sudbeck installed wattles maintenance prior to the 4 prior to the 4/7/22 inspection of the silf fewas removed in multiple kinspector will monitor for rinspection. The water corprior to the 6/30/22 inspections by prior to the 7/8/22 in Additional silt fence should be gene Graves was informed 5/19/22, 6/10/22.	arthern section of the run p as an extension of the sil 1/1/22 inspection. Sudbection. TAB repaired/reinstations along the north side of the sill of the sill for	be prior to the 5/18/21 inspector to the 1/18/22 inspection of the 1/18/22 inspection of the fence to the north prior to the kextended the silt fence to illed the silt fence along 72nd of the construction entrance yest of SB D, for water install actor repaired the eroded are ence where damaged adjaced after testing. Sudbeck install the wattles in the north section. Not done as of the last inspections of the last inspections of the last inspections.	n, extending the silt fer at 2/2/22 inspection. The south along the notation in the south along the notation prior to the 4/2/22 in ation prior to the 6/24 has southwest of SB In the construction talled silt fence around on of the run.	ence is still recommended. Sudbeck began silt fence orth side of the entrance 7/22 inspection. Gene spection. The silt fence 1/22 inspection, the D prior to the 6/24/22 entrance and NW of SB D d the flared end section of				
SF 2 Current Condition:		Perimeter	5/25/2021 nce prior to the 5/25/21 inspe	Active ection. Sudbeck main	No tained the silt fence prior to				
	the 6/30/22 inspection.								
SF 3	Silt fence	Southeast Corner	5/25/2021	Active	No				
Current Condition:		•	nce prior to the 5/25/21 inspects inspection. Sudbeck main						
SF 4	Silt fence	Southwest Perimeter	5/18/2021	Active	No				
STR Current Condition:	complete the majority of the maintenance and reinstallation of the silt fence prior to the 4/7/22 inspection. Sudbeck installed high porosity silt fence checks in the flow line of the swale prior to the 4/7/22 inspection. The silt fence was partially removed the future Ponderosa entrance along 72nd Street for storm sewer work prior to the 5/18/22 inspection, due to imminent paving reinstallation will not be recommended. Sudbeck maintained the silt fence around the culvert/Ponderosa Drive prior to the 6/24/22 inspection. Sudbeck maintained the silt fence prior to the 6/30/22 inspection. Streets S 72nd Street 5/18/2021 Active No								
Current Condition.	Street during the 6/9/22 in	•	•	or siit was observed ii	Good Condition - The streets were cleaned prior to the 5/31/22 inspection. Minor silt was observed in the curb line along 72nd				
					n the curb line along 72nd				
SW 1	Straw wattles	72nd ROW	7/8/2022	Active					
SW 1 Current Condition:	Straw Wattles Good Condition - Kersten	72nd ROW installed wattles along the	7/8/2022 e 72nd St. ROW prior to the	Active 7/8/22 inspection.	No				
SW 1 Current Condition: SWPPP Sign			7/8/2022 e 72nd St. ROW prior to the 5/18/2021						
Current Condition:	Good Condition - Kersten Misc/Other	installed wattles along the S 72nd and Schram	e 72nd St. ROW prior to the	7/8/22 inspection. Active	No No				
Current Condition: SWPPP Sign Current Condition: WO 1	Good Condition - Kersten Misc/Other Good Condition - The E&/ inspection. Concrete Washout	installed wattles along the S 72nd and Schram A inspector installed the S	e 72nd St. ROW prior to the 5/18/2021 EWPPP sign in the southwes 6/9/2022	7/8/22 inspection. Active	No No				
Current Condition: SWPPP Sign Current Condition: WO 1 Current Condition:	Good Condition - Kersten Misc/Other Good Condition - The E&/ inspection. Concrete Washout Fair Condition - Kersten in 1.) A liner should be instal 2.) Concrete waste piles s 1.) The E&A construction 2.) The E&A construction	installed wattles along the S 72nd and Schram A inspector installed the S On Site Installed a washout pit prior Illed in the pit. Should be cleaned up. Observer was informed or observer was informed or	e 72nd St. ROW prior to the 5/18/2021 EWPPP sign in the southwes 6/9/2022 In to the 6/9/22 inspection. In 6/10/22. Not done as of the 6/10/22. Not done as of the	7/8/22 inspection. Active t corner of the proper Active e last inspection.	No No ty during the 5/18/21 Yes				
Current Condition: SWPPP Sign Current Condition: WO 1	Good Condition - Kersten Misc/Other Good Condition - The E&/ inspection. Concrete Washout Fair Condition - Kersten in 1.) A liner should be instal 2.) Concrete waste piles s 1.) The E&A construction	installed wattles along the S 72nd and Schram A inspector installed the S On Site Installed a washout pit prior liled in the pit. Should be cleaned up.	e 72nd St. ROW prior to the 5/18/2021 WPPP sign in the southwes 6/9/2022 If to the 6/9/22 inspection.	7/8/22 inspection. Active t corner of the proper Active	No No ty during the 5/18/21				
Current Condition: SWPPP Sign Current Condition: WO 1 Current Condition:	Good Condition - Kersten Misc/Other Good Condition - The E&/ inspection. Concrete Washout Fair Condition - Kersten in 1.) A liner should be instal 2.) Concrete waste piles s 1.) The E&A construction 2.) The E&A construction Waste Storage Pending - Waste will be co "I certify, under penalty of accordance with a system submitted. Based on my ir gathering the information,	installed wattles along the S 72nd and Schram A inspector installed the S On Site Installed a washout pit prior Itel in the pit. Installed a washout pit prior Itel in the pit. Installed a washout pit prior Itel in the pit. Installed a washout pit prior Itel in the pit. Installed a washout pit prior Itel in the pit. I	e 72nd St. ROW prior to the 5/18/2021 EWPPP sign in the southwes 6/9/2022 If to the 6/9/22 inspection. 1 6/10/22. Not done as of the 6/10/22. Not done as of the 5/31/2021	7/8/22 inspection. Active t corner of the proper Active e last inspection. Pending pared under my direct gathered and evaluate m or those persons of dge and belief, true, a	No No ty during the 5/18/21 Yes No ion or supervision in ed the information irrectly responsible for accurate, and complete. I				