E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

E&A - P2018.228.001 Bill SID as of 2/17/22 P2018.228.000

		Bill SID as of 2/1	7/22 P2018.228.000		
Inspector: Jason Brackett	:				Stage
		Sevent	y Two Place		
			0624-5346-GP1		1
					•
Project Name:		CSW-	202004796		
For Week Ending:		3/	11/2023		
Project Location:		12101 S 72nd St, P	apillion, Sarpy County, NE		68046
Cradina	759	v I			
Grading: Sanitary Sewer:	1009				
Storm Sewer:	959				
Paving:	75%				
Seeding:	509	-			
Utilities:	759				
Overall Development:	439				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Ι
					Week
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"				
Wednesday:	0.02"	3/8/2023	Cloudy 41/35	12:45 PM	
Thursday:	0.25"				
Friday:	0.00"	3/10/2023	Cloudy 42/31	11:05 AM	
	0.11"				

Complaints:

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Rough grading began (6/15/21). Excavation for sanitary installation (9/28/21). Grading ceased due to winter conditions (1/5/22). Excavation for utility connections along 72nd (2/8/22). Grading for roadways (6/9/22). Lot 3 Replat 1 and Lot 4 Replat 1 scraping (11/2/22). Riprap installation and regrading at S 70th Street stub (11/2/22). Swale and ROW along Ponderosa connection finish graded (11/4/22). Swale and ROW along Ponderosa grading ceased (12/1/22).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading began (6/15/21). Excavation for sanitary installation (9/28/21). Grading ceased due to winter conditions (1/5/22). Excavation for utility connections along 72nd (2/8/22). Grading for roadways (6/9/22). Lot 3 Replat 1 and Lot 4 Replat 1 scraping (11/2/22). Riprap installation and regrading at S 70th Street stub (11/2/22). Swale and ROW along Ponderosa connection finish graded (11/4/22). Swale and ROW along Ponderosa grading ceased (12/1/22).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (6/15/21). Disking/seeding east side of site (7/8/22). Lot 1, 2, 3 - seeded (11/10/22). Seeding and matting swale and ROW along Ponderosa and Schram/72nd medians and ROWs (12/8/22).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Create Corrective Action?

No, see Findings section.

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

N/A	
Are construction entrances and adjacent streets being maintained adequately?	
Yes	
Create Corrective Action?	
N/A	
Is dust associated with the construction activity adequately controlled on the site?	
Yes	
Create Corrective Action?	
N/Δ	

Comments

Comments:

The site was inactive during the most recent inspection.

Lot 5 and 6 Replat 1 have been removed from this SWPPP and are covered by PAP-20220310-6351-GP1.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section of this report.
- 2) Disturbed and inactive areas of the site should be seeded. Gene Graves was informed to complete between April 15th and May 15th in the seeding window.
- 3) Erosion should be repaired and stabilized in the northeast corner of the site. Gene Graves was informed to complete between April 15th and May 15th in the seeding window.
- 4) 72nd Street slope should be re-graded and seeded and matted. SID to complete between April 1st and May 15th.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
CE 1	Construction Entrance	Schram Road		Removed			
Current Condition:	Removed - The entrance connection.	will no longer be used a	s of the 8/29/22 inspection du	ie to the completion of	the Schram Road		
D 1	Diversion	E of SB C	11/12/2021	Active	No		
Current Condition:	Good Condition - DEJ installed the diversion prior to the 11/12/21 inspection. Sudbeck was in the process of cleaning out the diversion during the 6/30/22 inspection. Sudbeck maintained the diversion prior to the 7/8/22 inspection. The diversion was removed at the S 70th stub prior to the 8/29/22 inspection, the inspector will monitor the need for reinstallation.						
D 2	Diversion	S of SB D		Removed			
Current Condition:			ated are now covered by PAF		1.		
D 3	Diversion	N of SB D		Removed			
Current Condition:			the 10/20/20 inspection, the o				
D 4	Diversion	E and SB B	7/8/2022	Active	No		
Current Condition:			prior to the 7/8/22 inspection.				
D 5	Diversion	Northwest Perimeter		Removed			
Current Condition:	Removed - The diversion		isting contours as of the 5/3/2				
D 6	Diversion	Western Perimeter	1/18/2022	Active	No		
Current Condition:	1/18/22 inspection. As of Road. DEJ/Gene Graves inspection.	the 5/3/22 inspection, D redirected the gap in th	rs to have been installed in the of will represent the swale and e diversion along the swale a	nd dirt berm at the wes djacent to 72nd Street	tern edge of future Schram		
ET 1	Erosion Control Terrace	N of SB D		Removed			
Current Condition:	Removed - Due to active	paving in the area, the t	errace will no longer be instal	led as of the 7/15/22 in	nspection.		
ET 2	Erosion Control Terrace	N of SB E		Removed			
Current Condition:	Removed - Due to active	paving in the area, the t	errace will no longer be instal	led as of the 7/15/22 in	nspection.		
ET 3	Erosion Control Terrace	N of SB B		Removed			
Current Condition:	Removed - Due to active	paving in the area, the t	errace will no longer be instal	led as of the 7/15/22 in	nspection.		
ET 4	Erosion Control Terrace	East Central		Removed			
Current Condition:	Removed - Due to active	paving in the area, the t	errace will no longer be instal	led as of the 7/15/22 in	nspection.		
EM 1	Erosion Control Matting	Northwest Side	7/15/2022	Active	No		
Current Condition:	seeded and matted by Co	mmercial Seeding prior			·		
EM 2	Erosion Control Matting		7/15/2022	Active	No		
Current Condition:			ne matting prior to the 7/15/22				
EM 3	Erosion Control Matting	Northeast Side	7/15/2022	Active	No		
Current Condition:			ne matting prior to the 7/15/22				
EM 4	Erosion Control Matting		12/8/2022	Active	No		
Current Condition:			ne seed/mat prior to the 12/8/2				
EM 5	Erosion Control Matting	West Side	5/31/2021	Pending	No		
Current Condition:	A water main extension pr in the area will be tempora inspection. Water main in	roject in the area will be arily halted until work is o astallation is active on si	alled within the seeding windo gin soon as of the 5/3/22 insp complete. Seeding of the slop te as of the 8/29/22 inspection finish grading along 72nd Str	ection, therefore, reco pe is still recommende n, water contractor will	ammendations for matting and as of the 5/3/22 I be seeding and matting		
	seeding/matting to follow.						
FT 1	seeding/matting to follow. Fuel Tank	SW Corner		Removed			
FT 1 Current Condition:			2 7/15/22 inspection.	Removed			

Full Tank Methods 1802 (1902) For a service of the	Compat Candition	Damas and TAD reserved	the first touch water to the	4/7/00 in an artism		
Gurrent Condition: Removed - RPL: removed the full floring from the 114/22 inspection. Removed Rem				e 4/7/22 inspection.	Removed	
Current Condition: Fig. 17 a. M. Masterial Storage Area Current Condition: For 17 a. M. Masterial Storage Area Current Condition: Removed				114/22 inspection	Removed	
### Semond Condition:				7 1 1722 moposion.	Removed	
Current Condition: Fig. 8 Fuel Tank				e 5/18/22 inspection.		l .
Gurrent Condition: With St. 1 Material Storage On Site Removed Removed Removed Removed Material Storage On Site Removed Removed Material Storage On Site Removed Removed Material Storage On Site Removed Material Storage On Site Removed Removed Material Storage On Site Removed Material Storage On Site Removed Material Storage Material Storage New York Material Storage Material Storage				'	Removed	
Maj	Current Condition:	Removed - The fuel tank	was removed prior to the	e 7/8/22 inspection.		
Methanal Storage	_				Removed	
Removed - Civil overlot development is mostly complete, material storage will be addressed on a lot by lot basis as of the 11/4/22 inspection.		Removed - Kersten remov	ed the fuel tank prior to	the 114/22 inspection.		
Particle Bathroom On Site Removed Remo		Material Storage	On Site		Removed	
SB A Sediment Basin X24 5/11/2022 Active Yes Current Condition: Removed I-RPI, removed the remaining portable toilet from the site prior to the 11/12/2 inspection. Removed I-RPI, removed the remaining portable toilet from the site prior to the 12/12/1 inspection. The basin outfall pipe and not propaganes to have been installed prior to the 41/3/2 inspection. The hasin outfall pipe and not propaganes to have been installed prior to the 41/3/2 inspection. The first own site of the 12/12/1 inspection. The basin outfall pipe and not propaganes to have been installed in prot to the 51/3/2 inspection. The first own site of the 12/12/1 inspection. The basin outfall pipe and not propaganes was reshaped prior to the 5/8/22/inspection. The E&A inspector painted the cleanout mark on 5/23/22. 1) The basin should be cleaned out and the slopes seeded/matted. 3) Erosion into the basin should be repaired and stabilized. 1) DEJ was informed to complete by 9/7/21. Not done as of the last inspection. Gene Graves were reminded on 10/15/21, 10/21/21, 10/28/21, 12/221, 2/11/22, 3/24/22, 5/5/22, 5/17/22, 6/10/22. 3) The SID is working to identify funding to complete the basin cleanout as of 3/10/23. SB B Current Condition: Removed I-RPI is working to identify funding to complete the basin cleanout as of 3/10/23. SB B Current Condition: Part Condition: 49% Filled I he basin has not proposed part propaganes and proposed part propaganes and proposed part propaganes. The part propaganes is the process of being installed during the 4/21/22 inspection. Developed proposed propos	Current Condition:		evelopment is mostly co	mplete, material storage will	be addressed on a lot	by lot basis as of the
SBA Sodment Basin X24 5/11/2022 Active Yes Current Condition: Fair Condition: 49% - The basin was partially due out prior to the 12/12/1 inspection. The basin undufflippe and rip rap appears to have been installed prior to the 4/13/22 inspection. The risk installed prior to the 6/11/22 inspection. The basin should be installed (baffle). 2) The basin should be installed (baffle). 2) The basin should be cleaned out and the slopes seeded/matted. 3) Erosion into the basin should be prajered and stabilized. 1) DEJ was informed to complete by 97/21. Not done as of the last inspection. Gene Graves were reminded on 10/15/21, 10/21/21, 10/22621, 12/2221, 21/11/22, 3/24/22, 5/67/22, 5/67/22, 6/67/22, 6/67/22, 21/11/22, 10/21/22, 10/21/22, 1/21/22, 3/24/22, 5/67/22, 6/67/22, 6/67/22, 6/67/22, 21/11/22, 10/21/22	PB X	Portable Bathroom	On Site		Removed	
Current Condition: Fair Condition - 49% - The basin was partially dug out prior to the 12/1/21 inspection. The basin outfall pipe and propagate to have been installed prior to the 4/3/22 inspection. The fiser was installed prior to the 6/1/3/22 inspection. The E&A inspector painted the cleanout mark on 5/23/22. 1 The basin should be installed (foaffle). 2 The basin should be cleaned out and the slopes seeded/matted. 3 Erosion into the basin should be pospired and stabilized. 1 DEJ was informed to complete by 9/7/21. Not done as of the last inspection. Gene Graves were reminded on 10/15/21, 10/21/21, 10/22/21, 10/22/21, 21/17/22, 3/24/22, 5/5/22, 5/5/7/22, 6/10/22. 2 The SBI is working to identify funding to complete the basin cleanout as of 3/10/23. 3 The SBI is working to identify funding to complete the basin cleanout as of 3/10/23. SB B	Current Condition:	Removed - RPL removed	the remaining portable	oilet from the site prior to the	11/4/22 inspection.	
appears to have been installed prior to the 4/13/22 inspection. The faser was installed prior to the 5/11/22 inspection. The basis was reshaped prior to the 5/62/22 inspection. The East A inspector painted the cleanout mark on 5/23/22. 1) The basin should be cleaned out and the slopes seeded/matted. 2) The basin should be cleaned out and the slopes seeded/matted. 3) Erosion into the basin should be repaired and stabilized. 1) DEJ was informed to complete by 97/21. Not done as of the last inspection. Gene Graves were reminded on 10/15/21, 10/21/21, 10/29/21, 12/22/1, 2/11/22, 3/24/22, 5/67/22, 5/67/22, 5/67/22, 6/10/22. 2) The SDI is sworking to identify funding to complete the basin cleanout as of 3/10/23. 3) The SDI is working to identify funding to complete the basin cleanout as of 3/10/23. 3) The SDI is working to identify funding to complete the basin cleanout as of 3/10/23. 3) The SDI is working to identify funding to complete the basin cleanout as of 3/10/23. 3) The SDI is working to identify funding to complete the basin cleanout as of 3/10/23. 3) The SDI is working to identify funding to expect painted the cleanout mark on 5/23/22. 4) The basin should be installed (baffle). 2) The basin should be cleaned out and the slopes seeded/matted. 4) DEL was informed to complete by 9/7/21. Not done as of the last inspection. Gene Graves were reminded on 10/15/21, 10/21/21, 10/22/21, 10/22/21, 12/12/2, 3/24/22, 5/67/22, 6/71/22, 6/71/22. 2) The SDI is working to identify funding to complete the basin cleanout as of 3/10/23. SB C Current Condition: SB C Felf Condition - 49% Filled - The basin was due to prior to the 11/12/21 inspection. The basin outfall prior appear to have been installed for to the 4/13/22 inspection. The E&A inspector pained the cleanout mark on 5/23/22. 1) The basin should be cleaned out and the slopes seeded/matted. 1) DEJ was informed to complete by 9/7/21. Not done as of the last inspection. The E&A inspector pained the cleanout mark on 5/23/22. 2) The SDI is working to identify fundi	SB A	Sediment Basin	X24	5/11/2022	Active	Yes
10/21/21, 10/29/21, 12/2/21, 2/11/22, 3/24/22, 5/5/22, 5/27/22, 6/10/22. 2) The SID is working to identify funding to complete the basin cleanout as of 3/10/23. SBC Sediment Basin H24 5/18/2022 Active Yes Current Condition: Fair Condition - 49% Filled - The basin was dug out prior to the 11/12/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection inspection. Devatering holes appear to have been installed in the riser prior to the 5/18/22 inspection. The E&A inspector painted the cleanout mark on 5/23/22. 1) The basin should be installed (baffle). 2) The basin should be cleaned out and the slopes seeded/matted. 1) DEJ was informed to complete by 9/7/21. Not done as of the last inspection. Gene Graves were reminded on 10/15/21, 10/21/22, 10/29/21, 12/12/22, 3/24/22, 5/5/22, 5/27/22, 6/10/22. 2) The SID is working to identify funding to complete the basin cleanout as of 3/10/23. SB D Sediment Basin H22 5/18/2022 Active Yes Current Condition: Fair Condition - 49% Filled - The basin was in the process of being dug out during the 11/4/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being dug out during the 11/4/21 inspection. The basin outfall prior to the 4/13/22 inspection. The riser was in the process of being dug out during the 11/4/21 inspection. The basin outfall prior to the 4/13/22 inspection. The riser was in the process of being dug out during the 11/4/21 inspection. The basin outfall prior to the 4/13/22 inspection. 1) Due to ground disturbance in the area baffle should be installed. 2) The basin should be cleaned out, the correct basin depth should be established, and the slopes seeded/matted. 1) DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. Gene Graves were reminded on 12/2/21, 2/11/22, 3/24/22, 5/5/22, 5/2		2) The basin should be a 3) Erosion into the basin 1) DEJ was informed to consider the state of 10/21/21, 10/29/21, 12/2/22) The SID is working to 3) The SID is working to Sediment Basin Fair Condition - 49% Filled continue to monitor. The was in the process of being prior to the 5/18/22 inspect.	cleaned out and the slope should be repaired a complete by 9/7/21. Not 21, 2/11/22, 3/24/22, 5/5 identify funding to concentrate in the basin outfall pipe and rigg installed during the 4/stion. The E&A inspectors at all of the should be stilled (baffle).	done as of the last inspection /22, 5/27/22, 6/10/22. mplete the basin cleanout mplete the basin cleanout 5/18/2022 oratially dug out prior to the so rap appears to have been in 21/22 inspection. Dewaterin or painted the cleanout mark	as of 3/10/23. as of 3/10/23. Active 3/14/21 inspection by Enstalled prior to the 4/19 g holes appear to have	Yes DEJ, the inspector will 3/22 inspection. The riser
Current Condition: Fair Condition - 49% Filled - The basin was dug out prior to the 11/12/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. Dewatering holes appear to have been installed in the riser prior to the 5/18/22 inspection. The E&A inspector painted the cleanout mark on 5/23/22. 1) The basin should be installed (baffle). 2) The basin should be cleaned out and the slopes seeded/matted. 1) DEJ was informed to complete by 9/7/21. Not done as of the last inspection. Gene Graves were reminded on 10/15/21, 10/21/21, 10/29/21, 12/2/21, 2/11/22, 3/24/22, 5/5/22, 5/27/22, 6/10/22. 2) The SID is working to identify funding to complete the basin cleanout as of 3/10/23. SB D Current Condition: Fair Condition - 49% Filled - The basin was in the process of being dug out during the 11/4/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. Dewatering holes appear to have been installed in the riser prior to the 5/18/22 inspection. 1) Due to ground disturbance in the area baffle should be installed. 2) The basin should be cleaned out, the correct basin depth should be established, and the slopes seeded/matted.		10/21/21, 10/29/21, 12/2/2	21, 2/11/22, 3/24/22, 5/5	/22, 5/27/22, 6/10/22.		reminded on 10/15/21,
to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. Dewatering holes appear to have been installed in the riser prior to the 5/18/22 inspection. The E&A inspector painted the cleanout mark on 5/23/22. 1) The basin should be installed (baffle). 2) The basin should be cleaned out and the slopes seeded/matted. 1) DEJ was informed to complete by 9/7/21. Not done as of the last inspection. Gene Graves were reminded on 10/15/21, 10/21/21, 10/29/21, 12/2/21, 2/11/22, 3/24/22, 5/5/22, 5/27/22, 6/10/22. 2) The SID is working to identify funding to complete the basin cleanout as of 3/10/23. SB D Sediment Basin H22 5/18/2022 Active Yes Current Condition: Fair Condition - 49% Filled - The basin was in the process of being dug out during the 11/4/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. The old area inlet was removed prior to the 4/21/22 inspection. Dewatering holes appear to have been installed in the riser prior to the 5/18/22 inspection. 1) Due to ground disturbance in the area baffle should be installed. 2) The basin should be cleaned out, the correct basin depth should be established, and the slopes seeded/matted. 1) DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. Gene Graves were reminded on 12/2/21, 2/11/22, 3/24/22, 5/5/22, 5/27/22, 6/10/22. "Survey to check basin installation elevations as of 6/9/22. Basin elevations incorrect per E&A survey prior to the 7/28/22 inspection. 2) The SID is working to identify funding to complete the basin cleanout as of 3/10/23. SB E Sediment Basin D19 5/3/2022 Active No Current Condition: Circuit Condition: Northern/Western Northern/Western Northern/Western	SB C					
SB D Sediment Basin H22 5/18/2022 Active Yes Current Condition: Fair Condition - 49% Filled - The basin was in the process of being dug out during the 11/4/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. The old area inlet was removed prior to the 4/21/22 inspection. Dewatering holes appear to have been installed in the riser prior to the 5/18/22 inspection. 1) Due to ground disturbance in the area baffle should be installed. 2) The basin should be cleaned out, the correct basin depth should be established, and the slopes seeded/matted. 1) DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. Gene Graves were reminded on 12/2/21, 2/11/22, 3/24/22, 5/5/22, 5/27/22, 6/10/22. *Survey to check basin installation elevations as of 6/9/22. Basin elevations incorrect per E&A survey prior to the 7/28/22 inspection. 2) The SID is working to identify funding to complete the basin cleanout as of 3/10/23. SB E Sediment Basin D19 5/3/2022 Active No Good Condition - 7% Filled - The basin was partially dug out prior to the 12/1/21 inspection. DEJ installed the riser prior to the 5/3/22 inspection. The E&A inspector painted the cleanout mark on 5/23/22. SE 1 Silt fence Northern/Western 5/18/2021 Active Yes		inspection. Dewatering he painted the cleanout mark 1) The basin should be ins 2) The basin should be of the bas	oles appear to have bee on 5/23/22. stalled (baffle). cleaned out and the sleened out and the sleened out 21. Not 21, 2/11/22, 3/24/22, 5/5	opes seeded/matted. done as of the last inspection //22, 5/27/22, 6/10/22.	o the 5/18/22 inspection	n. The E&A inspector
Current Condition: Fair Condition - 49% Filled - The basin was in the process of being dug out during the 11/4/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. The old area inlet was removed prior to the 4/21/22 inspection. Dewatering holes appear to have been installed in the riser prior to the 5/18/22 inspection. 1) Due to ground disturbance in the area baffle should be installed. 2) The basin should be cleaned out, the correct basin depth should be established, and the slopes seeded/matted. 1) DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. Gene Graves were reminded on 12/2/21, 2/11/22, 3/24/22, 5/5/22, 5/27/22, 6/10/22. *Survey to check basin installation elevations as of 6/9/22. Basin elevations incorrect per E&A survey prior to the 7/28/22 inspection. 2) The SID is working to identify funding to complete the basin cleanout as of 3/10/23. SB E Sediment Basin D19 5/3/2022 Active No Good Condition - 7% Filled - The basin was partially dug out prior to the 12/1/21 inspection. DEJ installed the riser prior to the 5/3/22 inspection. The E&A inspector painted the cleanout mark on 5/23/22. SE 1 Silt fence Northern/Western 5/18/2021 Active Yes	SB D			-		Voc
on 12/2/21, 2/11/22, 3/24/22, 5/5/22, 5/27/22, 6/10/22. *Survey to check basin installation elevations as of 6/9/22. Basin elevations incorrect per E&A survey prior to the 7/28/22 inspection. 2) The SID is working to identify funding to complete the basin cleanout as of 3/10/23. SB E Sediment Basin D19 5/3/2022 Active No Current Condition: Good Condition - 7% Filled - The basin was partially dug out prior to the 12/1/21 inspection. DEJ installed the riser prior to the 5/3/22 inspection. The E&A inspector painted the cleanout mark on 5/23/22. SET 1 Silt fence Northern/Western 5/18/2021 Active Yes		Fair Condition - 49% Filler pipe and rip rap appears to during the 4/21/22 inspect have been installed in the 1) Due to ground disturbation.	d - The basin was in the o have been installed prion. The old area inlet viser prior to the 5/18/22	process of being dug out du ior to the 4/13/22 inspection. vas removed prior to the 4/2 inspection. hould be installed.	ring the 11/4/21 insper The riser was in the 1/22 inspection. Dewa	ction. The basin outfall process of being installed atering holes appear to
Current Condition: Good Condition - 7% Filled - The basin was partially dug out prior to the 12/1/21 inspection. DEJ installed the riser prior to the 5/3/22 inspection. The E&A inspector painted the cleanout mark on 5/23/22. SET 1 Silt fence Northern/Western 5/18/2021 Active Yes		on 12/2/21, 2/11/22, 3/24/ elevations incorrect per Ed	22, 5/5/22, 5/27/22, 6/10 &A survey prior to the 7	0/22. *Survey to check basir/28/22 inspection.	n installation elevations	
Current Condition: Good Condition - 7% Filled - The basin was partially dug out prior to the 12/1/21 inspection. DEJ installed the riser prior to the 5/3/22 inspection. The E&A inspector painted the cleanout mark on 5/23/22. SET 1 Silt fence Northern/Western 5/18/2021 Active Yes						
SE 1 Silt tence 5/18/2021 Active Yes	SB E	Sediment Basin	D19	5/3/2022	Active	No
		Good Condition - 7% Fille	d - The basin was partia	lly dug out prior to the 12/1/2		

	Sudbeck installed wattles maintenance prior to the 4/7/22 inspec Graves repaired the silt fe was removed in multiple inspector will monitor for inspection. The water coprior to the 6/30/22 inspection. The water coprior to the 6/30/22 inspection. The water coprior to the 6/30/22 inspection. The water coprior to the 7/8/22 is Sudbeck repaired and exat the SB D outfall was of the Spring of 2023. Community of the silt fence needs 2) The silt fence needs 1) Gene Graves was infection.	orthern section of the run p s as an extension of the silt 4/1/22 inspection. Sudbection. TAB repaired/reinstall ence along the north side o locations, including southwaremoval. The water contra partractor removed the silt fe	rior to the 1/18/22 inspection fence to the north prior to the extended the silt fence to the extended the silt fence to the the construction entrance test of SB D, for water instruction repaired the eroded a since where damaged adjard after testing. Sudbeck in the silt fence along the nor 72nd Street prior to the 9/2 inspection, grading and seinstalled the silt fence not ad along 72nd Street.	on, extending the silt for the 2/2/22 inspection. The south along the notate prior to the 4/2 prior to the 5/26/22 in allation prior to the 6/24 preas southwest of SB coent to the construction stalled silt fence around the side of Schram prior (19/22 inspection. Mind tabilization of the 72nd	Sudbeck began silt fence oorth side of the entrance (7/22 inspection. Gene inspection. The silt fence 4/22 inspection, the Dipprior to the 6/24/22 inspection of the the flared end section of the to the 9/12/22 inspection. For damage to the silt fence Street ROW will begin in
SF 2	Silt fence	Northeastern Perimeter	5/25/2021	Active	Yes
Current Condition:	the 6/30/22 inspection. S 1) The silt fence needs 2) The silt fence can be 1) Gene Graves was inf	eloper installed the silt fence Sudbeck reinforced the silt for to be repaired in the norte removed where damaged formed to complete by 3/1 formed to complete by 3/1	fence with additional posts theast corner. d in upgradient areas.		•
SF 3	Silt fence	Southeast Corner eloper installed the silt fence	5/25/2021	Active	Yes
	1) The silt fence needs	to be patched at the basis	n outfall.		
	2) The silt fence can be 1) Gene Graves was inf 2) Gene Graves was inf	to be patched at the basic removed where damaged formed to complete by 3/1 formed to complete by 3/1	d in upgradient areas. 15/23. 15/23.		
SF 4 Current Condition:	2) The silt fence can be 1) Gene Graves was inf 2) Gene Graves was inf Silt fence	removed where damage	d in upgradient areas. 15/23. 15/23. 5/18/2021	Active ection. Gene Graves in	Yes nstalled silt fence around
	2) The silt fence can be 1) Gene Graves was inf 2) Gene Graves was inf Silt fence Fair Condition - The deve the Ponderosa Drive damage when work is complete. maintenance in the area complete the majority of thigh porosity silt fence che the future Ponderosa ent reinstallation will not be re 6/24/22 inspection. Sudb. removed for water installatence will not be recomm seeding and matting of the prior to the 12/8/22 inspection. 1) The silt fence needs 2) The silt fence can be 3) The silt fence needs 4) Silt fence needs 4) Silt fence needs 5) Additional silt fence 6) The silt fence needs 1) SID will complete wit 2) Gene Graves was inf 3) Gene Graves was inf 5) Gene Graves was inf	removed where damaged formed to complete by 3/1 ormed to complete by 3/1 Southwest Perimeter eloper installed the silt fencinection prior to the 10/13/2 ed a small portion of the silt Sanitary excavation around is now included below. Such the maintenance and reinst	d in upgradient areas. 15/23. 5/18/2021 be prior to the 5/18/21 insp it inspection. Excavation of tence prior to the 1/18/22 of Ponderosa Drive appears deck began silt fence ma callation of the silt fence pr swale prior to the 4/7/22 in r storm sewer work prior to caintained the silt fence are ce prior to the 6/30/22 insi spection, plans for stabilize imaged portions of silt fence in 2022. Commercial See er silt fence in the area prior to the swale. d in upgradient areas. iple locations. along the silt fence sou protect the Ponderosa dr of Ponderosa. along 72nd as of 3/10/23 15/23. 15/23. 15/23. 15/23. 15/23.	ection. Gene Graves in spoils from sanitary exitinspection, the inspection, the inspection in the inspection of the 4 conspection. The silt fend of the 5/18/22 inspection and the culvert/Ponder operation. Some of the station are being prepared were removed prior to the 12/8/22 inspection of the silt or to the 12/8/22 inspection.	nstalled silt fence around cavation in the area of tor will recommend repair the 2/2/22 inspection, 4/1/22 inspection. Sudbeck tion. Sudbeck installed ce was partially removed at n, due to imminent paving, rosa Drive prior to the silt fence was temporarily ed, reinstallation of the silt to the 11/4/22 inspection, fence checks in the swale ction.

Current Condition:	Fair Condition - Sudbeck	installed the silt fence p	rior to the 11/4/22 inspection	n.			
	The silt fence needs to be repaired and reinforced with additional t-posts.						
	Gene Graves was infor	med to complete by 3/1	5/23.				
SF 6	Silt fence	NE S 70th and Flint	11/10/2022	Active	Yes		
Current Condition:	Fair Condition - Sudbeck The silt fence needs to	·	rior to the 11/10/22 inspectined in.	on.			
	Gene Graves was infor	<u> </u>					
SF 7	Silt fence	NE S 70th and Stony	11/10/2022	Active	Yes		
Current Condition:		be repaired and reinfor	rior to the 11/10/22 inspection to the 11/10/22 inspection ced with additional t-pos				
SF 8	Silt fence	NW of SB C	12/8/2022	Active	No		
Current Condition:			ne silt fence prior to the 12/8/		INU		
Current Condition.	Good Condition - Comme		le siit terice prior to the 12/6	1 Inspection.			
SF 9 Current Condition:	Silt fence	SW Corner of 72nd and Schram	12/8/2022 silt fence prior to the 12/8/	Active	Yes		
	The silt fence needs to SID will complete with:	·	along 72nd as of 3/10/23.				
STR	Streets	S 72nd Street	5/18/2021	Active	Yes		
	Interior streets need to		/23.				
SW 1	Straw Wattles	72nd ROW	7/8/2022	Active	No		
Current Condition: SWPPP Sign	misplaced prior to the 12/	/1/22 inspection, grading he wattles was observed	e 72nd St. ROW prior to the and stabilization of the 72n ed during the 3/8/23 inspector	d Street ROW will begin	n in the Spring of 2023.		
Current Condition:			SWPPP sign in the southw	Active			
Current Condition.	inspection.		Sween sign in the southw		Try during the 5/16/21		
WO 1	Concrete Washout	On Site	<u> </u>	Removed			
Current Condition:	Removed - Sudbeck clea	ned up the remaining co	ncrete waste on site prior to	the 11/4/22 inspection			
WS1	Waste Storage	On Site	•	Removed			
Current Condition:	<u> </u>		on materials, portable toilets		parate BMPs in the BMP		
Certification Statement:	accordance with a system submitted. Based on my gathering the information	n designed to assure tha inquiry of the person or p , the information submitte	and all attachments were p t qualified personnel proper ersons who manage the sy ed is, to the best of my know ubmitting false information i	ly gathered and evaluat stem or those persons of wledge and belief, true,	ed the information directly responsible for accurate, and complete.		
spector Signature:	Jule Part			Reviewed By:	Get Sol		