E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Gervices De			18.228.001 //22 P2018.228.000				
Inspector: Jason Brackett		Stage					
Project Name:	Seventy Two Place PAP-20200624-5346-GP1 CSW-202004796				1		
For Week Ending:		4/15/2023					
Project Location:		4/15/2025 12101 S 72nd St, Papillion, Sarpy County, NE					
					68046		
Grading:	75%						
Sanitary Sewer:	100%						
Storm Sewer:	95%						
Paving:	75%						
Seeding: Utilities:	50% 75%						
	-						
Overall Development:	43%						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time			
					Week 1		
Sunday:	0.00"						
Monday:	0.12"						
Tuesday: Wednesday:	0.00"						
Thursday:	0.00"	4/13/2023	Sunny 88/58	10:55 AM			
Friday:	2.51"						
Saturday:	0.09"						
Construction Sequencing: Which portion(s) (i.e. drainage bas Rough grading began (6/15/2 connections along 72nd (2/8/2 70th Street stub (11/2/22). St (12/1/22). Which portion(s) (i.e. drainage bas Rough grading began (6/15/2 connections along 72nd (2/8/2 70th Street stub (11/2/22). St (12/1/22).	 Excavation for sanitary Grading for roadways (wale and ROW along Pondering) ins) of the site do not have grad Excavation for sanitary Grading for roadways (installation (9/28/21). (6/9/22). Lot 3 Replat 1 erosa connection finish ing, earthwork, or ground installation (9/28/21). (6/9/22). Lot 3 Replat 1	Grading ceased due to wint I and Lot 4 Replat 1 scrapin In graded (11/4/22). Swale a disturbance scheduled in the ne Grading ceased due to wint I and Lot 4 Replat 1 scrapin	er conditions (1/5/22). E g (11/2/22). Riprap insta and ROW along Ponderc ext 14 days? er conditions (1/5/22). E g (11/2/22). Riprap insta	Excavation for utility allation and regrading at S bsa grading ceased Excavation for utility allation and regrading at S		
What temporary or permanent stal Existing vegetation (6/15/21). Ponderosa and Schram/72nd	Disking/seeding east side of	of site (7/8/22). Lot 1,		eeding and matting swa	le and ROW along		
Checklist Questions: Are receiving waters adjacent to the Yes Create Corrective Action? N/A	he project free of any significant	signs of erosion or sedin	ent that would be associated wi	th the construction activity?			
Have disturbed areas been seeded No Create Corrective Action? No, see Findings and BMPs s	section.			on measure are adequate or	needed to prevent erosion.		
Are waste materials (concrete, cor No Create Corrective Action?	nstruction material, hazardous, e	etc.) being managed prope	eriy ?				

N	
No, see Findings section.	
Are construction entrances and adjacent streets being maintained adequately?	
Yes	
Create Corrective Action?	
N/A	
Is dust associated with the construction activity adequately controlled on the site?	
Yes	
Create Corrective Action?	
N/A	
Comments:	
O server sente	

Comments:

The site was inactive during the most recent inspection. Lot 5 and 6 Replat 1 have been removed from this SWPPP and are covered by PAP-20220310-6351-GP1.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):

1) Some maintenance is required in the BMP section of this report.

2) Disturbed and inactive areas of the site should be seeded. Gene Graves was informed to complete between April 15th and May 15th in the seeding window. Not done as of the last inspection. Gene Graves was reminded on 3/24/23. Sudbeck has been hired to conduct seeding in the seeding window as of the 3/30/23 inspection. Sudbeck to complete with mowing as of the 4/6/23 inspection.

3) Erosion should be repaired and stabilized in the northeast corner of the site. Gene Graves was informed to complete between April 15th and May 15th in the seeding window. Not done as of the last inspection. Gene Graves was reminded on 3/24/23, 3/30/23. Sudbeck repaired the erosion in the northeast corner of the lot prior to the 4/6/23 inspection, the inspector will monitor for stabilization.

4) 72nd Street slope should be re-graded and seeded and matted. SID to complete between April 1st and May 15th. Not done as of the last inspection. Plans sent to contractors on 3/24/23. Sudbeck to begin work by April 15th, 2023. Sudbeck completed grading work prior to the 4/6/23 inspection. Commercial Seeding was sent updated plans to stabilize the slope on 4/7/23.

5) Trash and debris needs to be cleaned up along the south side of the site. Gene Graves was informed to complete by 3/30/23, 3/30/23. Sudbeck to complete with mowing as of the 4/6/23 inspection.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance			
CE 1	Construction Entrance	Schram Road		Removed				
Current Condition:	Removed - The entrance	will no longer be used a	s of the 8/29/22 inspection du	e to the completion of	the Schram Road			
	connection.	-	-					
D 1	Diversion	E of SB C	11/12/2021	Active	No			
Current Condition:	Good Condition - DEJ inst	talled the diversion prior	to the 11/12/21 inspection.	Sudbeck was in the pre-	ocess of cleaning out the			
	diversion during the 6/30/2	diversion during the 6/30/22 inspection. Sudbeck maintained the diversion prior to the 7/8/22 inspection. The diversion was						
	removed at the S 70th stub prior to the 8/29/22 inspection, the inspector will monitor the need for reinstallation.							
D 2	Diversion	S of SB D		Removed				
Current Condition:	Removed - The area whe	re the diversions are loc	ated are now covered by PAF	P-20220310-6351-GP	1.			
D 3	Diversion	N of SB D		Removed				
Current Condition:	Removed - The stockpiles	were removed prior to	the 10/20/20 inspection, the c	liversion is no longer r	needed.			
D 4	Diversion	E and SB B	7/8/2022	Active	No			
Current Condition:	Good Condition - Sudbeck	k installed the diversion	prior to the 7/8/22 inspection.					
D 5	Diversion	Northwest Perimeter		Removed				
Current Condition:	Removed - The diversion	is not needed due to ex	isting contours as of the 5/3/2	2 inspection.				
D 6	Diversion	Western Perimeter		Removed				
Current Condition:	Removed - The remaining	portions of Schram hav	ve been installed as of the 3/2	3/23 inspection. Rec	ommendations for swal			
	regrading are included in t	he Findings section of t	his report.					
D 7	Diversion	Stub to SB A	3/23/2023	Active	No			
D 7 Current Condition:			3/23/2023 version from the stub road to S					
Current Condition:	Good Condition - Paving of Erosion Control Terrace	contractor installed a div N of SB D		BA prior to the 3/23/ Removed	23 inspection.			
Current Condition: ET 1	Good Condition - Paving of Erosion Control Terrace	contractor installed a div N of SB D	rersion from the stub road to S	BA prior to the 3/23/ Removed	23 inspection.			
Current Condition: ET 1 Current Condition:	Good Condition - Paving o Erosion Control Terrace Removed - Due to active Erosion Control Terrace	contractor installed a div N of SB D paving in the area, the t N of SB E	rersion from the stub road to S	B A prior to the 3/23/ Removed led as of the 7/15/22 in Removed	23 inspection. nspection.			
Current Condition: ET 1 Current Condition: ET 2	Good Condition - Paving o Erosion Control Terrace Removed - Due to active Erosion Control Terrace	contractor installed a div N of SB D paving in the area, the t N of SB E	ersion from the stub road to s errace will no longer be instal	B A prior to the 3/23/ Removed led as of the 7/15/22 in Removed	23 inspection. nspection.			
Current Condition: ET 1 Current Condition: ET 2 Current Condition:	Good Condition - Paving of Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Erosion Control Terrace	contractor installed a div N of SB D paving in the area, the t N of SB E paving in the area, the t N of SB B	ersion from the stub road to s errace will no longer be instal	SB A prior to the 3/23/ Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed	23 inspection. Inspection. Inspection.			
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3	Good Condition - Paving of Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Erosion Control Terrace	contractor installed a div N of SB D paving in the area, the t N of SB E paving in the area, the t N of SB B	ersion from the stub road to s errace will no longer be instal errace will no longer be instal	SB A prior to the 3/23/ Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed	23 inspection. Inspection. Inspection.			
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition:	Good Condition - Paving of Erosion Control Terrace Removed - Due to active Erosion Control Terrace Erosion Control Terrace	contractor installed a div N of SB D paving in the area, the t N of SB E paving in the area, the t N of SB B paving in the area, the t East Central	ersion from the stub road to s errace will no longer be instal errace will no longer be instal	B A prior to the 3/23/ Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed	23 inspection. Inspection. Inspection. Inspection.			
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4	Good Condition - Paving of Erosion Control Terrace Removed - Due to active Erosion Control Terrace Erosion Control Terrace	contractor installed a div N of SB D paving in the area, the t N of SB E paving in the area, the t N of SB B paving in the area, the t East Central	ersion from the stub road to S errace will no longer be instal errace will no longer be instal errace will no longer be instal errace will no longer be instal	B A prior to the 3/23/ Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed	23 inspection. Inspection. Inspection. Inspection.			
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition:	Good Condition - Paving of Erosion Control Terrace Removed - Due to active Erosion Control Matting	contractor installed a div N of SB D paving in the area, the t N of SB E paving in the area, the t N of SB B paving in the area, the t East Central paving in the area, the t Northwest Side	ersion from the stub road to S errace will no longer be instal errace will no longer be instal	B A prior to the 3/23/ Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Active	23 inspection. Inspection. Inspection. Inspection. Inspection. Inspection. Inspection. Inspection.			
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1	Good Condition - Paving of Erosion Control Terrace Removed - Due to active Erosion Control Matting	contractor installed a div N of SB D paving in the area, the t N of SB E paving in the area, the t N of SB B paving in the area, the t East Central paving in the area, the t Northwest Side rcial Seeding installed th	errace will no longer be instal errace will no longer be instal 7/15/2022 ne matting prior to the 7/15/22	B A prior to the 3/23/ Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Active	23 inspection. Inspection. Inspection. Inspection. Inspection. Inspection. Inspection. Inspection.			
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1	Good Condition - Paving of Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Commen	contractor installed a div N of SB D paving in the area, the t N of SB E paving in the area, the t N of SB B paving in the area, the t East Central paving in the area, the t Northwest Side rcial Seeding installed th	errace will no longer be instal errace will no longer be instal 7/15/2022 ne matting prior to the 7/15/22	B A prior to the 3/23/ Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Active	23 inspection. Inspection. Inspection. Inspection. Inspection. Inspection. Inspection. Inspection.			
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition:	Good Condition - Paving of Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co Erosion Control Matting	contractor installed a div N of SB D paving in the area, the t N of SB E paving in the area, the t N of SB B paving in the area, the t East Central paving in the area, the t Northwest Side rcial Seeding installed th mmercial Seeding prior North-Central	errace will no longer be instal errace will no longer be instal 7/15/2022 ne matting prior to the 7/15/22 to the 12/8/22 inspection. 7/15/2022	B A prior to the 3/23/ Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Active inspection. Portions Active	23 inspection. Ins			
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition:	Good Condition - Paving of Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co Erosion Control Matting	contractor installed a div N of SB D paving in the area, the t N of SB E paving in the area, the t N of SB B paving in the area, the t East Central paving in the area, the t Northwest Side rcial Seeding installed th mmercial Seeding prior North-Central	errace will no longer be instal errace will no longer be instal 7/15/2022 ne matting prior to the 7/15/22 to the 12/8/22 inspection.	B A prior to the 3/23/ Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Active inspection. Portions Active	23 inspection. Ins			
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition:	Good Condition - Paving of Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co Erosion Control Matting Good Condition - Comme Erosion Control Matting	contractor installed a div N of SB D paving in the area, the t N of SB E paving in the area, the t N of SB B paving in the area, the t East Central paving in the area, the t Northwest Side rcial Seeding installed th mmercial Seeding prior North-Central rcial Seeding installed th Northeast Side	ersion from the stub road to S errace will no longer be instal errace will no longer be instal errace will no longer be instal errace will no longer be instal 7/15/2022 ne matting prior to the 7/15/22 to the 12/8/22 inspection. 7/15/2022 ne matting prior to the 7/15/22 r/15/2022	B A prior to the 3/23/ Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Active inspection. Portions	23 inspection. Inspection.			
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 3	Good Condition - Paving of Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co Erosion Control Matting Good Condition - Comme Erosion Control Matting	contractor installed a div N of SB D paving in the area, the t N of SB E paving in the area, the t N of SB B paving in the area, the t East Central paving in the area, the t Northwest Side rcial Seeding installed th mmercial Seeding prior North-Central rcial Seeding installed th Northeast Side	errace will no longer be instal errace will no longer be instal 7/15/2022 ne matting prior to the 7/15/22 to the 12/8/22 inspection. 7/15/2022 ne matting prior to the 7/15/22	B A prior to the 3/23/ Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Active inspection. Portions	23 inspection. Inspection.			
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition:	Good Condition - Paving of Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Commen seeded and matted by Co Erosion Control Matting Good Condition - Commen Erosion Control Matting Good Condition - Commen Erosion Control Matting Good Condition - Commen Erosion Control Matting	contractor installed a div N of SB D paving in the area, the t N of SB E paving in the area, the t N of SB B paving in the area, the t East Central paving in the area, the t Northwest Side rcial Seeding installed th more and Seeding prior North-Central rcial Seeding installed th Northeast Side rcial Seeding installed th Northeast Side rcial Seeding installed th Southwest Corner	ersion from the stub road to S errace will no longer be instal errace will no longer be instal errace will no longer be instal errace will no longer be instal 7/15/2022 ne matting prior to the 7/15/22 to the 12/8/22 inspection. 7/15/2022 ne matting prior to the 7/15/22 ne matting prior to the 7/15/22 ne matting prior to the 7/15/22	B A prior to the 3/23/ Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Removed led as of the 7/15/22 in Active inspection. Portions Active inspection. Active inspection. Active inspection.	23 inspection. Ins			

Current Condition: FT 1 Current Condition: FT 2 Current Condition: FT 3 Current Condition: FT 4 Current Condition: FT 5	A water main extension p in the area will be tempor inspection. Water main in the area when installation seeding/matting to follow. The slope should be seed Commercial Seeding was Fuel Tank Removed - DEJ removed Fuel Tank Removed - TAB removed Fuel Tank Removed - RPL removed Fuel Tank Removed - The fuel tank Removed - The fuel tank	roject in the area will be arily halted until work is installation is active on si is complete. Additional ded/matted. Sent plans on 4/7/23. N SW Corner the fuel tank prior to the Material Storage Area the fuel tank prior to the Material Storage Area the fuel tank prior to the Material Storage Area the fuel tank prior to the Material Storage Area was removed prior to the Material Storage Area	2 4/7/22 inspection. 2 114/22 inspection. 2 5/18/22 inspection.	ection, therefore, reco be is still recommende n, water contractor wil eet to be completed ir	mmendations for matting d as of the 5/3/22 be seeding and matting	
Current Condition:	Removed - The fuel tank		e 7/8/22 inspection.	Descored		
FT 6 Current Condition:	Fuel Tank Removed - Kersten remo	On Site	the $11/4/22$ increation	Removed		
Lot 67	Individual Lot	Lot 67	4/6/2023	Active	No	
Current Condition:			n on the lot prior to the 4/6/23			
		U U	will monitor for removal and th	• •		
MS 1	Material Storage	On Site		Removed		
Current Condition:			mplete, material storage will b		by lot basis as of the	
	11/4/22 inspection.					
PB X	Portable Bathroom	On Site		Removed		
Current Condition:	Removed - RPL removed	the remaining portable	toilet from the site prior to the	11/4/22 inspection.		
SB A	Sediment Basin	X24	5/11/2022	Active	Yes	
Current Condition:	Fair Condition - 49% - Th	e basin was partially dug	out prior to the 12/1/21 inspe	ection. The basin outf	all pipe and rip rap	
	 2) The basin should be cleaned out and the slopes seeded/matted. 3) Erosion into the basin should be repaired and stabilized. 1) DEJ was informed to complete by 9/7/21. Not done as of the last inspection. Gene Graves were reminded on 10/15//10/21/21, 10/29/21, 12/2/21, 2/11/22, 3/24/22, 5/5/22, 5/27/22, 6/10/22. SID will complete during basin cleanout as of 3/2) The SID is working to identify funding to complete the basin cleanout as of 3/10/23. Not done as of the last inspectior 3) The SID is working to identify funding to complete the basin cleanout as of 3/10/23. Not done as of the last inspectior 					
	Codimont Dooin	001	E/48/2022	A stille	Vec	
SB B Current Condition:	Sediment Basin	O24	5/18/2022 partially dug out prior to the 9/	Active	Yes	
	continue to monitor. The was in the process of bein prior to the 5/18/22 inspect 1) The basin should be in 2) The basin should be cl 1) DEJ was informed to c 10/21/21, 10/29/21, 12/2/ 2) The SID is working to in	basin outfall pipe and rip ng installed during the 4/ ction. The E&A inspecto stalled (baffle). eaned out and the slope omplete by 9/7/21. Not 21, 2/11/22, 3/24/22, 5/5 dentify funding to comple	o rap appears to have been in 21/22 inspection. Dewatering or painted the cleanout mark of s seeded/matted. done as of the last inspection. /22, 5/27/22, 6/10/22. SID wi ete the basin cleanout as of 3.	stalled prior to the 4/1 holes appear to have n 5/23/22. . Gene Graves were to ll complete during bas /10/23. Not done as c	3/22 inspection. The riser been installed in the riser reminded on 10/15/21, in cleanout as of 3/23/23. If the last inspection.	
SB C	Sediment Basin	H24	5/18/2022	Active	Yes	
Current Condition:	 Fair Condition - 49% Filled - The basin was dug out prior to the 11/12/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. Dewatering holes appear to have been installed in the riser prior to the 5/18/22 inspection. The E&A inspector painted the cleanout mark on 5/23/22. 1) The basin should be installed (baffle). 2) The basin should be cleaned out and the slopes seeded/matted. 1) DEJ was informed to complete by 9/7/21. Not done as of the last inspection. Gene Graves were reminded on 10/15/21, 10/21/21, 12/2/21, 12/12, 3/24/22, 5/5/22, 5/27/22, 6/10/22. SID will complete during basin cleanout as of 3/23/23. 2) The SID is working to identify funding to complete the basin cleanout as of 3/10/23. Not done as of the last inspection. 					
	10/21/21, 10/29/21, 12/2/	21, 2/11/22, 3/24/22, 5/5	/22, 5/27/22, 6/10/22. SID wi	Il complete during bas	in cleanout as of 3/23/23.	
SB D	10/21/21, 10/29/21, 12/2/	21, 2/11/22, 3/24/22, 5/5	/22, 5/27/22, 6/10/22. SID wi	Il complete during bas	in cleanout as of 3/23/23.	

Current Condition:	pipe and rip rap appears t during the 4/21/22 inspect have been installed in the 1) Due to ground disturba 2) The basin should be cl 1) DEJ/Gene Graves wer on 12/2/21, 2/11/22, 3/24/ elevations incorrect per E	o have been installed prition. The old area inlet of riser prior to the 5/18/22 nce in the area baffle sheaned out, the correct be informed to complete P (22, 5/5/22, 5/27/22, 6/1) & A survey prior to the 7,		The riser was in the 1/22 inspection. Dewa hed, and the slopes s le last inspection. Ge installation elevation: omplete during basin o	process of being installed atering holes appear to eeded/matted. ne Graves were reminded s as of 6/9/22. Basin cleanout as of 3/23/23.
SB E	Sediment Basin	D19	5/3/2022	Active	No
Current Condition:			ally dug out prior to the 12/1/2 cleanout mark on 5/23/22.	T inspection. DEJ ins	stalled the riser prior to the
SF 1	Silt fence	Northern/Western Perimeter	5/18/2021	Active	Yes
Current Condition:	intentionally built in the not Sudbeck installed wattles maintenance prior to the 4 prior to the 4/7/22 inspect Graves repaired the silt fe was removed in multiple le inspector will monitor for r inspection. The water con prior to the 6/30/22 inspect SB D prior to the 7/8/22 ir Sudbeck repaired and ext at the SB D outfall was ob the Spring of 2023. Com Sudbeck cleaned out and damaged silt fence at the during seeding and mattin The silt fence needs to be Gene Graves was informed	orthern section of the rur as an extension of the s 4/1/22 inspection. Sudb ion. TAB repaired/reins ince along the north side ocations, including south emoval. The water con htractor removed the silt spection. Sudbeck insta spection. Sudbeck insta ended the silt fence alon oserved during the 12/1/ mercial Seeding repaired repaired the silt fence alon oserved during the 12/1/ mercial Seeding repaired repaired the silt fence alon oserved during the 12/1/ mercial Seeding repaired repaired the silt fence alon oserved during the 12/1/ mercial Seeding repaired as D outfall prior to the ag of the slope by 5/1/23 e reinstalled at the SB D ad to complete by 3/15/2 libeck to begin work by A		on, extending the silt f the 2/2/22 inspection. In the south along the r ad Street prior to the 4 e prior to the 5/26/22 in allation prior to the 6/2 reas southwest of SB sent to the construction istalled silt fence arou h side of Schram prior 19/22 inspection. Min abilization of the 72nd th of Schram prior to 1 4/6/23 inspection. Su a, Commercial Seeding spection. SID to com	ence is still recommended. Sudbeck began silt fence north side of the entrance /7/22 inspection. Gene nspection. The silt fence 4/22 inspection, the D prior to the 6/24/22 n entrance and NW of SB D nd the flared end section of r to the 9/12/22 inspection. or damage to the silt fence I Street ROW will begin in the 12/8/22 inspection. Idbeck removed the g will reinstall silt fence
SF 2 Current Condition:			5/25/2021 ence prior to the 5/25/21 insp		
			It fence with additional posts paired the silt fence in the no		
SF 3	Silt fence	Southeast Corner	5/25/2021	Active	No
Current Condition:	Good Condition - The developer installed the silt fence prior to the 5/25/21 inspection. The silt fence was partially removed for installation of the SB A outfall pipe prior to the 4/7/22 inspection. Sudbeck maintained the silt fence prior to the 6/30/22 inspection. Sudbeck began maintenance prior to the 3/30/23 inspection, the inspector will update when maintenance is complete. Sudbeck patched the silt fence at the basin outfall prior to the 4/6/23 inspection. Minor damaged silt fence remains south of SB B as of the 4/6/23 inspection, the silt fence is not needed and will be removed during grading of the property to the south.				
SF 4	Silt fence	Southwest Perimeter	5/18/2021	Active	No
Current Condition:	the Ponderosa Drive conr Ponderosa Drive damage when work is complete. S maintenance in the area is complete the majority of th high porosity silt fence ch the future Ponderosa entr reinstallation will not be re 6/24/22 inspection. Sudb removed for water installa fence will not be recomme seeding and matting of the prior to the 12/8/22 inspect	nection prior to the 10/13 d a small portion of the Sanitary excavation arous s now included below. S ne maintenance and reir ecks in the flow line of the ance along 72nd Street eccmmended. Sudbeck eck maintained the silt fi- tion prior to the 9/27/22 ended at this time. The e area will occur in mid I ption and installed perim	ence prior to the 5/18/21 insp //21 inspection. Excavation s silt fence prior to the 1/18/22 nd Ponderosa Drive appears Sudbeck began silt fence mai sstallation of the silt fence pri for storm sewer work prior to maintained the silt fence aro ence prior to the 6/30/22 insp inspection, plans for stabilizz damaged portions of silt fenc Nov. 2022. Commercial See eter silt fence in the area prior additional silt fence to protect	spoils from sanitary ex inspection, the inspect to be complete as of ntenance prior to the or to the 4/7/22 inspect spection. The silt fem the 5/18/22 inspectio und the culvert/Ponde ection. Some of the si tion are being prepar- e were removed prior ding reinstalled the sill or to the 12/8/22 inspe	cavation in the area of the will recommend repair the 2/2/22 inspection, 4/1/22 inspection. Sudbeck the subsect installed the was partially removed at n, due to imminent paving, rosa Drive prior to the silt fence was temporarily ed, reinstallation of the silt to the 11/4/22 inspection, the fence checks in the swale ction. Commercial Seeding

SF 5	Silt fence	NW corner of Lot 3 Replat 1	11/4/2022	Active	No		
Current Condition:	Good Condition - Sudbeck installed the silt fence prior to the 11/4/22 inspection. Sudbeck repaired and reinforced the silt fence prior to the 3/30/23 inspection.						
SF 6	Silt fence	NE S 70th and Flint	11/10/2022	Active	No		
Current Condition:	Good Condition - Sudbeck installed the silt fence prior to the 11/10/22 inspection. Gene Graves maintained the silt fence prior to the 3/23/23 inspection.						
SF 7	Silt fence	NE S 70th and Stony	11/10/2022	Active	No		
Current Condition:	Good Condition - Sudbeck installed the silt fence prior to the 11/10/22 inspection. Gene Graves maintained the silt fence prior to the 3/23/23 inspection.						
SF 8	Silt fence	NW of SB C	12/8/2022	Active	No		
Current Condition:	Good Condition - Comme	rcial Seeding installed th	e silt fence prior to the 12/8	/22 inspection.			
SF 9	Silt fence	SW Corner of 72nd and Schram	12/8/2022	Active	Yes		
Current Condition:	Fair Condition - Commerce	ial Seeding installed the	silt fence prior to the 12/8/2	2 inspection.			
		eding/matting work along	72nd as of 3/10/23. Not do		ction. Plans sent to		
STR	Streets	S 72nd Street	5/18/2021	Active	No		
Current Condition:			ing the most recent inspecti		-		
SW 1	Straw Wattles	72nd ROW	3	Removed			
Current Condition:		Removed - Sudbeck removed the wattles during grading prior to the 4/6/23 inspection. The slope will be seeded and matted b 5/1/23, wattles are no longer needed. Silt fence is in place where necessary.					
SWPPP Sign	Misc/Other	S 72nd and Schram	5/18/2021	Active	No		
Current Condition:	Good Condition - The E&A inspector installed the SWPPP sign in the southwest corner of the property during the 5/18/21 inspection.						
WO 1	Concrete Washout	On Site		Removed			
Current Condition:		ned up the remaining co	ncrete waste on site prior to	the 11/4/22 inspection			
WS 1	Waste Storage	On Site	, · · · ·	Removed			
Current Condition:	Removed - Waste storage of concrete, construction materials, portable toilets are covered under separate BMPs in the BMP section.						
Certification Statement:	accordance with a system submitted. Based on my in gathering the information,	designed to assure that nquiry of the person or p the information submitte	and all attachments were pr t qualified personnel property ersons who manage the sys ed is, to the best of my know ubmitting false information ir	y gathered and evaluat stem or those persons rledge and belief, true,	ted the information directly responsible for accurate, and complete. I		
Inspector Signature:	Jule Gant			Reviewed By:	Coto Sur		