E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

E&A - P2018.228.001 Bill SID as of 2/17/22 P2018.228.000

		Bill SID as of 2/17	7/22 P2018.228.000				
Inspector: Jason Brackett		Stage					
		Seventy Two Place					
		-			1		
			PAP-20200624-5346-GP1				
Project Name:		CSW-202004796					
For Week Ending:		9/3	30/2023				
Project Location:		12101 S 72nd St, Papillion, Sarpy County, NE					
Grading:	80%						
Sanitary Sewer:	100%						
Storm Sewer:	95%						
Paving:	80%						
Seeding:	75%						
Utilities:	80%						
Overall Development:	46%						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time			
					Week 1		
Sunday:	0.00"						
Monday:	0.00"						
Tuesday:	0.00"						
Wednesday:	0.00"						
Thursday:	0.00"	9/28/2023	Mostly Sunny 87/65	10:05 AM			
Friday:	0.00"						
Saturday:	0.00"						
Commisinto	Nana						
Complaints:	None.						

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Rough grading began (6/15/21). Excavation for sanitary installation (9/28/21). Grading ceased due to winter conditions (1/5/22). Excavation for utility connections along 72nd (2/8/22). Grading for roadways (6/9/22). Lot 3 Replat 1 and Lot 4 Replat 1 scraping (11/2/22). Riprap installation and regrading at S 70th Street stub (11/2/22). Swale and ROW along Ponderosa connection finish graded (11/4/22). Swale and ROW along Ponderosa grading ceased (12/1/22). Basin cleanouts and processing silt began (8/3/23).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading began (6/15/21). Excavation for sanitary installation (9/28/21). Grading ceased due to winter conditions (1/5/22). Excavation for utility connections along 72nd (2/8/22). Grading for roadways (6/9/22). Lot 3 Replat 1 and Lot 4 Replat 1 scraping (11/2/22). Riprap installation and regrading at S 70th Street stub (11/2/22). Swale and ROW along Ponderosa connection finish graded (11/4/22). Swale and ROW along Ponderosa grading ceased (12/1/22). Basin cleanouts and processing silt began (8/3/23).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (6/15/21). Disking/seeding east side of site (7/8/22). Lot 1, 2, 3 - seeded (11/10/22). Seeding and matting swale and ROW along Ponderosa and Schram/72nd medians and ROWs (12/8/22).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action

N/A
Are construction entrances and adjacent streets being maintained adequately?
Yes
Create Corrective Action?
N/A

s dust associated with the construction activity adequately controlled on the site?

Yes

N/A

Comments:

The site was inactive during the most recent inspection. Lot 5 and 6 Replat 1 have been removed from this SWPPP and are covered by PAP-20220310-6351-

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section of this report.
- 2) CIR 20147 was received, reviewed, and forwarded to Papio Park, LLC. The City Inspector recommends inlet protection along Schram Road. The E&A inspector contacted Commercial Seeding to install inlet filters on 9/28/23.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance	
05.4	•		Projected install Date		Waintenance	
CE 1	Construction Entrance	Schram Road		Removed	1	
Current Condition:	Removed - The entrance will no longer be used as of the 8/29/22 inspection due to the completion of the Schram Road					
	connection.					
D 1	Diversion	E of SB C	11/12/2021	Active	No	
Current Condition:			to the 11/12/21 inspection. S			
			maintained the diversion prio			
	removed at the S 70th stub prior to the 8/29/22 inspection, the inspector will monitor the need for reinstallation.					
D 2	Diversion	S of SB D		Removed		
Current Condition:	Removed - Due to addition	nal BMPs installed for th	ne Vestara Apartments, the di	version no longer nee	ds to be installed as o	
	6/8/23 inspection.		•	· ·		
D 3	Diversion	N of SB D	6/8/2023	Active	No	
Current Condition:			rior to the 6/8/23 inspection. T			
			air will be completed during ba		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
D 4	Diversion	E and SB B	7/8/2022	Active	No	
Current Condition:			prior to the 7/8/22 inspection.	7101170	110	
D 5	Diversion	Northwest Perimeter	prior to the 170/22 mepocheri.	Removed		
Current Condition:			sisting contours as of the 5/3/2		1	
D 6	Diversion	Western Perimeter		Removed		
Current Condition:	Removed - The remaining portions of Schram have been installed as of the 3/23/23 inspection. Recommendations for swale					
	regrading are included in the Findings section of this report.					
D 7	Diversion	Stub to SB A	3/23/2023	Active	No	
Current Condition:	Fair Condition - Paving contractor installed a diversion from the stub road to SB A prior to the 3/23/23 inspection. The diversion from the stub road to SB A prior to the 3/23/23 inspection. The diversion from the stub road to SB A prior to the 3/23/23 inspection.					
	IFair Condition - Paying co	ntractor installed a dive	rsion from the stub road to SE	3 A prior to the 3/23/2	3 inspection. The dive	
			rsion from the stub road to SE or to the 8/3/23 inspection, rep			
D 8						
D 8 Current Condition:	was temporarily filled in du	uring basin cleanout prio		eair will be completed Removed	during basin grading.	
	was temporarily filled in du	uring basin cleanout prio	or to the 8/3/23 inspection, rep	eair will be completed Removed	during basin grading.	
Current Condition:	was temporarily filled in do Diversions Removed - Due to utility ir Erosion Control Terrace	SB E stallation, the diversion N of SB D	or to the 8/3/23 inspection, rep	Removed d as of the 6/8/23 insp Removed	during basin grading.	
Current Condition: ET 1	was temporarily filled in do Diversions Removed - Due to utility ir Erosion Control Terrace	SB E stallation, the diversion N of SB D	or to the 8/3/23 inspection, reposition of the state of t	Removed d as of the 6/8/23 insp Removed	during basin grading.	
Current Condition: ET 1 Current Condition:	was temporarily filled in do Diversions Removed - Due to utility ir Erosion Control Terrace Removed - Due to active Erosion Control Terrace	SB E stallation, the diversion N of SB D paving in the area, the t N of SB E	or to the 8/3/23 inspection, reposition of the state of t	Removed d as of the 6/8/23 insp Removed ded as of the 7/15/22 i Removed	during basin grading. Dection. Inspection.	
Current Condition: ET 1 Current Condition: ET 2	was temporarily filled in do Diversions Removed - Due to utility ir Erosion Control Terrace Removed - Due to active Erosion Control Terrace	SB E stallation, the diversion N of SB D paving in the area, the t N of SB E	or to the 8/3/23 inspection, reposition of the state of t	Removed d as of the 6/8/23 insp Removed ded as of the 7/15/22 i Removed	during basin grading. Dection. Inspection.	
Current Condition: ET 1 Current Condition: ET 2 Current Condition:	was temporarily filled in do Diversions Removed - Due to utility ir Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Erosion Control Terrace	SB E Installation, the diversion N of SB D Daving in the area, the to N of SB E Daving in the area, the to N of SB E Daving in the area, the to N of SB B	or to the 8/3/23 inspection, reposition of the state of t	Removed d as of the 6/8/23 insp Removed led as of the 7/15/22 i Removed led as of the 7/15/22 i Removed	during basin grading.	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3	was temporarily filled in do Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Erosion Control Terrace	SB E Installation, the diversion N of SB D Installation the area, the area, the the area, the are	or to the 8/3/23 inspection, report to the 8/3/23 inspection, report of the state o	Removed d as of the 6/8/23 insp Removed ed as of the 7/15/22 i Removed	during basin grading.	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition:	was temporarily filled in do Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Erosion Control Terrace	SB E Installation, the diversion N of SB D Installation the area, the area, the the area, the are	or to the 8/3/23 inspection, report to the 8/3/23 inspection, report is are no longer recommended. Lerrace will no longer be install lerrace will no longer be install	Removed d as of the 6/8/23 insp Removed ed as of the 7/15/22 i Removed	during basin grading.	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4	was temporarily filled in do Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace	SB E Installation, the diversion N of SB D Deaving in the area, the t N of SB E Daving in the area, the t N of SB B Daving in the area, the t East Central Daving in the area, the t East Central Daving in the area, the t Northwest Side	or to the 8/3/23 inspection, report to the 8/3/23 inspection, report of the 8/3/23 inspection report of the 8/3/	Removed d as of the 6/8/23 insp Removed ed as of the 7/15/22 i Active	during basin grading.	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition:	was temporarily filled in do Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace	SB E Installation, the diversion N of SB D Deaving in the area, the t N of SB E Daving in the area, the t N of SB B Daving in the area, the t East Central Daving in the area, the t East Central Daving in the area, the t Northwest Side	or to the 8/3/23 inspection, report to the 8/3/23 inspection, report of the state o	Removed d as of the 6/8/23 insp Removed ed as of the 7/15/22 i Active	during basin grading. bection.	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1	was temporarily filled in do Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace	SB E Installation, the diversion N of SB D Deaving in the area, the t N of SB E Daving in the area, the t N of SB B Daving in the area, the t East Central Daving in the area, the t East Central Daving in the area, the t Northwest Side roial Seeding installed the	or to the 8/3/23 inspection, report to the 8/3/23 inspection, report of the 8/3/23 inspection report of the 8	Removed d as of the 6/8/23 insp Removed ed as of the 7/15/22 i Active	during basin grading. bection.	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition:	was temporarily filled in du Diversions Removed - Due to utility ir Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Commes seeded and matted by Co Erosion Control Matting	SB E Installation, the diversion IN of SB D IN of SB D IN of SB E IN of SB E IN of SB B	or to the 8/3/23 inspection, report to the 8/3/23 inspection, report of the 8/3/23 inspection.	Removed d as of the 6/8/23 insp Removed led as of the 7/15/22 i Active Inspection. Portions	during basin grading. bection.	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition:	was temporarily filled in descriptions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Commes seeded and matted by Co Erosion Control Matting Good Condition - Commes	SB E Installation, the diversion IN of SB D Installation, the diversion IN of SB D Installation in the area, the text of SB E Installation in the area, the text of SB B Installation in the area, th	or to the 8/3/23 inspection, report to the 8/3/23 inspection, report of the 8/3/23 inspection. 7/15/2022 The matting prior to the 7/15/22 in the 12/8/22 inspection. 7/15/2022 The matting prior to the 7/15/22 in the 12/8/22 inspection.	Removed d as of the 6/8/23 insp Removed led as of the 7/15/22 i Active Inspection. Portions	during basin grading.	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition:	was temporarily filled in descriptions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Commes seeded and matted by Co Erosion Control Matting Good Condition - Commes	SB E Installation, the diversion In N of SB D Installation in the area, the teleprocess of SB E	or to the 8/3/23 inspection, report to the 8/3/23 inspection, report of the 8/3/23 inspection, report of the 8/3/23 inspection, report of the 8/3/23 inspection. The matting prior to the 7/15/22 to the 12/8/22 inspection. The matting prior to the 7/15/22 to the 12/8/22 inspection. The matting prior to the 7/15/22 to the 17/15/2022 the matting prior to the 7/15/22 to the 7/15/202	Removed d as of the 6/8/23 insp. Removed ed as of the 7/15/22 i Active inspection. Active	during basin grading.	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition:	was temporarily filled in descriptions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Commes seeded and matted by Co Erosion Control Matting Good Condition - Comme Erosion Control Matting Good Condition - Comme	SB E Installation, the diversion IN of SB D Installation, the diversion IN of SB D Installation, the diversion IN of SB B Installation the area, the true IN of SB B Installation the area, the true IN of SB B Installation the area, the true IN of SB B Installation the area, the true IN of SB B Installation the area, the true IN orthwest Side Installation the area, the true IN ortheoretical Seeding installation the area of t	or to the 8/3/23 inspection, report to the 8/3/23 inspection, report of the 8/3/23 inspection, report of the 8/3/23 inspection, report of the 8/3/23 inspection in the 8/3/23 inspection.	Removed d as of the 6/8/23 insp. Removed ed as of the 7/15/22 i Active inspection. Active	during basin grading.	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 2 Current Condition: EM 3	was temporarily filled in descriptions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Commes seeded and matted by Co Erosion Control Matting Good Condition - Commes	SB E Installation, the diversion IN of SB D Installation, the diversion IN of SB D Installation, the diversion IN of SB B Installation the area, the true IN of SB B Installation the area, the true IN of SB B Installation the area, the true IN of SB B Installation the area, the true IN of SB B Installation the area, the true IN orthwest Side Installation the area, the true IN ortheoretical Seeding installation the area of t	or to the 8/3/23 inspection, report to the 8/3/23 inspection, report of the 8/3/23 inspection, report of the 8/3/23 inspection, report of the 8/3/23 inspection in the 8/3/23 inspection.	Removed d as of the 6/8/23 insp. Removed ed as of the 7/15/22 i Active inspection. Active	during basin grading.	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 2 Current Condition: EM 3	was temporarily filled in descriptions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Commes seeded and matted by Co Erosion Control Matting Good Condition - Comme Erosion Control Matting Good Condition - Comme	SB E Installation, the diversion IN of SB D Installation, the diversion IN of SB D Installation, the diversion IN of SB B Installation the area, the true IN of SB B Installation the area, the true IN of SB B Installation the area, the true IN of SB B Installation the area, the true IN of SB B Installation the area, the true IN orthwest Side Installation the area, the true IN ortheoretical Seeding installation the area of t	or to the 8/3/23 inspection, report to the 8/3/23 inspection, report of the 8/3/23 inspection, report of the 8/3/23 inspection, report of the 8/3/23 inspection in the 8/3/23 inspection.	Removed d as of the 6/8/23 insp. Removed ed as of the 7/15/22 i Active inspection. Active	during basin grading.	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 2 Current Condition: EM 3 Current Condition:	was temporarily filled in descriptions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Commeseeded and matted by Co Erosion Control Matting Good Condition - Commeserosion Control Matting Good Condition - Commeseeding and matting prior Erosion Control Matting	SB E Installation, the diversion IN of SB D Installation, the diversion IN of SB D Installation, the diversion IN of SB B Installation the area, the true IN of SB B Installation the area, the true IN of SB B Installation the area, the true IN of SB B Installation the area, the true IN of SB B Installation the area, the true IN of SB B Installation the area, the true IN of SB B Installation the area, the true IN of SB B Installation the area, the true In order the area, the	or to the 8/3/23 inspection, report to the 8/3/23 inspection, report of the 8/3/23 inspection, report of the 8/3/23 inspection, report of the 8/3/23 inspection of the 8/3/23 inspection.	Removed d as of the 6/8/23 insp. Removed ed as of the 7/15/22 i Active inspection. Portions Active inspection. Sudbeck Active	during basin grading.	

Current Condition:	Good Condition - The erosion control matting will be installed within the seeding window when the associated area reaches final grade. A water main extension project in the area will begin soon as of the 5/3/22 inspection, therefore, recommendations for matting in the area will be temporarily halted until work is complete. Seeding of the slope is still recommended as of the 5/3/22 inspection. Water main installation is active on site as of the 8/29/22 inspection, water contractor will be seeding and matting the area when installation is complete. Additional finish grading along 72nd Street to be completed in the Spring of 2023, seeding/matting to follow. Commercial Seeding seeded/matted the slope prior to the 4/20/23 inspection. Commercial Seeding repaired the erosion and re-seeded/matted the slope prior to the 5/4/23 inspection.						
FT 1	Fuel Tank	SW Corner	i i	Removed			
Current Condition:	Removed - DEJ removed the fuel tank prior to the 7/15/22 inspection.						
FT 2	Fuel Tank Material Storage Area Removed						
Current Condition:	Removed - TAB removed	•	e 4/7/22 inspection.				
FT 3	Fuel Tank	Material Storage Area	·	Removed			
Current Condition:	Removed - RPL removed the fuel tank prior to the 114/22 inspection.						
FT 4	Fuel Tank Material Storage Area Removed						
Current Condition:	Removed - The fuel tank		e 5/18/22 inspection.	T			
FT 5	Fuel Tank	Material Storage Area		Removed			
Current Condition:	Removed - The fuel tank		e 7/8/22 inspection.				
FT 6	Fuel Tank	On Site	1 11/1/02:	Removed			
Current Condition:	Removed - Kersten removed			D	V		
TEMP IPs XX Current Condition:	Inlet Protection Pending -	Schram Road	10/5/2023	Pending	Yes		
	Commercial Seeding wa	as informed to comple					
Lot 67	Individual Lot	Lot 67	4/6/2023	Active	No		
Current Condition:			n on the lot prior to the 4/6/23 will monitor for removal and the				
MS 1	Material Storage	On Site		Removed			
Current Condition:	Removed - Civil overlot de 11/4/22 inspection.	evelopment is mostly co	mplete, material storage will b	e addressed on a lot	by lot basis as of the		
PB X	Portable Bathroom	On Site		Removed			
Current Condition:			toilet from the site prior to the				
SB A	Sediment Basin	X24	5/11/2022	Active	Yes		
SB B Current Condition:	Fair Condition - 6% - The basin was partially dug out prior to the 12/1/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was installed prior to the 5/11/22 inspection. The basin was reshaped prior to the 5/26/22 inspection. The E&A inspector painted the cleanout mark on 5/23/22. The erosion into the basin are the only stormwater diversions to the basin and should remain in place as of the 6/8/23 inspection, additional grading will address these diversions when construction on the eastern phase begins. Basin cleanout began prior to the inspection on 7/20/23. The basin was cleaned out prior to the 7/27/23 inspection. 1) The baffle should be installed. 2) The basin slopes should be seeded/matted. 1) The baffle will be installed as part of basin cleanouts as of 3/10/23. Not done as of the last inspection. Plans are under review by the design engineer as of 6/5/23. RFP sent to contractors 6/21/23. Contractor hired on 6/30/23, work to resume after the July 4th holiday. 2) The SID is working to identify funding to complete the basin cleanout as of 3/10/23. Not done as of the last inspection. Plans are under review by the design engineer as of 6/5/23. RFP sent to contractors 6/21/23. Contractor hired on 6/30/23, work to resume after the July 4th holiday. Sediment Basin O24 5/18/2022 Active Yes Fair Condition - 6% Filled - The basin had been partially dug out prior to the 9/14/21 inspection by DEJ, the inspector will continue to monitor. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. Dewatering holes appear to have been installed in the riser prior to the 5/18/22 inspection. The E&A inspector painted the cleanout mark on 5/23/22. DEJ cleaned out the basin prior to the 6/29/23 inspection.						
	2) The basin slopes should be seeded/matted. 1) The baffle will be installed as part of basin cleanouts as of 3/10/23. Not done as of the last inspection. Plans are under review by the design engineer as of 6/5/23. Contractor hired, equipment on site as of 6/22/23. Work in progress as of the 6/29/23 inspection. 2) DEJ to complete as part of scope of work for basin cleanouts as of 6/30/23. Not done as of the last inspection.						
SB C	Sediment Basin	H24	5/18/2022	Active	Yes		
250	Codmining Dubin	1147	O/ TO/ LULL	7.0000	100		

Current Condition:	Fair Condition - 6% Filled - The basin was dug out prior to the 11/12/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. Dewatering holes appear to have been installed in the riser prior to the 5/18/22 inspection. The E&A inspector painted the cleanout mark on 5/23/22. DEJ cleaned out the basin prior to the 6/29/23 inspection. 1) The baffle should be installed. 2) The basin slopes should be seeded/matted.						
	1) The baffle will be installed as part of basin cleanouts as of 3/10/23. Not done as of the last inspection. Plans are under review by the design engineer as of 6/5/23. Contractor hired, equipment on site as of 6/22/23. Work in progress as of the 6/29/23 inspection.						
SB D	2) DEJ to complete as part of scope of work for basin cleanouts as of 6/30/23. Not done as of the last inspection.						
Current Condition:	Sediment Basin H22 5/18/2022 Active Yes Fair Condition - 6% Filled - The basin was in the process of being dug out during the 11/4/21 inspection. The basin outfall p and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed du the 4/21/22 inspection. The old area inlet was removed prior to the 4/21/22 inspection. Dewatering holes appear to have be installed in the riser prior to the 5/18/22 inspection. The basin was in the process of being cleaned out during the 7/27/23 inspection. The basin was cleaned out and the correct depth achieved as of the 8/3/23 inspection.						
	 The baffle should be ins The basin slopes should The baffle will be install 	d be seeded/matted.	nouts as of 3/10/23. Not done	e as of the last inspect	ion. Plans are under		
	after the July 4th holiday.		sent to contractors 6/21/23.				
00.5			asin cleanouts as 8/3/23. Not	·			
SB E Current Condition:	Sediment Basin Good Condition - 8% Fille	D19 d - The basin was partia	5/3/2022 ally dug out prior to the 12/1/2	Active 1 inspection. DEJ ins	No talled the riser prior to the		
	·	A inspector painted the Northern/Western	cleanout mark on 5/23/22.				
SF 1	Silt fence	Perimeter	5/18/2021 ence prior to the 5/18/21 insp	Active	No		
	4/7/22 inspection. The silt fence was removed in multiple locations, including southwest of SB D, for water installation prior to the 6/24/22 inspection. The water contractor removed the silt fence where damaged adjacent to the construction entrance and NW of SB D prior to the 6/30/22 inspection. Sudbeck installed silt fence around the flared end section of SB D prior to the 7/8/22 inspection. Sudbeck installed silt fence along the north side of Schram prior to the 9/12/22 inspection. Sudbeck repaired and extended the silt fence along 72nd Street prior to the 9/19/22 inspection. Commercial Seeding repaired/reinstalled the silt fence north of Schram prior to the 12/8/22 inspection. Commercial Seeding reinstalled the silt fence at the outfall prior to the 4/20/23 inspection. Sudbeck installed additional silt fence along the top of the slope southeast of 72nd and Schram prior to the 6/8/23 inspection. Papio Park LLC repaired the silt fence at the top of the slope prior to the 8/10/23 inspection.						
SF 2	Silt fence	Northeastern Perimeter	5/25/2021	Active	No		
Current Condition:	Fair Condition - The developer installed the silt fence prior to the 5/25/21 inspection. Sudbeck reinforced the silt fence with additional posts in the northeast corner of the site. Sudbeck removed the silt fence in upgradient areas and repaired the silt fence in the northeast corner of the site prior to the 4/6/23 inspection. Sudbeck reinstalled the silt fence and new silt fence checks prior to the 6/8/23 inspection. The silt fence was damaged by excessive water from the adjoining property prior to the 6/22/23 inspection, repair is not recommended at this time, remaining control will be addressed during grading of Phase II.						
SF 3	Silt fence	Southeast Corner	5/25/2021	Active	No		
Current Condition:	Good Condition - The developer installed the silt fence prior to the 5/25/21 inspection. The silt fence was partially removed for installation of the SB A outfall pipe prior to the 4/7/22 inspection. Minor damaged silt fence remains south of SB B as of the 4/6/23 inspection, the silt fence is not needed and will be removed during grading of the property to the south. The silt fence was partially burned down during a crop fire prior to the 4/20/23 inspection. Sudbeck reinstalled the silt fence prior to the 6/8/23 inspection.						
SF 4	Silt fence	Southwest Perimeter	5/18/2021	Active	No		
Current Condition:	Good Condition - The developer installed the silt fence prior to the 5/18/21 inspection. Gene Graves installed silt fence around the Ponderosa Drive connection prior to the 10/13/21 inspection. Sudbeck installed high porosity silt fence checks in the flow line of the swale prior to the 4/7/22 inspection. The silt fence was partially removed at the future Ponderosa entrance along 72nd Street for storm sewer work prior to the 5/18/22 inspection. Some of the silt fence was temporarily removed for water installation prior to the 9/27/22 inspection. The damaged portions of silt fence were removed prior to the 11/4/22 inspection. Commercial Seeding reinstalled the silt fence checks in the swale prior to the 12/8/22 inspection and installed perimeter silt fence in the area prior to the 12/8/22 inspection. Commercial Seeding reinforced the silt fence in the swale and installed additional silt fence to protect the drainage prior to the 3/30/23 inspection. Commercial Seeding cleaned out and repaired the silt fence checks north of the culvert and installed additional protection prior to the 5/4/23 inspection. The silt fence in the swale along Ponderosa is in fair condition as of the 5/4/23 inspection; however, to avoid disturbing growing vegetation, no maintenance is recommended at this time. OPPD damaged and removed portions of the silt fence prior to the 5/18/23 inspection, additional repairs will be recommended after OPPD work is complete. Papio Park LLC cleaned out the silt fence south of Ponderosa Drive prior to the 8/10/23 inspection. Commercial Seeding repaired/reinstalled the silt fence north of Ponderosa Drive prior to the 8/10/23 inspection.						
SF 5	Silt fence	NW corner of Lot 3	11/4/2022	Active	Yes		

Current Condition:	Fair Condition - Sudbeck installed the silt fence prior to the 11/4/22 inspection. Sudbeck repaired and reinforced the silt fence prior to the 3/30/23 inspection. Sudbeck extended and repaired the silt fence prior to the 6/8/23 inspection. OPPD damaged and removed portions of the silt fence prior to the 6/8/23 inspection, additional repairs will be recommended after OPPD work is complete. Commercial Seeding repaired the silt fence prior to the 8/17/23 inspection. The silt fence was damaged during sidewalk installation and needs to be repaired.					
	The contractor will be in	nformed to complete w	hen construction is finishe	ed as of the 9/28/23 in	spection.	
SF 6	Silt fence	NE S 70th and Flint	11/10/2022	Active	No	
Current Condition:	Good Condition - Sudbeck installed the silt fence prior to the 11/10/22 inspection. OPPD damaged and removed portions of the silt fence prior to the 6/15/23 inspection, additional repairs will be recommended after OPPD work is complete. Commercial Seeding repaired the silt fence prior to the 8/17/23 inspection.					
SF 7	Silt fence	NE S 70th and Stony	11/10/2022	Active	No	
Current Condition:	Good Condition - Sudbeck installed the silt fence prior to the 11/10/22 inspection. OPPD damaged and removed portions of the silt fence prior to the 6/15/23 inspection, additional repairs will be recommended after OPPD work is complete. Commercial Seeding repaired the silt fence prior to the 8/17/23 inspection.					
SF 8	Silt fence	NW of SB C	12/8/2022	Active	No	
Current Condition:	Fair Condition - Commercial Seeding installed the silt fence prior to the 12/8/22 inspection. OPPD damaged and removed portions of the silt fence prior to the 6/8/23 inspection, additional repairs will be recommended after OPPD work is complete. Due to utility work as of the 8/17/23 inspection, the silt fence will not be repaired; the area is well vegetated and the silt fence will be removed when work is complete.					
SF 9	Silt fence	SW Corner of 72nd and Schram	12/8/2022	Active	Yes	
		ed during sidewalk insta	illation and needs to be repai		n.	
STR	Streets	S 72nd Street	5/18/2021	Active	No	
Current Condition:	Good Condition - Sudbeck cleaned the streets prior to the 8/3/23 inspection. DEJ cleaned the streets prior to the 8/3/23 inspection. Papio Park LLC cleaned the streets prior to the 8/10/23 inspection.					
SW 1	Straw Wattles	72nd ROW		Removed		
Current Condition:			grading prior to the 4/6/23 ins in place where necessary.	pection. The slope wi	ll be seeded and matted by	
SWPPP Sign	Misc/Other	S 72nd and Schram	5/18/2021	Active	No	
Current Condition:			SWPPP sign in the southwe led at S 72st Street and Schr			
WO 1	Concrete Washout	On Site		Removed		
Current Condition:			ncrete waste on site prior to t			
WS1	Waste Storage	On Site		Removed		
Current Condition:	Removed - Waste storage section.	e of concrete, constructi	on materials, portable toilets	are covered under sep	parate BMPs in the BMP	
Certification Statement:	accordance with a system submitted. Based on my i gathering the information,	n designed to assure that nquiry of the person or p the information submitte	and all attachments were pro t qualified personnel properly persons who manage the syst ed is, to the best of my knowl ubmitting false information in	gathered and evaluate em or those persons of edge and belief, true, a	ed the information directly responsible for accurate, and complete. I	
Inspector Signature:	Jule Gart			Reviewed By:	G. to S. s.	