E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

E&A - P2018.228.001

		BIII SID as OI 2/ I	1122 F2010.220.000		
Inspector: Jason Bracket	t	Stage			
		Sevent	y Two Place		•
			0624-5346-GP1		1
			·202004796		l
Project Name:					
For Week Ending:		10	/28/2023		
Project Location:		12101 S 72nd St, P	apillion, Sarpy County, NE		68046
Grading:	80	0%			
Sanitary Sewer:	100	0%			
Storm Sewer:	95	5%			
Paving:	80	0%			
Seeding:	75	5%			
Utilities:	80	0%			
Overall Development:	4	7%			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week '
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"				
Wednesday:	0.01"				
Thursday:	0.12"	10/26/2023	Cloudy 74/37	11:05 AM	
Friday:	0.00"				
Saturday:	0.00"				
Complaints:	None.				

Construction Sequencing:

Vhich portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Rough grading began (6/15/21). Excavation for sanitary installation (9/28/21). Grading ceased due to winter conditions (1/5/22). Excavation for utility connections along 72nd (2/8/22). Grading for roadways (6/9/22). Lot 3 Replat 1 and Lot 4 Replat 1 scraping (11/2/22). Riprap installation and regrading at S 70th Street stub (11/2/22). Swale and ROW along Ponderosa connection finish graded (11/4/22). Swale and ROW along Ponderosa grading ceased (12/1/22). Basin cleanouts and processing silt began (8/3/23). Basin cleanouts completed (10/26/23). Sidewalk paving began (10/26/23).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading began (6/15/21). Excavation for sanitary installation (9/28/21). Grading ceased due to winter conditions (1/5/22). Excavation for utility connections along 72nd (2/8/22). Grading for roadways (6/9/22). Lot 3 Replat 1 and Lot 4 Replat 1 scraping (11/2/22). Riprap installation and regrading at S 70th Street stub (11/2/22). Swale and ROW along Ponderosa connection finish graded (11/4/22). Swale and ROW along Ponderosa grading ceased 12/1/22). Basin cleanouts and processing silt began (8/3/23). Basin cleanouts completed (10/26/23). Sidewalk paving began (10/26/23)

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (6/15/21). Disking/seeding east side of site (7/8/22). Lot 1, 2, 3 - seeded (11/10/22). Seeding and matting swale and ROW along Ponderosa and Schram/72nd medians and ROWs (12/8/22).

Checklist Questions:

e receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

reate Corrective Action?

N/A

Create Corrective Action?
No, see BMPs section.

re waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

N/A					
Are construction entrances and adja	acent streets being maintained	adequately?			
Yes					
Create Corrective Action?					
N/A					
Is dust associated with the construction	ction activity adequately contro	olled on the site?			
Yes					
Create Corrective Action?					
N/A					
Comments:					
Comments:					
The site was inactive during the	ne most recent inspection.	Lot 5 and 6 Replat 1 have	ve been removed from this S\	NPPP and are covere	d by PAP-20220310-6351-
GP1.					
Findings / Corrective Actions	s (Date):				
Findings / Corrective Actions	s (Date):				
1) Some maintenance is requir		nis report.			
2) Areas of sidewalk constructi			construction is complete. The	ne E&A inspector inqu	ired with the construction
observer about timeline as of the					
dormant seed and mat after	· ·	, , , , , , , , , , , , , , , , , , ,	pian		n graamig and mon
	g. caa top ac.rc.				
Hadama Nama	T	Lacation	Basis de desarroll Barre	01-1	84-1-1
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance

		0 - 0 -		Removed		
CE 1	Construction Entrance	Schram Road		Removed		
Current Condition:	Removed - The entrance	will no longer be used a	as of the 8/29/22 inspection du	e to the completion of	the Schram Road	
	Removed - The entrance will no longer be used as of the 8/29/22 inspection due to the completion of the Schram Road connection.					
D 1	Diversion	E of SB C	11/12/2021	Active	No	
Current Condition:			r to the 11/12/21 inspection. S			
Current Condition.			maintained the diversion price			
	· ·	•	spection, the inspector will me	•		
		•	T	,	I	
D 2	Diversion	S of SB D		Removed	de te les installed es ef t	
Current Condition:	Removed - Due to additional BMPs installed for the Vestara Apartments, the diversion no longer needs to be installed as of the					
D 3	6/8/23 inspection.	N -4 CD D	6/8/2023	A -4i	No	
	Diversion Condition Sudhad	N of SB D	prior to the 6/8/23 inspection.	Active		
Current Condition:				•	,	
	cleanout prior to the 8/3/23 inspection. The diversion does not need to be reinstalled where removed as of the 10/12/23					
D 4	inspection.	E 100 D	7/0/0000	A - C		
D 4	Diversion	E and SB B	7/8/2022	Active	No	
Current Condition:			prior to the 7/8/22 inspection.		1	
D 5	Diversion	Northwest Perimeter	:- t'	Removed		
Current Condition:			xisting contours as of the 5/3/2		1	
D 6	Diversion	Western Perimeter		Removed		
Current Condition:			ve been installed as of the 3/2	3/23 inspection. Rec	ommendations for swale	
	regrading are included in			T		
			2/22/2022	Active	Yes	
D 7 Current Condition:	was partially filled in durin	g basin cleanout prior to	3/23/2023 resion from the stub road to SE to the 8/3/23 inspection, repair	3 A prior to the 3/23/2 will be completed dur	3 inspection. The diversing basin grading.	
	Fair Condition - Paving co was partially filled in durin The diversion needs to be	ontractor installed a dive g basin cleanout prior to e reinstalled.	rsion from the stub road to SE	3 A prior to the 3/23/2 will be completed dur	3 inspection. The diversing basin grading.	
Current Condition:	Fair Condition - Paving oc was partially filled in durin The diversion needs to be DEJ was informed to com	ontractor installed a dive g basin cleanout prior to e reinstalled. plete as part of the scop	rsion from the stub road to SE to the 8/3/23 inspection, repair	3 A prior to the 3/23/2: will be completed dur one as of the last inspe	3 inspection. The diversing basin grading.	
Current Condition: D 8	Fair Condition - Paving oc was partially filled in durin The diversion needs to be DEJ was informed to com Diversions	ontractor installed a dive g basin cleanout prior to e reinstalled. plete as part of the scop SB E	or the 8/3/23 inspection, repair to the 8/3/23 inspection to the 8/3/	A prior to the 3/23/2: will be completed dur one as of the last inspe	3 inspection. The diversing basin grading.	
Current Condition: D 8 Current Condition:	Fair Condition - Paving oc was partially filled in durin The diversion needs to be DEJ was informed to com Diversions Removed - Due to utility in	phtractor installed a diverge basin cleanout prior to be reinstalled. plete as part of the scope SB E stallation, the diversion	rsion from the stub road to SE to the 8/3/23 inspection, repair	A prior to the 3/23/2: will be completed dur one as of the last inspector Removed d as of the 6/8/23 insp	3 inspection. The diversing basin grading.	
D 8 Current Condition: ET 1	Fair Condition - Paving or was partially filled in durin The diversion needs to be DEJ was informed to com Diversions Removed - Due to utility in Erosion Control Terrace	photractor installed a divergence of the score of the sco	pe of work on 10/5/23. Not do	A prior to the 3/23/2 will be completed durent one as of the last inspection of the last inspection of the 6/8/23 inspect	3 inspection. The diversing basin grading. ection. ection.	
D 8 Current Condition: ET 1 Current Condition:	Fair Condition - Paving or was partially filled in durin The diversion needs to be DEJ was informed to com Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active	potractor installed a diverge basin cleanout prior to be reinstalled. Plete as part of the score SB E stallation, the diversion N of SB D paving in the area, the terms of the score stallation of the score score stallation of the score score stallation of the score score score score stallation of the score score score stallation of the score scor	or the 8/3/23 inspection, repair to the 8/3/23 inspection to the 8/3/	A prior to the 3/23/2 will be completed during the as of the last inspection on the second of the se	3 inspection. The diversing basin grading. ection. ection.	
D 8 Current Condition: ET 1 Current Condition: ET 2	Fair Condition - Paving or was partially filled in durin The diversion needs to be DEJ was informed to com Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace	photractor installed a diverge basin cleanout prior to be reinstalled. SB E Installation, the diversion N of SB D Installation in the area, the to the second seco	pe of work on 10/5/23. Not do large are no longer recommended lettrace will no longer be instal	A prior to the 3/23/2: will be completed dur ne as of the last inspector Removed d as of the 6/8/23 inspector Removed led as of the 7/15/22 inspector Removed	inspection. The diversing basin grading. ection. ection. ection. nspection.	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition:	Fair Condition - Paving or was partially filled in durin The diversion needs to be DEJ was informed to com Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active	plete as part of the score as a lation of SB E paving in the area, the to N of SB E paving in the area, the te	pe of work on 10/5/23. Not do	A prior to the 3/23/2: will be completed dur ne as of the last inspector Removed d as of the 6/8/23 inspector Removed led as of the 7/15/22 inspector Removed	inspection. The diversing basin grading. ection. ection. ection. nspection.	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 2 Current Condition: ET 3	Fair Condition - Paving or was partially filled in durin The diversion needs to be DEJ was informed to com Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Erosion Control Terrace	photractor installed a diverge basin cleanout prior to be reinstalled. SB E Installation, the diversion N of SB D paving in the area, the to the stallation of the second proving in the area, the to the stallation of the second proving in the area, the to the stallation of the second proving in the area, the to the stallation of the second proving in the second proving	pe of work on 10/5/23. Not do as are no longer recommende leterrace will no longer be instal leterrace will no longer be instal	A prior to the 3/23/2: will be completed dur ne as of the last inspector Removed d as of the 6/8/23 insp Removed led as of the 7/15/22 i Removed led as of the 7/15/22 i Removed	inspection. The diversing basin grading. ection. ection. nspection. nspection.	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition:	Fair Condition - Paving or was partially filled in durin The diversion needs to be DEJ was informed to com Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Erosion Control Terrace	photractor installed a diverge basin cleanout prior to be reinstalled. SB E Installation, the diversion N of SB D Installation in the area, the to the stall paving in the area, the total paving in the area, the total paving in the area, the total paving in the area,	pe of work on 10/5/23. Not do large are no longer recommended lettrace will no longer be instal	A prior to the 3/23/2: will be completed dur ne as of the last inspector Removed d as of the 6/8/23 insp Removed led as of the 7/15/22 i Removed led as of the 7/15/22 i Removed	inspection. The diversing basin grading. ection. ection. nspection. nspection.	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 3	Fair Condition - Paving or was partially filled in durin The diversion needs to be DEJ was informed to com Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace	phtractor installed a diverge basin cleanout prior to general part of the scope reinstalled. SB E Installation, the diversion N of SB D Installation in the area, the the scope in the area,	pe of work on 10/5/23. Not do sare no longer recommended the recommended in the same will no longer be instald in the recommended in the recommend	A prior to the 3/23/2: will be completed dur me as of the last inspector Removed d as of the 6/8/23 inspector Removed led as of the 7/15/22 i Removed led as of the 7/15/22 i Removed led as of the 7/15/22 i Removed	inspection. The diversing basin grading. ection. ection. nspection. nspection. nspection. nspection.	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition:	Fair Condition - Paving or was partially filled in durin The diversion needs to be DEJ was informed to com Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active	plete as part of the score as a part of the score as part of the score as a part of the area, the term of SB B paving in the area, the term of SB B paving in the area, the term of SB B paving in the area, the term of SB B paving in the area, the term of SB B paving in the area, the term of SB B paving in the area, the term of SB B B paving in the area, the term of SB B B B B B B B B B B B B B B B B B B	pe of work on 10/5/23. Not do as are no longer recommende leterrace will no longer be instal leterrace will no longer be instal	A prior to the 3/23/2: will be completed dur me as of the last inspector Removed d as of the 6/8/23 inspector Removed led as of the 7/15/22 i Removed led as of the 7/15/22 i Removed led as of the 7/15/22 i Removed	inspection. The diversing basin grading. ection. ection. nspection. nspection. nspection. nspection.	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 3 Current Condition:	Fair Condition - Paving or was partially filled in durin The diversion needs to be DEJ was informed to com Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting	plete as part of the score as partialled. SB Enstallation, the diversion N of SB D paving in the area, the t N of SB B paving in the area, the t East Central paving in the area, the t Northwest Side	pe of work on 10/5/23. Not do less are no longer recommender le	Removed led as of the 7/15/22 i Removed	a inspection. The diversing basin grading. ection. ection. nspection. nspection. nspection. nspection. nspection. nspection. No	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 4 Current Condition:	Fair Condition - Paving or was partially filled in durin The diversion needs to be DEJ was informed to com Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme	plete as part of the score installed. SB E installation, the diversion N of SB D paving in the area, the to N of SB B paving in the area, the to East Central paving in the area, the to Northwest Side roial Seeding installed the standard seeding installed seeding seedi	pe of work on 10/5/23. Not do less are no longer recommended leterrace will no longer be instal leterrace will no longer	Removed led as of the 7/15/22 i Removed	a inspection. The diversing basin grading. ection. ection. nspection. nspection. nspection. nspection. nspection. nspection. No	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 4 Current Condition: EM 1 Current Condition:	Fair Condition - Paving or was partially filled in durin The diversion needs to be DEJ was informed to com Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co	plete as part of the score installed. SB E installation, the diversion N of SB D paving in the area, the the N of SB B paving in the area, the the East Central paving in the area, the the Northwest Side ricial Seeding installed the mmercial Seeding prior to the same of	pe of work on 10/5/23. Not do less are no longer recommended leterrace will no longer be installeterrace wil	Removed led as of the 7/15/22 i Removed	a inspection. The diversing basin grading. ection. ection. ection. nspection. nspection. nspection. nspection. No of the slope were re-	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition:	Fair Condition - Paving or was partially filled in durin The diversion needs to be DEJ was informed to com Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co	potractor installed a diverge basin cleanout prior to ge reinstalled. plete as part of the score in the scor	pe of work on 10/5/23. Not do le of	Removed led as of the 7/15/22 i Active	a inspection. The diversing basin grading. ection. ection. nspection. nspection. nspection. nspection. nspection. nspection.	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 4 Current Condition: EM 1 Current Condition:	Fair Condition - Paving or was partially filled in durin The diversion needs to be DEJ was informed to com Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co Erosion Control Matting Good Condition - Comme	potractor installed a diverge basin cleanout prior to general part of the score are reinstalled. SB E Installation, the diversion In N of SB D Installation, the area, the the score in the area, the the score in t	pe of work on 10/5/23. Not do less are no longer recommended leterrace will no longer be instal leterrace will no longer	Removed led as of the 7/15/22 i Active	a inspection. The diversing basin grading. ection. ection. ection. nspection. nspection. nspection. nspection. No of the slope were re-	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 1 Current Condition:	Fair Condition - Paving or was partially filled in durin The diversion needs to be DEJ was informed to com Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co Erosion Control Matting Good Condition - Comme	phericator installed a diverge basin cleanout prior to general part of the score reinstalled. SB E Installation, the diversion N of SB D Installation, the diversion N of SB E Installation, the area, the the score in the area, the the score in the area, the the score in th	pe of work on 10/5/23. Not do less are no longer recommended leterrace will no longer be installeterrace wil	Removed led as of the 7/15/22 i Active led as of the 7/15/22 i Active led as of the 7/15/22 i Active	a inspection. The diversing basin grading. ection. ection. nspection. nspection. nspection. No of the slope were re-	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 2 Current Condition: EM 2	Fair Condition - Paving or was partially filled in durin The diversion needs to be DEJ was informed to com Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co Erosion Control Matting Good Condition - Comme Erosion Control Matting	potractor installed a diverge basin cleanout prior to general part of the score reinstalled. Plete as part of the score in the score i	pe of work on 10/5/23. Not do less are no longer recommended leterrace will no longer be installeterrace wil	Removed led as of the 7/15/22 i Active led as of the 7/15/22 i Active led as of the 7/15/22 i Active	a inspection. The diversing basin grading. ection. ection. nspection. nspection. nspection. No of the slope were re-	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 2 Current Condition: EM 3 Current Condition:	Fair Condition - Paving or was partially filled in durin The diversion needs to be DEJ was informed to com Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co Erosion Control Matting Good Condition - Comme Erosion Control Matting Good Condition - Comme seeding and matting prior	plete as part of the score reinstalled. Plete as part of the score reinstalled. Plete as part of the score reinstallation, the diversion N of SB D paving in the area, the to N of SB B paving in the area, the to Reast Central paving in the area, the to Northwest Side roial Seeding installed the more reinstalled the Northeast Side roial Seeding installed the to the 4/27/23 inspections.	pe of work on 10/5/23. Not do less are no longer recommended leterrace will no longer be installeterrace wil	Removed ded as of the 7/15/22 i Removed led as of the 7/15/22 i Active led inspection. Portions Active	a inspection. The diversing basin grading. ection. pection. pection. pection. propertion. propertion.	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 2 Current Condition: EM 2	Fair Condition - Paving or was partially filled in durin The diversion needs to be DEJ was informed to come Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co Erosion Control Matting Good Condition - Comme Erosion Control Matting Good Condition - Comme Erosion Control Matting Good Condition - Comme Seeding and matting prior Erosion Control Matting	plete as part of the score installed. SB E installation, the diversion N of SB D paving in the area, the the N of SB B paving in the area, the the East Central paving in the area, the the Northwest Side ricial Seeding installed the Northeast Side ricial Seeding installed the Southwest Corner	pe of work on 10/5/23. Not do less are no longer recommended leterrace will no longer be installeterrace wil	Removed das of the 6/8/23 insp. Removed das of the 6/8/23 insp. Removed led as of the 7/15/22 i Active c inspection. Portions Active c inspection. Sudbeck	a inspection. The diversing basin grading. ection. ection. nspection. nspection. nspection. No of the slope were re-	

Current Condition:	grade. A water main extermatting in the area will be inspection. Water main in the area when installation seeding/matting to follow. repaired the erosion and residual process.	nsion project in the area temporarily halted until astallation is active on sit is complete. Additional Commercial Seeding so e-seeded/matted the slo	be installed within the seeding will begin soon as of the 5/3/ work is complete. Seeding of the as of the 8/29/22 inspection finish grading along 72nd Streeded/matted the slope prior ope prior to the 5/4/23 inspect n, the inspector will continue to	22 inspection, therefore the slope is still record, water contractor will eet to be completed into the 4/20/23 inspection. Minor erosion alo	ore, recommendations for mmended as of the 5/3/22 be seeding and matting in the Spring of 2023, ion. Commercial Seeding ong the south end of the	
FT 1	Fuel Tank	SW Corner		Removed		
Current Condition:	Removed - DEJ removed	the fuel tank prior to the	7/15/22 inspection.			
FT 2	Fuel Tank	Material Storage Area	·	Removed		
Current Condition:	Removed - TAB removed		e 4/7/22 inspection.			
FT 3	Fuel Tank	Material Storage Area	•	Removed		
Current Condition:	Removed - RPL removed		114/22 inspection.			
FT 4	Fuel Tank	Material Storage Area	•	Removed		
Current Condition:	Removed - The fuel tank	was removed prior to the	e 5/18/22 inspection.			
FT 5	Fuel Tank	Material Storage Area		Removed		
Current Condition:	Removed - The fuel tank	was removed prior to the	e 7/8/22 inspection.			
FT 6	Fuel Tank	On Site		Removed		
Current Condition:	Removed - Kersten removen					
TEMP IPs XX Current Condition:	Inlet Protection	Schram Road	10/5/2023	Active	Yes	
	Fair Condition - Commercial Seeding installed inlet filters along the south side of Schram Road prior to the 10/5/23 inspection. Inlet filters should be cleaned out. Commercial Seeding was informed to complete on behalf of the SID by 11/2/23.					
Lot 67	Individual Lot	Lot 67	4/6/2023	Active	No	
Current Condition:			on the lot prior to the 4/6/23			
		ne inspector will continue	e to monitor. Legacy Homes			
MS 1	Material Storage	On Site		Removed		
Current Condition:	Removed - Civil overlot de 11/4/22 inspection.	evelopment is mostly co	mplete, material storage will b	e addressed on a lot	by lot basis as of the	
PB X	Portable Bathroom	On Site		Removed		
Current Condition:	Removed - RPL removed	the remaining portable t	oilet from the site prior to the	11/4/22 inspection.		
SB A	Sediment Basin	X24	5/11/2022	Active	Yes	
Current Condition:	Fair Condition - 6% - The basin was partially dug out prior to the 12/1/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was installed prior to the 5/11/22 inspection. The basin was reshaped prior to the 5/26/22 inspection. The E&A inspector painted the cleanout mark on 5/23/22. The erosion into the basin are the only stormwater diversions to the basin and should remain in place as of the 6/8/23 inspection, additional grading will address these diversions when construction on the eastern phase begins. Basin cleanout began prior to the inspection on 7/20/23. The basin was cleaned out prior to the 7/27/23 inspection. DEJ installed the baffle prior to the 10/5/23 inspection. The SID is working to identify funding to complete the basin cleanout as of 3/10/23. Not done as of the last inspection. Plans are under review by the design engineer as of 6/5/23. RFP sent to contractors 6/21/23. Contractor hired on 6/30/23, work to resume after the July 4th holiday. DEJ hired Commercial Seeding to complete seeding/matting prior to the 10/5/23 inspection.					
SB B	Sediment Basin	O24	5/18/2022	Active	Yes	
Current Condition:	continue to monitor. The was in the process of beir prior to the 5/18/22 inspect the 6/29/23 inspection. D The basin slopes should to DEJ to complete as part of	basin outfall pipe and rip og installed during the 4/2 tion. The E&A inspecto EJ installed the baffle pr oe seeded/matted.	artially dug out prior to the 9/1 or ap appears to have been in 21/22 inspection. Dewatering or painted the cleanout mark of ior to the 10/5/23 inspection. In cleanouts as of 6/30/23. No prior to the 10/5/23 inspectio	stalled prior to the 4/1 I holes appear to have In 5/23/22. DEJ clear In the first done as of the last in	3/22 inspection. The riser been installed in the riser and out the basin prior to	
SB C	Sediment Basin	H24	5/18/2022	Active	Yes	
			-			

Current Condition:	Fair Condition - 6% Filled - The basin was dug out prior to the 11/12/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. Dewatering holes appear to have been installed in the riser prior to the 5/18/22 inspection. The E&A inspector painted the cleanout mark on 5/23/22. DEJ cleaned out the basin prior to the 6/29/23 inspection. DEJ installed the baffle prior to the 10/5/23 inspection.					
	The basin slopes should be seeded/matted. DEJ to complete as part of scope of work for basin cleanouts as of 6/30/23. Not done as of the last inspection. DEJ hired Commercial Seeding to complete seeding/matting prior to the 10/5/23 inspection.					
SB D	Sediment Basin	H22	5/18/2022	Active	Yes	
Current Condition:	Fair Condition - 6% Filled - The basin was in the process of being dug out during the 11/4/21 inspection. The basin outfall p and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed due the 4/21/22 inspection. The old area inlet was removed prior to the 4/21/22 inspection. Dewatering holes appear to have b installed in the riser prior to the 5/18/22 inspection. The basin was in the process of being cleaned out during the 7/27/23 inspection. The basin was cleaned out and the correct depth achieved as of the 8/3/23 inspection. DEJ installed the baffle prior to the 10/5/23 inspection. The basin slopes should be seeded/matted. DEJ to complete as part of scope of work for basin cleanouts as 8/3/23. Not done as of the last inspection. DEJ hired					
	Commercial Seeding to co	omplete seeding/matting	prior to the 10/5/23 inspection	n.		
SB E	Sediment Basin	D19	5/3/2022	Active	No	
Current Condition:		&A inspector painted the	ally dug out prior to the 12/1/2 c cleanout mark on 5/23/22.	1 inspection. DEJ ins	talled the riser prior to the	
SF 1 Current Condition:	Silt fence	Northern/Western Perimeter	5/18/2021 fence prior to the 5/18/21 insp	Active	No	
	extension of the silt fence to the north prior to the 2/2/22 inspection. Sudbeck extended the silt fence to the south along the north side of the entrance prior to the 4/7/22 inspection. TAB repaired/reinstalled the silt fence along 72nd Street prior to the 4/7/22 inspection. The silt fence was removed in multiple locations, including southwest of SB D, for water installation prior to the 6/24/22 inspection. The water contractor removed the silt fence where damaged adjacent to the construction entrance and NW of SB D prior to the 6/30/22 inspection. Sudbeck installed silt fence around the flared end section of SB D prior to the 7/8/22 inspection. Sudbeck installed silt fence along the north side of Schram prior to the 9/12/22 inspection. Sudbeck repaired and extended the silt fence along 72nd Street prior to the 9/19/22 inspection. Commercial Seeding repaired/reinstalled the silt fence north of Schram prior to the 12/8/22 inspection. Commercial Seeding reinstalled the silt fence at the outfall prior to the 4/20/23 inspection. Sudbeck installed additional silt fence along the top of the slope southeast of 72nd and Schram prior to the 6/8/23 inspection. Papio Park LLC repaired the silt fence at the top of the slope prior to the 8/10/23 inspection.					
SF 2	Silt fence	Northeastern Perimeter	5/25/2021	Active	No	
Current Condition:	Fair Condition - The developer installed the silt fence prior to the 5/25/21 inspection. Sudbeck reinforced the silt fence with additional posts in the northeast corner of the site. Sudbeck removed the silt fence in upgradient areas and repaired the silt fence in the northeast corner of the site prior to the 4/6/23 inspection. Sudbeck reinstalled the silt fence and new silt fence checks prior to the 6/8/23 inspection. The silt fence was damaged by excessive water from the adjoining property prior to the 6/22/23 inspection, repair is not recommended at this time, remaining control will be addressed during grading of Phase II. The area where the silt fence is located is adequately vegetated as of the 10/12/23 inspection, erosion repair and silt fence maintenance will be conducted during Phase II grading, no pollution concerns at this time.					
SF 3	Silt fence	Southeast Corner	5/25/2021	Active	No	
Current Condition:	Good Condition - The developer installed the silt fence prior to the 5/25/21 inspection. The silt fence was partially removed for installation of the SB A outfall pipe prior to the 4/7/22 inspection. Minor damaged silt fence remains south of SB B as of the 4/6/23 inspection, the silt fence is not needed and will be removed during grading of the property to the south. The silt fence					
SF 4 Current Condition:	was partially burned down during a crop fire prior to the 4/20/23 inspection. Sudbeck reinstalled the silt fence prior to the 6/8/23 inspection. Silt fence Southwest Perimeter 5/18/2021 Active No Good Condition - The developer installed the silt fence prior to the 5/18/21 inspection. Gene Graves installed silt fence around the Ponderosa Drive connection prior to the 10/13/21 inspection. Sudbeck installed high porosity silt fence checks in the flow line of the swale prior to the 4/7/22 inspection. The silt fence was partially removed at the future Ponderosa entrance along 72nd Street for storm sewer work prior to the 5/18/22 inspection. Some of the silt fence was temporarily removed for water installation prior to the 9/27/22 inspection. The damaged portions of silt fence were removed prior to the 11/4/22 inspection. Commercial Seeding reinstalled the silt fence checks in the swale prior to the 12/8/22 inspection and installed perimeter silt fence in the area prior to the 12/8/22 inspection. Commercial Seeding reinforced the silt fence in the swale and installed additional silt fence to protect the drainage prior to the 3/30/23 inspection. Commercial Seeding cleaned out and repaired the silt fence checks north of the culvert and installed additional protection prior to the 5/4/23 inspection. The silt fence in the swale along Ponderosa is in fair condition as of the 5/4/23 inspection; however, to avoid disturbing growing vegetation, no maintenance is recommended at this time. OPPD damaged and removed portions of the silt fence prior to the 5/18/23 inspection, additional repairs will be recommended after OPPD work is complete. Papio Park LLC cleaned out the silt fence south of Ponderosa Drive prior to the 8/10/23 inspection. Commercial Seeding repaired/reinstalled the silt fence north of Ponderosa Drive prior to the 8/10/23 inspection.					
SF 5	Silt fence	NW corner of Lot 3 Replat 1	11/4/2022	Active	Yes	

Current Condition:		the state of the s	rior to the 11/4/22 inspection. It is and repaired the silt fence p		
			6/8/23 inspection, additional rence prior to the 8/17/23 inspe		nended after OPPD work
	The silt fence was damag	ed during sidewalk insta	llation and needs to be repair	ed.	
	The contractor will be info	ormed to complete when	construction is finished as of	the 9/28/23 inspection	n. Not done as of the la
			10/12/23 inspection with the o		
			t fence repairs can be conduc		
	will be reinstalled as ne		g and then dormant seed ar	nd mat after ground	temp allows, silt fence
SF 6	Silt fence	NE S 70th and Flint	11/10/2022	Active	Yes
Current Condition:	Fair Condition - Sudbeck	installed the silt fence pr /23 inspection, additiona	ior to the 11/10/22 inspection I repairs will be recommended	. OPPD damaged an	d removed portions of t
		·	llation and needs to be repair	ed.	
	The contractor will be info	rmed to complete when	construction is finished as of	the 10/12/23 inspection	on. Not done as of the
			10/12/23 inspection with the o		
	· ·		t fence repairs can be conduc		
	· ·		g and then dormant seed ar	nd mat after ground	temp allows, silt fenc
	will be reinstalled as ne				
SF 7 Current Condition:	Silt fence	NE S 70th and Stony	11/10/2022	Active	No
Current Condition.		/23 inspection, additiona	prior to the 11/10/22 inspection I repairs will be recommended I inspection.		
SF 8	Silt fence	NW of SB C	12/8/2022	Active	No
	Due to utility work as of the	ne 8/17/23 inspection, the ki is complete. The E&A spection so that repairs	tion, additional repairs will be e silt fence will not be repaired A inspector inquired with the c can be conducted.	d; the area is well veg	etated and the silt fenc
SF 9	Silt fence	SW Corner of 72nd and Schram	12/8/2022 silt fence prior to the 12/8/22	Active	Yes
	The contractor will be info inspection. The E&A insp completion of the sidewall construction plan is to o	ormed to complete when bector inquired as of the k construction so that sill complete finish grading	construction is finished as of 10/12/23 inspection with the of the force repairs can be conducted and then dormant seed and then dormant seed and the conducted the force repairs can be conducted and then dormant seed and the force repairs can be conducted the force repairs can be conducted to the force of the force	the 9/21/23 inspection construction observer sted. As of the 10/26/	about the timeline for //23 inspection, the
OTD	will be reinstalled as ne		5/40/0004	Author	Ni
STR Current Condition:	Streets Good Condition - Sudbeck	S 72nd Street	5/18/2021 or to the 8/3/23 inspection. D	Active F I cleaned the street	No s prior to the 8/3/23
Ourient Condition.			rior to the 8/10/23 inspection.	Lo cicarica tric street	3 prior to the 0/0/20
0147.4	Straw Wattles				I
SW 1		72nd ROW		Removed	
SW 1 Current Condition:			grading prior to the 4/6/23 insp	Removed pection. The slope will	l be seeded and matted
	Removed - Sudbeck remo	oved the wattles during of	grading prior to the 4/6/23 insp s in place where necessary.		l be seeded and matted
Current Condition: SWPPP Sign	Removed - Sudbeck remo 5/1/23, wattles are no long Misc/Other	oved the wattles during ger needed. Silt fence is S 72nd and Schram	s in place where necessary. 5/18/2021	pection. The slope will Active	No
Current Condition:	Removed - Sudbeck remo 5/1/23, wattles are no long Misc/Other Good Condition - The E&	oved the wattles during ger needed. Silt fence is S 72nd and Schram A inspector installed the	s in place where necessary. 5/18/2021 SWPPP sign in the southwes	Active st corner of the proper	No ty during the 5/18/21
Current Condition: SWPPP Sign Current Condition:	Removed - Sudbeck remo 5/1/23, wattles are no long Misc/Other Good Condition - The E& inspection. An additional	oved the wattles during of ger needed. Silt fence is S 72nd and Schram A inspector installed the SWPPP sign was instal	s in place where necessary. 5/18/2021	Active st corner of the proper am prior to the 6/22/23	No ty during the 5/18/21
Current Condition: SWPPP Sign Current Condition: WO 1	Removed - Sudbeck remo 5/1/23, wattles are no long Misc/Other Good Condition - The E& inspection. An additional Concrete Washout	oved the wattles during of ger needed. Silt fence is S 72nd and Schram A inspector installed the SWPPP sign was install On Site	s in place where necessary. 5/18/2021 SWPPP sign in the southwested at S 72st Street and Schra	Active st corner of the proper am prior to the 6/22/23 Removed	No ty during the 5/18/21
Current Condition: SWPPP Sign Current Condition: WO 1 Current Condition:	Removed - Sudbeck remo 5/1/23, wattles are no long Misc/Other Good Condition - The E& inspection. An additional Concrete Washout Removed - Sudbeck clear	oved the wattles during of ger needed. Silt fence is S 72nd and Schram A inspector installed the SWPPP sign was install On Site need up the remaining co	s in place where necessary. 5/18/2021 SWPPP sign in the southwes	Active st corner of the proper am prior to the 6/22/23 Removed he 11/4/22 inspection.	No ty during the 5/18/21
Current Condition: SWPPP Sign Current Condition: WO 1	Removed - Sudbeck remo 5/1/23, wattles are no long Misc/Other Good Condition - The E& inspection. An additional Concrete Washout Removed - Sudbeck clear Waste Storage Removed - Waste storage	oved the wattles during of ger needed. Silt fence is S 72nd and Schram A inspector installed the SWPPP sign was instal On Site need up the remaining co	s in place where necessary. 5/18/2021 SWPPP sign in the southwested at S 72st Street and Schra	Active st corner of the proper am prior to the 6/22/23 Removed he 11/4/22 inspection.	No ty during the 5/18/21 3 inspection.
Current Condition: SWPPP Sign Current Condition: WO 1 Current Condition: WS 1	Removed - Sudbeck remo 5/1/23, wattles are no long Misc/Other Good Condition - The E& inspection. An additional Concrete Washout Removed - Sudbeck clean Waste Storage Removed - Waste storage section. "I certify, under penalty of accordance with a system submitted. Based on my in gathering the information,	oved the wattles during of ger needed. Silt fence is S 72nd and Schram A inspector installed the SWPPP sign was install On Site need up the remaining co On Site e of concrete, constructionally, that this document in designed to assure that inquiry of the person or put the information submitted.	s in place where necessary. 5/18/2021 SWPPP sign in the southwested at S 72st Street and Schrater waste on site prior to the	Active st corner of the proper am prior to the 6/22/23 Removed he 11/4/22 inspection. Removed are covered under sep pared under my direct gathered and evaluate em or those persons of edge and belief, true, a	No ty during the 5/18/21 B inspection. arrate BMPs in the BMF tion or supervision in ed the information directly responsible for accurate, and complete