E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

E&A - P2018.228.001 Bill SID as of 2/17/22 P2018.228.000

		DIII SID as OI 2/ I	1122 P2018.228.000					
Inspector: Jason Brackett		Stage						
		Sevent	y Two Place					
		1						
		'						
Project Name:		CSW-202004796						
For Week Ending:		8/3/2024						
Project Location:		12101 S 72nd St, Papillion, Sarpy County, NE						
Grading:	80%	Ι		Τ	T			
Sanitary Sewer:	100%							
Storm Sewer:	95%							
Paving:	80%							
Seeding:	80%							
Utilities:	80%							
Overall Development:	47%	47%						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time				
					Week			
Sunday:	0.00"							
Monday:	0.00"							
Tuesday:	0.00"							
Wednesday:	0.81"	7/31/2024	Mostly Sunny 93/76	10:30 AM				
Thursday:	0.00"							
Friday:	0.00"							
Saturday:	0.00"							

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Rough grading began (6/15/21), Excavation for sanitary installation (9/28/21). Grading ceased due to winter conditions (1/5/22). Excavation for utility connections along 72nd (2/8/22). Grading for roadways (6/9/22). Lot 3 Replat 1 and Lot 4 Replat 1 scraping (11/2/22). Birpap installation and regrading at S 70th Street stub (11/2/22). Swale and ROW along Ponderosa connection finish graded (11/4/22). Swale and ROW along Ponderosa grading ceased (12/1/22). Basin cleanouts and processing silt began (8/3/23). Basin cleanouts complete (10/26/23). Sidewalk paving complete (11/8/23). Regrading of southeast corner lots (12/6/23). All grading ceased due to winter conditions (1/4/24). Re-grading of sidewalk replacements (6/19/24).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading began (6/15/21). Excavation for sanitary installation (9/28/21). Grading ceased due to winter conditions (1/5/22). Excavation for utility connections along 72nd (2/8/22). Grading for roadways (6/9/22). Lot 3 Replat 1 and Lot 4 Replat 1 scraping (11/2/22). Riprap installation and regrading at \$ 70th Street stub (11/2/22). Swale and ROW along Ponderosa connection finish graded (11/4/22). Swale and ROW along Ponderosa grading ceased (12/1/22). Basin cleanouts and processing silt began (8/3/23). Basin cleanouts completed (10/26/23). Sidewalk paving complete (11/8/23). Regrading of southeast corner lots (12/6/23). All grading ceased due to winter conditions (1/4/24). Re-grading of sidewalk replacements (6/19/24).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (6/15/21). Disking/seeding east side of site (7/8/22). Lot 1, 2, 3 - seeded (11/10/22). Seeding and matting swale and ROW along Ponderosa and Schram/72nd medians and ROWs (12/8/22). Seeding/matting sidewalk disturbances began (11/8/23). Basin slopes seeded/matted (11/29/23). SE of S 72nd Street and Schram seeding/matting (12/13/23). Commercial Seeding seeded/matted portions of disturbance around sidewalk construction, light pole installation, and utility work (3/13/24). Commercial Seeding seeded/matted the northeast corner of 72nd and Schram (3/20/24). Re-seeding and matting around sidewalk replacements (6/19/24).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Create Corrective A

Create Corrective Action?

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

N/A

nstruction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?

No, see BMPs section.

Is dust associated with the construction activity adequately controlled on the site?

res	
Create Corrective Action?	
WA	

Comments:

Comments:

The site was inactive during the most recent inspection. Lot 5 and 6 Replat 1 have been removed from this SWPPP and are covered by PAP-20220310-6351-

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section of this report.
- 2) Disturbed areas of the north side of the Ponderosa Swale should be stabilized and the old silt fence removed when Vestara construction is complete. The inspector will continue to monitor and recommend maintenance when Vestara construction complete as of the 3/6/24 inspection.
- 3) Disturbed areas of poor vegetation growth need to be re-seeded and matted along the south side of Schram Road. The inspector sent a plan to Papio Park, LLC for approval on 5/23/24 prior to hiring a contractor to complete by 5/29/24. Not done as of the last inspection. Contractor hired prior to the 5/29/24 inspection. Contractor to complete erosion repair ASAP and permanent seeding in the Fall seeding window as of the 7/10/24 inspection.

 4) CIR 22370 was received, reviewed, and forwarded to Papio Park, LLC on 7/31/24. CIR is consistent with E&A insepctor's report.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
	•	Schram Road	Projected install Date	Removed	Wallitellance		
CE 1	Construction Entrance				(the Oakses Dead		
Current Condition:		Removed - The entrance will no longer be used as of the 8/29/22 inspection due to the completion of the Schram Road					
	connection.						
D 1	Diversion	E of SB C	11/12/2021	Active	No		
Current Condition:			to the 11/12/21 inspection.				
	diversion during the 6/30/22 inspection. Sudbeck maintained the diversion prior to the 7/8/22 inspection. The diversion was						
	removed at the S 70th stu	b prior to the 8/29/22 in	spection, the inspector will me	onitor the need for rei	nstallation.		
D 2	Diversion	S of SB D		Removed			
Current Condition:	Removed - Due to addition	nal BMPs installed for th	ne Vestara Apartments, the di	version no longer nee	eds to be installed as of		
	6/8/23 inspection.						
D 3	Diversion	N of SB D	6/8/2023	Active	No		
Current Condition:	Good Condition - Sudbeck	c installed the diversion	prior to the 6/8/23 inspection.	The diversion was p	artially filled in during b		
	cleanout prior to the 8/3/2	3 inspection. The diver	sion does not need to be rein	stalled where remove	d as of the 10/12/23		
	inspection.						
D 4	Diversion	E and SB B		Removed			
Current Condition:	Removed - Re-grading of	the lots by Ruff Grading	in the area has removed the	diversion as of the 2	/8/24 inspection,		
	reinstallation is not require	ed.					
D 5	Diversion	Northwest Perimeter		Removed			
Current Condition:	Removed - The diversion	is not needed due to ex	sisting contours as of the 5/3/2	22 inspection.	•		
D 6	Diversion	Western Perimeter	1	Removed			
Current Condition:	Removed - The remaining portions of Schram have been installed as of the 3/23/23 inspection. Recommendations for swale						
	regrading are included in the Findings section of this report.						
D 7	Diversion	Stub to SB A	3/23/2023	Active	No		
D 7 Current Condition:			3/23/2023 version from the stub road to 3				
	Good Condition - Paving	contractor installed a div		SB A prior to the 3/23	/23 inspection. The		
	Good Condition - Paving of diversion was partially filled	contractor installed a dived in during basin cleane	version from the stub road to	SB A prior to the 3/23 on, repair will be com	/23 inspection. The pleted during basin gra		
	Good Condition - Paving of diversion was partially fille DEJ reinstalled the divers	contractor installed a div ed in during basin cleand ions prior to the 11/15/2	version from the stub road to sout prior to the 8/3/23 inspecti	SB A prior to the 3/23 on, repair will be com vas partially removed	/23 inspection. The pleted during basin grate to build an access road		
	Good Condition - Paving of diversion was partially fille DEJ reinstalled the divers regrading of the southeas:	contractor installed a divention of the divined in during basin cleanding prior to the 11/15/2 toorner of the site and it	version from the stub road to sout prior to the 8/3/23 inspecti 3 inspection. The diversion v	SB A prior to the 3/23 on, repair will be com was partially removed prior to the 12/13/23	/23 inspection. The pleted during basin grate to build an access road inspection, the inspect		
	Good Condition - Paving of diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallat	contractor installed a diversity of the direction of the directions prior to the 11/15/2 toorner of the site and reion when access road is	version from the stub road to sout prior to the 8/3/23 inspection. The diversion when work at Ponderosa Place	SB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has	/23 inspection. The pleted during basin grate to build an access road inspection, the inspect		
	Good Condition - Paving of diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallat	contractor installed a diversity of the direction of the directions prior to the 11/15/2 toorner of the site and reion when access road is	version from the stub road to so but prior to the 8/3/23 inspecti 3 inspection. The diversion we new work at Ponderosa Places sono longer needed. Erosion	SB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has	/23 inspection. The pleted during basin grate to build an access road inspection, the inspect		
Current Condition:	Good Condition - Paving of diversion was partially filled DEJ reinstalled the divers regrading of the southeas will recommend reinstallat as of the 2/28/24 inspection	contractor installed a diversity of the contractor installed a diversity of the 11/15/2 to corner of the site and recommended in the corner of the site and recommended in the inspector will moon the inspector will moon.	version from the stub road to so but prior to the 8/3/23 inspecti 3 inspection. The diversion we new work at Ponderosa Places sono longer needed. Erosion	BB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has Removed	/23 inspection. The pleted during basin grate to build an access roainspection, the inspect drained the ponded an		
Current Condition: D 8	Good Condition - Paving of diversion was partially filled DEJ reinstalled the divers regrading of the southeas will recommend reinstallat as of the 2/28/24 inspection	contractor installed a diversity of the contractor installed a diversity of the 11/15/2 to corner of the site and recommended in the corner of the site and recommended in the inspector will moon the inspector will moon the corner of the cor	version from the stub road to so but prior to the 8/3/23 inspecti 3 inspection. The diversion was a place work at Ponderosa Place sono longer needed. Erosion whitor during future rain events	BB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has Removed	/23 inspection. The pleted during basin grate to build an access roainspection, the inspect drained the ponded an		
Current Condition: D 8 Current Condition:	Good Condition - Paving of diversion was partially filled DEJ reinstalled the divers regrading of the southeas will recommend reinstallat as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace	contractor installed a diversity of the installed and in during basin cleandries prior to the 11/15/2 to corner of the site and right ion when access road is on, the inspector will moon to the installation, the diversion N of SB D	version from the stub road to so but prior to the 8/3/23 inspecti 3 inspection. The diversion was a place work at Ponderosa Place sono longer needed. Erosion whitor during future rain events	BB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has Removed as of the 6/8/23 inspectors.	/23 inspection. The pleted during basin grate to build an access roadinspection, the inspection drained the ponded are pection.		
Current Condition: D 8 Current Condition: ET 1	Good Condition - Paving of diversion was partially filled DEJ reinstalled the divers regrading of the southeas will recommend reinstallat as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace	contractor installed a diversity of the installed and in during basin cleandries prior to the 11/15/2 to corner of the site and right ion when access road is on, the inspector will moon to the installation, the diversion N of SB D	version from the stub road to so the prior to the 8/3/23 inspection. The diversion when work at Ponderosa Places no longer needed. Erosion whiter during future rain events are no longer recommended.	BB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has Removed as of the 6/8/23 inspectors.	/23 inspection. The pleted during basin grate to build an access roadinspection, the inspection drained the ponded are pection.		
D 8 Current Condition: ET 1 Current Condition:	Good Condition - Paving of diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallat as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace	contractor installed a divide in during basin cleand in sprior to the 11/15/2 toorner of the site and it ion when access road is on, the inspector will most a BE installation, the diversion N of SB Dipaving in the area, the total site in the site	version from the stub road to so the prior to the 8/3/23 inspection. The diversion when work at Ponderosa Places no longer needed. Erosion whiter during future rain events are no longer recommended.	SB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has is. Removed d as of the 6/8/23 insy Removed led as of the 7/15/22 Removed	/23 inspection. The pleted during basin grate to build an access road inspection, the inspect drained the ponded are pection.		
D 8 Current Condition: ET 1 Current Condition: ET 2	Good Condition - Paving of diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallat as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Erosion Control Terrace	contractor installed a divide in during basin cleand in during basin cleand it in during basin cleand it is corner of the site and it is on, the inspector will most a BE installation, the diversion N of SB D basing in the area, the true N of SB E paving in the area, the true N of SB B	version from the stub road to so but prior to the 8/3/23 inspection. The diversion version work at Ponderosa Places in longer needed. Erosion white during future rain events as are no longer recommende errace will no longer be instal errace will no longer be instal	SB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has i. Removed das of the 6/8/23 ins Removed led as of the 7/15/22 Removed led as of the 7/15/22 Removed	/23 inspection. The pleted during basin grate to build an access road inspection, the inspect drained the ponded an opection.		
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition:	Good Condition - Paving of diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallat as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Erosion Control Terrace	contractor installed a divide in during basin cleand in during basin cleand it in during basin cleand it is corner of the site and it is on, the inspector will most a BE installation, the diversion N of SB D basing in the area, the true N of SB E paving in the area, the true N of SB B	version from the stub road to so but prior to the 8/3/23 inspection. The diversion view work at Ponderosa Place is no longer needed. Erosion whiter during future rain events are no longer recommende errace will no longer be instal	SB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has i. Removed das of the 6/8/23 ins Removed led as of the 7/15/22 Removed led as of the 7/15/22 Removed	/23 inspection. The pleted during basin grate to build an access road inspection, the inspect drained the ponded an opection.		
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 2 Current Condition: ET 3	Good Condition - Paving of diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallat as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Erosion Control Terrace	contractor installed a divide in during basin cleand in during basin cleand it in during basin cleand it is corner of the site and it is on, the inspector will most a BE installation, the diversion N of SB D basing in the area, the true N of SB E paving in the area, the true N of SB B	version from the stub road to so but prior to the 8/3/23 inspection. The diversion version work at Ponderosa Places in longer needed. Erosion white during future rain events as are no longer recommende errace will no longer be instal errace will no longer be instal	SB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has i. Removed das of the 6/8/23 ins Removed led as of the 7/15/22 Removed led as of the 7/15/22 Removed	/23 inspection. The pleted during basin grate to build an access road inspection, the inspect drained the ponded an opection.		
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition:	Good Condition - Paving of diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallat as of the 2/28/24 inspectic Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Erosion Control Terrace	contractor installed a divide in during basin cleand in during basin cleand it in during basin cleand it in the site and it is in when access road it in when access road it in the inspector will mose a BE installation, the diversion N of SB D paving in the area, the text N of SB B paving in the area, the text N of SB B paving in the area, the text East Central	version from the stub road to so but prior to the 8/3/23 inspection. The diversion version work at Ponderosa Places in longer needed. Erosion white during future rain events as are no longer recommende errace will no longer be instal errace will no longer be instal	BB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has be a soft the 6/8/23 ins Removed led as of the 7/15/22 Removed	/23 inspection. The pleted during basin grate to build an access road inspection, the inspect drained the ponded ar pection.		
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 4 Current Condition: EM 1	Good Condition - Paving of diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallat as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace	contractor installed a divide in during basin cleand in during basin cleand in sprior to the 11/15/2 to corner of the site and in ion when access road is on, the inspector will most a special stallation, the diversion N of SB Doaving in the area, the to N of SB Boaving in the area, the to East Central paying in the area, the to East Central paying in the area, the to Northwest Side	version from the stub road to so but prior to the 8/3/23 inspection. The diversion when work at Ponderosa Place is no longer needed. Erosion whiter during future rain events are no longer recommended. It is are no longer recommended errace will no longer be instal errace will no longer	BB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has in the second downward of the 6/8/23 inspace of the 6/8/23 inspace of the 7/15/22 Removed led as of the 7/15/22 Active	/23 inspection. The pleted during basin grate to build an access road inspection, the inspect drained the ponded are poection.		
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition:	Good Condition - Paving of diversion was partially filled DEJ reinstalled the divers regrading of the southeas will recommend reinstallat as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme	contractor installed a divide in during basin cleand in during basin cleand it in during basin cleand it is corner of the site and it is on, the inspector will most a Benstallation, the diversion N of SB Doaving in the area, the to N of SB Boaving in the area, the to East Central paving in the area, the to Northwest Side rotal Seeding installed the	version from the stub road to so but prior to the 8/3/23 inspection. The diversion when work at Ponderosa Places is no longer needed. Erosion whiter during future rain events are no longer recommended. It is are no longer recommended errace will no longer be instalderrace will no longe	BB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has in the second downward of the 6/8/23 inspace of the 6/8/23 inspace of the 7/15/22 Removed led as of the 7/15/22 Active	/23 inspection. The pleted during basin grate to build an access road inspection, the inspect drained the ponded an access road inspection.		
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 4 Current Condition: EM 1	Good Condition - Paving of diversion was partially filled DEJ reinstalled the divers regrading of the southeas will recommend reinstallat as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme	contractor installed a divide in during basin cleand in during basin cleand it in during basin cleand it is corner of the site and it is on, the inspector will most a Benstallation, the diversion N of SB Doaving in the area, the to N of SB Boaving in the area, the to East Central paving in the area, the to Northwest Side rotal Seeding installed the	version from the stub road to so but prior to the 8/3/23 inspection. The diversion when work at Ponderosa Place is no longer needed. Erosion whiter during future rain events are no longer recommended. It is are no longer recommended errace will no longer be instal errace will no longer	BB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has in the second downward of the 6/8/23 inspace of the 6/8/23 inspace of the 7/15/22 Removed led as of the 7/15/22 Active	/23 inspection. The pleted during basin grate to build an access road inspection, the inspect drained the ponded are poection.		
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 4 Current Condition: EM 1	Good Condition - Paving of diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallat as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Commenseeded and matted by Co	contractor installed a divide in during basin cleand in during basin cleand it in during basin cleand it is in the inspector will most a BE in the inspector will be in the inspector will be in the inspector will be inspector	version from the stub road to so but prior to the 8/3/23 inspection. The diversion via the work at Ponderosa Place is no longer needed. Erosion whiter during future rain events as are no longer recommende errace will no longer be installerrace will no lo	BB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has is. Removed d as of the 6/8/23 insy Removed led as of the 7/15/22 Active	/23 inspection. The pleted during basin grate to build an access road inspection, the inspect drained the ponded are poection.		
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition:	Good Condition - Paving of diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallat as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Commenseeded and matted by Co	contractor installed a divide in during basin cleand in during basin cleand it in during basin cleand it is in the inspector will most a BE in the inspector will be in the inspector will be in the inspector will be inspector	version from the stub road to so but prior to the 8/3/23 inspection. The diversion when work at Ponderosa Places is no longer needed. Erosion white or during future rain events are no longer recommende errace will no longer be instal errace will no longe	BB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has is. Removed d as of the 6/8/23 inspection. Removed led as of the 7/15/22 Active conspection.	/23 inspection. The pleted during basin grate to build an access road inspection, the inspect drained the ponded are poection.		
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 2 Current Condition: EM 3	Good Condition - Paving of diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallat as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Commenseeded and matted by Co Erosion Control Matting Good Condition - Commenseeded and matted by Co Erosion Control Matting	contractor installed a divide in during basin cleand in during basin cleand in some prior to the 11/15/2 to corner of the site and it ion when access road is on, the inspector will most a site of the installation, the diversion in the area, the to some proving in	version from the stub road to so but prior to the 8/3/23 inspection. The diversion via the work at Ponderosa Places in longer needed. Erosion white work at Ponderosa Places in longer needed. Erosion with the properties are no longer recommended are no longer recommended errace will no longer be installerrace will no	BB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has is. Removed das of the 6/8/23 inspection. Removed led as of the 7/15/22 Active inspection. Portions	/23 inspection. The pleted during basin grate to build an access road inspection, the inspect drained the ponded are precion.		
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition:	Good Condition - Paving of diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallat as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Commenseeded and matted by Co Erosion Control Matting Good Condition - Commenseeded and matted by Co Erosion Control Matting	contractor installed a divide in during basin cleand in during basin cleand in some prior to the 11/15/2 to corner of the site and it ion when access road is on, the inspector will most a site of the installation, the diversion in the area, the to some proving in	version from the stub road to so but prior to the 8/3/23 inspection. The diversion via the work at Ponderosa Places in longer needed. Erosion whiter during future rain events are no longer recommende errace will no longer be installerrace will no longer	BB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has is. Removed das of the 6/8/23 inspection. Removed led as of the 7/15/22 Active inspection. Portions	/23 inspection. The pleted during basin grate to build an access road inspection, the inspect drained the ponded are precion.		
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 2 Current Condition: EM 3	Good Condition - Paving of diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallat as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Commenseeded and matted by Co Erosion Control Matting Good Condition - Commenseeded and matted by Co Erosion Control Matting	contractor installed a divide in during basin cleand in during basin cleand in some prior to the 11/15/2 to corner of the site and it ion when access road is on, the inspector will most a site of the inspector	version from the stub road to 3 but prior to the 8/3/23 inspection. The diversion via the work at Ponderosa Places in longer needed. Erosion white work at Ponderosa Places in longer needed. Erosion with the properties are no longer recommended as are no longer recommended errace will no longer be installerrace will n	BB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has is. Removed das of the 6/8/23 inspection. Removed led as of the 7/15/22 Active inspection. Portions	/23 inspection. The pleted during basin grate to build an access road inspection, the inspect drained the ponded are precion.		
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 2 Current Condition: EM 3	Good Condition - Paving of diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallat as of the 2/28/24 inspection in the diversions regrading of the southeas will recommend reinstallat as of the 2/28/24 inspection in the diversions removed - Due to utility in the diversions resident of the diversion control Terrace removed - Due to active resion Control Terrace removed - Due to active resion Control Terrace removed - Due to active resion Control Matting resident of the diversion control matting resion Condition - Commensions resident resions control Matting resions control Matting resions condition - Commensions resident resions resident residen	contractor installed a divide in during basin cleand in during basin cleand in some prior to the 11/15/2 to corner of the site and it ion when access road is on, the inspector will most a site of the inspector	version from the stub road to 3 but prior to the 8/3/23 inspection. The diversion via the work at Ponderosa Places in longer needed. Erosion white work at Ponderosa Places in longer needed. Erosion with the properties are no longer recommended as are no longer recommended errace will no longer be installerrace will n	BB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has is. Removed das of the 6/8/23 inspection. Removed led as of the 7/15/22 Active inspection. Portions	/23 inspection. The pleted during basin grate to build an access road inspection, the inspect drained the ponded are precion.		
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 2 Current Condition: EM 3 Current Condition:	Good Condition - Paving of diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallat as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Commenseeded and matted by Co Erosion Control Matting Good Condition - Commenseeding and matting prior Erosion Control Matting	contractor installed a divide in during basin cleand in during basin cleand in some prior to the 11/15/2 to corner of the site and it icon when access road is on, the inspector will most a stallation, the diversion N of SB D paving in the area, the to N of SB B paving in the area, the to N of SB B paving in the area, the to Northwest Side roial Seeding installed the mercial Seeding installed the Northeast Side roial Seeding installed the to the 4/27/23 inspection Southwest Corner	version from the stub road to so but prior to the 8/3/23 inspection. The diversion value work at Ponderosa Places in longer needed. Erosion white work at Ponderosa Places in longer needed. Erosion with the properties are no longer recommended as are no longer recommended errace will no longer be installerrace will no	BB A prior to the 3/23 on, repair will be com vas partially removed prior to the 12/13/23 through the berm has be a soft the 6/8/23 ins Removed led as of the 6/8/23 ins Removed led as of the 7/15/22 Active an active an active action. Portions active a inspection. Sudbeck active	/23 inspection. The pleted during basin gra to build an access road inspection, the inspect drained the ponded ar pection.		

Current Condition:	Good Condition - The ero	sion control matting will	be installed within the seeding	a window when the as	sociated area reaches final
Current Condition.		•	will begin soon as of the 5/3/	•	
			work is complete. Seeding of		
			e as of the 8/29/22 inspection		
			finish grading along 72nd Streeded/matted the slope prior		
			pe prior to the 5/4/23 inspect		
			n, the inspector will continue		
	time.				
FT 1	Fuel Tank	SW Corner		Removed	
Current Condition:	Removed - DEJ removed		7/15/22 inspection.	D	
FT 2 Current Condition:	Fuel Tank Removed - TAB removed	Material Storage Area	A/7/22 inspection	Removed	
FT 3	Fuel Tank	Material Storage Area	4/1/22 Irispection.	Removed	
Current Condition:	Removed - RPL removed		114/22 inspection.		
FT 4	Fuel Tank	Material Storage Area		Removed	
Current Condition: FT 5	Removed - The fuel tank v Fuel Tank		e 5/18/22 inspection.	Domoved	
Current Condition:	Removed - The fuel tank	Material Storage Area	7/8/22 inspection	Removed	
FT 6	Fuel Tank	On Site	770/22 mapeonon.	Removed	
Current Condition:	Removed - Kersten remov	ed the fuel tank prior to	the 11/4/22 inspection.		
FT 7	Fuel Tank	On Site		Removed	
Current Condition: TEMP IPs XX	Removed - Ruff Grading r Inlet Protection	emoved the fuel tank pr Schram Road	for to the 12/20/23 inspection 10/5/2023	Active	No
Current Condition:			let filters along the south side		-
		•	rior to the 11/2/23 inspection.	•	·
			al Seeding cleaned out the inl		/28/24 inspection.
	Commercial Seeding clea	ned out the inlet filters p	rior to the 5/29/24 inspection.		
Lot 14	Individual Lot	Lot 14	2/8/2024	Active	No
Current Condition:			on on the lot prior to the 2/8/2		
	1.	•	The lot is relatively flat in the s are required. The majority		. , , ,
			wn a portable toilet on the lot		
		9/24 inspection. Hallmarl	K Homes stood up and secure	ed the portable toilet p	rior to the inspection on
1	6/5/24.	1	0/5/0004	1	
Lot 19 Current Condition:	Individual Lot	Lot 19 ler began excavation on	6/5/2024 the lot prior to the 6/5/24 insp	Active	No Probserved in the ROW
Current Condition.			I monitor for BMP installation		s observed in the NOW
Lot 20	Individual Lot	Lot 20	6/12/2024	Active	No
Current Condition:			lot prior to the 6/12/24 inspe		observed in the ROW
1 -4 07		•	onitor for removal and the ins		
Lot 67 Current Condition:	Individual Lot Removed - Legacy Home:	Lot 67	the 11/29/23 inspection	Removed	
Lot 68	Individual Lot	Lot 68	ino 11/20/20 inopodion.	Removed	
Current Condition:		s removed the portable t	oilet prior to the 12/20/23 insp	pection. The lot is ina	ctive.
MS 1	Material Storage	On Site		Removed	
Current Condition:		evelopment is mostly co	mplete, material storage will b	e addressed on a lot l	by lot basis as of the
	11/4/22 inspection.	0.03			ı
PB X Current Condition:	Portable Bathroom	On Site	oilet from the site prior to the	Removed	
PB Y	Portable Bathroom	On Site	onor from the site prior to the	Removed	
Current Condition:			et prior to the 1/4/24 inspecti		
SB A	Sediment Basin	X24	5/11/2022	Active	No
Current Condition:			ug out prior to the 12/1/21 ins		
		•	2 inspection. The riser was insection. E&A inspector painted the contract.	•	·
	· ·	•	sin and should remain in plac		
			n the eastern phase begins. E	•	
		•	/27/23 inspection. DEJ instal		•
			n slopes prior to the 11/29/23		- ·
		•	the basin was observed during future development of Pha	-	on, no maintenance is
SB B	Sediment Basin	O24	5/18/2022	Active	No
Current Condition:			partially dug out prior to the		
Carroni Condition			rap appears to have been in	•	=
			21/22 inspection. Dewatering		
		•	r painted the cleanout mark of		·
			ior to the 10/5/23 inspection. nmercial Seeding repaired the	7	
	pagin giopes prior to tile 1	meoreo mopeodon. Our	iiiioroidi Oseding repaired liil	o samo prior to tric 4/1	mer mopoulon.
SB C	Sediment Basin	H24	5/18/2022	Active	No
55 6	Codiment Basin	1147	0,10,2022	7.00.00	1.0

Current Condition:	Good Condition - 10% Filled - The basin was dug out prior to the 11/12/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. Dewatering holes appear to have been installed in the riser prior to the 5/18/22 inspection. The E&A inspector painted the cleanout mark on 5/23/22. DEJ cleaned out the basin prior to the 6/29/23 inspection. DEJ installed the baffle prior to the 10/5/23 inspection. Commercial Seeding seeded and matted the basin slopes prior to the 11/29/23					
	•	•	ted the remaining portions of			
SB D	Sediment Basin	H22	5/18/2022	Active	No	
Current Condition:	Good Condition - 10% Filled - The basin was in the process of being dug out during the 11/4/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. The old area inlet was removed prior to the 4/21/22 inspection. Dewatering holes appear to have been installed in the riser prior to the 5/18/22 inspection. The basin was in the process of being cleaned out during the 7/27/23 inspection. The basin was cleaned out and the correct depth achieved as of the 8/3/23 inspection. DEJ installed the baffle prior to the 10/5/23 inspection. Commercial Seeding seeded and matted the basin slopes prior to the 11/29/23 inspection. The damaged baffle was removed by Commercial Seeding prior to the 3/13/24 inspection, reinstallation is not needed due to adequate stabilization of the surrounding area.					
SB E	Sediment Basin	D19	5/3/2022	Active	No	
Current Condition:			ially dug out prior to the 12/1/2 aspection. The E&A inspector			
SF 1	Silt fence	Northern/Western Perimeter	5/18/2021	Active	No	
Current Condition:	extension of the silt fence north side of the entrance 4/7/22 inspection. The silt the 6/24/22 inspection. Th NW of SB D prior to the 6/7/8/22 inspection. Sudber and extended the silt fence fence north of Schram prio 4/20/23 inspection. Sudbe 6/8/23 inspection. Papio Falong S 72nd Street south about plowing in the area.	to the north prior to the prior to the 4/7/22 inspect fence was removed in the water contractor remission of Schröder and the water contractor remission of Schröder and the second from the 12/8/22 inspect the seck installed additional separk LLC repaired the sign of Schram was in the passing from the silt fence along Sas removed prior to the	ence prior to the 5/18/21 insp 2/2/22 inspection. Sudbeck e- ection. TAB repaired/reinstall- multiple locations, including s- oved the silt fence where dam- leck installed silt fence aroun- ong the north side of Schram p- or to the 9/19/22 inspection. Commercial Seeding rei- silt fence along the top of the silt fence at the top of the slope process of being removed during the silt fence at the top of the slope process of being removed during the silt fence at the top of the slope process of being removed pring 3/13/24 inspection, the only re-	extended the silt fence ad the silt fence along outhwest of SB D, for larged adjacent to the d the flared end section or to the 9/12/22 installed the silt fence slope southeast of 72re prior to the 8/10/23 ing the 12/13/23 inspect to the 12/20/23	e to the south along the 72nd Street prior to the water installation prior to construction entrance and on of SB D prior to the spection. Sudbeck repaired pepaired/reinstalled the silt at the outfall prior to the national schram prior to the enspection. The silt fence action due to City concerns spection. The silt fence	
SF 2	Silt fence	Northeastern Perimeter	5/25/2021	Active	No	
Current Condition:	Fair Condition - The developer installed the silt fence prior to the 5/25/21 inspection. Sudbeck reinforced the silt fence with additional posts in the northeast corner of the site. Sudbeck removed the silt fence in upgradient areas and repaired the silt fence in the northeast corner of the site prior to the 4/6/23 inspection. Sudbeck reinstalled the silt fence and new silt fence checks prior to the 6/8/23 inspection. The silt fence was damaged by excessive water from the adjoining property prior to the 6/22/23 inspection, repair is not recommended at this time, remaining control will be addressed during grading of Phase II. The area where the silt fence is located is adequately vegetated as of the 10/12/23 inspection, erosion repair and silt fence maintenance will be conducted during Phase II grading, no pollution concerns at this time.					
SF 3	Silt fence	Southeast Corner		Removed		
Current Condition:	Removed - The silt fence not recommended.	was removed during gra	ading of the project to the sou	th prior to the 2/8/24 in	nspection, reinstallation is	
SF 4 Current Condition:	Silt fence Southwest Perimeter 5/18/2021 Active No Fair Condition - The developer installed the silt fence prior to the 5/18/21 inspection. Gene Graves installed silt fence around the Ponderosa Drive connection prior to the 10/13/21 inspection. Sudbeck installed high porosity silt fence checks in the flow line of the swale prior to the 4/7/22 inspection. The silt fence was partially removed at the future Ponderosa entrance along 72nd Street for storm sewer work prior to the 5/18/22 inspection. Some of the silt fence was temporarily removed for water installation prior to the 9/27/22 inspection. The damaged portions of silt fence were removed prior to the 11/4/22 inspection. Commercial Seeding reinstalled the silt fence checks in the swale prior to the 12/8/22 inspection and installed perimeter silt fence in the area prior to the 12/8/22 inspection. Commercial Seeding reinforced the silt fence in the swale and installed additional silt fence to protect the drainage prior to the 3/30/23 inspection. Commercial Seeding cleaned out and repaired the silt fence checks north of the culvert and installed additional protection prior to the 5/4/23 inspection. The silt fence in the swale along Ponderosa is in fair condition as of the 5/4/23 inspection, however, to avoid disturbing growing vegetation, no maintenance is recommended at this time. OPPD damaged and removed portions of the silt fence prior to the 5/18/23 inspection, additional repairs will be recommended after OPPD work is complete. Papio Park LLC cleaned out the silt fence south of Ponderosa Drive prior to the 8/10/23 inspection. Commercial Seeding repaired/reinstalled the silt fence north of Ponderosa Drive prior to the 8/10/23 inspection. Some of the silt fence along the southern perimeter of the site is significantly damaged as of the 2/8/24 inspection; however, due to imminent grading of the project to the south and removal of the silt fence, no maintenance is recommended. Commercial Seeding removed the damaged portions of silt fence along 72nd St					
	72nd Street for storm sew installation prior to the 9/2 Commercial Seeding reins fence in the area prior to tl additional silt fence to prot silt fence checks north of along Ponderosa is in fair maintenance is recommer inspection, additional repa south of Ponderosa Drive Ponderosa Drive prior to tl damaged as of the 2/8/24 no maintenance is recomm seeded/matted the area piremoved prior to the 7/10// Ponderosa Swale were ob	er work prior to the 5/18 7/22 inspection. The dastalled the silt fence checked the 12/8/22 inspection. (It the culvert and installed condition as of the 5/4/2 hirs will be recommended prior to the 8/10/23 inspection; however, during the 17/23 inspection; however, during the 18/13/24 inspection to the 3/13/24 inspection to the 3/13/24 inspection, reinstalla	M22 inspection. Some of the samaged portions of silt fence was in the swale prior to the 1 Commercial Seeding reinforce to the 3/30/23 inspection. Con additional protection prior to the 23 inspection; however, to avoid a after OPPD work is complet to exist of the silt fence along the to imminent grading of the eeding removed the damaged ction. All silt fence except for tion is not recommended. Mile	oved at the future Ponsilt fence was tempora were removed prior to 2/8/22 inspection and at the silt fence in the inmercial Seeding clea the 5/4/23 inspection. bid disturbing growing ons of the silt fence p e. Papio Park LLC cl repaired/reinstalled the ne southern perimeter project to the south ar al portions of silt fence silt fence checks in the or damage to the silt	derosa entrance along arily removed for water the 11/4/22 inspection. installed perimeter silt swale and installed ned out and repaired the The silt fence in the swale vegetation, no rior to the 5/18/23 eaned out the silt fence he silt fence north of of the site is significantly and removal of the silt fence, along 72nd Street and he Ponderosa Swale was fence checks in the	

Current Condition:	Fair Condition - Sudbeck installed the silt fence prior to the 11/4/22 inspection. Sudbeck repaired and reinforced the silt fence prior to the 3/30/23 inspection. Sudbeck extended and repaired the silt fence prior to the 6/8/23 inspection. OPPD damaged and removed portions of the silt fence prior to the 6/8/23 inspection, additional repairs will be recommended after OPPD work is complete. Commercial Seeding repaired the silt fence prior to the 8/17/23 inspection. Commercial Seeding repaired the silt fence prior to the 11/29/23 inspection. The silt fence needs to be cleaned out/repaired in multiple locations.					
			approval on 5/23/24 prior to h	0	. ,	
	done as of the last inspec	ction. Commercial Seedi	ing to complete during return	to site for seeding as t	or the 1/10/24 inspection.	
SF 6	Silt fence	NE S 70th and Flint		Removed		
Current Condition:	Removed - Commercial S		fence and seeded/matted the	area prior to the 3/13	/24 inspection.	
SF 7	Silt fence	NE S 70th and Stony		Removed		
Current Condition:			fence and seeded/matted the			
SF 8	Silt fence	NW of SB C	12/8/2022	Active	No	
Current Condition:	portions of the silt fence p Due to utility work as of th will be removed when wo	orior to the 6/8/23 inspection, the 8/17/23 inspection, the rk is complete. The E&P aspection so that repairs	ne silt fence prior to the 12/8/2 tion, additional repairs will be e silt fence will not be repaired inspector inquired with the can be conducted. Commercan	recommended after Cd; the area is well vegonstruction observer i	PPPD work is complete. etated and the silt fence f OPPD is complete in the	
SF 9	Silt fence	NE Corner of 72nd and Schram		Removed		
Current Condition:		•	naining portions of the silt fendaround the utilities prior to the	•	inspection. Commercial	
STR	Streets	S 72nd Street	5/18/2021	Active	Yes	
	The streets in front of lo					
SW 1	Straw Wattles	72nd ROW		Removed		
Current Condition:	Removed - Sudbeck removed	oved the wattles during o	grading prior to the 4/6/23 insp in place where necessary.		ll be seeded and matted b	
SWPPP Sign	Misc/Other	S 72nd and Schram	5/18/2021	Active	No	
Current Condition:		A inspector installed the	SWPPP sign in the southwes led at S 72st Street and Schra			
WO 1	Concrete Washout	On Site		Removed		
Current Condition:			ncrete waste on site prior to t		I	
WS 1	Waste Storage	On Site		Removed		
Current Condition:	<u> </u>		on materials, portable toilets a		arate BMPs in the BMP	
Certification Statement:	accordance with a system submitted. Based on my i gathering the information,	n designed to assure tha nquiry of the person or p , the information submitte	and all attachments were pre t qualified personnel properly persons who manage the systed is, to the best of my knowled ubmitting false information inc	gathered and evaluate em or those persons of edge and belief, true, a	ed the information directly responsible for accurate, and complete. I	
spector Signature:	Jule Short			Reviewed By:	Get Sie	