E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

E&A - P2018.228.001 Bill SID as of 2/17/22 P2018.228.000

			1/22 1 2010.220.000			
Inspector: Jason Brackett					Stage	
Project Name:		Seventy Two Place PAP-20200624-5346-GP1 CSW-202004796				
-						
For Week Ending:		8/17/2024 12101 S 72nd St, Papillion, Sarpy County, NE				
Project Location:						
Grading:	80%					
Sanitary Sewer:	100%	,				
Storm Sewer:	95%					
Paving:	80%					
Seeding:	80%					
Jtilities:	80%					
Overall Development:	47%	,				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time		
Sunday:	0.00"				We	
Monday:	1.20"				1:55 AM - 5:55 AM	
Tuesday:	0.00"				1:33 AW - 3:33 AW	
Wednesday:	2.66"				2:35 AM - 5:55 AM	
Thursday:	0.00"					
riday:	0.00"	8/16/2024	Partly Cloudy 87/63	10:30 AM		
Saturday:	0.00"					

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Rough grading began (6/15/21). Excavation for sanitary installation (9/28/21). Grading ceased due to winter conditions (1/5/22). Excavation for utility connections along 72nd (2/8/22). Grading for roadways (6/9/22). Lot 3 Replat 1 and Lot 4 Replat 1 scraping (11/2/22). Riprap installation and regrading at \$ 70th Street stub (11/2/22). Swale and ROW along Ponderosa connection finish graded (11/4/22). Swale and ROW along Ponderosa grading ceased (12/1/22). Basin cleanouts and processing silt began (8/3/23). Basin cleanouts completed (10/26/23). Sidewalk paving began (10/26/23). Sidewalk paving complete (11/8/23). Regrading of southeast corner lots (12/6/23). All grading ceased due to winter conditions (1/4/24). Re-grading of sidewalk replacements (6/19/24).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading began (6/15/21). Excavation for sanitary installation (9/28/21). Grading ceased due to winter conditions (1/5/22). Excavation for utility connections along 72nd (2/8/22). Grading for roadways (6/9/22). Lot 3 Replat 1 and Lot 4 Replat 1 scraping (11/2/22). Riprap installation and regrading at S 70th Street stub (11/2/22). Swale and ROW along Ponderosa connection finish graded (11/4/22). Swale and ROW along Ponderosa grading ceased (12/1/22). Basin cleanouts and processing silt began (8/3/23). Basin cleanouts completed (10/26/23). Sidewalk paving began (10/26/23). Sidewalk paving complete (11/8/23). Regrading of southeast corner lots (12/6/23). All grading ceased due to winter conditions (1/4/24). Re-grading of sidewalk replacements (6/19/24).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (6/15/21). Disking/seeding east side of site (7/8/22). Lot 1, 2, 3 - seeded (11/10/22). Seeding and matting swale and ROW along Ponderosa and Schram/72nd medians and ROWs (12/8/22). Seeding/matting sidewalk disturbances began (11/8/23). Basin slopes seeded/matted (11/29/23). SE of S 72nd Street and Schram seeding/matting (12/13/23). Commercial Seeding seeded/matted portions of disturbance around sidewalk construction, light pole installation, and utility work (3/13/24). Commercial Seeding seeded/matted the northeast corner of 72nd and Schram (3/20/24). Re-seeding and matting around sidewalk replacements (6/19/24).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion

Create Corrective Action?

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

N/A

No, see BMPs section.

s dust associated with the construction activity adequately controlled on the site?

Create Corrective Action?

N/A

Comments:

Comments:

The site was inactive during the most recent inspection. Lot 5 and 6 Replat 1 have been removed from this SWPPP and are covered by PAP-20220310-6351-GP1.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section of this report.
- 2) Disturbed areas of the north side of the Ponderosa Swale should be stabilized and the old silt fence removed when Vestara construction is complete. The inspector will continue to monitor and recommend maintenance when Vestara construction complete as of the 3/6/24 inspection.
- 3) Disturbed areas of poor vegetation growth need to be re-seeded and matted along the south side of Schram Road. The inspector sent a plan to Papio Park, LLC for approval on 5/23/24 prior to hiring a contractor to complete by 5/29/24. Not done as of the last inspection. Contractor hired prior to the 5/29/24 inspection. Contractor to complete erosion repair ASAP and permanent seeding in the Fall seeding window as of the 7/10/24 inspection.

	Type	Location	Projected Install Date	Status	Maintenance		
Unique Name CE 1	Construction Entrance	Schram Road	1 Tojecteu mstan Bute	Removed	Mantenance		
Current Condition:			L s of the 8/29/22 inspection du		the Sehrem Bood		
Current Condition.	connection.	wiii no longer be used a	s of the 6/29/22 inspection du	e to the completion of	the Schlam Road		
D 1	Diversion	E of SB C	11/12/2021	Active	No		
Current Condition:	Good Condition - DEJ inst	talled the diversion prior	to the 11/12/21 inspection. S	Sudbeck was in the pro	ocess of cleaning out the		
	diversion during the 6/30/22 inspection. Sudbeck maintained the diversion prior to the 7/8/22 inspection. The diversion was removed at the S 70th stub prior to the 8/29/22 inspection, the inspector will monitor the need for reinstallation.						
D 2	Diversion	S of SB D	T	Removed			
Current Condition:			I ne Vestara Apartments, the di		le to be installed as of the		
Current Condition.	6/8/23 inspection.	ilai bivii 3 ilistalied loi ti	ie vestara Apartments, trie di	version no longer need	ds to be installed as of the		
D 3	Diversion	N of SB D	6/8/2023	Active	No		
Current Condition:			prior to the 6/8/23 inspection.				
Current Condition.			sion does not need to be reins				
D 4	Diversion	E and SB B		Removed			
Current Condition:	Removed - Re-grading of reinstallation is not require	,	in the area has removed the	diversion as of the 2/8	8/24 inspection,		
D 5	Diversion	Northwest Perimeter		Removed			
Current Condition:	Removed - The diversion	is not needed due to ex	isting contours as of the 5/3/2	2 inspection.	•		
D 6	Diversion	Western Perimeter		Removed			
Current Condition:	Removed - The remaining	portions of Schram have	ve been installed as of the 3/2	3/23 inspection. Reco	mmendations for swale		
	regrading are included in t	the Findings section of t	his report.				
D 7	Diversion	Stub to SB A	3/23/2023	Active	No		
Current Condition:			ersion from the stub road to S				
	diversion was partially filled in during basin cleanout prior to the 8/3/23 inspection, repair will be completed during basin grading. DEJ reinstalled the diversions prior to the 11/15/23 inspection. The diversion was partially removed to build an access road for regrading of the southeast corner of the site and new work at Ponderosa Place prior to the 12/13/23 inspection, the inspector will recommend reinstallation when access road is no longer needed. Erosion through the berm has drained the ponded area as of the 2/28/24 inspection, the inspector will monitor during future rain events.						
	regrading of the southeas will recommend reinstallat	ions prior to the 11/15/2 t corner of the site and r ion when access road is	3 inspection. The diversion we new work at Ponderosa Place s no longer needed. Erosion t	as partially removed t prior to the 12/13/23 i	o build an access road for nspection, the inspector		
D 8	regrading of the southeas will recommend reinstallat	ions prior to the 11/15/2 t corner of the site and r ion when access road is	3 inspection. The diversion we new work at Ponderosa Place s no longer needed. Erosion t	as partially removed t prior to the 12/13/23 i	o build an access road for nspection, the inspector		
D 8 Current Condition:	regrading of the southeas will recommend reinstallat of the 2/28/24 inspection, Diversions	ions prior to the 11/15/2 t corner of the site and r ion when access road is the inspector will monito SB E	3 inspection. The diversion we new work at Ponderosa Place s no longer needed. Erosion t	as partially removed to prior to the 12/13/23 in hrough the berm has a Removed	o build an access road for nspection, the inspector drained the ponded area as		
	regrading of the southeas will recommend reinstallat of the 2/28/24 inspection, Diversions	ions prior to the 11/15/2 t corner of the site and r ion when access road is the inspector will monito SB E estallation, the diversion	3 inspection. The diversion we work at Ponderosa Place so longer needed. Erosion to during future rain events.	as partially removed to prior to the 12/13/23 in hrough the berm has a Removed	o build an access road for nspection, the inspector drained the ponded area as		
Current Condition:	regrading of the southeas will recommend reinstallat of the 2/28/24 inspection, Diversions Removed - Due to utility in Erosion Control Terrace	ions prior to the 11/15/2 t corner of the site and r ion when access road is the inspector will monite SB E stallation, the diversion N of SB D	3 inspection. The diversion we work at Ponderosa Place so longer needed. Erosion to during future rain events.	as partially removed to prior to the 12/13/23 in hrough the berm has a Removed as of the 6/8/23 insparenced.	o build an access road for nspection, the inspector drained the ponded area as ection.		
Current Condition: ET 1	regrading of the southeas will recommend reinstallat of the 2/28/24 inspection, Diversions Removed - Due to utility in Erosion Control Terrace	ions prior to the 11/15/2 t corner of the site and r ion when access road is the inspector will monite SB E nstallation, the diversion N of SB D paving in the area, the t	3 inspection. The diversion water work at Ponderosa Place is no longer needed. Erosion to during future rain events. I sare no longer recommended.	as partially removed to prior to the 12/13/23 in hrough the berm has a Removed as of the 6/8/23 insparenced.	o build an access road for nspection, the inspector drained the ponded area as ection.		
Current Condition: ET 1 Current Condition:	regrading of the southeas will recommend reinstallat of the 2/28/24 inspection, Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace	ions prior to the 11/15/2 t corner of the site and r ion when access road is the inspector will monite SB E installation, the diversion N of SB D paving in the area, the t paving in the area, the te	3 inspection. The diversion water work at Ponderosa Place is no longer needed. Erosion to during future rain events. I sare no longer recommended.	as partially removed to prior to the 12/13/23 in hrough the berm has a Removed as of the 6/8/23 insparenced as of the 7/15/22 in Removed	o build an access road for nspection, the inspector drained the ponded area as ection.		
Current Condition: ET 1 Current Condition: ET 2	regrading of the southeas will recommend reinstallat of the 2/28/24 inspection, Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Erosion Control Terrace	ions prior to the 11/15/2 t corner of the site and r ion when access road is the inspector will monito SB E stallation, the diversion N of SB D paving in the area, the t N of SB E paving in the area, the t N of SB B	3 inspection. The diversion whew work at Ponderosa Place is no longer needed. Erosion to during future rain events. s are no longer recommended between the process are no longer recommended between the process are no longer be install between the process are not longer	as partially removed to prior to the 12/13/23 in hrough the berm has a Removed as of the 6/8/23 insparence as of the 7/15/22 in Removed ed as of the 7/15/22 in Removed	o build an access road for nspection, the inspector drained the ponded area as ection.		
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition:	regrading of the southeas will recommend reinstallat of the 2/28/24 inspection, Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Removed - Due to active	ions prior to the 11/15/2 t corner of the site and r ion when access road is the inspector will monito SB E stallation, the diversion N of SB D paving in the area, the t N of SB B paving in the area, the t N of SB B paving in the area, the t	3 inspection. The diversion was work at Ponderosa Place is no longer needed. Erosion to during future rain events. Is are no longer recommended errace will no longer be install	Removed as of the 6/8/23 insp Removed as of the 6/8/23 insp Removed ed as of the 7/15/22 ir Removed ed as of the 7/15/22 ir Removed ed as of the 7/15/22 ir	o build an access road for nspection, the inspector drained the ponded area as ection.		
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4	regrading of the southeas will recommend reinstallat of the 2/28/24 inspection, Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace	ions prior to the 11/15/2 t corner of the site and r ion when access road is the inspector will monito SB E stallation, the diversion N of SB D paving in the area, the t N of SB E paving in the area, the t N of SB B paving in the area, the t East Central	3 inspection. The diversion whew work at Ponderosa Place is no longer needed. Erosion to during future rain events. s are no longer recommended errace will no longer be install	Removed as of the 6/8/23 insp Removed d as of the 6/8/23 insp Removed ed as of the 7/15/22 ir Removed	o build an access road for nspection, the inspector drained the ponded area as ection. pspection. pspection. pspection. pspection.		
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition:	regrading of the southeas will recommend reinstallat of the 2/28/24 inspection, Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active	ions prior to the 11/15/2 t corner of the site and r ion when access road is the inspector will monito SB E Installation, the diversion N of SB D paving in the area, the t N of SB E paving in the area, the t SP SB E Paving in the area, the t East Central paving in the area, the t	3 inspection. The diversion whew work at Ponderosa Place is no longer needed. Erosion to during future rain events. Is are no longer recommended. Errace will no longer be install.	Removed as of the 7/15/22 ir Removed ed as of the 7/15/22 ir	o build an access road for nspection, the inspector drained the ponded area as ection. cection. nspection. nspection. nspection. nspection.		
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 4 Current Condition: EM 1	regrading of the southeas will recommend reinstallat of the 2/28/24 inspection, Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace	ions prior to the 11/15/2 t corner of the site and r ion when access road is the inspector will monite SB E Installation, the diversion N of SB D paving in the area, the t N of SB B paving in the area, the t East Central paving in the area, the t Northwest Side	3 inspection. The diversion when work at Ponderosa Place is no longer needed. Erosion to during future rain events. Is sare no longer recommended errace will no longer be install	as partially removed to prior to the 12/13/23 in hrough the berm has a series of the 6/8/23 insport of the 6/8/23 insport of the 6/8/23 insport of the 7/15/22 in Removed ed as of the 7/15/22 in Active	o build an access road for nspection, the inspector drained the ponded area as ection. spection. spection. spection. spection. spection. spection.		
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition:	regrading of the southeas will recommend reinstallat of the 2/28/24 inspection, Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme	ions prior to the 11/15/2 t corner of the site and r ion when access road is the inspector will monite SB E stallation, the diversion N of SB D paving in the area, the t N of SB B paving in the area, the t East Central paving in the area, the t Northwest Side rcial Seeding installed the	3 inspection. The diversion whew work at Ponderosa Place is no longer needed. Erosion to during future rain events. s are no longer recommended errace will no longer be install matter will no longer be install errace will no longer be install errace will no longer be install matter will no longer be install errace will no longer be install matter will no longer be install errace will no longer be install matter will no longer be install errace will no longer be install errace will no longer be install matter will no longer be install errace will errac	as partially removed to prior to the 12/13/23 in hrough the berm has a series of the 6/8/23 insport of the 6/8/23 insport of the 6/8/23 insport of the 7/15/22 in Removed ed as of the 7/15/22 in Active	o build an access road for nspection, the inspector drained the ponded area as ection. spection. spection. spection. spection. spection. spection.		
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition:	regrading of the southeas will recommend reinstallat of the 2/28/24 inspection, Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co	ions prior to the 11/15/2 t corner of the site and r ion when access road is the inspector will monite SB E stallation, the diversion N of SB D paving in the area, the t N of SB B paving in the area, the t East Central paving in the area, the t Northwest Side rcial Seeding installed tr mmercial Seeding prior	3 inspection. The diversion when work at Ponderosa Place is no longer needed. Erosion to during future rain events. s are no longer recommended errace will no longer be install 7/15/2022 he matting prior to the 7/15/22 to the 12/8/22 inspection.	Removed I as of the 6/8/23 insp Removed I as of the 6/8/23 insp Removed I as of the 7/15/22 ir Removed I Remo	o build an access road for nspection, the inspector drained the ponded area as ection. spection. spection. spection. spection. spection. spection. No of the slope were re-		
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition:	regrading of the southeas will recommend reinstallat of the 2/28/24 inspection, Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co	ions prior to the 11/15/2 t corner of the site and r ion when access road is the inspector will monite. SB E stallation, the diversion N of SB D paving in the area, the t N of SB E paving in the area, the t East Central paving in the area, the t Northwest Side roial Seeding installed the mmercial Seeding prior North-Central	3 inspection. The diversion whew work at Ponderosa Place is no longer needed. Erosion to during future rain events. S are no longer recommended errace will no longer be install 7/15/2022 to the 12/8/22 inspection.	Removed I as of the 6/8/23 insp Removed I as of the 6/8/23 insp Removed I as of the 7/15/22 ir Removed I Active I Active	o build an access road for nspection, the inspector drained the ponded area as ection. spection. spection. spection. spection. spection. No		
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition:	regrading of the southeas will recommend reinstallat of the 2/28/24 inspection, Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme Good Condition - Comme	ions prior to the 11/15/2 t corner of the site and r ion when access road is the inspector will monitor. SB E stallation, the diversion N of SB D paving in the area, the t N of SB B paving in the area, the t East Central paving in the area, the t Northwest Side roial Seeding installed the mercial Seeding installed the roial seeding ins	3 inspection. The diversion whew work at Ponderosa Place is no longer needed. Erosion to during future rain events. Is are no longer recommended errace will no longer be install 7/15/2022 to the 12/8/22 inspection. 7/15/2022 to the 12/8/22 inspection.	Removed I as of the 6/8/23 inspection. Removed I as of the 6/8/23 inspection. Removed I as of the 6/8/23 inspection. Removed I as of the 7/15/22 in Active I active Inspection.	o build an access road for nspection, the inspector drained the ponded area as ection. ection. inspection. inspection.		
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 3	regrading of the southeas will recommend reinstallat of the 2/28/24 inspection, Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme Good Condition - Comme Erosion Control Matting Good Condition - Comme	ions prior to the 11/15/2 t corner of the site and r ion when access road is the inspector will monito. SB E stallation, the diversion N of SB D paving in the area, the t N of SB B paving in the area, the t East Central paving in the area, the t Northwest Side North-Central roal Seeding installed the North-Central roal Seeding installed the Northeast Side	3 inspection. The diversion whew work at Ponderosa Place is no longer needed. Erosion to during future rain events. s are no longer recommended errace will no longer be install 7/15/2022 to the 12/8/22 inspection. 7/15/2022 The matting prior to the 7/15/22 to the 17/15/2022 The matting prior to the 7/15/22 to the 17/15/2022	Removed I as of the 6/8/23 insp Removed I as of the 6/8/23 insp Removed I as of the 7/15/22 ir Active I active	o build an access road for nspection, the inspector drained the ponded area as ection. ection. inspection. inspection.		
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition:	regrading of the southeas will recommend reinstallat of the 2/28/24 inspection, Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co Erosion Control Matting Good Condition - Comme Erosion Control Matting	ions prior to the 11/15/2 t corner of the site and r ion when access road is the inspector will monito. SB E stallation, the diversion N of SB D paving in the area, the t N of SB E paving in the area, the t East Central paving in the area, the t Northwest Side road Seeding prior North-Central road Seeding installed the Northeast Side road Seeding installed the Road Seeding Inst	3 inspection. The diversion whew work at Ponderosa Place is no longer needed. Erosion to during future rain events. Is are no longer recommended errace will no longer be install 7/15/2022 to the 12/8/22 inspection. 7/15/2022 to the 12/8/22 inspection.	Removed I as of the 6/8/23 insp Removed I as of the 6/8/23 insp Removed I as of the 7/15/22 ir Active I active	o build an access road for nspection, the inspector drained the ponded area as ection. ection. inspection. inspection.		
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition:	regrading of the southeas will recommend reinstallat of the 2/28/24 inspection, Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co Erosion Control Matting Good Condition - Comme Erosion Control Matting Good Condition - Comme	ions prior to the 11/15/2 t corner of the site and r ion when access road is the inspector will monito. SB E stallation, the diversion N of SB D paving in the area, the t N of SB E paving in the area, the t East Central paving in the area, the t Northwest Side road Seeding prior North-Central road Seeding prior North-Central road Seeding installed the Northeast Side road Seeding installed the Seeding installed the Seeding installed the Northeast Side road Seeding installed the Road Seeding Installed t	3 inspection. The diversion whew work at Ponderosa Place is no longer needed. Erosion to during future rain events. s are no longer recommended errace will no longer be install 7/15/2022 to the 12/8/22 inspection. 7/15/2022 ne matting prior to the 7/15/22 one matting prior to the 7/15/22	Removed I as of the 6/8/23 insp Removed I as of the 6/8/23 insp Removed I as of the 7/15/22 ir Active I active	o build an access road for nspection, the inspector drained the ponded area as ection. ection. inspection. inspection.		
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 2 Current Condition: EM 3 Current Condition:	regrading of the southeas will recommend reinstallat of the 2/28/24 inspection, Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co Erosion Control Matting Good Condition - Comme Erosion Control Matting Good Condition - Comme Around Matting Good Condition - Comme Erosion Control Matting Good Condition - Comme Around Matting	ions prior to the 11/15/2 t corner of the site and r ion when access road is the inspector will monito SB E installation, the diversion N of SB D paving in the area, the to N of SB E paving in the area, the to SB E paving	3 inspection. The diversion whew work at Ponderosa Place is no longer needed. Erosion to during future rain events. Is are no longer recommended errace will no longer be install 7/15/2022 to the 12/8/22 inspection. 7/15/2022 to the 12/8/22 inspection. 7/15/2022 to matting prior to the 7/15/22 to matting prior to the 7/15/22 to matting prior to the 7/15/22 the matting prior to the 7/15/22 the matting prior to the 7/15/22	as partially removed to prior to the 12/13/23 in hrough the berm has a series of the 6/8/23 insported as of the 6/8/23 insported as of the 7/15/22 in Removed ed as of the 7/15/22 in Active inspection. Portions a series of the 7/15/22 in Active inspection. Sudbeck Active	o build an access road for nspection, the inspector drained the ponded area as ection. ection. inspection. inspection.		
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition:	regrading of the southeas will recommend reinstallat of the 2/28/24 inspection, Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co Erosion Control Matting Good Condition - Comme Erosion Control Matting Good Condition - Comme Around Matting Good Condition - Comme Erosion Control Matting Good Condition - Comme Around Matting	ions prior to the 11/15/2 t corner of the site and r ion when access road is the inspector will monito SB E installation, the diversion N of SB D paving in the area, the to N of SB E paving in the area, the to SB E paving	3 inspection. The diversion whew work at Ponderosa Place is no longer needed. Erosion to during future rain events. s are no longer recommended errace will no longer be install 7/15/2022 to the 12/8/22 inspection. 7/15/2022 ne matting prior to the 7/15/22 one matting prior to the 7/15/22	as partially removed to prior to the 12/13/23 in hrough the berm has a series of the 6/8/23 insported as of the 6/8/23 insported as of the 7/15/22 in Removed ed as of the 7/15/22 in Active inspection. Portions a series of the 7/15/22 in Active inspection. Sudbeck Active	o build an access road for nspection, the inspector drained the ponded area as ection. ection. inspection. inspection.		

Current Condition:		•	be installed within the seeding will begin soon as of the 5/3/			
	matting in the area will be inspection. Water main in the area when installation	temporarily halted until estallation is active on sit is complete. Additional	work is complete. Seeding of te as of the 8/29/22 inspection finish grading along 72nd Stro	the slope is still recor , water contractor will eet to be completed in	mmended as of the 5/3/22 be seeding and matting the Spring of 2023,	
			eeded/matted the slope prior to ope prior to the 5/4/23 inspecti			
	slope was observed during time.	g the 10/12/23 inspectio	n, the inspector will continue t	o monitor, no mainter	nance is required at this	
FT 1	Fuel Tank	SW Corner		Removed		
Current Condition:	Removed - DEJ removed	the fuel tank prior to the	7/15/22 inspection.			
FT 2	Fuel Tank	Material Storage Area		Removed		
Current Condition:	Removed - TAB removed	the fuel tank prior to the	4/7/22 inspection.	-		
FT 3	Fuel Tank	Material Storage Area		Removed		
Current Condition:	Removed - RPL removed		e 114/22 inspection.		1	
FT 4 Current Condition:	Fuel Tank Removed - The fuel tank	Material Storage Area	5/18/22 inspection	Removed		
FT 5	Fuel Tank	Material Storage Area		Removed		
Current Condition:	Removed - The fuel tank			rtemoved		
FT 6	Fuel Tank	On Site	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Removed		
Current Condition:	Removed - Kersten remov		the 11/4/22 inspection.			
FT 7	Fuel Tank	On Site	·	Removed		
Current Condition:			ior to the 12/20/23 inspection.			
TEMP IPs XX	Inlet Protection	Schram Road	10/5/2023	Active	No	
Current Condition:			let filters along the south side			
			rior to the 11/2/23 inspection.			
	Seeding cleaned out the in		ding cleaned out the inlet filter 29/24 inspection.	is prior to the 2/20/24	inspection. Commercial	
Lot 14	Individual Lot	Lot 14	2/8/2024	Active	No	
Current Condition:			ion on the lot prior to the 2/8/2			
			The lot is relatively flat in the			
			s are required. The majority			
			wn a portable toilet on the lot			
		9/24 inspection. Hallman	k Homes stood up and secure	a the portable tollet p	rior to the inspection on	
Lot 19	6/5/24. Individual Lot	Lot 19	6/5/2024	Active	No	
Current Condition:			the lot prior to the 6/5/24 insp			
Guirent Gondition.			I monitor for BMP installation		CODSCIVED III LIIC TOVV	
Lot 20	Individual Lot	Lot 20	6/12/2024	Active	No	
Current Condition:	Active - Legacy Homes be	egan construction on the	lot prior to the 6/12/24 inspec	ction. Dirt piles were	observed in the ROW	
	during the 6/12/24 inspect	tion, the inspector will me	onitor for removal and the inst	tallation of BMPs.		
Lot 25	Individual Lot	Lot 25	8/7/2024	Active	No	
Current Condition:		•	the lot prior to the 8/4/24 insp	•	e observed in the ROW	
1 107			I monitor for BMP installation	·		
Lot 67	Individual Lot	Lot 67	Ab - 44/20/22 :	Removed		
Current Condition: Lot 68	Removed - Legacy Home: Individual Lot	Lot 68	Ine 11/29/23 inspection.	Removed	I	
Current Condition:			toilet prior to the 12/20/23 insp		ctive	
MS 1	Material Storage	On Site		Removed		
Current Condition:			ı mplete, material storage will b		ov lot basis as of the	
	11/4/22 inspection.				,	
PB X	Portable Bathroom	On Site		Removed		
Current Condition:			coilet from the site prior to the		<u> </u>	
PB Y	Portable Bathroom	On Site	I II I II I I I I I I I I I I I I I I	Removed		
Current Condition:			let prior to the 1/4/24 inspection		<u> </u>	
SB A	Sediment Basin	X24	5/11/2022	Active	No	
Current Condition:	Good Condition - 10% - T	he basin was partially du	ug out prior to the 12/1/21 insp	pection. The basin ou	tfall pipe and rip rap	
	appears to have been installed prior to the 4/13/22 inspection. The riser was installed prior to the 5/11/22 inspection. The basin					
	was reshaped prior to the 5/26/22 inspection. The E&A inspector painted the cleanout mark on 5/23/22. The erosion into the					
	basin are the only stormwater diversions to the basin and should remain in place as of the 6/8/23 inspection, additional grading					
	will address these diversions when construction on the eastern phase begins. Basin cleanout began prior to the inspection on 7/20/23. The basin was cleaned out prior to the 7/27/23 inspection. DEJ installed the baffle prior to the 10/5/23 inspection.					
	Commercial Seeding seeded and matted the basin slopes prior to the 11/29/23 inspection. Commercial Seeding repaired the					
	baffle prior to the 4/17/24 inspection. Erosion into the basin was observed during the 7/8/24 inspection, no maintenance is					
	1	•	ing future development of Pha	-	zii, no maintenance is	
SB B	<u> </u>	1	· · · · · · · · · · · · · · · · · · ·	ı	No	
Current Condition:	Sediment Basin	O24	5/18/2022 n partially dug out prior to the	Active 9/14/21 inspection by	No DE L the inspector will	
Current Condition.			rap appears to have been in		· ·	
			21/22 inspection. Dewatering	•	•	
	· •	-	r painted the cleanout mark o			
	li.	•	ior to the 10/5/23 inspection.		·	
	basin slopes prior to the 1	1/29/23 inspection. Cor	mmercial Seeding repaired the	e baffle prior to the 4/1	7/24 inspection.	
	<u> </u>					
SB C	Sediment Basin	H24	5/18/2022	Active	No	

	Good Condition - 10% Filled - The basin was dug out prior to the 11/12/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. Dewatering holes appear to have been installed in the riser prior to the 5/18/22 inspection. The E&A inspector painted the cleanout mark on 5/23/22. DEJ cleaned out the basin prior to the 6/29/23 inspection. DEJ installed the baffle prior to the 10/5/23 inspection. Commercial Seeding seeded and matted the basin slopes prior to the 11/29/23 inspection. Commercial Seeding seeded and matted the remaining portions of the outlot prior to the 3/13/24 inspection.						
SB D	Sediment Basin	H22	5/18/2022	Active	No		
	Good Condition - 10% Filled - The basin was in the process of being dug out during the 11/4/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. The old area inlet was removed prior to the 4/21/22 inspection. Dewatering holes appear to have been installed in the riser prior to the 5/18/22 inspection. The basin was in the process of being cleaned out during the 7/27/23 inspection. The basin was cleaned out and the correct depth achieved as of the 8/3/23 inspection. DEJ installed the baffle prior to the 10/5/23 inspection. Commercial Seeding seeded and matted the basin slopes prior to the 11/29/23 inspection. The damaged baffle was removed by Commercial Seeding prior to the 3/13/24 inspection, reinstallation is not needed due to adequate stabilization of the surrounding area.						
SB E	Sediment Basin	D19	5/3/2022	Active	No		
Current Condition:		·	ially dug out prior to the 12/1/2	•			
SF 1	Silt fence	Northern/Western Perimeter	5/18/2021	Active	No		
	Good Condition - The developer installed the silt fence prior to the 5/18/21 inspection. Sudbeck installed wattles as an extension of the silt fence to the north prior to the 2/2/22 inspection. Sudbeck extended the silt fence to the south along the north side of the entrance prior to the 4/7/22 inspection. TAB repaired/reinstalled the silt fence along 72nd Street prior to the 4/7/22 inspection. The silt fence was removed in multiple locations, including southwest of SB D, for water installation prior to the 6/24/22 inspection. The water contractor removed the silt fence where damaged adjacent to the construction entrance and NW of SB D prior to the 6/30/22 inspection. Sudbeck installed silt fence around the flared end section of SB D prior to the 7/8/22 inspection. Sudbeck installed silt fence along the north side of Schram prior to the 9/12/22 inspection. Sudbeck repaired and extended the silt fence along 72nd Street prior to the 9/19/22 inspection. Commercial Seeding repaired/reinstalled the silt fence north of Schram prior to the 12/8/22 inspection. Commercial Seeding reinstalled the silt fence at the outfall prior to the 4/20/23 inspection. Sudbeck installed additional silt fence along the top of the slope southeast of 72nd and Schram prior to the 6/8/23 inspection. Papio Park LLC repaired the silt fence at the top of the slope prior to the 8/10/23 inspection. The silt fence along S 72nd Street south of Schram was in the process of being removed during the 12/13/23 inspection. The silt fence around the basin outfall was removed prior to the 3/13/24 inspection, the only remaining silt fence under this finding is along the top of the slope southeast of 72nd and Schram.						
SE 3		N. 11 1					
SF 2	Silt fence	Northeastern Perimeter	5/25/2021	Active	No		
Current Condition:	Fair Condition - The devel additional posts in the nor fence in the northeast cor checks prior to the 6/8/23 6/22/23 inspection, repair area where the silt fence is maintenance will be condu	Perimeter oper installed the silt fer theast corner of the site ner of the site prior to th inspection. The silt fen- is not recommended at s located is adequately ucted during Phase II gra	5/25/2021 nce prior to the 5/25/21 inspec . Sudbeck removed the silt fe e 4/6/23 inspection. Sudbeck ce was damaged by excessive this time, remaining control wivegetated as of the 10/12/23 i ading, no pollution concerns a	Lection. Sudbeck reinford ence in upgradient area reinstalled the silt fer e water from the adjoin ill be addressed during inspection, erosion rep t this time.	Leed the silt fence with as and repaired the silt ce and new silt fence ning property prior to the grading of Phase II. The		
Current Condition:	Fair Condition - The devel additional posts in the nor fence in the northeast corr checks prior to the 6/8/23 6/22/23 inspection, repair area where the silt fence is maintenance will be conducted. Silt fence	Perimeter loper installed the silt fer theast corner of the site ner of the site prior to th inspection. The silt fen- is not recommended at s located is adequately ucted during Phase II gra Southeast Corner	nce prior to the 5/25/21 inspect. Sudbeck removed the silt feet e 4/6/23 inspection. Sudbeck ce was damaged by excessive this time, remaining control wivegetated as of the 10/12/23 in ading, no pollution concerns a	ction. Sudbeck reinford ction. Sudbeck reinford the reinstalled the silt fend water from the adjoin ill be addressed during inspection, erosion rep t this time.	ced the silt fence with cas and repaired the silt ce and new silt fence ning property prior to the grading of Phase II. The pair and silt fence		
Current Condition:	Fair Condition - The devel additional posts in the nor fence in the northeast corr checks prior to the 6/8/23 6/22/23 inspection, repair area where the silt fence is maintenance will be conducted. Silt fence	Perimeter loper installed the silt fer theast corner of the site ner of the site prior to th inspection. The silt fen- is not recommended at s located is adequately ucted during Phase II gra Southeast Corner	Ince prior to the 5/25/21 inspect. Sudbeck removed the silt feet e 4/6/23 inspection. Sudbeck ce was damaged by excessive this time, remaining control wivegetated as of the 10/12/23 is	ction. Sudbeck reinford ction. Sudbeck reinford the reinstalled the silt fend water from the adjoin ill be addressed during inspection, erosion rep t this time.	ced the silt fence with cas and repaired the silt ce and new silt fence ning property prior to the grading of Phase II. The pair and silt fence		
SF 3 Current Condition: SF 4 Current Condition:	Fair Condition - The devel additional posts in the normal fence in the northeast corn checks prior to the 6/8/23 6/22/23 inspection, repair area where the silt fence is maintenance will be conducted. Silt fence Removed - The silt fence in the interest of the silt fence not recommended. Silt fence Fair Condition - The devel the Ponderosa Drive connument of the swale prior to the 72nd Street for storm sew installation prior to the 9/2 Commercial Seeding reins fence in the area prior to the additional silt fence to profusilt fence checks north of along Ponderosa is in fair maintenance is recommer inspection, additional repasouth of Ponderosa Drive Ponderosa Drive prior to the damaged as of the 2/8/24 no maintenance is recommer seeded/matted the area premoved prior to the 7/10/	Perimeter loper installed the silt fer theast corner of the site mer of the site prior to th inspection. The silt fen is not recommended at s located is adequately lacted during Phase II gra Southeast Corner was removed during gra Southwest Perimeter loper installed the silt fer lection prior to the 10/13 lection prior to the 5/18 7/22 inspection. The lection prior to the 5/18 7/22 inspection. The lectithe drainage prior to the tellect the drainage prior to the culvert and installed condition as of the 5/4/2 linded at this time. OPPE liris will be recommended prior to the 8/10/23 insp lection; however, du mended. Commercial Se lirior to the 3/13/24 inspec 24 inspection, reinstalla	nce prior to the 5/25/21 inspect. Sudbeck removed the silt feet e 4/6/23 inspection. Sudbeck ce was damaged by excessive this time, remaining control wivegetated as of the 10/12/23 in ading, no pollution concerns a	ction. Sudbeck reinforder ceition. Sudbeck ceition. Gene Graves in the sudbeck ceition. Gene Graves in color of the sudbeck ceition. Gene Graves in the color of the sudbeck ceition. Gene Graves in the sudbeck ceition. Gene Graves in the sudbeck ceition and color of the sudbeck ceition. Gene Graves in the color of the sudbeck ceition. Gene Graves in the sudbeck ceition. Sudbeck cei	Leed the silt fence with as and repaired the silt cand new silt fence and new silt fence and new silt fence of grading of Phase II. The pair and silt fence around the second silt fence around the silt fence and installed perimeter silt swale and installed and out and repaired the silt fence in the swale vegetation, no ior to the 5/18/23 the silt fence in the silt fence around of the silt fence around of the silt fence, along 72nd Street and the Ponderosa Swale was fence checks in the		

Current Condition:	Fair Condition - Sudbeck installed the silt fence prior to the 11/4/22 inspection. Sudbeck repaired and reinforced the silt fence prior to the 3/30/23 inspection. Sudbeck extended and repaired the silt fence prior to the 6/8/23 inspection. OPPD damaged and removed portions of the silt fence prior to the 6/8/23 inspection, additional repairs will be recommended after OPPD work is complete. Commercial Seeding repaired the silt fence prior to the 8/17/23 inspection. Commercial Seeding repaired the silt fence prior to the 11/29/23 inspection. The silt fence needs to be cleaned out/repaired in multiple locations.					
	The inspector sent a plan	to Papio Park, LLC for a	approval on 5/23/24 prior to hi ng to complete during return t			
SF 6	Silt fence	NE S 70th and Flint		Removed		
Current Condition:			fence and seeded/matted the		/24 inspection.	
SF 7	Silt fence	NE S 70th and Stony		Removed		
Current Condition:			fence and seeded/matted the		/24 inspection.	
SF 8 Current Condition:	Silt fence	NW of SB C	12/8/2022 ne silt fence prior to the 12/8/2	Active	No	
	Due to utility work as of the be removed when work is	e 8/17/23 inspection, the complete. The E&A institution so that repairs can be	tion, additional repairs will be e silt fence will not be repaired spector inquired with the const be conducted. Commercial Se	t; the area is well vege ruction observer if OF	etated and the silt fence w PPD is complete in the are	
SF 9	Silt fence	NE Corner of 72nd and Schram		Removed		
Current Condition:			naining portions of the silt fend around the utilities prior to the		inspection. Commercial	
STR	Streets	S 72nd Street	5/18/2021	Active	Yes	
	The streets in front of lots Hallmark Homes was info		on 8/2/24. Not done as of the	e last inspection.		
SW 1	Straw Wattles	72nd ROW		Removed		
Current Condition:	Removed - Sudbeck removed the wattles during grading prior to the 4/6/23 inspection. The slope will be seeded and matted by 5/1/23, wattles are no longer needed. Silt fence is in place where necessary.					
SWPPP Sign	Misc/Other	S 72nd and Schram	5/18/2021	Active	No	
Current Condition: WO 1		SWPPP sign was install	e SWPPP sign in the southwo ed at S 72st Street and Schra the 8/16/24 inspection.		, ,	
Current Condition:			I			
WS 1	Waste Storage	On Site	no oto waoto on site prior to ti	Removed		
Current Condition:			l on materials, portable toilets a		L arate BMPs in the BMP	
Certification Statement:	accordance with a system submitted. Based on my ingathering the information,	designed to assure that nquiry of the person or p the information submitte	and all attachments were pre t qualified personnel properly ersons who manage the syste ed is, to the best of my knowle ubmitting false information inc	gathered and evaluate em or those persons d edge and belief, true, a	ed the information irectly responsible for accurate, and complete. I	
nspector Signature:	Jack Mart			Reviewed By:	But Silv	