E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

E&A - P2018.228.001 Bill SID as of 2/17/22 P2018 228 000

			//22 P2018.228.000				
Inspector: Jason Brackett		Stage					
		•	y Two Place 0624-5346-GP1		1		
					'		
Project Name:		CSW-202004796					
For Week Ending:		9/1	4/2024				
Project Location:		12101 S 72nd St, Papillion, Sarpy County, NE					
Grading:	80%		T				
Sanitary Sewer:	100%						
Storm Sewer:	95%						
Paving:	80%						
Seeding:	80%						
Utilities:	80%						
Overall Development:	47%						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time			
					Week		
Sunday:	0.00"						
Monday:	0.00"						
Tuesday:	0.00"						
Wednesday:	0.00"						
Thursday:	0.00"						
Friday:	0.00"	9/13/2024	Mostly Sunny 87/59	1:20 PM			
Saturday:	0.00"						

Construction Sequencing:

sins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 d

Rough grading began (6/15/21). Excavation for sanitary installation (9/28/21). Grading ceased due to winter conditions (1/5/22). Excavation for utility connections along 72nd (2/8/22). Grading for roadways (6/9/22). Lot 3 Replat 1 and Lot 4 Replat 1 scraping (11/2/22). Riprap installation and regrading at S 70th Street stub (11/2/22). Swale and ROW along Ponderosa connection finish graded (11/4/22). Swale and ROW along Ponderosa grading ceased (12/1/22). Basin cleanouts and processing silt began (8/3/23). Basin cleanouts completed (10/26/23). Sidewalk paving began (10/26/23). Sidewalk paving complete (11/8/23). Regrading of southeast corner lots (12/6/23). All grading ceased due to winter conditions (1/4/24). Re-grading of sidewalk replacements (6/19/24).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading began (6/15/21). Excavation for sanitary installation (9/28/21). Grading ceased due to winter conditions (1/5/22). Excavation for utility connections along 72nd (2/8/22). Grading for roadways (6/9/22). Lot 3 Replat 1 and Lot 4 Replat 1 scraping (11/2/22). Riprap installation and regrading at S 70th Street stub (11/2/22). Swale and ROW along Ponderosa connection finish graded (11/4/22). Swale and ROW along Ponderosa grading ceased (12/1/22). Basin cleanouts and processing silt began (8/3/23). Basin cleanouts completed (10/26/23). Sidewalk paving began (10/26/23). Sidewalk paving complete (11/8/23). Regrading of southeast corner lots (12/6/23). All grading ceased due to winter conditions (1/4/24). Re-grading of sidewalk replacements (6/19/24).

What temporary or permanent stabilization measures listed in this section are being impl

Existing vegetation (6/15/21). Disking/seeding east side of site (7/8/22). Lot 1, 2, 3 - seeded (11/10/22). Seeding and matting swale and ROW along Ponderosa and Schram/72nd medians and ROWs (12/8/22). Seeding/matting sidewalk disturbances began (11/8/23). Basin slopes seeded/matted (11/29/23). SE of S 72nd Street and Schram seeding/matting (12/13/23). Commercial Seeding seeded/matted portions of disturbance around sidewalk construction, light pole installation, and utility work (3/13/24). Commercial Seeding seeded/matted the northeast corner of 72nd and Schram (3/20/24). Re-seeding and matting around sidewalk replacements (6/19/24).

Checklist Questions:

eiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

'es

reate Corrective Action?

lave disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

No, see Findings section.

re waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

N/A

reate Corrective Action?

dust associated with the construction activity adequately controlled on the site?

Yes	
Create Corrective Action?	
N/A	

Comments:

Comments:

The site was active for home building during the most recent inspection.

Lot 5 and 6 Replat 1 have been removed from this SWPPP and are covered by PAP-20220310-6351-GP1.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section of this report.
- 2) Disturbed areas of the north side of the Ponderosa Swale should be stabilized and the old silt fence removed when Vestara construction is complete. The inspector will continue to monitor and recommend maintenance when Vestara construction complete as of the 3/6/24 inspection.
- 3) Disturbed areas of poor vegetation growth need to be re-seeded and matted along the south side of Schram Road. The inspector sent a plan to Papio Park, LLC for approval on 5/23/24 prior to hiring a contractor to complete by 5/29/24. Not done as of the last inspection. Contractor hired prior to the 5/29/24 inspection. Contractor to complete erosion repair ASAP and permanent seeding in the Fall seeding window as of the 7/10/24 inspection.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CE 1	Construction Entrance	Schram Road		Removed		
Current Condition:	Removed - The entrance will no longer be used as of the 8/29/22 inspection due to the completion of the Schram Road connection.					
D 1	Diversion	E of SB C	11/12/2021	Active	No	
Current Condition:	diversion during the 6/30/ removed at the S 70th stu	22 inspection. Sudbeck b prior to the 8/29/22 in	to the 11/12/21 inspection. S maintained the diversion prio spection, the inspector will mo	or to the 7/8/22 inspect conitor the need for rein	ion. The diversion wa	
D 2	Diversion	S of SB D		Removed		
Current Condition:	Removed - Due to additio 6/8/23 inspection.		ne Vestara Apartments, the di	version no longer nee	ds to be installed as of	
D 3	Diversion	N of SB D	6/8/2023	Active	No	
Current Condition:			prior to the 6/8/23 inspection. sion does not need to be reins			
D 4	Diversion	E and SB B		Removed		
Current Condition:	Removed - Re-grading of reinstallation is not require	ed.	in the area has removed the		8/24 inspection,	
D 5	Diversion	Northwest Perimeter		Removed		
Current Condition:			isting contours as of the 5/3/2		T	
D 6	Diversion	Western Perimeter		Removed		
Current Condition:	Removed - The remaining regrading are included in	, ,	ve been installed as of the 3/2 his report.	3/23 inspection. Rec	ommendations for swa	
D 7	Diversion	Stub to SB A	3/23/2023	Active	No	
Current Condition:	diversion was partially fille	ed in during basin cleand	version from the stub road to Sout prior to the 8/3/23 inspection. The diversion w	on, repair will be comp	oleted during basin gra	
	diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstalla	ed in during basin cleand ions prior to the 11/15/2 t corner of the site and it tion when access road is	out prior to the 8/3/23 inspections inspection. The diversion wheek work at Ponderosa Places no longer needed. Erosion to	on, repair will be comp vas partially removed of prior to the 12/13/23 through the berm has	bleted during basin gra to build an access road inspection, the inspect	
	diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstalla as of the 2/28/24 inspection	ed in during basin cleand ions prior to the 11/15/2 t corner of the site and it tion when access road it on, the inspector will mo	out prior to the 8/3/23 inspections of the diversion when work at Ponderosa Place	on, repair will be comp vas partially removed of prior to the 12/13/23 through the berm has	bleted during basin gra to build an access road inspection, the inspect	
D 8	diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallar as of the 2/28/24 inspection	ed in during basin cleand ions prior to the 11/15/2 t corner of the site and it ion when access road is on, the inspector will mo	out prior to the 8/3/23 inspections inspection. The diversion when work at Ponderosa Places no longer needed. Erosion in nitor during future rain events	on, repair will be comp vas partially removed prior to the 12/13/23 through the berm has Removed	pleted during basin gra to build an access road inspection, the inspect drained the ponded ar	
D 8 Current Condition:	diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallar as of the 2/28/24 inspection Diversions Removed - Due to utility in	ed in during basin cleand ions prior to the 11/15/2 t corner of the site and it ion when access road is on, the inspector will moss E	out prior to the 8/3/23 inspections inspection. The diversion wheek work at Ponderosa Places no longer needed. Erosion to	on, repair will be compared prior to the 12/13/23 through the berm has Removed das of the 6/8/23 insp	pleted during basin gra to build an access road inspection, the inspect drained the ponded an	
D 8 Current Condition: ET 1	diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallar as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace	ed in during basin cleand ions prior to the 11/15/2 t corner of the site and it ion when access road is on, the inspector will moss B E installation, the diversion N of SB D	out prior to the 8/3/23 inspections inspection. The diversion when work at Ponderosa Places no longer needed. Erosion in itor during future rain events are no longer recommended.	on, repair will be compared by as partially removed prior to the 12/13/23 through the berm has Removed das of the 6/8/23 insp	pleted during basin grate build an access road inspection, the inspection drained the ponded an ection.	
D 8 Current Condition: ET 1 Current Condition:	diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallar as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active	ed in during basin cleand ions prior to the 11/15/2 t corner of the site and it ion when access road is on, the inspector will moss B E installation, the diversion N of SB D paving in the area, the terms ions ions proving in the area, the terms ions ions in the area, the terms ions in the area.	out prior to the 8/3/23 inspections inspection. The diversion when work at Ponderosa Places no longer needed. Erosion in nitor during future rain events	on, repair will be compared prior to the 12/13/23 through the berm has Removed as of the 6/8/23 insp Removed led as of the 7/15/22 i	pleted during basin grate build an access road inspection, the inspection drained the ponded an ection.	
D 8 Current Condition: ET 1 Current Condition: ET 2	diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstalla as of the 2/28/24 inspecti Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace	ed in during basin cleand ions prior to the 11/15/2 t corner of the site and it ion when access road is on, the inspector will moss Enstallation, the diversion N of SB D paving in the area, the to N of SB E	out prior to the 8/3/23 inspections inspection. The diversion when work at Ponderosa Place is no longer needed. Erosion initor during future rain events is are no longer recommended errace will no longer be installed.	on, repair will be compared by prior to the 12/13/23 through the berm has been seen as of the 6/8/23 inspared as of the 6/8/23 inspared as of the 7/15/22 in Removed	pleted during basin grate build an access road inspection, the inspect drained the ponded ar ection.	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition:	diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstalla as of the 2/28/24 inspecti Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active	ed in during basin cleand ions prior to the 11/15/2 t corner of the site and in the site and in the site and in the site and in the inspector will most allation, the diversion N of SB D paving in the area, the the paving in the area, the the site ions proving in the area, the the site ions prior to the site ions in the site and in the site an	out prior to the 8/3/23 inspections inspection. The diversion when work at Ponderosa Places no longer needed. Erosion in itor during future rain events are no longer recommended.	on, repair will be compared by as partially removed prior to the 12/13/23 through the berm has been seen as the 6/8/23 inspared as of the 6/8/23 inspared led as of the 7/15/22 in Removed led as of t	pleted during basin grate build an access road inspection, the inspect drained the ponded are ection.	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3	diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstalla as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Erosion Control Terrace	ed in during basin cleand ions prior to the 11/15/2 t corner of the site and in tion when access road is on, the inspector will most allation, the diversion N of SB D paving in the area, the to N of SB B	out prior to the 8/3/23 inspections inspection. The diversion when work at Ponderosa Places no longer needed. Erosion initor during future rain events are no longer recommended errace will no longer be installerrace will no longer be installerrace.	on, repair will be compared by as partially removed prior to the 12/13/23 through the berm has been seen as of the 6/8/23 inspace as of the 6/8/23 inspace as of the 7/15/22 in Removed led as of the 7/15/22 in Removed	pleted during basin grate build an access road inspection, the inspect drained the ponded ar ection. ection. espection.	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3	diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstalla as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace Removed - Due to active Erosion Control Terrace	ed in during basin cleand ions prior to the 11/15/2 t corner of the site and in tion when access road is on, the inspector will most allation, the diversion N of SB D paving in the area, the to N of SB B	out prior to the 8/3/23 inspections inspection. The diversion when work at Ponderosa Place is no longer needed. Erosion initor during future rain events is are no longer recommended errace will no longer be installed.	on, repair will be compared by as partially removed prior to the 12/13/23 through the berm has been seen as of the 6/8/23 inspace as of the 6/8/23 inspace as of the 7/15/22 in Removed led as of the 7/15/22 in Removed	pleted during basin grate build an access road inspection, the inspect drained the ponded an ection. ection. espection.	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4	diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallar as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace	ed in during basin cleand ions prior to the 11/15/2 t corner of the site and in the ion when access road is on, the inspector will most about the installation, the diversion N of SB D paving in the area, the the ion N of SB B paving in the area, the the ion SB B paving in the area, the the ion SB B paving in the area, the the ion SB B paving in the area, the the ion SB B paving in the area, the the ion SB B paving in the area, the the ion SB B paving in the area, the the ion SB B B SB B B SB B B SB B B B B B B B	out prior to the 8/3/23 inspection. The diversion when work at Ponderosa Place is no longer needed. Erosion initor during future rain events is are no longer recommended. Errace will no longer be instal errace will no lon	on, repair will be compared by as partially removed prior to the 12/13/23 through the berm has been seen as of the 6/8/23 inspace of the 6/8/23 inspace of the 7/15/22 in Removed led as of the 7/15/22 in Removed	pleted during basin grate build an access road inspection, the inspect drained the ponded an ection. ection. nspection. nspection.	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition:	diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallar as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace	ed in during basin cleand ions prior to the 11/15/2 t corner of the site and in the ion when access road is on, the inspector will most about the installation, the diversion N of SB D paving in the area, the the ion N of SB B paving in the area, the the ion SB B paving in the area, the the ion SB B paving in the area, the the ion SB B paving in the area, the the ion SB B paving in the area, the the ion SB B paving in the area, the the ion SB B paving in the area, the the ion SB B B SB B B SB B B SB B B B B B B B	out prior to the 8/3/23 inspections inspection. The diversion when work at Ponderosa Places no longer needed. Erosion initor during future rain events are no longer recommended errace will no longer be installerrace will no longer be installerrace.	on, repair will be compared by as partially removed prior to the 12/13/23 through the berm has been seen as of the 6/8/23 inspace of the 6/8/23 inspace of the 7/15/22 in Removed led as of the 7/15/22 in Removed	pleted during basin grate build an access road inspection, the inspect drained the ponded are ection. Inspection. Inspection. Inspection. Inspection.	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1	diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallar as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Terrace	ed in during basin cleand ions prior to the 11/15/2 t corner of the site and in the ion when access road is on, the inspector will most about the inspector	out prior to the 8/3/23 inspection. The diversion when work at Ponderosa Place is no longer needed. Erosion in itor during future rain events is are no longer recommended. Errace will no longer be install errace will e	on, repair will be compared by as partially removed prior to the 12/13/23 through the berm has a second by a secon	pleted during basin grate build an access road inspection, the inspect drained the ponded are ection. paspection. paspection. paspection. paspection. paspection. paspection.	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition:	diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstalla as of the 2/28/24 inspection Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co	ad in during basin cleand ions prior to the 11/15/2 t corner of the site and in tion when access road is on, the inspector will most a BE installation, the diversion N of SB D paving in the area, the to N of SB B paving in the area, the to East Central paving in the area, the to Northwest Side roial Seeding installed the mmercial Seeding prior	out prior to the 8/3/23 inspection. The diversion when work at Ponderosa Place is no longer needed. Erosion in the diversion of the properties are no longer recommended. It is are no longer recommended in the prior will no longer be install errace will no longer b	on, repair will be compared by as partially removed or prior to the 12/13/23 through the berm has been seen as of the 6/8/23 inspared by as of the 6/8/23 inspared by a few partial provided as of the 7/15/22 in Removed been seen as of the 7/15/22 in Removed been as of the 7/15/2	pleted during basin gra to build an access road inspection, the inspect drained the ponded ar ection. espection. enspection. enspection. nspection. nspection. No of the slope were re-	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition:	diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallar as of the 2/28/24 inspective Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co	ed in during basin cleand ions prior to the 11/15/2 t corner of the site and in the site and in the site and in the site and in the inspector will more a site and in the inspector will more a site and in the inspector will more a site and in the site and	out prior to the 8/3/23 inspection. The diversion when work at Ponderosa Place is no longer needed. Erosion initor during future rain events is are no longer recommended errace will no longer be installerrace will no longe	on, repair will be compared by as partially removed or prior to the 12/13/23 through the berm has been seen as the compared by as of the 6/8/23 inspared by as of the 6/8/23 inspared by a few powers of the 7/15/22 in the compared by a few powers of the 7/15/22 in the compared by a few powers of the 7/15/22 in the compared by a few powers of the 7/15/22 in the compared by a few powers of the 7/15/22 in the the 7/15/2	pleted during basin grate build an access road inspection, the inspect drained the ponded are ection. paspection. paspection. paspection. paspection. paspection. paspection.	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition:	diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallar as of the 2/28/24 inspectiv Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme	ed in during basin cleand ions prior to the 11/15/2 t corner of the site and in the site and i	out prior to the 8/3/23 inspection. The diversion when work at Ponderosa Place is no longer needed. Erosion initor during future rain events is are no longer recommended. errace will no longer be install 7/15/2022 The matting prior to the 7/15/22 to the 12/8/22 inspection. 7/15/2022 The matting prior to the 7/15/22 to the 12/8/22 inspection.	on, repair will be compared by as partially removed prior to the 12/13/23 through the berm has been seen as the 6/8/23 inspace of the 6/8/23 inspace of the 6/8/23 inspace of the 7/15/22 in Removed led as of the 7/15/22 in Active conspection.	oleted during basin gra to build an access road inspection, the inspect drained the ponded ar ection. espection. enspection. enspection. No of the slope were re-	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 2 Current Condition: EM 3	diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstalla as of the 2/28/24 inspective Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme Erosion Control Matting Good Condition - Comme	ed in during basin cleand ions prior to the 11/15/2 t corner of the site and in the corner of the site and in the inspector will most as a con, the inspector will most as a constant and in the area, the total seeding in the area, the total seeding installed the most as a constant a	out prior to the 8/3/23 inspection. The diversion where work at Ponderosa Place is no longer needed. Erosion initor during future rain events as are no longer recommended. Errace will no longer be install 7/15/2022 to the 12/8/22 inspection. 7/15/2022 ne matting prior to the 7/15/22 ene matting prior to the 7/15/22	on, repair will be compared by as partially removed prior to the 12/13/23 through the berm has been seen as of the 6/8/23 inspace as of the 6/8/23 inspace as of the 7/15/22 in Removed led as of the 7/15/22 in Active conspection. Portions	pleted during basin gra to build an access road inspection, the inspect drained the ponded ar ection. ection. espection. espection. espection. No of the slope were re-	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition:	diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstalla as of the 2/28/24 inspectie Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme Erosion Control Matting Good Condition - Comme Erosion Control Matting Good Condition - Comme	ad in during basin cleand ions prior to the 11/15/2 to corner of the site and in the corner of the site and in the inspector will most as a con, the inspector will most as a constant and in the area, the total seeding in the area, the total seeding installed the most as a constant as a c	out prior to the 8/3/23 inspection. The diversion where work at Ponderosa Place is no longer needed. Erosion initor during future rain events as are no longer recommended. Errace will no longer be install errace will no longer be	on, repair will be compared by as partially removed prior to the 12/13/23 through the berm has been seen as of the 6/8/23 inspanding as of the 6/8/23 inspanding as of the 7/15/22 in Removed led as of the 7/15/22 in Active inspection. Portions active inspection. Active inspection. Sudbeck	obleted during basin grate build an access road inspection, the inspect drained the ponded are ection. ection. espection. espection. espection. No of the slope were re- No installed additional	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 3 Current Condition:	diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallar as of the 2/28/24 inspective Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co Erosion Control Matting Good Condition - Comme Erosion Control Matting Good Condition - Comme Erosion Control Matting Good Condition - Comme Erosion Control Matting Frosion Control Matting Good Condition - Comme Erosion Control Matting Erosion Control Matting	ad in during basin cleand ions prior to the 11/15/2 t corner of the site and in the corner of the site and in the inspector will most as a con, the inspector will most as a constant as a con	out prior to the 8/3/23 inspection. The diversion where work at Ponderosa Place is no longer needed. Erosion initor during future rain events are no longer recommended. Is are no longer recommended. In a sare no longer recommended in the prior in the recommended in the	on, repair will be compared by as partially removed prior to the 12/13/23 through the berm has been seen as of the 6/8/23 inspace as of the 6/8/23 inspace as of the 7/15/22 in Removed led as of the 7/15/22 in Active an inspection. Portions led as of the 7/15/22 in Active an inspection. Active an Active an Active and	pleted during basin gra to build an access road inspection, the inspect drained the ponded ar ection. ection. espection. espection. espection. No of the slope were re-	
D 8 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition:	diversion was partially fille DEJ reinstalled the divers regrading of the southeas will recommend reinstallar as of the 2/28/24 inspective Diversions Removed - Due to utility in Erosion Control Terrace Removed - Due to active Erosion Control Matting Good Condition - Comme seeded and matted by Co Erosion Control Matting Good Condition - Comme Erosion Control Matting Good Condition - Comme Erosion Control Matting Good Condition - Comme Erosion Control Matting Frosion Control Matting Good Condition - Comme Erosion Control Matting Erosion Control Matting	ad in during basin cleand ions prior to the 11/15/2 t corner of the site and in the corner of the site and in the inspector will most as a con, the inspector will most as a constant as a con	out prior to the 8/3/23 inspection. The diversion where work at Ponderosa Place is no longer needed. Erosion initor during future rain events as are no longer recommended. Errace will no longer be install errace will no longer be	on, repair will be compared by as partially removed prior to the 12/13/23 through the berm has been seen as of the 6/8/23 inspace as of the 6/8/23 inspace as of the 7/15/22 in Removed led as of the 7/15/22 in Active an inspection. Portions led as of the 7/15/22 in Active an inspection. Active an Active an Active and	pleted during basin gra to build an access road inspection, the inspect drained the ponded an ection. ection. espection. espection. No of the slope were re- No installed additional	

Current Condition:	grade. A water main exter matting in the area will be inspection. Water main in the area when installation seeding/matting to follow. repaired the erosion and reslope was observed durin time.	nsion project in the area temporarily halted until astallation is active on sit is complete. Additional Commercial Seeding see-seeded/matted the slog the 10/12/23 inspection	be installed within the seeding will begin soon as of the 5/3/4 work is complete. Seeding of the as of the 8/29/22 inspector finish grading along 72nd Streeded/matted the slope prior to the 5/4/23 inspect n, the inspector will continue	22 inspection, therefore the slope is still record, water contractor will eet to be completed into the 4/20/23 inspection. Minor erosion alcord monitor, no mainter	re, recommendations for mmended as of the 5/3/22 be seeding and matting in the Spring of 2023, ion. Commercial Seeding and the south end of the
FT 1	Fuel Tank	SW Corner		Removed	
Current Condition:	Removed - DEJ removed		27/15/22 inspection.		
FT 2	Fuel Tank	Material Storage Area		Removed	
Current Condition:	Removed - TAB removed	the fuel tank prior to the	e 4/7/22 inspection.		
FT 3	Fuel Tank	Material Storage Area		Removed	
Current Condition:	Removed - RPL removed		114/22 inspection.		
FT 4	Fuel Tank	Material Storage Area		Removed	
Current Condition:	Removed - The fuel tank		e 5/18/22 inspection.		
FT 5	Fuel Tank	Material Storage Area	7/0/00:	Removed	
Current Condition:	Removed - The fuel tank		e 7/8/22 inspection.		
FT 6	Fuel Tank	On Site	11-44/4/00:	Removed	
Current Condition: FT 7	Removed - Kersten remov Fuel Tank	on Site	une 11/4/22 Inspection.	Removed	
Current Condition:			ior to the 12/20/23 inspection		
TEMP IPs XX	Inlet Protection	Schram Road	10/5/2023	Active	No
Current Condition:			let filters along the south side		-
ourient obligation.	Commercial Seeding clea filters prior to the 11/29/23	ned out the inlet filters p 3 inspection. Commercia	rior to the 11/2/23 inspection. al Seeding cleaned out the inl rior to the 5/29/24 inspection.	Commercial Seeding	cleaned out the inlet
Lot 14	Individual Lot	Lot 14		Removed	
Current Condition:	Removed - Hallmark Hom				
Lot 19	Individual Lot	Lot 19	6/5/2024	Active	No
Current Condition:			ation on the lot prior to the 6/5 tion. Hallmark Homes stake		
Lot 20	Individual Lot	Lot 20	6/12/2024	Active	No
Current Condition:			uction on the lot prior to the 6	/12/24 inspection. Ha	Ilmark Homes installed
	perimeter silt fence prio	r to the 9/13/24 inspec	tion.		
Lot 25	Individual Lot	Lot 25	8/7/2024	Active	No
Current Condition:	Good Condition - Hallma	ark Homes began excav	ation on the lot prior to the 8/4	1/24 inspection. Hallm	ark Homes installed
	perimeter silt fence prio				
Lot 67	Individual Lot	Lot 67		Removed	
Current Condition:	Removed - Legacy Home		the 11/29/23 inspection.		
Lot 68	Individual Lot	Lot 68		Removed	
Current Condition:			toilet prior to the 12/20/23 insp		ctive.
MS 1	Material Storage	On Site		Removed	
Current Condition:	11/4/22 inspection.		mplete, material storage will l		by lot basis as of the
PB X	Portable Bathroom	On Site		Removed	
Current Condition:			oilet from the site prior to the		
PB Y	Portable Bathroom	On Site	lat maian ta tha 4/4/04 ' · · · · · · ·	Removed	
Current Condition:			let prior to the 1/4/24 inspecti		NI.
SB A	Sediment Basin	X24	5/11/2022	Active	No
Current Condition:	appears to have been inst was reshaped prior to the basin are the only stormw will address these diversion 7/20/23. The basin was of Commercial Seeding seed baffle prior to the 4/17/24	talled prior to the 4/13/2: 5/26/22 inspection. The ater diversions to the basins when construction of deaned out prior to the 7 ded and matted the basinspection. Erosion into	ug out prior to the 12/1/21 insp 2 inspection. The riser was inspector painted the control of th	stalled prior to the 5/1 leanout mark on 5/23/e as of the 6/8/23 insparsion cleanout began led the baffle prior to the inspection. Commercing the 7/8/24 inspection	1/22 inspection. The basin (22. The erosion into the pection, additional grading prior to the inspection on the 10/5/23 inspection.
SB B	Sediment Basin	O24	5/18/2022	Active	No
Current Condition:	Good Condition - 10% Fill continue to monitor. The was in the process of beir prior to the 5/18/22 inspec the 6/29/23 inspection. D	ed - The basin had beer basin outfall pipe and rip ng installed during the 4/ stion. The E&A inspecto EJ installed the baffle pi	n partially dug out prior to the partially dug out prior to the parapapears to have been in 21/22 inspection. Dewatering prior painted the cleanout mark crior to the 10/5/23 inspection.	9/14/21 inspection by stalled prior to the 4/1 holes appear to have in 5/23/22. DEJ clean Commercial Seeding	DEJ, the inspector will 3/22 inspection. The riser been installed in the riser led out the basin prior to seeded and matted the
SB C	Sediment Basin	H24	5/18/2022	Active	No

Current Condition:	Good Condition - 10% Filled - The basin was dug out prior to the 11/12/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. Dewatering holes appear to have been installed in the riser prior to the 5/18/22 inspection. The E&A inspector painted the cleanout mark on 5/23/22. DEJ cleaned out the basin prior to the 6/29/23 inspection. DEJ installed the baffle prior to the 10/5/23 inspection. Commercial Seeding seeded and matted the basin slopes prior to the 11/29/23 inspection. Commercial Seeding seeded and matted the remaining portions of the outlot prior to the 3/13/24 inspection.						
SB D Current Condition:	Sediment Basin H22 5/18/2022 Active No Good Condition - 10% Filled - The basin was in the process of being dug out during the 11/4/21 inspection. The basin outfall pipe and rip rap appears to have been installed prior to the 4/13/22 inspection. The riser was in the process of being installed during the 4/21/22 inspection. The old area inlet was removed prior to the 4/21/22 inspection. Dewatering holes appear to have been installed in the riser prior to the 5/18/22 inspection. The basin was in the process of being cleaned out during the 7/27/23 inspection. The basin was cleaned out and the correct depth achieved as of the 8/3/23 inspection. DEJ installed the baffle prior to the 10/5/23 inspection. Commercial Seeding seeded and matted the basin slopes prior to the 11/29/23 inspection. The damaged baffle was removed by Commercial Seeding prior to the 3/13/24 inspection, reinstallation is not needed due to adequate stabilization of the surrounding area.						
SB E	Sediment Basin	D19	5/3/2022	Active	No		
Current Condition:			ially dug out prior to the 12/1/				
SF 1	Silt fence	Northern/Western Perimeter	5/18/2021	Active	No		
Current Condition:	extension of the silt fence north side of the entrance 4/7/22 inspection. The sil the 6/24/22 inspection. TI NW of SB D prior to the 6 7/8/22 inspection. Sudber and extended the silt fence fence north of Schram prior 4/20/23 inspection. Sudbor 6/8/23 inspection. Papio I along S 72nd Street south about plowing in the area.	to the north prior to the prior to the 4/7/22 inspet fence was removed in the water contractor removed. If the water contractor removed in the water contractor removed in the water contractor. Sudble calong 72nd Street prior to the 12/8/22 inspect the ceck installed additional separk LLC repaired the sit of Schram was in the part of Schram was in the par	ence prior to the 5/18/21 insp 2/2/22 inspection. Sudbeck e- ection. TAB repaired/reinstall- multiple locations, including s oved the silt fence where dan eck installed silt fence aroun- ing the north side of Schram por to the 9/19/22 inspection. Commercial Seeding rei silt fence along the top of the silt fence at the top of the slope process of being removed during the silt fence at the top of the slope process of being removed during the silt fence at the top of the slope frocess of being removed puring the silt fence at the top of the slope frocess of being removed puring the silt fence at the top of the slope frocess of being removed puring the silt fence at the top of the slope frocess of being removed puring the silt fence at the solution, the only respectively.	extended the silt fence ed the silt fence along outhwest of SB D, for naged adjacent to the d the flared end section or or or to the 9/12/22 inscanding the silt fence slope southeast of 72 e prior to the 8/10/23 ing the 12/13/23 insper to the 12/20/23	e to the south along the 172nd Street prior to the 272nd and Schram prior to the 272nd and 272		
SF 2	Silt fence	Northeastern Perimeter	5/25/2021	Active	No		
Current Condition:	Fair Condition - The developer installed the silt fence prior to the 5/25/21 inspection. Sudbeck reinforced the silt fence with additional posts in the northeast corner of the site. Sudbeck removed the silt fence in upgradient areas and repaired the silt fence in the northeast corner of the site prior to the 4/6/23 inspection. Sudbeck reinstalled the silt fence and new silt fence checks prior to the 6/8/23 inspection. The silt fence was damaged by excessive water from the adjoining property prior to the 6/22/23 inspection, repair is not recommended at this time, remaining control will be addressed during grading of Phase II. The area where the silt fence is located is adequately vegetated as of the 10/12/23 inspection, erosion repair and silt fence maintenance will be conducted during Phase II grading, no pollution concerns at this time.						
SF 3	Silt fence	Southeast Corner		Removed			
Current Condition:	Removed - The silt fence not recommended.	was removed during gra	ading of the project to the sou	th prior to the 2/8/24 i	nspection, reinstallation is		
SF 4	Silt fence	Southwest Perimeter	5/18/2021	Active	No		
Current Condition:	Fair Condition - The developer installed the silt fence prior to the 5/18/21 inspection. Gene Graves installed silt fence around the Ponderosa Drive connection prior to the 10/13/21 inspection. Sudbeck installed high porosity silt fence checks in the flow line of the swale prior to the 4/7/22 inspection. The silt fence was partially removed at the future Ponderosa entrance along 72nd Street for storm sewer work prior to the 5/18/22 inspection. Some of the silt fence was temporarily removed for water installation prior to the 9/27/22 inspection. The damaged portions of silt fence were removed prior to the 11/4/22 inspection. Commercial Seeding reinstalled the silt fence checks in the swale prior to the 12/8/22 inspection and installed perimeter silt fence in the area prior to the 12/8/22 inspection. Commercial Seeding reinforced the silt fence in the swale and installed additional silt fence to protect the drainage prior to the 3/30/23 inspection. Commercial Seeding cleaned out and repaired the silt fence checks north of the culvert and installed additional protection prior to the 5/4/23 inspection. The silt fence in the swale along Ponderosa is in fair condition as of the 5/4/23 inspection; however, to avoid disturbing growing vegetation, no maintenance is recommended at this time. OPPD damaged and removed portions of the silt fence prior to the 5/18/23 inspection, additional repairs will be recommended after OPPD work is complete. Papio Park LLC cleaned out the silt fence south of Ponderosa Drive prior to the 8/10/23 inspection. Commercial Seeding repaired/reinstalled the silt fence north of Ponderosa Drive prior to the 8/17/23 inspection. Some of the silt fence along the southern perimeter of the site is significantly damaged as of the 2/8/24 inspection; however, due to imminent grading of the project to the south and removal of the silt fence, no maintenance is recommended. Commercial Seeding removed the damaged portions of silt fence along 72nd Street and seeded/matted the area prior to the 3/13/24 inspecti						
SF 5	Silt fence	NW corner of Lot 3 Replat 1	11/4/2022	Active	Yes		

Current Condition:	Fair Condition - Sudbeck installed the silt fence prior to the 11/4/22 inspection. Sudbeck repaired and reinforced the silt fence prior to the 3/30/23 inspection. Sudbeck extended and repaired the silt fence prior to the 6/8/23 inspection. OPPD damaged and removed portions of the silt fence prior to the 6/8/23 inspection, additional repairs will be recommended after OPPD work complete. Commercial Seeding repaired the silt fence prior to the 8/17/23 inspection. Commercial Seeding repaired the silt fence prior to the 11/29/23 inspection. The silt fence needs to be cleaned out/repaired in multiple locations. The inspector sent a plan to Papio Park, LLC for approval on 5/23/24 prior to hiring a contractor to complete by 5/29/24. Not done as of the last inspection. Commercial Seeding to complete during return to site for seeding as of the 7/10/24 inspection.					
SF 6	Silt fence	NE S 70th and Flint		Removed		
Current Condition:			fence and seeded/matted the		l 1/24 inspection	
SF 7	Silt fence	NE S 70th and Stony	Terroe and seeded/matted the	Removed	724 Inopeditori.	
Current Condition:			fence and seeded/matted the		3/24 inspection.	
SF 8	Silt fence	NW of SB C	12/8/2022	Active	No	
Current Condition:			ne silt fence prior to the 12/8/2			
	will be removed when wor	rk is complete. The E&A spection so that repairs ction.	e silt fence will not be repaired A inspector inquired with the co can be conducted. Commerc	onstruction observer i	f OPPD is complete in the	
SF 9	Silt fence	NE Corner of 72nd and Schram		Removed		
Current Condition:			naining portions of the silt fend around the utilities prior to the		inspection. Commercial	
STR	Streets	S 72nd Street	5/18/2021	Active	Yes	
QW 4		rmed to complete ASAP	on 8/2/24. Not done as of th	<u> </u>		
SW 1 Current Condition:	Straw Wattles 72nd ROW Removed Removed - Sudbeck removed the wattles during grading prior to the 4/6/23 inspection. The slope will be seeded and matted by 5/1/23, wattles are no longer needed. Silt fence is in place where necessary.					
SWPPP Sign	Misc/Other	S 72nd and Schram	5/18/2021	Active	No	
Current Condition:	inspection. An additional inspector reinstalled the S	A inspector installed the SWPPP sign was instal SWPPP sign prior to the	SWPPP sign in the southwes led at S 72st Street and Schra	st corner of the proper am prior to the 6/22/23		
WO 1	Concrete Washout	On Site		Removed		
Current Condition:			ncrete waste on site prior to the		T	
WS 1	Waste Storage	On Site		Removed		
Current Condition:	Removed - Waste storage section.	e of concrete, construction	on materials, portable toilets a	re covered under sep	parate BMPs in the BMP	
Certification Statement:	accordance with a system submitted. Based on my in gathering the information,	n designed to assure that inquiry of the person or p the information submitte	and all attachments were pre- t qualified personnel properly persons who manage the syste ed is, to the best of my knowled ubmitting false information incompanies.	gathered and evaluat em or those persons o edge and belief, true,	ed the information directly responsible for accurate, and complete. I	
nspector Signature:	Ja, le Gart			Reviewed By:	Boto See	