E&A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

CHECKLIST QUESTIONS:

Environmental Services Dept. Manager **Engineering Answers** E&A- P2014.577.001 Inspector: Matt Vanicek Stage **Shelby High School** 2 NER115160 Project Name: 1/28/2017 For Week Ending: Project Location: Walnut St. and Washington St, Shelby, NE (Polk County) 68662 Grading: 100% Sanitary Sewer: Storm Sewer: 100% 100% Paving: 90% Seeding: 50% 100% Utilities: Overall Development: 70% Amount in tenths RAIN FALL AMOUNTS Date inspected Weather Conditions Sunday: 0.00" Monday 0.01 Tuesday 0.01" Wednesday 0.00" Thursday 0.00" Friday 0.00" Saturday 0.00' Sunday: 0.00" Monday 0.00" 01/23/17 37/28 Partly Cloudy Tuesday 0.00" Wednesday 0.00 Thursday 0.00" Friday 0.00" Saturday 0.00" Sunday: N/A N/A Monday N/A N/A Tuesday N/A N/A Wednesday N/A N/A Thursday N/A N/A Friday N/A N/A N/A N/A Saturday None Complaints: Construction Sequencing: Grading is active (6/11/15) Phase 1 was compete prior to the 7/18/15 inspection. The grading of Phase 2 started prior to the 11/3/15 inspection. Grading of Phase 2 has been completed. Minor grading will be completed at a later date(3/7/16) BD Construction completed grading the parking lot (8/1/16) Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? Grading is active (6/11/15) Phase 1 was compete prior to the 7/18/15 inspection. The grading of Phase 2 started prior to the 11/3/15 inspection. Grading of Phase 2 has been completed. Minor grading will be completed at a later date(3/7/16) BD Construction completed grading the parking lot (8/1/16) Existing Vegetation. The area West and East of the football field and track were seeded or sodded(11/3/15) SUMMARY QUESTIONS: Are approved entrances and adjacent streets being maintained adequately? No, See BMP section.

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?						
Yes						
Is dust associated with the construction activity	y adequately contr	olled on the site?				
Yes						
Comments:						

Comments:

Construction of the school building is active as of the last inspection. School is active in parts of the building as of the last inspection.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):

- 1) See BMP section for required maintenance.
- 2.) The area disturbed along the west end of the athletic field needs to be seeded and stabilized. BD Construction was informed to complete by 1/30/17.
- 3.) The sediment that has deposited in the drainageway next to B3 needs to be cleaned up. BD Construction was informed to complete by 1/30/17.
- 4.) The area disturbed by utility work in the drainage way to the south of the site needs to be stabilized. BD Construction was informed to

complete by 1/30/17.					
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
		Southwest of Football			
A1	Silt Fence	Field		Removed	
Current Condition:	Removed - BD	Construction removed t	he silt fence for final stabiliz	ation as of the 9/24	1/15 inspection.
A2	Silt Fence	South of Football Field		Removed	
Current Condition:	Removed - The	silt fence was removed	due to paving in the area a	s of the 9/15/15 ins	pection.
A3	Silt Fence	East of Football Field		Removed	
Current Condition:	Removed - BD		he silt fence for final stabiliz	ation as of the 9/24	/15 inspection.
	0111 5	Northwest of Football			
A4	Silt Fence	Field	<u> </u>	Removed	
Current Condition:	Removed - The	e silt fence is no longer r	needed due to paving in the	area as of the 9/15	/15 inspection.
A.E.	0:4 5	\\\+ -+ \		Daman	
A5	Silt Fence	West of Football Field		Removed	/4 <i>E</i> in an action
Current Condition:	Removed - BD	Construction removed t	he silt fence for final stabiliz	ation as of the 9/24	1/15 inspection.
40	0:4 5	0		Da	
A9	Silt Fence	Southeast side of site		Removed	
Current Condition:	Removed - The	silt fence was not need	led during construction.		
A10	Silt Fence	Southeast side of site	1/20/2017	Donding	Yes
				Pending	
Current Condition:			ne silt fence prior to the 10/1		nstall utilities. The
	inspector will m	ionitor the area to deterr	mine if the silt fence needs to	o be reinstalled.	
	The silt fence	needs to be repaired/re	einstalled.		
	BD Constructi	on was informed to co	mplete by 1/30/17.		
A11	Silt Fence	South side of site	11/3/2015	Active	Yes
Current Condition:	Poor Condition				
	The silt fence	needs to be repaired/re	einstalled.		
	BD Constructi	on was informed to co	mplete by 1/30/17		
	DD GONGLIGGE	Southwest corner of			
A12	Silt Fence	site	11/3/2015	Active	Yes
Current Condition:	Poor Condition		1170/2010	7101170	100
Guirent Gonation.	1 oor condition				
	The cilt fence	needs to be repaired/re	oinstalled		
	The Silt lence	needs to be repaired/it	enistaneu.		
	PD Constructi	on was informed to co	mplete by 1/20/17		
	BD Constructi		This is a second of the second		
A42	0:14 =====	Southwest corner of	44/0/0045	A -4:	\/
A13	Silt Fence	site	11/3/2015	Active	Yes
Current Condition:	Poor Condition				
	The silt fence needs to be repaired/reinstalled.				
	BD Constructi	on was informed to co	mplete by 1/30/17.		ı
- :-		South of existing			
A17	Inlet filter	building	3/21/2016	Active	No
Current Condition:			alled the inlets prior to the 3/		
	•		at this time. The inspector of		is BMP as of the
	lasts inspection	due to school be active	and this area not being acc	essible.	
		South of existing			
A18	Inlet filter	building	3/21/2016	Active	Yes
•					

Current Condition:	Fair Condition - The inspector could not inspect this BMP as of the lasts inspection due to school be active				
	and this area not being accessible.				
	The silt fence in undermined and needs to be backfilled. BD Construction was informed to complete by 6/2/16. Not done as of last inspection. BD Construction				
			19/16, 12/13/16, 1/24/17	s of last inspection.	BD Construction
		Between building on		_	
A19 Current Condition:	Inlet filter Pending - Then	north side of the site	to inspection on 11/14/16.	Removed	
	. ename men	Between building on			
A20	Inlet filter	north side of the site	3/7/2016	Active	No
Current Condition:		nstruction installed the in is needed at this time.	nlets prior to the 3/7/16 insp	ection. The inlet is	above grade so no
		Between building on			
A21 Current Condition:	Inlet filter	north side of the site	3/7/2016 3/21/16 inspection. The inle	Active	No no PMD protection is
Current Condition.	needed at this t	ime.		is above grade so	TIO BIVIE PROTECTION IS
В	Construction Entrance	Southwest of Football Field		Removed	
Current Condition:	_		nanent entrance for school		as of the 1/27/16
	inspection.	•			
B 2	Construction Entrance	South side of existing parking lot	11/3/2015	Active	Yes
Current Condition:	Fair Condition -				
	Rock needs to	be added to the entranc	e.		
			1.1. b. 40/05/40 No. 1.1.		DD Occupied
		n was informed to comp on 12/13/16, 1/24/17	plete by 10/25/16. Not done	as of last inspectio	n. BD Construction
	Construction				
B 3	Entrance	Southeast side of site	11/3/2015	Active	Yes
Current Condition:	Fair Condition -	45% епестіле.			
	Rock needs to	be added to the entranc	e.		
	DD Constantin		1.1.1.1. 40/05/40 No. 1		
		n was informed to comp on 12/13/16, 1/24/17	plete by 10/25/16. Not done	as of last inspectio	n. BD Construction
	, and the same of	Southeast of Football			
C1	Inlet Protection			Removed	
Current Condition:		s BMP is being removed f the 3/21/16 inspection	from the report due to the i	inlet be located in a	completed area of
00	5	Northeast of Football			
C2 Current Condition:	Inlet Protection		I from the report due to the	Removed	completed area of
Carrent Contaition.		f the 3/21/16 inspection	•	mict be located in a	completed area of
		Northwest of			
C3	Bale Check	Football Field	1/30/2017	Pending	Yes
Current Condition:	Pending -				
			ed due to continued runof	f from the athletic	field erroding the
	adjacent drain	age way.			
	BD Constructi	on was informed to co	mplete by 1/30/17.		
C7	Bale Check	East property line	12/19/2016	Pending	Yes
Current Condition:	Pending				
	The bale check	needs to be reinstalled	in the drainage ditch.		
	BD Constructio	n was informed to comp	olete by 12/19/16. Not done	as of last inspectio	n. BD construction
	was reminded				
CW Current Condition:	Concrete	On Site	4/1/2017 ded until paving starts again	Pending	No No
STR	Streets	On site	In Place	Active	No
Current Condition:		i - No major signs of tra		Active	INU
		Southwest of Football		A	.,
SWPPP Sign Current Condition:	SWPPP Sign	Field	7/1/2015 ed the SWPPP sign on 7/1/1	Active	No
Garrent Condition.	Jood Collultion	Southeast Corners of	G GIG OVVIEE SIGN ON 1/1/1		
Wattle Check 1	Straw Wattle	site	6/11/2015	Active	No
Current Condition:	Good Condition	- BD Construction insta North west corner of	alled the wattle prior to the 6	711/15 inspection.	
Wattle Check 2	Straw Wattle	site	11/18/2015	Active	Yes
Wattie Officer 2		•			

Current Condition:	Fair Condition	Fair Condition Additional wattles need to be installed, or a more substantial BMP needs to be installed to prevent more sediment from migrating to drainageway.				
	BD Construction	on was informed to comp	lete by 1/30/17.			
Wattle Check 3	Straw Wattle	West of entrance B3	6/11/2015	Active	Yes	
Current Condition:	Additional watt more sediment	BD Construction installed les need to be installed, from migrating to drain on was informed to comp	or a more substantial	·	stalled to prevent	
ctor Signature:	HES Can			Reviewed By:	Branzen Sturra	

Date to complete inspection. 02/06/17