E&A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

Environmental Services Dept. M	anager			Engineering A		
		E&A- P2014.57	77.001			
nspector: Nick Jenkins	lick Jenkins					
		Shelby	High School		0	
Project Name:			2			
		NER115160 5/13/2017				
or Week Ending:			ton St, Shelby, NE (Polk C			
Project Location:	ounty)	68662				
Grading:	100%					
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	93%					
Seeding: Jtilities:	50% 100%					
Overall Development:	70%					
	· · ·		<u> </u>			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions			
Sunday:	0.00"				Week	
Monday	0.00"					
Tuesday	0.01"					
Vednesday	0.00"					
Thursday	0.00"	04/00/4=	40/05 D :			
Friday	0.52"	04/28/17	46/35 Rain			
Saturday	0.06"				Week	
Sunday:	2.46"				week	
Monday	0.09"	05/01/17	60/33 Partly Cloudy			
Tuesday	0.00"		, ,			
Wednesday	0.27"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"				Week	
Sunday:	0.00"				***************************************	
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.60"	05/10/17	Tstorm 62/53			
Thursday	0.00"					
Friday Saturday	0.00"					
Saturday	0.00					
	None					
Complaints:	<del></del>					
Construction Comments						
Construction Sequencing: Vhich portion(s) (i.e. drainage basins) o	of the site have had a tempor	ary or permanent coses	tion of grading parthwork or gr	ound disturbance in the	last 14 dave?	
Grading is active (6/11/15) Phase Grading of Phase 2 has been com	1 was compete prior to the	e 7/18/15 inspection.	The grading of Phase 2 sta			
BD Construction completed gradin	g the parking lot (8/1/16)			<u> </u>		
Which portion(s) (i.e. drainage basins) o						
Grading is active (6/11/15) Phase Grading of Phase 2 has been com BD Construction completed gradin	pleted. Minor grading will			arted prior to the 11/3/	15 inspection.	
<u> </u>						
What temporary or permanent stabilizat Existing Vegetation. The area We started (4/28/17).				Paving of the school	addition has	
SUMMARY QUESTIONS:						
are approved entrances and adjacent s	treets being maintained adea	uately?				
lo, See BMP section.	being maintained adeq					

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?								
No- sediment was deposited in the drainage way next to B3.								
CHECKLIST QUESTIONS:								
Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?								
No, See Findings/Corrective Actions Section.								
Is dust associated with the construction activity adequately controlled on the site?								
Yes								

## Comments:

## Comments:

Construction of the school building is active as of the last inspection. School is active in parts of the building as of the last inspection. Water was being pumped out of a graded section of the school addition as of the last inspection.

## Findings / Corrective Actions (Date):

## Findings / Corrective Actions (Date):

- 1.) See BMP section for required maintenance.
- 2.) The area disturbed along the west end of the athletic field needs to be seeded and stabilized. BD Construction was informed to complete by 1/30/17. Not done as of the last inspection. BD Construction was reminded on 3/21/17, 3/30/17, 4/16/17, 5/1/17
- 3.) The sediment that has deposited in the drainage way next to B3 needs to be cleaned up. BD Construction was informed to complete by 1/30/17. Not done as of the last inspection. BD Construction was reminded on 3/21/17, 3/30/17, 4/16/17, 5/1/17
- 4.) The area disturbed by utility work in the drainage way to the south of the site needs to be stabilized. BD Construction was informed to complete by 1/30/17. Not done as of the last inspection. BD Construction was reminded on 3/21/17, 3/30/17, 4/16/17, 5/1/17
- 5.) The concrete spoils around the playground and parking lot need to be removed. BD Construction was informed to complete by 4/23/17. Not done as of last inspection. BD Construction was reminded on 5/1/17.

as or last inspection. BB construction	s of last inspection. BD Construction was reminded on 5/1/17.						
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
		Southwest of Football	-				
A1	Silt Fence	Field		Removed			
Current Condition:	Removed - BD	Construction removed to	he silt fence for final stabiliza	ation as of the 9/24	/15 inspection.		
A2	Silt Fence	South of Football Field		Removed			
Current Condition:			due to paving in the area as		l nection		
A3	Silt Fence	East of Football Field	ado to paving in the drea at	Removed	0001011.		
Current Condition:	Removed - BD		he silt fence for final stabiliza	ation as of the 9/24	/15 inspection.		
		Northwest of Football			,		
A4	Silt Fence	Field		Removed			
Current Condition:	Removed - The	silt fence is no longer n	eeded due to paving in the	area as of the 9/15/	15 inspection.		
	0111.5						
A5	Silt Fence	West of Football Field	71.6 6 6 1 6 1 77	Removed	(45: 0:		
Current Condition:	Removed - BD	Construction removed to	he silt fence for final stabiliza	ation as of the 9/24 I	/15 inspection.		
A9	Silt Fence	Southeast side of site		Removed			
Current Condition:		silt fence was not need	ed during construction	1100104			
	11000000						
A10	Silt Fence	Southeast side of site		Pending	Yes		
Current Condition:	Pending - BD C	onstruction removed the	e silt fence prior to the 10/18	/16 inspection to in	stall utilities. The		
	inspector will m	onitor the area to detern	nine if the silt fence needs to	be reinstalled.			
	The silt fence n	The silt fence needs to be repaired/reinstalled.					
		BD Construction was informed to complete by 1/30/17. Not done as of the last inspection. BD Construction					
	was reminded o	was reminded on 3/21/17, 3/30/17, 4/16/17, 5/1/17.					
A11	Silt Fence	South side of site	11/3/2015	Active	Yes		
Current Condition:	Poor Condition						
		The silt fence needs to be rengized/reinstalled					
	The silt fence needs to be repaired/reinstalled.						
	BD Construction was informed to complete by 1/30/17. Not done as of the last inspection. BD Construction						
	was reminded on 3/21/17, 3/30/17, 4/16/17, 5/1/17						
	0.11. E	Southwest corner of	44/0/0045		V		
A12	Silt Fence	site	11/3/2015	Active	Yes		
Current Condition:	Poor Condition						
	The silt fence n	The silt fence needs to be repaired/reinstalled.					
	The sit tence needs to be repaired/reinstalled.						
	BD Construction was informed to complete by 1/30/17. Not done as of the last inspection. BD Construction						
	was reminded on 3/21/17, 3/30/17, 4/16/17, 5/1/17						
	Southwest corner of						
A13	Silt Fence	site	11/3/2015	Active	Yes		
Current Condition:	Poor Condition		1 1 1 1				
	The silt fence needs to be repaired/reinstalled.						
	BD Construction was informed to complete by 1/30/17. Not done as of the last inspection. BD Construction						
	was reminded on 3/21/17, 3/30/17, 4/16/17, 5/1/17						

		South of existing		l				
A17 Current Condition:	Inlet filter	building - BD Construction insta	3/21/2016	Active	No No No No			
Guirent Gondition.	Good Condition - BD Construction installed the inlets prior to the 3/21/16 inspection. The inlets are above grade so no BMP protection is needed at this time. The inspector could not inspect this BMP as of the last inspection due to school being active and this area not being accessible.							
		South of existing	<u> </u>	I				
A18	Inlet filter	building	3/21/2016	Active	Yes			
Current Condition:	Fair Condition - The inspector could not inspect this BMP as of the lasts inspection due to school be and this area not being accessible.							
	The silt fence in undermined and needs to be backfilled.							
	BD Construction was informed to complete by 6/2/16. Not done as of last inspection. BD Construction was reminded on 7/20/16, 9/20/16, 10/19/16, 12/13/16, 1/24/17, 3/21/17, 3/30/17, 4/16/17, 5/1/17							
A19	Inlet filter	Between building on north side of the site		Removed				
Current Condition:			r to inspection on 11/14/16.	Removed				
		Between building on						
A20	Inlet filter	north side of the site	3/7/2016	Active	Yes			
Current Condition:	Fair Condition	•						
	The inlet pipe is	s broken off at the under	pipe and needs to be reinst	talled.				
	BD Construction	on was informed to comp	olete by 5/8/17. <b>Not done as</b>	of last inspection				
		Between building on						
A21	Inlet filter	north side of the site	3/7/2016	Active	No			
Current Condition:	Active - The inl		s/21/16 inspection. The inlet	is above grade so	no BMP protection is			
В	Construction Entrance	Southwest of Football Field		Removed				
Current Condition:			nanent entrance for school r		as of the 1/27/16			
	Construction	South side of existing	ı	1				
B 2	Entrance	parking lot	11/3/2015	Active	Yes			
Current Condition:	<b>Poor</b> Condition	1 - 30% effective.	121 2					
	Rock needs to	Rock needs to be added to the entrance.						
	BD Construction	BD Construction was informed to complete by 10/25/16. Not done as of last inspection. BD Construction						
	was reminded on 12/13/16, 1/24/17, 3/21/17, 3/30/17, 4/16/17, 5/1/17							
	Construction							
В 3	Entrance	Southeast side of site	I .	Active				
Current Condition:	Removed - BD	Construction paved the	construction entrance prior	to inspection on 5/1	/17.			
		Southeast of Football						
C1	Inlet Protection			Removed				
Current Condition:	Removed - This BMP is being removed from the report due to the inlet be located in a completed area of the project as of the 3/21/16 inspection.							
		Northeast of Football		1				
C2	Inlet Protection			Removed				
Current Condition:		s BMP is being removed of the 3/21/16 inspection	from the report due to the i	nlet be located in a	completed area of			
		Northwest of Football						
C3	Bale Check	Field	1/30/2017	Pending	Yes			
Current Condition:	Pending -							
	The bale check needs to be reinstalled due to continued runoff from the athletic field eroding the adjacent							
	drainage way.							
	BD Construction was informed to complete by 1/30/17. Not done as of the last inspection. BD Construction was reminded on 3/21/17, 3/30/17, 4/16/17, 5/1/17							
			-					
C7 Current Condition:	Bale Check Pending	East property line	12/19/2016	Pending	Yes			
Current Condition:								
	The bale check needs to be reinstalled in the drainage ditch.							
	BD Construction was informed to complete by 12/19/16. Not done as of last inspection. BD construction							
	was reminded on 1/24/17. BD Construction was reminded on 3/21/17, 3/30/17, 4/16/17, 5/1/17							
CW	Concrete	On Site	3/27/2017	Pending	Yes			

Current Condition:	Pending - The concrete will not be needed until paving starts again in the spring of 2017.					
	The washout needs to be installed.					
	DD 0					
	BD Construction was informed to complete by 3/27/17. Not done as of the last inspection. BD Construction was reminded on 3/30/17, 4/16/17, 5/1/17.					
STR	Streets On site In Place Active No					
Current Condition:	Good Condition - No major signs of track off.					
Current Condition.	Cood Condition	Southwest of Football	it on.			
SWPPP Sign	SWPPP Sign	Field	7/1/2015	Active	No	
Current Condition:	Good Condition	- The inspector installed	the SWPPP sign on 7/1/1	5.	•	
		Southeast Corners of				
Wattle Check 1	Straw Wattle	site	6/11/2015	Active	No	
Current Condition:	Good Condition		lled the wattle prior to the 6	/11/15 inspection.		
		North west corner of				
Wattle Check 2	Straw Wattle	site	11/18/2015	Active	Yes	
Current Condition:	Fair Condition Condition					
	Additional wattles need to be installed, or a more substantial BMP needs to be installed to prevent more					
	sediment from migrating to drainage way.					
	DD Combination was informative annulate by 4/20/47. Net the continue of the last increase in DD Combination					
	BD Construction was informed to complete by 1/30/17. Not done as of the last inspection. BD Construction was reminded on 3/21/17, 3/30/17, 4/16/17, 5/1/17					
W # 01 1 0		<u> </u>	•	1 4 11		
Wattle Check 3	Straw Wattle	West of entrance B3	6/11/2015	Active	Yes	
Current Condition:	Fair Condition - B3 and the street near the school addition has been paved. No BMP is needed due to the					
	elevation of the street.					
	The wattles need to be removed.					
	BD Construction was informed to complete by 5/8/17. Not done as of last inspection.					
4.1 01.						
MIN Van Dian						
TULK MINING				211.		
Inspector Signature: Reviewed By:						