E&A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599

www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

•		E&A- P2014.5	77.001			
Inspector: Matt Vanicek					Stage	
Project Name:		4				
For Week Ending:		NER115160 1/13/2017				
Project Location:	Waln	68662				
rojoet zooddom			gton St, Shelby, NE (Polk C		00002	
Grading:	100%					
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	100%					
Seeding:	70%					
Utilities:	100%					
Overall Development:	94%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions			
Sunday:	0.00"				Week	
Monday	0.00"			 	+	
Tuesday	0.00"					
Nednesday	0.00"					
Thursday	0.00"					
riday	0.02"					
Saturday	0.00"					
					Week	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.01"					
riday	0.00"					
Saturday	0.02"					
Normal according	0.0011				Week	
Sunday:	0.03" 0.00"		_			
Monday Fuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
Suturuuy	0.00				Weel	
Sunday:	0.00"				11001	
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.02"					
riday	0.00"					
Saturday	0.00"					
Sunday:	0.00"				Week	
Monday	0.00"					
Tuesday	0.00"					
Vednesday	0.00"	1/10/2018	46/24 Partly Cloudy			
Thursday	0.00"					
riday	0.00"					
Saturday	0.00"					
	None					
Complaints:	INOLIG					
Construction Sequencing:						

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?:

Grading is active (6/11/15) Phase 1 was compete prior to the 7/18/15 inspection. The grading of Phase 2 started prior to the 11/3/15 inspection. Grading of Phase 2 has been completed. Minor grading will be completed at a later date (3/7/16). BD Construction completed grading the parking lot (8/1/16)

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Grading is active (6/11/15). Phase 1 was compete prior to the 7/18/15 inspection. The grading of Phase 2 started prior to the 11/3/15 inspection. Grading of Phase 2 has been completed. Minor grading will be completed at a later date (3/7/16). BD Construction completed grading the parking lot (8/1/16).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing Vegetation. The area West and East of the football field and track were seeded or sodded(11/3/15). Paving of the school addition has started (4/28/17). Parking lot islands and drainage easement along south side of football field stabilized (8/14/17). Area around the playground and basketball court on the east side of the school was sodded (8/30/17). River rock placed on parking lot islands around flared ends (12/4/17).

SUMMARY QUESTIONS:

Are approved entrances and adjacent streets being maintained adequately?

Yes

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

No- sediment was deposited in the drainage along the south side of the site.

CHECKLIST QUESTIONS:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

dust associated with the construction activity adequately controlled on the site?

Yes

Comments:

Comments:

- 1) An Email was received from Doug Walter asking what percentage of the project area needs to be stabilized in order to stop performing erosion control inspections. Zach Jilek informed Doug Walter that the site needs 70% density of permanent ground cover to meet closure requirements. There are also BMP's that need will need to be removed after stabilization has taken place. The current estimated ground cover is around 50% as of the inspection on 10/07/17.
- 2) BD Construction was emailed a maintenance plan on 10/26/17 and they responded informing that they had plans to seed areas of the development for Spring, 2018.
- 3) The project will be inspected on a monthly basis as of 12/12/17 due to winter conditions and no plans to resume until spring.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1.) See BMP section for required maintenance.
- 2.) The area disturbed along the west end of the athletic field needs to be seeded and stabilized. BD Construction was informed to complete by 1/30/17. Not done as of last inspection. BD Construction was reminded on 3/21/17, 3/30/17, 4/16/17, 5/1/17, 5/24/17, 6/28/17, 8/20/17, 9/18/17, 10/25/17
- 3.) The sediment that has deposited in the drainage way along the south side of the site needs to be cleaned up. BD Construction was informed to complete by 1/30/17. Not done as of the last inspection. BD Construction was reminded on 3/21/17, 3/30/17, 4/16/17, 5/1/17, 5/24/17, 6/28/17, 8/20/17, 9/18/17, 10/25/17
- 4.) The area disturbed by utility work in the drainage way to the south of the site needs to be stabilized. BD Construction was informed to complete by 1/30/17. Not done as of the last inspection. BD Construction was reminded on 3/21/17, 3/30/17, 4/16/17, 5/1/17, 5/24/17, 6/28/17, 8/20/17, 9/18/17, 10/25/17
- 6.) Detention pond was completed and the area needs to be stabilized. Also a silt fence needs to be installed at the outlet pipe to prevent more runoff to ditch. BD Construction was informed to complete by 5/29/17. A piece of silt fence fabric was installed across the outlet pipe, but was not entrenched or secured. The pond was not stabilized as of the last inspection. BD Construction removed the silt fence from the outfall prior to the inspection on 6/14/17. BD Construction was informed to reinstall silt fence or a bale check at the outfall on 6/28/17 by 7/5/17. Not done as of the last inspection. BD Construction was reminded on 8/20/17, 9/18/17, 10/25/17

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
		Southwest of Football				
A1	Silt Fence	Field		Removed		
Current Condition:	Removed - BD	Construction removed t	he silt fence for final stabiliz	ation as of the 9/24	1/15 inspection.	
A2		South of Football Field		Removed		
Current Condition:	Removed - The silt fence was removed due to paving in the area as of the 9/15/15 inspection.					
A3	Silt Fence	East of Football Field		Removed		
Current Condition:	Removed - BD		he silt fence for final stabiliz	ation as of the 9/24	1/15 inspection.	
		Northwest of Football				
A4	Silt Fence	Field		Removed		
Current Condition:	Removed - The	silt fence is no longer r	eeded due to paving in the	area as of the 9/15	/15 inspection.	
A5	Silt Fence	West of Football Field		Removed		
Current Condition:	Removed - BD	Construction removed t	he silt fence for final stabiliz	ation as of the 9/24	I/15 inspection.	
A9	Silt Fence	Southeast side of site		Removed		
Current Condition:	Removed - The	silt fence was not need	ed during construction.	ı	1	
440	0.11 E	0 - 11 1 - 1 - 1 1 - 1 1		D		
A10	Silt Fence	Southeast side of site		Removed	. (0.2 - 0	
Current Condition:			of area and inactivity it will		at this time.	
A11	Silt Fence	South side of site	line of a discount of the	Removed	Hard at the Control DD	
Current Condition:	Silt Fence was removed due to completion of parking lot. Silt fence will not be re-installed at this time. BD Southwest corner of					
A12	Cilt Fonce		1/30/2017	Donding	Yes	
Current Condition:	Silt Fence	site	1/30/2017	Pending	res	
Current Condition:	Pending -					
	The silt fence needs to be reinstalled or the area needs to be stabilized.					
	BD Construction was informed to complete by 1/30/17. Not done as of the last inspection. BD Construction					
	was reminded on 3/21/17, 3/30/17, 4/16/17, 5/1/17, 5/24/17, 6/28/17, 8/20/17, 9/18/17, 10/25/17.					
		Southwest corner of				
A13	Silt Fence	site	1/30/2017	Pending	Yes	
L	•	•				

Current Condition:	Pending -					
Guirent Condition.	Pending -					
	The silt fence needs to be reinstalled or the area needs to be stabilized.					
	PD Construction was informed to complete by 4/20/47. Not done as of the last increasing DD Co. 1					
	BD Construction was informed to complete by 1/30/17. Not done as of the last inspection. BD Construction was reminded on 3/21/17, 3/30/17, 4/16/17, 5/1/17, 5/24/17, 6/28/17, 8/20/17, 9/18/17, 10/25/17.					
		South of existing				
A17	Inlet filter	building	action on F/22/17 by DD Co	Removed		
Current Condition:	Removed- Area	South of existing	pection on 5/22/17 by BD Co	onstruction.		
A18	Inlet filter	building		Removed		
Current Condition:	Removed- Area	a was paved prior to insp Between building on	pection on 5/22/17 by BD Co	onstruction.		
A19	Inlet filter	north side of the site		Removed		
Current Condition:	Pending - Then	inlet was removed prio	to inspection on 11/14/16.			
A20	Inlet filter	Between building on north side of the site	3/7/2016	Active	No	
Current Condition:						
	Good Condition - BD Construction repaired and paved around the inlet prior to the inspection on 6/14/17. E&A will monitor the need for BMP installation.					
		Between building on				
A21	Inlet filter	north side of the site	7/5/2017	Pending	Yes	
Current Condition:	Pending -					
	Inlet protection	needs to be installed or	the area around the inlet ne	eeds to be stabilized	d.	
			elete by 7/5/17. Not done as	of the last inspection	on. BD Construction	
	was reminded (on 8/20/17, 9/18/17, 10/3 Between building on	23/17	<u> </u>		
A22	Inlet filter	north side of the site	7/5/2017	Pending	Yes	
Current Condition:	Pending -					
	Inlet pretection	nanda ta ha inatallad ar	the area around the inlet no	anda ta ba atabiliza	d	
	inlet protection	needs to be installed of	the area around the inlet ne	eeds to be stabilized	u.	
	BD Constructio	n was informed to comp	lete by 7/5/17. Not done as	of the last inspection	on. BD Construction	
	was reminded of	on 8/20/17, 9/18/17, 10/2	25/17			
		Southwest of Football				
				D		
B Current Condition:	Entrance Removed - This	Field s entrance is now a perr	nanent entrance for school	Removed maintenance crews	as of the 1/27/16	
B Current Condition:			nanent entrance for school		as of the 1/27/16	
Current Condition:	Removed - This	s entrance is now a perr	nanent entrance for school i	maintenance crews	as of the 1/27/16	
Current Condition:	Removed - This inspection. Construction Entrance	s entrance is now a perr South side of existing parking lot		maintenance crews		
Current Condition:	Removed - This inspection. Construction Entrance	s entrance is now a perr South side of existing parking lot	nanent entrance for school in the contract of	maintenance crews		
Current Condition:	Removed - This inspection. Construction Entrance	s entrance is now a perr South side of existing parking lot		maintenance crews		
B 2 Current Condition: B 3	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance	Sentrance is now a perr South side of existing parking lot Construction removed t Southeast side of site	he entrance for paving purp	Removed oses prior to the ins	spection on 6/14/17.	
Current Condition: B 2 Current Condition:	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance	Sentrance is now a perr South side of existing parking lot Construction removed t Southeast side of site Construction paved the		Removed oses prior to the ins	spection on 6/14/17.	
B 2 Current Condition: B 3	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance	South side of existing parking lot Construction removed t Southeast side of site Construction paved the Southeast of Football	he entrance for paving purp	Removed oses prior to the ins	spection on 6/14/17.	
B 2 Current Condition: B 2 Current Condition: B 3 Current Condition:	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This	South side of existing parking lot Construction removed t Southeast side of site Construction paved the Southeast of Football Field S BMP is being removed	he entrance for paving purp construction entrance prior	Removed oses prior to the ins Active to inspection on 5/	spection on 6/14/17.	
B 2 Current Condition: B 3 Current Condition: C1	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This	South side of existing parking lot Construction removed t Southeast side of site Construction paved the Southeast of Football Field S BMP is being removed ff the 3/21/16 inspection	he entrance for paving purp construction entrance prior	Removed oses prior to the ins Active to inspection on 5/	spection on 6/14/17.	
B 2 Current Condition: B 3 Current Condition: C1 Current Condition:	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This the project as of	South side of existing parking lot Construction removed t Southeast side of site Construction paved the Southeast of Football Field S BMP is being removed for the 3/21/16 inspection Northeast of Football	he entrance for paving purp construction entrance prior	Removed oses prior to the ins Active to inspection on 5/ Removed inlet be located in a	spection on 6/14/17.	
B 2 Current Condition: B 3 Current Condition: C1	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This the project as o	Sentrance is now a perr South side of existing parking lot Construction removed to Southeast side of site Construction paved the Southeast of Football Field S BMP is being removed of the 3/21/16 inspection Northeast of Football Field	he entrance for paving purp construction entrance prior	Removed oses prior to the ins Active to inspection on 5/ Removed inlet be located in a	spection on 6/14/17. 1/17. completed area of	
B 2 Current Condition: B 3 Current Condition: C1 Current Condition:	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This the project as o	South side of existing parking lot Construction removed to Southeast side of site Construction paved the Southeast of Football Field S BMP is being removed the 3/21/16 inspection Northeast of Football Field S BMP is being removed the 3/21/16 inspection	he entrance for paving purp construction entrance prior from the report due to the i	Removed oses prior to the ins Active to inspection on 5/ Removed inlet be located in a	spection on 6/14/17. 1/17. completed area of	
B 2 Current Condition: B 3 Current Condition: C1 Current Condition: C2 Current Condition:	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This the project as of the pr	South side of existing parking lot Construction removed to Southeast side of site Construction paved the Southeast of Football Field S BMP is being removed the 3/21/16 inspection Northeast of Football Field S BMP is being removed fithe 3/21/16 inspection Northwest of Football Northwest of Football	construction entrance prior I from the report due to the i	Removed oses prior to the in: Active to inspection on 5/ Removed inlet be located in a	spection on 6/14/17. 1/17. completed area of completed area of	
B 2 Current Condition: B 3 Current Condition: C1 Current Condition: C2 Current Condition:	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This the project as of the pr	South side of existing parking lot Construction removed to Southeast side of site Construction paved the Southeast of Football Field S BMP is being removed the 3/21/16 inspection Northeast of Football Field S BMP is being removed the 3/21/16 inspection	he entrance for paving purp construction entrance prior from the report due to the i	Removed oses prior to the ins Active to inspection on 5/ Removed inlet be located in a	spection on 6/14/17. 1/17. completed area of	
B 2 Current Condition: B 3 Current Condition: C1 Current Condition: C2 Current Condition:	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This the project as of the pr	South side of existing parking lot Construction removed to Southeast side of site Construction paved the Southeast of Football Field S BMP is being removed the 3/21/16 inspection Northeast of Football Field S BMP is being removed fithe 3/21/16 inspection Northwest of Football Northwest of Football	construction entrance prior I from the report due to the i	Removed oses prior to the in: Active to inspection on 5/ Removed inlet be located in a	spection on 6/14/17. 1/17. completed area of completed area of	
B 2 Current Condition: B 3 Current Condition: C1 Current Condition: C2 Current Condition:	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This the project as of the project as of the project as of the project as of the project as o	Sentrance is now a perr South side of existing parking lot Construction removed t Southeast side of site Construction paved the Southeast of Football Field S BMP is being removed of the 3/21/16 inspection Northeast of Football Field S BMP is being removed of the 3/21/16 inspection Northeast of Football Field Northwest of Football Field Northwest of Football Field	construction entrance prior I from the report due to the i	Removed oses prior to the instance to inspection on 5/ Removed inlet be located in a Removed inlet be located in a Pending	spection on 6/14/17. 1/17. 1 completed area of completed area of Yes	
B 2 Current Condition: B 3 Current Condition: C1 Current Condition: C2 Current Condition:	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This the project as of the project as of the project as of the project as of the project as o	Sentrance is now a perr South side of existing parking lot Construction removed t Southeast side of site Construction paved the Southeast of Football Field S BMP is being removed of the 3/21/16 inspection Northeast of Football Field S BMP is being removed of the 3/21/16 inspection Northeast of Football Field Northwest of Football Field Northwest of Football Field	construction entrance prior I from the report due to the i	Removed oses prior to the instance to inspection on 5/ Removed inlet be located in a Removed inlet be located in a Pending	spection on 6/14/17. 1/17. 1 completed area of completed area of Yes	
B 2 Current Condition: B 3 Current Condition: C1 Current Condition: C2 Current Condition:	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This the project as of the project as of the project as of the project as of the project as o	South side of existing parking lot Construction removed to Southeast side of site Construction paved the Southeast of Football Field S BMP is being removed the 3/21/16 inspection Northeast of Football Field S BMP is being removed the 3/21/16 inspection Northeast of Football Field S BMP is being removed the 3/21/16 inspection Northwest of Football Field	construction entrance prior I from the report due to the i	Removed oses prior to the in: Active to inspection on 5/ Removed inlet be located in a Removed inlet be located in a	spection on 6/14/17. 1/17. 1/17. 1 completed area of Completed area of Yes Proding the adjacent	
B 2 Current Condition: B 3 Current Condition: C1 Current Condition: C2 Current Condition:	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This the project as of the pr	Sentrance is now a perr South side of existing parking lot Construction removed to Southeast side of site Construction paved the Southeast of Football Field Northwest of Football Field In was informed to comp	he entrance for paving purp construction entrance prior I from the report due to the interprit due to the interprit due to the interprit due to the interprit due to continued runoff from	Removed oses prior to the ins Active to inspection on 5/ Removed inlet be located in a Removed inlet be located in a Pending In the athletic field ess of the last inspect	a completed area of Yes Proding the adjacent Gion. BD Construction	
B 2 Current Condition: B 3 Current Condition: C1 Current Condition: C2 Current Condition: C3 Current Condition:	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This the project as of the pr	South side of existing parking lot Construction removed to Southeast side of site Construction paved the Southeast of Football Field In was informed to compone 3/21/17, 3/30/17, 4/10	he entrance for paving purp construction entrance prior If from the report due to the interpret due to the interpret due to the interpret due to continued runoff from the to continue the to conti	Removed oses prior to the instance crews Removed oses prior to the instance crews Active to inspection on 5/ Removed inlet be located in a removed in the athletic field earlier to the last inspect of the	spection on 6/14/17. 1/17. 1/17. 1 completed area of Yes 2 completed area of Yes 2 completed area of 1 completed area of 1 completed area of	
B 2 Current Condition: B 3 Current Condition: C1 Current Condition: C2 Current Condition: C3 Current Condition:	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This the project as of the pr	Sentrance is now a perr South side of existing parking lot Construction removed to Southeast side of site Construction paved the Southeast of Football Field Southeast of	the entrance for paving purp construction entrance prior from the report due to the information of the infor	Removed oses prior to the instance crews Active to inspection on 5/ Removed inlet be located in a Pending Pending The athletic field of the instance of the last inspection on 5/ Active Active	spection on 6/14/17. 1/17. 1/17. 1 completed area of Yes 2 completed area of Yes 2 completed area of No	
B 2 Current Condition: B 3 Current Condition: C1 Current Condition: C2 Current Condition: C3 Current Condition:	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This the project as of the pr	Sentrance is now a perr South side of existing parking lot Construction removed to Southeast side of site Construction paved the Southeast of Football Field Southeast of	he entrance for paving purp construction entrance prior If from the report due to the interpret due to the interpret due to the interpret due to continued runoff from the to continue the to conti	Removed oses prior to the instance crews Active to inspection on 5/ Removed inlet be located in a Pending Pending The athletic field of the instance of the last inspection on 5/ Active Active	spection on 6/14/17. 1/17. 1/17. 1 completed area of Yes 2 completed area of Yes 2 completed area of No	
Current Condition: B 2 Current Condition: B 3 Current Condition: C1 Current Condition: C2 Current Condition: C3 Current Condition: C4 Current Condition:	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This the project as of the pr	South side of existing parking lot Construction removed to Southeast side of site Construction paved the Southeast of Football Field S BMP is being removed of the 3/21/16 inspection Northeast of Football Field S BMP is being removed of the 3/21/16 inspection Northwest of Football Field Northwest of Football Field I needs to be reinstalled I needs to be reinstalled I now was informed to compon 3/21/17, 3/30/17, 4/10 North of B2 I n BD Construction installed Northwest of Football	the entrance for paving purp construction entrance prior of the form the report due to the information of th	Removed oses prior to the instance crews Active to inspection on 5/ Removed inlet be located in a Removed inlet be located in a Pending The athletic field e s of the last inspect 7, 8/20/17, 9/18/17 Active ared end prior to the	spection on 6/14/17. 1/17. 1/17. 1/17. 1 completed area of Yes 2 completed area of Yes 2 completed area of No e inspection on	
Current Condition: B 2 Current Condition: B 3 Current Condition: C1 Current Condition: C2 Current Condition: C3 Current Condition:	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This the project as of the pr	South side of existing parking lot Construction removed to Southeast side of site Construction paved the Southeast of Football Field Southeast of Football Southeast of Football Southeast of Football Southeast of Football Construction install Southeast side of site Southeast side of Southeast side of Football Southeast side of Football Construction removed to Construction removed to Construction removed to Southeast side of Football Southeast side of Southeast side	the entrance for paving purp construction entrance prior from the report due to the information of the infor	Removed oses prior to the instance crews Active to inspection on 5/ Removed inlet be located in a Removed inlet be located in a Pending The athletic field e s of the last inspect 7, 8/20/17, 9/18/17 Active ared end prior to the	spection on 6/14/17. 1/17. 1/17. 1/17. 1 completed area of Yes 2 completed area of Yes 2 completed area of No e inspection on	
Current Condition: B 2 Current Condition: B 3 Current Condition: C1 Current Condition: C2 Current Condition: C3 Current Condition: C4 Current Condition: C5 Current Condition:	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This the project as of the pr	South side of existing parking lot Construction removed to Southeast side of site Construction paved the Southeast of Football Field Southeast of Field Sou	the entrance for paving purp construction entrance prior of the form the report due to the information of th	Removed oses prior to the instance crews Active to inspection on 5/ Removed inlet be located in a Removed inlet be located in a Pending The athletic field of the located in a Active The active The last inspect The last ins	spection on 6/14/17. 1/17. 1/17. 1/17. 1 completed area of Yes 2 completed area of Yes 2 completed area of No e inspection on	
Current Condition: B 2 Current Condition: B 3 Current Condition: C1 Current Condition: C2 Current Condition: C3 Current Condition: C3 Current Condition: C4 Current Condition: C5 Current Condition:	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This the project as of the inspect as of the in	South side of existing parking lot Construction removed to Southeast side of site Construction paved the Southeast of Football Field Southeast of Fie	he entrance for paving purp construction entrance prior I from the report due to the interpretation of the i	Removed oses prior to the ins Active to inspection on 5/ Removed inlet be located in a Removed inlet be located in a Pending The athletic field of the last inspect 7, 8/20/17, 9/18/17 Active ared end prior to the lead of the last inspect Removed Removed Removed Removed Removed Removed	spection on 6/14/17. 1/17. 1/17. 1 completed area of Yes 2 completed area of Yes 2 completed area of No 2 inspection on 1 completed area of 1 completed area of 2 completed area of 2 completed area of 3 completed area of 4 completed area of 2 completed area of 2 completed area of 3 completed area of 4 completed area of 2 completed area of 2 completed area of 3 completed area of 4 completed area of 2 completed area of 3 completed area of 4 completed area of 4 completed area of 2 completed area of 3 completed area of 4 completed area of 5 completed area of 5 completed area of 5 completed area of 5 completed area of 6 completed area of 6 completed area of 8 comp	
Current Condition: B 2 Current Condition: B 3 Current Condition: C1 Current Condition: C2 Current Condition: C3 Current Condition: C4 Current Condition: C5 Current Condition:	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This the project as of the inspect as of the in	South side of existing parking lot Construction removed to Southeast side of site Construction paved the Southeast of Football Field Southeast of Fie	the entrance for paving purp construction entrance prior of the form the report due to the information of th	Removed oses prior to the ins Active to inspection on 5/ Removed inlet be located in a Removed inlet be located in a Pending The athletic field of the last inspect 7, 8/20/17, 9/18/17 Active ared end prior to the lead of the last inspect Removed Removed Removed Removed Removed Removed	spection on 6/14/17. 1/17. 1/17. 1 completed area of Yes 2 completed area of Yes 2 completed area of No 2 inspection on 1 completed area of 1 completed area of 2 completed area of 2 completed area of 3 completed area of 4 completed area of 2 completed area of 2 completed area of 3 completed area of 4 completed area of 2 completed area of 2 completed area of 3 completed area of 4 completed area of 2 completed area of 3 completed area of 4 completed area of 4 completed area of 2 completed area of 3 completed area of 4 completed area of 5 completed area of 5 completed area of 5 completed area of 5 completed area of 6 completed area of 6 completed area of 8 comp	
Current Condition: B 2 Current Condition: B 3 Current Condition: C1 Current Condition: C2 Current Condition: C3 Current Condition: C3 Current Condition: C4 Current Condition: C5 Current Condition:	Removed - This inspection. Construction Entrance Removed - BD Construction Entrance Removed - BD Inlet Protection Removed - This the project as of the inspect as of the in	South side of existing parking lot Construction removed to Southeast side of site Construction paved the Southeast of Football Field Southeast of Football Construction removed to spection on 8/30/17. Northwest of Football Construction removed to construction on 8/30/17. Northwest of Football Construction removed to construction removed to spection on 8/30/17.	he entrance for paving purp construction entrance prior I from the report due to the interpretation of the i	Removed oses prior to the ins Active to inspection on 5/ Removed inlet be located in a Removed inlet be located in a Pending The athletic field of the last inspect 7, 8/20/17, 9/18/17 Active ared end prior to the lead of the last inspect Removed Removed Removed Removed Removed Removed	spection on 6/14/17. 1/17. 1/17. 1 completed area of Yes 2 completed area of Yes 2 completed area of No 2 inspection on 1 completed area of 1 completed area of 2 completed area of 2 completed area of 3 completed area of 4 completed area of 2 completed area of 2 completed area of 3 completed area of 4 completed area of 2 completed area of 2 completed area of 3 completed area of 4 completed area of 2 completed area of 3 completed area of 4 completed area of 4 completed area of 2 completed area of 3 completed area of 4 completed area of 5 completed area of 5 completed area of 5 completed area of 5 completed area of 6 completed area of 6 completed area of 8 comp	

Current Condition:	Removed - BD Construction removed the straw wattle prior to the inspection on 11/7/17.				
		Northwest of Football			
C8	Bale Check	Field		Removed	
Current Condition:	Removed - BD	Construction removed t	he straw wattle due to comp	letion of sodding/st	abilization in the
	area as of the inspection on 8/30/17.				
	Concrete				
CW	Washout	On Site		Removed	
Current Condition:	Removed - Due to all major paving being completed a washout is no longer being recommended.				
STR	Streets	On site	In Place	Active	No
Current Condition:	Good Condition - No major signs of track off.				
		Southwest of Football			
SWPPP Sign	SWPPP Sign	Field	7/1/2015	Active	No
Current Condition:	Good Condition - The inspector installed the SWPPP sign on 7/1/15.				
		Southeast Corners of			
Wattle Check 1	Straw Wattle	site		Removed	
Current Condition:	Removed - BD Construction removed the wattle prior to the inspection on 7/27/17.				
		North west corner of			
Wattle Check 2	Straw Wattle	site		Removed	
Current Condition:	Removed - BD Construction removed the straw wattle prior to the inspection on 11/7/17.				
Wattle Check 3	Straw Wattle	West of entrance B3	_	Removed	
Current Condition:	Removed - BD	Construction removed t	he straw wattle prior to inspe	ection on 5/22/17.	
Inspector Signature:			Reviewed By:	Get Sol	