E&A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

		E&A- P2	019.327.000		
Inspector: Jason Brackett		Stage			
Project Name:		2			
For Week Ending:		68059			
Project Location:	SW				
Project Location.	Phase I				
Grading:	100	%			
Sanitary Sewer:	1009	%			
Storm Sewer:	1009				
Paving:	1009				
Seeding:	75°				
Utilities:	100				
Overall Development:	709	%			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.06"				
Wednesday	0.3"				
Thursday	0.38"				
Friday	0.00"				
Saturday	0.00"				
					Week
Sunday:	0.00"				
Monday	0.00"	3/23/2020	Cloudy 49/38	2:25 AM	
Tuesday	0.00"		,		
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.10"				
Saturday	0.30"				
Saturday	0.30				Week
Friday	N/A				
Monday	N/A				
Tuesday	N/A				
Wednesday	N/A				
Thursday	N/A				
Friday	N/A				
Saturday	N/A				
Complaints:					

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading in Phase I was completed prior to E&A being hired to conduct SWPPP inspections (1/3/2020).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading in Phase I was completed prior to E&A being hired to conduct SWPPP inspections (1/3/2020).

What temporary or permanent stabilization measures listed in this section are being implemented? Site was seeded prior to E&A being hired to conduct SWPPP inspections (1/3/2020).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion

No, See Findings Section.

Yes

No, See BMPs section

No, See BMPs section

Are construction entrances and adjacent streets being maintained adequately?

No, See BMPs section

Create Corrective Action?
No, See BMPs section

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Comments: Site was active for homebuilding during the most recent inspection.

Civil development and some homebuilding was completed prior to E&A being hired to conduct SWPPP inspections on 1/3/2020. Projected install dates for the BMPs listed below will reflect the date when the inspector first observed the BMPs on 1/3/2020.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section of this report.
- 2) Vacant-disturbed lots need to be stabilized.
- A. Lot 69 R1, 87 R1, 1R2, 2R2, and 18 needs to be stabilized. Gene Graves was informed to complete by 1/17/2020 when weather allows. Not done as of the last inspection. Gene Graves was reminded on 3/11/2020.
- B. Overgraded lots during homebuilding construction need to be stabilized. All builders were informed to complete by 1/17/2020 when weather allows and as-needed. Not done as of the last inspection.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
Al 1	Area Inlet Protection	See SWPPP	1/3/2020	Pending	Yes		
Current Condition:	Pending - Area inlet was installed prior to the 1/3/2020 inspection. Silt fence wrap needs to be installed around the area inlet. Gene Graves was informed to complete by 1/10/2020. Not done as of the last inspection. Gene Graves was reminded on 3/11/2020.						
Al 2	Area Inlet Protection	See SWPPP	1/3/2020	Active	No		
Current Condition:	matted and the inlet drains	s to SB 2; no inlet prote	prior to the 1/3/2020 inspection to the 1/3/2020 inspection tion will be recommended at	this time.			
Al 3 Current Condition:	Area Inlet Protection	See SWPPP	3/9/2020 stalled prior to the 3/9/2020 in	Active	Yes		
	Remaining silt fence/T-posts around the inlet should be removed. Gene Graves was informed to complete by 3/16/20. Not done as of the last inspection.						
Al 4	Area Inlet Protection	See SWPPP	3/9/2020	Active	No		
Current Condition:	Active - Area inlet with dome grate was installed prior to the 3/9/20 inspection. The surrounding area was seeded and matted and the inlet drains to SB 2; no inlet protection will be recommended at this time.						
CW 1	Concrete Washout	Lot 81 Replat 1	1/3/2020	Active	Yes		
Current Condition:	Fair Condition - A lot level concrete washout was installed on Lot 81 Replat 1 prior to the 1/3/2020 inspection. 1.) Concrete washout needs to be cleaned out and a berm needs to be built along the front of the washout to prevent concrete waste from running off into the street. 2.) Rock needs to be added to the approach for the concrete washout to prevent trackout when in use. 1.) Gene Graves was informed to complete by 1/10/2020. Not done as of the last inspection. Gene Graves was reminded on 3/11/2020. 2.) Gene Graves was informed to complete by 1/10/2020. Not done as of the last inspection. Gene Graves was reminded on 3/11/2020.						
IP 1	Inlet Protection	See SWPPP	1/3/2020	Active	No		
Current Condition:	Good Condition - Curb inle		ed prior to the 1/3/2020 inspe	ction.			
IP 2	Inlet Protection	See SWPPP	1/3/2020	Active	No		
Current Condition:	Good Condition - Curb inle	et protection was install	ed prior to the 1/3/2020 inspe	ction.			
IP 3	Inlet Protection	See SWPPP	1/3/2020	Active	No		
Current Condition:	Good Condition - Curb inle	et protection was install	ed prior to the 1/3/2020 inspe	ction.			
IP 4	Inlet Protection	See SWPPP	1/3/2020	Active	No		

Owner to Own ditions	On and On an alliform County fort	-11	li l 1l 1/0/0000 i		
Current Condition: IP 5	Inlet Protection	et protection was installe See SWPPP	ed prior to the 1/3/2020 insp 1 1/3/2020	Active	No
Current Condition:			ed prior to the 1/3/2020 insp		140
IP 6	Inlet Protection	See SWPPP	1/3/2020	Active	No
Current Condition:			ed prior to the 1/3/2020 insp		
IP 7	Inlet Protection	See SWPPP	1/3/2020	Active	No
Current Condition:	Good Condition - Curb inl	et protection was installe	ed prior to the 1/3/2020 insp	ection.	
IP 8	Inlet Protection	See SWPPP	1/3/2020	Active	No
Current Condition:	Good Condition - Curb inl	et protection was installe	ed prior to the 1/3/2020 insp	ection.	
IP 9	Inlet Protection	See SWPPP	1/3/2020	Active	Yes
Current Condition:	Fair Condition - Curb inlet	protection was installed	d prior to the 1/3/2020 inspe	ction.	
	IP needs to be cleaned ou Gene Graves was informe 3/11/2020.		2020. Not done as of the las	st inspection. Gene Gra	ves was reminded o
IP 10	Inlet Protection	See SWPPP	1/3/2020	Active	No
Current Condition:			ed prior to the 1/3/2020 insp		-
IP 11	Inlet Protection	See SWPPP	1/3/2020	Active	No
Current Condition:	Good Condition - Curb inl	et protection was installe	ed prior to the 1/3/2020 insp	ection.	
IP 12	Inlet Protection	See SWPPP	1/3/2020	Active	No
Current Condition:	Good Condition - Curb inl		ed prior to the 1/3/2020 insp		
IP 13	Inlet Protection	See SWPPP	1/3/2020	Active	No
Current Condition:			ed prior to the 1/3/2020 insp		
IP 14	Inlet Protection	See SWPPP	1/3/2020	Active	No
Current Condition:			ed prior to the 1/3/2020 insp	_	
IP 15	Inlet Protection	See SWPPP	1/3/2020	Active	Yes
Current Condition:	Fair Condition - Curb inlet	protection was installed	d prior to the 1/3/2020 inspe	ction.	
	Gene Graves was informe	ed to complete by 1/10/2	2020. Not done as of the las	st inspection. Gene Gra	ves was reminded
	3/11/2020.				
IP 16	Inlet Protection	See SWPPP	1/3/2020	Active	No
IP 16 Current Condition:	Inlet Protection		1/3/2020 ed prior to the 1/3/2020 insp		No
	Inlet Protection Good Condition - Curb inl Inlet Protection	et protection was installe See SWPPP	ed prior to the 1/3/2020 insp 1/3/2020	ection. Active	No No
Current Condition: IP 17 Current Condition:	Inlet Protection Good Condition - Curb inl Inlet Protection Good Condition - Curb inl	et protection was installe See SWPPP et protection was installe	ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp	ection. Active	No
Current Condition: IP 17 Current Condition: IP 18	Inlet Protection Good Condition - Curb inl Inlet Protection Good Condition - Curb inl Inlet Protection	See SWPPP et protection was installe et protection was installe See SWPPP	ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp 1/3/2020	Active Active Active	
Current Condition: IP 17 Current Condition: IP 18 Current Condition:	Inlet Protection Good Condition - Curb inl Inlet Protection Good Condition - Curb inl Inlet Protection Good Condition - Curb inl Good Condition - Curb inl	et protection was installe See SWPPP et protection was installe See SWPPP et protection was installe	ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp	Active ection. Active ection. Active ection.	No No
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19	Inlet Protection Good Condition - Curb inl Inlet Protection Good Condition - Curb inl Inlet Protection Good Condition - Curb inl Inlet Protection Inlet Protection	et protection was installe See SWPPP et protection was installe See SWPPP et protection was installe See SWPPP	ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp ed prior to the 1/3/2020 insp	Active Active Active Active Active Active	No
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition:	Inlet Protection Good Condition - Curb inl Good Condition - Curb inl	et protection was installe See SWPPP et protection was installe See SWPPP et protection was installe See SWPPP et protection was installe	ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp ed prior to the 1/3/2020 insp	Active ection. Active ection. Active ection. Active ection.	No No No
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20	Inlet Protection Good Condition - Curb inl Inlet Protection	et protection was installe See SWPPP See SWPPP	ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp 1/3/2020	Active ection. Active ection. Active ection. Active ection. Active ection. Active	No No
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition:	Inlet Protection Good Condition - Curb inl	et protection was installe See SWPPP et protection was installe	ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp ed prior to the 1/3/2020 insp	Active section. Active section. Active section. Active section. Active section.	No No No
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 20 Current Condition: IP 21	Inlet Protection Good Condition - Curb inl Inlet Protection	et protection was installe See SWPPP	ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp 1/3/2020	Active section.	No No No
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 21 Current Condition:	Inlet Protection Good Condition - Curb inl	et protection was installe See SWPPP	ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp	Active section. Active section. Active section. Active section. Active section. Active section.	No No No No
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 21 Current Condition: IP 22	Inlet Protection Good Condition - Curb inl Inlet Protection	et protection was installe See SWPPP	ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp	Active section.	No No No
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 22 Current Condition:	Inlet Protection Good Condition - Curb inl Inlet Protection	et protection was installe See SWPPP et protection was installe	ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp	Active section.	No No No No No No
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 22 Current Condition: IP 23	Inlet Protection Good Condition - Curb inl Inlet Protection	et protection was installe See SWPPP	ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp	Active section.	No No No No
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 22 Current Condition:	Inlet Protection Good Condition - Curb inl	et protection was installe See SWPPP	ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp	Active section.	No No No No No No
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 23 Current Condition: IP 24	Inlet Protection Good Condition - Curb inl Inlet Protection	et protection was installe See SWPPP	ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp	Active section.	No No No No No No No
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 22 Current Condition: IP 23 Current Condition:	Inlet Protection Good Condition - Curb inl Inlet Protection	et protection was installe See SWPPP	ed prior to the 1/3/2020 insp 1/3/2020	Active section.	No No No No No No No
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 23 Current Condition: IP 24 Current Condition:	Inlet Protection Good Condition - Curb inl Inlet Protection	et protection was installe See SWPPP	ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp	Active section.	No No No No No No No No
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 24 Current Condition: IP 24 Current Condition: IP 25	Inlet Protection Good Condition - Curb inl Inlet Protection	et protection was installe See SWPPP	ed prior to the 1/3/2020 insp 1/3/2020	Active section.	No No No No No No No No
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 24 Current Condition: IP 25 Current Condition:	Inlet Protection Good Condition - Curb inl Inlet Protection	et protection was installe See SWPPP	ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp	Active section.	No
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 24 Current Condition: IP 24 Current Condition: IP 25 Current Condition: IP 26 Current Condition: IP 26 Current Condition: IP 27	Inlet Protection Good Condition - Curb inl Inlet Protection	et protection was installe See SWPPP	ed prior to the 1/3/2020 insp 1/3/2020	Active section.	No
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 23 Current Condition: IP 24 Current Condition: IP 25 Current Condition: IP 26 Current Condition:	Inlet Protection Good Condition - Curb inl Inlet Protection	et protection was installe See SWPPP	ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp	Active section.	No
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 24 Current Condition: IP 24 Current Condition: IP 25 Current Condition: IP 26 Current Condition: IP 27 Current Condition: IP 27 Current Condition: IP 27 Current Condition: IP 27	Inlet Protection Good Condition - Curb inl Inlet Protection	et protection was installe See SWPPP	ed prior to the 1/3/2020 insp 1/3/2020	Active section.	No
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 24 Current Condition: IP 25 Current Condition: IP 26 Current Condition: IP 27 Current Condition: IP 28 Current Condition:	Inlet Protection Good Condition - Curb inl Inlet Protection	et protection was installe See SWPPP	ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp	Active section.	No N
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 24 Current Condition: IP 25 Current Condition: IP 26 Current Condition: IP 27 Current Condition: IP 28 Current Condition: Lot 1 Replat 4	Inlet Protection Good Condition - Curb inl Inlet Protection	et protection was installe See SWPPP	ed prior to the 1/3/2020 insp 1/3/2020	Active section.	No N
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 24 Current Condition: IP 25 Current Condition: IP 26 Current Condition: IP 27 Current Condition: IP 28 Current Condition:	Inlet Protection Good Condition - Curb inl	et protection was installe See SWPPP et protection was installe	ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp	Active section. Pending 120 inspection.	No N
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 24 Current Condition: IP 25 Current Condition: IP 26 Current Condition: IP 27 Current Condition: IP 28 Current Condition: IP 28 Current Condition: IP 28 Current Condition: IP 28 Current Condition: Lot 1 Replat 4 Current Condition:	Inlet Protection Good Condition - Curb inl Inlet Protection	et protection was installe See SWPPP	ed prior to the 1/3/2020 insp	Active section. Active section.	No N
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 24 Current Condition: IP 25 Current Condition: IP 26 Current Condition: IP 27 Current Condition: IP 28 Current Condition: IP 28 Current Condition: IP 28 Current Condition: Lot 1 Replat 4 Current Condition: Lot 2 Replat 3	Inlet Protection Good Condition - Curb inl Inlet Protection	et protection was installe See SWPPP et protecti	ed prior to the 1/3/2020 insp 1/3/2020 ed prior to the 1/3/2020 insp	Active section.	No N
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 24 Current Condition: IP 25 Current Condition: IP 26 Current Condition: IP 27 Current Condition: IP 28 Current Condition: IP 28 Current Condition: IP 28 Current Condition: IP 28 Current Condition: Lot 1 Replat 4 Current Condition:	Inlet Protection Good Condition - Curb inl Individual Lot Pending - Charleston Hore Silt fence needs to be inst Charleston Homes was in reminded on 3/10/2020, 3 Individual Lot Active - Proline Homes b	et protection was installe See SWPPP et protection was installe Lot 1 Replat 4 nes began construction formed to complete by 1 /25/20. Lot 2 Replat 3 egan construction on the	ed prior to the 1/3/2020 insp	Active section.	No N
Current Condition: IP 17 Current Condition: IP 18 Current Condition: IP 19 Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 24 Current Condition: IP 25 Current Condition: IP 26 Current Condition: IP 27 Current Condition: IP 28 Current Condition: IP 28 Current Condition: IP 28 Current Condition: Lot 1 Replat 4 Current Condition: Lot 2 Replat 3	Inlet Protection Good Condition - Curb inl Inlet Protection	et protection was installe See SWPPP et protection was installe Lot 1 Replat 4 nes began construction formed to complete by 1 /25/20. Lot 2 Replat 3 egan construction on the	ed prior to the 1/3/2020 insp	Active section.	No N

Current Condition:	Pending - Urban Spark Construction began construction on the lot prior to the 2/10/2020 inspection. Urban Spark Construction removed the dirt pile from the ROW prior to the inspection on 2/24/20. Silt fence needs to be installed in the rear of the lot and along the east side of the lot. Urban Spark Construction was informed to complete by 2/10/2020. Not done as of the last inspection.							
Lot 17 Replat 1	Individual Lot	Lot 17 Replat 1	1/3/2020	Active	Yes			
Current Condition:	Fair Condition - Carlson C Custom Homes builder in: Silt fence needs to be exte	stalled silt fence in the rea	r of the lot prior to the 1/3		nspection. Carlson			
	Carlson Custom Homes binspection. Carlson Custo	ouilder will be informed to	complete by 1/10/2020 wh	en identified. Not done	e as of the last			
Lot 18 Replat 1	Individual Lot	Lot 18 Replat 1	1/27/2020	Active	No			
Current Condition:	Active - Charleston Home will monitor the need for E	s began construction on the	ne lot prior to the 1/27/202	0 inspection. Lot is rel	atively flat, the inspector			
Lot 21 Replat 1	Individual Lot	Lot 21 Replat 1	1/3/2020	Pending	Yes			
Current Condition:	Silt fence needs to be inst	Pending - McCaul Contracting began construction on the lot prior to the 1/3/2020 inspection. Silt fence needs to be installed along the north side of the lot and in the northernmost corner. McCaul Contracting was informed to complete by 1/10/2020. Not done as of the last inspection. McCaul Contracting was						
Lot 24 Replat 1	Individual Lot	Lot 24 Replat 1	1/3/2020	Active	Yes			
Current Condition:	Fair Condition - Carlson C Custom Homes builder in: 1.) Silt fence needs to be the lot. 2.) Silt fence is damaged	stalled silt fence in the sou	in the southeast corner of	ide of the lot prior to th	e 1/3/2020 inspection.			
Lot 56 Replat 1 Current Condition:	Inspection. Carlson Custor 2.) Carlson Custom Home inspection. Carlson Custor Individual Lot Fair Condition - Jeck & Coinstalled silt fence in the northeast corr	Lot 56 Replat 1 company Inc began constru	to complete by 1/10/2020 on 3/10/2020. 1/3/2020 on the lot prior to the prior to the 1/13/2020 inspection on the 1/13/2020 inspection to the	Active e 1/3/2020 inspection.	Yes Jeck & Company Inc.			
	Silt fence needs to be inst	talled along the south and informed to complete by 1 k & Company Inc was rer	east sides of the lot. /10/2020. Not done as of	the last inspection. Je	eck & Company was			
Lot 60 Replat 1	Individual Lot	Lot 60 Replat 1	1/3/2020	Pending	Yes			
Current Condition:	Pending - Urban Spark Co 1.) Silt fence needs to be 2.) Straw wattles need to b 1.) Urban Spark Construct Construction was reminde 2.) Urban Spark Construct	installed in the rear of the be installed along the fron tion was informed to competed on 2/13/2020.	lot and part-way up each at of the lot.	side around all ground				
1 22 2	Construction was reminde		blete by 1/10/2020. Not do	one as of the last inspe				
Lot 62 Replat 1	Individual Lot	ed on 2/13/2020. Lot 62 Replat 1	3/9/2020	Active	ction. Urban Spark			
Current Condition:	Individual Lot Good Condition - Paceset installed silt fence along th installed a wattle in the we	ed on 2/13/2020. Lot 62 Replat 1 tter Homes began constru he southwest and northwe	3/9/2020 ction on the lot prior to the st sides of the lot prior to	Active 3/9/2020 inspection. the 3/9/2020 inspection	L No Pacesetter Homes			
	Individual Lot Good Condition - Paceset installed silt fence along the	Lot 62 Replat 1 Itter Homes began construite southwest and northweest corner of the lot prior to Lot 77 Replat 1 Is began excavation on the lot prior to the lot 77 Replat 1	3/9/2020 ction on the lot prior to the st sides of the lot prior to to the 3/9/2020 inspection. 3/23/2020 he lot prior to the 3/23/3	Active a 3/9/2020 inspection. the 3/9/2020 inspection Active 0 inspection. A dirt p	No Pacesetter Homes Pacesetter Homes No			
Current Condition: Lot 77 Replat 1 Current Condition:	Individual Lot Good Condition - Paceset installed silt fence along the installed a wattle in the we Individual Lot Active - Sundown Home the ROW; however, Sun	Lot 62 Replat 1 Itter Homes began construite southwest and northweest corner of the lot prior to Lot 77 Replat 1 s began excavation on to down Homes was active	3/9/2020 ction on the lot prior to the st sides of the lot prior to to the 3/9/2020 inspection. 3/23/2020 he lot prior to the 3/23/3	Active 2 3/9/2020 inspection. the 3/9/2020 inspection Active 0 inspection. A dirt p	No Pacesetter Homes Pacesetter Homes No			
Current Condition: Lot 77 Replat 1	Individual Lot Good Condition - Paceset installed silt fence along tt installed a wattle in the we Individual Lot Active - Sundown Home the ROW; however, Sun Individual Lot	Lot 62 Replat 1 Itter Homes began construite southwest and northweest corner of the lot prior to Lot 77 Replat 1 Is began excavation on to down Homes was active Lot 85 Replat 1 builder began excavation	3/9/2020 ction on the lot prior to the st sides of the lot prior to to the 3/9/2020 inspection. 3/23/2020 he lot prior to the 3/23/3 ely excavating at the time 3/23/2020 n on the lot prior to the	Active 2 3/9/2020 inspection. 2 Active 3/9/2020 inspection Active 0 inspection. A dirt pe, the inspector will ce Active 3/23/30 inspection. A	No Pacesetter Homes No			

Current Condition:	Fair Condition - Charleston Homes began construction on the lot prior to the 1/3/2020 inspection. Charleston Homes staked down a portable toilet on the front of the lot prior to the 1/3/2020 inspection. Charleston Homes removed the portable toilet and installed straw wattles along the front of the lot prior to the 3/23/20 inspection. Silt fence needs to be installed along the north side of the lot.					
	Charleston Homes was informed to complete by 1/10/2020. Not done as of the last inspection. Charleston Homes was reminded on 3/10/2020, 3/25/20.					
Lot 121 Replat 1	Individual Lot	Lot 121 Replat 1	1/3/2020	Pending	Yes	
Current Condition:	Silt fence needs to be inst	cting began construction	on the lot prior to the 1/3/20 ot behind all ground disturba	nce or the lot needs to		
Lot 122 Replat 1	Individual Lot	Lot 122 Replat 1	1/3/2020	Pending	Yes	
Current Condition:	concrete waste prior to the Silt fence needs to be inst	e 3/9/2020 inspection.	on on the lot prior to the 1/3/ ot behind all ground disturba	nce.	cleaned up the	
Lot 123 Replat 1	Individual Lot	Lot 123 Replat 1	1/3/2020	Active	Yes	
Current Condition:			uction on the lot prior to the			
	 Silt fence needs to be installed along the south and east sides of the lot. Straw wattles on the front of the lot need to be repaired/replaced. Charleston Homes was informed to complete by 1/10/2020. Not done as of the last inspection. Charleston H reminded on 3/10/2020, 3/25/2020. Charleston Homes was informed to complete by 3/30/2020. 					
Lot 124 Replat 1	Individual Lot	Lot 124 Replat 1	1/3/2020	Pending	Yes	
Current Condition:			on on the lot prior to the 1/3/			
Lot 125 Replat 1 Current Condition:	D&E Custom Building was Individual Lot Pending - McCaul Contract Silt fence needs to be inst	s informed to complete to Lot 125 Replat 1 cting began construction talled along the south ar	nd east sides of the lot and in any 1/10/2020. Not done as of 1/3/2020 non the lot prior to the 1/3/20 nd east sides of the lot and in 1/10/2020. Not done as of 1/10/2020. Not done as of	of the last inspection. Pending 020 inspection. n the northeast corner.	Yes	
	reminded on 3/10/2020.					
SB 1	Sediment Basin	See SWPPP	1/3/2020	Active	No No	
Current Condition:	-		Illed prior to the 1/3/2020 ins	' 		
SB 2 Current Condition:	Sediment Basin	See SWPPP	1/3/2020 Illed prior to the 1/3/2020 ins	Active	No No	
SB 3	Sediment Basin	See SWPPP	1/3/2020	Active	No	
Current Condition:			lled prior to the 1/3/2020 ins			
SB 4	Sediment Basin	See SWPPP	1/3/2020	Active	No	
Current Condition:			lled prior to the 1/3/2020 ins			
SF 1	Silt fence	See SWPPP	1/3/2020	Active	Yes	
Current Condition:	Silt fence can be removed Gene Graves was informe 3/11/2020.	d behind Lot 93 Replat 1 ed to complete by 1/10/2	due to established vegetation. Not done as of the las	on. t inspection. Gene Gr	aves was reminded on	
SF 2	Silt fence	See SWPPP	1/3/2020	Active	Yes	
Current Condition:	1.) Silt fence needs to be 2.) Silt fence needs to be	properly trenched in mu reinstalled where remov	Itiple locations along the silt red behind Lot 100 Replat 1.	fence run.		
	on 3/11/2020.		0/2020. Not done as of the	· ·		
SF 3	Silt fence	See SWPPP	1/3/2020	Active	Yes	
				, ,,,,,		

Current Condition:	Fair Condition - Silt fence was installed across the front of Lot 87 Replat 1 prior to the 1/3/2020 inspection.					
	Silt fence needs to be properly trenched in and hooked on either side of the lot.					
	Gene Graves was informed to complete by 1/10/2020. Not done as of the last inspection. Gene Graves was reminded on 3/11/2020.					
		Internal/S 132nd and				
STR	Streets	Main Street	1/3/2020	Active	Yes	
	Minor street cleaning is needed throughout the site (Cedar Circle, Lilac Circle, Elm Circle, SE of Lot 69 Replat 1, front of Lot 87 Replat 1, adjacent to the concrete washout, and at the N 10th Avenue stub road). All builders and Gene Graves were informed to complete by 1/4/2020. Not done as of the last inspection. Gene Graves was reminded on 3/11/2020.					
SWPPP Signs	Misc/Other	S 132nd Street and Man Street	1/27/2020	Active	No	
Current Condition:			.,,			
Current Condition.	Good Condition - E&A inspector installed SWPPP signs at the intersection of Main Street and N 10th Ave and S 132nd Street and Hazel Lane during the 1/27/20 inspection.					
Inspector Signature:	Jule Mont			Reviewed By:	But Sul	