E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Fnaineering Answers

Environmental Services De	pt. wanager			Liigineerin	g Allswers
		E&A - P20	19.327.000		
Inspector: Shaun McGuire					Stage
Project Name:			gfield Pines 201600337		1
For Week Ending:		12/	/31/2022		68059
Project Location:	SW o	f 132nd Street and I	Platteview Road, Springfiel	ld, NE	
	Phase I				
Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%				
Seeding:	75%				
Utilities:	100%				
Overall Development:	70%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"				
Wednesday:	0.00"	12/28/2022	Sunny 45/28	11:30 AM	
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
Complaints:	None				
Construction Sequencing:					
Which portion(s) (i.e. drainage bas	ins) of the site have had a temp	orary or permanent cess	sation of grading, earthwork, or gr	round disturbance in the last 14	days?

Grading in Phase I was completed prior to E&A being hired to conduct SWPPP inspections (1/3/20).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading in Phase I was completed prior to E&A being hired to conduct SWPPP inspections (1/3/20).

What temporary or permanent stabilization measures listed in this section are being implemented?

Site was seeded prior to E&A being hired to conduct SWPPP inspections (1/3/20). Portion of ground to the southeast of SB 4 seeded and matted (5/11/20).

Checklist Questions:

re receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

-lave disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Create Corrective Action?

No, see Findings section.

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

No, see BMPs section and Findings section.

Are construction entrances and adjacent streets being maintained adequately?

Yes

Create Corrective Action?

N/A

s dust associated with the construction activity adequately controlled on the site?

Yes

reate Corrective Action?

N/A

Comments

Comments: Site was active for homebuilding during the most recent inspection.

The School Site was graded prior to the 9/23/20 inspection. The School Site is not covered by the Springfield Pines permit (SPR-20200728-5543-GP1).

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section of this report.
- 2) Vacant-disturbed lots need to be stabilized.
- A. Overgraded lots during homebuilding construction need to be stabilized. All builders were informed to complete by 1/17/20 when weather allows and asneeded. Not done as of the last inspection. All builders were reminded on 9/24/20, 6/24/21.
- 3) Concrete waste was located throughout the development. D.R. Horton was informed to clean up concrete waste in SB 4 on 3/3/22. Not done as of last inspection. D.R. Horton was reminded on 3/24/22, 5/24/22, 6/2/22, 6/17/22, 6/23/22, 8/19/22, 8/31/22, 11/11/22. D.R. Horton was informed to clean up concrete waste on lot 72 on 8/31/22. Not done as of last inspection. D.R. Horton was reminded on 11/11/22.

	-			1 6	1		
Unique Name	Type	Location	Projected Install Date	Status	Maintenance		
Al 1	Area Inlet Protection	See SWPPP	1/3/2020 inspection. The surrounding	Active	No the inlet drains to SP		
Current Condition:	1; no inlet protection will b	•		area is vegetated and	Title fillet dialits to SB		
Al 2	Area Inlet Protection	See SWPPP	1/3/2020	Active	No		
Current Condition:			installed prior to the 1/3/20 ins				
			rotection will be recommended				
		·	man installed 3 additional inlet: nlet protection prior to the 11/9	·	ection prior to the		
Al 3	Area Inlet Protection	See SWPPP	3/9/2020	Active	No		
Current Condition:			prior to the 3/9/20 inspections.				
	silt fence/T-posts around			_			
Al 4	Area Inlet Protection	See SWPPP	3/9/2020	Active	No		
Current Condition:	Active - Area inlet with do	me grate was installed p	prior to the 3/9/20 inspection.	The surrounding area	was seeded and		
	matted and the inlet drains	s to SB 2; no inlet prote	ction will be recommended at	this time.			
CW 1	Concrete Washout	Lot 81 Replat 1		Removed			
Current Condition:	Removed - A lot level con	crete washout was insta	alled on Lot 81 Replat 1 prior to	o the 1/3/20 inspection	n. Gene Graves		
	cleaned out the concrete	washout prior to the insp	pection on 5/11/20, the berm re	ecommendation is no	longer needed. Gene		
		• • •	oach prior to the 6/1/20 inspec				
	· ·	•	aves relocated the concrete wa				
			he concrete washout prior to t	•			
		•	tion, the E&A inspector will me				
		•	inspection. Mobile washout wrete washout on to lot 117 price	-	•		
	•		/22 inspection. D.R. Horton re	•			
	10/11/22 inspection, the E			moved the concrete w	ashout phor to the		
ID 4	•	See SWPPP	T	Damariad	I		
IP 1 Current Condition:	Inlet Protection		Let filter prior to the 4/27/20 insp	Removed	a hasin reinstallation		
Current Condition.	is not recommended.	eeding removed the line	et linter prior to the 4/2//20 map	bection. The drains to	a basiii, reilistallation		
IP 2	Inlet Protection	See SWPPP		Removed			
Current Condition:	Removed - Commercial S	eeding removed the inle	et filter prior to the 4/27/20 insp	pection. Inlet drains to	a basin, reinstallation		
	is not recommended. D.R.	. Horton reinstalled the i	inlet filter prior to the 6/21/22 in	nspection. D.R. Horton	n removed the inlet filter		
	prior to the 12/21/22 inspe	ection. Inlet drains to a b	easin, reinstallation is not reco	mmended.			
IP 3	Inlet Protection	See SWPPP		Removed			
Current Condition:	Removed - Commercial S	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation					
	is not recommended.						
IP 4	Inlet Protection	See SWPPP		Removed			
Current Condition:			et filter prior to the 4/27/20 ins				
			filter protection prior to the 5/3		Horton removed the		
	inlet filter prior to the 12/2	1/22 inspection. Inlet dra	ains to a basin, reinstallation is	s not recommended.			
IP 5	Inlet Protection	See SWPPP		Removed			
Current Condition:		•	et filter prior to the 4/27/20 insp				
			filter protection prior to the 5/3	•	Horton removed the		
	·		ains to a basin, reinstallation is		T		
IP 6	Inlet Protection	See SWPPP		Removed	- basis asis at Hadaa		
Current Condition:		•	et filter prior to the 4/27/20 insp				
			filter protection prior to the 8/3	•	Horton removed the		
ID 7	· · · · · · · · · · · · · · · · · · ·		ains to a basin, reinstallation is	•	I		
IP 7 Current Condition:	Inlet Protection	See SWPPP	l et filter prior to the 4/27/20 insp	Removed	a hasin reinstallation		
Current Condition:	is not recommended.	ceaning removed the IME	5. mei phoi to the 4/2//20 INS	Jeonon, mieruranis (a vasiii, itiiistallatiUN		
IP 8	Inlet Protection	See SWPPP		Removed	T		
Current Condition:			I et filter prior to the 4/27/20 insp		a hasin reinstallation		
Our on Sonation.		•	filter protection prior to the 8/3				
			ains to a basin, reinstallation is	•			
IP 9	•	See SWPPP		1	I		
17 9	Inlet Protection	366 34144	l	Removed			

Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.
ID 40	
IP 10	Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is
Current Condition:	not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton cleaned out the
	inlet filter prior to the 6/7/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton
	removed the inlet filter prior to the 12/21/22 inspection. D.N. Horton remarkative the machiner filter prior to the 12/21/22 inspection. B.N. Horton remarkative the machiner filter prior to the 12/21/22 inspection. B.N. Horton remarkative the machiner filter prior to the 0/1/22 inspection.
	removed the filler prior to the 12/27/22 inspection. Thet drains to a basin, removalization is not recommended.
IP 11	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is
	not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton repaired the inlet
	filter prior to the 4/5/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 6/28/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.
	removed the filler filler prior to the 12/21/22 inspection. Thet drains to a basin, reinstallation is not recommended.
IP 12	Jalet Destantion Con CM/DDD
Current Condition:	Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation
Current Condition:	is not recommended.
ID 40	
IP 13	Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation
Current Condition:	is not recommended.
15.11	
IP 14	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation
15.45	is not recommended.
IP 15 Current Condition:	Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation
Current Condition:	is not recommended.
IP 16	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation
Current Condition.	is not recommended.
IP 17	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation
Carront Condition:	is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the
	inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a
	basin, reinstallation is not recommended.
IP 18	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 5/11/20 inspection. Inlet drains to a basin, reinstallation
	is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 5/3/22 inspection. D.R. Horton cleaned out the
	inlet filter prior to the 7/12/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 8/23/22 inspection. D.R. Horton
	removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.
IP 19	Inlet Protection See SWPPP Removed
IP 19 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation
Current Condition: IP 20 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.
Current Condition: IP 20 Current Condition: IP 21	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed
Current Condition: IP 20 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation reinstallation.
Current Condition: IP 20 Current Condition: IP 21	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the
Current Condition: IP 20 Current Condition: IP 21	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a
Current Condition: IP 20 Current Condition: IP 21 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.
Current Condition: IP 20 Current Condition: IP 21	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.
Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed
Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.
Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Removed
Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 23	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.
Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 23	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed - Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.
Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 23 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 7/26/22 inspection.
Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 23	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton removed the
Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 23 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 7/26/22 inspection. Inlet Protection See SWPPP Removed Removed Removed Removed D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter protection Prior to the 7/26/22 inspection.
Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 23 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 7/26/22 inspection. Inlet Protection See SWPPP Removed Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. D.R. Horton removed the inlet filter prior to the 7/26/22 inspection.
Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 24 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. D.R. Horton removed the
Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 23 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection
IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 24 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection
Current Condition: IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 24 Current Condition: IP 25 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton removed the inlet filter
IP 20 Current Condition: IP 21 Current Condition: IP 22 Current Condition: IP 22 Current Condition: IP 23 Current Condition: IP 24 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 7/26/22 inspection. Inlet Protection See SWPPP Removed Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton reinstalled inlet filter prior to the 3/1/22 inspection. D.R. Horton reinstalled inlet filter prior to the 3/1/22 inspection. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet fi

Current Condition:		mended. D.R. Horton re prior to the 8/16/22 inpe	e inlet filter prior to the 4/27/20 installed inlet filter protection p ection.		
			2. Not done as of last inspection	on.	
IP 27	Inlet Protection	See SWPPP		Removed	
Current Condition:			et filter prior to the 4/27/20 insp		a basin, reinstallation
17.00	is not recommended.		1	· · · · · · · · · · · · · · · · · · ·	
IP 28 Current Condition:	Inlet Protection	See SWPPP	Let filter prior to the 4/27/20 insp	Removed	a basin, roinstallation
Current Condition:	is not recommended.	seeding removed the inte	et filter prior to trie 4/27/20 irisp	Dection. The drains to	a Dasiii, Teiristaliation
Lot 1 Replat 1	Individual Lot	Lot 1 Replat 1		Removed	
Current Condition:	Removed - D.R. Horton s		4/12/22 inspection.		
Lot 4 Replat 3 Current Condition:	Individual Lot Removed - D.R. Horton s	Lot 4 Replat 3	11/0/22 inspection	Removed	
Lot 6 Replat 1	Individual Lot	Lot 6 Replat 1	i 173/22 inspection.	Removed	
Current Condition:	Removed - D.R. Horton s		e 11/9/22 inspection.		
Lot 7 Replat 1	Individual Lot	Lot 7 Replat 1		Removed	
Current Condition: Lot 10 Replat 1	Removed - Carlson Tile II		o the 6/21/22 inspection.	Removed	
Current Condition:	Individual Lot Removed - D.R. Horton s	Lot 10 Replat 1 odded the lot prior to the	e 4/19/22 inspection.	Removed	
Lot 11 Replat 1	Individual Lot	Lot 11 Replat 1		Removed	
Current Condition:	Removed - D.R. Horton s	odded the lot prior to the	4/19/22 inspection.		
Lot 13 Replat 1	Individual Lot	Lot 13 Replat 1	4/40/00 :	Removed	
Current Condition: Lot 19 Replat 1	Removed - D.R. Horton s Individual Lot	Lot 19 Replat 1	4/19/22 inspection.	Removed	
Current Condition:	Removed - Brooks Builde		the 5/10/22 inspection.	Removed	
Lot 20 Replat 1	Individual Lot	Lot 20 Replat 1		Removed	
Current Condition:			r to the 8/23/22 inspection.	·	
Lot 22 Replat 1 Current Condition:	Individual Lot Removed - Urban Spark :	Lot 22 Replat 1	o F/17/22 increation	Removed	
Lot 23 Replat 1	Individual Lot	Lot 23 Replat 1	e 3/17/22 inspection.	Removed	
Current Condition:	Removed - D.R. Horton s		4/12/22 inspection.	1100104	
Lot 28 Replat 1	Individual Lot	Lot 28 Replat 1		Removed	
Current Condition:	Removed - D.R. Horton s		e 4/12/22 inspection.	B	
Lot 30 Replat 1 Current Condition:	Individual Lot Removed - D.R. Horton s	Lot 30 Replat 1	11/2/22 inspection	Removed	
Lot 33 Replat 1	Individual Lot	Lot 33 Replat 1	1 1/2/22 mopodion.	Removed	
Current Condition:	Removed - D.R. Horton s		5/17/22 inspection.		
Lot 34 Replat 1	Individual Lot	Lot 34 Replat 1	to the A/C/O4 incompetition	Removed	
Current Condition: Lot 43 Replat 1	Removed - Sundown Hor Individual Lot	Lot 43 Replat 1	to the 4/6/21 inspection.	Removed	
Current Condition:	Removed - D.R. Horton s		7/26/22 inspection.	rtomovou	
Lot 45 Replat 1	Individual Lot	Lot 20 Replat 1	6/14/2022	Pending	Yes
Current Condition:			of the lot prior to the 6/14/22 in e lot is relatively flat, no BMPs		
			the concrete waste on the lot		
		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	1.) Silt fence should be in				
	2.) Wattles should be inst	alled on the front of the	lot.		
	1.) Brooks Builders was in	nformed to complete by	7/19/22. Not done as of last in:	spection, Brooks Build	ders were reminded on
	11/3/22.			-,	
		nformed to complete by	7/19/22. Not done as of last in:	spection. Brooks Build	lers were reminded on
Let 46 Deplet 1	11/3/22. Individual Lot	Lat 46 Danlat 1		Domovad	
Lot 46 Replat 1 Current Condition:		Lot 46 Replat 1 Homes sodded the lot pr	rior to the 5/17/22 inspection.	Removed	
Lot 47 Replat 1	Individual Lot	Lot 47 Replat 1		Removed	
Current Condition:			o the 11/11/21 inspection.		
Lot 48 Replat 1	Individual Lot	Lot 48 Replat 1	10/25/22 inaparties	Removed	
Current Condition: Lot 49 Replat 1	Removed - D.R. Horton s Individual Lot	Lot 49 Replat 1	turzorzz irispection.	Removed	
Current Condition:	Removed - D.R. Horton s		e 10/11/22 inspection.	1 TOMOVOG	
Lot 51 Replat 1	Individual Lot	Lot 51 Replat 1		Removed	
Current Condition:	Removed - D.R. Horton s		e 10/11/22 inspection.	Domessed	
Lot 53 Replat 1 Current Condition:	Individual Lot Removed - Hubbell Home	Lot 53 Replat 1	the 7/29/21 inspection	Removed	
Lot 55 Replat 1	Individual Lot	Lot 55 Replat 1	5/11/2020	Active	Yes
-1					

Current Condition:	Fair Condition - Gene Graves installed silt fence on the side of the lot prior to the inspection on 5/11/20. Future silt fence maintenance will be sent to the builder of the lot when construction begins. Minor damage to the silt fence was observed during the 6/22/21 inspection, the inspector will monitor. Landmark Performance Corporation began excavation on the lot prior to the 8/23/22 inspection. Dirt piles were observed in the ROW during the 8/23/22 inspection. Landmark Performance Corporation removed the concrete waste and the dirt piles from the ROW prior to the 9/13/22 inspection. 1.) Silt fence perimeter should be installed. 2.) Wattles should be installed along the front of the lot. 1.) Landmark Performance Corporation was informed to complete by 8/30/22. Not done as of last inspection. Landmark Performance Corporation was informed to complete by 8/30/22. Not done as of last inspection. Landmark Performance Corporation was informed to complete by 8/30/22. Not done as of last inspection. Landmark	
	Performance Corporation was reminded on 11/3/22.	
Lot 57 Replat 1	Individual Lot Lot 57 Replat 1 Removed	
Current Condition:	Removed - Pacesetter Homes sodded the lot prior to the 7/12/22 inspection.	
Lot 58 Replat 1 Current Condition:	Individual Lot Lot 58 Replat 1 Removed	
Lot 59 Replat 1	Removed - Proline Homes sodded the lot prior to the 12/21/21 inspection. Individual Lot Lot 59 Replat 1 Removed	
Current Condition:	Removed - Nelson Builders sodded the lot prior to the 6/21/22 inspection.	
Lot 63 Replat 1	Individual Lot Lot 63 Replat 1 4/26/2022 Pending Yes	
Current Condition:	Pending - Urban Spark began excavation of the lot prior to the 4/26/22 inspection. Dirt pile was noticed in the ROW during	q
	Silt fence should be installed on the sides, rear, and southeast corner of the lot. Urban Spark was informed to complete by 5/3/22. Not done as of last inspection. Urban Spark was reminded on 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22	
Lot 67 Replat 1	Individual Lot Lot 67 Replat 1 Removed	
Current Condition:	Removed - Proline Homes sodded the lot prior to the 7/7/21 inspection.	
Lot 69 Replat 1	Individual Lot Lot 69 Replat 1 Removed	
Current Condition:	Removed - Fools Inc sodded the lot prior to the 7/10/21 inspection. Individual Lot Lot 70 Replat 1 Removed	
Lot 70 Replat 1 Current Condition:	Removed - Urban Spark sodded the lot prior to the 8/23/21 inspection.	
Lot 71 Replat 1	Individual Lot Lot 71 Replat 1 Removed	
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 8/16/22 inspection.	_
Lot 74 Replat 1	Individual Lot Lot 74 Replat 1 Removed	
Current Condition:	Removed - Sundown Homes sodded the lot prior to the 9/28/21 inspection.	
Lot 75 Replat 1	Individual Lot Lot 75 Replat 1 Removed	
Current Condition:	Removed - Jeck & Company sodded the lot prior to the 7/10/21 inspection.	
Lot 78 Replat 1	Individual Lot Lot 78 Replat 1 Removed	
Current Condition:	Removed - Sundown Homes sodded the lot prior to the 7/19/22 inspection.	
Lot 81 Replat 1	Individual Lot Lot 81 Replat 1 Removed	
Current Condition:	Removed - Nelson Builders sodded the lot prior to the 10/12/21 inspection.	
Lot 82 Replat 1 Current Condition:	Individual Lot Lot 82 Replat 1 4/19/2022 Active Yes Fair Condition - Urban Spark began excavation of the lot prior to the 4/19/22 inspection. Dirt pile was noticed in the ROW	
	during the 4/26/22 inspection. Urban Spark installed silt fence on the south side of the lot prior to the 4/26/22 inspection. Urban Spark removed the dirt pile from the ROW prior to the 5/17/22 inspection. Outflow pipe behind the lot should be cleaned out and uncovered. Urban Spark was informed to complete by 6/28/22. Not done as of last inspection. Urban Spark was reminded on 8/2/22, 11/3/22, 11/9/22	
Lot 84 Replat 1	Individual Lot Lot 84 Replat 1 Removed	
Current Condition:	Removed - Pacesetter Homes sodded the lot prior to the 5/10/21 inspection.	
Lot 90 Replat 1 Current Condition:	Individual Lot	-
Lot 95 Replat 1	Individual Lot Lot 95 Replat 1 Removed	
Current Condition:	Removed - Nelson Builders sodded the lot prior to the 5/3/21 inspection.	-
Lot 96 Replat 1	Individual Lot Lot 96 Replat 1 Removed	-
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 8/16/22 inspection.	
Lot 97 Replat 1	Individual Lot Lot 97 Replat 1 Removed	
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 12/7/22 inspection.	
Lot 98 Replat 1	Individual Lot Lot 98 Replat 1 Removed	
Current Condition:	Removed - McCaul Contracting sodded the lot prior to the 12/21/21 inspection.	
Lot 100 Replat 1	Individual Lot Lot 100 Replat 1 Removed	
Current Condition:	Removed - Woodland Homes sodded the lot prior to the 1/4/22 inspection.	
Lot 101 Replat 1	Individual Lot Lot 101 Replat 1 10/25/2021 Active Yes	

Current Condition:	in the ROW during the 10 installed silt fence at the re Spark removed the dirt pil. 1.) Silt fence should be re 2.) Wattles should be inst 3.) Silt fence should be old 4.) Silt fence should be inst 5.) Sediment that has was 1.) Urban Spark was infor 1/5/22, 3/8/22, 4/27/22, 5/2.) Urban Spark was infor 1/5/22, 3/8/22, 4/27/22, 5/3.) Urban Spark was infor 4/27/22, 5/6/22, 6/23/22, 8.) Urban Spark was infor 4/27/22, 5/6/22, 6/23/22, 8.	/25/21 inspection, the inear of the lot prior to the les from the ROW prior of paired/reinstalled at the alled on the front of the leaned out and sediment stalled on the sides of the shed on to adjoining lots med to complete by 12/16/22, 6/23/22, 8/2/22, 11/26/22, 6/23/22, 8/2/22, 11/2/22, 11/2/22, 11/3/22,	rear of the lot. lot. that has fallen past the prope e lot. should be cleaned up. 14/21. Not done as of the last 1/3/22, 11/9/22 14/21. Not done as of the last 1/3/22, 11/9/22 2/22. Not done as of last inspec	al and the installation oce recommendations of the recommendation of the recommend	of BMPs. Urban Spark have changed. Urban buld be cleaned up. ark was reminded on ark was reminded on as reminded on 3/8/22, as reminded on
	5.) Urban Spark was infor 4/27/22, 5/6/22, 6/23/22, 8		2/22. Not done as of last inspe	ection. Orban Spark w	as reminded on
Lot 105 Replat 1	4/27/22, 5/6/22, 6/23/22, 8	Lot 105 Replat 1		Removed	
Current Condition:	Removed - D.R. Horton s		± 11/2/22 inspection.	Nemoved	
Lot 110 Replat 1	Individual Lot	Lot 110 Replat 1	,opoonorn	Removed	
Current Condition:	Removed - Fools Inc sodo	ded the lot prior to the 1	1/11/21 inspection.		
Lot 112 Replat 1	Individual Lot	Lot 112 Replat 1		Removed	
Current Condition:			prior to the 4/12/22 inspection.		
Lot 116 Replat 1	Individual Lot Removed - D.R. Horton se	Lot 116 Replat 1	11/2/22 inspection	Removed	
Current Condition: Lot 119 Replat 1	Individual Lot	Lot 119 Replat 1	7/19/2022	Active	No
Current Condition:			ing the front of the lot prior to		
	inactive.		9		,
Lot 120 Replat 1	Individual Lot	Lot 120 Replat 1	3/1/2022	Active	Yes
Current Condition:			attles prior to the 3/1/22 inspe		
	Silt fence should be remo		Not done as of last inspection	ı. D.R. Horton was ren	ninded on 11/11/22.
Lot 126 Replat 1	Individual Lot	Lot 127 Replat 1	11/23/2021	Active	No
Current Condition:	D.R. Horton resecured the prior to the 11/16/22 inspec	e portable toilet prior to t	on Lot 126 prior to the 11/23, he 3/29/22 inspection. D.R. H	orton removed the po	
Lot 127 Replat 1 Current Condition:	Individual Lot Removed - D.R. Horton se		10/25/22 inspection	Removed	
Lot 128 Replat 1	Individual Lot	Lot 128 Replat 1	10/20/22 Hopection.	Removed	
Current Condition:	Removed - D.R. Horton se		10/25/22 inspection.		
SB 1	Sediment Basin	See SWPPP	1/3/2020	Active	No
Current Condition:			ed prior to the 1/3/20 inspection plate prior to the 4/27/20 insp	•	
SB 2	Sediment Basin	See SWPPP	1/3/2020	Active	No
Current Condition:	Good Condition - 1% filled Seeding plugged the botto	- The basin was installed om 2 rows of holes in the	ed prior to the 1/3/20 inspection orifice plate prior to the 4/27 cleaned out the basin prior to	on with a permanent ri /20 inspection. Hasum	ser. Commercial an began cleaning out
SB 3	Sediment Basin	See SWPPP	1/3/2020	Active	No
Current Condition:			ed prior to the 1/3/20 inspection plate prior to the 4/27/20 insp	•	
SB 4	Sediment Basin	See SWPPP	1/3/2020	Active	No
Current Condition:	Seeding plugged the lowe seeded and matted the er 5/11/20. All future recomprior to the 10/11/22 inspe	est dewatering hole and losion at the inlet pipe armendation of maintenantection. E&A inspector with	lled prior to the 1/3/20 inspect packfilled the erosion prior to ad installed a straw wattle at the ce for the wattle will be includ il monitor for installation of pe	the 4/27/20 inspection he stub road prior to the ed with SB 4. Riser in manent riser.	. Commercial seeding ne inspection on
SF 1	Silt fence	See SWPPP	fance prior to the 4/07/00 '	Removed	
Current Condition: SF 2	Removed - Commercial S Silt fence	See SWPPP	fence prior to the 4/27/20 insp	Removed	
Current Condition:	Removed - Wattles were recommendations.	removed for home cons	truction prior to the 10/26/21 i	nspection. See Lot Bl	MPs for further
SF 3	Silt fence	See SWPPP	for author years (m. 2011)	Removed	
Current Condition:	kemoved - Silt fence was	removed in preparation	for active construction prior to	une 5/18/20 inspection	л.

SF 4	Silt fence	Springfield Trail		Removed			
Current Condition:	Removed - The remaining	emoved - The remaining wattles have been mulched or removed as of the 4/9/21 inspection.					
W1	Straw Wattle	SB 4 Stub Road		Removed			
Current Condition:	Removed - Tim Geis cleaned the street and removed the wattle prior to the 7/15/20 inspection, reinstallation is not						
	necessary.						
		Internal/S 132nd and					
STR	Streets	Main Street	1/3/2020	Active	No		
Current Condition:	Good Condition - Streets	were clean and free of tr	ack out during the 11/9/22 i	nspection.			
		S 132nd Street and					
SWPPP Signs	Misc/Other	Man Street	1/27/2020	Active	No		
Current Condition:	Good Condition - E&A inspector installed SWPPP signs at the intersection of Main Street and N 10th Ave and S 132nd						
	Street and Hazel Lane du	ring the 1/27/20 inspection	on.				
Certification Statement:	"I certify, under penalty of	law, that this document	and all attachments were p	repared under my			
	direction or supervision in accordance with a system designed to assure that qualified personnel						
	properly gathered and evaluated the information submitted. Based on my inquiry of the person or						
	persons who manage the system or those persons directly responsible for gathering the information,						
	the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I						
	am aware that there are significant penalties for submitting false information including the possibility						
	of fines and imprisonment	t for knowing violations."					
	_						
	Sm Msg m			6	25 SM		
nspector Signature:	-	1		Reviewed By:			