E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

Environmental Services De	pt. Manager			gcc	y minoritario
	1	E&A - P20	19.327.000		
Inspector: Shaun McGuire					Stage
		Spring	gfield Pines		1
Project Name:		CSW-	201600337		
For Week Ending:		1/	14/2023		68059
Project Location:	SW o	d, NE			
	Phase I				
Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%				
Seeding:	75%				
Utilities:	100%				
Overall Development:	70%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"				
Wednesday:	0.00"	1/11/2023	Overcast 37/25	12:40 PM	
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
Complaints:	None				
Construction Sequencing:					

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading in Phase I was completed prior to E&A being hired to conduct SWPPP inspections (1/3/20).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading in Phase I was completed prior to E&A being hired to conduct SWPPP inspections (1/3/20).

What temporary or permanent stabilization measures listed in this section are being implemented?

Site was seeded prior to E&A being hired to conduct SWPPP inspections (1/3/20). Portion of ground to the southeast of SB 4 seeded and matted (5/11/20).

## **Checklist Questions:**

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

No

Create Corrective Action?

No, see Findings section.

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

Create Corrective Action?

No, see BMPs section and Findings section.

Are construction entrances and adjacent streets being maintained adequately?

Yes

Create Corrective Action?

N/A

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

## Comments

Comments: Site was active for homebuilding during the most recent inspection.

The School Site was graded prior to the 9/23/20 inspection. The School Site is not covered by the Springfield Pines permit (SPR-20200728-5543-GP1).

## Findings / Corrective Actions (Date):

## Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section of this report.
- 2) Vacant-disturbed lots need to be stabilized.
- A. Overgraded lots during homebuilding construction need to be stabilized. All builders were informed to complete by 1/17/20 when weather allows and asneeded. Not done as of the last inspection. All builders were reminded on 9/24/20, 6/24/21.
- 3) Concrete waste was located throughout the development. D.R. Horton was informed to clean up concrete waste in SB 4 on 3/3/22. Not done as of last inspection. D.R. Horton was reminded on 3/24/22, 5/24/22, 6/2/22, 6/17/22, 6/23/22, 8/19/22, 8/31/22, 11/11/22. D.R. Horton was informed to clean up concrete waste on lot 72 on 8/31/22. Not done as of last inspection. D.R. Horton was reminded on 11/11/22.

	<del>-</del>			1 6	1
Unique Name	Type	Location	Projected Install Date	Status	Maintenance
Al 1	Area Inlet Protection	See SWPPP	1/3/2020 inspection. The surrounding	Active	No the inlet drains to SP
Current Condition:	1; no inlet protection will b	•		area is vegetated and	Title fillet dialits to SB
Al 2	Area Inlet Protection	See SWPPP	1/3/2020	Active	No
Current Condition:			installed prior to the 1/3/20 ins		
			rotection will be recommended		
		·	man installed 3 additional inlet: nlet protection prior to the 11/9	·	ection prior to the
Al 3	Area Inlet Protection	See SWPPP	3/9/2020	Active	No
Current Condition:			prior to the 3/9/20 inspections.		
	silt fence/T-posts around			_	
Al 4	Area Inlet Protection	See SWPPP	3/9/2020	Active	No
Current Condition:	Active - Area inlet with do	me grate was installed p	prior to the 3/9/20 inspection.	The surrounding area	was seeded and
	matted and the inlet drains	s to SB 2; no inlet prote	ction will be recommended at	this time.	
CW 1	Concrete Washout	Lot 81 Replat 1		Removed	
Current Condition:	Removed - A lot level con	crete washout was insta	alled on Lot 81 Replat 1 prior to	o the 1/3/20 inspection	n. Gene Graves
	cleaned out the concrete	washout prior to the insp	pection on 5/11/20, the berm re	ecommendation is no	longer needed. Gene
		• • •	oach prior to the 6/1/20 inspec		
	· ·	•	aves relocated the concrete wa		
			he concrete washout prior to t	•	
		•	tion, the E&A inspector will me		
		•	inspection. Mobile washout wrete washout on to lot 117 price	-	•
	•		/22 inspection. D.R. Horton re	•	
	10/11/22 inspection, the E			moved the concrete w	ashout phor to the
ID 4	•	See SWPPP	T	Damariad	I
IP 1 Current Condition:	Inlet Protection		Let filter prior to the 4/27/20 insp	Removed	a hasin reinstallation
Current Condition.	is not recommended.	eeding removed the line	et litter prior to the 4/2//20 map	bection. The drains to	a basiii, reilistallation
IP 2	Inlet Protection	See SWPPP		Removed	
Current Condition:	Removed - Commercial S	eeding removed the inle	et filter prior to the 4/27/20 insp	pection. Inlet drains to	a basin, reinstallation
	is not recommended. D.R.	. Horton reinstalled the i	inlet filter prior to the 6/21/22 in	nspection. D.R. Horton	n removed the inlet filter
	prior to the 12/21/22 inspe	ection. Inlet drains to a b	easin, reinstallation is not reco	mmended.	
IP 3	Inlet Protection	See SWPPP		Removed	
Current Condition:	Removed - Commercial S	eeding removed the inle	et filter prior to the 4/27/20 insp	pection. Inlet drains to	a basin, reinstallation
	is not recommended.				
IP 4	Inlet Protection	See SWPPP		Removed	
Current Condition:			et filter prior to the 4/27/20 ins		
			filter protection prior to the 5/3		Horton removed the
	inlet filter prior to the 12/2	1/22 inspection. Inlet dra	ains to a basin, reinstallation is	s not recommended.	
IP 5	Inlet Protection	See SWPPP		Removed	
Current Condition:		•	et filter prior to the 4/27/20 insp		
			filter protection prior to the 5/3	•	Horton removed the
	·		ains to a basin, reinstallation is		T
IP 6	Inlet Protection	See SWPPP		Removed	- basis asis tallada
Current Condition:		•	et filter prior to the 4/27/20 insp		
			filter protection prior to the 8/3	•	Horton removed the
ID 7	· · · · · · · · · · · · · · · · · · ·		ains to a basin, reinstallation is	•	I
IP 7 Current Condition:	Inlet Protection	See SWPPP	l et filter prior to the 4/27/20 insp	Removed	a hasin reinstallation
Current Condition:	is not recommended.	ceaning removed the IME	5. mei phoi to the 4/2//20 INS	Jeonon, mieruranis (	a vasiii, itiiistallatiUN
IP 8	Inlet Protection	See SWPPP		Removed	T
Current Condition:			I et filter prior to the 4/27/20 insp		a hasin reinstallation
Our on Sonation.		•	filter protection prior to the 8/3		
			ains to a basin, reinstallation is	•	
IP 9	•	See SWPPP		1	I
17 9	Inlet Protection	366 34144	l	Removed	

Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.
ID 40	
IP 10	Inlet Protection   See SWPPP   Removed   Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is
Current Condition:	not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton cleaned out the
	inlet filter prior to the 6/7/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton
	removed the inlet filter prior to the 12/21/22 inspection. D.N. Horton remarkative the machiner filter prior to the 12/21/22 inspection. B.N. Horton remarkative the machiner filter prior to the 12/21/22 inspection. B.N. Horton remarkative the machiner filter prior to the 0/1/22 inspection. B.N. Horton remarkative the machiner filter prior to the 0/1/22 inspection.
	removed the filler prior to the 12/27/22 inspection. Thet drains to a basin, removalization is not recommended.
IP 11	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is
	not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton repaired the inlet
	filter prior to the 4/5/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 6/28/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.
	removed the filler filler prior to the 12/21/22 inspection. Thet drains to a basin, reinstallation is not recommended.
IP 12	Jalet Destantion Con CM/DDD
Current Condition:	Inlet Protection See SWPPP Removed  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation
Current Condition:	is not recommended.
ID 40	
IP 13	Inlet Protection See SWPPP Removed  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation
Current Condition:	is not recommended.
15.11	
IP 14	Inlet Protection   See SWPPP   Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation
15.45	is not recommended.
IP 15 Current Condition:	Inlet Protection See SWPPP Removed  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation
Current Condition:	is not recommended.
IP 16	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation
Current Condition.	is not recommended.
IP 17	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation
Carront Condition:	is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the
	inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a
	basin, reinstallation is not recommended.
IP 18	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 5/11/20 inspection. Inlet drains to a basin, reinstallation
	is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 5/3/22 inspection. D.R. Horton cleaned out the
	inlet filter prior to the 7/12/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 8/23/22 inspection. D.R. Horton
	removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.
IP 19	Inlet Protection See SWPPP Removed
IP 19 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation
Current Condition:  IP 20  Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.
Current Condition:  IP 20 Current Condition:  IP 21	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed  Removed
Current Condition:  IP 20  Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation reinstallation.
Current Condition:  IP 20 Current Condition:  IP 21	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the
Current Condition:  IP 20 Current Condition:  IP 21	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a
Current Condition:  IP 20 Current Condition:  IP 21 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.
Current Condition:  IP 20 Current Condition:  IP 21	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.
Current Condition:  IP 20 Current Condition:  IP 21 Current Condition:  IP 22	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed
Current Condition:  IP 20 Current Condition:  IP 21 Current Condition:  IP 22 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.
Current Condition:  IP 20 Current Condition:  IP 21 Current Condition:  IP 22	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed  Removed - Removed
Current Condition:  IP 20 Current Condition:  IP 21 Current Condition:  IP 22 Current Condition:  IP 23	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.
Current Condition:  IP 20 Current Condition:  IP 21 Current Condition:  IP 22 Current Condition:  IP 23	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed - Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.
Current Condition:  IP 20 Current Condition:  IP 21 Current Condition:  IP 22 Current Condition:  IP 23 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 7/26/22 inspection.
Current Condition:  IP 20 Current Condition:  IP 21 Current Condition:  IP 22 Current Condition:  IP 23	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton removed the
Current Condition:  IP 20 Current Condition:  IP 21 Current Condition:  IP 22 Current Condition:  IP 23 Current Condition:  IP 23 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 7/26/22 inspection.  Inlet Protection See SWPPP Removed Removed Removed Removed D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter protection Prior to the 7/26/22 inspection.
Current Condition:  IP 20 Current Condition:  IP 21 Current Condition:  IP 22 Current Condition:  IP 23 Current Condition:  IP 23 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 7/26/22 inspection.  Inlet Protection See SWPPP Removed Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. D.R. Horton removed the inlet filter prior to the 7/26/22 inspection.
Current Condition:  IP 20 Current Condition:  IP 21 Current Condition:  IP 22 Current Condition:  IP 23 Current Condition:  IP 24 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. D.R. Horton removed the
Current Condition:  IP 20 Current Condition:  IP 21 Current Condition:  IP 22 Current Condition:  IP 23 Current Condition:  IP 23 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.    Inlet Protection
IP 20 Current Condition:  IP 21 Current Condition:  IP 22 Current Condition:  IP 22 Current Condition:  IP 23 Current Condition:  IP 24 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.    Inlet Protection
Current Condition:  IP 20 Current Condition:  IP 21 Current Condition:  IP 22 Current Condition:  IP 23 Current Condition:  IP 24 Current Condition:  IP 25 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection  See SWPPP  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection  See SWPPP  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection  See SWPPP  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection  See SWPPP  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton removed the inlet filter
IP 20 Current Condition:  IP 21 Current Condition:  IP 22 Current Condition:  IP 22 Current Condition:  IP 23 Current Condition:  IP 24 Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.  Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 7/26/22 inspection.  Inlet Protection See SWPPP Removed Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton reinstalled inlet filter prior to the 3/1/22 inspection. D.R. Horton reinstalled inlet filter prior to the 3/1/22 inspection. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet fi

Current Condition:		mended. D.R. Horton re prior to the 8/16/22 inpe	e inlet filter prior to the 4/27/20 installed inlet filter protection p ction.		
	D.R. Horton was informed	I to complete by 11/16/2	2. Not done as of last inspecti	on.	
IP 27	Inlet Protection	See SWPPP	<u>.</u>	Removed	
Current Condition:			et filter prior to the 4/27/20 insp		a basin_reinstallation
Gurrom Gorianion.	is not recommended.	ooung romorou are and	xe. pe. te te ./2//20ep		a saom, romotanamor.
IP 28	Inlet Protection	See SWPPP		Removed	
Current Condition:	Removed - Commercial S	eeding removed the inle	et filter prior to the 4/27/20 insp	ection. Inlet drains to	a basin, reinstallation
	is not recommended.				
Lot 1 Replat 1	Individual Lot	Lot 1 Replat 1		Removed	
Current Condition:	Removed - D.R. Horton se		4/12/22 inspection.		
Lot 4 Replat 3	Individual Lot	Lot 4 Replat 3		Removed	
Current Condition:	Removed - D.R. Horton se		11/9/22 inspection.		
Lot 6 Replat 1	Individual Lot	Lot 6 Replat 1		Removed	
Current Condition:	Removed - D.R. Horton se		e 11/9/22 inspection.		
Lot 7 Replat 1	Individual Lot	Lot 7 Replat 1		Removed	
Current Condition:	Removed - Carlson Tile Ir		o the 6/21/22 inspection.	Damariad	
Lot 10 Replat 1 Current Condition:	Individual Lot Removed - D.R. Horton se	Lot 10 Replat 1	1/19/22 inspection	Removed	
Lot 11 Replat 1	Individual Lot	Lot 11 Replat 1	l 19/22 Irispection.	Removed	
Current Condition:	Removed - D.R. Horton so		1/10/22 inspection	Removed	
Lot 13 Replat 1	Individual Lot	Lot 13 Replat 1	19/22 Inspection:	Removed	
Current Condition:	Removed - D.R. Horton so		4/19/22 inspection	removed	
Lot 19 Replat 1	Individual Lot	Lot 19 Replat 1	, 1, 10,22 mapadiam.	Removed	
Current Condition:	Removed - Brooks Builde		the 5/10/22 inspection.	1101110100	
Lot 20 Replat 1	Individual Lot	Lot 20 Replat 1		Removed	
Current Condition:			r to the 8/23/22 inspection.		
Lot 22 Replat 1	Individual Lot	Lot 22 Replat 1		Removed	
Current Condition:	Removed - Urban Spark s	sodded the lot prior to th	e 5/17/22 inspection.		
Lot 23 Replat 1	Individual Lot	Lot 23 Replat 1		Removed	
Current Condition:	Removed - D.R. Horton se		4/12/22 inspection.		
Lot 28 Replat 1	Individual Lot	Lot 28 Replat 1		Removed	
Current Condition:	Removed - D.R. Horton se		4/12/22 inspection.		
Lot 30 Replat 1	Individual Lot	Lot 30 Replat 1		Removed	
Current Condition:	Removed - D.R. Horton se		e 11/2/22 inspection.		
Lot 33 Replat 1	Individual Lot	Lot 33 Replat 1	F/47/00:	Removed	
Current Condition: Lot 43 Replat 1	Removed - D.R. Horton so		5/17/22 Inspection.	Removed	
Current Condition:	Individual Lot Removed - D.R. Horton se	Lot 43 Replat 1	7/26/22 increation	Removed	
Lot 45 Replat 1	Individual Lot	Lot 20 Replat 1	6/14/2022	Pending	Yes
Current Condition:			of the lot prior to the 6/14/22 in		
	ROW, Ē&A inspector will Builders removed the dirt  1.) Silt fence should be inst. 2.) Wattles should be inst.  1.) Brooks Builders was ir 11/3/22. 2.) Brooks Builders was ir	monitor for removal. The pile from the ROW and stalled on the east side alled on the front of the aftermed to complete by a	e lot is relatively flat, no BMPs the concrete waste on the lot and rear of the lot.	are recommended at prior to the 7/26/22 ins	this time. Brooks spection.
	11/3/22.				
Lot 46 Replat 1	Individual Lot	Lot 46 Replat 1	in to the 5/47/00 in a col	Removed	
Current Condition:			fior to the 5/17/22 inspection.	Domessed	
Lot 48 Replat 1 Current Condition:	Individual Lot	Lot 48 Replat 1	10/25/22 increation	Removed	
Lot 49 Replat 1	Removed - D.R. Horton se Individual Lot	Lot 49 Replat 1	: 10/25/22 INSPECTION.	Domoved	
Current Condition:	Removed - D.R. Horton se		10/11/22 inspection	Removed	
Lot 51 Replat 1	Individual Lot	Lot 51 Replat 1	, 10, 11,22 mapeonom.	Removed	
Current Condition:	Removed - D.R. Horton so		10/11/22 inspection	Romoveu	
Lot 55 Replat 1	Individual Lot	Lot 55 Replat 1	5/11/2020	Active	Yes
	a.r.addi Eot		5,, 2020		. 30

Lot 57 Replat 1 Current Condition: Lot 59 Replat 1 Current Condition: Lot 63 Replat 1 Current Condition:	maintenance will be sent to during the 6/22/21 inspect prior to the 8/23/22 inspect Corporation removed the 1.) Silt fence perimeter sh 2.) Wattles should be instantial to the should be	to the builder of the lot was tion, the inspector will motion. Dirt piles were obsconcrete waste and the could be installed.  alled along the front of the ecorporation was information was reminded on 11/3/2 to 57 Replat 1 to 59 Rep	med to complete by 8/30/22. No. 22. med to complete by 8/30/22. No. 22. med to complete by 8/30/22. No. 22. med to the 7/12/22 inspection. med to the 6/21/22 inspection. Med 4/26/2022 of prior to the 4/26/22 inspection.	or damage to the silt of Corporation began 8/23/22 inspection. Let to the 9/13/22 inspection began 8/23/22 inspection beg	fence was observed excavation on the lot andmark Performance tion.  spection. Landmark spection. Landmark  Yes ed in the ROW during
	Silt fence should be instal Urban Spark was informed 6/23/22, 8/2/22, 11/3/22,	led on the sides, rear, a d to complete by 5/3/22. 11/9/22	dirt pile from the ROW prior to nd southeast corner of the lot. Not done as of last inspection	n. Urban Spark was r	
Lot 71 Replat 1 Current Condition:	Individual Lot Removed - D.R. Horton se	Lot 71 Replat 1	9/16/22 inconcition	Removed	1
Lot 78 Replat 1	Individual Lot	Lot 78 Replat 1	or rorzz inspection.	Removed	
Current Condition:	Removed - Sundown Hon		to the 7/19/22 inspection.	rtomovou	
Lot 82 Replat 1	Individual Lot	Lot 82 Replat 1	4/19/2022	Active	Yes
Current Condition:			the lot prior to the 4/19/22 insections that the thick the south side		
	Outflow pipe behind the lo Urban Spark was informed 11/3/22, 11/9/22		and uncovered.  2. Not done as of last inspection	on. Urban Spark was	reminded on 8/2/22,
L 400 D L 44	-	1 100 5 111		-	
Lot 90 Replat 1	Individual Lot	Lot 90 Replat 1	11/0/22 inapaction	Removed	
Current Condition:	Individual Lot Removed - D.R. Horton so	odded the lot prior to the	a 11/9/22 inspection.		I
	Individual Lot Removed - D.R. Horton so Individual Lot	odded the lot prior to the Lot 96 Replat 1	·	Removed Removed	
Current Condition: Lot 96 Replat 1 Current Condition: Lot 97 Replat 1	Individual Lot Removed - D.R. Horton so Individual Lot Removed - D.R. Horton so Individual Lot	odded the lot prior to the Lot 96 Replat 1 odded the lot prior to the Lot 97 Replat 1	e 8/16/22 inspection.		
Current Condition: Lot 96 Replat 1 Current Condition: Lot 97 Replat 1 Current Condition:	Individual Lot Removed - D.R. Horton so Individual Lot Removed - D.R. Horton so Individual Lot Removed - D.R. Horton so	odded the lot prior to the Lot 96 Replat 1 odded the lot prior to the Lot 97 Replat 1 odded the lot prior to the	e 8/16/22 inspection.	Removed Removed	
Current Condition: Lot 96 Replat 1 Current Condition: Lot 97 Replat 1 Current Condition: Lot 100 Replat 1	Individual Lot Removed - D.R. Horton so Individual Lot Removed - D.R. Horton so Individual Lot Removed - D.R. Horton so Individual Lot Individual Lot	odded the lot prior to the Lot 96 Replat 1 odded the lot prior to the Lot 97 Replat 1 odded the lot prior to the Lot 100 Replat 1	2 8/16/22 inspection. 2 12/7/22 inspection.	Removed	
Current Condition: Lot 96 Replat 1 Current Condition: Lot 97 Replat 1 Current Condition: Lot 100 Replat 1 Current Condition:	Individual Lot Removed - D.R. Horton so Individual Lot Removed - D.R. Horton so Individual Lot Removed - D.R. Horton so	odded the lot prior to the Lot 96 Replat 1 odded the lot prior to the Lot 97 Replat 1 odded the lot prior to the Lot 100 Replat 1 mes sodded the lot prior	2 8/16/22 inspection. 2 12/7/22 inspection.	Removed Removed	Yes
Current Condition: Lot 96 Replat 1 Current Condition: Lot 97 Replat 1 Current Condition: Lot 100 Replat 1	Individual Lot Removed - D.R. Horton so Individual Lot Removed - D.R. Horton so Individual Lot Removed - D.R. Horton so Individual Lot Removed - Woodland Hoo Individual Lot	odded the lot prior to the Lot 96 Replat 1 odded the lot prior to the Lot 97 Replat 1 odded the lot prior to the Lot 100 Replat 1 mes sodded the lot prior Lot 101 Replat 1	e 8/16/22 inspection. e 12/7/22 inspection. to the 1/4/22 inspection.	Removed Removed Removed Active	
Current Condition: Lot 96 Replat 1 Current Condition: Lot 97 Replat 1 Current Condition: Lot 100 Replat 1 Current Condition: Lot 101 Replat 1 Current Condition:	Individual Lot Removed - D.R. Horton so Individual Lot Removed - Woodland Hoo Individual Lot Fair Condition - Unidentific in the ROW during the 10 installed silt fence at the ro Spark removed the dirt pil  1.) Silt fence should be re 2.) Wattles should be inst 3.) Silt fence should be inst 3.) Silt fence should be inst 5.) Sediment that has was  1.) Urban Spark was infor 1/5/22, 3/8/22, 4/27/22, 5/ 2.) Urban Spark was infor 4/27/22, 5/6/22, 6/23/22, 8/ 4.) Urban Spark was infor 4/27/22, 5/6/22, 6/23/22, 8/ 5.) Urban Spark was infor 4/27/22, 5/6/22, 6/23/22, 8/ 5.) Urban Spark was infor 4/27/22, 5/6/22, 6/23/22, 8/ 5.) Urban Spark was infor 4/27/22, 5/6/22, 6/23/22, 8/ 5.) Urban Spark was infor 4/27/22, 5/6/22, 6/23/22, 8/ 5.) Urban Spark was infor 4/27/22, 5/6/22, 6/23/22, 8/ 5.) Urban Spark was infor 4/27/22, 5/6/22, 6/23/22, 8/ 5.) Urban Spark was infor 4/27/22, 5/6/22, 6/23/22, 8/	odded the lot prior to the Lot 96 Replat 1 odded the lot prior to the Lot 97 Replat 1 odded the lot prior to the Lot 97 Replat 1 deded the lot prior to the Lot 100 Replat 1 mes sodded the lot prior Lot 101 Replat 1 ed builder began constru/25/21 inspection, the in ear of the lot prior to the les from the ROW prior to paired/reinstalled at the alled on the front of the eaned out and sediment stalled on the sides of the shed on to adjoining lots med to complete by 12/ 6/22, 6/23/22, 8/2/22, 1 med to complete by 12/ 6/22, 11/3/22, 11/9/22 med to complete by 3/1: 8/2/22, 11/3/22, 11/9/22	e 8/16/22 inspection.  a 12/7/22 inspection.  a 12/7/22 inspection.  10/25/2021  Juction on the lot prior to the 10  spector will monitor for remove 1/4/22 inspection.  Maintenant to the 2/15/22 inspection.  Trear of the lot.  Juction on the lot prior to the 10  spector will monitor for remove 1/4/22 inspection.  Trear of the lot.  Juction on the lot prior to the 10  spector will monitor for remove 1/4/22 inspection.  Trear of the lot.  Juction on the lot prior to the 10  spector will monitor for remove 1/4/22 inspection.  Trear of the lot.  July 1/2/2 inspection.  14/21. Not done as of the last 1/3/22, 11/9/22  14/21. Not done as of the last 1/3/22, 11/9/22	Removed  Removed  Removed  Active  J/25/21 inspection. Dal and the installation ce recommendations  rty line to the east ship inspection. Urban Spinspection. Urban Spark vection.	or pitt piles were observed of BMPs. Urban Spark have changed. Urban ould be cleaned up.  ould be cleaned up.  our was reminded on a sark
Current Condition: Lot 96 Replat 1 Current Condition: Lot 97 Replat 1 Current Condition: Lot 100 Replat 1 Current Condition: Lot 101 Replat 1 Current Condition: Lot 101 Replat 1 Current Condition:	Individual Lot Removed - D.R. Horton so Individual Lot Removed - Woodland Hoo Individual Lot Fair Condition - Unidentific in the ROW during the 10 installed silt fence at the re Spark removed the dirt pil  1.) Silt fence should be re 2.) Wattles should be inst 3.) Silt fence should be inst 3.) Urban Spark was infor 1/5/22, 3/8/22, 4/27/22, 5/ 2.) Urban Spark was infor 4/27/22, 5/6/22, 6/23/22, 8/ 4.) Urban Spark was infor 4/27/22, 5/6/22, 6/23/22, 8/ 5.) Urban Spark was infor 4/27/22, 5/6/22, 6/23/22, 8/ Individual Lot	odded the lot prior to the Lot 96 Replat 1 odded the lot prior to the Lot 97 Replat 1 odded the lot prior to the Lot 97 Replat 1 odded the lot prior to the Lot 90 Replat 1 mes sodded the lot prior Lot 100 Replat 1 mes sodded the lot prior Lot 101 Replat 1 ed builder began constr //25/21 inspection, the in ear of the lot prior to the les from the ROW prior to paired/reinstalled at the alled on the front of the eaned out and sediment stalled on the sides of the shed on to adjoining lots med to complete by 12/ /6/22, 6/23/22, 8/2/22, 1 med to complete by 2/2: /8/2/22, 11/3/22, 11/9/22 med to complete by 3/1: /8/2/22, 11/3/22, 11/9/22 med to complete by 3/1: /8/2/22, 11/3/22, 11/9/22 med to complete by 3/1: /8/2/22, 11/3/22, 11/9/22 Lot 105 Replat 1	2 8/16/22 inspection. 2 12/7/22 inspection. 2 12/7/22 inspection. 2 10/25/2021 3 10	Removed  Removed  Removed  Active 0/25/21 inspection. Dal and the installation ce recommendations  rty line to the east ship inspection. Urban Spection. Urban Spection. Urban Spark vection.	or pitt piles were observed of BMPs. Urban Spark have changed. Urban ould be cleaned up.  ould be cleaned up.  our was reminded on a sark
Current Condition: Lot 96 Replat 1 Current Condition: Lot 97 Replat 1 Current Condition: Lot 100 Replat 1 Current Condition: Lot 101 Replat 1 Current Condition: Lot 105 Replat 1 Current Condition:	Individual Lot Removed - D.R. Horton so Individual Lot Removed - Woodland Hoo Individual Lot Fair Condition - Unidentificin the ROW during the 10 Installed silt fence at the re Spark removed the dirt pil  1.) Silt fence should be re 2.) Wattles should be inst 3.) Silt fence should be inst 3.) Urban Spark was infor 1/5/22, 3/8/22, 4/27/22, 5/ 2.) Urban Spark was infor 1/5/22, 3/8/22, 4/27/22, 5/ 3.) Urban Spark was infor 4/27/22, 5/6/22, 6/23/22, 8/ 5.) Urban Spark was infor 4/27/22, 5/6/22, 6/23/22, 8/ Individual Lot Removed - D.R. Horton se	odded the lot prior to the Lot 96 Replat 1 odded the lot prior to the Lot 97 Replat 1 odded the lot prior to the Lot 97 Replat 1 odded the lot prior to the Lot 100 Replat 1 mes sodded the lot prior Lot 101 Replat 1 ed builder began constructor of the lot prior to the les from the ROW prior to the les from the ROW prior of the lot prior to the les from the ROW prior of the lot prior to the les from the sides of the les from the sid	2 8/16/22 inspection. 2 12/7/22 inspection. 2 12/7/22 inspection. 2 10/25/2021 3 10	Removed  Removed  Removed  Active  0/25/21 inspection. Dal and the installation ce recommendations  rty line to the east shipspection. Urban Spection. Urban Spark vection.	or pitt piles were observed of BMPs. Urban Spark have changed. Urban ould be cleaned up.  ould be cleaned up.  our was reminded on a sark
Current Condition: Lot 96 Replat 1 Current Condition: Lot 97 Replat 1 Current Condition: Lot 100 Replat 1 Current Condition: Lot 101 Replat 1 Current Condition: Lot 105 Replat 1 Current Condition: Lot 105 Replat 1 Current Condition:	Individual Lot Removed - D.R. Horton so Individual Lot Removed - Woodland Hoo Individual Lot Fair Condition - Unidentific in the ROW during the 10 installed silt fence at the respect of the solution	odded the lot prior to the Lot 96 Replat 1 odded the lot prior to the Lot 97 Replat 1 odded the lot prior to the Lot 97 Replat 1 odded the lot prior to the Lot 100 Replat 1 mes sodded the lot prior Lot 101 Replat 1 ed builder began constructure /25/21 inspection, the interprior to the lot prior to the less from the ROW prior paired/reinstalled at the alled on the front of the less from the sides of the lot prior to the less from the lot prior to the lot prior to the less from the ROW prior paired/reinstalled at the late on the sides of the lot prior to the lot prior to the lot prior to the lot prior lot	2 8/16/22 inspection. 2 12/7/22 inspection. 2 12/7/22 inspection. 2 10/25/2021 3 10	Removed  Removed  Removed  Active  J/25/21 inspection. Dal and the installation ce recommendations  rty line to the east ship inspection. Urban Spinspection. Urban Spark vection.	or pitt piles were observed of BMPs. Urban Spark have changed. Urban ould be cleaned up.  ould be cleaned up.  our was reminded on a sark
Current Condition: Lot 96 Replat 1 Current Condition: Lot 97 Replat 1 Current Condition: Lot 100 Replat 1 Current Condition: Lot 101 Replat 1 Current Condition: Lot 101 Replat 1 Current Condition: Lot 110 Replat 1 Current Condition: Lot 110 Replat 1 Current Condition: Lot 112 Replat 1 Current Condition: Lot 112 Replat 1 Current Condition: Lot 116 Replat 1	Individual Lot Removed - D.R. Horton so Individual Lot Removed - Woodland Hoo Individual Lot Fair Condition - Unidentific in the ROW during the 10 installed silt fence at the responsible so the solution of the solu	odded the lot prior to the Lot 96 Replat 1 odded the lot prior to the Lot 97 Replat 1 odded the lot prior to the Lot 97 Replat 1 odded the lot prior to the Lot 100 Replat 1 mes sodded the lot prior Lot 101 Replat 1 ed builder began construction less from the ROW prior paired/reinstalled at the alled on the front of the eaned out and sediment stalled on the sides of the shed on to adjoining lots med to complete by 12/ 26/22, 6/23/22, 8/2/22, 1 med to complete by 12/ 26/22, 6/23/22, 8/2/22, 1 med to complete by 3/1: 8/2/22, 11/3/22, 11/9/22 Lot 105 Replat 1 Building sodded the lot prior to the Lot 112 Replat 1 Building sodded the lot prior to the Lot 116 Replat 1	a 8/16/22 inspection.  a 12/7/22 inspection.  10/25/2021  Lection on the lot prior to the 10 spector will monitor for remove 1/4/22 inspection.  To the 2/15/22 inspection. Maintenant to the 2/15/22 inspection.  Trear of the lot.  Lot.  Interpretation of the lot spector will monitor the proper lot.  Interpretation of the lot.  Interpretation of the last 1/3/22, 11/9/22  Interpretation of the last 1/3/22, 11/9/22  Interpretation of last inspection.  Interpretation of last inspection.  Interpretation of the 4/12/22 inspection.  Interpretation of the 4/12/22 inspection.	Removed  Removed  Removed  Active  0/25/21 inspection. Dal and the installation ce recommendations  rty line to the east shipspection. Urban Spection. Urban Spark vection.	or pitt piles were observed of BMPs. Urban Spark have changed. Urban ould be cleaned up.  ould be cleaned up.  our was reminded on a sark
Current Condition: Lot 96 Replat 1 Current Condition: Lot 97 Replat 1 Current Condition: Lot 100 Replat 1 Current Condition: Lot 101 Replat 1 Current Condition: Lot 101 Replat 1 Current Condition: Lot 112 Replat 1 Current Condition: Lot 112 Replat 1 Current Condition: Lot 112 Replat 1 Current Condition:	Individual Lot Removed - D.R. Horton so Individual Lot Removed - Woodland Hoo Individual Lot Fair Condition - Unidentific in the ROW during the 10 installed silt fence at the ro Spark removed the dirt pil  1.) Silt fence should be re 2.) Wattles should be inst 3.) Silt fence should be inst 3.) Silt fence should be inst 5.) Sediment that has was  1.) Urban Spark was infor 1/5/22, 3/8/22, 4/27/22, 5/ 3.) Urban Spark was infor 1/5/22, 3/8/22, 6/23/22, 8/ 4.) Urban Spark was infor 4/27/22, 5/6/22, 6/23/22, 8/ 5.) Urban Spark was infor 4/27/22, 5/6/22, 6/23/22, 8/ Individual Lot Removed - D.R. Horton so Individual Lot Removed - D&E Custom	odded the lot prior to the Lot 96 Replat 1 odded the lot prior to the Lot 97 Replat 1 odded the lot prior to the Lot 97 Replat 1 odded the lot prior to the Lot 100 Replat 1 mes sodded the lot prior Lot 101 Replat 1 ed builder began construction less from the ROW prior paired/reinstalled at the alled on the front of the eaned out and sediment stalled on the sides of the shed on to adjoining lots med to complete by 12/ 26/22, 6/23/22, 8/2/22, 1 med to complete by 12/ 26/22, 6/23/22, 8/2/22, 1 med to complete by 3/1: 8/2/22, 11/3/22, 11/9/22 Lot 105 Replat 1 Building sodded the lot prior to the Lot 112 Replat 1 Building sodded the lot prior to the Lot 116 Replat 1	a 8/16/22 inspection.  a 12/7/22 inspection.  10/25/2021  Lection on the lot prior to the 10 spector will monitor for remove 1/4/22 inspection.  To the 2/15/22 inspection. Maintenant to the 2/15/22 inspection.  Trear of the lot.  Lot.  Interpretation of the lot spector will monitor the proper lot.  Interpretation of the lot.  Interpretation of the last 1/3/22, 11/9/22  Interpretation of the last 1/3/22, 11/9/22  Interpretation of last inspection.  Interpretation of last inspection.  Interpretation of the 4/12/22 inspection.  Interpretation of the 4/12/22 inspection.	Removed  Removed  Removed  Active  0/25/21 inspection. Dal and the installation ce recommendations  rty line to the east ship inspection. Urban Spark vection.	or pitt piles were observed of BMPs. Urban Spark have changed. Urban ould be cleaned up.  ould be cleaned up.  our was reminded on a sark

	Good Condition - D.R. Ho inactive.					
Lot 120 Replat 1	Individual Lot	Lot 120 Replat 1	3/1/2022	Active	Yes	
Current Condition:	Fair Condition - D.R. Horton installed perimeter wattles prior to the 3/1/22 inspection. D.R. Horton began excavating the lot prior to the 4/26/22 inspection. D.R. Horton installed silt fence at the rear of the lot prior to the 7/12/22 inspection. D.R. Horton sodded the lot prior to the 11/9/22 inspection. Silt fence still remains at the rear of the lot.  Silt fence should be removed.					
			Not done as of last inspection	n. D.R. Horton was rer	ninded on 11/11/22.	
Lot 126 Replat 1	Individual Lot	Lot 127 Replat 1	11/23/2021	Active	No	
Current Condition:		e portable toilet prior to	t on Lot 126 prior to the 11/23 the 3/29/22 inspection. D.R. I	•	,	
Lot 127 Replat 1	Individual Lot	Lot 127 Replat 1		Removed		
Current Condition:	Removed - D.R. Horton s		e 10/25/22 inspection.	<del> </del>	1	
Lot 128 Replat 1	Individual Lot	Lot 128 Replat 1	40/05/00 :	Removed		
Current Condition: SB 1	Removed - D.R. Horton s	See SWPPP	e 10/25/22 inspection. 1/3/2020	A ations	l Na	
Current Condition:		d - The basin was instal om 4 holes in the orifice	ed prior to the 1/3/20 inspect plate prior to the 4/27/20 ins			
SB 2	Sediment Basin	See SWPPP	1/3/2020	Active	No	
Current Condition:	Seeding plugged the botte	om 2 rows of holes in th	ed prior to the 1/3/20 inspect e orifice plate prior to the 4/2 cleaned out the basin prior t	7/20 inspection. Hasun	nan began cleaning	
SB 3	Sediment Basin	See SWPPP	1/3/2020	Active	No	
Current Condition:		om 4 holes in the orifice	led prior to the 1/3/20 inspect plate prior to the 4/27/20 ins			
SB 4  Current Condition:	Seeding plugged the lower	est dewatering hole and	1/3/2020 alled prior to the 1/3/20 inspectoackfilled the erosion prior to the distance and installed a straw wattle at	the 4/27/20 inspection	n. Commercial seedi	
	Good Condition - 30% filled Seeding plugged the lower seeded and matted the et 5/11/20. All future recom	ed - The basin was insta est dewatering hole and rosion at the inlet pipe a mendation of maintenar	alled prior to the 1/3/20 inspec	the 4/27/20 inspection the stub road prior to the ded with SB 4. Riser in	riser. Commercial n. Commercial seedi ne inspection on	
Current Condition:	Good Condition - 30% filling Seeding plugged the lower seeded and matted the eta 5/11/20. All future recomprior to the 10/11/22 inspection.	ed - The basin was instated - The basin was instated and rosion at the inlet pipe a mendation of maintenar ection. E&A inspector w	alled prior to the 1/3/20 insper backfilled the erosion prior to nd installed a straw wattle at ace for the wattle will be inclu- ill monitor for installation of po	ction with a temporary of the 4/27/20 inspection the stub road prior to the stub road prior to the ded with SB 4. Riser in termanent riser.  Removed	riser. Commercial n. Commercial seed the inspection on	
SF 1 Current Condition:	Good Condition - 30% filling Seeding plugged the lower seeded and matted the eta 5/11/20. All future recomprior to the 10/11/22 inspection of the seeding solution. Silt fence Removed - Commercial States.	ed - The basin was instated - The basin was instated and rosion at the inlet pipe a mendation of maintenar ection. E&A inspector was see SWPPP deeding removed the silt	alled prior to the 1/3/20 insper backfilled the erosion prior to nd installed a straw wattle at ace for the wattle will be inclu-	ction with a temporary of the 4/27/20 inspection the stub road prior to the stub road prior to the ded with SB 4. Riser in termanent riser.  Removed spection.	riser. Commercial n. Commercial seed the inspection on	
Current Condition:	Good Condition - 30% filli Seeding plugged the lowe seeded and matted the et 5/11/20. All future recom prior to the 10/11/22 inspi Silt fence Removed - Commercial S	ed - The basin was instated - The basin was instated for the watering hole and rosion at the inlet pipe a mendation of maintenarection. E&A inspector was see SWPPP seeding removed the silt See SWPPP	alled prior to the 1/3/20 insper backfilled the erosion prior to nd installed a straw wattle at ace for the wattle will be inclu- ill monitor for installation of po	ction with a temporary of the 4/27/20 inspection the stub road prior to the stub road prior to the ded with SB 4. Riser in the stub road prior to the student student in the student student in the student student in the stu	riser. Commercial b. Commercial seed the inspection on the basin was remo	
SF 1 Current Condition: SF 2 Current Condition: SF 3	Good Condition - 30% filling Seeding plugged the lower seeded and matted the eta 5/11/20. All future recomprior to the 10/11/22 inspiration of the seeding solution of the seeding solution of the seeding solution. Silt fence the seeding seeding solution of the seeding se	ed - The basin was instated - The basin was instated to devate from the pipe and rosion at the inlet pipe a mendation of maintenar ection. E&A inspector was see SWPPP seeding removed the siltage SwPPP removed for home cons	alled prior to the 1/3/20 inspection backfilled the erosion prior to and installed a straw wattle at the for the wattle will be inclustill monitor for installation of prior to the 4/27/20 installation prior to the 10/26/21	ction with a temporary of the 4/27/20 inspection the stub road prior to the student road prior to th	iser. Commercial commercial seed the inspection on the basin was remained.  MPs for further	
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition:	Good Condition - 30% filling Seeding plugged the lower seeded and matted the error 5/11/20. All future recomprior to the 10/11/22 inspection of the seeding silt fence and seeding silt fence and seeding silt fence are recommendations.  Silt fence are recommendations.  Silt fence are recommendations.	ed - The basin was instated and rosion at the inlet pipe a mendation of maintenar ection. E&A inspector was see SWPPP seeding removed the silt See SWPPP removed for home constant of the swall see SWPPP removed in preparation.	alled prior to the 1/3/20 inspections to the erosion prior to the installed a straw wattle at the erosion prior to the first alled a straw wattle at the erosion of prior to the erosion of prior to the 4/27/20 installation	ction with a temporary of the 4/27/20 inspection the stub road prior to the stud road road prior to the stud road road road road road road road roa	iser. Commercial commercial seed the inspection on the basin was remained.  MPs for further	
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4	Good Condition - 30% fills Seeding plugged the lowe seeded and matted the et 5/11/20. All future recomprior to the 10/11/22 inspection Silt fence Removed - Commercial Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence Removed - Silt fence Silt fence Silt fence	ed - The basin was instatest dewatering hole and rosion at the inlet pipe a mendation of maintenarection. E&A inspector was See SWPPP seeding removed the silt See SWPPP removed for home consumer of the see SWPPP seeding removed for home consumer of the see SWPPP seeding removed for home consumer of the see SWPPP seeding removed in preparation of Springfield Trail	alled prior to the 1/3/20 inspectoackfilled the erosion prior to not installed a straw wattle at the for the wattle will be inclusiff monitor for installation of prior to the 4/27/20 installation prior to the 10/26/21 installa	ction with a temporary of the 4/27/20 inspection the stub road prior to the stub road prior	iser. Commercial commercial seed the inspection on the basin was reme	
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition:	Good Condition - 30% filling Seeding plugged the lower seeded and matted the error 5/11/20. All future recomprior to the 10/11/22 inspection of the seeding prior to the 10/11/22 inspection of the seeding solid fence. Removed - Commercial Seeding Silt fence. Removed - Wattles were recommendations.  Silt fence Removed - Silt fence was Silt fence. Removed - The remaining seeding see	ed - The basin was instatest dewatering hole and rosion at the inlet pipe a mendation of maintenarection. E&A inspector was See SWPPP seeding removed the silt See SWPPP removed for home consumer of the seeding removed for seeding removed for home consumer of the seeding removed for home consumer of the seeding removed for home consumer of the seeding removed in preparation of the seeding removed removed in preparation of the seeding removed r	alled prior to the 1/3/20 inspection backfilled the erosion prior to and installed a straw wattle at the for the wattle will be inclustill monitor for installation of prior to the 4/27/20 installation prior to the 10/26/21	ction with a temporary of the 4/27/20 inspection the stub road prior to the stub road road road road road road road road	iser. Commercial commercial seed the inspection on the basin was rem	
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4	Good Condition - 30% filling Seeding plugged the lower seeded and matted the eterory of the 10/11/20. All future recomprior to the 10/11/22 inspection of th	ed - The basin was instatest dewatering hole and rosion at the inlet pipe a mendation of maintenar ection. E&A inspector was established. See SWPPP seeding removed the siltage of the see SWPPP removed for home consumer in Springfield Trailage wattles have been multiple of the street and removed in preparation and the street and removed in seeding removed in preparation and seeding wattles have been multiple seeding removed in preparation and the street and removed in preparation and seeding seeding removed in preparation and seeding see	alled prior to the 1/3/20 inspectoackfilled the erosion prior to not installed a straw wattle at the for the wattle will be inclusiff monitor for installation of prior to the 4/27/20 installation prior to the 10/26/21 installa	ction with a temporary of the 4/27/20 inspection the stub road prior to the students of the s	iser. Commercial c. Commercial seed he inspection on the basin was reme  MPs for further  Don.	
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition:	Good Condition - 30% filling Seeding plugged the lower seeded and matted the eterory of the 10/11/20. All future recomprior to the 10/11/22 inspective for the solution of the seeded - Commercial Seeding Silt fence Removed - Wattles were recommendations.  Silt fence Removed - Silt fence was silt fence Removed - Silt fence Removed - The remaining Straw Wattle Removed - Tim Geis clean necessary.	ed - The basin was instatest dewatering hole and rosion at the inlet pipe a mendation of maintenar ection. E&A inspector was established. See SWPPP removed for home consumer of the sum of	alled prior to the 1/3/20 inspect backfilled the erosion prior to not installed a straw wattle at icce for the wattle will be incluill monitor for installation of prior to the 4/27/20 instance prior to the 4/27/20 instance prior to the 10/26/21 truction prior to the 10/26/21 to active construction prior ched or removed as of the 4/20 product the wattle prior to the 7/20 products the prior to the 7/20 products the wattle prior to the 7/20 products the wattle prior to the 7/20 products the prior to the 7/20 products the	ction with a temporary of the 4/27/20 inspection the stub road prior to the stub remanent riser.  Removed spection.  Removed inspection. See Lot Bit to the 5/18/20 inspection.  Removed 15/20 inspection.  Removed 15/20 inspection, reinst	iser. Commercial c. Commercial seed he inspection on the basin was rem  MPs for further  Don.  allation is not	
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition: W1 STR	Good Condition - 30% filling Seeding plugged the lower seeded and matted the error of the 10/11/22 inspiration of	ed - The basin was instated and rosion at the inlet pipe a mendation of maintenar ection. E&A inspector was see SWPPP seeding removed the siltage of the see SWPPP removed for home consumptions of Springfield Trailage wattles have been mular shadowned the street and removed in Street and removed the street and street an	alled prior to the 1/3/20 inspect backfilled the erosion prior to the installed a straw wattle at the for the wattle will be inclusiful monitor for installation of prior to the 4/27/20 installation prior to the 4/27/20 installation prior to the 10/26/21 installation prior to the 10/26/21 installation prior to the 4/27/20 installation prior to the 10/26/21 installa	ction with a temporary of the 4/27/20 inspection the stub road prior to the stub remanent riser.  Removed spection.  Removed inspection. See Lot Bi Removed to the 5/18/20 inspection.  Removed 15/20 inspection.  Removed 15/20 inspection, reinstipped 15	iser. Commercial c. Commercial seed he inspection on the basin was rem  MPs for further  Don.	
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition:	Good Condition - 30% filling Seeding plugged the lower seeded and matted the error of the 10/11/22 inspiration of	ed - The basin was instated and rosion at the inlet pipe a mendation of maintenar ection. E&A inspector was see SWPPP seeding removed the siltage of the see SWPPP removed for home consumptions of Springfield Trailage wattles have been mular shadowned the street and removed in Street and removed the street and street an	alled prior to the 1/3/20 inspect backfilled the erosion prior to not installed a straw wattle at icce for the wattle will be incluill monitor for installation of prior to the 4/27/20 instance prior to the 4/27/20 instance prior to the 10/26/21 truction prior to the 10/26/21 to active construction prior ched or removed as of the 4/20 product the wattle prior to the 7/20 products the prior to the 7/20 products the wattle prior to the 7/20 products the wattle prior to the 7/20 products the prior to the 7/20 products the	ction with a temporary of the 4/27/20 inspection the stub road prior to the stub remanent riser.  Removed spection.  Removed inspection. See Lot Bi Removed to the 5/18/20 inspection.  Removed 15/20 inspection.  Removed 15/20 inspection, reinstipped 15	iser. Commercial c. Commercial seed he inspection on the basin was rem  MPs for further  on.  callation is not	
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition: STR Current Condition:	Good Condition - 30% filling Seeding plugged the lower seeded and matted the error of the 10/11/22 inspiration of	ed - The basin was instated at dewatering hole and rosion at the inlet pipe a mendation of maintenarection. E&A inspector was see SWPPP seeding removed the siltage of the seeding removed the siltage of the seeding removed for home consumptions. See SWPPP removed in preparation and Springfield Trailage wattles have been multiples and the street and removed in the street and stree	alled prior to the 1/3/20 inspect backfilled the erosion prior to the installed a straw wattle at the form the wattle will be inclusiful monitor for installation of prior to the 4/27/20 installation prior to the 4/27/20 installation prior to the 10/26/21 installation prior to the 10/26/21 installation prior to the 4/27/20 installation prior to the 10/26/21 installation prior to the 10/26/21 installation prior to the 4/27/20 installation prior t	ction with a temporary of the 4/27/20 inspection the stub road prior to the stub remanent riser.  Removed spection.  Removed inspection. See Lot Bi Removed to the 5/18/20 inspection.  Removed 15/20 inspection.  Removed 15/20 inspection, reinstipped 15	iser. Commercial c. Commercial seed he inspection on the basin was rem  MPs for further  Don.  allation is not	
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition: W1 STR	Good Condition - 30% fills Seeding plugged the lowe seeded and matted the et 5/11/20. All future recomprior to the 10/11/22 inspection Silt fence Removed - Commercial Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence was Silt fence Removed - The remaining Straw Wattle Removed - Tim Geis cleanecessary.  Streets Good Condition - Streets Misc/Other Good Condition - E&A ins	ed - The basin was instatest dewatering hole and rosion at the inlet pipe a mendation of maintenarection. E&A inspector was see SWPPP seeding removed the silt. See SWPPP removed for home consumers of the seeding removed for home consumers of the seeding removed in preparation. Springfield Trail symmetric was been multiple seeding removed in preparation. See SWPPP removed in preparation. Springfield Trail symmetric have been multiple seeding and free and free of the seeding	alled prior to the 1/3/20 inspect backfilled the erosion prior to not installed a straw wattle at the for the wattle will be inclusiff monitor for installation of prior to the 4/27/20 installation prior to the 4/27/20 installation prior to the 10/26/21 installation prior to the 4/27/20 installation prior to the 7/27/2020 installation prior to the 11/9/22 installation prior to the 11/27/2020 in	ction with a temporary of the 4/27/20 inspection the stub road prior to the stub remanent riser.  Removed spection.  Removed inspection. See Lot Black Removed road removed	iser. Commercial c. Commercial seed the inspection on the basin was remove the basin was remo	
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition: STR Current Condition: STR Current Condition:	Good Condition - 30% fills Seeding plugged the lowe seeded and matted the et 5/11/20. All future recomprior to the 10/11/22 inspection Silt fence Removed - Commercial Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence was Silt fence Removed - The remaining Straw Wattle Removed - Tim Geis cleanecessary.  Streets Good Condition - Streets  Misc/Other Good Condition - E&A ins Street and Hazel Lane du "I certify, under penalty of direction or supervision in properly gathered and ev- persons who manage the the information submitted	ed - The basin was instatest dewatering hole and rosion at the inlet pipe a mendation of maintenarection. E&A inspector was see SWPPP seeding removed the siltage of the seeding removed the siltage of the seeding removed for home consumptions. See SWPPP removed for home consumptions of the seeding removed in preparation. Springfield Trailage wattles have been multiple seeding removed in preparation. See SWPPP removed in preparation. See SWPPP removed in preparation. Seeding in the street and removed in the street and removed in the street and free of the seeding in the seeding removed in the seeding removed in the seeding removed in the seeding	alled prior to the 1/3/20 inspect backfilled the erosion prior to the installed a straw wattle at the form the wattle will be inclusiful monitor for installation of prior to the 4/27/20 installation prior to the 4/27/20 installation prior to the 10/26/21 installation prior to the 4/27/20 installation prior to the 4/27/20 installation prior to the 10/26/21 installation prior to the 10/26/21 installation prior to the 4/27/2020 installation prior to the 1/3/2020 installation prior to the 1/27/2020 installation prior to the 1/2/2/2020 installatio	ction with a temporary of the 4/27/20 inspection the stub road prior to the stub remanent riser.  Removed spection.  Removed to the 5/18/20 inspection.  Removed remo	iser. Commercial c. Commercial seed the inspection on the basin was remove the basin was remo	