E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

0040 007 000

E	n	g	İn	e	е	r	in	g	A	n	S	W	e	r	S

Inspector: Shaun McGuire			19.327.000		
	•				Stage
		Spring	field Pines		
Drojact Nama			201600337		1
Project Name:					
For Week Ending:			11/2023		68059
Project Location:		f 132nd Street and I	Platteview Road, Springfield	, NE	
Grading:	Phase I 100%				
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%				
Seeding:	75%				
Utilities:	100%				
Overall Development:	70%				
		Γ			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Most
Sunday:	0.00"				Week
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"	0/0/0000	0	44.00	
Wednesday:	0.00"	2/8/2023	Sunny 53/32	11:00 AM	
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
Complaints:	None				
••••••					
	•				
Construction Sequencing:					
Which portion(s) (i.e. drainage ba	asins) of the site have had a tempo	prary or permanent cess			
			ation of grading, earthwork, or gro	und disturbance in the last 14	days?
Grading in Phase I was com	inleted prior to E&A being hire			und disturbance in the last 14	days?
	pleted prior to E&A being hire	ed to conduct SWPP	P inspections (1/3/20).		Gays?
Which portion(s) (i.e. drainage ba Grading in Phase I was com	asins) of the site do not have grad pleted prior to E&A being hire	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20).		oays?
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented?	tt 14 days?	
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20).	tt 14 days?	
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented?	tt 14 days?	
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E&	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented?	tt 14 days?	
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E& Checklist Questions:	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this A being hired to conduct SWI	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple PPP inspections (1/3	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented? //20). Portion of ground to the	tt 14 days? southeast of SB 4 seeded	
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E& Checklist Questions: Are receiving waters adjacent to	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this A being hired to conduct SWI	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple PPP inspections (1/3	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented?	tt 14 days? southeast of SB 4 seeded	
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E& Checklist Questions:	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this A being hired to conduct SWI	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple PPP inspections (1/3	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented? //20). Portion of ground to the	tt 14 days? southeast of SB 4 seeded	
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E& Checklist Questions: Are receiving waters adjacent to Yes	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this A being hired to conduct SWI	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple PPP inspections (1/3	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented? //20). Portion of ground to the	tt 14 days? southeast of SB 4 seeded	
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E& Checklist Questions: Are receiving waters adjacent to Yes Create Corrective Action?	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this A being hired to conduct SWI	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple PPP inspections (1/3	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented? //20). Portion of ground to the	tt 14 days? southeast of SB 4 seeded	
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E& Checklist Questions: Are receiving waters adjacent to Yes Create Corrective Action? N/A	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this A being hired to conduct SWI the project free of any significant	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple PPP inspections (1/3 signs of erosion or sedi	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented? //20). Portion of ground to the	tt 14 days? southeast of SB 4 seeded	and matted (5/11/20).
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E& Checklist Questions: Are receiving waters adjacent to Yes Create Corrective Action? N/A Have disturbed areas been seeded No	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this A being hired to conduct SWI the project free of any significant	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple PPP inspections (1/3 signs of erosion or sedi	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented? /20). Portion of ground to the ment that would be associated wit	tt 14 days? southeast of SB 4 seeded	and matted (5/11/20).
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E& Checklist Questions: Are receiving waters adjacent to Yes Create Corrective Action? N/A Have disturbed areas been seed No Create Corrective Action?	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this A being hired to conduct SWI the project free of any significant	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple PPP inspections (1/3 signs of erosion or sedi	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented? /20). Portion of ground to the ment that would be associated wit	tt 14 days? southeast of SB 4 seeded	and matted (5/11/20)
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E& Checklist Questions: Are receiving waters adjacent to Yes Create Corrective Action? N/A Have disturbed areas been seeded No	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this A being hired to conduct SWI the project free of any significant	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple PPP inspections (1/3 signs of erosion or sedi	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented? /20). Portion of ground to the ment that would be associated wit	tt 14 days? southeast of SB 4 seeded	and matted (5/11/20).
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E& Checklist Questions: Are receiving waters adjacent to Yes Create Corrective Action? N/A Have disturbed areas been seed No Create Corrective Action? No, see Findings section.	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this A being hired to conduct SWI the project free of any significant	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple PPP inspections (1/3 signs of erosion or sedi	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented? /20). Portion of ground to the ment that would be associated wit	tt 14 days? southeast of SB 4 seeded	and matted (5/11/20).
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E& Checklist Questions: Are receiving waters adjacent to Yes Create Corrective Action? N/A Have disturbed areas been seeded No Create Corrective Action? No, see Findings section. Are waste materials (concrete, concept)	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this A being hired to conduct SWI the project free of any significant ed or otherwise stabilized as requ	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple PPP inspections (1/3 signs of erosion or sedi	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented? /20). Portion of ground to the ment that would be associated wit	tt 14 days? southeast of SB 4 seeded	and matted (5/11/20).
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E& Checklist Questions: Are receiving waters adjacent to Yes Create Corrective Action? N/A Have disturbed areas been seeded No Create Corrective Action? No, see Findings section. Are waste materials (concrete, cr No Create Corrective Action?	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this A being hired to conduct SWI the project free of any significant ed or otherwise stabilized as requ	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple PPP inspections (1/3 signs of erosion or sedi	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented? /20). Portion of ground to the ment that would be associated wit	tt 14 days? southeast of SB 4 seeded	and matted (5/11/20)
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E& Checklist Questions: Are receiving waters adjacent to Yes Create Corrective Action? N/A Have disturbed areas been seeded No Create Corrective Action? No, see Findings section. Are waste materials (concrete, concept)	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this A being hired to conduct SWI the project free of any significant ed or otherwise stabilized as requ	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple PPP inspections (1/3 signs of erosion or sedi	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented? /20). Portion of ground to the ment that would be associated wit	tt 14 days? southeast of SB 4 seeded	and matted (5/11/20).
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E& Checklist Questions: Are receiving waters adjacent to Yes Create Corrective Action? N/A Have disturbed areas been seed No Create Corrective Action? No, see Findings section. Are waste materials (concrete, ct No Create Corrective Action? No, see BMPs section and F	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this A being hired to conduct SWI the project free of any significant ed or otherwise stabilized as requ onstruction material, hazardous, e	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple PPP inspections (1/3 signs of erosion or sedi	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented? /20). Portion of ground to the ment that would be associated wit	tt 14 days? southeast of SB 4 seeded	and matted (5/11/20).
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E& Checklist Questions: Are receiving waters adjacent to Yes Create Corrective Action? N/A Have disturbed areas been seed No Create Corrective Action? No, see Findings section. Are waste materials (concrete, cr No Create Corrective Action? No, see BMPs section and F	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this A being hired to conduct SWI the project free of any significant ed or otherwise stabilized as requ	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple PPP inspections (1/3 signs of erosion or sedi	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented? /20). Portion of ground to the ment that would be associated wit	tt 14 days? southeast of SB 4 seeded	and matted (5/11/20).
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E& Checklist Questions: Are receiving waters adjacent to Yes Create Corrective Action? N/A Have disturbed areas been seeded No Create Corrective Action? No, see Findings section. Are waste materials (concrete, c No Create Corrective Action? No, see BMPs section and F Are construction entrances and a Yes Create Corrective Action?	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this A being hired to conduct SWI the project free of any significant ed or otherwise stabilized as requ onstruction material, hazardous, e	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple PPP inspections (1/3 signs of erosion or sedi	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented? /20). Portion of ground to the ment that would be associated wit	tt 14 days? southeast of SB 4 seeded	and matted (5/11/20).
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E& Checklist Questions: Are receiving waters adjacent to Yes Create Corrective Action? N/A Have disturbed areas been seede No Create Corrective Action? No, see Findings section. Are waste materials (concrete, cc No Create Corrective Action? No, see BMPs section and F Are construction entrances and a Yes	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this A being hired to conduct SWI the project free of any significant ed or otherwise stabilized as requ onstruction material, hazardous, e	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple PPP inspections (1/3 signs of erosion or sedi	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented? /20). Portion of ground to the ment that would be associated wit	tt 14 days? southeast of SB 4 seeded	and matted (5/11/20).
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E& Checklist Questions: Are receiving waters adjacent to Yes Create Corrective Action? N/A Have disturbed areas been seedd No Create Corrective Action? No, see Findings Section. Are waste materials (concrete, co No Create Corrective Action? No, see BMPs section and F Are construction entrances and a Yes Create Corrective Action? N/A	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this A being hired to conduct SWI the project free of any significant ed or otherwise stabilized as requi- construction material, hazardous, e -indings section. adjacent streets being maintained	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple PPP inspections (1/3 signs of erosion or sedi ired? List inactive portion etc.) being managed prop adequately?	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented? /20). Portion of ground to the ment that would be associated wit	tt 14 days? southeast of SB 4 seeded	and matted (5/11/20).
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E& Checklist Questions: Are receiving waters adjacent to Yes Create Corrective Action? N/A Have disturbed areas been seedd No Create Corrective Action? No, see Findings Section. Are waste materials (concrete, co No Create Corrective Action? No, see BMPs section and F Are construction entrances and a Yes Create Corrective Action? N/A	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this A being hired to conduct SWI the project free of any significant ed or otherwise stabilized as requ onstruction material, hazardous, e	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple PPP inspections (1/3 signs of erosion or sedi ired? List inactive portion etc.) being managed prop adequately?	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented? /20). Portion of ground to the ment that would be associated wit	tt 14 days? southeast of SB 4 seeded	and matted (5/11/20).
Which portion(s) (i.e. drainage ba Grading in Phase I was com What temporary or permanent st Site was seeded prior to E& Checklist Questions: Are receiving waters adjacent to Yes Create Corrective Action? N/A Have disturbed areas been seeded No Create Corrective Action? No, see Findings section. Are waste materials (concrete, co No Create Corrective Action? No, see BMPs section and F Are construction entrances and a Yes Create Corrective Action? No, see BMPs section and F Are construction entrances and a Yes	asins) of the site do not have grad pleted prior to E&A being hire abilization measures listed in this A being hired to conduct SWI the project free of any significant ed or otherwise stabilized as requi- construction material, hazardous, e -indings section. adjacent streets being maintained	ed to conduct SWPP ing, earthwork, or groun ed to conduct SWPP section are being imple PPP inspections (1/3 signs of erosion or sedi ired? List inactive portion etc.) being managed prop adequately?	P inspections (1/3/20). d disturbance scheduled in the nex P inspections (1/3/20). mented? /20). Portion of ground to the ment that would be associated wit	tt 14 days? southeast of SB 4 seeded	and matted (5/11/20).

Comments:

Comments: Site was active for homebuilding during the most recent inspection.

The School Site was graded prior to the 9/23/20 inspection. The School Site is not covered by the Springfield Pines permit (SPR-20200728-5543-GP1).

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) Some maintenance is required in the BMP section of this report.

2) Vacant-disturbed lots need to be stabilized.

A. Overgraded lots during homebuilding construction need to be stabilized. All builders were informed to complete by 1/17/20 when weather allows and as needed. Not done as of the last inspection. All builders were reminded on 9/24/20, 6/24/21.

3) Concrete waste was located throughout the development. D.R. Horton was informed to clean up concrete waste in SB 4 on 3/3/22. Not done as of last inspection. D.R. Horton was reminded on 3/24/22, 5/24/22, 6/2/22, 6/17/22, 6/23/22, 8/19/22, 8/31/22, 11/11/22. D.R. Horton was informed to clean up concrete waste on lot 72 on 8/31/22. Not done as of last inspection. D.R. Horton was reminded on 11/11/22.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
AI 1	Area Inlet Protection	See SWPPP	1/3/2020	Active	No
Current Condition:) inspection. The surrounding	area is vegetated and	the inlet drains to SB
	1; no inlet protection will b				
Al 2	Area Inlet Protection	See SWPPP	1/3/2020	Active	No
Current Condition:	Good Condition - Area Init	et with dome grate was	installed prior to the 1/3/20 installed prior to the 1/3/20 instruction will be recommende	d at this time. Urban S	ang area was seeded
			man installed 3 additional inlet		
	-		nlet protection prior to the 11/9		
AI 3	Area Inlet Protection	See SWPPP	3/9/2020	Active	No
Current Condition:			prior to the 3/9/20 inspections.		
	silt fence/T-posts around		-		, · · · · · · · · · · · · · · · · · · ·
AI 4	Area Inlet Protection	See SWPPP	3/9/2020	Active	No
Current Condition:			prior to the 3/9/20 inspection.		was seeded and
	matted and the inlet drain	s to SB 2; no inlet prote	ction will be recommended at	this time.	
CW 1	Concrete Washout	Lot 81 Replat 1		Removed	
Current Condition:			alled on Lot 81 Replat 1 prior t		
			bection on $5/11/20$, the berm r		-
			oach prior to the 6/1/20 inspect aves relocated the concrete w		
			he concrete washout prior to t		
			tion, the E&A inspector will m	•	
	-		inspection. Mobile washout v		
	12/21/21 inspection. D.R.	Horton installed a conci	rete washout on to lot 117 price	or to the 5/10/22 inspe	ction. D.R. Horton
			22 inspection. D.R. Horton re	moved the concrete w	ashout prior to the
	10/11/22 inspection, the E	&A inspector will monito	or for reinstallation.		
IP 1	Inlet Protection	See SWPPP		Removed	
Current Condition:		eeding removed the inle	et filter prior to the 4/27/20 ins	pection. Inlet drains to	o a basin, reinstallation
IP 2	is not recommended. Inlet Protection	See SWPPP		Removed	
Current Condition:			et filter prior to the 4/27/20 ins		a basin. reinstallation
		0	inlet filter prior to the 6/21/22 i		,
	prior to the 12/21/22 inspe	ection. Inlet drains to a b	asin, reinstallation is not reco	mmended.	
IP 3	Inlet Protection	See SWPPP		Removed	
Current Condition:	Removed - Commercial S	eeding removed the inle	et filter prior to the 4/27/20 ins	pection. Inlet drains to	a basin, reinstallation
	is not recommended.				
IP 4	Inlet Protection	See SWPPP		Removed	
Current Condition:			et filter prior to the 4/27/20 ins		
			filter protection prior to the 5/	•	. Horton removed the
		-	ains to a basin, reinstallation is	1	
IP 5	Inlet Protection	See SWPPP	t filter prior to the 4/27/20 ins	Removed	a basin reinstallation
Current Condition:		0	filter protection prior to the 5/		
			ains to a basin, reinstallation is	•	
IP 6	Inlet Protection	See SWPPP		Removed	
Current Condition:			et filter prior to the 4/27/20 ins		a basin, reinstallation
	is not recommended. D.R	. Horton reinstalled inlet	filter protection prior to the 8/	30/22 inspection. D.R.	. Horton removed the
	inlet filter prior to the 12/2	1/22 inspection. Inlet dra	ains to a basin, reinstallation is	s not recommended.	
IP 7	Inlet Protection	See SWPPP		Removed	
Current Condition:		eeding removed the inle	et filter prior to the 4/27/20 ins	pection. Inlet drains to	a basin, reinstallation
	is not recommended.			1	
IP 8	Inlet Protection	See SWPPP		Removed	
Current Condition:		0	et filter prior to the 4/27/20 ins		
			filter protection prior to the 8/ ains to a basin, reinstallation is	•	. Horion removed the
			amo io a paoin, teitiotaliation i: T		1
IP 9	Inlet Protection	See SWPPP	1	Removed	

Current Condition:	Removed - Commercial S is not recommended.	eeding removed the inle	et filter prior to the 4/27/20	inspection. Inlet drains to	o a pasin, reinstalla
IP 10	Inlet Protection	See SWPPP		Removed	
Current Condition:	not recommended. D.R. H inlet filter prior to the 6/7/2	lorton reinstalled inlet fil 22 inspection. D.R. Horto	et filter prior to the 4/27/20 ter protection prior to the 3 on reinstalled the inlet filter ction. Inlet drains to a basi	/1/22 inspection. D.R. Ho prior to the 6/21/22 insp	orton cleaned out the ction. D.R. Horton
IP 11	Inlet Protection	See SWPPP		Removed	
Current Condition:	not recommended. D.R. H filter prior to the 4/5/22 ins	lorton reinstalled inlet fil spection. D.R. Horton cle	t filter prior to the 4/27/20 ter protection prior to the 3 eaned out the inlet filter pri- ction. Inlet drains to a basin	/1/22 inspection. D.R. Ho or to the 6/28/22 inspecti	orton repaired the ir on. D.R. Horton
IP 12	Inlet Protection	See SWPPP		Removed	
Current Condition:			et filter prior to the 4/27/20		o a basin, reinstalla
IP 13	Inlet Protection	See SWPPP		Removed	
Current Condition:	Removed - Commercial S is not recommended.	eeding removed the inle	et filter prior to the 4/27/20	inspection. Inlet drains to	o a basin, reinstalla
IP 14	Inlet Protection	See SWPPP		Removed	
Current Condition:	Removed - Commercial S is not recommended.		et filter prior to the 4/27/20	inspection. Inlet drains to	o a basin, reinstalla
IP 15	Inlet Protection	See SWPPP		Removed	
Current Condition:	is not recommended.		et filter prior to the 4/27/20		o a basin, reinstalla
IP 16	Inlet Protection	See SWPPP		Removed	
Current Condition:	Removed - Commercial S is not recommended.	eeding removed the inle	et filter prior to the 4/27/20	inspection. Inlet drains to	o a basin, reinstalla
IP 17 Current Condition:	Inlet Protection	See SWPPP	et filter prior to the 4/27/20	Removed	
IP 18 Current Condition:	basin, reinstallation is not Inlet Protection Removed - Commercial S is not recommended. D.R inlet filter prior to the 7/12	recommended. See SWPPP eeding removed the inle Horton reinstalled inlet /22 inspection. D.R. Hor	on removed the inlet filter p t filter prior to the 5/11/20 filter protection prior to the ton cleaned out the inlet fil	Removed inspection. Inlet drains to 5/3/22 inspection. D.R. ter prior to the 8/23/22 in	a basin, reinstalla Horton cleaned out spection. D.R. Hor
	· · · · · · · · · · · · · · · · · · ·		ction. Inlet drains to a basi	n, reinstallation is not rec	ommended.
IP 19	Inlet Protection	See SWPPP		Removed	
Current Condition:	is not recommended.	eeding removed the init	et filter prior to the 4/27/20	inspection. Inlet drains to	o a basin, reinstalla
IP 20	Inlet Protection	See SWPPP		Removed	
Current Condition:		eeding removed the inle	et filter prior to the 4/27/20	inspection. Inlet drains to	o a basin, reinstalla
IP 21	is not recommended. Inlet Protection	See SWPPP		Removed	
Current Condition:			et filter prior to the 4/27/20		a basin. reinstalla
	is not recommended. D.R inlet filter prior to the 8/2/2 basin, reinstallation is not	. Horton reinstalled inlet 2 inspection. D.R. Horto recommended.	filter protection prior to the on removed the inlet filter p	3/29/22 inspection. D.R rior to the 12/21/22 insp	. Horton maintained
IP 22 Current Condition:	Inlet Protection	See SWPPP	et filter prior to the 4/27/20	Removed	a basin reinetelle
	is not recommended.				
IP 23 Current Condition:		. Horton reinstalled inlet	I et filter prior to the 4/27/20 filter protection prior to the		
IP 24	Inlet Protection	See SWPPP		Removed	
Current Condition:		Horton reinstalled inlet	et filter prior to the 4/27/20 filter protection prior to the	•	
					L
IP 25	Inlet Protection	See SWPPP		Removed	
IP 25 Current Condition:	Removed - Commercial S	eeding removed the inle	t filter prior to the 4/27/20 let filter prior to the 5/31/22	inspection. Inlet drains to	a basin, reinstall

Current Condition:	Fair Condition - Commercial Seeding removed the inlet filt	er prior to the 4/27/20 inspection. Inlet drains to a basin,
		inlet filter protection prior to the 3/29/22 inspection. D.R. Hortor
	cleaned out the inlet filter prior to the 8/16/22 inpection.	
	Inlet filter should be removed.	
	D.R. Horton was informed to complete by 11/16/22. Not do	one as of last inspection.
IP 27	Inlet Protection See SWPPP	Removed
Current Condition:		rior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation
	is not recommended.	i ,
IP 28	Inlet Protection See SWPPP	Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter pr	rior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation
	is not recommended.	
Lot 1 Replat 1	Individual Lot Lot 1 Replat 1	Removed
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 4/12/22	inspection.
Lot 4 Replat 3	Individual Lot Lot 4 Replat 3	Removed
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 11/9/22	inspection.
Lot 6 Replat 1	Individual Lot Lot 6 Replat 1	Removed
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 11/9/22	
Lot 7 Replat 1	Individual Lot Lot 7 Replat 1	Removed
Current Condition:	Removed - Carlson Tile Inc. sodded the lot prior to the 6/2	
Lot 10 Replat 1	Individual Lot Lot 10 Replat 1	Removed
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 4/19/22	
Lot 11 Replat 1	Individual Lot Lot 11 Replat 1	Removed
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 4/19/22	
Lot 13 Replat 1	Individual Lot Lot 13 Replat 1	Removed
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 4/19/22	
Lot 19 Replat 1	Individual Lot Lot 19 Replat 1	Removed
Current Condition:	Removed - Brooks Builders sodded the lot prior to the 5/10	
Lot 20 Replat 1	Individual Lot Lot 20 Replat 1	Removed
Current Condition:	Active - Sundown Homes LLC sodded the lot prior to the 8	
Lot 22 Replat 1	Individual Lot Lot 22 Replat 1	Removed
Current Condition:	Removed - Urban Spark sodded the lot prior to the 5/17/2	
Lot 23 Replat 1	Individual Lot Lot 23 Replat 1	Removed
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 4/12/22	
Lot 28 Replat 1	Individual Lot Lot 28 Replat 1	Removed
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 4/12/22	
Lot 30 Replat 1	Individual Lot Lot 30 Replat 1	Removed
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 11/2/22	
Lot 33 Replat 1	Individual Lot Lot 33 Replat 1	Removed
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 5/17/22	
Lot 43 Replat 1	Individual Lot Lot 43 Replat 1	Removed
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 7/26/22	
Lot 45 Replat 1	Individual Lot Lot 20 Replat 1	6/14/2022 Pending Yes
Current Condition:		t prior to the 6/14/22 inspection. Dirt piles were observed in the
		elatively flat, no BMPs are recommended at this time. Brooks
	Builders removed the dirt pile from the ROW and the conc	rete waste on the lot prior to the 7/26/22 inspection.
	1.) Silt fence should be installed on the east side and rear	of the lot.
	2.) Wattles should be installed on the front of the lot.	
		Not done as of last inspection. Brooks Builders were reminded of
	11/3/22.	
		Not done as of last inspection. Brooks Builders were reminded of
	11/3/22.	
Lot 46 Replat 1	Individual Lot Lot 46 Replat 1	Removed
Current Condition:	Individual Lot Lot 46 Replat 1 Removed - Epic Custom Homes sodded the lot prior to the	e 5/17/22 inspection.
Current Condition: Lot 48 Replat 1	Individual Lot Lot 46 Replat 1 Removed - Epic Custom Homes sodded the lot prior to the Individual Lot Lot 48 Replat 1	e 5/17/22 inspection. Removed
Current Condition: Lot 48 Replat 1 Current Condition:	Individual Lot Lot 46 Replat 1 Removed - Epic Custom Homes sodded the lot prior to the Individual Lot Lot 48 Replat 1 Removed - D.R. Horton sodded the lot prior to the 10/25/2	e 5/17/22 inspection. Removed 22 inspection.
Current Condition: Lot 48 Replat 1 Current Condition: Lot 49 Replat 1	Individual Lot Lot 46 Replat 1 Removed - Epic Custom Homes sodded the lot prior to the Individual Lot Lot 48 Replat 1 Removed - D.R. Horton sodded the lot prior to the 10/25/2 Individual Lot Individual Lot Lot 49 Replat 1	e 5/17/22 inspection. Removed 22 inspection. Removed
Current Condition: Lot 48 Replat 1 Current Condition: Lot 49 Replat 1 Current Condition:	Individual Lot Lot 46 Replat 1 Removed - Epic Custom Homes sodded the lot prior to the Individual Lot Lot 48 Replat 1 Removed - D.R. Horton sodded the lot prior to the 10/25/2 Individual Lot Individual Lot Lot 49 Replat 1 Removed - D.R. Horton sodded the lot prior to the 10/25/2 Individual Lot Lot 49 Replat 1 Removed - D.R. Horton sodded the lot prior to the 10/11/2	e 5/17/22 inspection. Removed 22 inspection. Removed 22 inspection.
Current Condition: Lot 48 Replat 1 Current Condition: Lot 49 Replat 1 Current Condition: Lot 51 Replat 1	Individual Lot Lot 46 Replat 1 Removed - Epic Custom Homes sodded the lot prior to the Individual Lot Lot 48 Replat 1 Removed - D.R. Horton sodded the lot prior to the 10/25/2 Individual Lot Lot 49 Replat 1 Removed - D.R. Horton sodded the lot prior to the 10/25/2 Individual Lot Lot 49 Replat 1 Removed - D.R. Horton sodded the lot prior to the 10/11/2 Individual Lot Lot 51 Replat 1	e 5/17/22 inspection. Removed 22 inspection. Removed 22 inspection. Removed
Current Condition: Lot 48 Replat 1 Current Condition: Lot 49 Replat 1 Current Condition:	Individual Lot Lot 46 Replat 1 Removed - Epic Custom Homes sodded the lot prior to the Individual Lot Lot 48 Replat 1 Removed - D.R. Horton sodded the lot prior to the 10/25/2 Individual Lot Individual Lot Lot 49 Replat 1 Removed - D.R. Horton sodded the lot prior to the 10/25/2 Individual Lot Lot 49 Replat 1 Removed - D.R. Horton sodded the lot prior to the 10/11/2	e 5/17/22 inspection. Removed 22 inspection. Removed 22 inspection. Removed

Future silt fence ce was observed avation on the lot mark Performand
avation on the lot mark Performand ction. Landmark ction. Landmark <u>Yes</u> n the ROW durin nded on 5/6/22, <u>Yes</u> ticed in the ROW 6/22 inspection.
mark Performano Stion. Landmark Stion. Landmark Performance Yes n the ROW durin nded on 5/6/22, Yes ticed in the ROW 6/22 inspection.
tion. Landmark tion. Landmark Yes n the ROW durin nded on 5/6/22, Yes ticed in the ROW 6/22 inspection.
tion. Landmark tion. Landmark Yes n the ROW durin nded on 5/6/22, Yes ticed in the ROW 6/22 inspection.
tion. Landmark
Yes n the ROW durin nded on 5/6/22, Yes ticed in the ROW 6/22 inspection.
Yes n the ROW durin nded on 5/6/22, Yes ticed in the ROW 6/22 inspection.
n the ROW durin nded on 5/6/22, <u>Yes</u> ticed in the ROW 6/22 inspection.
n the ROW durin nded on 5/6/22, <u>Yes</u> ticed in the ROW 6/22 inspection.
n the ROW durin nded on 5/6/22, <u>Yes</u> ticed in the ROW 6/22 inspection.
n the ROW durin nded on 5/6/22, <u>Yes</u> ticed in the ROW 6/22 inspection.
n the ROW durin nded on 5/6/22, <u>Yes</u> ticed in the ROW 6/22 inspection.
n the ROW durin nded on 5/6/22, <u>Yes</u> ticed in the ROW 6/22 inspection.
nded on 5/6/22, Yes ticed in the ROW 6/22 inspection.
nded on 5/6/22, Yes ticed in the ROW 6/22 inspection.
Yes ticed in the ROW 6/22 inspection.
Yes ticed in the ROW 6/22 inspection.
Yes ticed in the ROW 6/22 inspection.
Yes ticed in the ROW 6/22 inspection.
Yes ticed in the ROW 6/22 inspection.
ticed in the ROW 6/22 inspection. ninded on 8/2/22,
ticed in the ROW 6/22 inspection. ninded on 8/2/22,
ticed in the ROW 6/22 inspection. ninded on 8/2/22,
ticed in the ROW 6/22 inspection. ninded on 8/2/22,
ticed in the ROW 6/22 inspection. ninded on 8/2/22,
ticed in the ROW 6/22 inspection. ninded on 8/2/22,
ninded on 8/2/22,
ninded on 8/2/22,
ninded on 8/2/22,
Yes
ere observed in th
Urban Spark
ve changed. Urba
d be cleaned up.
. So olcanda up.
was reminded or
was reminded or
reminded on 3/8/
reminded on
rominded er
reminded on

	inactive.	orton installed wattles alo			
Lot 120 Replat 1	Individual Lot	Lot 120 Replat 1	3/1/2022	Active	Yes
Current Condition:	Fair Condition - D.R. Hor	ton installed perimeter wa	attles prior to the 3/1/22 in	spection. D.R. Horton b	began excavating the
			ed silt fence at the rear of		
	Horton sodded the lot pri	or to the 11/9/22 inspection	on. Silt fence still remains	at the rear of the lot.	
	Silt fence should be remo	oved.			
	D.R. Horton was informe	d to complete by 9/6/22.	Not done as of last inspec	tion. D.R. Horton was r	reminded on 11/11/22
Lot 126 Replat 1	Individual Lot	Lot 127 Replat 1	11/23/2021	Active	No
Current Condition:			on Lot 126 prior to the 11		
current condition.		•	he 3/29/22 inspection. D.F		•
	prior to the 11/16/22 insp	• •	ne sizaizz inspection. D.i		
Lot 127 Replat 1	Individual Lot	Lot 127 Replat 1		Removed	
Current Condition:	Removed - D.R. Horton s		10/25/22 inspection.		
Lot 128 Replat 1	Individual Lot	Lot 128 Replat 1		Removed	
Current Condition:		sodded the lot prior to the		1	- I
SB 1	Sediment Basin	See SWPPP	1/3/2020	Active	No
Current Condition:			ed prior to the 1/3/20 inspe		
		om 4 holes in the orifice	plate prior to the 4/27/20 i	nspection. Hasuman cle	eaned out the basin p
	to the 8/9/22 inspection.				
SB 2	Sediment Basin	See SWPPP	1/3/2020	Active	No
Current Condition:	Good Condition - 1% fille	d - The basin was installe	ed prior to the 1/3/20 inspe	ection with a permanent	t riser. Commercial
			orifice plate prior to the 4		
			cleaned out the basin pric		
00.0					
SB 3	Sediment Basin	See SWPPP	1/3/2020	Active	No
Current Condition:			ed prior to the 1/3/20 inspe		
		om 4 holes in the orifice	plate prior to the 4/27/20 i	nspection. Hasuman cle	eaned out the basin p
	to the 8/9/22 inspection.				
		0 0000000			
SB 4	Sediment Basin	See SWPPP	1/3/2020	Active	No
SB 4 Current Condition:	Good Condition - 30% fill	ed - The basin was insta	lled prior to the 1/3/20 insp	pection with a temporar	ry riser. Commercial
	Good Condition - 30% fill Seeding plugged the low	ed - The basin was insta est dewatering hole and I	lled prior to the 1/3/20 insp packfilled the erosion prior	bection with a temporar to the 4/27/20 inspecti	ry riser. Commercial ion. Commercial seed
	Good Condition - 30% fill Seeding plugged the low seeded and matted the e	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar	lled prior to the 1/3/20 insp backfilled the erosion prior ad installed a straw wattle	bection with a temporar to the 4/27/20 inspecti at the stub road prior to	ry riser. Commercial ion. Commercial see o the inspection on
	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recorr	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar mendation of maintenan	lled prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc	bection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser	ry riser. Commercial ion. Commercial seed the inspection on
Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar mendation of maintenan ection. E&A inspector wi	lled prior to the 1/3/20 insp backfilled the erosion prior ad installed a straw wattle	bection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser.	ry riser. Commercial ion. Commercial seed the inspection on
Current Condition: SF 1	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar mendation of maintenan ection. E&A inspector wi See SWPPP	lled prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc Il monitor for installation of	bection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed	ry riser. Commercial ion. Commercial seed the inspection on
Current Condition: SF 1 Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar mendation of maintenan ection. E&A inspector wi See SWPPP Seeding removed the silt	lled prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc	bection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed inspection.	ry riser. Commercial ion. Commercial seed the inspection on
Current Condition: SF 1 Current Condition: SF 2	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector wi See SWPPP Seeding removed the silt See SWPPP	lled prior to the 1/3/20 insp packfilled the erosion prior nd installed a straw wattle ce for the wattle will be inc Il monitor for installation of fence prior to the 4/27/20	ection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed inspection. Removed	y riser. Commercial ion. Commercial seed of the inspection on in the basin was rem
Current Condition: SF 1 Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector wi See SWPPP Seeding removed the silt See SWPPP	lled prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc Il monitor for installation of	ection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed inspection. Removed	y riser. Commercial ion. Commercial seed of the inspection on in the basin was rem
Current Condition: SF 1 Current Condition: SF 2	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector wi See SWPPP Seeding removed the silt See SWPPP	lled prior to the 1/3/20 insp packfilled the erosion prior nd installed a straw wattle ce for the wattle will be inc Il monitor for installation of fence prior to the 4/27/20	ection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed inspection. Removed	y riser. Commercial ion. Commercial seed of the inspection on in the basin was rem
Current Condition: SF 1 Current Condition: SF 2	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence	ed - The basin was insta est dewatering hole and h rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector wi See SWPPP Seeding removed the silt See SWPPP removed for home const See SWPPP	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc Il monitor for installation of fence prior to the 4/27/20 rruction prior to the 10/26/3	bection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed Removed Removed Removed	y riser. Commercial ion. Commercial seed o the inspection on in the basin was rem BMPs for further
Current Condition: SF 1 Current Condition: SF 2 Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence	ed - The basin was insta est dewatering hole and h rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector wi See SWPPP Seeding removed the silt See SWPPP removed for home const See SWPPP	lled prior to the 1/3/20 insp packfilled the erosion prior nd installed a straw wattle ce for the wattle will be inc Il monitor for installation of fence prior to the 4/27/20	bection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed Removed Removed Removed	y riser. Commercial ion. Commercial seed o the inspection on in the basin was rem BMPs for further
SF 1 Current Condition: SF 2 Current Condition: SF 3	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence	ed - The basin was insta est dewatering hole and h rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector wi See SWPPP Seeding removed the silt See SWPPP removed for home const See SWPPP	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc Il monitor for installation of fence prior to the 4/27/20 rruction prior to the 10/26/3	bection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed Removed Removed Removed	y riser. Commercial ion. Commercial seed o the inspection on in the basin was rem BMPs for further
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence wat Silt fence	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector wi See SWPPP Seeding removed the silt See SWPPP removed for home const See SWPPP s removed in preparation Springfield Trail	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc Il monitor for installation of fence prior to the 4/27/20 rruction prior to the 10/26/3	bection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed inspection. Removed 21 inspection. See Lot Removed or to the 5/18/20 inspect Removed	y riser. Commercial ion. Commercial seed o the inspection on in the basin was rem BMPs for further
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence was Silt fence Removed - Silt fence was Silt fence Removed - The remainin Straw Wattle	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector wi See SWPPP Seeding removed the silt See SWPPP removed for home const See SWPPP s removed in preparation Springfield Trail g wattles have been mult SB 4 Stub Road	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc Il monitor for installation of fence prior to the 4/27/20 ruction prior to the 10/26/2 for active construction pri ched or removed as of the	bection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed inspection. Removed 21 inspection. See Lot Removed or to the 5/18/20 inspect Removed 4/9/21 inspection. Removed	y riser. Commercial ion. Commercial seed of the inspection on in the basin was rem BMPs for further ction.
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence was Silt fence Removed - Silt fence was Silt fence Removed - The remainin Straw Wattle	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector wi See SWPPP Seeding removed the silt See SWPPP removed for home const See SWPPP s removed in preparation Springfield Trail g wattles have been mult SB 4 Stub Road	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc Il monitor for installation of fence prior to the 4/27/20 ruction prior to the 10/26/2 for active construction pri ched or removed as of the	bection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed inspection. Removed 21 inspection. See Lot Removed or to the 5/18/20 inspect Removed 4/9/21 inspection. Removed	y riser. Commercial ion. Commercial seed of the inspection on in the basin was rem BMPs for further ction.
Current Condition: SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence wat Silt fence Removed - The remainin Straw Wattle Removed - Tim Geis clea	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector wi See SWPPP Seeding removed the silt See SWPPP removed for home const See SWPPP s removed in preparation Springfield Trail g wattles have been mult SB 4 Stub Road	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc Il monitor for installation of fence prior to the 4/27/20 furuction prior to the 10/26/2 for active construction prior	bection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed inspection. Removed 21 inspection. See Lot Removed or to the 5/18/20 inspect Removed 4/9/21 inspection. Removed	y riser. Commercial ion. Commercial see o the inspection on in the basin was rem BMPs for further ction.
Current Condition: SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence was Silt fence Removed - Silt fence was Silt fence Removed - The remainin Straw Wattle	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector wi See SWPPP Seeding removed the silt See SWPPP removed for home const See SWPPP s removed in preparation Springfield Trail g wattles have been mult SB 4 Stub Road aned the street and remo	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc Il monitor for installation of fence prior to the 4/27/20 ruction prior to the 10/26/2 for active construction pri ched or removed as of the	bection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed inspection. Removed 21 inspection. See Lot Removed or to the 5/18/20 inspect Removed 4/9/21 inspection. Removed	y riser. Commercial ion. Commercial see o the inspection on in the basin was rem BMPs for further ction.
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence was Silt fence Removed - Silt fence was Silt fence Removed - The remainin Straw Wattle Removed - Tim Geis clear necessary.	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector wi See SWPPP Seeding removed the silt See SWPPP removed for home const See SWPPP s removed in preparation Springfield Trail g wattles have been mult SB 4 Stub Road aned the street and remo	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc Il monitor for installation of fence prior to the 4/27/20 ruction prior to the 10/26/2 for active construction pri ched or removed as of the ved the wattle prior to the	vection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed inspection. Removed 21 inspection. See Lot Removed d/9/21 inspection. Removed 4/9/21 inspection. Removed 7/15/20 inspection, reir	y riser. Commercial ion. Commercial seed of the inspection on in the basin was rem BMPs for further ction.
Current Condition: SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition: W1 Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence was Silt fence Removed - Silt fence was Silt fence Removed - The remainin Straw Wattle Removed - Tim Geis clea necessary. Streets	ed - The basin was insta est dewatering hole and h rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector will See SWPPP Seeding removed the silt See SWPPP removed for home constant See SWPPP s removed in preparation Springfield Trail g wattles have been mult SB 4 Stub Road aned the street and remo	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc il monitor for installation of fence prior to the 4/27/20 for active construction prior ched or removed as of the ved the wattle prior to the 1/3/2020	Active	y riser. Commercial ion. Commercial see o the inspection on in the basin was rem BMPs for further ction.
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence was Silt fence Removed - Silt fence was Silt fence Removed - The remainin Straw Wattle Removed - Tim Geis clea necessary. Streets	ed - The basin was insta est dewatering hole and h rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector wil See SWPPP Seeding removed the silt See SWPPP removed for home const See SWPPP s removed in preparation Springfield Trail g wattles have been mult SB 4 Stub Road aned the street and remo Internal/S 132nd and Main Street were clean and free of to	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc Il monitor for installation of fence prior to the 4/27/20 ruction prior to the 10/26/2 for active construction pri ched or removed as of the ved the wattle prior to the	Active	y riser. Commercial ion. Commercial see o the inspection on in the basin was rem BMPs for further ction.
Current Condition: SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition: STR Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence wat Silt fence Removed - Silt fence wat Silt fence Removed - The remainin Straw Wattle Removed - Tim Geis clea necessary. Streets Good Condition - Streets	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar mendation of maintenan- ection. E&A inspector wi See SWPPP Seeding removed the silt See SWPPP removed for home const See SWPPP s removed in preparation Springfield Trail g wattles have been mult SB 4 Stub Road aned the street and remo Internal/S 132nd and Main Street were clean and free of tt S 132nd Street and	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc I monitor for installation of fence prior to the 4/27/20 for active construction prior ched or removed as of the ched or removed as of the 1/3/2020 rack out during the 11/9/22	ection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed anspection. Removed Prior to the 5/18/20 inspect Removed 4/9/21 inspection. Removed 4/9/21 inspection. Removed 7/15/20 inspection, reir Active 2 inspection.	y riser. Commercial ion. Commercial seed of the inspection on in the basin was rem BMPs for further BMPs for further ction.
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition: STR Current Condition: STR Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence wat Silt fence Removed - The remainin Straw Wattle Removed - The remainin Straw Wattle Removed - Tim Geis clea necessary. Streets Good Condition - Streets Misc/Other	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector wi See SWPPP Seeding removed the silt See SWPPP removed for home const See SWPPP s removed for home const See SWPPP s removed in preparation Springfield Trail g wattles have been mult SB 4 Stub Road aned the street and remo Internal/S 132nd and Main Street were clean and free of tr S 132nd Street and Man Street	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc I monitor for installation of fence prior to the 4/27/20 for active construction pri ched or removed as of the 1/3/2020 fack out during the 11/9/22 1/27/2020	Active	y riser. Commercial see o the inspection on in the basin was rem BMPs for further ction.
Current Condition: SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition: STR Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence wat Silt fence Removed - The remainin Straw Wattle Removed - The remainin Straw Wattle Removed - Tim Geis clea necessary. Streets Good Condition - Streets Misc/Other Good Condition - E&A in:	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector wi See SWPPP Seeding removed the silt See SWPPP removed for home const See SWPPP s removed for home const See SWPPP s removed in preparation Springfield Trail g wattles have been mult SB 4 Stub Road aned the street and remo Internal/S 132nd and Main Street were clean and free of tr S 132nd Street and Man Street spector installed SWPPP	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc I monitor for installation of fence prior to the 4/27/20 fruction prior to the 10/26/3 for active construction pri ched or removed as of the 1/3/2020 ack out during the 11/9/22 1/27/2020 signs at the intersection of	Active	y riser. Commercial see o the inspection on in the basin was rem BMPs for further ction.
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition: STR Current Condition: STR Current Condition: SWPPP Signs Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence wat Silt fence Removed - The remainin Straw Wattle Removed - The remainin Straw Wattle Removed - Tim Geis clea necessary. Streets Good Condition - Streets Misc/Other Good Condition - E&A in Street and Hazel Lane du	ed - The basin was insta est dewatering hole and I rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector wi See SWPPP Seeding removed the silt See SWPPP removed for home const See SWPPP s removed for home const See SWPPP s removed in preparation Springfield Trail g wattles have been mult SB 4 Stub Road aned the street and remo Internal/S 132nd and Main Street were clean and free of th S 132nd Street and Man Street spector installed SWPPP uring the 1/27/20 inspecti	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc I monitor for installation of fence prior to the 4/27/20 for active construction pri ched or removed as of the 1/3/2020 rack out during the 11/9/22 1/27/2020 signs at the intersection of on.	bection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed inspection. Removed 21 inspection. See Lot Removed or to the 5/18/20 inspect Removed 4/9/21 inspection. Removed 4/9/21 inspection. Removed 7/15/20 inspection, reir Active inspection. Active of Main Street and N 10	y riser. Commercial see o the inspection on in the basin was rem BMPs for further ction.
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition: STR Current Condition: STR Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence wat Silt fence Removed - The remainin Straw Wattle Removed - The remainin Straw Wattle Removed - The remainin Straw Wattle Removed - Tim Geis clea necessary. Streets Good Condition - Streets Misc/Other Good Condition - E&A in: Street and Hazel Lane du	ed - The basin was insta est dewatering hole and I rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector wi See SWPPP Seeding removed the silt See SWPPP removed for home const See SWPPP s removed for home const See SWPPP s removed in preparation Springfield Trail g wattles have been mult SB 4 Stub Road aned the street and remo Internal/S 132nd and Main Street were clean and free of tr S 132nd Street and Man Street spector installed SWPPP uring the 1/27/20 inspecti f law, that this document	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc l monitor for installation of fence prior to the 4/27/20 truction prior to the 10/26/3 for active construction pri ched or removed as of the 1/3/2020 rack out during the 11/9/22 1/27/2020 signs at the intersection of on.	bection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed inspection. Removed 21 inspection. See Lot Removed or to the 5/18/20 inspect Removed 4/9/21 inspection. Removed 4/9/21 inspection. Removed 7/15/20 inspection, reir Active inspection. Active of Main Street and N 10 prepared under my	y riser. Commercial see o the inspection on in the basin was rem BMPs for further ction.
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition: STR Current Condition: STR Current Condition: SWPPP Signs Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence was Silt fence Removed - Silt fence was Silt fence Removed - The remainin Straw Wattle Removed - The remainin Straw Wattle Good Condition - E&A in: Streets and Hazel Lane du "I certify, under penalty o direction or supervision in	ed - The basin was insta est dewatering hole and h rosion at the inlet pipe ar imendation of maintenam- ection. E&A inspector wil See SWPPP Seeding removed the silt See SWPPP removed for home const See SWPPP sermoved for home const See SWPPP sermoved in preparation Springfield Trail g wattles have been mult SB 4 Stub Road aned the street and remo Internal/S 132nd and Main Street were clean and free of tr S 132nd Street and Man Street spector installed SWPPP uring the 1/27/20 inspecti f law, that this document n accordance with a syste	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc il monitor for installation of fence prior to the 4/27/20 for active construction prior to the 10/26/2 for active construction prior ched or removed as of the 1/3/2020 ack out during the 11/9/22 1/27/2020 ' signs at the intersection of on. and all attachments were	bection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed inspection. Removed 21 inspection. See Lot Removed 21 inspection. See Lot Removed 4/9/21 inspection. Removed 4/9/21 inspection. Removed 7/15/20 inspection, reir Active 2 inspection. Active 2 f Main Street and N 10 prepared under my t qualified personnel	y riser. Commercial see o the inspection on in the basin was rem BMPs for further ction.
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition: STR Current Condition: STR Current Condition: SWPPP Signs Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence was Silt fence Removed - Silt fence was Silt fence Removed - The remainin Straw Wattle Removed - The remainin Straw Wattle Good Condition - E&A in: Streets and Hazel Lane du "I certify, under penalty o direction or supervision in	ed - The basin was insta est dewatering hole and h rosion at the inlet pipe ar imendation of maintenam- ection. E&A inspector wil See SWPPP Seeding removed the silt See SWPPP removed for home const See SWPPP sermoved for home const See SWPPP sermoved in preparation Springfield Trail g wattles have been mult SB 4 Stub Road aned the street and remo Internal/S 132nd and Main Street were clean and free of tr S 132nd Street and Man Street spector installed SWPPP uring the 1/27/20 inspecti f law, that this document n accordance with a syste	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc l monitor for installation of fence prior to the 4/27/20 truction prior to the 10/26/3 for active construction pri ched or removed as of the 1/3/2020 rack out during the 11/9/22 1/27/2020 signs at the intersection of on.	bection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed inspection. Removed 21 inspection. See Lot Removed 21 inspection. See Lot Removed 4/9/21 inspection. Removed 4/9/21 inspection. Removed 7/15/20 inspection, reir Active 2 inspection. Active 2 f Main Street and N 10 prepared under my t qualified personnel	y riser. Commercial see o the inspection on in the basin was rem BMPs for further ction.
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition: STR Current Condition: STR Current Condition: SWPPP Signs Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence was Silt fence Removed - Silt fence was Silt fence Removed - The remainin Straw Wattle Removed - Tim Geis clea necessary. Streets Good Condition - Streets Misc/Other Good Condition - E&A in: Street and Hazel Lane du "I certify, under penalty o direction or supervision in properly gathered and ew persons who manage the	ed - The basin was insta est dewatering hole and h rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector will See SWPPP Seeding removed the silt See SWPPP removed for home const see SWPPP s removed in preparation Springfield Trail g wattles have been mult SB 4 Stub Road aned the street and remo Internal/S 132nd and Main Street were clean and free of th S 132nd Street and Man Street spector installed SWPPP uring the 1/27/20 inspecti f law, that this document n accordance with a syste auluated the information s	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc ill monitor for installation of fence prior to the 4/27/20 for active construction prior to the 10/26/3 for active construction prior ched or removed as of the 1/3/2020 rack out during the 11/9/22 1/27/2020 rsigns at the intersection of on. and all attachments were em designed to assure tha ubmitted. Based on my in s directly responsible for g	ection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed an analysis and the study of the sector Removed at inspection. See Lot Removed at inspection. See Lot Removed at inspection. Removed at to the 5/18/20 inspect rot to the 5/18/20 inspect and the sector Removed at sector. Removed at sec	y riser. Commercial seed o the inspection on in the basin was rem BMPs for further ction. nstallation is not No No No No No
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition: STR Current Condition: STR Current Condition: SWPPP Signs Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence was Silt fence Removed - Silt fence was Silt fence Removed - The remainin Straw Wattle Removed - Tim Geis clea necessary. Streets Good Condition - Streets Misc/Other Good Condition - E&A in: Street and Hazel Lane du "I certify, under penalty o direction or supervision in properly gathered and ew persons who manage the	ed - The basin was insta est dewatering hole and h rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector will See SWPPP Seeding removed the silt See SWPPP removed for home const see SWPPP s removed in preparation Springfield Trail g wattles have been mult SB 4 Stub Road aned the street and remo Internal/S 132nd and Main Street were clean and free of th S 132nd Street and Man Street spector installed SWPPP uring the 1/27/20 inspecti f law, that this document n accordance with a syste auluated the information s	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc il monitor for installation of fence prior to the 4/27/20 for active construction prior to the 10/26/2 for active construction prior ched or removed as of the 1/3/2020 ack out during the 11/9/22 1/27/2020 signs at the intersection of on. and all attachments were erm designed to assure tha ubmitted. Based on my in	ection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed an analysis and the study of the sector Removed at inspection. See Lot Removed at inspection. See Lot Removed at inspection. Removed at to the 5/18/20 inspect rot to the 5/18/20 inspect and the sector Removed at sector. Removed at sec	y riser. Commercial seed o the inspection on in the basin was rem BMPs for further ction. nstallation is not No No No No No
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition: STR Current Condition: STR Current Condition: SWPPP Signs Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence was Silt fence Removed - Silt fence was Silt fence Removed - The remainin Straw Wattle Removed - Tim Geis clea necessary. Streets Good Condition - Streets Misc/Other Good Condition - E&A in Street and Hazel Lane du "I certify, under penalty o direction or supervision in properly gathered and ev persons who manage the the information submitted	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar imendation of maintenan- ection. E&A inspector wil See SWPPP Seeding removed the silt See SWPPP removed for home const see SWPPP s removed in preparation Springfield Trail g wattles have been mult SB 4 Stub Road aned the street and remo Internal/S 132nd and Main Street were clean and free of th S 132nd Street and Man Street spector installed SWPPP uring the 1/27/20 inspecti f law, that this document n accordance with a syste aluated the information s	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc ill monitor for installation of fence prior to the 4/27/20 for active construction prior to the 10/26/3 for active construction prior ched or removed as of the 1/3/2020 rack out during the 11/9/22 1/27/2020 rsigns at the intersection of on. and all attachments were em designed to assure tha ubmitted. Based on my in s directly responsible for g	ection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed an appection. Removed at inspection. See Lot Removed at inspection. See Lot Removed at inspection. Removed at 5/18/20 inspect ro to the 5/18/20 inspect Removed at proved at pr	y riser. Commercial see o the inspection on in the basin was ren BMPs for further ction. nstallation is not No Dth Ave and S 132nd
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition: STR Current Condition: STR Current Condition: SWPPP Signs Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence was Silt fence Removed - Silt fence was Silt fence Removed - The remainin Straw Wattle Removed - Tim Geis clea necessary. Streets Good Condition - Streets Misc/Other Good Condition - E&A in Street and Hazel Lane du "I certify, under penalty o direction or supervision in properly gathered and ev persons who manage the the information submitted	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar mendation of maintenan- ection. E&A inspector wi See SWPPP Seeding removed the silt See SWPPP removed for home const see SWPPP removed for home const see SWPPP s removed in preparation Springfield Trail g wattles have been muld SB 4 Stub Road aned the street and remo Internal/S 132nd and Main Street were clean and free of tr S 132nd Street and Man Street spector installed SWPPP uring the 1/27/20 inspecti f law, that this document n accordance with a syste aluated the information s e system or those persons d is, to the best of my kno significant penalties for su	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc I monitor for installation of fence prior to the 4/27/20 for active construction pri ched or removed as of the 1/3/2020 rack out during the 11/9/22 1/27/2020 'signs at the intersection of on. and all attachments were em designed to assure tha ubmitted. Based on my in s directly responsible for g wiledge and belief, true, ar ubmitting false information	ection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed an appection. Removed at inspection. See Lot Removed at inspection. See Lot Removed at inspection. Removed at 5/18/20 inspect ro to the 5/18/20 inspect Removed at proved at pr	y riser. Commercial seed o the inspection on in the basin was rem BMPs for further Ction. Installation is not No Dth Ave and S 132nd
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition: STR Current Condition: STR Current Condition: SWPPP Signs Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence wat Silt fence Removed - Silt fence wat Silt fence Removed - Silt fence wat Silt fence Removed - The remainin Straw Wattle Removed - The remainin Straw Wattle Removed - Tim Geis clea necessary. Streets Good Condition - Streets Misc/Other Good Condition - E&A in: Street and Hazel Lane du "I certify, under penalty o direction or supervision in properly gathered and ev persons who manage the the information submitted am aware that there are	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar mendation of maintenan- ection. E&A inspector wi See SWPPP Seeding removed the silt See SWPPP removed for home const see SWPPP removed for home const see SWPPP s removed in preparation Springfield Trail g wattles have been muld SB 4 Stub Road aned the street and remo Internal/S 132nd and Main Street were clean and free of tr S 132nd Street and Man Street spector installed SWPPP uring the 1/27/20 inspecti f law, that this document n accordance with a syste aluated the information s e system or those persons d is, to the best of my kno significant penalties for su	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc I monitor for installation of fence prior to the 4/27/20 for active construction pri ched or removed as of the 1/3/2020 rack out during the 11/9/22 1/27/2020 'signs at the intersection of on. and all attachments were em designed to assure tha ubmitted. Based on my in s directly responsible for g wiledge and belief, true, ar ubmitting false information	ection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed an appection. Removed at inspection. See Lot Removed at inspection. See Lot Removed at inspection. Removed at 5/18/20 inspect ro to the 5/18/20 inspect Removed at proved at pr	y riser. Commercial seed o the inspection on in the basin was rem BMPs for further Ction. Installation is not No Dth Ave and S 132nd
SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: W1 Current Condition: STR Current Condition: STR Current Condition: SWPPP Signs Current Condition:	Good Condition - 30% fill Seeding plugged the low seeded and matted the e 5/11/20. All future recom prior to the 10/11/22 insp Silt fence Removed - Commercial S Silt fence Removed - Wattles were recommendations. Silt fence Removed - Silt fence wat Silt fence Removed - Silt fence wat Silt fence Removed - Silt fence wat Silt fence Removed - The remainin Straw Wattle Removed - The remainin Straw Wattle Removed - Tim Geis clea necessary. Streets Good Condition - Streets Misc/Other Good Condition - E&A in: Street and Hazel Lane du "I certify, under penalty o direction or supervision in properly gathered and ev persons who manage the the information submitted am aware that there are	ed - The basin was insta est dewatering hole and l rosion at the inlet pipe ar mendation of maintenan- ection. E&A inspector wi See SWPPP Seeding removed the silt See SWPPP removed for home const see SWPPP removed for home const see SWPPP s removed in preparation Springfield Trail g wattles have been muld SB 4 Stub Road aned the street and remo Internal/S 132nd and Main Street were clean and free of tr S 132nd Street and Man Street spector installed SWPPP uring the 1/27/20 inspecti f law, that this document n accordance with a syste aluated the information s e system or those persons d is, to the best of my kno significant penalties for su	led prior to the 1/3/20 insp packfilled the erosion prior ad installed a straw wattle ce for the wattle will be inc I monitor for installation of fence prior to the 4/27/20 for active construction pri ched or removed as of the 1/3/2020 rack out during the 11/9/22 1/27/2020 'signs at the intersection of on. and all attachments were em designed to assure tha ubmitted. Based on my in s directly responsible for g wiledge and belief, true, ar ubmitting false information	ection with a temporar to the 4/27/20 inspecti at the stub road prior to luded with SB 4. Riser permanent riser. Removed an appection. Removed at inspection. See Lot Removed at inspection. See Lot Removed at inspection. Removed at 5/18/20 inspect ro to the 5/18/20 inspect Removed at proved at pr	y riser. Commercial seed o the inspection on in the basin was rem BMPs for further Ction. Installation is not No Dth Ave and S 132nd