E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



N/A

Comments:

Zachary A. Jilek, CPESC, CISEC **Engineering Answers** Environmental Services Dept. Manager E&A - P2019.327.000 Inspector: Shaun McGuire Stage **Springfield Pines** 1 CSW-201600337 Project Name: 4/29/2023 68059 For Week Ending: Project Location: SW of 132nd Street and Platteview Road, Springfield, NE Phase I Grading: 100% Sanitary Sewer: 100% Storm Sewer: 100% Paving: 100% Seeding: 75% **Utilities:** 100% Overall Development: 70% Amount in tenths RAIN FALL AMOUNTS Date inspected Weather Conditions Time Week 1 Sunday: 0.00" Monday: 0.00" Tuesday: 0.00" Wednesday: 0.00" 4/26/2023 Sunny 66/42 1:45 PM Thursday: 0.00" Friday: 0.08" Saturday: 0.00" Complaints: None Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Grading in Phase I was completed prior to E&A being hired to conduct SWPPP inspections (1/3/20). ed in the next 14 days? Grading in Phase I was completed prior to E&A being hired to conduct SWPPP inspections (1/3/20). Site was seeded prior to E&A being hired to conduct SWPPP inspections (1/3/20). Portion of ground to the southeast of SB 4 seeded and matted (5/11/20). Checklist Questions: re receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes reate Corrective Action? N/A lave disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion. Create Corrective Action?
No, see Findings section No, see BMPs section and Findings section Yes N/A ed with the construction activity adequately controlled on the site? Yes

Comments: Site was active for homebuilding during the most recent inspection.

The School Site was graded prior to the 9/23/20 inspection. The School Site is not covered by the Springfield Pines permit (SPR-20200728-5543-GP1).

Findings / Corrective Actions (Date)

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section of this report.
- 2) Vacant-disturbed lots need to be stabilized.

A. Overgraded lots during homebuilding construction need to be stabilized. All builders were informed to complete by 1/17/20 when weather allows and asneeded. Not done as of the last inspection. All builders were reminded on 9/24/20, 6/24/21. As of the 3/1/2023 inspection there are no longer any overgraded inactive lots. Inactive lots still need stabilization.

3) Concrete waste was located throughout the development. D.R. Horton was informed to clean up concrete waste in SB 4 on 3/3/22. Not done as of last inspection. D.R. Horton was reminded on 3/24/22, 5/24/22, 6/2/22, 6/17/22, 6/23/22, 8/19/22, 8/31/22, 11/11/22, 3/1/23. D.R. Horton was informed to clean up concrete waste on lot 72 on 8/31/22. Not done as of last inspection. D.R. Horton was reminded on 11/11/22, 3/1/23, 4/21/23

Unique Name	Type	Location	Projected Install Date	Status	Maintenance	
Al 1	Area Inlet Protection	See SWPPP	1/3/2020	Active	No	
Current Condition:	Active - Area inlet was installed prior to the 1/3/20 inspection. The surrounding area is vegetated and the inlet drains to SB 1; r inlet protection will be recommended at this time.					
Al 2	Area Inlet Protection	See SWPPP	1/3/2020	Active	Yes	
Current Condition:			stalled prior to the 1/3/20 insp			
			ction will be recommended at			
			talled 3 additional inlets and a	the state of the s	prior to the 11/922	
	inspection. Orban Spark c	leaned out the inlet prot	ection prior to the 11/9/22 insp	pection.		
	Inlet protection should be					
	Inlet protection should be cleaned out.					
	D.R. Horton was informed	to complete by 4/26/23	. Not done as of last inspect	ion.		
Al 3	Area Inlet Protection	See SWPPP	3/9/2020	Active	No	
Current Condition:	Active - Area inlet with dor	me grate was installed p	prior to the 3/9/20 inspections.	Commercial Seeding	removed the remaining s	
	fence/T-posts around the					
Al 4	Area Inlet Protection	See SWPPP	3/9/2020	Active	No	
Current Condition:			prior to the 3/9/20 inspection.	The surrounding area	was seeded and matted a	
			recommended at this time.			
CW 1	Concrete Washout	Lot 81 Replat 1		Removed	L	
Current Condition:			alled on Lot 81 Replat 1 prior to			
	·	•	11/20, the berm recommenda	•		
			e 6/1/20 inspection. Gene Gra			
			oncrete washout from Lot 81 R			
		· ·	prior to the 7/7/21 inspection. C monitor for reinstallation. D.R		·	
			vas removed by D.R. Horton p			
	· ·		the 5/10/22 inspection. D.R. H		•	
		•	oncrete washout prior to the 1		•	
	for reinstallation.			, .		
IP 1	Inlet Protection	See SWPPP		Removed		
Current Condition:	Removed - Commercial S	eeding removed the inle	et filter prior to the 4/27/20 insp	pection. Inlet drains to	a basin, reinstallation is	
UD 0	not recommended.	0 0111000	1			
IP 2 Current Condition:	Inlet Protection	See SWPPP	Let filter prior to the 4/27/20 insp	Removed	a basis reinstallation is	
Current Condition.		•	et filter prior to the 6/21/22 ins			
			reinstallation is not recommen		emoved the inlet litter pric	
IP 3	·	See SWPPP	Terristanduorris not recommen			
Current Condition:	Inlet Protection		Let filter prior to the 4/27/20 insp	Removed	a hasin reinstallation is	
Current Condition.	not recommended.	eeding removed the line	et litter prior to the 4/21/20 ms	bection. Tillet dialits to	o a basiii, reilistallatioii is	
IP 4	Inlet Protection	See SWPPP	1	Removed		
Current Condition:			et filter prior to the 4/27/20 ins		n a hasin reinstallation is	
ourront condition.		•	ter protection prior to the 5/31.	•		
			asin, reinstallation is not recor			
IP 5	Inlet Protection	See SWPPP	1	Removed		
Current Condition:			et filter prior to the 4/27/20 insp		a basin, reinstallation is	
			ter protection prior to the 5/3/2			
			asin, reinstallation is not reco	•		
IP 6	Inlet Protection	See SWPPP		Removed		
Current Condition:	Removed - Commercial S	eeding removed the inle	et filter prior to the 4/27/20 insp	pection. Inlet drains to	a basin, reinstallation is	
			ter protection prior to the 8/30		lorton removed the inlet fil	
	prior to the 12/21/22 inspe	ction. Inlet drains to a b	asin, reinstallation is not recor	mmended.		
IP 7	Inlet Protection	See SWPPP		Removed		
Current Condition:		eeding removed the inle	et filter prior to the 4/27/20 insp	pection. Inlet drains to	a basin, reinstallation is	
	not recommended.			•		
IP 8	Inlet Protection	See SWPPP		Removed		
Current Condition:		•	et filter prior to the 4/27/20 insp			
			ter protection prior to the 8/30	•	lorton removed the inlet fil	
	prior to the 12/21/22 inspe		asin, reinstallation is not recor	mmended.		
ID O	Inlet Protection	See SWPPP		Removed		
IP 9						
Current Condition:			et filter prior to the 4/27/20 ins		a basin, reinstallation is	

IP 10	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is no
	recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton cleaned out the inlet filter
	prior to the 6/7/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton removed the inlet
	filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.
IP 11	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is no
	recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton repaired the inlet filter prior
	to the 4/5/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 6/28/22 inspection. D.R. Horton removed the inlet filter
	prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.
IP 12	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is
	not recommended.
IP 13	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is
	not recommended.
IP 14	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is
	not recommended.
IP 15	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is
	not recommended.
IP 16	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is
	not recommended.
IP 17	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is
	not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet
	filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin,
15.40	reinstallation is not recommended.
IP 18	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 5/11/20 inspection. Inlet drains to a basin, reinstallation is
	not recommended. D.R. Horton reinstalled inlet filter protection prior to the 5/3/22 inspection. D.R. Horton cleaned out the inlet
	filter prior to the 7/12/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 8/23/22 inspection. D.R. Horton removed
	the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.
IP 19	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is
Current Condition.	not recommended.
IP 20	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is
	not recommended.
IP 21	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is
	not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet
	filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin,
	reinstallation is not recommended.
IP 22	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is
	not recommended.
IP 23	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is
	not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter
10.04	prior to the 7/26/22 inspection.
IP 24	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter
	· · · · · · · · · · · · · · · · · · ·
ID OF	prior to the 7/26/22 inspection.
IP 25 Current Condition:	Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is
Current Condition.	not recommended. D.R. Horton removed the inlet filter prior to the 5/31/22 inspection.
IP 26	Inlet Protection See SWPPP 3/29/2022 Active Yes
Current Condition:	Fair Condition - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation
	is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton cleaned out the inle
	filter prior to the 8/16/22 inspection.
	Inlet filter should be removed.
	D.P. Horton was informed to complete by 11/16/22. Not done as of lost inspecting. D.P. Horton was privated as 2/4/22. Horton
	D.R. Horton was informed to complete by 11/16/22. Not done as of last inspection. D.R. Horton was reminded on 3/1/23, 4/21/23
IP 27	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is
our on condition.	not recommended.
IP 28	Inlet Protection See SWPPP Removed

the state of the s	Removed - Commercial Se	eding removed the inle	t filter prior to the 4/27/20 insp	ection. Inlet drains to	a basin, reinstallation is
Let 1 Deplet 1	not recommended.	Let 1 Deplet 1		Damayad	
Lot 1 Replat 1 Current Condition:	Individual Lot Removed - D.R. Horton so	Lot 1 Replat 1	4/12/22 inspection	Removed	
Lot 4 Replat 3	Individual Lot	Lot 4 Replat 3	4/ 12/22 inspection.	Removed	
Current Condition:	Removed - D.R. Horton so		11/9/22 inspection.		
Lot 6 Replat 1	Individual Lot	Lot 6 Replat 1		Removed	
Current Condition:	Removed - D.R. Horton so		11/9/22 inspection.		
Lot 7 Replat 1 Current Condition:	Individual Lot Removed - Carlson Tile Ind	Lot 7 Replat 1	the 6/21/22 inspection	Removed	
Lot 10 Replat 1	Individual Lot	Lot 10 Replat 1	the 6/21/22 Inspection.	Removed	
Current Condition:	Removed - D.R. Horton so		4/19/22 inspection.	rtomovou	
Lot 11 Replat 1	Individual Lot	Lot 11 Replat 1		Removed	
Current Condition:	Removed - D.R. Horton so		4/19/22 inspection.		
Lot 13 Replat 1	Individual Lot	Lot 13 Replat 1	1/12/22	Removed	
Current Condition: Lot 19 Replat 1	Removed - D.R. Horton so Individual Lot	Lot 19 Replat 1	4/19/22 inspection.	Removed	
Current Condition:	Removed - Brooks Builders		the 5/10/22 inspection	Removed	
Lot 20 Replat 1	Individual Lot	Lot 20 Replat 1	and of total inopoducti.	Removed	
Current Condition:	Active - Sundown Homes L		to the 8/23/22 inspection.		
Lot 22 Replat 1	Individual Lot	Lot 22 Replat 1		Removed	
Current Condition:	Removed - Urban Spark so		e 5/17/22 inspection.		1
Lot 23 Replat 1 Current Condition:	Individual Lot Removed - D.R. Horton so	Lot 23 Replat 1	4/12/22 inspection	Removed	
Lot 28 Replat 1	Individual Lot	Lot 28 Replat 1	4/12/22 Inspection.	Removed	
Current Condition:	Removed - D.R. Horton so		4/12/22 inspection.	rtomovou	
Lot 30 Replat 1	Individual Lot	Lot 30 Replat 1	· Aprendam	Removed	
Current Condition:	Removed - D.R. Horton so		11/2/22 inspection.		
Lot 33 Replat 1	Individual Lot	Lot 33 Replat 1	E/47/00 : ''	Removed	
Current Condition: Lot 43 Replat 1	Removed - D.R. Horton so		5/17/22 inspection.	Domovod	
Current Condition:	Individual Lot Removed - D.R. Horton so	Lot 43 Replat 1	7/26/22 inspection	Removed	
Lot 45 Replat 1	Individual Lot	Lot 45 Replat 1	7720/22 inspection.	Removed	
Current Condition:			prior to the 4/26/23 inspecti		
Lot 46 Replat 1	Individual Lot	Lot 46 Replat 1		Removed	
Current Condition:			ior to the 5/17/22 inspection.		
Lot 48 Replat 1	Individual Lot	Lot 48 Replat 1	10/25/22 in an action	Removed	
Current Condition: Lot 49 Replat 1	Removed - D.R. Horton so Individual Lot	Lot 49 Replat 1	10/25/22 Inspection.	Removed	
Current Condition:	Removed - D.R. Horton so		10/11/22 inspection.	romoved	
Lot 51 Replat 1	Individual Lot	Lot 51 Replat 1		Removed	
Current Condition:	Removed - D.R. Horton so	dded the lot prior to the	10/11/22 inspection.		
Lot 55 Replat 1 Current Condition:	Individual Lot	Lot 55 Replat 1	5/11/2020	Active	Yes
	Fair Condition - Gene Graves installed silt fence on the side of the lot prior to the inspection on 5/11/20. Future silt fence maintenance will be sent to the builder of the lot when construction begins. Minor damage to the silt fence was observed during the 6/22/21 inspection, the inspector will monitor. D&E Custom Building began excavation on the lot prior to the 8/23/22 inspection. Dirt piles were observed in the ROW during the 8/23/22 inspection. D&E Custom Building removed the concrete waste and the dirt piles from the ROW prior to the 9/13/22 inspection. 1.) Silt fence perimeter should be installed. 2.) Wattles should be installed along the front of the lot.				
	waste and the dirt piles from 1.) Silt fence perimeter sho	n the ROW prior to the uld be installed. Iled along the front of th	9/13/22 inspection.	D&E Custom Building	
	waste and the dirt piles from 1.) Silt fence perimeter sho 2.) Wattles should be insta 3.) Streets should be clean 1.) Landmark Performance Performance Corporation vlast inspection. D&E Custo 2.) Landmark Performance Performance Corporation vlast inspection. D&E Custo	n the ROW prior to the uld be installed. Iled along the front of the ed. Corporation was inform vas reminded on 11/3/2 m Building was reminded Corporation was inform vas reminded on 11/3/2 m Building was reminded mas reminded was reminded mas reminded	9/13/22 inspection. The lot. The l	ot done as of last insp informed to complete ot done as of last insp informed to complete	pection. Landmark by 3/8/23. Not done as of pection. Landmark by 3/8/23. Not done as of
Lot 57 Replat 1	waste and the dirt piles from 1.) Silt fence perimeter sho 2.) Wattles should be insta 3.) Streets should be clean 1.) Landmark Performance Performance Corporation vlast inspection. D&E Custo 2.) Landmark Performance Performance Corporation vlast inspection. D&E Custo 3.) Landmark Performance Individual Lot	un the ROW prior to the uld be installed. Illed along the front of the ed. Corporation was inform vas reminded on 11/3/2 m Building was reminded corporation was inform vas reminded on 11/3/2 m Building was reminded Corporation was inform Lot 57 Replat 1	ned to complete by 8/30/22. N 2. D&E Custom Building was ad on 4/20/23. ned to complete by 8/30/22. N 2. D&E Custom Building was ad on 4/20/23. ned to complete by 4/20/23. N	ot done as of last insp informed to complete ot done as of last insp informed to complete	pection. Landmark by 3/8/23. Not done as of pection. Landmark by 3/8/23. Not done as of
Current Condition:	waste and the dirt piles from 1.) Silt fence perimeter sho 2.) Wattles should be insta 3.) Streets should be clean 1.) Landmark Performance Performance Corporation v last inspection. D&E Custo 2.) Landmark Performance Performance Corporation v last inspection. D&E Custo 3.) Landmark Performance Individual Lot Removed - Pacesetter Hor	un the ROW prior to the uld be installed. Illed along the front of the ed. Corporation was inform vas reminded on 11/3/2 m Building was reminded Corporation was inform vas reminded on 11/3/2 m Building was reminded Corporation was inform Lot 57 Replat 1 nes sodded the lot prior	ned to complete by 8/30/22. N 2. D&E Custom Building was ad on 4/20/23. ned to complete by 8/30/22. N 2. D&E Custom Building was ad on 4/20/23. ned to complete by 4/20/23. N	ot done as of last inspinformed to complete ot done as of last inspinformed to complete ot done as of last inspinformed to complete Removed	pection. Landmark by 3/8/23. Not done as of pection. Landmark by 3/8/23. Not done as of
Current Condition: Lot 59 Replat 1	waste and the dirt piles from 1.) Silt fence perimeter sho 2.) Wattles should be insta 3.) Streets should be clean 1.) Landmark Performance Performance Corporation vlast inspection. D&E Custo 2.) Landmark Performance Performance Corporation vlast inspection. D&E Custo 3.) Landmark Performance Individual Lot Removed - Pacesetter Hore Individual Lot	uld be installed. Illed along the front of the ed. Corporation was inform vas reminded on 11/3/2 m Building was reminded Corporation was inform vas reminded on 11/3/2 m Building was reminded on 11/3/2 m Building was reminded corporation was inform Lot 57 Replat 1 nes sodded the lot prior Lot 59 Replat 1	ned to complete by 8/30/22. N 2. D&E Custom Building was ed on 4/20/23. ned to complete by 8/30/22. N 2. D&E Custom Building was ed on 4/20/23. ned to complete by 4/20/23. N 2. to the 7/12/22 inspection.	ot done as of last insp informed to complete ot done as of last insp informed to complete ot done as of last in	pection. Landmark by 3/8/23. Not done as of pection. Landmark by 3/8/23. Not done as of
Current Condition: Lot 59 Replat 1 Current Condition:	waste and the dirt piles from 1.) Silt fence perimeter sho 2.) Wattles should be insta 3.) Streets should be clean 1.) Landmark Performance Performance Corporation values inspection. D&E Custo 2.) Landmark Performance Performance Corporation values inspection. D&E Custo 3.) Landmark Performance Individual Lot Removed - Pacesetter Horn Individual Lot Removed - Nelson Builders	uld be installed. Illed along the front of the ed. Corporation was inform was reminded on 11/3/2 m Building was reminded Corporation was inform was reminded on 11/3/2 m Building was reminded Corporation was inform Lot 57 Replat 1 mes sodded the lot prior Lot 59 Replat 1 s sodded the lot prior to	ned to complete by 8/30/22. N 2. D&E Custom Building was ad on 4/20/23. Ned to complete by 8/30/22. N 2. D&E Custom Building was ad on 4/20/23. Ned to complete by 8/30/22. Ned to complete by 4/20/23. Ned to complete by 4/20/23. Ned to the 7/12/22 inspection.	ot done as of last inspiniformed to complete ot done as of last inspiniformed to complete ot done as of last in Removed	pection. Landmark by 3/8/23. Not done as of pection. Landmark by 3/8/23. Not done as of spection.
Current Condition: Lot 59 Replat 1 Current Condition: Lot 63 Replat 1	waste and the dirt piles from 1.) Silt fence perimeter sho 2.) Wattles should be insta 3.) Streets should be clean 1.) Landmark Performance Performance Corporation volume inspection. D&E Custo 2.) Landmark Performance Performance Corporation volume inspection. D&E Custo 3.) Landmark Performance Individual Lot Removed - Pacesetter Hore Individual Lot Removed - Nelson Builders Individual Lot	un the ROW prior to the uld be installed. Corporation was information was reminded on 11/3/2 m Building was reminded Corporation was information was information was information was reminded on 11/3/2 m Building was reminded Corporation was information w	ned to complete by 8/30/22. N 2. D&E Custom Building was ad on 4/20/23. ned to complete by 8/30/22. N 2. D&E Custom Building was ad on 4/20/23. ned to complete by 4/20/23. Note to the 7/12/22 inspection. the 6/21/22 inspection. 4/26/2022	ot done as of last inspinformed to complete of done as of last inspinformed to complete of done as of last inspin Removed Removed Pending	pection. Landmark by 3/8/23. Not done as of by 3/8/23. Not done as of by 3/8/23. Not done as of spection.
Current Condition: Lot 59 Replat 1 Current Condition:	waste and the dirt piles from 1.) Silt fence perimeter sho 2.) Wattles should be insta 3.) Streets should be clean 1.) Landmark Performance Performance Corporation volume inspection. D&E Custo 2.) Landmark Performance Performance Corporation volume inspection. D&E Custo 3.) Landmark Performance Individual Lot Removed - Pacesetter Hore Individual Lot Removed - Nelson Builders Individual Lot Pending - Urban Spark beg 4/26/22 inspection. Urban Silt fence should be installed Urban Spark was informed	un the ROW prior to the uld be installed. Corporation was information was reminded on 11/3/2 m Building was reminded Corporation was inform Lot 57 Replat 1 nes sodded the lot prior Lot 59 Replat 1 sodded the lot prior to Lot 63 Replat 1 pan excavation of the lot park removed the dirt and on the sides, rear, are to complete by 5/3/22.	ned to complete by 8/30/22. N 2. D&E Custom Building was ad on 4/20/23. Ned to complete by 8/30/22. N 2. D&E Custom Building was ad on 4/20/23. Ned to complete by 8/30/22. Ned to complete by 4/20/23. Ned to complete by 4/20/23. Ned to the 7/12/22 inspection.	ot done as of last inspinformed to complete ot done as of last inspinformed to complete ot done as of last inspinformed to complete ot done as of last inspection. Removed Pending Ditt pile was notice to 5/17/22 inspection. The lot should be so	pection. Landmark by 3/8/23. Not done as of pection. Landmark by 3/8/23. Not done as of spection. Yes d in the ROW during the
Current Condition: Lot 59 Replat 1 Current Condition: Lot 63 Replat 1 Current Condition:	waste and the dirt piles from 1.) Silt fence perimeter sho 2.) Wattles should be insta 3.) Streets should be clean 1.) Landmark Performance Performance Corporation v last inspection. D&E Custo 2.) Landmark Performance Performance Corporation v last inspection. D&E Custo 3.) Landmark Performance Individual Lot Removed - Pacesetter Hor Individual Lot Removed - Nelson Builders Individual Lot Pending - Urban Spark beg 4/26/22 inspection. Urban S Silt fence should be installed	un the ROW prior to the uld be installed. Corporation was information was reminded on 11/3/2 m Building was reminded Corporation was inform Lot 57 Replat 1 nes sodded the lot prior Lot 59 Replat 1 sodded the lot prior to Lot 63 Replat 1 pan excavation of the lot park removed the dirt and on the sides, rear, are to complete by 5/3/22.	9/13/22 inspection. ned to complete by 8/30/22. N 2. D&E Custom Building was ed on 4/20/23. ned to complete by 8/30/22. N 2. D&E Custom Building was ed on 4/20/23. ned to complete by 4/20/23. N into the 7/12/22 inspection. 4/26/2022 t prior to the 4/26/22 inspectio pile from the ROW prior to the ad southeast corner of the lot of	ot done as of last inspinformed to complete ot done as of last inspinformed to complete ot done as of last inspinformed to complete ot done as of last inspection. Removed Pending Ditt pile was notice to 5/17/22 inspection. The lot should be so	pection. Landmark by 3/8/23. Not done as of pection. Landmark by 3/8/23. Not done as of spection. Yes d in the ROW during the
Current Condition: Lot 59 Replat 1 Current Condition: Lot 63 Replat 1	waste and the dirt piles from 1.) Silt fence perimeter sho 2.) Wattles should be insta 3.) Streets should be clean 1.) Landmark Performance Performance Corporation vlast inspection. D&E Custo 2.) Landmark Performance Performance Corporation vlast inspection. D&E Custo 3.) Landmark Performance Individual Lot Removed - Pacesetter Hon Individual Lot Removed - Nelson Builders Individual Lot Pending - Urban Spark beg 4/26/22 inspection. Urban S Silt fence should be installed Urban Spark was informed 8/2/22, 11/3/22, 11/9/22, 3/	un the ROW prior to the uld be installed. Illed along the front of the ed. Corporation was inform was reminded on 11/3/2 m Building was reminded on 11/3/2 m Building was reminded corporation was inform Lot 57 Replat 1 nes sodded the lot prior Lot 59 Replat 1 sodded the lot prior to Lot 63 Replat 1 apan excavation of the lot fil	ned to complete by 8/30/22. No. 2. D&E Custom Building was ad on 4/20/23. No. 2. D&E Custom Building was ad on 4/20/23. No. 2. D&E Custom Building was ad on 4/20/23. No. 2. D&E Custom Building was ad on 4/20/23. No. 2. D&E Custom Building was ad on 4/20/23. No. 2. D&E Custom Building was ad on 4/20/23. No. 2. D&E Custom Building was ad on 4/20/23. No. 2. D&E Custom Building was ad on 4/20/22 inspection. 4/26/20/22 1 trior to the 4/26/22 inspection pile from the ROW prior to the ad southeast corner of the lot of the southeast corner of the southeast corne	ot done as of last inspinformed to complete of done as of last inspinformed to complete of done as of last inspection. Removed Removed Pending n. Dirt pile was notice of 1/17/22 inspection. For the lot should be so	pection. Landmark by 3/8/23. Not done as of pection. Landmark by 3/8/23. Not done as of spection. Yes d in the ROW during the
Current Condition: Lot 59 Replat 1 Current Condition: Lot 63 Replat 1 Current Condition: Lot 71 Replat 1 Current Condition: Lot 78 Replat 1	waste and the dirt piles from 1.) Silt fence perimeter sho 2.) Wattles should be insta 3.) Streets should be clean 1.) Landmark Performance Performance Corporation volume inspection. D&E Custo 2.) Landmark Performance Performance Corporation volume inspection. D&E Custo 3.) Landmark Performance Individual Lot Removed - Pacesetter Horn Individual Lot Removed - Nelson Builders Individual Lot Pending - Urban Spark beg 4/26/22 inspection. Urban S Silt fence should be installed Urban Spark was informed 8/2/22, 11/3/22, 11/9/22, 3/ Individual Lot Removed - D.R. Horton soon Individual Lot Removed - D.R. Horton soon Individual Lot	uld be installed. Illed along the front of the ed. Corporation was inform was reminded on 11/3/2 m Building was reminded Corporation was inform was reminded on 11/3/2 m Building was reminded on 11/3/2 m Building was reminded Corporation was inform Lot 57 Replat 1 mes sodded the lot prior Lot 59 Replat 1 sodded the lot prior to Lot 63 Replat 1 gan excavation of the lot Spark removed the dirt and on the sides, rear, are to complete by 5/3/22. 1/23, 4/20/23 Lot 71 Replat 1 didded the lot prior to the Lot 78 Replat 1	ned to complete by 8/30/22. N 2. D&E Custom Building was ed on 4/20/23. ned to complete by 8/30/22. N 2. D&E Custom Building was ed on 4/20/23. ned to complete by 8/30/22. N 2. D&E Custom Building was ed on 4/20/23. ned to complete by 4/20/23. N 2 to the 7/12/22 inspection. 4/26/2022 t prior to the 4/26/22 inspectio pile from the ROW prior to the nd southeast corner of the lot of Not done as of last inspection. 8/16/22 inspection.	ot done as of last inspinformed to complete of done as of last inspinformed to complete of done as of last inspection. Removed Removed Pending n. Dirt pile was notice of 1/17/22 inspection. For the lot should be so	pection. Landmark by 3/8/23. Not done as of pection. Landmark by 3/8/23. Not done as of spection. Yes d in the ROW during the
Current Condition: Lot 59 Replat 1 Current Condition: Lot 63 Replat 1 Current Condition: Lot 71 Replat 1 Current Condition:	waste and the dirt piles from 1.) Silt fence perimeter sho 2.) Wattles should be insta 3.) Streets should be clean 1.) Landmark Performance Performance Corporation vlast inspection. D&E Custo 2.) Landmark Performance Performance Corporation vlast inspection. D&E Custo 3.) Landmark Performance Individual Lot Removed - Pacesetter Hore Individual Lot Removed - Nelson Builders Individual Lot Pending - Urban Spark beg 4/26/22 inspection. Urban Silt fence should be installed Urban Spark was informed 8/2/22, 11/3/22, 11/9/22, 3/2 Individual Lot Removed - D.R. Horton so	uld be installed. Illed along the front of the ed. Corporation was inform was reminded on 11/3/2 m Building was reminded Corporation was inform was reminded on 11/3/2 m Building was reminded on 11/3/2 m Building was reminded Corporation was inform Lot 57 Replat 1 mes sodded the lot prior Lot 59 Replat 1 sodded the lot prior to Lot 63 Replat 1 gan excavation of the lot Spark removed the dirt and on the sides, rear, are to complete by 5/3/22. 1/23, 4/20/23 Lot 71 Replat 1 didded the lot prior to the Lot 78 Replat 1	ned to complete by 8/30/22. N 2. D&E Custom Building was ed on 4/20/23. ned to complete by 8/30/22. N 2. D&E Custom Building was ed on 4/20/23. ned to complete by 8/30/22. N 2. D&E Custom Building was ed on 4/20/23. ned to complete by 4/20/23. N 2 to the 7/12/22 inspection. 4/26/2022 t prior to the 4/26/22 inspectio pile from the ROW prior to the nd southeast corner of the lot of Not done as of last inspection. 8/16/22 inspection.	ot done as of last inspinformed to complete of done as of last inspinformed to complete of done as of last inspection. Removed Removed Pending n. Dirt pile was notice of 5/17/22 inspection. For the lot should be so	pection. Landmark by 3/8/23. Not done as of pection. Landmark by 3/8/23. Not done as of spection. Yes d in the ROW during the

Current Condition:	Fair Condition - Urban Spark began excavation of the lot prior to the 4/19/22 inspection. Dirt pile was noticed in the ROW during the 4/26/22 inspection. Urban Spark installed silt fence on the south side of the lot prior to the 4/26/22 inspection. Urban Spark removed the dirt pile from the ROW prior to the 5/17/22 inspection.					
	1.) Outflow pipe behind the lot should be cleaned out and uncovered. 2.) Silt fence should be repaired and extended on the side of the lot. 3.) Sediment that washed on to lot 83 should be cleaned up. 4.) Streets and sidewalk should be cleaned.					
	1.) Urban Spark was informed to complete by 6/28/22. Not done as of last inspection. Urban Spark was reminded on 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23					
	2.) Urban Spark was informed to complete by 4/26/23. Not done as of last inspection.					
	 Urban Spark was informed to complete by 4/26/23. Not done as of last inspection. Urban Spark was informed to complete by 4/20/23. Not done as of last inspection. 					
Lot 90 Replat 1	Individual Lot	Lot 90 Replat 1		Removed		
Current Condition: Lot 96 Replat 1	Removed - D.R. Horton so Individual Lot	Lot 96 Replat 1	11/9/22 inspection.	Removed		
Current Condition:	Removed - D.R. Horton so		8/16/22 inspection.	removed		
Lot 97 Replat 1	Individual Lot	Lot 97 Replat 1		Removed		
Current Condition: Lot 100 Replat 1	Removed - D.R. Horton so Individual Lot	Lot 100 Replat 1	12/7/22 inspection.	Removed		
Current Condition:	Removed - Woodland Hor		to the 1/4/22 inspection.	removed		
Lot 101 Replat 1	Individual Lot	Lot 101 Replat 1	10/25/2021	Active	Yes	
Current Condition:			on the lot prior to the 10/25/21 nonitor for removal and the ins			
			ection. Maintenance recommer			
	the dirt piles from the ROV			· ·		
	4.) 07/4 (60 1 2 0 1 2 1 1 1			
			rear of the lot or the lot should ot or the lot should be sodded.			
			that has fallen past the proper		ould be cleaned up.	
	4.) Silt fence should be ins5.) Sediment that has was		e lot or the lot should be sodd should be cleaned up.	ed.		
			14/21. Not done as of the last i 1/9/22, 3/1/23, 4/20/23. Home			
			4/21. Not done as of the last i			
			1/9/22, 3/1/23, 4/20/23. Home			
			2/22. Not done as of last inspe 3/1/23, 4/20/23. Home owner			
			2/22. Not done as of last inspe			
			/20/23. Home owner was inf		-	
	5.) Urban Spark was informed to complete by 3/12/22. Not done as of last inspection. Urban Spark was reminded on 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed to complete by 5/3/23.					
	5/6/22, 6/23/22, 6/2/22, 11	13/22, 11/9/22, 3/1/23, 4	1/20/23. Home Owner was im	ormed to complete i	Jy 5/3/23.	
Lot 105 Replat 1	Individual Lot	Lot 105 Replat 1		Removed		
Current Condition:	Removed - D.R. Horton so		11/2/22 inspection.	Kellloveu		
Lot 112 Replat 1	Individual Lot	Lot 112 Replat 1		Removed		
Current Condition: Lot 116 Replat 1	Removed - D&E Custom E Individual Lot	Building sodded the lot p Lot 116 Replat 1	prior to the 4/12/22 inspection.	Removed		
Current Condition:	Removed - D.R. Horton so		11/2/22 inspection.	Kemoved		
Lot 119 Replat 1	Individual Lot	Lot 119 Replat 1	7/19/2022	Active	No	
Current Condition:			ng the front of the lot prior to t		ŕ	
Lot 120 Replat 1 Current Condition:	Individual Lot	Lot 120 Replat 1	3/1/2022 attles prior to the 3/1/22 inspec	Active	Yes	
Current Condition:		· · · · · · · · · · · · · · · · · · ·	atties prior to the 3/1/22 inspect tence at the rear of the lot pri			
	·		II remains at the rear of the lot		oodon. D. K. Fronon coddod	
	Silt fence should be remov	ved.				
1 . 100 B . 1 . 1	4/21/23	· · ·	Not done as of last inspection.			
Lot 126 Replat 1 Current Condition:	Individual Lot Active - D.R. Horton stake	Lot 127 Replat 1	11/23/2021 on Lot 126 prior to the 11/23/2	Active 21 inspection. The lot	No is currently inactive D.R	
Current Condition.		•	29/22 inspection. D.R. Horton	•	-	
	the 11/16/22 inspection.	.,	,			
Lot 127 Replat 1	Individual Lot	Lot 127 Replat 1		Removed		
Current Condition:	Removed - D.R. Horton so		10/25/22 inspection.			
Lot 128 Replat 1 Current Condition:	Individual Lot Removed - D.R. Horton so	Lot 128 Replat 1	10/25/22 inspection	Removed		
SB 1	Sediment Basin	See SWPPP	1/3/2020	Active	No	
Current Condition:	Good Condition - 1% filled	- The basin was installed	red prior to the 1/3/20 inspection to the 4/27/20 inspection. Ha	n with a permanent ri	ser. Commercial Seeding	
SB 2	Sediment Basin	See SWPPP	1/3/2020	Active	No	
<u> </u>	Countrie Dasin	OCC OVVIII	1/0/2020	/ IOUVE	140	

Current Condition:	Good Condition - 1% filled - The basin was installed prior to the 1/3/20 inspection with a permanent riser. Commercial Seeding plugged the bottom 2 rows of holes in the orifice plate prior to the 4/27/20 inspection. Hausman began cleaning out the basin prior to the 8/9/22 inspection. Hasuman cleaned out the basin prior to the 8/16/22 inspection.				
SB 3	Sediment Basin	See SWPPP	1/3/2020	Active	No
Current Condition:			ed prior to the 1/3/20 inspection		
	plugged the bottom 4 holes in the orifice plate prior to the 4/27/20 inspection. Hausman cleaned out the basin prior to the 8/9/22 inspection.				
SB 4	Sediment Basin	See SWPPP	1/3/2020	Active	No
Current Condition:	Good Condition - 30% filled - The basin was installed prior to the 1/3/20 inspection with a temporary riser. Commercial Seeding plugged the lowest dewatering hole and backfilled the erosion prior to the 4/27/20 inspection. Commercial seeding seeded and matted the erosion at the inlet pipe and installed a straw wattle at the stub road prior to the inspection on 5/11/20. All future recommendation of maintenance for the wattle will be included with SB 4. Riser in the basin was removed prior to the 10/11/22 inspection. E&A inspector will monitor for installation of permanent riser.				
SF 1	Silt fence	See SWPPP		Removed	
Current Condition:			fence prior to the 4/27/20 insp	ection.	
SF 2	Silt fence	See SWPPP		Removed	
Current Condition:	Removed - Wattles were r recommendations.		ruction prior to the 10/26/21 in	spection. See Lot BN	MPs for further
SF 3	Silt fence	See SWPPP		Removed	
Current Condition:	Removed - Silt fence was		for active construction prior to	the 5/18/20 inspection	n.
SF 4	Silt fence	Springfield Trail		Removed	
Current Condition:			thed or removed as of the 4/9/		
W1	Straw Wattle	SB 4 Stub Road		Removed	
Current Condition:	Removed - Tim Geis cleaned the street and removed the wattle prior to the 7/15/20 inspection, reinstallation is not necessary.				
STR	Streets	Internal/S 132nd and Main Street	1/3/2020	Active	No
Current Condition:	Good Condition - Streets v		ack out during the 11/9/22 ins	pection.	_
CWDDD Ciana	Mice/Other	S 132nd Street and	4/27/2020	Activo	No
SWPPP Signs Current Condition:	Misc/Other Man Street 1/27/2020 Active No				
Current Condition:	Good Condition - E&A inspector installed SWPPP signs at the intersection of Main Street and N 10th Ave and S 132nd Street				
0. 177. 17. 01.1	and Hazel Lane during the 1/27/20 inspection. "I certify, under penalty of law, that this document and all attachments were prepared under my				
Certification Statement:					
	direction or supervision in accordance with a system designed to assure that qualified personnel				
	properly gathered and evaluated the information submitted. Based on my inquiry of the person or				
	persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility				
	of fines and imprisonment	for knowing violations."			
Inspector Signature:	Sm Nogni			Reviewed By:	Gets Soly