E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com

Comments:



Zachary A. Jilek, CPESC, CISEC **Engineering Answers** Environmental Services Dept. Manager E&A - P2019.327.000 Inspector: Shaun McGuire Stage **Springfield Pines** 1 CSW-201600337 Project Name: 5/27/2023 68059 For Week Ending: Project Location: SW of 132nd Street and Platteview Road, Springfield, NE Phase I Grading: 100% Sanitary Sewer: 100% Storm Sewer: 100% Paving: 100% Seeding: 75% **Utilities:** 100% Overall Development: 70% Amount in tenths RAIN FALL AMOUNTS Date inspected Weather Conditions Time Week 1 Sunday: 0.00" Monday: 0.00" Tuesday: 0.00" Wednesday: 0.00" 5/24/2023 Sunny 87/63 8:40 AM Thursday: 0.00" Friday: 0.00" Saturday: 0.00" Complaints: None Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Grading in Phase I was completed prior to E&A being hired to conduct SWPPP inspections (1/3/20). ed in the next 14 days? Grading in Phase I was completed prior to E&A being hired to conduct SWPPP inspections (1/3/20). Site was seeded prior to E&A being hired to conduct SWPPP inspections (1/3/20). Portion of ground to the southeast of SB 4 seeded and matted (5/11/20). Checklist Questions: re receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes reate Corrective Action? N/A lave disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion. Create Corrective Action?
No, see Findings section No, see BMPs section and Findings section Yes N/A ed with the construction activity adequately controlled on the site? Yes N/A

Comments: Site was active for homebuilding during the most recent inspection.

The School Site was graded prior to the 9/23/20 inspection. The School Site is not covered by the Springfield Pines permit (SPR-20200728-5543-GP1).

Findings / Corrective Actions (Date)

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section of this report.
- 2) Vacant-disturbed lots need to be stabilized.

A. Overgraded lots during homebuilding construction need to be stabilized. All builders were informed to complete by 1/17/20 when weather allows and asneeded. Not done as of the last inspection. All builders were reminded on 9/24/20, 6/24/21. As of the 3/1/2023 inspection there are no longer any overgraded inactive lots. Inactive lots still need stabilization.

3) Concrete waste was located throughout the development. D.R. Horton was informed to clean up concrete waste in SB 4 on 3/3/22. Not done as of last inspection. D.R. Horton was reminded on 3/24/22, 5/24/22, 6/2/22, 6/17/22, 6/23/22, 8/19/22, 8/31/22, 11/11/22, 3/1/23. D.R. Horton was informed to clean up concrete waste on lot 72 on 8/31/22. Not done as of last inspection. D.R. Horton was reminded on 11/11/22, 3/1/23, 4/21/23

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
Al 1	Area Inlet Protection	See SWPPP	1/3/2020	Active	No
Current Condition:	Active - Area inlet was ins	talled prior to the 1/3/20) inspection. The surrounding a	area is vegetated and	the inlet drains to SB 1; no
	inlet protection will be reco	mmended at this time.			
Al 2	Area Inlet Protection	See SWPPP	1/3/2020	Active	Yes
Current Condition:			stalled prior to the 1/3/20 inspe		
		' I	ction will be recommended at t		S S
	the state of the s		talled 3 additional inlets and ad		prior to the 11/922
	inspection. Orban Spark C	leaned out the inlet pro	tection prior to the 11/9/22 insp	ection.	
	Inlet protection should be	cleaned out			
	mot protection chodia be	olouriou out.			
	D.R. Horton was informed	to complete by 4/26/23	3. Not done as of last inspection	n. SID was informed t	to complete by 5/10/23. Not
	done as of last inspection.		·		
Al 3	Area Inlet Protection	See SWPPP	3/9/2020	Active	No
Current Condition:		•	prior to the 3/9/20 inspections.	Commercial Seeding	removed the remaining silt
A1.4	fence/T-posts around the i			A -4:	N-
Al 4 Current Condition:	Area Inlet Protection	See SWPPP	3/9/2020	Active	No
Current Condition:			orior to the 3/9/20 inspection. T recommended at this time.	ne surrounding area	was seeded and malled and
CW 1	Concrete Washout	Lot 81 Replat 1	Tecommended at this time.	Removed	1
Current Condition:		· •	alled on Lot 81 Replat 1 prior to		n. Gene Graves cleaned out
ourient condition.			11/20, the berm recommendat	•	
	-	·	e 6/1/20 inspection. Gene Gra	-	
			oncrete washout from Lot 81 R		•
			orior to the 7/7/21 inspection. G		
	to the 10/12/21 inspection	, the E&A inspector will	monitor for reinstallation. D.R.	Horton installed a m	obile washout on Lot 126
	· ·		was removed by D.R. Horton p		•
			the 5/10/22 inspection. D.R. H		
		. Horton removed the c	oncrete washout prior to the 10	0/11/22 inspection, the	e E&A inspector will monitor
ID 4	for reinstallation.	0 014/000			1
IP 1 Current Condition:	Inlet Protection	See SWPPP	Let filter prior to the 4/27/20 insp	Removed	o a basin, roinstallation is
Current Condition.	not recommended.	eeding removed the init	et liiter prior to trie 4/27/20 irisp	dection. The drains to	o a basiii, reiiistallatioii is
IP 2	Inlet Protection	See SWPPP		Removed	
Current Condition:	Removed - Commercial S	eeding removed the inle	et filter prior to the 4/27/20 insp	ection. Inlet drains to	o a basin, reinstallation is
			et filter prior to the 6/21/22 insp		removed the inlet filter prior
	to the 12/21/22 inspection	. Inlet drains to a basin,	reinstallation is not recommer	nded.	
IP 3	Inlet Protection	See SWPPP		Removed	
Current Condition:		eeding removed the inl	et filter prior to the 4/27/20 insp	ection. Inlet drains to	o a basin, reinstallation is
	not recommended.		T		T
IP 4	Inlet Protection	See SWPPP		Removed	to a basin asimatallation is
Current Condition:		•	let filter prior to the 4/27/20 ins Iter protection prior to the 5/31/	•	
			pasin, reinstallation is not recor		ionon removed the iniet inter
IP 5	Inlet Protection	See SWPPP		Removed	
Current Condition:			et filter prior to the 4/27/20 insp		n a hasin reinstallation is
		•	Iter protection prior to the 5/3/2		
			pasin, reinstallation is not recor		
IP 6	Inlet Protection	See SWPPP		Removed	
Current Condition:	Removed - Commercial S	eeding removed the inle	et filter prior to the 4/27/20 insp	ection. Inlet drains to	o a basin, reinstallation is
			Iter protection prior to the 8/30/	•	forton removed the inlet filte
	· ·		pasin, reinstallation is not recor		
IP 7	Inlet Protection	See SWPPP		Removed	<u> </u>
Current Condition:		eeding removed the inl	et filter prior to the 4/27/20 insp	pection. Inlet drains to	o a basin, reinstallation is
ID 0	not recommended.	0 0111555	T		T
IP 8	Inlet Protection	See SWPPP	ot filter prior to the 4/07/00 !	Removed	o o booin, roinstallation :-
Current Condition:		•	et filter prior to the 4/27/20 insp Iter protection prior to the 8/30/		
			pasin, reinstallation is not recor	•	ionon removed the iniet lille
ID 0			I Tomoranation is not recor		T
IP 9	Inlet Protection	See SWPPP	L	Removed	_1

filter prior to the 8/16/22 inspection. Inlet filter should be removed.	Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.					
Removed - Commercial Sending emoved the intel filter prior to the 427720 inspection. Net draws to a basin, reinstallation is not recommended. Dr. Horton criental cut in the intel filter prior to the 87727 inspection. DR. Horton cleaned out the intel filter prior to the 87727 inspection. DR. Horton cleaned out the intel filter prior to the 87727 inspection. DR. Horton removed the intel filter prior to the 87727 inspection. DR. Horton removed the intel filter prior to the 87727 inspection. DR. Horton removed the intel filter prior to the 47720 inspection. DR. Horton repaired the intel filter prior to the 47720 inspection. DR. Horton removed the intel filter prior to the 47720 inspection. DR. Horton repaired the intel filter prior to the 47720 inspection. DR. Horton removed the intel filter prior to the 47720 inspection. DR. Horton removed the intel filter prior to the 47720 inspection. DR. Horton removed the intel filter prior to the 47720 inspection. DR. Horton removed the intel filter prior to the 47720 inspection. DR. Horton removed the intel filter prior to the 47720 inspection. DR. Horton removed the intel filter prior to the 47720 inspection. DR. Horton removed the intel filter prior to the 47720 inspection. Intel draws to a basin, reinstallation is not recommended. Prior	IP 10	Inlet Protection See SWPPP Removed					
Current Condition: Removed - Commercial Seeding removed the intel filter prior to the 4/27/20 inspection. D.R. Horton repaired the relief filter prior to the 4/522 inspection. D.R. Horton removed the intel filter prior to the 1/22 (22 people). Intel filter prior to the 4/27/20 inspection. D.R. Horton removed the intel filter prior to the 4/27/20 inspection. Intel drains to a basin, reinstallation is not recommended. P 13 Intel Protection Removed - Commercial Seeding removed the intel filter prior to the 4/27/20 inspection. Intel drains to a basin, reinstallation is not recommended. P 14 Current Condition: Removed - Commercial Seeding removed the intel filter prior to the 4/27/20 inspection. Intel drains to a basin, reinstallation is not recommended. P 15 Current Condition: Removed - Commercial Seeding removed the intel filter prior to the 4/27/20 inspection. Intel drains to a basin, reinstallation is not recommended. P 16 Current Condition: Removed - Commercial Seeding removed the intel filter prior to the 4/27/20 inspection. Intel drains to a basin, reinstallation is not recommended. P 16 Current Condition: Removed - Commercial Seeding removed the intel filter prior to the 4/27/20 inspection. Intel drains to a basin, reinstallation is not recommended. P 16 Current Condition: Removed - Commercial Seeding removed the intel filter prior to the 4/27/20 inspection. Intel drains to a basin, reinstallation is not recommended. P 16 Current Condition: Removed - Commercial Seeding removed the intel filter prior to the 4/27/20 inspection. Intel drains to a basin, reinstallation is not recommended. P 16 Current Condition: Removed - Commercial Seeding removed the intel filter prior to the 4/27/20 inspection. Intel drains to a basin, reinstallation is not recommended. P 16 Removed - Commercial Seeding removed the intel filter prior	Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 6/7/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton removed the if liter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.	ilter				
recommended. D.R. Horton reinstalled in let filter protection prior to the 49/12/2 inspection. D.R. Horton repaired the inlet filter prior to the 12/21/2 inspection. D.R. Horton repaired the inlet filter prior to the 12/21/2 inspection. D.R. Horton removed the inlet filter prior to the 12/21/2 inspection. Inlet drains to a basin, reinstallation is not recommended. P 12 Intel Protection Removed - Commorcial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. P 13 Intel Protection Removed - Commorcial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. In 14 Intel Protection Removed - Commorcial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. In 14 Intel Protection Sea SWPPP Removed Current Condition: Removed - Commorcial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. In 14 Intel Protection Sea SWPPP Removed Current Condition: Removed - Commorcial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. In 15 Sea SWPPP Removed - Commorcial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. In 15 Sea SWPPP Removed - Commorcial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. In 15 Sea SWPPP Removed - Commorcial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. In 15 Sea SWPPP Removed - Commorcial Seeding removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. In 15 Sea SWPPP - Removed - Commorcial Seeding removed the inlet filter prior to the 4/27							
Current Condition: In P 13 Intel Protection See SWPPP Intel Protection Removed - Commended. P 14 Intel Protection Removed - Commended. P 15 Current Condition: P 16 Current Condition: P 16 Intel Protection Removed - Commended. P 17 Intel Protection Removed - Commended. P 18 Intel Protection Removed - Commended. P 19 Removed - Commended. Removed - Commended. Removed - Commended. Removed - Commended. P 19 Removed - Commended. Re		recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton repaired the inlet filter to the 4/5/22 inspection. D.R. Horton removed the inlet prior to the 12/21/22 inspection. D.R. Horton removed the inlet prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.	prior				
Pi3		Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation	is				
P 14 Intel Protection See SWPPP Removed Remove	ID 12						
P14 Intel Protection See SWPPP Removed			ic				
Pi4 Intel Protection See SWPPP Removed Removed Commencial Seeding removed the intel filter prior to the 4/27/20 inspection. Intel drains to a basin, reinstallation is not recommended. Pi 5 Intel Protection See SWPPP Removed	Current Condition.		15				
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. P 15	ID 14						
P 16		Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation	is				
Intel Protection See SWPPP Removed	IP 15	Inlet Protection See SWPPP Removed					
P 16	Current Condition:	· · · · · · · · · · · · · · · · · · ·	is				
Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Per to the filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. D.R. Horton maintained the inlet filter prior to the 4/27/20 inspection. D.R. Horton maintained the inlet filter prior to the 4/27/20 inspection. D.R. Horton maintained the inlet filter prior to the 4/27/20 inspection. D.R. Horton maintained the inlet filter prior to the 4/27/20 inspection. D.R. Horton maintained the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. O.R. Horton reinstallated inlet filter prior to the 5/3/22 inspection. D.R. Horton reinstallation is not recommended. D.R. Horton related inlet filter prior to the 5/3/22 inspection. D.R. Horton reinstallation is not recommended. D.R. Horton reinstallated inlet filter prior to the 5/3/22 inspection. D.R. Horton reinstallation is not recommended. P 19							
P17							
Intel Protection See SWPPP Removed Rem	Current Condition:	· · · · · · · · · · · · · · · · · · ·	is				
Current Condition: not recommended. DR. Hotton reinstallation is not recommended. IP 18 Current Condition: New York Commercial Seeding removed the inlet filter prior to the 3/29/22 inspection. DR. Hotton maintained the inlet filter prior to the 8/29/22 inspection. DR. Hotton maintained the inlet filter prior to the 8/29/22 inspection. Inlet drains to a basin, reinstallation is not recommended. IP 18 Current Condition: Nemoved Commercial Seeding removed the inlet filter prior to the 5/1/20 inspection. Inlet drains to a basin, reinstallation is not recommended. DR. Hotton reinstalled inlet filter prior to the 5/3/22 inspection. DR. Hotton removed the inlet filter prior to the 8/29/22 inspection. DR. Hotton removed the inlet filter prior to the 8/29/22 inspection. DR. Hotton removed the inlet filter prior to the 1/21/22 inspection. DR. Hotton removed the inlet filter prior to the 1/21/22 inspection. DR. Hotton removed the inlet filter prior to the 1/21/22 inspection. DR. Hotton removed the inlet filter prior to the 1/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. IP 20 Inlet Protection See SWPPP Removed Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. IP 21 Inlet Protection See SWPPP Removed Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. IP 21 Inlet Protection See SWPPP Removed Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. IP 22 Inlet Protection See SWPPP Removed Commercial Seeding removed the inlet filter prior to the 3/29/22 inspection. Inlet drains to a basin, reinstallation is not recommended. IP 23 Inlet Protection See SWPPP Removed Removed Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPP	ID 47						
not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/29/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. P			ic				
Removed - Commercial Seeding removed the inlet filter prior to the 5/11/20 inspection. In let drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 8/23/22 inspection. D.R. Horton removed the inlet filter prior to the 8/23/22 inspection. D.R. Horton removed the inlet filter prior to the 8/23/22 inspection. D.R. Horton removed the inlet filter prior to the 1/2/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. P 19	current condition.	not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the in filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin	ılet				
not recommended. D.R. Horton reinstalled inlet filter prior to the 6/3/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 7/1/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 8/3/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. P 19							
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. P 20		not recommended. D.R. Horton reinstalled inlet filter protection prior to the 5/3/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 7/12/22 inspection. D.R. Horton removed					
Inlet Protection See SWPPP Removed							
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. D.R. Horton maintained the inlet filter prior to the 3/29/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. P 22		not recommended.	is				
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 8/29/22 inspection. D.R. Horton removed the inlet filter prior to the 8/29/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. IP 22		Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation	is				
not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. IP 22							
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. Current Condition:		not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin,					
IP 23 Inlet Protection See SWPPP Removed Removed Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter protection prior to the 7/26/22 inspection. IP 24 Inlet Protection See SWPPP Removed Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton removed the inlet filter prior to the 5/31/22 inspection. IP 26 Inlet Protection See SWPPP 3/29/2022 Active Yes Current Condition: Fair Condition: See SWPPP 3/29/2022 Active Yes Fair Condition - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/29/22 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/29/22 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation in the filter prior to the 8/16/22 inspection. Inlet drains to a basin, reinstallatio							
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstallation is not recommended.		not recommended.	IS				
not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 7/26/22 inspection. P 24			is				
Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 7/26/22 inspection. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton removed the inlet filter prior to the 5/31/22 inspection. IP 26 Inlet Protection See SWPPP 3/29/2022 Active Yes Current Condition: Fair Condition - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 5/31/22 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 5/31/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 8/16/22 inspection. D.R. Horton was informed to complete by 11/16/22. Not done as of last inspection. D.R. Horton was reminded on 3/1/23, 4/21/23 SID was informed to complete by 5/10/23. Not done as of last inspection.		not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter					
not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 7/26/22 inspection. IP 25			ic				
Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton removed the inlet filter prior to the 5/31/22 inspection. IP 26 Inlet Protection See SWPPP 3/29/2022 Active Yes Current Condition: Fair Condition - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter prior to the 3/29/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 8/16/22 inspection. Inlet filter should be removed. D.R. Horton was informed to complete by 11/16/22. Not done as of last inspection. D.R. Horton was reminded on 3/1/23, 4/21/23 SID was informed to complete by 5/10/23. Not done as of last inspection.		not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton removed the inlet f prior to the 7/26/22 inspection.					
not recommended. D.R. Horton removed the inlet filter prior to the 5/31/22 inspection. IP 26							
Current Condition: Fair Condition - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 8/16/22 inspection. Inlet filter should be removed. D.R. Horton was informed to complete by 11/16/22. Not done as of last inspection. D.R. Horton was reminded on 3/1/23, 4/21/23 SID was informed to complete by 5/10/23. Not done as of last inspection.		not recommended. D.R. Horton removed the inlet filter prior to the 5/31/22 inspection.	is				
is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 8/16/22 inspection. Inlet filter should be removed. D.R. Horton was informed to complete by 11/16/22. Not done as of last inspection. D.R. Horton was reminded on 3/1/23, 4/21/23 SID was informed to complete by 5/10/23. Not done as of last inspection.			41-				
SID was informed to complete by 5/10/23. Not done as of last inspection.	Current Condition:	is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 8/16/22 inspection.					
IP 27 Inlet Protection See SWPPP Removed		D.R. Horton was informed to complete by 11/16/22. Not done as of last inspection. D.R. Horton was reminded on 3/1/23, 4/21/23. SID was informed to complete by 5/10/23. Not done as of last inspection.					
	IP 27	Inlet Protection See SWPPP Removed					

0	In 1.0 :10	P 141 11	. (1)		1 1 1 1 1 1 1 1	
Current Condition:		eaing removea the inle	t filter prior to the 4/27/20 insp	ection. Inlet drains to	a basin, reinstallation is	
	not recommended.					
IP 28	Inlet Protection	See SWPPP		Removed		
Current Condition:		eding removed the inle	t filter prior to the 4/27/20 insp	ection. Inlet drains to	a basin, reinstallation is	
	not recommended.				T	
Lot 1 Replat 1	Individual Lot	Lot 1 Replat 1		Removed		
Current Condition:	Removed - D.R. Horton soc		4/12/22 inspection.			
Lot 4 Replat 3	Individual Lot	Lot 4 Replat 3		Removed		
Current Condition:	Removed - D.R. Horton soc		11/9/22 inspection.			
Lot 6 Replat 1	Individual Lot	Lot 6 Replat 1		Removed		
Current Condition:	Removed - D.R. Horton soc	dded the lot prior to the	11/9/22 inspection.			
Lot 7 Replat 1	Individual Lot	Lot 7 Replat 1		Removed		
Current Condition:	Removed - Carlson Tile Inc	s. sodded the lot prior to	the 6/21/22 inspection.			
Lot 10 Replat 1	Individual Lot	Lot 10 Replat 1		Removed		
Current Condition:	Removed - D.R. Horton soc	dded the lot prior to the	4/19/22 inspection.			
Lot 11 Replat 1	Individual Lot	Lot 11 Replat 1	·	Removed		
Current Condition:	Removed - D.R. Horton soc	ded the lot prior to the	4/19/22 inspection.			
Lot 13 Replat 1	Individual Lot	Lot 13 Replat 1	·	Removed		
Current Condition:	Removed - D.R. Horton soo		4/19/22 inspection.			
Lot 19 Replat 1	Individual Lot	Lot 19 Replat 1	1, 10, 22 110 postion	Removed		
Current Condition:	Removed - Brooks Builders		the 5/10/22 inspection	1101110100		
Lot 20 Replat 1	Individual Lot	Lot 20 Replat 1	tilo o, ro,zz mopocion.	Removed		
Current Condition:	Active - Sundown Homes L		to the 8/23/22 inspection	rtemoved	<u> </u>	
Lot 22 Replat 1	Individual Lot	Lot 22 Replat 1	to the orzorzz mapection.	Removed		
Current Condition:	Removed - Urban Spark so		5/17/22 inspection	r cilioveu	1	
Lot 23 Replat 1	Individual Lot	Lot 23 Replat 1	5 0/ 17/22 IIISPECTION.	Removed		
Current Condition:	Removed - D.R. Horton soc		4/12/22 inspection	Nemoveu	l	
Lot 28 Replat 1	Individual Lot	Lot 28 Replat 1	T/ 12/22 IIISPECTION.	Removed	T	
			4/40/00 in an artists	Removed		
Current Condition:	Removed - D.R. Horton soc		4/12/22 inspection.	Damad		
Lot 30 Replat 1	Individual Lot	Lot 30 Replat 1	11/0/00 1	Removed		
Current Condition:	Removed - D.R. Horton soc		11/2/22 inspection.			
Lot 33 Replat 1	Individual Lot	Lot 33 Replat 1		Removed		
Current Condition:	Removed - D.R. Horton soc		5/17/22 inspection.			
Lot 43 Replat 1	Individual Lot	Lot 43 Replat 1		Removed		
Current Condition:	Removed - D.R. Horton soc		7/26/22 inspection.			
Lot 45 Replat 1	Individual Lot	Lot 45 Replat 1		Removed		
Current Condition:	Removed - Brooks Builders		or to the 4/26/23 inspection.			
Lot 46 Replat 1	Individual Lot	Lot 46 Replat 1		Removed		
Current Condition:	Removed - Epic Custom Ho	omes sodded the lot pr	ior to the 5/17/22 inspection.			
Lot 48 Replat 1	Individual Lot	Lot 48 Replat 1		Removed		
Current Condition:	Removed - D.R. Horton soc	dded the lot prior to the	10/25/22 inspection.			
Lot 49 Replat 1	Individual Lot	Lot 49 Replat 1		Removed		
Current Condition:	Removed - D.R. Horton soc	dded the lot prior to the	10/11/22 inspection.			
Lot 51 Replat 1	Individual Lot	Lot 51 Replat 1		Removed		
Current Condition:	Removed - D.R. Horton soc	dded the lot prior to the	10/11/22 inspection.			
Lot 55 Replat 1	Individual Lot	Lot 55 Replat 1	5/11/2020	Active	Yes	
Current Condition:	Fair Condition - Gene Grave		n the side of the lot prior to the	inspection on 5/11/2		
			hen construction begins. Mind			
			D&E Custom Building began e			
			luring the 8/23/22 inspection. [
			9/13/22 inspection. D&E Cus			
	5/24/23 inspection.	ii tile KOW phoi to tile	9/13/22 Inspection. Dat Cus	tom building cleaner	u the streets prior to the	
	3/24/23 Hispection.					
	4.) 07/4 (
	1.) Silt fence perimeter sho					
	2.) Wattles should be instal	led along the front of th	ne lot.			
	1.) Landmark Performance	Corporation was inform	ned to complete by 8/30/22. N	ot done as of last insp	ection. Landmark	
	Performance Corporation w	as reminded on 11/3/2	2. D&E Custom Building was	informed to complete	by 3/8/23. Not done as of	
	Performance Corporation was reminded on 11/3/22. D&E Custom Building was informed to complete by 3/8/23. Not done as of last inspection. D&E Custom Building was reminded on 4/20/23. 2.) Landmark Performance Corporation was informed to complete by 8/30/22. Not done as of last inspection. Landmark Performance Corporation was reminded on 11/3/22. D&E Custom Building was informed to complete by 3/8/23. Not done as of					
	last inspection. D&E Custon		3	omiod to complete	Sy Stores. Not done as of	
Lot 57 Replat 1	Individual Lot	Lot 57 Replat 1	GG 311 4/20/23.	Removed		
Current Condition:	Removed - Pacesetter Hom		r to the 7/12/22 increation	Nemoveu	1	
Lot 59 Replat 1			to the 1/12/22 Inspection.	Removed		
	Individual Lot	Lot 59 Replat 1	the 6/24/22 inc = +!	Removed	I	
Current Condition:	Removed - Nelson Builders		tne 6/21/22 inspection.	D 1		
Lot 63 Replat 1	Individual Lot	Lot 63 Replat 1	- 5/40/00 in : :'	Removed		
Current Condition:	Removed - Urban Spark so		e 5/10/23 inspection.			
Lot 71 Replat 1	Individual Lot	Lot 71 Replat 1		Removed		
Current Condition:	Removed - D.R. Horton soc		8/16/22 inspection.			
Lot 78 Replat 1	Individual Lot	Lot 78 Replat 1		Removed	I	
				Ttomovou		
Current Condition:	Removed - Sundown Home	es sodded the lot prior t				
			to the 7/19/22 inspection. 4/19/2022	Active	Yes	

Current Condition:	Fair Condition - Urban Spark began excavation of the lot prior to the 4/19/22 inspection. Dirt pile was noticed in the ROW during the 4/26/22 inspection. Urban Spark installed silt fence on the south side of the lot prior to the 4/26/22 inspection. Urban Spark removed the dirt pile from the ROW prior to the 5/17/22 inspection. Urban Spark cleaned the streets and sidewalk prior to the 5/10/23 inspection. 1.) Outflow pipe behind the lot should be cleaned out and uncovered. 2.) Silt fence should be repaired and trenched in on the side of the lot. 3.) Sediment that washed on to lot 83 should be cleaned up.					
	1.) Urban Spark was informed to complete by 6/28/22. Not done as of last inspection. Urban Spark was reminded on 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23					
			6/23. Not done as of last inspe 6/23. Not done as of last inspe			
Lot 90 Replat 1	Individual Lot	Lot 90 Replat 1	1/23. NOT done as of last mape	Removed		
Current Condition:	Removed - D.R. Horton so	odded the lot prior to the	11/9/22 inspection.			
Lot 96 Replat 1	Individual Lot	Lot 96 Replat 1	0/40/00 :	Removed		
Current Condition: Lot 97 Replat 1	Removed - D.R. Horton so Individual Lot	Lot 97 Replat 1	8/16/22 inspection.	Removed		
Current Condition:	Removed - D.R. Horton so		12/7/22 inspection.	rtemoved	1	
Lot 100 Replat 1	Individual Lot	Lot 100 Replat 1	·	Removed		
Current Condition:	Removed - Woodland Hor			1		
Lot 101 Replat 1 Current Condition:	Individual Lot	Lot 101 Replat 1	10/25/2021 on the lot prior to the 10/25/21	Active	Yes	
Lot 10E Poplet 1	during the 10/25/21 inspection, the inspector will monitor for removal and the installation of BMPs. Home owner installed silt fence at the rear of the lot prior to the 1/4/22 inspection. Maintenance recommendations have changed. Home owner removed the dirt piles from the ROW prior to the 2/15/22 inspection. 1.) Silt fence should be repaired/reinstalled at the rear of the lot or the lot should be sodded. 2.) Wattles should be installed on the front of the lot or the lot should be sodded. 3.) Silt fence should be cleaned out and sediment that has fallen past the property line to the east should be cleaned up. 4.) Silt fence should be installed on the sides of the lot or the lot should be sodded. 5.) Sediment that has washed on to adjoining lots should be cleaned up. 1.) Urban Spark was informed to complete by 12/14/21. Not done as of the last inspection. Urban Spark was reminded on 1/5/22, 3/8/22, 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed to complete by 5/3/23. 2.) Urban Spark was informed to complete by 12/14/21. Not done as of the last inspection. Urban Spark was reminded on 1/5/22, 3/8/22, 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed to complete by 5/3/23. 3.) Urban Spark was informed to complete by 2/22/22. Not done as of last inspection. Urban Spark was reminded on 3/8/22, 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed to complete by 5/3/23. 4.) Urban Spark was informed to complete by 3/12/22. Not done as of last inspection. Urban Spark was reminded on 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed to complete by 5/3/23. 5.) Urban Spark was informed to complete by 3/12/22. Not done as of last inspection. Urban Spark was reminded on 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed to complete by 5/3/23. 5.) Urban Spark was informed to complete by 3/12/23. Home owner was inform					
Lot 105 Replat 1 Current Condition:	Individual Lot Removed - D.R. Horton so	Lot 105 Replat 1	11/2/22 inspection	Removed		
Lot 112 Replat 1	Individual Lot	Lot 112 Replat 1		Removed		
Current Condition:			rior to the 4/12/22 inspection.	ı	1	
Lot 116 Replat 1	Individual Lot	Lot 116 Replat 1	11/2/22 increation	Removed		
Current Condition: Lot 119 Replat 1	Removed - D.R. Horton so Individual Lot	Lot 119 Replat 1	7/19/2022	Active	No	
Current Condition:			ng the front of the lot prior to t			
Lot 120 Replat 1	Individual Lot	Lot 120 Replat 1	3/1/2022	Active	Yes	
Current Condition:	Fair Condition - D.R. Horton installed perimeter wattles prior to the 3/1/22 inspection. D.R. Horton began excavating the lot prior to the 4/26/22 inspection. D.R. Horton installed silt fence at the rear of the lot prior to the 7/12/22 inspection. D.R. Horton sodded the lot prior to the 11/9/22 inspection. Silt fence still remains at the rear of the lot. Silt fence should be removed. D.R. Horton was informed to complete by 9/6/22. Not done as of last inspection. D.R. Horton was reminded on 11/11/22, 3/1/23, 4/21/23					
Lot 126 Replat 1	Individual Lot	Lot 127 Replat 1	11/23/2021	Active	No is surrently inactive. D.B.	
Current Condition:	Horton resecured the portathe 11/16/22 inspection.	able toilet prior to the 3/2	on Lot 126 prior to the 11/23/2 29/22 inspection. D.R. Horton	removed the portable	•	
Lot 127 Replat 1	Individual Lot	Lot 127 Replat 1	10/05/00 inone -+!	Removed		
Current Condition: Lot 128 Replat 1	Removed - D.R. Horton so Individual Lot	Lot 128 Replat 1	10/25/22 inspection.	Removed	1	
Current Condition:	Removed - D.R. Horton so		10/25/22 inspection	rtemoveu	1	
SB 1						
	Sediment Basin	See SWPPP	1/3/2020	Active	No	
Current Condition:	Good Condition - 1% filled	- The basin was installe		n with a permanent ri	ser. Commercial Seeding	

Current Condition:	Good Condition - 1% filled - The basin was installed prior to the 1/3/20 inspection with a permanent riser. Commercial Seeding plugged the bottom 2 rows of holes in the orifice plate prior to the 4/27/20 inspection. Hausman began cleaning out the basin prior to the 8/9/22 inspection. Hasuman cleaned out the basin prior to the 8/16/22 inspection.					
SB 3	Sediment Basin	See SWPPP	1/3/2020	Active	No	
Current Condition:			ed prior to the 1/3/20 inspection			
	plugged the bottom 4 holes in the orifice plate prior to the 4/27/20 inspection. Hausman cleaned out the basin prior to the 8/9/22 inspection.					
SB 4	Sediment Basin	See SWPPP	1/3/2020	Active	No	
Current Condition:	Good Condition - 30% filled - The basin was installed prior to the 1/3/20 inspection with a temporary riser. Commercial Seeding plugged the lowest dewatering hole and backfilled the erosion prior to the 4/27/20 inspection. Commercial seeding seeded and matted the erosion at the inlet pipe and installed a straw wattle at the stub road prior to the inspection on 5/11/20. All future recommendation of maintenance for the wattle will be included with SB 4. Riser in the basin was removed prior to the 10/11/22 inspection. E&A inspector will monitor for installation of permanent riser.					
SF 1	Silt fence	See SWPPP		Removed		
Current Condition:			fence prior to the 4/27/20 insp	ection.		
SF 2	Silt fence	See SWPPP		Removed		
Current Condition:	Removed - Wattles were r recommendations.		ruction prior to the 10/26/21 in	spection. See Lot BN	MPs for further	
SF 3	Silt fence	See SWPPP		Removed		
Current Condition:	Removed - Silt fence was		for active construction prior to	the 5/18/20 inspection	n.	
SF 4	Silt fence	Springfield Trail		Removed		
Current Condition:			thed or removed as of the 4/9/			
W1	Straw Wattle	SB 4 Stub Road		Removed		
Current Condition:	Removed - Tim Geis cleaned the street and removed the wattle prior to the 7/15/20 inspection, reinstallation is not necessary.					
STR	Streets	Internal/S 132nd and Main Street	1/3/2020	Active	No	
Current Condition:	Good Condition - Streets v		ack out during the 11/9/22 ins	pection.	_	
CWDDD Ciana	Mice/Other	S 132nd Street and	1/27/2020	Activo	No	
SWPPP Signs Current Condition:	Misc/Other	Man Street		Active	No	
Current Condition:	Good Condition - E&A inspector installed SWPPP signs at the intersection of Main Street and N 10th Ave and S 132nd Street					
0. 155. 15. 01.1	and Hazel Lane during the 1/27/20 inspection. "I certify, under penalty of law, that this document and all attachments were prepared under my					
Certification Statement:						
	direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility					
	of fines and imprisonment	for knowing violations."				
Inspector Signature:	Sm Nogni			Reviewed By:	Gets Soly	