E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com

Comments:



Zachary A. Jilek, CPESC, CISEC **Engineering Answers** Environmental Services Dept. Manager E&A - P2019.327.000 Inspector: Shaun McGuire Stage **Springfield Pines** 1 CSW-201600337 Project Name: 6/3/2023 68059 For Week Ending: Project Location: SW of 132nd Street and Platteview Road, Springfield, NE Phase I Grading: 100% Sanitary Sewer: 100% Storm Sewer: 100% Paving: 100% Seeding: 75% **Utilities:** 100% Overall Development: 70% Amount in tenths RAIN FALL AMOUNTS Date inspected Weather Conditions Time Week 1 Sunday: 0.00" Monday: 0.00" Tuesday: 0.00" Wednesday: 0.00" 5/31/2023 Sunny 88/66 9:05 AM Thursday: 0.43" Friday: 0.09" Saturday: 0.03 Complaints: None Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Grading in Phase I was completed prior to E&A being hired to conduct SWPPP inspections (1/3/20). ed in the next 14 days? Grading in Phase I was completed prior to E&A being hired to conduct SWPPP inspections (1/3/20). Site was seeded prior to E&A being hired to conduct SWPPP inspections (1/3/20). Portion of ground to the southeast of SB 4 seeded and matted (5/11/20). Checklist Questions: re receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes reate Corrective Action? N/A lave disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion. Create Corrective Action?
No, see Findings section No, see BMPs section and Findings section Yes N/A ed with the construction activity adequately controlled on the site? Yes N/A

Comments: Site was active for homebuilding during the most recent inspection.

The School Site was graded prior to the 9/23/20 inspection. The School Site is not covered by the Springfield Pines permit (SPR-20200728-5543-GP1).

Findings / Corrective Actions (Date)

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section of this report.
- 2) Vacant-disturbed lots need to be stabilized.

A. Overgraded lots during homebuilding construction need to be stabilized. All builders were informed to complete by 1/17/20 when weather allows and asneeded. Not done as of the last inspection. All builders were reminded on 9/24/20, 6/24/21. As of the 3/1/2023 inspection there are no longer any overgraded inactive lots. Inactive lots still need stabilization.

3) Concrete waste was located throughout the development. D.R. Horton was informed to clean up concrete waste in SB 4 on 3/3/22. Not done as of last inspection. D.R. Horton was reminded on 3/24/22, 5/24/22, 6/2/22, 6/17/22, 6/23/22, 8/19/22, 8/31/22, 11/11/22, 3/1/23. D.R. Horton was informed to clean up concrete waste on lot 72 on 8/31/22. Not done as of last inspection. D.R. Horton was reminded on 11/11/22, 3/1/23, 4/21/23

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
Al 1	Area Inlet Protection	See SWPPP	1/3/2020	Active	No
Current Condition:	Active - Area inlet was ins	talled prior to the 1/3/20) inspection. The surrounding a	area is vegetated and	the inlet drains to SB 1; no
	inlet protection will be reco	ommended at this time.			
Al 2	Area Inlet Protection	See SWPPP	1/3/2020	Active	Yes
Current Condition:			stalled prior to the 1/3/20 inspe		
		, and a second s	ction will be recommended at t		S S
	the state of the s		talled 3 additional inlets and actection prior to the 11/9/22 insp		orior to the 11/922
	inspection. Orban Spark C	leaned out the inlet pro	rection prior to the 11/9/22 insp	ection.	
	Inlet protection should be	cleaned out.			
	D.R. Horton was informed	to complete by 4/26/23	B. Not done as of last inspection	n. SID was informed t	to complete by 5/10/23. Not
	done as of last inspection.				
Al 3	Area Inlet Protection	See SWPPP	3/9/2020	Active	No
Current Condition:		•	orior to the 3/9/20 inspections.	Commercial Seeding	removed the remaining silt
Al 4	fence/T-posts around the Area Inlet Protection	See SWPPP	3/9/2020	Active	No
Current Condition:			prior to the 3/9/20 inspection. T		
Current Condition.			recommended at this time.	ne surrounding area	was seeded and matted and
CW 1	Concrete Washout	Lot 81 Replat 1		Removed	
Current Condition:			alled on Lot 81 Replat 1 prior to		n. Gene Graves cleaned out
			11/20, the berm recommendat	•	
			e 6/1/20 inspection. Gene Gra	-	
	11/4/20 inspection. Gene	Graves relocated the co	oncrete washout from Lot 81 R	eplat 1 to Lot 1 prior t	to the 4/6/21 inspection.
			prior to the 7/7/21 inspection. G		•
			monitor for reinstallation. D.R.		
	· ·		was removed by D.R. Horton p		•
			the 5/10/22 inspection. D.R. Forcete washout prior to the 10		
	for reinstallation.	. Holton removed the c	officiete washout prior to the 10	o/ 11/22 inspection, th	e L&A irispector will monitor
IP 1	Inlet Protection	See SWPPP		Removed	
Current Condition:			et filter prior to the 4/27/20 insp		o a basin, reinstallation is
	not recommended.				
IP 2	Inlet Protection	See SWPPP		Removed	
Current Condition:		•	et filter prior to the 4/27/20 insp		
			et filter prior to the 6/21/22 inspreinstallation is not recommer		removed the inlet filter prior
ID 0	· ·		Temstaliation is not recommen		T
IP 3 Current Condition:	Inlet Protection	See SWPPP	Let filter prior to the 4/27/20 insp	Removed	a a basin, rainstallation is
Current Condition.	not recommended.	eeding removed the mi	et liiter prior to trie 4/27/20 irisp	dection. Thet drains to	o a dasin, remstaliation is
IP 4	Inlet Protection	See SWPPP		Removed	
Current Condition:			let filter prior to the 4/27/20 ins		to a basin, reinstallation is
		•	Iter protection prior to the 5/31/	•	
	prior to the 12/21/22 inspe	ection. Inlet drains to a b	pasin, reinstallation is not recor	nmended.	
IP 5	Inlet Protection	See SWPPP		Removed	
Current Condition:	Removed - Commercial S	eeding removed the inle	et filter prior to the 4/27/20 insp	ection. Inlet drains to	o a basin, reinstallation is
			Iter protection prior to the 5/3/2		orton removed the inlet filter
			pasin, reinstallation is not recor		T
IP 6	Inlet Protection	See SWPPP	1.534 11 1/07/00:	Removed	1 1 1 1 1 1 1
Current Condition:		•	et filter prior to the 4/27/20 insp Iter protection prior to the 8/30/		
			pasin, reinstallation is not recor	•	ionon removed the iniet line
IP 7	Inlet Protection	See SWPPP	Table 1 of 100 100 100 100 100 100 100 100 100 10	Removed	1
Current Condition:			Let filter prior to the 4/27/20 insp		o a basin, reinstallation is
	not recommended.				
IP 8	Inlet Protection	See SWPPP		Removed	
Current Condition:			et filter prior to the 4/27/20 insp		o a basin, reinstallation is
		•	Iter protection prior to the 8/30/		
	prior to the 12/21/22 inspe	ection. Inlet drains to a b	pasin, reinstallation is not recor	nmended.	
IP 9	Inlet Protection	See SWPPP		Removed	

Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin not recommended.	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.					
IP 10 Inlet Protection See SWPPP Removed						
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton cleaner prior to the 6/7/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection.	d out the inlet filter					
IP 11 Inlet Protection See SWPPP Removed						
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton repaire to the 4/5/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 6/28/22 inspection. D.R. Horton repaire prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.	d the inlet filter prior					
P 12	n, reinstallation is					
not recommended. IP 13 Inlet Protection See SWPPP Removed						
IP 13 Inlet Protection See SWPPP Removed Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin	roinetallation is					
not recommended.	i, reinstallation is					
IP 14 Inlet Protection See SWPPP Removed						
Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin not recommended.	n, reinstallation is					
IP 15 Inlet Protection See SWPPP Removed						
Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin	n, reinstallation is					
not recommended.						
IP 16 Inlet Protection See SWPPP Removed						
Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin	n, reinstallation is					
not recommended. IP 17 Inlet Protection See SWPPP Removed						
IP 17	roinetallation is					
not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. Inlet differ prior to the 8/2/22 inspection. Inlet differ prior to the 12/21/22 inspection.	aintained the inlet					
IP 18 Inlet Protection See SWPPP Removed						
not recommended. D.R. Horton reinstalled inlet filter protection prior to the 5/3/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 8/23/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 8/23/22 inspection. D.R. the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.	Removed - Commercial Seeding removed the inlet filter prior to the 5/11/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 5/3/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 7/12/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 8/23/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.					
IP 19 Inlet Protection See SWPPP Removed						
Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin not recommended. IP 20 Inlet Protection See SWPPP Removed	n, reinstallation is					
	Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended.					
IP 21 Inlet Protection See SWPPP Removed						
not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton m filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet direinstallation is not recommended.	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.					
IP 22 Inlet Protection See SWPPP Removed						
Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin not recommended.	n, reinstallation is					
P 23 Inlet Protection See SWPPP Removed	reinstallation is					
not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton ren prior to the 7/26/22 inspection.	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 7/26/22 inspection.					
P 24 Inlet Protection See SWPPP Removed	roinetallation is					
not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton renprior to the 7/26/22 inspection.						
IP 25 Inlet Protection See SWPPP Removed						
Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin not recommended. D.R. Horton removed the inlet filter prior to the 5/31/22 inspection.	n, reinstallation is					
IP 26 Inlet Protection See SWPPP 3/29/2022 Active	Yes					
is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton filter prior to the 8/16/22 inspection.	Fair Condition - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 8/16/22 inspection. Inlet filter should be removed.					
Inlet filter should be removed.						
D.R. Horton was informed to complete by 11/16/22. Not done as of last inspection. D.R. Horton was reminded SID was informed to complete by 5/10/23. Not done as of last inspection. IP 27 Inlet Protection See SWPPP Removed	d on 3/1/23, 4/21/23.					

0	10 10 10 10 10 10 10 10 10 10 10 10 10 1					
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is					
	not recommended.					
IP 28	Inlet Protection See SWPPP Removed					
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is					
	not recommended.					
Lot 1 Replat 1	Individual Lot					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 4/12/22 inspection.					
Lot 4 Replat 3	Individual Lot					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 11/9/22 inspection.					
Lot 6 Replat 1	Individual Lot Lot 6 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 11/9/22 inspection.					
Lot 7 Replat 1	Individual Lot Lot 7 Replat 1 Removed					
Current Condition:	Removed - Carlson Tile Inc. sodded the lot prior to the 6/21/22 inspection.					
Lot 10 Replat 1	Individual Lot Lot 10 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 4/19/22 inspection.					
Lot 11 Replat 1	Individual Lot Lot 11 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 4/19/22 inspection.					
Lot 13 Replat 1	Individual Lot Lot 13 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 4/19/22 inspection.					
Lot 19 Replat 1	Individual Lot Lot 19 Replat 1 Removed					
Current Condition:	Removed - Brooks Builders sodded the lot prior to the 5/10/22 inspection.					
Lot 20 Replat 1	Individual Lot Lot 20 Replat 1 Removed					
Current Condition:	Active - Sundown Homes LLC sodded the lot prior to the 8/23/22 inspection.					
Lot 22 Replat 1	Individual Lot Lot 22 Replat 1 Removed					
Current Condition:	Removed - Urban Spark sodded the lot prior to the 5/17/22 inspection.					
Lot 23 Replat 1	Individual Lot Lot 23 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 4/12/22 inspection.					
Lot 28 Replat 1	Individual Lot Lot 28 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 4/12/22 inspection.					
Lot 30 Replat 1	Individual Lot Lot 30 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 11/2/22 inspection.					
Lot 33 Replat 1	Individual Lot Lot 33 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 5/17/22 inspection.					
Lot 43 Replat 1	Individual Lot Lot 43 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 7/26/22 inspection.					
Lot 45 Replat 1	Individual Lot Lot 45 Replat 1 Removed					
Current Condition:	Removed - Brooks Builders Inc. sodded the lot prior to the 4/26/23 inspection.					
Lot 46 Replat 1	Individual Lot Lot 46 Replat 1 Removed					
Current Condition:	Removed - Epic Custom Homes sodded the lot prior to the 5/17/22 inspection.					
Lot 48 Replat 1	Individual Lot Lot 48 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 10/25/22 inspection.					
Lot 49 Replat 1	Individual Lot Lot 49 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 10/11/22 inspection.					
Lot 51 Replat 1	Individual Lot Lot 51 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 10/11/22 inspection.					
Lot 55 Replat 1	Individual Lot Lot 55 Replat 1 5/11/2020 Active Yes					
Current Condition:	Fair Condition - Gene Graves installed silt fence on the side of the lot prior to the inspection on 5/11/20. Future silt fence					
	maintenance will be sent to the builder of the lot when construction begins. Minor damage to the silt fence was observed during					
	the 6/22/21 inspection, the inspector will monitor. D&E Custom Building began excavation on the lot prior to the 8/23/22					
	inspection. Dirt piles were observed in the ROW during the 8/23/22 inspection. D&E Custom Building removed the concrete					
	waste and the dirt piles from the ROW prior to the 9/13/22 inspection. D&E Custom Building cleaned the streets prior to the					
	5/24/23 inspection.					
	and the second s					
	1.) Silt fence perimeter should be installed.					
	2.) Wattles should be installed along the front of the lot.					
1.) Landmark Performance Corporation was informed to complete by 8/30/22. Not done as of last inspection. Landmark						
						Performance Corporation was reminded on 11/3/22. D&E Custom Building was informed to complete by 3/8/23. Not done as of
	last inspection. D&E Custom Building was reminded on 4/20/23.					
2.) Landmark Performance Corporation was informed to complete by 8/30/22. Not done as of last inspection. Landmark						
	Performance Corporation was reminded on 11/3/22. D&E Custom Building was informed to complete by 3/8/23. Not done as of					
	last inspection. D&E Custom Building was reminded on 4/20/23.					
Let E7 Deplot 4						
Lot 57 Replat 1						
Current Condition:	Removed - Pacesetter Homes sodded the lot prior to the 7/12/22 inspection.					
Lot EO Dealet 4						
Lot 59 Replat 1	Individual Lot Lot 59 Replat 1 Removed					
Current Condition:	Removed - Nelson Builders sodded the lot prior to the 6/21/22 inspection.					
Current Condition: Lot 63 Replat 1	Removed - Nelson Builders sodded the lot prior to the 6/21/22 inspection. Individual Lot Lot 63 Replat 1 Removed					
Current Condition: Lot 63 Replat 1 Current Condition:	Removed - Nelson Builders sodded the lot prior to the 6/21/22 inspection. Individual Lot Lot 63 Replat 1 Removed Removed - Urban Spark soddedf the lot prior to the 5/10/23 inspection.					
Current Condition: Lot 63 Replat 1 Current Condition: Lot 71 Replat 1	Removed - Nelson Builders sodded the lot prior to the 6/21/22 inspection. Individual Lot Lot 63 Replat 1 Removed Removed - Urban Spark soddedf the lot prior to the 5/10/23 inspection. Individual Lot Lot 71 Replat 1 Removed					
Current Condition: Lot 63 Replat 1 Current Condition: Lot 71 Replat 1 Current Condition:	Removed - Nelson Builders sodded the lot prior to the 6/21/22 inspection. Individual Lot Lot 63 Replat 1 Removed Removed - Urban Spark soddedf the lot prior to the 5/10/23 inspection. Individual Lot Lot 71 Replat 1 Removed Removed - D.R. Horton sodded the lot prior to the 8/16/22 inspection.					
Current Condition: Lot 63 Replat 1 Current Condition: Lot 71 Replat 1	Removed - Nelson Builders sodded the lot prior to the 6/21/22 inspection. Individual Lot					
Current Condition: Lot 63 Replat 1 Current Condition: Lot 71 Replat 1 Current Condition:	Removed - Nelson Builders sodded the lot prior to the 6/21/22 inspection. Individual Lot Lot 63 Replat 1 Removed Removed - Urban Spark soddedf the lot prior to the 5/10/23 inspection. Individual Lot Lot 71 Replat 1 Removed Removed - D.R. Horton sodded the lot prior to the 8/16/22 inspection.					
Current Condition: Lot 63 Replat 1 Current Condition: Lot 71 Replat 1 Current Condition: Lot 78 Replat 1	Removed - Nelson Builders sodded the lot prior to the 6/21/22 inspection. Individual Lot					

Current Condition:	Fair Condition - Urban Spark began excavation of the lot prior to the 4/19/22 inspection. Dirt pile was noticed in the ROW during the 4/26/22 inspection. Urban Spark installed silt fence on the south side of the lot prior to the 4/26/22 inspection. Urban Spark removed the dirt pile from the ROW prior to the 5/17/22 inspection. Urban Spark cleaned the streets and sidewalk prior to the 5/10/23 inspection. 1.) Outflow pipe behind the lot should be cleaned out and uncovered. 2.) Silt fence should be repaired and trenched in on the side of the lot. 3.) Sediment that washed on to lot 83 should be cleaned up.					
	1.) Urban Spark was informed to complete by 6/28/22. Not done as of last inspection. Urban Spark was reminded on 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23					
	2.) Urban Spark was informed to complete by 4/26/23. Not done as of last inspection. 3.) Urban Spark was informed to complete by 4/26/23. Not done as of last inspection.					
Lot 90 Replat 1	Individual Lot	Lot 90 Replat 1	WZO. Not dono do or last mopo	Removed		
Current Condition:	Removed - D.R. Horton so	odded the lot prior to the	11/9/22 inspection.		1	
Lot 96 Replat 1 Current Condition:	Individual Lot Removed - D.R. Horton so	Lot 96 Replat 1	8/16/22 inspection	Removed		
Lot 97 Replat 1	Individual Lot	Lot 97 Replat 1	o/ 10/22 Inspection.	Removed		
Current Condition:	Removed - D.R. Horton so	odded the lot prior to the	12/7/22 inspection.			
Lot 100 Replat 1	Individual Lot	Lot 100 Replat 1		Removed		
Current Condition: Lot 101 Replat 1	Removed - Woodland Hou Individual Lot	Lot 101 Replat 1	to the 1/4/22 inspection. 10/25/2021	Active	Yes	
Current Condition:			on the lot prior to the 10/25/21			
Lot 105 Replat 1	during the 10/25/21 inspection, the inspector will monitor for removal and the installation of BMPs. Home owner installed silt fence at the rear of the lot prior to the 1/4/22 inspection. Maintenance recommendations have changed. Home owner removed the dirt piles from the ROW prior to the 2/15/22 inspection. 1.) Silt fence should be repaired/reinstalled at the rear of the lot or the lot should be sodded. 2.) Wattles should be installed on the front of the lot or the lot should be sodded. 3.) Silt fence should be cleaned out and sediment that has fallen past the property line to the east should be cleaned up. 4.) Silt fence should be installed on the sides of the lot or the lot should be sodded. 5.) Sediment that has washed on to adjoining lots should be cleaned up. 1.) Urban Spark was informed to complete by 12/14/21. Not done as of the last inspection. Urban Spark was reminded on 1/5/22, 3/8/22, 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed to complete by 5/3/23. 2.) Urban Spark was informed to complete by 12/14/21. Not done as of the last inspection. Urban Spark was reminded on 1/5/22, 3/8/22, 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed to complete by 5/3/23. 3.) Urban Spark was informed to complete by 2/22/22. Not done as of last inspection. Urban Spark was reminded on 3/8/22, 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed to complete by 5/3/23. 4.) Urban Spark was informed to complete by 3/12/22. Not done as of last inspection. Urban Spark was reminded on 4/27/22, 5/6/22, 8/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed to complete by 5/3/23. 5.) Urban Spark was informed to complete by 3/12/22. Not done as of last inspection. Urban Spark was reminded on 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed to complete by 5/3/23. 5.) Urban Spark was informed to complete by 3/12/22. Not done as of last i					
Lot 105 Replat 1	Individual Lot Removed - D.R. Horton so	Lot 105 Replat 1	11/2/22 increation	Removed		
Current Condition: Lot 112 Replat 1	Individual Lot	Lot 112 Replat 1	i i/Z/ZZ iiispection.	Removed		
Current Condition:			prior to the 4/12/22 inspection.			
Lot 116 Replat 1	Individual Lot	Lot 116 Replat 1	44/0/00 1	Removed		
Current Condition: Lot 119 Replat 1	Removed - D.R. Horton so Individual Lot	Lot 119 Replat 1	11/2/22 inspection. 7/19/2022	Active	No	
Current Condition:			ng the front of the lot prior to t			
Lot 120 Replat 1	Individual Lot	Lot 120 Replat 1	3/1/2022	Active	Yes	
Current Condition:	Fair Condition - D.R. Horton installed perimeter wattles prior to the 3/1/22 inspection. D.R. Horton began excavating the lot prior to the 4/26/22 inspection. D.R. Horton installed silt fence at the rear of the lot prior to the 7/12/22 inspection. D.R. Horton sodded the lot prior to the 11/9/22 inspection. Silt fence still remains at the rear of the lot. Silt fence should be removed. D.R. Horton was informed to complete by 9/6/22. Not done as of last inspection. D.R. Horton was reminded on 11/11/22, 3/1/23, 4/21/23					
Lot 126 Replat 1	Individual Lot	Lot 127 Replat 1	11/23/2021	Active	No is surrently inactive. D.B.	
Current Condition:	Horton resecured the portathe 11/16/22 inspection.	able toilet prior to the 3/2	on Lot 126 prior to the 11/23/2 29/22 inspection. D.R. Horton	removed the portable	•	
Lot 127 Replat 1	Individual Lot	Lot 127 Replat 1	10/25/22 inapportion	Removed		
Current Condition: Lot 128 Replat 1	Removed - D.R. Horton so Individual Lot	Lot 128 Replat 1	10/25/22 Inspection.	Removed	1	
Current Condition:			10/05/00 : .:	Romovou		
SB 1	Removed - D.R. Horion St	Jaaea the lot phor to the	10/25/22 inspection.			
	Sediment Basin	See SWPPP	1/3/2020	Active	No	
Current Condition:	Sediment Basin Good Condition - 1% filled	See SWPPP I - The basin was installed		n with a permanent ri	ser. Commercial Seeding	

Current Condition:	Good Condition - 1% filled - The basin was installed prior to the 1/3/20 inspection with a permanent riser. Commercial Seeding plugged the bottom 2 rows of holes in the orifice plate prior to the 4/27/20 inspection. Hausman began cleaning out the basin prior to the 8/9/22 inspection. Hasuman cleaned out the basin prior to the 8/16/22 inspection.					
SB 3	Sediment Basin	See SWPPP	1/3/2020	Active	No	
Current Condition:			ed prior to the 1/3/20 inspection			
	plugged the bottom 4 holes in the orifice plate prior to the 4/27/20 inspection. Hausman cleaned out the basin prior to the 8/9/22 inspection.					
SB 4	Sediment Basin	See SWPPP	1/3/2020	Active	No	
Current Condition:	Good Condition - 30% filled - The basin was installed prior to the 1/3/20 inspection with a temporary riser. Commercial Seeding plugged the lowest dewatering hole and backfilled the erosion prior to the 4/27/20 inspection. Commercial seeding seeded and matted the erosion at the inlet pipe and installed a straw wattle at the stub road prior to the inspection on 5/11/20. All future recommendation of maintenance for the wattle will be included with SB 4. Riser in the basin was removed prior to the 10/11/22 inspection. E&A inspector will monitor for installation of permanent riser.					
SF 1	Silt fence	See SWPPP		Removed		
Current Condition:			fence prior to the 4/27/20 insp	ection.		
SF 2	Silt fence	See SWPPP		Removed		
Current Condition:	Removed - Wattles were removed for home construction prior to the 10/26/21 inspection. See Lot BMPs for further recommendations.					
SF 3	Silt fence	See SWPPP		Removed		
Current Condition:	Removed - Silt fence was		for active construction prior to	the 5/18/20 inspection	n.	
SF 4	Silt fence	Springfield Trail		Removed		
Current Condition:			thed or removed as of the 4/9/			
W1	Straw Wattle	SB 4 Stub Road		Removed		
Current Condition:	Removed - Tim Geis cleaned the street and removed the wattle prior to the 7/15/20 inspection, reinstallation is not necessary.					
STR	Streets	Internal/S 132nd and Main Street	1/3/2020	Active	No	
Current Condition:	Good Condition - Streets v		ack out during the 11/9/22 ins	pection.	_	
CWDDD Ciana	Mice/Other	S 132nd Street and	4/27/2020	Activo	No	
SWPPP Signs Current Condition:	Misc/Other Man Street 1/27/2020 Active No					
Current Condition:	Good Condition - E&A inspector installed SWPPP signs at the intersection of Main Street and N 10th Ave and S 132nd Street					
0. 177. 17. 01.1	and Hazel Lane during the 1/27/20 inspection. "I certify, under penalty of law, that this document and all attachments were prepared under my					
Certification Statement:						
	direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or					
	persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I					
	am aware that there are significant penalties for submitting false information including the possibility					
	of fines and imprisonment	tor knowing violations."				
Inspector Signature:	Sm Nogni			Reviewed By:	Gets Soly	