E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com

Comments:



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager **Engineering Answers** E&A - P2019.327.000 Inspector: Shaun McGuire Stage **Springfield Pines** 1 CSW-201600337 Project Name: 6/17/2023 68059 For Week Ending: Project Location: SW of 132nd Street and Platteview Road, Springfield, NE Phase I Grading: 100% Sanitary Sewer: 100% Storm Sewer: 100% Paving: 100% Seeding: 75% **Utilities:** 100% Overall Development: 70% Amount in tenths RAIN FALL AMOUNTS Date inspected Weather Conditions Time Sunday: 0.71" Rain 12:00 AM - 5:00 AM Monday: 0.00" Tuesday: 0.00" Wednesday: 0.00" 6/14/2023 Sunny 88/62 11:35 AM Thursday: 0.00" Friday: 0.00" Saturday: 0.00" Complaints: None Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Grading in Phase I was completed prior to E&A being hired to conduct SWPPP inspections (1/3/20). ed in the next 14 days? Grading in Phase I was completed prior to E&A being hired to conduct SWPPP inspections (1/3/20). Site was seeded prior to E&A being hired to conduct SWPPP inspections (1/3/20). Portion of ground to the southeast of SB 4 seeded and matted (5/11/20). Checklist Questions: re receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes reate Corrective Action? N/A lave disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion. Create Corrective Action?
No, see Findings section No, see BMPs section and Findings section Yes N/A ed with the construction activity adequately controlled on the site? Yes N/A

Comments: Site was active for homebuilding during the most recent inspection.

The School Site was graded prior to the 9/23/20 inspection. The School Site is not covered by the Springfield Pines permit (SPR-20200728-5543-GP1).

Findings / Corrective Actions (Date)

## Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section of this report.
- 2) Vacant-disturbed lots need to be stabilized.

A. Overgraded lots during homebuilding construction need to be stabilized. All builders were informed to complete by 1/17/20 when weather allows and asneeded. Not done as of the last inspection. All builders were reminded on 9/24/20, 6/24/21. As of the 3/1/2023 inspection there are no longer any overgraded inactive lots. Inactive lots still need stabilization.

3) Concrete waste was located throughout the development. D.R. Horton was informed to clean up concrete waste in SB 4 on 3/3/22. Not done as of last inspection. D.R. Horton was reminded on 3/24/22, 5/24/22, 6/2/22, 6/17/22, 6/23/22, 8/19/22, 8/31/22, 11/11/22, 3/1/23. D.R. Horton was informed to clean up concrete waste on lot 72 on 8/31/22. Not done as of last inspection. D.R. Horton was reminded on 11/11/22, 3/1/23, 4/21/23

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
Al 1	Area Inlet Protection	See SWPPP	1/3/2020	Active	No		
Current Condition:	Active - Area inlet was ins	Active - Area inlet was installed prior to the 1/3/20 inspection. The surrounding area is vegetated and the inlet drains to SB 1; no					
	inlet protection will be recommended at this time.						
Al 2	Area Inlet Protection	See SWPPP	1/3/2020	Active	Yes		
Current Condition:	Fair Condition - Area inlet	with dome grate was in:	stalled prior to the 1/3/20 inspe	ection. The surrounding	ng area was seeded and		
			ction will be recommended at t				
	inlet prior to the 2/15/22 inspection. Hausman installed 3 additional inlets and added inlet protection prior to the 11/922						
	inspection. Urban Spark c	leaned out the inlet prot	ection prior to the 11/9/22 insp	ection.			
	Inlet protection should be	cleaned out.					
		to complete by 4/26/23	. Not done as of last inspection	n. SID was informed to	o complete by 5/10/23. Not		
	done as of last inspection.	2 2111222					
AI 3	Area Inlet Protection	See SWPPP	3/9/2020	Active	No		
Current Condition:		•	prior to the 3/9/20 inspections.	Commercial Seeding	removed the remaining silt		
A1.4	fence/T-posts around the			A ('	T		
Al 4	Area Inlet Protection	See SWPPP	3/9/2020	Active	No No		
Current Condition:		•	prior to the 3/9/20 inspection. T	ne surrounding area	was seeded and matted and		
	<u> </u>		recommended at this time.		1		
CW 1	Concrete Washout	Lot 81 Replat 1		Removed			
Current Condition:			illed on Lot 81 Replat 1 prior to	•			
	· ·	•	11/20, the berm recommendat	_			
			e 6/1/20 inspection. Gene Gra		·		
	<u> </u>		ncrete washout from Lot 81 R	•			
		•	rior to the 7/7/21 inspection. G		•		
	· ·	•	monitor for reinstallation. D.R.				
			vas removed by D.R. Horton p				
		•	the 5/10/22 inspection. D.R. H		•		
		. Horton removed the co	oncrete washout prior to the 10	i/11/22 inspection, the	e E&A inspector will monitor		
ID 4	for reinstallation.	0 014/000	I		1		
IP 1	Inlet Protection	See SWPPP	+ filt + - + 4/07/00 in	Removed			
Current Condition:	not recommended.	eeding removed the inte	et filter prior to the 4/27/20 insp	ection. Thet drains to	a basin, reinstallation is		
IP 2	Inlet Protection	See SWPPP		Removed			
Current Condition:			et filter prior to the 4/27/20 insc		a basin, reinstallation is		
		Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton removed the inlet filter prior					
			reinstallation is not recommer				
IP 3	Inlet Protection	See SWPPP		Removed			
Current Condition:			et filter prior to the 4/27/20 insp		a hasin reinstallation is		
Garrent Gonation.	not recommended.	ooding romovod the line	or mice, prior to the 1/21/20 mor	ootion. Innot draine to	a baom, romotanation to		
IP 4	Inlet Protection	See SWPPP		Removed			
Current Condition:			et filter prior to the 4/27/20 ins		o a basin reinstallation is		
			ter protection prior to the 5/31/				
			asin, reinstallation is not recor	•			
IP 5	Inlet Protection	See SWPPP	, 	Removed			
Current Condition:			et filter prior to the 4/27/20 insp		a hasin reinstallation is		
ourront condition.			ter protection prior to the 5/3/2				
			asin, reinstallation is not recor				
IP 6	Inlet Protection	See SWPPP		Removed			
Current Condition:			et filter prior to the 4/27/20 insp		a basin, reinstallation is		
			ter protection prior to the 8/30/				
			asin, reinstallation is not recor	•			
IP 7	Inlet Protection	See SWPPP		Removed			
Current Condition:			et filter prior to the 4/27/20 insp		a basin, reinstallation is		
	not recommended.						
IP 8	Inlet Protection	See SWPPP		Removed			
Current Condition:			I et filter prior to the 4/27/20 insp		a basin, reinstallation is		
our on John Condition.		•					
	not recommended. D.R. Horton reinstalled inlet filter protection prior to the 8/30/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.						
ID 0	<u>'</u>		I		1		
IP 9	Inlet Protection	See SWPPP	l	Removed	1		

Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin not recommended.	n, reinstallation is				
IP 10 Inlet Protection See SWPPP Removed					
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton cleaner prior to the 6/7/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection.	d out the inlet filter				
IP 11 Inlet Protection See SWPPP Removed					
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton repaire to the 4/5/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 6/28/22 inspection. D.R. Horton repaire prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.	d the inlet filter prior				
P 12	n, reinstallation is				
not recommended.  IP 13 Inlet Protection See SWPPP Removed					
IP 13 Inlet Protection See SWPPP Removed  Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin	roinetallation is				
not recommended.	i, reinstallation is				
IP 14 Inlet Protection See SWPPP Removed					
Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin not recommended.	n, reinstallation is				
IP 15 Inlet Protection See SWPPP Removed					
Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin	n, reinstallation is				
not recommended.					
IP 16 Inlet Protection See SWPPP Removed					
Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin	n, reinstallation is				
not recommended.  IP 17 Inlet Protection See SWPPP Removed					
IP 17	roinetallation is				
not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. Inlet differ prior to the 8/2/22 inspection. Inlet differ prior to the 12/21/22 inspection.	aintained the inlet				
IP 18 Inlet Protection See SWPPP Removed					
Removed - Commercial Seeding removed the inlet filter prior to the 5/11/20 inspection. Inlet drains to a basin not recommended. D.R. Horton reinstalled inlet filter protection prior to the 5/3/22 inspection. D.R. Horton cleared out the inlet filter prior to the 8/23/22 inspection. D.R. the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.	aned out the inlet				
IP 19 Inlet Protection See SWPPP Removed					
Current Condition:         Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin not recommended.           IP 20         Inlet Protection         See SWPPP         Removed	n, reinstallation is				
Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin not recommended.	n, reinstallation is				
IP 21 Inlet Protection See SWPPP Removed					
not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton m filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet direinstallation is not recommended.	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin,				
IP 22 Inlet Protection See SWPPP Removed					
Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin not recommended.	n, reinstallation is				
P 23   Inlet Protection   See SWPPP   Removed	reinstallation is				
not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton ren prior to the 7/26/22 inspection.	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 7/26/22 inspection.				
P 24   Inlet Protection   See SWPPP   Removed	roinetallation is				
not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton renprior to the 7/26/22 inspection.					
IP 25 Inlet Protection See SWPPP Removed					
Current Condition:  Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin not recommended. D.R. Horton removed the inlet filter prior to the 5/31/22 inspection.	n, reinstallation is				
IP 26 Inlet Protection See SWPPP 3/29/2022 Active	Yes				
is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton filter prior to the 8/16/22 inspection.	Fair Condition - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 8/16/22 inspection.  Inlet filter should be removed.				
Inlet filter should be removed.					
D.R. Horton was informed to complete by 11/16/22. Not done as of last inspection. D.R. Horton was reminded SID was informed to complete by 5/10/23. Not done as of last inspection.  IP 27  Inlet Protection See SWPPP Removed	d on 3/1/23, 4/21/23.				

0	10 10 10 10 10 10 10 10 10 10 10 10 10 1					
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is					
	not recommended.					
IP 28	Inlet Protection See SWPPP Removed					
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is					
	not recommended.					
Lot 1 Replat 1	Individual Lot					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 4/12/22 inspection.					
Lot 4 Replat 3	Individual Lot					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 11/9/22 inspection.					
Lot 6 Replat 1	Individual Lot Lot 6 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 11/9/22 inspection.					
Lot 7 Replat 1	Individual Lot Lot 7 Replat 1 Removed					
Current Condition:	Removed - Carlson Tile Inc. sodded the lot prior to the 6/21/22 inspection.					
Lot 10 Replat 1	Individual Lot Lot 10 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 4/19/22 inspection.					
Lot 11 Replat 1	Individual Lot Lot 11 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 4/19/22 inspection.					
Lot 13 Replat 1	Individual Lot Lot 13 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 4/19/22 inspection.					
Lot 19 Replat 1	Individual Lot   Lot 19 Replat 1   Removed					
Current Condition:	Removed - Brooks Builders sodded the lot prior to the 5/10/22 inspection.					
Lot 20 Replat 1	Individual Lot   Lot 20 Replat 1   Removed					
Current Condition:	Active - Sundown Homes LLC sodded the lot prior to the 8/23/22 inspection.					
Lot 22 Replat 1	Individual Lot Lot 22 Replat 1 Removed					
Current Condition:	Removed - Urban Spark sodded the lot prior to the 5/17/22 inspection.					
Lot 23 Replat 1	Individual Lot Lot 23 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 4/12/22 inspection.					
Lot 28 Replat 1	Individual Lot Lot 28 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 4/12/22 inspection.					
Lot 30 Replat 1	Individual Lot Lot 30 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 11/2/22 inspection.					
Lot 33 Replat 1	Individual Lot Lot 33 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 5/17/22 inspection.					
Lot 43 Replat 1	Individual Lot Lot 43 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 7/26/22 inspection.					
Lot 45 Replat 1	Individual Lot Lot 45 Replat 1 Removed					
Current Condition:	Removed - Brooks Builders Inc. sodded the lot prior to the 4/26/23 inspection.					
Lot 46 Replat 1	Individual Lot Lot 46 Replat 1 Removed					
Current Condition:	Removed - Epic Custom Homes sodded the lot prior to the 5/17/22 inspection.					
Lot 48 Replat 1	Individual Lot Lot 48 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 10/25/22 inspection.					
Lot 49 Replat 1	Individual Lot Lot 49 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 10/11/22 inspection.					
Lot 51 Replat 1	Individual Lot Lot 51 Replat 1 Removed					
Current Condition:	Removed - D.R. Horton sodded the lot prior to the 10/11/22 inspection.					
Lot 55 Replat 1	Individual Lot Lot 55 Replat 1 5/11/2020 Active Yes					
Current Condition:	Fair Condition - Gene Graves installed silt fence on the side of the lot prior to the inspection on 5/11/20. Future silt fence					
	maintenance will be sent to the builder of the lot when construction begins. Minor damage to the silt fence was observed during					
	the 6/22/21 inspection, the inspector will monitor. D&E Custom Building began excavation on the lot prior to the 8/23/22					
	inspection. Dirt piles were observed in the ROW during the 8/23/22 inspection. D&E Custom Building removed the concrete					
	waste and the dirt piles from the ROW prior to the 9/13/22 inspection. D&E Custom Building cleaned the streets prior to the					
	5/24/23 inspection.					
	and the second s					
	1.) Silt fence perimeter should be installed.					
	2.) Wattles should be installed along the front of the lot.					
	1.) Landmark Performance Corporation was informed to complete by 8/30/22. Not done as of last inspection. Landmark					
	Performance Corporation was reminded on 11/3/22. D&E Custom Building was informed to complete by 3/8/23. Not done as of					
	last inspection. D&E Custom Building was reminded on 4/20/23.					
	2.) Landmark Performance Corporation was informed to complete by 8/30/22. Not done as of last inspection. Landmark					
	Performance Corporation was reminded on 11/3/22. D&E Custom Building was informed to complete by 3/8/23. Not done as of					
	last inspection. D&E Custom Building was reminded on 4/20/23.					
Let E7 Deplot 4						
Lot 57 Replat 1						
Current Condition:	Removed - Pacesetter Homes sodded the lot prior to the 7/12/22 inspection.					
Lot EO Dealet 4						
Lot 59 Replat 1	Individual Lot Lot 59 Replat 1 Removed					
Current Condition:	Removed - Nelson Builders sodded the lot prior to the 6/21/22 inspection.					
Current Condition: Lot 63 Replat 1	Removed - Nelson Builders sodded the lot prior to the 6/21/22 inspection.  Individual Lot Lot 63 Replat 1 Removed					
Current Condition: Lot 63 Replat 1 Current Condition:	Removed - Nelson Builders sodded the lot prior to the 6/21/22 inspection.  Individual Lot Lot 63 Replat 1 Removed  Removed - Urban Spark soddedf the lot prior to the 5/10/23 inspection.					
Current Condition: Lot 63 Replat 1 Current Condition: Lot 71 Replat 1	Removed - Nelson Builders sodded the lot prior to the 6/21/22 inspection.  Individual Lot Lot 63 Replat 1 Removed  Removed - Urban Spark soddedf the lot prior to the 5/10/23 inspection.  Individual Lot Lot 71 Replat 1 Removed					
Current Condition: Lot 63 Replat 1 Current Condition: Lot 71 Replat 1 Current Condition:	Removed - Nelson Builders sodded the lot prior to the 6/21/22 inspection.  Individual Lot Lot 63 Replat 1 Removed  Removed - Urban Spark soddedf the lot prior to the 5/10/23 inspection.  Individual Lot Lot 71 Replat 1 Removed  Removed - D.R. Horton sodded the lot prior to the 8/16/22 inspection.					
Current Condition: Lot 63 Replat 1 Current Condition: Lot 71 Replat 1	Removed - Nelson Builders sodded the lot prior to the 6/21/22 inspection.  Individual Lot					
Current Condition: Lot 63 Replat 1 Current Condition: Lot 71 Replat 1 Current Condition:	Removed - Nelson Builders sodded the lot prior to the 6/21/22 inspection.  Individual Lot Lot 63 Replat 1 Removed  Removed - Urban Spark soddedf the lot prior to the 5/10/23 inspection.  Individual Lot Lot 71 Replat 1 Removed  Removed - D.R. Horton sodded the lot prior to the 8/16/22 inspection.					
Current Condition: Lot 63 Replat 1 Current Condition: Lot 71 Replat 1 Current Condition: Lot 78 Replat 1	Removed - Nelson Builders sodded the lot prior to the 6/21/22 inspection.  Individual Lot					

Current Condition:	Fair Condition - Urban Spark began excavation of the lot prior to the 4/19/22 inspection. Dirt pile was noticed in the ROW during the 4/26/22 inspection. Urban Spark installed silt fence on the south side of the lot prior to the 4/26/22 inspection. Urban Spark removed the dirt pile from the ROW prior to the 5/17/22 inspection. Urban Spark cleaned the streets and sidewalk prior to the 5/10/23 inspection.  1.) Outflow pipe behind the lot should be cleaned out and uncovered. 2.) Silt fence should be repaired and trenched in on the side of the lot.						
	<ol> <li>Sediment that washed on to lot 83 should be cleaned up.</li> <li>Urban Spark was informed to complete by 6/28/22. Not done as of last inspection. Urban Spark was reminded on 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23</li> <li>Urban Spark was informed to complete by 4/26/23. Not done as of last inspection.</li> </ol>						
	3.) Urban Spark was informed to complete by 4/26/23. Not done as of last inspection.						
Lot 90 Replat 1 Current Condition:	Individual Lot Removed - D.R. Horton so	Lot 90 Replat 1	11/0/22 inapaction	Removed			
Lot 96 Replat 1	Individual Lot	Lot 96 Replat 1	11/9/22 Inspection.	Removed			
Current Condition:	Removed - D.R. Horton so		8/16/22 inspection.				
Lot 97 Replat 1	Individual Lot	Lot 97 Replat 1		Removed			
Current Condition:	Removed - D.R. Horton so		12/7/22 inspection.	Damayad			
Lot 100 Replat 1 Current Condition:	Individual Lot Removed - Woodland Ho	Lot 100 Replat 1	to the 1/4/22 inspection	Removed			
Lot 101 Replat 1	Individual Lot	Lot 101 Replat 1	10/25/2021	Active	Yes		
Current Condition:			on the lot prior to the 10/25/21				
Lot 105 Replat 1 Current Condition: Lot 112 Replat 1 Current Condition:	fence at the rear of the lot prior to the 1/4/22 inspection. Maintenance recommendations have changed. Home owner removed the dirt piles from the ROW prior to the 2/15/22 inspection.  1.) Silt fence should be repaired/reinstalled at the rear of the lot or the lot should be sodded. 2.) Wattles should be installed on the front of the lot or the lot should be sodded. 3.) Silt fence should be cleaned out and sediment that has fallen past the property line to the east should be cleaned up. 4.) Silt fence should be installed on the sides of the lot or the lot should be sodded. 5.) Sediment that has washed on to adjoining lots should be cleaned up. 1.) Urban Spark was informed to complete by 12/14/21. Not done as of the last inspection. Urban Spark was reminded on 1/5/22, 3/8/22, 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 31/123, 4/20/23. Home owner was informed to complete by 5/3/23. 2.) Urban Spark was informed to complete by 12/14/21. Not done as of the last inspection. Urban Spark was reminded on 1/5/22, 3/8/22, 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed to complete by 5/3/23. 3.) Urban Spark was informed to complete by 2/22/22. Not done as of last inspection. Urban Spark was reminded on 3/8/22, 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed to complete by 5/3/23. 4.) Urban Spark was informed to complete by 3/12/22. Not done as of last inspection. Urban Spark was reminded on 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 13/23, 4/20/23. Home owner was informed to complete by 5/3/23. 5.) Urban Spark was informed to complete by 3/12/22. Not done as of last inspection. Urban Spark was reminded on 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed to complete by 5/3/23. 5.) Urban Spark was informed to complete by 3/12/22. Not done as of last inspection. Urban Spark was reminded on 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed to co						
Lot 116 Replat 1 Current Condition:	Individual Lot Removed - D.R. Horton so	Lot 116 Replat 1	11/2/22 inspection	Removed			
Lot 119 Replat 1	Individual Lot	Lot 119 Replat 1	7/19/2022	Active	No		
Current Condition:	Good Condition - D.R. Ho	rton installed wattles alo	ng the front of the lot prior to	the 7/19/22 inspection.	Lot is currently inactive.		
Lot 120 Replat 1 Current Condition:	Individual Lot	Lot 120 Replat 1	3/1/2022	Active	Yes		
Lot 126 Replat 1	Fair Condition - D.R. Horton installed perimeter wattles prior to the 3/1/22 inspection. D.R. Horton began excavating the lot prior to the 4/26/22 inspection. D.R. Horton installed silt fence at the rear of the lot prior to the 7/12/22 inspection. D.R. Horton sodded the lot prior to the 11/9/22 inspection. Silt fence still remains at the rear of the lot.  Silt fence should be removed.  D.R. Horton was informed to complete by 9/6/22. Not done as of last inspection. D.R. Horton was reminded on 11/11/22, 3/1/23, 4/21/23  Individual Lot Lot 127 Replat 1 11/23/2021 Active No						
Current Condition:							
	Active - D.R. Horton staked down a portable toilet on Lot 126 prior to the 11/23/21 inspection. The lot is currently inactive. D.R. Horton resecured the portable toilet prior to the 3/29/22 inspection. D.R. Horton removed the portable toilet from the lot prior to the 11/16/22 inspection.						
Lot 127 Replat 1 Current Condition:	Individual Lot Removed - D.R. Horton so	Lot 127 Replat 1	10/25/22 inspection	Removed			
Lot 128 Replat 1	Individual Lot	Lot 128 Replat 1	TOTAUTAA HISPEUUUII.	Removed			
Current Condition:	Removed - D.R. Horton so		10/25/22 inspection.				
SB 1	Sediment Basin	See SWPPP	1/3/2020	Active	No		
Current Condition:	plugged the bottom 4 hole	s in the orifice plate prio	ed prior to the 1/3/20 inspection to the 4/27/20 inspection. He unplugged and the basin is 1/3/2020	ausman cleaned out th	e basin prior to the 8/9/22		
-	•	•	-				

Current Condition:	Good Condition - 1% filled - The basin was installed prior to the 1/3/20 inspection with a permanent riser. Commercial Seeding plugged the bottom 2 rows of holes in the orifice plate prior to the 4/27/20 inspection. Hausman began cleaning out the basin prior to the 8/9/22 inspection. Hausman cleaned out the basin prior to the 8/9/22 inspection. Bottom 2 holes of the orifice plate					
	were unplugged and the b					
SB 3	Sediment Basin	See SWPPP	1/3/2020	Active	No	
Current Condition:	Good Condition - 1% filled	d - The basin was installed	prior to the 1/3/20 inspec	tion with a permanent ris	er. Commercial Seeding	
	plugged the bottom 4 holes in the orifice plate prior to the 4/27/20 inspection. Hausman cleaned out the basin prior to the 8/9/22					
	inspection. Bottom 4 holes of the orifice plate were unplugged and the basin is now functioning as a post construction basin as of					
	the 6/7/23 inspection.					
SB 4	Sediment Basin	See SWPPP	1/3/2020	Active	No	
Current Condition:	Good Condition - 30% fille	ed - The basin was installe	ed prior to the 1/3/20 inspe	ection with a temporary ris	ser. Commercial Seeding	
	plugged the lowest dewat					
	matted the erosion at the	0			Ü	
	recommendation of maint					
		will monitor for installation				
SF 1	Silt fence	See SWPPP	<u> </u>	Removed		
Current Condition:		seeding removed the silt fe	ence prior to the 4/27/20 in			
SF 2	Silt fence	See SWPPP		Removed		
Current Condition:	Removed - Wattles were	removed for home constru	iction prior to the 10/26/21	I inspection. See Lot BM	IPs for further	
	recommendations.					
SF 3	Silt fence	See SWPPP		Removed		
Current Condition:		removed in preparation for	or active construction prior		า.	
SF 4	Silt fence	Springfield Trail	•	Removed		
Current Condition:	Removed - The remaining	wattles have been mulch	ed or removed as of the	1/9/21 inspection.		
W1	Straw Wattle	SB 4 Stub Road		Removed		
Current Condition:	Removed - Tim Geis clea	ned the street and remove	ed the wattle prior to the 7	/15/20 inspection, reinsta	llation is not necessary.	
		Internal/S 132nd and				
STR	Streets	Main Street	1/3/2020	Active	No	
Current Condition:	Good Condition - Streets	were clean and free of trac	ck out during the 11/9/22 i	inspection.		
		S 132nd Street and				
SWPPP Signs	Misc/Other	Man Street	1/27/2020	Active	No	
Current Condition:	Good Condition - E&A inspector installed SWPPP signs at the intersection of Main Street and N 10th Ave and S 132nd Street					
	and Hazel Lane during the 1/27/20 inspection.					
Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my					
	direction or supervision in accordance with a system designed to assure that qualified personnel					
	properly gathered and evaluated the information submitted. Based on my inquiry of the person or					
	persons who manage the system or those persons directly responsible for gathering the information,					
	the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I					
	am aware that there are significant penalties for submitting false information including the possibility					
	of fines and imprisonment for knowing violations."					
	// N/C -					
	San Moyn				Sit Sil	
Inspector Signature:	6	1		Reviewed By:		