E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com

Comments:



Zachary A. Jilek, CPESC, CISEC **Engineering Answers** Environmental Services Dept. Manager E&A - P2019.327.000 Inspector: Shaun McGuire Stage **Springfield Pines** 1 CSW-201600337 Project Name: 7/15/2023 68059 For Week Ending: Project Location: SW of 132nd Street and Platteview Road, Springfield, NE Phase I Grading: 100% Sanitary Sewer: 100% Storm Sewer: 100% Paving: 100% Seeding: 75% **Utilities:** 100% Overall Development: 70% Amount in tenths RAIN FALL AMOUNTS Date inspected Weather Conditions Time Week 1 Sunday: 0.00" Monday: 0.15" 0.00" Tuesday: Wednesday: 0.42" 7/12/2023 Sunny 84/63 11:50 AM Thursday: 0.00" Friday: 0.23" Saturday: 0 00' Complaints: None Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Grading in Phase I was completed prior to E&A being hired to conduct SWPPP inspections (1/3/20). ed in the next 14 days? Grading in Phase I was completed prior to E&A being hired to conduct SWPPP inspections (1/3/20). Site was seeded prior to E&A being hired to conduct SWPPP inspections (1/3/20). Portion of ground to the southeast of SB 4 seeded and matted (5/11/20). Checklist Questions: re receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes reate Corrective Action? N/A lave disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion. Create Corrective Action?
No, see Findings section No, see BMPs section and Findings section Yes N/A ed with the construction activity adequately controlled on the site? Yes N/A

Comments: Site was active for homebuilding during the most recent inspection.

The School Site was graded prior to the 9/23/20 inspection. The School Site is not covered by the Springfield Pines permit (SPR-20200728-5543-GP1).

Findings / Corrective Actions (Date)

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section of this report.
- 2) Concrete waste was located throughout the development. D.R. Horton was informed to clean up concrete waste in SB 4 on 3/3/22. Not done as of last inspection. D.R. Horton was reminded on 3/24/22, 5/24/22, 6/2/22, 6/17/22, 6/23/22, 8/19/22, 8/31/22, 11/11/22, 3/1/23, 4/21/23, 6/21/23

| Unique Name | Туре | Location | Projected Install Date | Status | Maintenance | | |
|-------------------------|---|-----------------------------|--|--------------------------|--------------------------------|--|--|
| Al 1 | Area Inlet Protection | See SWPPP | 1/3/2020 | Active | No | | |
| Current Condition: | Active - Area inlet was ins | talled prior to the 1/3/20 | inspection. The surrounding a | area is vegetated and | the inlet drains to SB 1; no | | |
| | inlet protection will be reco | | | | | | |
| Al 2 | Area Inlet Protection | See SWPPP | 1/3/2020 | Active | Yes | | |
| Current Condition: | | | stalled prior to the 1/3/20 inspection will be recommended at | | | | |
| | | | ction will be recommended at talled 3 additional inlets and ad | | | | |
| | | | ection prior to the 11/9/22 insp | | 1101 to the 11/922 | | |
| | mopositom ordan opani o | ouriou out aro amot prot | 5 such prior to the 11,6/22 map | | | | |
| | Inlet protection should be | cleaned out. | | | | | |
| | | | | | | | |
| | | | . Not done as of last inspection | n. SID was informed to | o complete by 5/10/23. Not | | |
| Al 3 | done as of last inspection. Area Inlet Protection | See SWPPP | 3/9/2020 | Active | No | | |
| Current Condition: | | | prior to the 3/9/20 inspections. | | | | |
| | fence/T-posts around the | • | • | Commonda Cooding | romovou ino romaning on | | |
| Al 4 | Area Inlet Protection | See SWPPP | 3/9/2020 | Active | No | | |
| Current Condition: | Active - Area inlet with do | me grate was installed p | rior to the 3/9/20 inspection. T | he surrounding area | was seeded and matted and | | |
| | the inlet drains to SB 2; no | inlet protection will be | recommended at this time. | | | | |
| CW 1 | Concrete Washout | Lot 81 Replat 1 | | Removed | | | |
| Current Condition: | | | illed on Lot 81 Replat 1 prior to | | | | |
| | · | • | 11/20, the berm recommendate | • | | | |
| | | | e 6/1/20 inspection. Gene Gra increte washout from Lot 81 R | | • | | |
| | - | | rior to the 7/7/21 inspection. | • | | | |
| | | • | monitor for reinstallation. D.R. | | • | | |
| | | | vas removed by D.R. Horton p | | | | |
| | installed a concrete wash | out on to lot 117 prior to | the 5/10/22 inspection. D.R. H | forton cleaned out the | concrete washout prior to | | |
| | | . Horton removed the co | oncrete washout prior to the 10 | 0/11/22 inspection, the | E&A inspector will monitor | | |
| ID 4 | for reinstallation. | C CWDDD | I | D | 1 | | |
| IP 1 Current Condition: | Inlet Protection | See SWPPP | Let filter prior to the 4/27/20 insp | Removed | a hasin reinstallation is | | |
| Current Condition. | not recommended. | ecuing removed the init | et liiter prior to trie 4/21/20 iris | dection. The drains to | a basiii, reiristaliation is | | |
| IP 2 | Inlet Protection | See SWPPP | | Removed | | | |
| Current Condition: | | | et filter prior to the 4/27/20 insp | | | | |
| | not recommended. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. | | | | | | |
| ID 0 | · | | remstaliation is not recommen | | 1 | | |
| IP 3 Current Condition: | Inlet Protection | See SWPPP | Let filter prior to the 4/27/20 insp | Removed | a hasin reinstallation is | | |
| Current Condition. | not recommended. | ecang removed the inte | et litter prior to the 4/27/20 ms | Dection. The drains to | a basin, remstaliation is | | |
| IP 4 | Inlet Protection | See SWPPP | | Removed | | | |
| Current Condition: | | | et filter prior to the 4/27/20 ins | | o a basin, reinstallation is | | |
| | | | ter protection prior to the 5/31/ | | | | |
| | prior to the 12/21/22 inspe | ection. Inlet drains to a b | asin, reinstallation is not recor | nmended. | | | |
| IP 5 | Inlet Protection | See SWPPP | | Removed | | | |
| Current Condition: | | • | et filter prior to the 4/27/20 insp | | | | |
| | | | ter protection prior to the 5/3/2 | • | rton removed the inlet filter | | |
| IP 6 | Inlet Protection | | asin, reinstallation is not recor I | Removed | | | |
| Current Condition: | | | t filter prior to the 4/27/20 insp | | a basin, reinstallation is | | |
| | | • | ter protection prior to the 8/30/ | | | | |
| | prior to the 12/21/22 inspe | ection. Inlet drains to a b | asin, reinstallation is not recor | nmended. | | | |
| IP 7 | Inlet Protection | See SWPPP | | Removed | | | |
| Current Condition: | | eeding removed the inle | et filter prior to the 4/27/20 insp | pection. Inlet drains to | a basin, reinstallation is | | |
| | not recommended. | | T | T | 1 | | |
| IP 8 | Inlet Protection | See SWPPP | - | Removed | - 1 | | |
| Current Condition: | | | et filter prior to the 4/27/20 insp | | | | |
| | | | ter protection prior to the 8/30/ asin, reinstallation is not recor | • | orton removed the iniet filter | | |
| IP 9 | Inlet Protection | See SWPPP | | Removed | 1 | | |
| Current Condition: | | | I et filter prior to the 4/27/20 insp | | a basin, reinstallation is | | |
| | not recommended. | | | | , | | |
| IP 10 | Inlet Protection | See SWPPP | | Removed | | | |
| 11 10 | IIIICE I TOLECTION | OCC OVVIII | ı | Romoveu | 1 | | |

| Current Condition: | Removed - Commercial Seeding removed the inle | et filter prior to the 4/27/20 inst | pection. Inlet drains to | a hasin reinstallation is not |
|------------------------------------|---|--------------------------------------|-----------------------------|--------------------------------|
| Current Condition. | recommended. D.R. Horton reinstalled inlet filter | | | |
| | prior to the 6/7/22 inspection. D.R. Horton reinsta | • | • | |
| | filter prior to the 12/21/22 inspection. Inlet drains t | o a basin, reinstallation is not | recommended. | |
| | | | | |
| IP 11 | Inlet Protection See SWPPP | | Removed | |
| Current Condition: | Removed - Commercial Seeding removed the inle | | | |
| | recommended. D.R. Horton reinstalled inlet filter to the 4/5/22 inspection. D.R. Horton cleaned out | • | • | • |
| | prior to the 12/21/22 inspection. Inlet drains to a b | • | | onton removed the iniet liner |
| | phot to the 12/21/22 moposion. mot draine to a s | don', romotanation to not room | illionada. | |
| IP 12 | Inlet Protection See SWPPP | | Removed | |
| Current Condition: | Removed - Commercial Seeding removed the inle | et filter prior to the 4/27/20 insp | pection. Inlet drains to | a basin, reinstallation is |
| ID 40 | not recommended. | T | D | T |
| IP 13 Current Condition: | Inlet Protection See SWPPP Removed - Commercial Seeding removed the inle | t filter prior to the 4/27/20 incr | Removed | a hasin rainstallation is |
| Gurrent Goriation. | not recommended. | or lines prior to the 4/27/20 map | occitori. Iriict didirio to | a basin, remotaliation is |
| IP 14 | Inlet Protection See SWPPP | | Removed | |
| Current Condition: | Removed - Commercial Seeding removed the inle | et filter prior to the 4/27/20 insp | | a basin, reinstallation is |
| | not recommended. | | | |
| IP 15 | Inlet Protection See SWPPP | | Removed | |
| Current Condition: | Removed - Commercial Seeding removed the inle | et filter prior to the 4/27/20 insp | pection. Inlet drains to | a basin, reinstallation is |
| IP 16 | not recommended. Inlet Protection See SWPPP | | Removed | I |
| Current Condition: | Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet | Let filter prior to the 4/27/20 inst | | l a hasin reinstallation is |
| | not recommended. | 5. m.e. pe. te te ./2./2eep | occurrent much didmic to | a baom, romotanation to |
| IP 17 | Inlet Protection See SWPPP | | Removed | |
| Current Condition: | Removed - Commercial Seeding removed the inle | | | |
| | not recommended. D.R. Horton reinstalled inlet fil | | • | |
| | filter prior to the 8/2/22 inspection. D.R. Horton re reinstallation is not recommended. | moved the inlet filter prior to th | ie 12/21/22 inspection | . Inlet drains to a basin, |
| IP 18 | Inlet Protection See SWPPP | 1 | Removed | |
| Current Condition: | Removed - Commercial Seeding removed the inle | et filter prior to the 5/11/20 insp | | a basin, reinstallation is |
| | not recommended. D.R. Horton reinstalled inlet fil | | | |
| | filter prior to the 7/12/22 inspection. D.R. Horton of | | | |
| | the inlet filter prior to the 12/21/22 inspection. Inle | t drains to a basin, reinstallatio | on is not recommende | d. |
| IP 19 | Inlet Protection See SWPPP | | Removed | I |
| Current Condition: | Removed - Commercial Seeding removed the inle | Let filter prior to the 4/27/20 inst | | a basin reinstallation is |
| | not recommended. | 721720 mor | occion. Iniot dianio to | a baom, romotanation to |
| IP 20 | Inlet Protection See SWPPP | | Removed | |
| Current Condition: | Removed - Commercial Seeding removed the inle | et filter prior to the 4/27/20 insp | pection. Inlet drains to | a basin, reinstallation is |
| IP 21 | not recommended. Inlet Protection See SWPPP | 1 | Removed | <u> </u> |
| Current Condition: | Removed - Commercial Seeding removed the inle | Let filter prior to the 4/27/20 inst | | a basin reinstallation is |
| | not recommended. D.R. Horton reinstalled inlet fil | | | |
| | filter prior to the 8/2/22 inspection. D.R. Horton re | moved the inlet filter prior to th | e 12/21/22 inspection | . Inlet drains to a basin, |
| | reinstallation is not recommended. | | | |
| IP 22 | Inlet Protection See SWPPP | . (1) | Removed | |
| Current Condition: | Removed - Commercial Seeding removed the inlunot recommended. | et filter prior to the 4/27/20 insp | pection. Inlet drains to | a basın, reinstallation is |
| IP 23 | Inlet Protection See SWPPP | T | Removed | |
| Current Condition: | Removed - Commercial Seeding removed the inle | Let filter prior to the 4/27/20 inst | | a basin, reinstallation is |
| | not recommended. D.R. Horton reinstalled inlet fil | | | |
| | prior to the 7/26/22 inspection. | | | |
| IP 24 | Inlet Protection See SWPPP | | Removed | |
| Current Condition: | Removed - Commercial Seeding removed the inle | | | |
| | not recommended. D.R. Horton reinstalled inlet fil | ter protection prior to the 3/1/2 | 22 inspection. D.R. Ho | rton removed the inlet filter |
| IP 25 | prior to the 7/26/22 inspection. Inlet Protection See SWPPP | | Removed | |
| Current Condition: | Removed - Commercial Seeding removed the inle | Let filter prior to the 4/27/20 inst | | l a hasin reinstallation is |
| | not recommended. D.R. Horton removed the inlet | | | a baom, romotanation to |
| IP 26 | Inlet Protection See SWPPP | · · · | Removed | I |
| Current Condition: | Removed - SID removed the inlet filter prior to the | 6/28/23 inspection. | Removed | |
| IP 27 | Inlet Protection See SWPPP | | Removed | |
| Current Condition: | Removed - Commercial Seeding removed the inle | et filter prior to the 4/27/20 insp | pection. Inlet drains to | a basin, reinstallation is |
| IP 28 | not recommended. | I | Domoved | 1 |
| Current Condition: | Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet | Let filter prior to the 4/27/20 incr | Removed | a basin reinstallation is |
| our on condition. | not recommended. | 7 Prior to tile 4/21/20 IIIS | Journal Intermediates to | a sasiii, iciiistailatioii is |
| Lot 1 Replat 1 | Individual Lot Lot 1 Replat 1 | | Removed | |
| Current Condition: | Removed - D.R. Horton sodded the lot prior to the | 4/12/22 inspection. | | |
| Lot 4 Replat 3 Current Condition: | Individual Lot Lot 4 Replat 3 Removed - D.R. Horton sodded the lot prior to the | 11/0/22 inspection | Removed | |
| Lot 6 Replat 1 | Individual Lot Lot 6 Replat 1 | FITALZ INSPECTION. | Removed | |
| Current Condition: | Removed - D.R. Horton sodded the lot prior to the | 11/9/22 inspection. | | |
| Lot 7 Replat 1 | Individual Lot Lot 7 Replat 1 | | Removed | |
| | | | | |

| Current Condition: | Removed - Carlson Tile Ir | oc coddod the let prior to | the 6/21/22 inspection | | | |
|--------------------|---|-------------------------------|------------------------------------|------------------------|-----------------------------|--|
| Lot 10 Replat 1 | Individual Lot | Lot 10 Replat 1 | the 6/21/22 inspection. | Removed | l | |
| Current Condition: | Removed - D.R. Horton se | | 4/10/22 inspection | Removed | | |
| Lot 11 Replat 1 | Individual Lot | Lot 11 Replat 1 | 14/19/22 Inspection. | Removed | 1 | |
| Current Condition: | Removed - D.R. Horton s | | 4/40/22 increation | Removed | | |
| | | | 4/19/22 inspection. | Domovad | 1 | |
| Lot 13 Replat 1 | Individual Lot | Lot 13 Replat 1 | 4/40/00 in an artism | Removed | | |
| Current Condition: | Removed - D.R. Horton se | | 4/19/22 inspection. | Б 1 | T | |
| Lot 19 Replat 1 | Individual Lot | Lot 19 Replat 1 | | Removed | | |
| Current Condition: | Removed - Brooks Builde | | the 5/10/22 inspection. | | 1 | |
| Lot 20 Replat 1 | Individual Lot | Lot 20 Replat 1 | | Removed | | |
| Current Condition: | | | to the 8/23/22 inspection. | | 1 | |
| Lot 22 Replat 1 | Individual Lot | Lot 22 Replat 1 | | Removed | | |
| Current Condition: | Removed - Urban Spark s | | e 5/17/22 inspection. | | | |
| Lot 23 Replat 1 | Individual Lot | Lot 23 Replat 1 | | Removed | | |
| Current Condition: | Removed - D.R. Horton s | odded the lot prior to the | 4/12/22 inspection. | | | |
| Lot 26 Replat 1 | Individual Lot | Lot 26 Replat 1 | 7/12/2023 | Active | No | |
| Current Condition: | Good Condition - Carlso | n Tile Inc began excav | ation of the lot prior to the 7 | /12/23 inspection. Ca | arlson Tile Inc installed | |
| | silt fence on the side an | d front of the lot prior t | to the 7/12/23 inspection. | | | |
| Lot 28 Replat 1 | Individual Lot | Lot 28 Replat 1 | - | Removed | I | |
| | | | 4/40/00 in an artism | Removed | | |
| Current Condition: | Removed - D.R. Horton se | badea the lot prior to the | 4/12/22 inspection. | Daman | T | |
| Lot 30 Replat 1 | Individual Lot | Lot 30 Replat 1 | 14/0/00: | Removed | | |
| Current Condition: | Removed - D.R. Horton se | | I I I/Z/ZZ INSPECTION. | | I | |
| Lot 33 Replat 1 | Individual Lot | Lot 33 Replat 1 | 5/47/00: | Removed | l | |
| Current Condition: | Removed - D.R. Horton se | | | | | |
| Lot 36 Replat 1 | Individual Lot | Lot 36 Replat 1 | 6/21/2023 | Active | No | |
| Current Condition: | | | ation of the lot prior to the 6/21 | 1/23 inspection. Paces | setter Homes installed silt | |
| | fence on the side and rea | r of the lot prior to the 6/2 | 21/23 inspection. | | | |
| Lot 43 Replat 1 | Individual Lot | Lot 43 Replat 1 | | Removed | | |
| Current Condition: | Removed - D.R. Horton s | | 7/26/22 inspection | Nemoveu | 1 | |
| Lot 45 Replat 1 | Individual Lot | Lot 45 Replat 1 | TIZOIZZ ITISPECTION. | Removed | | |
| | | | or to the 4/26/23 inspection. | Removed | l . | |
| Current Condition: | | | or to the 4/26/23 inspection. | Daman | T | |
| Lot 46 Replat 1 | Individual Lot | Lot 46 Replat 1 | | Removed | | |
| Current Condition: | | | ior to the 5/17/22 inspection. | | 1 | |
| Lot 48 Replat 1 | Individual Lot | Lot 48 Replat 1 | | Removed | | |
| Current Condition: | Removed - D.R. Horton se | | 10/25/22 inspection. | | 1 | |
| Lot 49 Replat 1 | Individual Lot | Lot 49 Replat 1 | | Removed | | |
| Current Condition: | Removed - D.R. Horton se | | 10/11/22 inspection. | | | |
| Lot 51 Replat 1 | Individual Lot | Lot 51 Replat 1 | | Removed | | |
| Current Condition: | Removed - D.R. Horton s | odded the lot prior to the | 10/11/22 inspection. | | | |
| Lot 55 Replat 1 | Individual Lot | Lot 55 Replat 1 | | Removed | | |
| Current Condition: | Removed - D&E Custom | Building sodded the lot p | prior to the 6/28/23 inspection. | | | |
| Lot 57 Replat 1 | Individual Lot | Lot 57 Replat 1 | | Removed | | |
| Current Condition: | | | r to the 7/12/22 inspection. | | • | |
| Lot 59 Replat 1 | Individual Lot | Lot 59 Replat 1 | 10 1.10 17 12/22 1110000110111 | Removed | | |
| Current Condition: | Removed - Nelson Builde | | the 6/21/22 inspection | rtomovou | | |
| Lot 63 Replat 1 | Individual Lot | Lot 63 Replat 1 | the 6/21/22 mapeedion. | Removed | | |
| Current Condition: | Removed - Urban Spark s | | ne 5/10/23 inspection | removed | <u> </u> | |
| Lot 71 Replat 1 | Individual Lot | Lot 71 Replat 1 | le 3/10/23 irispection. | Removed | 1 | |
| Current Condition: | Removed - D.R. Horton se | | 9/16/22 inapportion | Removed | | |
| | Individual Lot | Lot 78 Replat 1 | 6/16/22 Inspection. | Removed | 1 | |
| Lot 78 Replat 1 | | | t- th- 7/40/00 iti | Removed | | |
| Current Condition: | Removed - Sundown Hon | les sodded the lot prior t | to trie 7/19/22 inspection. | A -4! | \/ | |
| Lot 82 Replat 1 | Individual Lot | Lot 82 Replat 1 | | Active | Yes | |
| Current Condition: | | | the lot prior to the 4/19/22 insp | | | |
| | | | ence on the south side of the I | | | |
| | | the ROW prior to the 5/ | 17/22 inspection. Urban Spark | cleaned the streets a | and sidewalk prior to the | |
| | 5/10/23 inspection. | | | | | |
| | | | | | | |
| | 1.) Outflow pipe behind th | e lot should be cleaned | out and uncovered | | | |
| | | | | | | |
| | 2.) Silt fence should be repaired and trenched in on the side of the lot.3.) Sediment that washed on to lot 83 should be cleaned up.4.) Sidewalk should be cleaned. | | | | | |
| | | | | | | |
| | 4.) Sidewalk should be cit | earieu. | | | | |
| | | | 2/22 N | | | |
| | 1.) Urban Spark was informed to complete by 6/28/22. Not done as of last inspection. Urban Spark was reminded on 8/2/22, | | | | | |
| | 11/3/22, 11/9/22, 3/1/23, 4/20/23, 6/21/23 2.) Urban Spark was informed to complete by 4/26/23. Not done as of last inspection. Urban Spark was reminded on 6/21/23. 3.) Urban Spark was informed to complete by 4/26/23. Not done as of last inspection. Urban Spark was reminded on 6/21/23. 4.) Urban Spark was informed to complete by 6/22/23. Not done as of last inspection. | | | | | |
| | | | | | | |
| | | | | | | |
| 1 | | | | | | |
| 1 | | | | | | |
| | | | | | | |
| Lot 90 Replat 1 | Individual Lot | Lot 90 Replat 1 | | Removed | | |
| Current Condition: | Removed - D.R. Horton se | | 11/9/22 inspection. | | | |
| Lot 96 Replat 1 | Individual Lot | Lot 96 Replat 1 | • | Removed | | |
| Current Condition: | Removed - D.R. Horton se | | 8/16/22 inspection | | • | |
| Lot 97 Replat 1 | Individual Lot | Lot 97 Replat 1 | | Removed | | |
| Current Condition: | Removed - D.R. Horton s | | 12/7/22 inspection | | | |
| Lot 100 Replat 1 | Individual Lot | Lot 100 Replat 1 | | Removed | | |
| Current Condition: | Removed - Woodland Ho | mes sodded the lot prior | to the 1/4/22 inspection | Nomoveu | 1 | |
| Lot 101 Replat 1 | Individual Lot | Lot 101 Replat 1 | 10/25/2021 | Active | Yes | |
| Lot for Replat I | individual Lut | Lot for Replat f | 10/23/2021 | ACTIVE | 162 | |

| Current Condition: | Fair Condition - Home owner began construction on the lot prior to the 10/25/21 inspection. Dirt piles were observed in the ROW during the 10/25/21 inspection, the inspector will monitor for removal and the installation of BMPs. Home owner installed silt fence at the rear of the lot prior to the 1/4/22 inspection. Maintenance recommendations have changed. Home owner removed the dirt piles from the ROW prior to the 2/15/22 inspection. | | | | | |
|-------------------------------------|---|--|---|---|---|--|
| | 1.) Silt fence should be repaired/reinstalled at the rear of the lot or the lot should be sodded. 2.) Wattles should be installed on the front of the lot or the lot should be sodded. 3.) Silt fence should be cleaned out and sediment that has fallen past the property line to the east should be cleaned up. 4.) Silt fence should be installed on the sides of the lot or the lot should be sodded. 5.) Sediment that has washed on to adjoining lots should be cleaned up. 1.) Urban Spark was informed to complete by 12/14/21. Not done as of the last inspection. Urban Spark was reminded on 1/5/3/3/8/22, 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed to complete by 5/3/23. Michael Bos was reminded on 6/21/23. 2.) Urban Spark was informed to complete by 12/14/21. Not done as of the last inspection. Urban Spark was reminded on 1/5/3/8/22, 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed to complete by 5/3/23. Michael Bos was reminded on 6/21/23. 3.) Urban Spark was informed to complete by 2/22/22. Not done as of last inspection. Urban Spark was reminded on 3/8/22, 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed to complete by 5/3/23. Michael Bos was reminded on 6/21/23. 4.) Urban Spark was informed to complete by 3/12/22. Not done as of last inspection. Urban Spark was reminded on 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed to complete by 5/3/23. Michael Bos was reminded on 6/21/23. A.) Urban Spark was informed to complete by 3/12/22. Not done as of last inspection. Urban Spark was reminded on 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed to complete by 5/3/23. Michael Bos was reminded on 6/21/23. A.) Urban Spark was informed to complete by 3/12/22. Not done as of last inspection. Urban Spark was reminded on 4/27/22, 5/6/22, 6/23/22, 8/2/22, 11/3/22, 11/9/22, 3/1/23, 4/20/23. Home owner was informed | | | | | |
| | | | | | | |
| | reminded on 6/21/23. 5.) Urban Spark was infor | med to complete by 3/12 | 2/22. Not done as of last inspe l/20/23. Home owner was info | ction. Urban Spark wa | as reminded on 4/27/22, | |
| Lot 105 Replat 1 | Individual Lot | Lot 105 Replat 1 | | Removed | | |
| Current Condition: | Removed - D.R. Horton se | | 11/2/22 inspection. | | | |
| Lot 112 Replat 1 Current Condition: | Individual Lot | Lot 112 Replat 1 | prior to the 4/12/22 inspection. | Removed | | |
| Lot 116 Replat 1 | Individual Lot | Lot 116 Replat 1 | mor to the 4/12/22 inspection. | Removed | | |
| Current Condition: | Removed - D.R. Horton se | | | | | |
| Lot 119 Replat 1 | Individual Lot | Lot 119 Replat 1 | 7/19/2022 | Active | No | |
| Current Condition: | | | ing the front of the lot prior to t | · | . Lot is currently inactive. | |
| Lot 120 Replat 1 Current Condition: | Individual Lot | Lot 120 Replat 1 | L 11/9/22 inspection. D.R. Hort | Removed | unce prior to the 6/21/23 | |
| Lot 126 Replat 1 | inspection. | Lot 127 Replat 1 | 11/23/2021 | Active | No | |
| Current Condition: | Active - D.R. Horton staked down a portable toilet on Lot 126 prior to the 11/23/21 inspection. The lot is currently inactive. D.R. Horton resecured the portable toilet prior to the 3/29/22 inspection. D.R. Horton removed the portable toilet from the lot prior to the 11/16/22 inspection. | | | | | |
| Lot 127 Replat 1 | Individual Lot | Lot 127 Replat 1 | | Removed | | |
| Current Condition: | Removed - D.R. Horton se | | 10/25/22 inspection. | | 1 | |
| Lot 128 Replat 1 Current Condition: | Individual Lot Removed - D.R. Horton se | Lot 128 Replat 1 | 10/25/22 inspection | Removed | | |
| SB 1 | Sediment Basin | See SWPPP | 1/3/2020 | Active | No | |
| Current Condition: | Good Condition - 1% filled - The basin was installed prior to the 1/3/20 inspection with a permanent riser. Commercial Seeding plugged the bottom 4 holes in the orifice plate prior to the 4/27/20 inspection. Hausman cleaned out the basin prior to the 8/9/22 inspection. Bottom 4 holes of the orifice plate were unplugged and the basin is now functioning as a post construction basin as of the 6/7/23 inspection. | | | | | |
| SB 2 | Sediment Basin | See SWPPP | 1/3/2020 | Active | No | |
| Current Condition: | Good Condition - 1% filled - The basin was installed prior to the 1/3/20 inspection with a permanent riser. Commercial Seeding plugged the bottom 2 rows of holes in the orifice plate prior to the 4/27/20 inspection. Hausman began cleaning out the basin prior to the 8/9/22 inspection. Hasuman cleaned out the basin prior to the 8/16/22 inspection. Bottom 2 holes of the orifice plate were unplugged and the basin is now functioning as a post construction basin as of the 6/7/23 inspection. | | | | | |
| SB 3 | Sediment Basin | See SWPPP | 1/3/2020 | Active | No No | |
| Current Condition: | plugged the bottom 4 hole inspection. Bottom 4 hole the 6/7/23 inspection. | es in the orifice plate prices of the orifice plate were | ed prior to the 1/3/20 inspection to the 4/27/20 inspection. Has a unplugged and the basin is r | ausman cleaned out the now functioning as a p | ne basin prior to the 8/9/22 post construction basin as of | |
| SB 4 Current Condition: | plugged the lowest dewate matted the erosion at the | ering hole and backfilled inlet pipe and installed a enance for the wattle wil will monitor for installati | 1/3/2020 Illed prior to the 1/3/20 inspect the erosion prior to the 4/27/2 straw wattle at the stub road I be included with SB 4. Riser on of permanent riser. | 20 inspection. Comme prior to the inspection | ercial seeding seeded and on 5/11/20. All future | |
| SF 1 | Silt fence | See SWPPP | Ļ | Removed | | |
| Current Condition: | | | fence prior to the 4/27/20 insp | | 1 | |
| SF 2 Current Condition: | Silt fence Removed - Wattles were recommendations. | | I truction prior to the 10/26/21 in | Removed spection. See Lot BN | I MPs for further | |
| SF 3 | Silt fence | See SWPPP | | Removed | | |
| Current Condition: | | | for active construction prior to | | on. | |
| SF 4 | Silt fence | Springfield Trail | London removed as of the 4/9 | Removed /21 inspection | 1 | |
| Current Condition: | | | med or removed as of the 4/9 | Z L DISOCCION | | |

| W1 | Straw Wattle | SB 4 Stub Road | | Removed | | |
|--------------------------|--|--|--------------------------------|-----------------------|------------------------|--|
| Current Condition: | Removed - Tim Geis cleaned the street and removed the wattle prior to the 7/15/20 inspection, reinstallation is not necessary. | | | | | |
| | | | | | | |
| | | Internal/S 132nd and | | | | |
| STR | Streets | Main Street | 1/3/2020 | Active | No | |
| Current Condition: | Good Condition - Streets | were clean and free of tra | ack out during the 11/9/22 ins | pection. | | |
| | | S 132nd Street and | | | | |
| SWPPP Signs | Misc/Other | Man Street | 1/27/2020 | Active | No | |
| Current Condition: | Good Condition - E&A ins | pector installed SWPPP | signs at the intersection of M | ain Street and N 10th | Ave and S 132nd Street | |
| | and Hazel Lane during the | e 1/27/20 inspection. | | | | |
| Certification Statement: | "I certify, under penalty of | law, that this document a | and all attachments were prep | ared under my | | |
| | direction or supervision in | accordance with a syste | m designed to assure that qu | alified personnel | | |
| | properly gathered and eva | aluated the information su | ubmitted. Based on my inquiry | of the person or | | |
| | persons who manage the system or those persons directly responsible for gathering the information, | | | | | |
| | the information submitted | is, to the best of my know | wledge and belief, true, accur | ate, and complete. I | | |
| | am aware that there are significant penalties for submitting false information including the possibility | | | | | |
| | of fines and imprisonment for knowing violations." | | | | | |
| | 1 | The same same same same same same same sam | | | | |
| | Sim MoGni | | | | Post Su | |
| Inspector Signature: | | | | Reviewed By: | | |