E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. Manager

Engineering Answers

		E&A - P20	19.327.000		
Inspector: Dylan Wagner					
Project Name:	Springfield Pines CSW-201600337				Stage 1
For Week Ending:		9/2	1/2024		
Project Location:	SW	of 132nd Street and P	latteview Road, Springfield,	NE	68059
	Phase I				
Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%				
Seeding:	75%				
Utilities:	100%				
Overall Development:	70%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week 1
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"	9/17/2024	Cloudy 86/67	8:10 AM	
Wednesday:	0.00"				
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
Complaints:	None.				
Construction Sequencing:	·	·	·	·	

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading in Phase I was completed prior to E&A being hired to conduct SWPPP inspections (1/3/20).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading in Phase I was completed prior to E&A being hired to conduct SWPPP inspections (1/3/20).

Site was seeded prior to E&A being hired to conduct SWPPP inspections (1/3/20). Portion of ground to the southeast of SB 4 seeded and matted (5/11/20).

Checklist Questions

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

ruction entrances and adjacent streets being maintained adequately?

Yes

N/A

N/A

Comments: Site was active for homebuilding during the most recent inspection.

*The School Site is not covered by the Springfield Pines permit (SPR-20200728-5543-GP1).

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) Some maintenance is required in the BMP section of this report.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance	
Al 1	Area Inlet Protection	See SWPPP		Removed		
Current Condition:	Removed - Area inlet was installed prior to the 1/3/20 inspection. The surrounding area is vegetated and the inlet drains to SB 1; no					
	inlet protection will be recommended at this time.					

Current Condition: Ansa Intellect and for in infection is 158 2, no intellectorised out the including is 158 2, no intellectorised out the intellectorise of the infection is 158 2, no intellectorised out the interpretation prior to the 21/1522 inspection. Place of the intellectorise o		
matted and the intel drains to S8 2; no intel protection will be recommended at this time. Urban Spati, initialled big prote some prior to the 1975/22 inspection. Spark cleaned out the intel protection prior to the 11/8/22 inspection. SID cleaned out the intel protection prior to the 10/11/2 inspection. A 3	Al 2	
Spark cleaned out the intel protection prior to the 1/922 inspection. SID cleaned out the intel protection prior to the 10/11/2 inspection. A 13 Area Intel Protection See SWPPP 39/2020 Active No. Active Intel with other grate was installed prior to the 49/20 inspection. Commercial Seeding removed the remaining from 17-20-20sts around the intel prior to the 49/20 inspection. Commercial Seeding removed the intel filter prior to the 49/20 inspection. Gene Graves cleaned active Active Active Active Active Active Active Intel with other grate was installed prior to the 59/20 inspection. Gene Graves cleaned active A	Current Condition:	matted and the inlet drains to SB 2; no inlet protection will be recommended at this time. Urban Spark installed big reds around in
Current Condition: Active - Area infelt with doring grate was installed prior to the 4/27/20 inspection. Commercial Seeding removed the remaining fence? T-posts around the infelt prior to the 4/27/20 inspection. The surrounding area was seeded and matter interest to the control of the c		Spark cleaned out the inlet protection prior to the 11/9/22 inspection. SID cleaned out the inlet protection prior to the 10/11/23
An International Protection of See SWPPP Arrained Protection See SWPPP Arrained Protection See SWPPP Arrained Protection See SWPPP Arrained Protection See SwpPPP Arrained Protection See	Al 3	Area Inlet Protection See SWPPP 3/9/2020 Active No
Current Condition: Active - Area intex with dome grate was installed prior to the 3/9/20 inspection. The surrounding area was seeded and malter inlet drains to S.9.2 to in left protection will be recommended at this time. Current Condition: Removed - A tot level concrete washout was installed on Lot 81 Replat 1 prior to the 1/3/20 inspection. Gene Graves cleaned concrete washout prior to the 1/1/20, the beam recommendation is no longer needed. Gene Graves cleaned concrete washout prior to the 1/1/20 inspection. Gene Graves cleaned concrete washout prior to the 1/1/20 inspection. Gene Graves relocated the concrete washout prior to the 1/1/20 inspection. Gene Graves relocated the concrete washout from Lot 81 Replat 1 to Lot 1 prior to the 4/6/21 inspection. Gene Graves relocated the concrete washout prior to the 1/1/20 inspection. Gene Graves relocated the concrete washout prior to the 1/1/20 inspection. Gene Graves relocated the concrete washout prior to the 1/1/20 inspection. Gene Graves relocated the concrete washout prior to the 1/1/20 inspection. Gene Graves relocated the concrete washout prior to the 1/1/20 inspection. The Lot 1/1/20 inspection of 1/1/20 in	Current Condition:	Active - Area inlet with dome grate was installed prior to the 3/9/20 inspections. Commercial Seeding removed the remaining silt fence/T-posts around the inlet prior to the 4/27/20 inspection.
Current Condition: Concrete Washout Lot 61 Replait Lot 61 Replait Concrete Washout Concrete Washout Lot 61 Replait Concrete Washout Concrete Washou	Al 4	Area Inlet Protection See SWPPP 3/9/2020 Active No
Current Condition: Removed - A lot level concrete washout was installed on Lot 81 Replat 1 prior to the 1/3/20 inspection. Gene Graves determed concrete washout proto to the inspection on \$1/120, the berm commendation in on longer needed. Gene Graves determed concrete washout proto the 61/20 inspection. Gene Graves determed out the concrete washout proto the 11/4/2 inspection. Gene Graves reconced the concrete washout proto to the 11/4/2 inspection. Gene Graves removed the concrete washout proto to the 11/4/2 inspection, flowed out the concrete washout proto to the 11/4/2 inspection, the EAA inspection, the EAA inspection will monitor for reinstallation. Dr. Horton installed an ambile washout of 12/6 prior to the 11/4/2 inspection, the EAA inspection, the EAA inspection, the EAA inspection will monitor for reinstallation. Dr. Horton proton to the 12/21/21 inspection. Dr. Horton installed and the concrete washout proto to the 10/11/22 inspection. Dr. Horton installed and the concrete washout proto to the 10/11/22 inspection. The formation of the 11/4/2 inspection. Dr. Horton installed and the concrete washout proto to the 10/11/22 inspection. Dr. Horton installation in the 11/4/2 inspection. Intel drains to a basin, reinstallation for commended. P	Current Condition:	Active - Area inlet with dome grate was installed prior to the 3/9/20 inspection. The surrounding area was seeded and matted and inlet drains to SB 2; no inlet protection will be recommended at this time.
concrete washout prior to the inspection on \$11420, the berm recommendation is no longer needed. Gene Graves added ro concrete washout prior to the 41702 inspection. Gene Graves cleaned out the concrete washout prior to the 11702 inspection. Gene Graves centered out the concrete washout prior to the 1170 inspection. Gene Graves removed the concrete washout prior to the 101 inspection, the E&A inspection. Gene Graves removed the concrete washout prior to the 101 inspection, the E&A inspection. Mobile washout was removed by D&R. Horton prior to the 1221/121 inspection. D&R thorton cleaned out the concrete washout prior to the 101 inspection. D&R thorton cleaned out the concrete washout prior to the 101 inspection. D&R thorton cleaned out the concrete washout prior to the 101 inspection. D&R thorton cleaned out the concrete washout prior to the 101 inspection. D&R thorton cleaned out the concrete washout prior to the 101 inspection. D&R thorton cleaned out the concrete washout prior to the 101 inspection. D&R thorton cleaned out the concrete washout prior to the 101 inspection. D&R thorton cleaned out the concrete washout prior to the 101 inspection. D&R thorton cleaned out the concrete washout prior to the 101 inspection. D&R thorton cleaned out the concrete washout prior to the 101 inspection. D&R thorton cleaned out the concrete washout prior to the 101 inspection. D&R thorton cleaned the 101 inspection. D&R thorton reinstallation inspection. D&R thorton reinstallation inspection in the 101 inspection. D&R thorton reinstallation in the 101 inspection in the 101 inspection. D&R thorton rein	CW 1	Concrete Washout Lot 81 Replat 1 Removed
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. D.R. Horton reinstalled the intet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. D.R. Horton reinstalled the intet filter prior to the 6/21/22 inspection. D.R. Horton removed the inlet filter prior to the 6/21/22 inspection. D.R. Horton removed the inlet filter prior to the 4/27/20 inspection. D.R. Horton removed the inlet filter prior to the 4/27/20 inspection. D.R. Horton removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. P 3	Current Condition:	Removed - A lot level concrete washout was installed on Lot 81 Replat 1 prior to the 1/3/20 inspection. Gene Graves cleaned out concrete washout prior to the inspection on 5/11/20, the berm recommendation is no longer needed. Gene Graves added rock to concrete washout approach prior to the 6/1/20 inspection. Gene Graves cleaned out the concrete washout prior to the 11/4/20 inspection. Gene Graves relocated the concrete washout from Lot 81 Replat 1 to Lot 1 prior to the 4/6/21 inspection. Gene Grave cleaned out the concrete washout prior to the 10/12/2 inspection, the E&A inspector will monitor for reinstallation. D.R. Horton installed a mobile washout on Lot 126 prior to the 11/23/2 inspection. Mobile washout was removed by D.R. Horton prior to the 12/21/21 inspection. D.R. Horton installed a concrete washout on to lot 117 prior to the 5/10/22 inspection. D.R. Horton cleaned out the concrete washout prior to the 7/5/22 inspection. D.R. Horton cleaned out the concrete washout prior to the 7/5/22 inspection. D.R. Horton cleaned out the concrete washout prior to the 7/5/22 inspection. D.R. Horton cleaned out the concrete washout prior to the 7/5/22 inspection. D.R. Horton cleaned out the concrete washout prior to the 7/5/22 inspection. D.R. Horton cleaned out the Concrete washout prior to the 7/5/22 inspection. D.R. Horton cleaned out the Concrete washout prior to the 7/5/22 inspection. D.R. Horton cleaned out the Concrete washout prior to the 7/5/22 inspection. D.R. Horton cleaned out the Concrete washout prior to the 7/5/22 inspection. D.R. Horton cleaned out the Concrete washout prior to the 7/5/22 inspection. D.R. Horton cleaned out the Concrete washout prior to the 7/5/22 inspection. D.R. Horton cleaned out the Concrete washout prior to the 7/5/22 inspection.
Removed - Commercial Seeding removed the intel filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. D. R. Horton reinstalled the intel filter prior to the 6/27/20 inspection. Inlet drains to a basin, reinstallation recommended. D. R. Horton reinstalled the intel filter prior to the 6/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. P3	IP 1	Inlet Protection See SWPPP Removed
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. D. R. Horton removed the inlet filter prior to the 6/21/22 inspection. D. R. Horton removed the inlet filter prior to the 6/21/22 inspection. D. R. Horton removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. P.4	Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is no
recommended. D.R. Horton reinstallad the inlet filter prior to the 6/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. IP3	IP 2	Inlet Protection See SWPPP Removed
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. P.4	Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is no recommended. D.R. Horton reinstalled the inlet filter prior to the 6/21/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.
P4	IP 3	Inlet Protection See SWPPP Removed
Removed - Commercial Seeding removed the inlef filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. D. R. Horton reinstalled inlef filter protection prior to the 5/31/22 inspection. D. R. Horton removed the inlef filter to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. P 5	Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is no recommended.
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. D. R. Horton reinstalled inlet filter protection prior to the 5/31/22 inspection. D. R. Horton removed the inlet filte to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. D. R. Horton removed the inlet filter protection prior to the 5/31/22 inspection. Inlet drains to a basin, reinstallation recommended. D. R. Horton reinstalled inlet filter protection prior to the 5/31/22 inspection. D. R. Horton removed the inlet filter protection prior to the 5/31/22 inspection. D. R. Horton removed the inlet filter protection prior to the 5/31/22 inspection. D. R. Horton reinstallation is not recommended. D. R. Horton reinstallation is not recommended. The drains to a basin, reinstallation is not recommended. P. Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. D. R. Horton reinstallation is not recommended. D. R. Horton reinstallation is not recommended. P. Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. D. R. Horton reinstallation is not recommended. P. Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. P. Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. P. Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D. R. Horton reinstallation is not recommended. D. R. Horton reinstallation is not recommended. P 1	IP 4	Inlet Protection See SWPPP Removed
Removed - Commercial Seeding removed the linet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. D.R. Horton reinstalled inlet filter protection prior to the 5/3/22 inspection. D.R. Horton removed the linet filter protection by the 1/2/11/22 inspection. D.R. Horton removed the linet filter protection is not recommended. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. D.R. Horton reinstallation recommended. D.R. Horton reinstalled inlet filter protection prior to the 8/30/22 inspection. D.R. Horton removed the inlet filter protection prior to the 2/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. IP 8		Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 5/31/22 inspection. D.R. Horton removed the inlet filter prior to the 5/31/22 inspection.
recommended. D.R. Horton reinstalled inlet filter protection prior to the 5/3/22 inspection. D.R. Horton removed the inlet filter the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. Inlet Protection See SWPPP Removed	IP 5	Inlet Protection See SWPPP Removed
Inlet Protection	Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is no recommended. D.R. Horton reinstalled inlet filter protection prior to the 5/3/22 inspection. D.R. Horton removed the inlet filter prior the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. D.R. Horton reinstalled inlet filter protection prior to the 8/30/22 inspection. D.R. Horton removed the inlet filter to the 1/27/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. IP 7	IP 6	Inlet Protection See SWPPP Removed
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. P 8	Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is no recommended. D.R. Horton reinstalled inlet filter protection prior to the 8/30/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.
P 8	IP 7	
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. D.R. Horton reinstalled inlet filter protection prior to the 8/30/22 inspection. D.R. Horton removed the inlet filter to the 12/21/22 inspection. Inlet drains to a basin, reinstallation prior to the 4/27/20 inspection. D.R. Horton removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. P 10	Current Condition:	
recommended, D.R. Horton reinstalled inlet filter protection prior to the 8/30/22 inspection. D.R. Horton removed the inlet filter to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. P 9	IP 8	Inlet Protection See SWPPP Removed
P 9	Current Condition:	recommended. D.R. Horton reinstalled inlet filter protection prior to the 8/30/22 inspection. D.R. Horton removed the inlet filter prior
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. P 10	IP 9	Inlet Protection See SWPPP Removed
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is recommended. D.R. Horton reinstalled inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 6/21/22 inspection. D.R. Horton removed the inlet filter prior to the 6/21/22 inspection. D.R. Horton removed the inlet filter prior to the 6/21/22 inspection. D.R. Horton removed the inlet filter prior to the 6/21/22 inspection. D.R. Horton removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is recommended. P 11		Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is no
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is recommended. D.R. Horton reinstalled inlet filter prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to the 6/21/22 inspection. D.R. Horton removed the inlet filter prior to the 6/21/22 inspection. D.R. Horton removed the inlet filter prior to the 6/21/22 inspection. D.R. Horton removed the inlet filter prior to the 6/21/22 inspection. D.R. Horton removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is recommended. D.R. Horton reinstalled inlet filter prior to the 4/27/20 inspection. D.R. Horton repaired the inlet filter prior to the 6/28/22 inspection. D.R. Horton removed the inlet filter prior to the 6/28/22 inspection. D.R. Horton removed the inlet filter prior to the 6/28/22 inspection. D.R. Horton removed the inlet filter prior to the 6/28/22 inspection. D.R. Horton removed the inlet filter prior to the 6/28/22 inspection. D.R. Horton removed the inlet filter prior to the 6/28/22 inspection. D.R. Horton removed the inlet filter prior to the 6/28/22 inspection. D.R. Horton removed the inlet filter prior to the 6/28/22 inspection. D.R. Horton removed the inlet filter prior to the 6/28/22 inspection. D.R. Horton removed the inlet filter prior to the 6/28/22 inspection. Inlet drains to a basin, reinstallation recommended. IP 12	IP 10	Inlet Protection See SWPPP Removed
IP 11 Inlet Protection See SWPPP Removed Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton repaired the inlet filter the 4/5/22 inspection. D.R. Horton removed the inlet filter prior to the 6/28/22 inspection. D.R. Horton removed the inlet filter to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. IP 12 Inlet Protection See SWPPP Removed Current Condition: IP 13 Inlet Protection See SWPPP Removed Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended.		Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton cleaned out the inlet filter p to the 6/7/22 inspection. D.R. Horton removed the inlet filter prior to the 6/21/22 inspection. D.R. Horton removed the inlet filter prior to the 6/21/22 inspection.
Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton repaired the inlet filter the 4/5/22 inspection. D.R. Horton removed the inlet filter prior to the 6/28/22 inspection. D.R. Horton removed the inlet filter to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended. IP 12	IP 11	
P 12		Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton repaired the inlet filter prior the 4/5/22 inspection. D.R. Horton removed the inlet filter prior to the 6/28/22 inspection. D.R. Horton removed the inlet filter prior to the 6/28/22 inspection.
Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. IP 13 Inlet Protection See SWPPP Removed Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. IP 14 Inlet Protection See SWPPP Removed	ID 49	
IP 13		Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is no
Current Condition: Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation recommended. IP 14 Inlet Protection See SWPPP Removed	IP 13	
		Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is no
	IP 14	Inlet Protection See SWPPP Removed
recommended.		Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is no

IP 15	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not
	recommended.
IP 16	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not
	recommended.
IP 17	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not
	recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter pri
	to the 8/2/22 inspection. D.R. Horton removed the inlet filter prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is
	not recommended.
IP 18	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 5/11/20 inspection. Inlet drains to a basin, reinstallation is not
	recommended. D.R. Horton reinstalled inlet filter protection prior to the 5/3/22 inspection. D.R. Horton cleaned out the inlet filter prior
	to the 7/12/22 inspection. D.R. Horton cleaned out the inlet filter prior to the 8/23/22 inspection. D.R. Horton removed the inlet filter
	prior to the 12/21/22 inspection. Inlet drains to a basin, reinstallation is not recommended.
IP 19	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not
	recommended.
IP 20	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not
ID 04	recommended.
IP 21	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not
	recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/29/22 inspection. D.R. Horton maintained the inlet filter prior to the 8/2/22 inspection. Inlet drains to a basin, reinstallation is
	not recommended.
ID 00	
IP 22 Current Condition:	Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not
Current Condition.	recommended.
IP 23	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not
Current Condition.	recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to
	the 7/26/22 inspection.
IP 24	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not
	recommended. D.R. Horton reinstalled inlet filter protection prior to the 3/1/22 inspection. D.R. Horton removed the inlet filter prior to
	the 7/26/22 inspection.
IP 25	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not
	recommended. D.R. Horton removed the inlet filter prior to the 5/31/22 inspection.
IP 26	Inlet Protection See SWPPP Removed
Current Condition:	Removed - SID removed the inlet filter prior to the 6/28/23 inspection.
IP 27	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not
	recommended.
IP 28	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet filter prior to the 4/27/20 inspection. Inlet drains to a basin, reinstallation is not
	recommended.
Lot 26 Replat 1	Individual Lot Lot 26 Replat 1 Removed
Current Condition: Lot 36 Replat 1	Removed - Carlson Tile Inc sodded the lot prior to the 4/24/24 inspection. Individual Lot Lot 36 Replat 1 Removed
Current Condition:	Individual Lot
Lot 45 Replat 1	Individual Lot Lot 45 Replat 1 Removed
Current Condition:	Removed - Brooks Builders Inc. sodded the lot prior to the 4/26/23 inspection.
Lot 55 Replat 1	Individual Lot Lot 55 Replat 1 Removed
Current Condition:	Removed - D&E Custom Building sodded the lot prior to the 6/28/23 inspection.
Lot 63 Replat 1	Individual Lot Lot 63 Replat 1 Removed
Current Condition:	Removed - Urban Spark sodded the lot prior to the 5/10/23 inspection.
Lot 72 Replat 1	Individual Lot Lot 72 Replat 1 5/1/2024 Active Yes

Current Condition:	Fair Condition - D&E Custom Building began excavation on the lot prior to the 5/1/24inspection. Dirt piles were observed in the ROW. E&A inspector will monitor for removal. D&E Custom Building installed wattles along the front and side of the lot prior to the 5/22/24 inspection. D&E Custom Building cleaned the streets in front of the lot prior to the 6/5/24 inspection. D&E Custom Building cleaned the streets in front of the lot prior to the 7/10/24 inspection. 1.) Silt fence should be installed on the rear of the lot. 2.) Wattles should be installed along the curb line. 3.) Wattles on the side of the lot should be cleaned out/reinstalled. 4.) Escaped sediment on to lot 71 should be cleaned up. 5.) Concrete waste should be cleaned up. 1.) D&E Custom Building was informed to complete by 5/8/24. Not done as of last inspection. D&E Custom Building was reminded on 5/30/24, 8/28/24. 2.) D&E Custom Building was informed to complete by 7/10/24. Not done as of last inspection. D&E Custom Building was reminded on 8/28/24. 3.) D&E Custom Building was informed to complete by 7/10/24. Not done as of last inspection. D&E Custom Building was reminded on 8/28/24. 4.) D&E Custom Building was informed to complete by 7/10/24. Not done as of last inspection. D&E Custom Building was reminded on 8/28/24. 4.) D&E Custom Building was informed to complete by 7/10/24. Not done as of last inspection. D&E Custom Building was reminded					
		was informed to complete	by 7/10/24. Not done as of las	st inspection. D&E Cus	tom Building was reminded	
Lot 82 Replat 1	on 8/28/24. Individual Lot	Lot 82 Replat 1	l	Removed	I	
Current Condition:	Removed - Urban Spark s		8/30/23 inspection.	Removed		
Lot 94 Replat 1	Individual Lot	Lot 94 Replat 1		Removed		
Current Condition:	Removed - Sundown Hom		the 8/13/24 inspection.	_		
Lot 101 Replat 1	Individual Lot	Lot 101 Replat 1	action Homogy	Removed	no lete prior to the 0/00/00	
Current Condition:	Removed - Lot was seed	-α ρποι το της δ/9/23 insp	ection. Homeowner removed t	ne sediment on adjoint	rig iots prior to the 8/30/23	
Lot 113 Replat 1	Individual Lot	Lot 113 Replat 1		Removed		
Current Condition:			ior to the 6/5/24 inspection.	rtemoved		
Lot 117 Replat 1 Current Condition:	Individual Lot	Lot 117 Replat 1	2/21/2024 ation on the lot prior to the 2/21	Active	Yes	
	 Wattles should be installed along the curb line. Silt fence should be cleaned out and repaired. Escaped sediment on to lot 118 should be cleaned up. Nexgen Builders LLC was informed to complete by 2/28/24. Not done as of last inspection. Nexgen Builders LLC was reminded on 4/18/24, 5/22/24, 6/26/24, 7/10/24, 8/28/24 Nexgen Builders LLC was informed to complete by 5/29/24. Not done as of last inspection. Nexgen Builders LLC was reminded on 6/26/24, 7/10/24, 8/28/24 Nexgen Builders LLC was informed to complete by 7/17/24. Not done as of the last inspection. Nexgen Builders LLC was reminded on 8/28/24. 					
Lot 119 Replat 1	Individual Lot	Lot 119 Replat 1		Removed		
Current Condition:			ior to the 7/16/24 inspection.	Romovod	<u> </u>	
Lot 120 Replat 1 Current Condition:	Individual Lot Removed - D.R. Horton so	Lot 120 Replat 1 odded the lot prior to the	<u>l</u> 11/9/22 inspection. D.R. Hortor	Removed removed the silt fence	Prior to the 6/21/23	
	inspection.	T				
Lot 126 Replat 1 Current Condition:			11/23/2021 on Lot 126 prior to the 11/23/21 3/22 inspection. D.R. Horton re			
SB 1	Sediment Basin	See SWPPP	1/3/2020	Active	No Common and a Constitution	
Current Condition:	plugged the bottom 4 hole	s in the orifice plate prior	d prior to the 1/3/20 inspection to the 4/27/20 inspection. Hau unplugged and the basin is no	sman cleaned out the b	basin prior to the 8/9/22	
SB 2	Sediment Basin	See SWPPP	1/3/2020	Active	No	
Current Condition:	Good Condition - 1% filled - The basin was installed prior to the 1/3/20 inspection with a permanent riser. Commercial Seeding plugged the bottom 2 rows of holes in the orifice plate prior to the 4/27/20 inspection. Hausman began cleaning out the basin prior to the 8/9/22 inspection. Hausman cleaned out the basin prior to the 8/16/22 inspection. Bottom 2 holes of the orifice plate were unplugged and the basin is now functioning as a post construction basin as of the 6/7/23 inspection.					
SB 3	Sediment Basin	See SWPPP	1/3/2020	Active	No	
Current Condition:	Good Condition - 1% filled - The basin was installed prior to the 1/3/20 inspection with a permanent riser. Commercial Seeding plugged the bottom 4 holes in the orifice plate prior to the 4/27/20 inspection. Hausman cleaned out the basin prior to the 8/9/22 inspection. Bottom 4 holes of the orifice plate were unplugged and the basin is now functioning as a post construction basin as of the 6/7/23 inspection.					
SB 4	Sediment Basin	See SWPPP	the 10/11/20 : "	Removed		
Current Condition: SF 1	Removed - Riser in the ba	Sin was removed prior to See SWPPP	the 10/11/22 inspection.	Domoved	<u> </u>	
SF 1 Current Condition:	Silt fence Removed - Commercial S		Lence prior to the 4/27/20 inspec	Removed ction.	l	
SF 2	Silt fence	See SWPPP	. p 13 8.13 1/21/20 11/0pot	Removed		
						

Current Condition:	Removed - Wattles were removed for home construction prior to the 10/26/21 inspection. See Lot BMPs for further recommendations.					
SF 3	Silt fence	See SWPPP		Removed		
Current Condition:	Removed - Silt fence was removed in preparation for active construction prior to the 5/18/20 inspection.					
SF 4	Silt fence	Springfield Trail		Removed		
Current Condition:	Removed - The remaining		ed or removed as of the 4/9/2	1 inspection.		
W1	Straw Wattle	SB 4 Stub Road		Removed		
Current Condition:	Removed - Tim Geis cleaned the street and removed the wattle prior to the 7/15/20 inspection, reinstallation is not necessary.					
		Internal/S 132nd and				
STR	Streets	Main Street	1/3/2020	Active	No	
Current Condition:	Good Condition - Streets v	vere clean and free of trac	ck out during the 11/9/22 inspe	ection.		
		S 132nd Street and				
SWPPP Signs	Misc/Other	Man Street	1/27/2020	Active	No	
Current Condition:	Good Condition - E&A insp Hazel Lane during the 1/27		igns at the intersection of Mair	n Street and N 10th Ave	e and S 132nd Street and	
Certification Statement:	accordance with a system Based on my inquiry of the information, the information	designed to assure that of person or persons who ron submitted is, to the best	nd all attachments were prepar qualified personnel properly gar nanage the system or those pet t of my knowledge and belief, t tion including the possibility of	thered and evaluated the ersons directly responsi rue, accurate, and com	ne information submitted. ible for gathering the oplete. I am aware that there	
Inspector Signature:	Julin Wagner			Reviewed By:	Pet Sel	