E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Enaineerina Answers

nspector: Chase Wickard					Stage
		Tekamah Medical Clinic			
					2
Project Name:			01702196 1/2018		
or Week Ending:					
Project Location:	Hwy 32 and K St Tekamah, NE (Burt County)				68061
				1	
Grading:	75%				
Sanitary Sewer:	0%				
Storm Sewer: Paving:	0%				
Seeding:	0%				
Jtilities:	0%				
Overall Development:	10%				
		1			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions		
Sunday:	0.00"				Wee
Monday	0.00"				
Tuesday	0.00"				
Vednesday	0.00"				
Thursday Thursday	0.00"				
riday	0.00"				
Saturday	0.00"				
- 1-	0.000				Wee
Sunday: Monday	0.00"				
ruesday	0.00"	02/20/18	19/10 Rain		
Vednesday	0.00"	02/20/10	13/10 Italii		
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Wee
Sunday:	NA				
Monday	NA				
Tuesday	NA				
Vednesday Fhursday	NA NA				
Friday	NA NA	+			
Saturday	NA NA				
Juturuuy	IVA	!			
Complaints:	None				
		T			
Construction Sequencing:	· ·	1	!	!	1
Vhich portion(s) (i.e. drainage basins)	of the site have had a temporary	or permanent cessation	on of grading, earthwork, or g	round disturbance in th	e last 14 days?
Grading began on the entire site (12/20/17)				
Matala manatana (A.V. a.	-Esth-atta-di-		Betoubeness of the Late of Co.		
Vhich portion(s) (i.e. drainage basins) Grading began on the entire site (earthwork, or ground d	usturbance scheduled in the	next 14 days? :	
	· /	ı	<u> </u>		
Vhat temporary or permanent stabiliza	tion managers listed in this cost	ion are being impleme	ntod2	1	<u> </u>

SUMMARY QUESTIONS: Are approved entrances and ac

Are approved entrances and adjacent streets being maintained adequately?

Yes

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

No, See findings section

CHECKLIST QUESTIONS:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Is dust associated with the construction activity adequately controlled on the site?

Yes

Comments:

Comments:

- 1. The site was inactive during the last inspection.
- 2. An existing outlet was not identified on the SWPPP but is present on site. The inspector has recommended silt fence to filter the water before leaving the site to ensure silt does not migrate to the adjacent waterway.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) Some maintenance is required in the BMP section.

			Projected Install				
Unique Name	Type	Location	Date	Status	Maintenance		
·	Construction	North eastern side of					
A1	Entrance	site	12/20/2017	Active	No		
Current Condition:	Good Condition - McCarthy Building Companies installed the construction entrance prior to the insp						
	on 12/20/17.						
		l					
B1	Silt Fence	Northern Perimeter	12/20/2017	Active	No No		
Current Condition:	Good Condition - McC	Carthy Building Companie	es installed the silt fend	ce prior to the insp	ection on 12/20/17.		
		T			Т		
B2	Silt Fence	South of A1	12/20/2017	Pending	No		
Current Condition:	Pending - The silt fend	ce is currently not necess	sary. The inspector wil	I continue to monit	or.		
		South western side of					
B3	Silt Fence	site	12/20/2017	Active	No		
Current Condition:	Good Condition - McCarthy Building Companies installed the silt fence prior to the inspection on 12/20/17.						
B4	Silt Fence	Southern Perimeter	12/20/2017	Active	No		
Current Condition:	Good Condition - McC	arthy Building Companie	es installed the silt fen	ce prior to the insp	ection on 12/20/17.		
		T			T		
B5	Silt Fence	Eastern Perimeter	12/20/2017	Active	No		
Current Condition:	Good Condition - McC	arthy Building Companie	es installed the silt fen	ce prior to the insp	ection on 12/20/17.		
B6	Silt Fence	South East side of site	12/20/2017	Active	No		
Current Condition:	Good Condition - McC	Carthy Building Companie	es installed the silt fen	ce prior to the insp	ection on 12/20/17.		
		South eastern corner					
B7	Silt Fence	of site	12/27/2017	Pending	Yes		
	Pending -	0.0.0	.2,2.,20	. Griding			
	· ·						
	The silt fence needs installed around the existing outlet.						
		mpanies was informed to					
	•	mind McCarthy Buildin	ig Companies when	weather condition	is allow for		
Current Condition:	maintenance.						
Current Condition.							
STR	Streets	Northern side of site	12/20/2017	Active	No		
Current Condition:	Good Condition- No m	najor signs of track off.			ı		

SWPPP Sign	Misc./Other	South of A1	1/3/2018	Active	No
Current Condition:	Good Condition - The i	nspector installed the si	ign during the 1/3/18 in	nspection.	•
			•		
Spector Signature:	· auled			Reviewed By:	Get See