E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Engineering Answers

nspector: Chase Wickard					Stage		
-p		Takamah N	ledical Clinic				
					2		
Project Name:		CSW-201702196					
or Week Ending:		3/24/2018					
Project Location:	Hwy 32 and K St Tekamah, NE (Burt County)				68061		
Grading:	75%						
Sanitary Sewer: Storm Sewer:	0%						
Paving:	0%						
Seeding:	0%						
Utilities:	0%						
Overall Development:	10%						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions		Mo		
Sunday:	0.00"				Wee		
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.72"	00/47/40	20/20 0				
Saturday	0.03"	03/17/18	39/32 Overcast		We.		
Sundaye	0.00"				Wee		
Sunday: Monday	0.01"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.20"						
Saturday	0.00"	03/24/18	39/32 Snow				
Daniel and	N/A				Wee		
Sunday: Monday	NA NA						
Tuesday	NA NA						
Wednesday	NA						
Thursday	NA NA						
Friday	NA						
Saturday	NA						
Complaints:	None						
		I		 			
Construction Sequencing:	I	<u> </u>					
Which portion(s) (i.e. drainage basins)	of the site have had a temporary	or permanent cessation	on of grading, earthwork, or gr	ound disturbance in the	last 14 days?		
Grading began on the entire site ((12/20/17)						
Vhich portion(s) (i.e. drainage basins)	of the site do not have grading of	arthwork or ground d	isturbance scheduled in the n	evt 14 days?			
Grading began on the entire site (araiwork, or ground d	istarbance scrieduled in the no	TAL 14 Udyof:			
	·	<u> </u>					
Vhat temporary or permanent stabiliza	tion measures listed in this secti	on are being impleme	nted?				

SUMMARY QUESTIONS:

Are approved entrances and adjacent streets being maintained adequately?

No, See BMP section

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

No, See findings section

CHECKLIST QUESTIONS:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Is dust associated with the construction activity adequately controlled on the site?

Yes

Comments:

Comments:

- 1. The site was inactive during the last inspection.
- 2. An existing outlet was not identified on the SWPPP but is present on site. The inspector has recommended silt fence to filter the water before leaving the site to ensure silt does not migrate to the adjacent waterway.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) Some maintenance is required in the BMP section.

	Projected Install							
Unique Name	Туре	Location	Date	Status	Maintenance			
	Construction	North eastern side of						
A1	Entrance	site	12/20/2017	Active	No			
Current Condition:	Good Condition - 75% effective-McCarthy Building added rock prior to the inspection on 3/24/18							
B1 Current Condition:	Silt Fence	Northern Perimeter	12/20/2017	Active	No			
Current Condition:	Good Condition - McCarthy Building Companies installed the silt fence prior to the inspection on 12/20/17.							
		1 1						
DO.	0:14 =====	Courtle of A4	40/00/0047	Dan dia a	NI-			
B2 Current Condition:	Silt Fence	South of A1	12/20/2017	Pending	No			
Current Condition:	Pending - The slit tend	ce is currently not necess	ary. The inspector wil	continue to monit	or.			
		South western side of						
B3	Silt Fence	site	12/20/2017	Active	No			
Current Condition:	Good Condition - McC	Carthy Building Companie	s installed the silt fen	ce prior to the inspe	ection on 12/20/17.			
B4	Silt Fence	Southern Perimeter	12/20/2017	Active	No			
Current Condition:	Good Condition - McC	Carthy Building Companie	s installed the silt fen	ce prior to the inspe	ection on 12/20/17.			
B5	Silt Fence	Eastern Perimeter	12/20/2017	Active	Yes			
Current Condition:	Fair Condition -							
	The silt fence needs re-paired.							
	McCarthy Builidng Company was informed to complete by 3/13/19. Not done as of the last inspection							
	McCarthy Builidng Company was informed to complete by 3/13/18. Not done as of the last inspection.							
B6	Silt Fence	South East side of site	12/20/2017	Active	No			
Current Condition:	Good Condition - McC	Carthy Building Companie	s installed the silt fen	ce prior to the inspe	ection on 12/20/17.			
		South eastern corner						
B7	Silt Fence	of site	12/27/2017	Pending	Yes			
Current Condition:	Pending -	5. 51.5	, , _ 0 11					
	To stating							
	The silt fence needs installed around the existing outlet.							
	McCarthy Building Companies was informed to complete by 12/27/17. McCarthy Building Company was							
	reminded on 3/7/18.							

STR	Streets	Northern side of site	12/20/2017	Active	No	
Current Condition:	Good Condition- No major signs of track off.					
SWPPP Sign Current Condition:	Misc./Other Good Condition - The	South of A1 inspector installed the si	1/3/2018 gn during the 1/3/18 ii	Active nspection.	No	
Inspector Signature:			Reviewed By:	Coto Sol		