E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager **Engineering Answers**

	E&A- P2015	5.767.003	
Inspector: Chase Wickard			Stage
Project Name:	Tekama CSV	2	
For Week Ending:		V-201702196 0/27/2018	
Project Location:		- Tekamah, NE (Burt County)	68061
Grading:	85%		
Sanitary Sewer:	90%		
Storm Sewer:	90%		
Paving:	0%		
Seeding:	0%		
Utilities:	25%		
Overall Development:	50%		

RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions		
					Week 1
Sunday:	0.06"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.13"				
Saturday	0.00"				
					Week 2
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"	10/23/18	61/32 Clear		
Wednesday	0.00"				
Thursday	0.14"				
Friday	0.00"				
Saturday	0.00"				
					Week
Sunday:	NA				
Monday	NA				
Tuesday	NA				
Wednesday	NA				
Thursday	NA				
Friday	NA				
Saturday	NA				
	None				
Complaints:					
Construction Sequencing:					
Which portion(s) (i.e. drainage basin	s) of the site have had a tempo	orary or permanent cessation	on of grading, earthwork, or g	round disturbance in th	e last 14 days?
Grading began on the entire site	e (12/20/17).				
Malaian and in the Mine alarian and the state					
Which portion(s) (i.e. drainage basin		ing, earthwork, or ground d	isturbance scheduled in the i	next 14 days? :	
Grading began on the entire site	e (12/20/17)				

Existing Vegetation (12/20/2012)					
SUMMARY QUESTIONS:					
Are approved entrances and adjacent streets	s being maintained adequa	tely?			
No, See BMP section					
Are receiving waters adjacent to the project	free of any significant signs	s of erosion or sediment tha	it would be associated wit	th the construction ac	tivity?
Yes					
CHECKLIST QUESTIONS:					
Are waste materials (concrete, construction	material, hazardous, etc.) b	eing managed properly?			
Yes					
Is dust associated with the construction acti	vity adequately controlled	on the site?			
Yes					
Comments:					
Comments:					
1. The site was active for minor buildir	ng construction during t	he time of inspection.			
Findings / Corrective Actions (Date):				
Finding and / Operations Applications (Detail					

Findings / Corrective Actions (Date):
1) Some maintenance is required in the BMP section.
2) An existing outlet was not identified on the SWPPP but is present on site. The inspector has recommended McCarthy Grading install silt fence to filter the water before leaving the site to ensure silt does not migrate to the adjacent waterway.

			Projected Install		
Unique Name	Туре	Location	Date	Status	Maintenance
	Construction	North eastern side of			
A1	Entrance	site	12/20/2017	Active	Yes
Current Condition:	Fair Condition - 40% e	ffective-			
	Rock needs added to t	ine entrance.			
	McCarthy Building was	informed to complete b	ov 9/26/18 Not done a	s of the last inspec	tion
	Neodriny Duilding was		by 5/20/10. Not dolle a		
B1	Silt Fence	Northern Perimeter	12/20/2017	Active	No
Current Condition:	Good Condition - McC	arthy Building Companie	es installed the silt fen	ce prior to the insp	ection on 12/20/17.
		-			
B2	Silt Fence	South of A1	12/20/2017	Pending	No
Current Condition:	Pending - The silt fence	e is currently not neces	sary. The inspector wi	Il continue to monit	or.
		South western side of			
B3	Silt Fence	site	12/20/2017	Active	No
Current Condition:		arthy Building Companie			
		and y Danan g company			
B4	Silt Fence	Southern Perimeter	12/20/2017	Active	No
Current Condition:		arthy Building Companie			
		anny balang company			
B5	Silt Fence	Eastern Perimeter	12/20/2017	Active	Yes
Current Condition:	Fair Condition-	•	•	•	
	Due to a stream runnir	ng through the site the s	ilt fence keeps eroding	j .	
		e area the inspector reco			
	Tence to avoid further r	maintenance during the	inspection on 9/18/18	. Not done as of the	e last inspection.
B6	Silt Fence	South East side of site	12/20/2017	Active	No
Current Condition:	Good Condition - McC	arthy Building Companie	es installed the silt fen	ce prior to the insp	ection on 12/20/17.
		bserved during the 8/31	1/18 inspection. Area	is heavily vegetate	d and reinstallation
	will not be recommend	ed at this time.			

		South eastern corner				
B7	Silt Fence	of site	12/27/2017	Active	No	
Current Condition:	Good Condition - Mc	Good Condition - McCarthy Building Companies installed the silt fence prior to the inspection on 5/2				
STR	Streets	Northern side of site	12/20/2017	Active	No	
Current Condition:	Good Condition- No t	rack out was observed du	iring the inspection or	n 9/21/18.		
SWPPP Sign	Misc./Other	South of A1	1/3/2018	Active	No	
SWPPP Sign Current Condition:		South of A1 e inspector installed the sig			No	
Current Condition:				nspection.	No Reto S.a.	