E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Ma

Minor existing perimeter vegetation (12/08/20).

Checklist Questions:

Engineering Answers

Environmental Services De	pt. Manager			Lingineering Answer	,
		E&A - P202	20.235.001		T
Inspector: Joe Manning					Stage
	Tel	kamah-Horm	an High School A	ddition	2
Project Name:			an riigh School A N-202004897	luullion	_
For Week Ending:			2/13/2021		
Project Location:			h Street, Tekamah, NE		68061
	070/				
Grading: Sanitary Sewer:	97%				
Storm Sewer:	21%				+
Paving:	45%				+
Seeding:	0%				
Utilities:	20%				<u> </u>
Overall Development:	35%				
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Time	
					Week
Sunday:	0.00"				
Monday	0.15"				
Tuesday	0.00"				
Wednesday	0.00"	1/27/2021	Sunny 29/14	9:50 AM	
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Week
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Week
Sunday:	0.02"				
Monday	0.00"				
Tuesday	0.00"	2/9/2021	Sunny 7/-19	12:50 PM	
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.01"				
Saturday	0.01"				
Complaints:					
Construction Communication					
Construction Sequencing: Which portion(s) (i.e. drainage base	sins) of the site have had a temp	orary or permanent ce	ssation of grading, earthwork	, or ground disturbance in the last	14 days?
Majar avadina aananlata (124	00/20) Ctampa a suca musa di b	(12/00/20)			
Major grading complete (12/0 Which portion(s) (i.e. drainage base			und disturbance scheduled in	the next 14 days? :	
Major grading complete (12/0					
What temporary or permanent sta			olemented?		
Minor existing perimeter year	etation (12/08/20)				

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?
No - See BMP Section (FT).

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

No - See BMP Section (Str.)

Is dust associated with the construction activity adequately controlled on the site?

Yes

Creat Corrective Action?

N/A

Comments

The site was active for building construction during the current inspection.

Due to winter conditions prior to the inspection on 1/27/21, the site will be temporarily inspected on the basis of a Winter Stage or 3rd Stage (with inspections every 30 days or after .50" of precipitation).

Due to snow-covered conditions, not all BMPs could be observed during the most recent inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1.) Some maintenance is required in the BMP section.
- 2.) The site was being accessed off of Highway 75 north and south of M Street. These access points should be blocked or construction entrances should be installed. Hausmann Construction was informed to complete by 1/04/21. Not done as of the last inspection. Hausmann Construction was reminded on-site on 1/11/21. Hausmann Construction blocked the two access points to the site off of Highway 75 prior to the inspection on 1/27/21.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CE 01	Construction Entrance	K13		Removed		
Current Condition:	Removed - Hausmann paved the construction entrance prior to the inspection on 1/11/21.					
CE 02	Construction Entrance	M8	12/8/2020	Active	No	
Current Condition:	Good Condition - 95% effective - Hausmann Construction installed the construction entrance prior to the first inspection on 12/08/20.					
CE 03	Construction Entrance	H10	12/8/2020	Active	No	
Current Condition:	Good Condition - 95% effective - Hausmann Construction installed the construction entrance prior to the first inspection on 12/08/20.					
CE 04	Construction Entrance	H10		Removed		
Current Condition:	Removed - Hausmann Construction fully paved M Street prior to the inspection on 2/09/21.					
FT	Fuel Tank	On Site	12/8/2020	Active	Yes	
Current Condition:	Fair Condition - Hausmann Construction placed a double-walled fuel tank on site prior to the first inspection on 12/08/20. E&A inspector will monitor and recommend additional containment as needed. Secondary containment should be installed around the two diesel tanks on site and any spills should be cleaned up. Hausmann Construction was informed to complete by 1/04/21. Not done as of the last inspection. Hausmann Construction was reminded on-site on 1/11/21.					
IF 01	Inlet Protection	S14	12/8/2020	Pending	No	

Current Condition:				was observed in the area dud at this time. The E&A insp	
IF 02	Inlet Protection	H13	12/8/2020	Active	No
Current Condition:	Good Condition - Hausm	ann Construction pay		ghway 75 prior to the first ins	
IF 03	Inlet Protection	H12	12/8/2020	Pending	No
Current Condition:	Pending - Inlet protection monitor.	n will be recommende	d when the inlet is installe	d at or below grade. The E&	A inspector v
IF 04	Inlet Protection	K11	12/17/2020	Active	No
Current Condition:	Construction installed in	et protection prior to in the area prior to the	the inspection on 12/17/20 te inspection on 12/28/20.	to the first inspection on 12/ Hausmann Construction re Hausmann Construction re Active	emoved the in
Current Condition:				the first inspection on 12/0	
Current Condition.	Construction installed in	et protection prior to in the area prior to the	the inspection on 12/17/20	. Hausmann Construction rep	emoved the in
IF 06	Inlet Protection	H10	12/8/2020	Pending	No
Current Condition:	monitor.	n will be recommende	T	d at or below grade. The E&	A inspector w
IF 07	Inlet Protection	R8	12/8/2020	Pending	No
Current Condition:	Pending - Inlet protection monitor.	n will be recommende	ed when the inlet is installe	d at or below grade. The E&	A inspector v
IF 08	Inlet Protection	R7	12/8/2020	Pending	No
Current Condition:	Pending - Curb Inlet prof will monitor.	ection will be recomn	nended when the inlet is in	stalled at or below grade. Th	ne E&A inspe
IF 09	Inlet Protection	P7	12/8/2020	Pending	No
Current Condition:	Pending - Inlet protection monitor.	n will be recommende	d when the inlet is installe	d at or below grade. The E&	A inspector v
IF 10	Inlet Protection	M2	12/8/2020	Active	No
Current Condition:	Good Condition - Hausm	ann Construction ins	talled inlet protection prior	to the first inspection on 12/	/08/20.
IF 11	Inlet Protection	N2	12/8/2020	Active	No
Current Condition:			talled inlet protection prior	to the first inspection on 12/	/08/20.
MS 01	Material Storage	On Site	d as necessary	Pending	
Current Condition: PB	Pending - The material s Sanitary Waste Management	On Site	12/8/2020	Active	No
Current Condition:	Good Condition - Hausm	ann Construction pla	ced and secured three por	table toilets on site prior to to to the prior to the prior to the	
SF 01 Current Condition:	Silt Fence Good Condition - Hausm	S12 - R14 nann Construction ins	12/17/2020 talled the silt fence prior to	Active the inspection on 12/17/20.	No
SF 02	Silt Fence	R14 - K14	12/8/2020	Pending	No
Current Condition:	inspector will monitor.			recommended at this time.	The E&A
SF 03	Silt Fence	J13 - H14	12/8/2020	Pending	No
Current Condition:	inspector will monitor.		•	recommended at this time.	
SF 04 Current Condition:	Silt Fence	M2 - F13	12/8/2020	Active ilt fence prior to the first ins	No nection on
	12/08/20.				
SF 05 Current Condition:	Silt Fence	K6 - J10	12/8/2020	Pending recommended at this time.	No The F&A
SF 06	inspector will monitor. Silt Fence	L8 - J13	12/8/2020	Pending	No No
Current Condition:				recommended at this time.	
STR	Streets	On Site	12/8/2020	Active	Yes
Current Condition:	basis.	was informed to com	plete by 12/09/20. Not dor	nould be cleaned on a daily one as of the last inspection.	

SWPPP Sign	SWPPP Signs	West side of site	12/17/2020	Active	Yes	
Current Condition:	Fair Condition - The E&A inspector installed the SWPPP sign during the inspection on 12/17/20. Hausmann					
	Construction moved the SWPPP sign prior to the inspection on 2/09/21.					
	The sign should be reinstalled visibly near one of the site entrances. Hausmann Construction was informed to complete by 2/16/21.					
WO 01	Concrete Washout	On Site	12/8/2020	Active	No	
Current Condition:	Good Condition - Hausmann Construction placed a concrete washout on site prior to the first inspection on 12/08/20.					
	Hausmann Construction cleaned up the concrete washout outside of the pit prior to the inspection on 12/17/20.					
	Hausmann Construction placed another concrete washout on site prior to the inspection on 12/28/20.					
WS 01	Waste Storage Area	On Site	12/8/2020	Pending	No	
Current Condition:	Pending - The waste storage area will be installed as necessary.					
	Je line			Sut Sul		
Inspector Signature:			Reviewed By:			