E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Enai	neer	ina	Answers

Inspector: Joe Manning					Stage		
Project Name:	Tekamah-Herman High School Addition CSW-202004897						
For Week Ending:		9/11/2021					
Project Location:			t - Tekamah, NE (Burt Cou	ntu)	68061		
Grading:	98%						
Sanitary Sewer:	20%						
Storm Sewer:	60%						
Paving:	96%						
Seeding: Utilities:	0%						
Overall Development:	45%						
					-		
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Time	Wool		
Sunday:	0.24"				Weel		
Monday	1.07"						
Tuesday	0.72"	8/31/2021	Mostly Sunny 81/65	8:55 AM			
Wednesday	0.00"						
Thursday	0.13"						
Friday	0.07"						
Saturday	0.00"						
outuruuy	0.00				Weel		
Sunday:	0.00"						
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"						
outuruuy	0.00				Weel		
Sunday:	N/A						
Monday	N/A						
Tuesday	N/A						
Wednesday	N/A						
Thursday	N/A						
Friday	N/A						
Saturday	N/A						
		•		·			
Complaints:							
Construction Sequencing:	•						
Which portion(s) (i.e. drainage ba	isins) of the site have had a temp	orary or permanent ce	ssation of grading, earthwork, or	r ground disturbance in the last	14 days?		
Major grading complete (12/ (8/31/21).		Ŭ ()	č	· · · · ·	Fine grading		
Which portion(s) (i.e. drainage ba Major grading complete (12/					Fine grading		
(8/31/21). What temporary or permanent sta					ine grading		
max temporary of permanent Sta	asinzation measures listed in this	s section are being IMP	nementeu :				

Checklist Questions:					
Are receiving waters adjace	nt to the project free of a	ny significant signs	of erosion or sediment th	at would be associated wi	th the
construction activity?					
Yes Create Corrective Action?					
N/A					
Have disturbed areas been s		ilized as required? L	ist inactive portions of th	ne project and if stabilization	on measure are
adequate or needed to preve Yes	nt erosion.				
Create Corrective Action?					
N/A					
Are waste materials (concre	te construction material	hazardous etc.) he	ing managed properly?		
No		, 1122110003, 010.7 50	ing managea property.		
Create Corrective Action?					
No - See BMP Section (FT, PTs, and	CW).				
Are construction entrances	and adjacent streets beir	ng maintained adequ	ately?		
Create Corrective Action?					
No - See BMP Section (CEs and Str).					
Is dust associated with the c	construction activity adec	quately controlled or	n the site?		
Yes					
Create Corrective Action?					
N/A					
Comments:					
Comments:					
The site was active during the	most recent inspection.				
Findings / Corrective Action					
Findings / Corrective Action					
1.) Some maintenance is requ	red in the BMP section.				
	<u>+</u>			a . <i>i</i>	
Unique Name	Type	Location	Projected Install Date	Status	Maintenance
CE 01	Construction Entrance	K13		Removed	
Current Condition:	· ·		entrance prior to the inspe		
CE 02	Construction Entrance	M8		Removed	04
Current Condition:			e construction entrance pri	or to the inspection on 7/30/	21.
CE 03	Construction Entrance	H10		Removed	
Current Condition:			e construction entrance pri	or to the inspection on 6/26/	21.
CE 04	Construction Entrance	H10		Removed	
Current Condition:	Removed - Hausmann C	Construction fully nave	d M. Ctup at mujan to the incu		
			a M Street prior to the insp	bection on 2/09/21.	
CE 05	Construction Entrance	N4	a m Street prior to the insp	Removed	
CE 05 Current Condition:	Construction Entrance	N4			21.
Current Condition:	Construction Entrance Removed - Hausmann C	N4 Construction paved the		Removed or to the inspection on 7/30/:	21.
Current Condition:	Construction Entrance Removed - Hausmann C Construction Entrance	N4 Construction paved the R13	e construction entrance pri	Removed or to the inspection on 7/30/ Removed	
Current Condition:	Construction Entrance Removed - Hausmann C Construction Entrance	N4 Construction paved the R13	e construction entrance pri	Removed or to the inspection on 7/30/:	
Current Condition:	Construction Entrance Removed - Hausmann C Construction Entrance	N4 Construction paved the R13	e construction entrance pri	Removed or to the inspection on 7/30/ Removed	
Current Condition: CE 06 Current Condition:	Construction Entrance Removed - Hausmann C Construction Entrance Removed - Hausmann C Fuel Tank Fair Condition - Hausma	N4 Construction paved the R13 Construction paved the On Site	e construction entrance pri e area near the constructio 12/8/2020 ed a double-walled fuel tan	Removed or to the inspection on 7/30/ Removed n entrance prior to the inspe Active	ction on 8/13/21. Yes pection on
Current Condition: CE 06 Current Condition: FT	Construction Entrance Removed - Hausmann C Construction Entrance Removed - Hausmann C Fuel Tank Fair Condition - Hausma 12/08/20. E&A inspector	N4 Construction paved the R13 Construction paved the On Site nn Construction place will monitor and reco	e construction entrance pri e area near the constructio 12/8/2020 ed a double-walled fuel tani mmend additional containr	Removed or to the inspection on 7/30/ Removed n entrance prior to the inspe Active c on site prior to the first insp nent as needed. Hausmann	ction on 8/13/21. Yes pection on Construction
Current Condition: CE 06 Current Condition: FT	Construction Entrance Removed - Hausmann C Construction Entrance Removed - Hausmann C Fuel Tank Fair Condition - Hausma 12/08/20. E&A inspector placed one of the diesel	N4 Construction paved the R13 Construction paved the On Site nn Construction place will monitor and reco	e construction entrance pri e area near the constructio 12/8/2020 ed a double-walled fuel tani mmend additional containr	Removed or to the inspection on 7/30/ Removed n entrance prior to the inspe Active	ction on 8/13/21. Yes pection on Construction
Current Condition: CE 06 Current Condition: FT	Construction Entrance Removed - Hausmann C Construction Entrance Removed - Hausmann C Fuel Tank Fair Condition - Hausma 12/08/20. E&A inspector	N4 Construction paved the R13 Construction paved the On Site nn Construction place will monitor and reco	e construction entrance pri e area near the constructio 12/8/2020 ed a double-walled fuel tani mmend additional containr	Removed or to the inspection on 7/30/ Removed n entrance prior to the inspe Active c on site prior to the first insp nent as needed. Hausmann	ction on 8/13/21. Yes pection on Construction
Current Condition: CE 06 Current Condition: FT	Construction Entrance Removed - Hausmann C Construction Entrance Removed - Hausmann C Fuel Tank Fair Condition - Hausma 12/08/20. E&A inspector placed one of the diesel 6/09/21. Secondary containment	N4 Construction paved the R13 Construction paved the On Site Inn Construction place will monitor and reco tanks in secondary co	e construction entrance pri e area near the constructio 12/8/2020 ed a double-walled fuel tan mmend additional containr ontainment and cleaned up	Removed or to the inspection on 7/30/ Removed n entrance prior to the inspe Active c on site prior to the first insp nent as needed. Hausmann	ction on 8/13/21. Yes pection on Construction he inspection on
Current Condition: CE 06 Current Condition: FT	Construction Entrance Removed - Hausmann C Construction Entrance Removed - Hausmann C Fuel Tank Fair Condition - Hausma 12/08/20. E&A inspector placed one of the diesel 6/09/21.	N4 Construction paved the R13 Construction paved the On Site Inn Construction place will monitor and reco tanks in secondary co	e construction entrance pri e area near the constructio 12/8/2020 ed a double-walled fuel tan mmend additional containr ontainment and cleaned up	Removed or to the inspection on 7/30/ Removed n entrance prior to the inspe Active on site prior to the first insp nent as needed. Hausmann spills from the site prior to t	ction on 8/13/21. Yes pection on Construction he inspection on
Current Condition: CE 06 Current Condition: FT	Construction Entrance Removed - Hausmann C Construction Entrance Removed - Hausmann C Fuel Tank Fair Condition - Hausma 12/08/20. E&A inspector placed one of the diesel 6/09/21. Secondary containment capacity of the tank).	N4 Construction paved the R13 Construction paved the On Site In Construction place will monitor and reco tanks in secondary co should be installed ar	e construction entrance pri e area near the constructio 12/8/2020 ed a double-walled fuel tani mmend additional containr ontainment and cleaned up ound the diesel tank on the	Removed or to the inspection on 7/30/ Removed n entrance prior to the inspective Active on site prior to the first inspective on site prior to the first inspective son son site prior to the first inspective son si	ction on 8/13/21. Yes pection on Construction he inspection on least 110%
Current Condition: CE 06 Current Condition: FT	Construction Entrance Removed - Hausmann C Construction Entrance Removed - Hausmann C Fuel Tank Fair Condition - Hausma 12/08/20. E&A inspector placed one of the diesel 6/09/21. Secondary containment capacity of the tank). Hausmann Construction	N4 Construction paved the R13 Construction paved the On Site In Construction place will monitor and reco tanks in secondary co should be installed ar	e construction entrance pri e area near the constructio 12/8/2020 ed a double-walled fuel tani mmend additional containr ontainment and cleaned up ound the diesel tank on the plete by 1/04/21. Not done	Removed or to the inspection on 7/30/ Removed n entrance prior to the inspection Active on site prior to the first inspection to the first inspection to the first inspection. He	ction on 8/13/21. Yes pection on Construction he inspection on least 110%
Current Condition: CE 06 Current Condition: FT	Construction Entrance Removed - Hausmann C Construction Entrance Removed - Hausmann C Fuel Tank Fair Condition - Hausma 12/08/20. E&A inspector placed one of the diesel 6/09/21. Secondary containment capacity of the tank). Hausmann Construction	N4 Construction paved the R13 Construction paved the On Site In Construction place will monitor and reco tanks in secondary co should be installed ar	e construction entrance pri e area near the constructio 12/8/2020 ed a double-walled fuel tani mmend additional containr ontainment and cleaned up ound the diesel tank on the plete by 1/04/21. Not done	Removed or to the inspection on 7/30/ Removed n entrance prior to the inspective Active on site prior to the first inspective on site prior to the first inspective son son site prior to the first inspective son si	ction on 8/13/21. Yes Dection on Construction he inspection on least 110%
Current Condition: CE 06 Current Condition: FT	Construction Entrance Removed - Hausmann C Construction Entrance Removed - Hausmann C Fuel Tank Fair Condition - Hausma 12/08/20. E&A inspector placed one of the diesel 6/09/21. Secondary containment capacity of the tank). Hausmann Construction Construction was remined	N4 Construction paved the R13 Construction paved the On Site In Construction place will monitor and reco tanks in secondary co should be installed ar	e construction entrance pri e area near the constructio 12/8/2020 ed a double-walled fuel tani mmend additional containr ontainment and cleaned up ound the diesel tank on the plete by 1/04/21. Not done	Removed or to the inspection on 7/30/ Removed n entrance prior to the inspection Active on site prior to the first inspection to the first inspection to the first inspection. He	ction on 8/13/21. Yes Dection on Construction he inspection on least 110%

Current Condition:	Eair Condition - Existing	curb inlet along High	Nav 75 Hausmann Constr	uction installed inlet protection	on prior to the		
current condition.				ring the inspection on 5/19/2			
	The inlet protection should be cleaned off.						
	Hausmann Construction			e as of the last inspection. H	ausmann		
IF 02	Inlet Protection	H13	12/8/2020	Active	No		
Current Condition:		-		ghway 75 prior to the first ins			
	12/08/20. Hausmann Co	onstruction installed in It the inlet protection p	let protection prior to the in prior to the inspection on 3	nspection on 1/11/21. Hausn 8/15/21. Hausmann Construc	nann		
IF 03	Inlet Protection	H12	6/9/2021	Pending	No		
Current Condition:	Pending - The inlet was inlet is at or below grade			protection will be recommer	nded when the		
IF 04	Inlet Protection	K11	12/17/2020	Active	No		
Current Condition:	Construction installed in protection due to paving	let protection prior to t in the area prior to th	the inspection on 12/17/20 e inspection on 12/28/20.	b the first inspection on 12/08 0. Hausmann Construction rei 1. Hausmann Construction reir 1. Paired the inlet protection pr	moved the inlenstalled the inle		
IF 05	Inlet Protection	J11	12/17/2020	Active	No		
Current Condition:				the first inspection on 12/08			
	protection due to paving	in the area prior to th	e inspection on 12/28/20.	 Hausmann Construction rep Hausmann Construction rep eaned out the inlet protection 	laced the inlet		
IF 06	Inlet Protection	H10	6/9/2021	Pending	No		
Current Condition:	Pending - The inlet was inlet is at or below grade			protection will be recommer	nded when the		
IF 07 Current Condition:	Inlet Protection	R8	8/20/2021 The inlet prior to the inspect	Pending	Yes		
	Hausmann Construction		• •	e as of the last inspection. H	ausmann		
IF 08	Inlet Protection	R7	8/13/2021	Active	No		
Current Condition:			inlet prior to the inspection ade. The E&A inspector w	n on 8/13/21. Inlet protection ill monitor.	will be		
IF 09	Inlet Protection	P7	6/26/2021	Pending	Yes		
Current Condition:	paved the area surround Inlet protection should b	ting the curb inlet prio e installed. was informed to com	r to the inspection on 7/30 plete by 8/20/21. Not done	ion on 6/26/21. Hausmann C /21. e as of the last inspection. Ha			
IF 10	Inlet Protection	M2	12/8/2020	Active	Yes		
Current Condition:	Construction cleaned ou The inlet protection shou Hausmann Construction	it and repositioned the uld be cleaned out/rep was informed to com	e inlet protection prior to th positioned.	e as of the last inspection. He			
IF 11	Inlet Protection	N2	12/8/2020	Active	Yes		
Current Condition:	Fair Condition - Hausmann Construction installed inlet protection prior to the first inspection on 12/08/20. Hausmann Construction cleaned out and repositioned the inlet protection prior to the inspection on 5/27/21. The inlet protection should be cleaned out/repositioned.						
	Hausmann Construction			Not done as of the last inspo	ection.		
MS 01	Material Storage	On Site	12/8/2020	Pending	No		
Current Condition:	Pending - The material s	storage will be installe	d as necessary.	1			
PB	Sanitary Waste Management	On Site	12/8/2020	Active	Yes		

Current Condition:	Fair Condition - Hausmann Construction placed and secured three portable toilets on site prior to the first inspection on 12/08/20. Hausmann Construction placed and secured two additional portable toilets prior to the inspection on 12/17/20. Hausmann Construction secured the two portable toilets at the job trailer prior to the inspection on 6/21/21. Hausmann Construction secured four of the five portable toilets on site prior to the inspection on 8/26/21.				
		was informed to com		e as of the last inspection. Ha 21, 8/03/21, 8/13/21	ausmann
SF 01	Silt Fence	S12 - R14		Removed	
Current Condition:	Removed - Hausmann 8/31/21.	Construction remov	ed the silt fence and fine	graded the area prior to th	e inspection o
SF 02	Silt Fence	R14 - K14	12/8/2020	Pending	No
Current Condition:	inspector will monitor.	-		recommended at this time. T	
SF 03 Current Condition:	Silt Fence Pending - Due to paving inspector will monitor.	J13 - H14 and the grade in the	12/8/2020 area, silt fence will not be	Pending recommended at this time. T	No The E&A
SF 04	Silt Fence	M2 - F13	12/8/2020	Active	Yes
Current Condition:				t fence prior to the first inspe	
	inspector will monitor. The western check shou Hausmann Construction	uld be cleaned out, rep	aired, and backfilled.	estall will not be made at this as of the last inspection. Ha 21	
SF 05	Silt Fence	K6 - J10	12/8/2020	Pending	No
Current Condition:				recommended at this time. T	
	inspector will monitor.	-			
SF 06	Silt Fence	L8 - J13	12/8/2020	Pending	No No
Current Condition:	inspector will monitor.	and the grade in the	area, silt fence will not be	recommended at this time. T	ne E&A
STR	Streets	On Site	12/8/2020	Active	Yes
Current Condition:	The streets (M Street ar Hausmann Construction	nd Highway 75) should was informed to com		e as of the last inspection. Ha	ausmann
SWPPP Sign	SWPPP Signs	South of Building	12/17/2020	Pending	Yes
Current Condition:	moved the SWPPP sign to the inspection on 2/22 to the inspection on 7/30 The SWPPP sign should	prior to the inspection 2/21. Hausmann Cons 0/21. d be reinstalled.	n on 2/09/21. Hausmann C truction removed the site plete by 8/06/21 (on-site).	ction on 12/17/20. Hausman Construction reinstalled the S fence the SWPPP sign was s Not done as of the last inspe	WPPP sign pri secured on pric
WO 01	Concrete Washout	On Site	12/8/2020	Active	Yes
Current Condition:	Hausmann Construction Hausmann Construction Construction cleaned up waste was observed out Concrete waste outside	cleaned up the concr placed another concr the concrete waste o side of the washout p of the washout pit sho was informed to com	ete washout outside of the ete washout on site prior to utside of the pit prior to th t during the inspection on ould be cleaned up. plete by 6/16/21. Not done	site prior to the first inspectio e pit prior to the inspection or to the inspection on 12/28/20 e inspection on 3/08/21. Son 3/15/21.	า 12/17/20. 9. Hausmann าe concrete
WS 01	Waste Storage Area	On Site	12/8/2020	Pending	No
Current Condition:	Pending - The waste sto				
	11. 1.			Porto Sul	