E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. Manager

Engineering Answers

		E&A - P202	20.235.001			
nspector: Joe Manning					Stage	
Project Name:	Tel	2				
For Week Ending:	10/9/2021 112 N 13th Street - Tekamah, NE (Burt County)					
Project Location:						
•			, ,			
Grading:	99%					
Sanitary Sewer:	100%					
Storm Sewer:	95%					
Paving:	100%					
Seeding:	0%				1	
Utilities:	50%					
Overall Development:	85%					
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Time		
Sunday.	0.00"				Wee	
Sunday:	0.00"	0/07/0004	0 000			
Monday	0.00"	9/27/2021	Sunny 90/54	8:15 AM		
Tuesday	0.00"					
Nednesday	0.00"					
Thursday	1.63"	9/30/2021	Cloudy 85/65	6:00 PM		
Friday	0.01"					
Saturday	0.02"					
					Wee	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"				1	
Friday	0.00"					
•	0.00"					
Saturday	0.00				Wee	
Sunday:	N/A				1.00	
Monday	N/A					
Tuesday	N/A					
	N/A					
Thursday	N/A					
Friday	N/A				1	
Saturday	N/A				1	
	1			_ L		
Complaints:						
Construction Sequencing:						

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Major grading complete (12/08/20). Storm sewer work began (12/08/20). Minor grading to be completed at a later date (3/08/21). Fine grading throughout site (8/31/21).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Major grading complete (12/08/20). Storm sewer work began (12/08/20). Minor grading to be completed at a later date (3/08/21). Fine grading throughout site (8/31/21).

What temporary or permanent stabilization measures listed in this section are being implemented?

Minor existing perimeter vegetation (12/08/20). Seeding/matting in the southern half of the site, landscaping in parking lot medians (9/30/21).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Create Corrective Action?

No - See Findings Section.

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

Create Corrective Action?

No - See BMP Section (FT and PT)

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

No - See BMP Section (Str).

Is dust associated with the construction activity adequately controlled on the site?

Create Corrective Action?

N/A

Comments:

Comments:

The site was **inactive** during the most recent inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1.) Some maintenance is required in the BMP section.
- 2.) The site should be stabilized or straw wattles should be installed along the curb lines throughout the site. Hausmann Construction was informed to complete by 9/20/21. Hausmann Construction seeded and matted the site south of 'M' Street prior to the inspection on 9/30/21.

FT Fuel Tank On Site 12/8/2020 Active Yes Current Condition: Fair Condition - Hausmann Construction placed a double-walled fuel tank on site prior to the first inspection on 12/08/20. E&A inspector will monitor and recommend additional containment as needed. Hausmann Construction placed one of the diesel tanks in secondary containment and cleaned up spills from the site prior to the inspection or 6/09/21.		T		l		I	
Current Condition: Removed - Hausmann paved the construction entrance prior to the inspection on 1/11/21. CE 02 Construction Entrance M8 Removed Current Condition: Removed - Hausmann Construction paved the construction entrance prior to the inspection on 7/30/21. CE 03 Construction Entrance H10 Removed Current Condition: Removed - Hausmann Construction paved the construction entrance prior to the inspection on 6/26/21. CE 04 Construction Entrance H10 Removed Current Condition: Removed - Hausmann Construction fully paved M Street prior to the inspection on 2/09/21. CE 05 Construction Entrance N4 Removed Current Condition: Removed - Hausmann Construction paved the construction entrance prior to the inspection on 7/30/21. CE 06 Construction Entrance R13 Removed Current Condition: Removed - Hausmann Construction paved the area near the construction entrance prior to the inspection on 8/13/21 FT Fuel Tank On Site 12/8/2020 Active Yes Current Condition: Fair Condition - Hausmann Construction placed a double-walled fuel tank on site prior to the first inspection on 12/08/20. E&A inspector will monitor and recommend additi	Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
Current Condition: CE 03 Construction Entrance H10 Removed Current Condition: Removed - Hausmann Construction paved the construction entrance prior to the inspection on 7/30/21. CE 03 Construction Entrance H10 Removed Current Condition: Removed - Hausmann Construction paved the construction entrance prior to the inspection on 6/26/21. CE 04 Construction Entrance H10 Removed Current Condition: Removed - Hausmann Construction fully paved M Street prior to the inspection on 2/09/21. CE 05 Construction Entrance N4 Removed Current Condition: Removed - Hausmann Construction paved the construction entrance prior to the inspection on 7/30/21. CE 06 Construction Entrance R13 Removed Current Condition: Removed - Hausmann Construction paved the area near the construction entrance prior to the inspection on 8/13/21 FT Fuel Tank On Site 12/8/2020 Active Yes Current Condition: Fair Condition - Hausmann Construction placed a double-walled fuel tank on site prior to the first inspection on 12/08/20. E&A inspector will monitor and recommend additional containment as needed. Hausmann Construction placed one of the diesel tanks in secondary containment and cleaned up spills from the site prior to the inspection or 6/09/21.	CE 01	Construction Entrance	K13		Removed		
Current Condition: Removed - Hausmann Construction paved the construction entrance prior to the inspection on 7/30/21. CE 03	Current Condition:	Removed - Hausmann paved the construction entrance prior to the inspection on 1/11/21.					
Current Condition: Removed - Hausmann Construction paved the construction entrance prior to the inspection on 6/26/21. CE 04 Construction Entrance H10 Removed Current Condition: Removed - Hausmann Construction fully paved M Street prior to the inspection on 2/09/21. CE 05 Construction Entrance N4 Removed Current Condition: Removed - Hausmann Construction paved the construction entrance prior to the inspection on 7/30/21. CE 06 Construction Entrance R13 Removed Current Condition: Removed - Hausmann Construction paved the area near the construction entrance prior to the inspection on 8/13/21 FT Fuel Tank On Site 12/8/2020 Active Yes Current Condition: Fair Condition - Hausmann Construction placed a double-walled fuel tank on site prior to the first inspection on 12/08/20. E&A inspector will monitor and recommend additional containment as needed. Hausmann Construction placed one of the diesel tanks in secondary containment and cleaned up spills from the site prior to the inspection or 6/09/21.	CE 02	Construction Entrance	M8		Removed		
Current Condition: Removed - Hausmann Construction paved the construction entrance prior to the inspection on 6/26/21. CE 04 Construction Entrance H10 Removed Current Condition: Removed - Hausmann Construction fully paved M Street prior to the inspection on 2/09/21. CE 05 Construction Entrance N4 Removed Current Condition: Removed - Hausmann Construction paved the construction entrance prior to the inspection on 7/30/21. CE 06 Construction Entrance R13 Removed Current Condition: Removed - Hausmann Construction paved the area near the construction entrance prior to the inspection on 8/13/21 FT Fuel Tank On Site 12/8/2020 Active Yes Current Condition: Fair Condition - Hausmann Construction placed a double-walled fuel tank on site prior to the first inspection on 12/08/20. E&A inspector will monitor and recommend additional containment as needed. Hausmann Construction placed one of the diesel tanks in secondary containment and cleaned up spills from the site prior to the inspection or 6/09/21.	Current Condition:	Removed - Hausmann Construction paved the construction entrance prior to the inspection on 7/30/21.					
CE 04 Construction Entrance H10 Removed Current Condition: Removed - Hausmann Construction fully paved M Street prior to the inspection on 2/09/21. CE 05 Construction Entrance N4 Removed Current Condition: Removed - Hausmann Construction paved the construction entrance prior to the inspection on 7/30/21. CE 06 Construction Entrance R13 Removed Current Condition: Removed - Hausmann Construction paved the area near the construction entrance prior to the inspection on 8/13/21 FT Fuel Tank On Site 12/8/2020 Active Yes Current Condition: Fair Condition - Hausmann Construction placed a double-walled fuel tank on site prior to the first inspection on 12/08/20. E&A inspector will monitor and recommend additional containment as needed. Hausmann Construction placed one of the diesel tanks in secondary containment and cleaned up spills from the site prior to the inspection or 6/09/21.	CE 03	Construction Entrance	H10		Removed		
Current Condition: Removed - Hausmann Construction fully paved M Street prior to the inspection on 2/09/21. CE 05 Construction Entrance N4 Removed Current Condition: Removed - Hausmann Construction paved the construction entrance prior to the inspection on 7/30/21. CE 06 Current Condition: Removed - Hausmann Construction paved the area near the construction entrance prior to the inspection on 8/13/21 FT Fuel Tank On Site 12/8/2020 Active Yes Current Condition: Fair Condition - Hausmann Construction placed a double-walled fuel tank on site prior to the first inspection on 12/08/20. E&A inspector will monitor and recommend additional containment as needed. Hausmann Construction placed one of the diesel tanks in secondary containment and cleaned up spills from the site prior to the inspection or 6/09/21.	Current Condition:	Removed - Hausmann C	onstruction paved the	e construction entrance pri	or to the inspection on 6/26/	21.	
CE 05 Current Condition: Removed - Hausmann Construction paved the construction entrance prior to the inspection on 7/30/21. CE 06 Current Condition: Removed - Hausmann Construction paved the area near the construction entrance prior to the inspection on 8/13/21 FT Fuel Tank On Site 12/8/2020 Active Yes Current Condition: Fair Condition - Hausmann Construction placed a double-walled fuel tank on site prior to the first inspection on 12/08/20. E&A inspector will monitor and recommend additional containment as needed. Hausmann Construction placed one of the diesel tanks in secondary containment and cleaned up spills from the site prior to the inspection or 6/09/21.	CE 04	Construction Entrance	H10		Removed		
Current Condition: Removed - Hausmann Construction paved the construction entrance prior to the inspection on 7/30/21. CE 06 Current Condition: Removed - Hausmann Construction paved the area near the construction entrance prior to the inspection on 8/13/21 FT Fuel Tank On Site 12/8/2020 Active Yes Current Condition: Fair Condition - Hausmann Construction placed a double-walled fuel tank on site prior to the first inspection on 12/08/20. E&A inspector will monitor and recommend additional containment as needed. Hausmann Construction placed one of the diesel tanks in secondary containment and cleaned up spills from the site prior to the inspection or 6/09/21.	Current Condition:	Removed - Hausmann C	Construction fully pave	ed M Street prior to the insp	pection on 2/09/21.		
Ce 06 Current Condition: Removed - Hausmann Construction paved the area near the construction entrance prior to the inspection on 8/13/21 FT Fuel Tank On Site 12/8/2020 Active Yes Current Condition: Fair Condition - Hausmann Construction placed a double-walled fuel tank on site prior to the first inspection on 12/08/20. E&A inspector will monitor and recommend additional containment as needed. Hausmann Construction placed one of the diesel tanks in secondary containment and cleaned up spills from the site prior to the inspection or 6/09/21.	CE 05	Construction Entrance	N4		Removed		
Current Condition: Removed - Hausmann Construction paved the area near the construction entrance prior to the inspection on 8/13/21 FT Fuel Tank On Site 12/8/2020 Active Yes Current Condition: Fair Condition - Hausmann Construction placed a double-walled fuel tank on site prior to the first inspection on 12/08/20. E&A inspector will monitor and recommend additional containment as needed. Hausmann Construction placed one of the diesel tanks in secondary containment and cleaned up spills from the site prior to the inspection or 6/09/21.	Current Condition:	Removed - Hausmann Construction paved the construction entrance prior to the inspection on 7/30/21.					
FT Fuel Tank On Site 12/8/2020 Active Yes Current Condition: Fair Condition - Hausmann Construction placed a double-walled fuel tank on site prior to the first inspection on 12/08/20. E&A inspector will monitor and recommend additional containment as needed. Hausmann Construction placed one of the diesel tanks in secondary containment and cleaned up spills from the site prior to the inspection or 6/09/21.	CE 06	Construction Entrance	R13		Removed		
Current Condition: Fair Condition - Hausmann Construction placed a double-walled fuel tank on site prior to the first inspection on 12/08/20. E&A inspector will monitor and recommend additional containment as needed. Hausmann Construction placed one of the diesel tanks in secondary containment and cleaned up spills from the site prior to the inspection or 6/09/21.	Current Condition:	Removed - Hausmann Construction paved the area near the construction entrance prior to the inspection on 8/13/21.					
12/08/20. E&A inspector will monitor and recommend additional containment as needed. Hausmann Construction placed one of the diesel tanks in secondary containment and cleaned up spills from the site prior to the inspection or 6/09/21.	FT	Fuel Tank	On Site	12/8/2020	Active	Yes	
capacity of the tank). Hausmann Construction was informed to complete by 1/04/21. Not done as of the last inspection. Hausmann	Current Condition:	12/08/20. E&A inspector will monitor and recommend additional containment as needed. Hausmann Construction placed one of the diesel tanks in secondary containment and cleaned up spills from the site prior to the inspection on 6/09/21. Secondary containment should be installed around the diesel tank on the western side of the site (at least 110% capacity of the tank). Hausmann Construction was informed to complete by 1/04/21. Not done as of the last inspection. Hausmann Construction was reminded on-site on 1/11/21, 3/09/21, 4/10/21, 4/20/21 (on-site), 5/21/21, 6/10/21, 6/26/21, 8/03/21,					
IF 01 Inlet Protection S14 12/8/2020 Active Yes	IF 01	Inlet Protection	S14	12/8/2020	Active	Yes	

Current Condition:	Fair Condition - Existing curb inlet along Highway 75. Hausmann Construction installed inlet protection prior to the inspection on 4/7/21. E&A inspector repositioned the inlet protection during the inspection on 5/19/21. The inlet protection should be cleaned off.					
	Hausmann Construction Construction was remind	· ·		as of the last inspection. F	lausmann	
IF 02	Inlet Protection	H13	12/8/2020	Active	No	
Current Condition:	12/08/20. Hausmann Co	nstruction installed inle t the inlet protection pr	et protection prior to the in Fior to the inspection on 3	ghway 75 prior to the first in espection on 1/11/21. Haus /15/21. Hausmann Constru	mann	
IF 03	Inlet Protection	H12	6/9/2021	Pending	No	
Current Condition:	Pending - The inlet was i inlet is at or below grade			protection will be recomme	nded when the	
IF 04	Inlet Protection	K11	12/17/2020	Active	No	
Current Condition:	Good Condition - Hausmann Construction installed the curb inlet prior to the first inspection on 12/08/20. Hausman Construction installed inlet protection prior to the inspection on 12/17/20. Hausmann Construction removed the inle protection due to paving in the area prior to the inspection on 12/28/20. Hausmann Construction reinstalled the inle protection prior to the inspection on 2/09/21. Hausmann Construction repaired the inlet protection prior to the inspection on 5/19/21.					
IF 05	Inlet Protection	J11	12/17/2020	Active	No	
Current Condition:				the first inspection on 12/0		
	protection due to paving protection prior to the insinspection on 5/27/21.	in the area prior to the spection on 1/11/21. Ha	e inspection on 12/28/20. ausmann Construction cle	. Hausmann Construction re Hausmann Construction re eaned out the inlet protection	placed the inle	
IF 06 Current Condition:	Inlet Protection	H10	6/9/2021	Pending protection will be recomme	No No	
Current Condition:	inlet is at or below grade			protection will be recomme	inded when the	
IF 07	Inlet Protection	R8	9/27/2021	Active	No	
Current Condition:	Good Condition - Hausi	mann Construction ins		inspection on 8/13/21. Ha		
IF 08	Inlet Protection	R7	9/27/2021	Active	No	
Current Condition:			talled the inlet prior to the to the to the to the total to the inspection on 9/2	inspection on 8/13/21. Ha 1 7/21.	usmann	
IF 09	Inlet Protection	P7	6/26/2021	Pending	Yes	
Current Condition:	Pending - Hausmann Construction installed the inlet prior to the inspection on 6/26/21. Hausmann Construction paved the area surrounding the curb inlet prior to the inspection on 7/30/21.					
	Inlet protection should be installed. Hausmann Construction was informed to complete by 8/20/21. Not done as of the last inspection. Hausmann					
				as of the last inspection. H	łausmann	
IE 10	Construction was remind	led on 8/26/21 (on-site	9), 9/13/21			
IF 10	Construction was remind Inlet Protection	led on 8/26/21 (on-site M2	12/8/2020	Active	No	
Current Condition:	Construction was remind Inlet Protection Good Condition - Hause Hausmann Construction Hausmann Construction	Med on 8/26/21 (on-site M2 mann Construction inst cleaned out and repose on cleaned out and re	12/8/2020 12/8/2020 talled inlet protection priositioned the inlet protection positioned the inlet protection	Active r to the first inspection on 1 n prior to the inspection on ection prior to the inspec	No 2/08/20. 5/27/21. tion on 9/27/2	
Current Condition:	Construction was remind Inlet Protection Good Condition - Hause Hausmann Construction Hausmann Construction Inlet Protection	ded on 8/26/21 (on-site M2 mann Construction instice cleaned out and repose on cleaned out	12/8/2020 12/8/2020 13/8/2020 14	Active r to the first inspection on 1 n prior to the inspection on ection prior to the inspec Active	No 2/08/20. 5/27/21. tion on 9/27/2	
Current Condition:	Construction was remind Inlet Protection Good Condition - Hause Hausmann Construction Hausmann Construction Inlet Protection Good Condition - Hause Hausmann Construction	Med on 8/26/21 (on-site M2 mann Construction instite cleaned out and repose on cleaned out and repose on Cleaned out and repose on Cleaned out and repose cleaned out and repose cleaned out and repose cleaned out and repose	12/8/2020 talled inlet protection priositioned the inlet protectio positioned the inlet prot 12/8/2020 talled inlet protection priositioned the inlet protection priositioned the inlet protection priositioned the inlet protection	Active r to the first inspection on 1 n prior to the inspection on ection prior to the inspec	No 2/08/20. 5/27/21. tion on 9/27/2 No 2/08/20. 5/27/21.	
Current Condition:	Construction was remind Inlet Protection Good Condition - Hause Hausmann Construction Hausmann Construction Inlet Protection Good Condition - Hause Hausmann Construction	Med on 8/26/21 (on-site M2 mann Construction instite cleaned out and repose on cleaned out and repose on Cleaned out and repose on Cleaned out and repose cleaned out and repose cleaned out and repose cleaned out and repose	12/8/2020 talled inlet protection priositioned the inlet protectio positioned the inlet prot 12/8/2020 talled inlet protection priositioned the inlet protection priositioned the inlet protection priositioned the inlet protection	Active r to the first inspection on 1 n prior to the inspection on rection prior to the inspection Active r to the first inspection on 1 n prior to the inspection on	No 2/08/20. 5/27/21. tion on 9/27/2 No 2/08/20. 5/27/21.	
Current Condition: IF 11 Current Condition:	Construction was remind Inlet Protection Good Condition - Hause Hausmann Construction Hausmann Construction Inlet Protection Good Condition - Hause Hausmann Construction Hausmann Construction Hausmann Construction Material Storage Pending - The material s	M2 mann Construction instelled on 8/26/21 (on-site M2 mann Construction instelled out and reposed out and repo	12/8/2020 12/8/2020 12/8/2020 12/8/2020 12/8/2020 12/8/2020 12/8/2020 12/8/2020	Active r to the first inspection on 1 n prior to the inspection on ection prior to the inspect Active r to the first inspection on 1 n prior to the inspection on 1 n prior to the inspection on ection prior to the inspec	No 2/08/20. 5/27/21. tion on 9/27/2 No 2/08/20. 5/27/21. tion on 9/27/2	
IF 11 Current Condition: MS 01 Current Condition:	Construction was remind Inlet Protection Good Condition - Hause Hausmann Construction Hausmann Construction Good Condition - Hause Hausmann Construction Hausmann Construction Hausmann Construction Hausmann Construction Hausmann Construction Sanitary Waste	Med on 8/26/21 (on-site M2 mann Construction instite cleaned out and reposite N2 mann Construction instite cleaned out and reposite cleaned out and reposite cleaned out and reposite on Cleaned ou	12/8/2020 talled inlet protection priositioned the inlet protection positioned the inlet protection positioned the inlet protection positioned the inlet protection priositioned the inlet protection positioned the inlet protection priority in the inlet priority in the in	Active r to the first inspection on 1 n prior to the inspection on rection prior to the inspection Active r to the first inspection on 1 n prior to the inspection on rection prior to the inspection Pending	No 2/08/20. 5/27/21. tion on 9/27/2 No 2/08/20. 5/27/21. tion on 9/27/2 No 2/08/20. 5/27/21. tion on 9/27/2	
IF 11 Current Condition: MS 01	Construction was remind Inlet Protection Good Condition - Hause Hausmann Construction Hausmann Construction Good Condition - Hause Hausmann Construction Hausmann Construction Hausmann Construction Hausmann Construction Sometime Storage Pending - The material s Sanitary Waste Management	mann Construction installed on 8/26/21 (on-site M2 mann Construction installed N2 mann Construction installed On Site On Site On Site	12/8/2020 talled inlet protection priositioned the inlet protection positioned the inlet protection positioned the inlet protection positioned the inlet protection priositioned the inlet protection prositioned the inlet protection positioned the inlet protection priority in the inlet priority in the in	Active r to the first inspection on 1 n prior to the inspection on ection prior to the inspect Active r to the first inspection on 1 n prior to the inspection on 1 n prior to the inspection on ection prior to the inspec	No 2/08/20. 5/27/21. tion on 9/27/2 No 2/08/20. 5/27/21. tion on 9/27/2 No Yes	

SF 01	Silt Fence	S12 - R14		Removed		
Current Condition:	8/31/21.			ded the area prior to the insp		
SF 02	Silt Fence	R14 - K14	12/8/2020	Pending	No	
Current Condition:	Pending - Due to paving and the grade in the area, silt fence will not be recommended at this time. The E&A inspector will monitor.					
SF 03	Silt Fence	J13 - H14	12/8/2020	Pending	No	
Current Condition:	inspector will monitor.		area, silt fence will not be	recommended at this time. T	he E&A	
SF 04	Silt Fence	M2 - F13		Removed		
Current Condition:		nd matted the area p	prior to the inspection on	o the inspection on 9/27/21. I 9/30/21.	Hausmann	
SF 05	Silt Fence	K6 - J10	12/8/2020	Pending	No	
Current Condition:	Pending - Due to paving inspector will monitor.	and the grade in the		recommended at this time. T	he E&A	
SF 06	Silt Fence	L8 - J13	12/8/2020	Pending	No	
Current Condition:	inspector will monitor.			recommended at this time. T		
STR Current Condition:	Streets	On Site	12/8/2020 ned the streets prior to the	Active	Yes	
			plete by 5/20/21. Not done 21, 7/30/21 (on-site), 8/03/	e as of the last inspection. Ha 21, 8/13/21, 9/13/21	ausmann	
SWPPP Sign	SWPPP Signs	South of Building	12/17/2020	Pending	Yes	
Current Condition:	Pending- The E&A inspector installed the SWPPP sign during the inspection on 12/17/20. Hausmann Construction moved the SWPPP sign prior to the inspection on 2/09/21. Hausmann Construction reinstalled the SWPPP sign prior to the inspection on 2/22/21. Hausmann Construction removed the site fence the SWPPP sign was secured on prior to the inspection on 7/30/21. The SWPPP sign should be reinstalled. Hausmann Construction was informed to complete by 8/06/21 (on-site). Not done as of the last inspection. Hausmann Construction was reminded on 8/03/21, 8/13/21, 9/13/21					
WO 01	Concrete Washout	On Site		Removed		
Current Condition:	inspection on 9/27/21.			d the washout from the site	prior to the	
WS 01	Waste Storage Area	On Site	12/8/2020	Pending	No	
Current Condition:	Pending - The waste sto	rage area will be insta	alled as necessary.	2.1.		
Inspector Signature:	you -		Reviewed By:	Posts Sol		