E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

ENGINEERING • PLANNING • FIELD SERVICES **Erosion Control Specialist- Manager** E&A- P2005.030.000 Stage Inspector: Patrick Pierce The Heritage NER110495 Project Name: 4/10/2010 For Week Ending: East of 156th Street and North and South of Rainwood Road- Bennington, NE 68007 (Douglas County) Project Location: Grading: 100% Sanitary Sewer: Storm Sewer: 100% 100% Paving: 100% Seeding: 100% Utilities: 100% Overall Development: RAIN FALL AMOUNTS Amount in inches Date inspected Sunday: Trace 0.00" Monday Tuesday Trace Wednesday 0.00" Thursday 0.00' Friday 0.28" Saturday 0.00" Sunday: 0.00" Monday 0.00" Tuesday 0.00" Wednesday 0.00" Thursday 0.00" Friday 0.00" Saturday 0.20' Sunday: 0.00" Monday 0.00' Tuesday Wednesday 0.00' Thursday 0.00 Friday 0.02 0.00" Saturday Sunday: 0.00" 04/05/10 Monday 0.11" Tuesday 0.08" Wednesday 0.08 Thursday 0.00" Friday 0.00" Saturday 0.00" None Complaints: Construction Sequencing: hich portion(s) (i.e. drainage basins) of the site have had a temporary or pern Entire site, grading completed 7/2006 and site seeded 9/5/06. Entire site, grading completed 7/2006 and site seeded 9/5/06.

Wetlands Mitigation Seeding (5/31/06), Slopes Seeded/Matted (8/30/06), Temp. Seeded (9/5/06), Re-Seeded 5/21/07, Re-Seeded ROW on 9/5/07 & 11/14/07, Erosion seeded in various areas (4/09)

Comments:

Comments:

Home construction is the only activity on site.

Findings / Corrective Actions (Date):

- 1) Some maintenance required in the BMP section.
 2) There are a few pieces of lot level silt fence that are down and damaged as of inspection on 3/12/10. Cassi with Newstreet was sent a plan requesting that this silt fence be repaired by 3/19/10. This was not complete prior to inspection on 04/05/10

requesting that this silt fence be repa	inca by 3/13/10. This Was	not complete prior to if	15pection on 04/05/10					
			Projected Install					
Unique Name	Туре	Location	Date	Status	Maintance			
CE 1	Construction Entrance	N41d00m00s W96d00m00s		Domovod				
CE 1 Current Condition:	Entrance was been			Removed				
Current Condition.	Construction	N41d00m00s						
CE 2	Entrance	W96d00m00s	6/1/2006	Active	No			
Current Condition:	Good Condition- 75	% Effective (Rocked or	n 6/2006 by Sudbeck)					
		N41d00m00s						
SB 1	Sediment Basin	W96d00m00s		Removed				
Current Condition:	Removed per Gradi	ing Modification; to be	constructed when school	ol site is graded.	-			
		N41d00m00s						
SB 2	Sediment Basin	W96d00m00s		Removed				
Current Condition:	Removed per Gradi	ng Modification	•					
	·	N41d00m00s	1		1			
SB 3	Sediment Basin	W96d00m00s	11/14/2005	Active	No			
Current Condition:	Good Condition- 19		11/14/2003	Active	140			
Carront Condition.	Cleanout 9/24/07 by Dave Hausman							
		N41d00m00s						
SB 4	Sediment Basin	W96d00m00s	11/14/2005	Active	No			
Current Condition:	Good Condition- 20				1			
			T	I	1			
SB 5	Sediment Basin	N41d00m00s W96d00m00s	11/2/2005	Active	No			
Current Condition:	Good Condition- 23		11/2/2005	Active	INO			
Current Condition.	Outlet Pipe recompacted by Sudbeck due to undermining- 4/2006							
	Oddiet i ipe recompi	N41d00m00s	To disdomining 4/2000					
SB 6	Sediment Basin	W96d00m00s	11/2/2005	Active	No			
Current Condition:	Good Condition- 36				1			
	Cleanout 10/2006 b	y Dave Hausman						
		N41d00m00s						
SF 1	Silt Fence	W96d00m00s		Removed				
Current Condition:	Removed by Nick V	Venninghoff prior to ins	pection on 10/15/09 du	e to dense vegetation.	1			
	·							
		N41d00m00s						
SF 2	Silt Fence	W96d00m00s	10/24/2005	Active	Yes			
Current Condition:	Fair Condition							
	Verious group class this ailt fance are down and domared as of inspection 0/40/40							
	Various areas along this silt fence are down and damaged as of inspection on 3/12/10.							
	Cassi with Newstreet was sent a plan requesting that this silt fence be repaired by 3/19/10. This was							
	not complete as of last inspection.							
		N41d00m00s	1	<u> </u>				
SF 3		W96d00m00s	10/24/2005	Active	Yes			
Current Condition:	Fair Condition		. 5,2 1/2000	7.0040				
	Various areas along this silt fence are down and damaged as of inspection on 3/12/10.							
	Cassi with Newstreet was sent a plan requesting that this silt fence be repaired by 3/19/10. This was							
	not complete as of I	ast inspection.						
		N41d00m00s						
SF 4	Silt Fence	W96d00m00s		Removed	No			
Current Condition:	Removed due to pe		Т	Т	1			
SE 5	Cilt Fons	N41d00m00s	6/40/2006	Activo	No			
SF 5 Current Condition:	Silt Fence Good Condition	W96d00m00s	6/19/2006	Active	No			
Current Condition:	Good Condition	N41d00m00s						
SF 6	Silt Fence	W96d00m00s	11/9/2005	Active	Yes			

Current Condition:	Fair Condition Various areas along this silt fence are down, damaged and full as of inspection on 3/12/10. Cassi with Newstreet was sent a plan requesting that this silt fence be cleaned out and repaired by 3/19/10. This was not complete as of last inspection.						
STR	Street Cleaning	N41d00m00s W96d00m00s	2/26/2007	Active	No		
Current Condition:	Good Condition- No major signs of track off.						
SWPPP Sign Current Condition:	Signs Good Condition: 156th and Cleveland	1 sign on site	8-19-08	Active	No		
nspector Signature:			Reviewed By:	Zadnany K. Jild	۲		