E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager Engineering Answers

Environmental Services Dept. I	Manager				
		&A- P2005.030.000			
Inchester: Alex Presses		ot 195 P2005.030.02	24		Stage
Inspector: Alex Brown			Slaye		
		The Herit			3   1
Project Name:	NER110495 5/14/2022				
For Week Ending:					
Project Locations	East of 156th Street, North and South of Rainwood Road - Bennington, NE (Douglas County)				68007
Project Location:					
	The Heritage	Replat 6			
Grading:	100%	90%			
Sanitary Sewer:	100%	95%			
Storm Sewer:	100%	80%			
Paving:	100%	50%			
Seeding:	100%	15%			
Utilities:	<u>    100%</u> 98%	0% 			
Overall Development:	98%	20%			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
		Date inspected	Weather Conditions	Time	Week 1
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.16"	4/12/2022	Cloudy / Windy 91/51	12:15 PM	
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Week 2
Sunday:	0.01"				
Monday:	0.00"	4/4.0/0000	01	0.05 PM	
Tuesday: Wednesday:	0.00" 0.01"	4/19/2022	Cloudy 52/29	3:05 PM	
Thursday:	0.01"				
Friday:	0.33"				
Saturday:	0.07"				
					Week 3
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"	4/26/2022	Sunny 72/30	12:20 PM	
Wednesday:	0.00"				
Thursday:	0.01"				
Friday: Saturday:	0.22"				
	0.02				Week 4
Sunday:	0.00"				Week 4
Monday:	1.17"				
Tuesday:	0.03"	5/3/2022	Cloudy 53/41	11:30 AM	
Wednesday:	0.02"				
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
Sunday:	0.05"				Week 5
Sunday: Monday	0.00"				
Tuesday	0.00"	5/10/2022	Partly Cloudy 86/68	12:35 PM	
Wednesday	0.00"	0/10/2022	Party cloudy 00/00	12.001 W	
Thursday	0.07"				
Friday	0.02"				
Saturday	0.01"				

	The E&A inspector met wit	ha homoownor Tom a	nd NDEE inspector Char	lia to discuss ron	oval of plug in
O a marta inter	The E&A inspector met with basin outlot. Per NDEE insp				
Complaints:	increased trash pick-up wit		regulatory concerns, bu	LOA Inspector w	
onstruction Sequencing:					
	of the site have had a temporary or pern	nanent cessation of grading	, earthwork, or ground disturba	nce in the last 14 days	\$?
				-	
ntire site, grading completed 7/2	006 and site seeded 9/5/06. Gradir	ng began on old school s	ite east of Stargrass Road	(11/9/17). Grading	activity on site idle
	tion began in replat 6 (9/27/21). <b>St</b> i				
hich portion(s) (i.e. drainage basins)	of the site do not have grading, earthwo	rk, or ground disturbance so	cheduled in the next 14 days?		
ntire site, grading completed 7/2	006 and site seeded 9/5/06. Gradir	n <mark>g began on old school s</mark>	ite east of Stargrass Road	(11/9/17). Grading	activity on site idle
	tion began in replat 6 (9/27/21). <b>St</b> i		4/12/22).		
	tion measures listed in this section are				
0	1/06), Slopes Seeded/Matted (8/30	<i>p</i> 1 (	<i>,</i> , , , , , , , , , , , , , , , , , , ,		
	4/09), Old Basin 5 was seeded and				
	ng SB#4 has been seeded (5/22/1	8). Stub road at the end	of N 149th Street seeded a	nd matted (9/8/20).	Replat 6 was temp
eeded (8/9/21).					
hecklist Questions:					
	o the project free of any significa	Int signs of erosion or s	sediment that would be as	sociated with the	construction
ctivity? es					
reate Corrective Action?					
/A					
	led or otherwise stabilized as ree	quired? List inactive po	ortions of the project and	if stabilization me	asure are adequat
r needed to prevent erosion.					
es					
reate Corrective Action?					
re waste materials (concrete, o	construction material, hazardous	s. etc.) being managed	properly?		
D	, ,	,, <b></b> g			
reate Corrective Action?					
o - See BMP Section (Lot 22)					
	adia and streats being maintain	ad adamintahi0			
Are construction entrances and	adjacent streets being maintain	ed adequately?			
Create Corrective Action?					
o - See BMP section					
	struction activity adequately con	trolled on the site?			
es Create Corrective Action?					
A					
comments:					
comments:					
. Site was inactive for home buil	ding during the most recent insp	Poplat 6 was as	tive during the most recent	increation	
	ang danng the moot recent mop	ection. Replat 0 was ac		inspection.	
	accommodate the dirt from the gra				itor its effectivenes
. SB 4 is being partially closed to he surrounding area is primarily		ading of the new area as	of 11/9/17. The inspector v	vill continue to mon	
. SB 4 is being partially closed to he surrounding area is primarily	accommodate the dirt from the gra	ading of the new area as	of 11/9/17. The inspector v	vill continue to mon	
. SB 4 is being partially closed to he surrounding area is primarily s of the 8/13/18 inspection.	accommodate the dirt from the gra built out so the remaining basin car	ading of the new area as	of 11/9/17. The inspector v	vill continue to mon	
. SB 4 is being partially closed to he surrounding area is primarily s of the 8/13/18 inspection. indings / Corrective Actions (D	accommodate the dirt from the gra built out so the remaining basin car late):	ading of the new area as	of 11/9/17. The inspector v	vill continue to mon	
. SB 4 is being partially closed to he surrounding area is primarily s of the 8/13/18 inspection. indings / Corrective Actions (D indings / Corrective Actions (D	accommodate the dirt from the gra built out so the remaining basin can hate): hate):	ading of the new area as	of 11/9/17. The inspector v	vill continue to mon	
. SB 4 is being partially closed to he surrounding area is primarily s of the 8/13/18 inspection. indings / Corrective Actions (D indings / Corrective Actions (D	accommodate the dirt from the gra built out so the remaining basin can hate): hate):	ading of the new area as	of 11/9/17. The inspector v	vill continue to mon	
. SB 4 is being partially closed to he surrounding area is primarily is of the 8/13/18 inspection. indings / Corrective Actions (D indings / Corrective Actions (D .) Some maintenance is required	accommodate the dirt from the gra built out so the remaining basin car late): ate): in the BMP section.	ading of the new area as n accommodate the flow	of 11/9/17. The inspector v coming from the adjacent l	vill continue to mon ots. The basin was	working effectively
. SB 4 is being partially closed to he surrounding area is primarily s of the 8/13/18 inspection. indings / Corrective Actions (D indings / Corrective Actions (D	accommodate the dirt from the gra built out so the remaining basin can hate): hate):	ading of the new area as	of 11/9/17. The inspector v	vill continue to mon	
. SB 4 is being partially closed to he surrounding area is primarily is of the 8/13/18 inspection. indings / Corrective Actions (D indings / Corrective Actions (D .) Some maintenance is required	accommodate the dirt from the gra built out so the remaining basin car late): ate): in the BMP section.	ading of the new area as n accommodate the flow Location	of 11/9/17. The inspector v coming from the adjacent l	vill continue to mon ots. The basin was	working effectively
SB 4 is being partially closed to he surrounding area is primarily is of the 8/13/18 inspection. indings / Corrective Actions (D indings / Corrective Actions (D .) Some maintenance is required	accommodate the dirt from the gra built out so the remaining basin car late): ate): in the BMP section.	ading of the new area as n accommodate the flow Location	of 11/9/17. The inspector v coming from the adjacent l	vill continue to mon ots. The basin was	working effectively
SB 4 is being partially closed to he surrounding area is primarily s of the 8/13/18 inspection. indings / Corrective Actions (D indings / Corrective Actions (D ) Some maintenance is required Unique Name	accommodate the dirt from the grabult out so the remaining basin can built out so the remaining basin can bate): hate): in the BMP section. Type	ading of the new area as n accommodate the flow Location Intersection of Rosewood and Rainwood Road	of 11/9/17. The inspector v coming from the adjacent I Projected Install Date 11/21/2017	vill continue to mon ots. The basin was Status Pending	Maintenance
SB 4 is being partially closed to he surrounding area is primarily s of the 8/13/18 inspection. indings / Corrective Actions (D indings / Corrective Actions (D .) Some maintenance is required Unique Name CE 1 Current Condition:	accommodate the dirt from the grabuilt out so the remaining basin car built out so the remaining basin car late): late): in the BMP section. Construction Entrance Pending - The inspector will i	ading of the new area as n accommodate the flow Location Intersection of Rosewood and Rainwood Road recommend an entrance	of 11/9/17. The inspector v coming from the adjacent I Projected Install Date 11/21/2017	vill continue to mon ots. The basin was Status Pending of the 11/21/2017	Maintenance
SB 4 is being partially closed to he surrounding area is primarily is of the 8/13/18 inspection. indings / Corrective Actions (D indings / Corrective Actions (D ) Some maintenance is required Unique Name CE 1 Current Condition: CW 1	accommodate the dirt from the grabult out so the remaining basin car built out so the remaining basin car late): in the BMP section. Type Construction Entrance Pending - The inspector will i Concrete Washout	Ading of the new area as n accommodate the flow Location Intersection of Rosewood and Rainwood Road recommend an entrance Lot 20	of 11/9/17. The inspector v coming from the adjacent I Projected Install Date 11/21/2017 if it becomes necessary as	vill continue to mon ots. The basin was Status Pending of the 11/21/2017 Removed	Maintenance No inspection.
SB 4 is being partially closed to be surrounding area is primarily is of the 8/13/18 inspection. indings / Corrective Actions (D indings / Corrective Actions (D ) Some maintenance is required Unique Name CE 1 Current Condition: CW 1 Current Condition:	accommodate the dirt from the grabuilt out so the remaining basin car built out so the remaining basin car late): In the BMP section. Construction Entrance Pending - The inspector will in Concrete Washout Removed - Boyer Young clear	Ading of the new area as n accommodate the flow Location Intersection of Rosewood and Rainwood Road recommend an entrance Lot 20 aned out and removed th	of 11/9/17. The inspector v coming from the adjacent I Projected Install Date 11/21/2017 if it becomes necessary as	vill continue to mon ots. The basin was Status Pending of the 11/21/2017 Removed o the 9/26/15 inspe	Maintenance No inspection.
SB 4 is being partially closed to he surrounding area is primarily is of the 8/13/18 inspection. indings / Corrective Actions (D indings / Corrective Actions (D .) Some maintenance is required Unique Name CE 1 Current Condition: CW 1 Current Condition: CW 2	accommodate the dirt from the grabult out so the remaining basin car built out so the remaining basin car late): In the BMP section. Construction Entrance Pending - The inspector will I Concrete Washout Removed - Boyer Young clea	Ading of the new area as n accommodate the flow Location Intersection of Rosewood and Rainwood Road recommend an entrance Lot 20 aned out and removed th Lot 162	of 11/9/17. The inspector v coming from the adjacent I Projected Install Date 11/21/2017 if it becomes necessary as concrete washout prior to	vill continue to mon ots. The basin was Status Pending of the 11/21/2017 Removed the 9/26/15 inspe Removed	Maintenance No inspection.
. SB 4 is being partially closed to he surrounding area is primarily is of the 8/13/18 inspection. indings / Corrective Actions (D indings / Corrective Actions (D .) Some maintenance is required Unique Name CE 1 Current Condition: CW 1 Current Condition:	accommodate the dirt from the grabuilt out so the remaining basin car built out so the remaining basin car late): In the BMP section. Construction Entrance Pending - The inspector will in Concrete Washout Removed - Boyer Young clear	Ading of the new area as n accommodate the flow Location Intersection of Rosewood and Rainwood Road recommend an entrance Lot 20 aned out and removed th Lot 162 aned out and removed th	of 11/9/17. The inspector v coming from the adjacent I Projected Install Date 11/21/2017 if it becomes necessary as concrete washout prior to	vill continue to mon ots. The basin was Status Pending of the 11/21/2017 Removed the 9/26/15 inspe Removed	Maintenance No inspection.
SB 4 is being partially closed to he surrounding area is primarily is of the 8/13/18 inspection. indings / Corrective Actions (D indings / Corrective Actions (D .) Some maintenance is required Unique Name CE 1 Current Condition: CW 1 Current Condition: CW 2 Current Condition:	accommodate the dirt from the grabult out so the remaining basin car built out so the remaining basin car inte): in the BMP section. Construction Entrance Pending - The inspector will in Concrete Washout Removed - Boyer Young clear Concrete Washout	Ading of the new area as n accommodate the flow Location Intersection of Rosewood and Rainwood Road recommend an entrance Lot 20 aned out and removed th Lot 162 aned out and removed th Rosewater Prky and	of 11/9/17. The inspector v coming from the adjacent I Projected Install Date 11/21/2017 if it becomes necessary as concrete washout prior to	Status Pending of the 11/21/2017 Removed the 9/26/15 inspe Removed the 9/26/15 inspe	Maintenance No inspection.
SB 4 is being partially closed to he surrounding area is primarily is of the 8/13/18 inspection. indings / Corrective Actions (D indings / Corrective Actions (D .) Some maintenance is required Unique Name CE 1 Current Condition: CW 1 Current Condition: CW 2 Current Condition: IF 1	accommodate the dirt from the grabult out so the remaining basin car built out so the remaining basin car inte): in the BMP section. Construction Entrance Pending - The inspector will n Concrete Washout Removed - Boyer Young cleat Concrete Washout Removed - Boyer Young cleat Inlet Filter	Ading of the new area as n accommodate the flow Location Intersection of Rosewood and Rainwood Road recommend an entrance Lot 20 aned out and removed th Lot 162 aned out and removed th Rosewater Prky and Chicory St.	of 11/9/17. The inspector v coming from the adjacent I Projected Install Date 11/21/2017 if it becomes necessary as e concrete washout prior to concrete washout prior to	vill continue to mon ots. The basin was Status Pending of the 11/21/2017 Removed the 9/26/15 inspe Removed	Maintenance No inspection.
SB 4 is being partially closed to he surrounding area is primarily is of the 8/13/18 inspection. indings / Corrective Actions (D indings / Corrective Actions (D .) Some maintenance is required Unique Name CE 1 Current Condition: CW 1 Current Condition: CW 2 Current Condition: IF 1 Current Condition:	accommodate the dirt from the gra built out so the remaining basin car inte): in the BMP section. Construction Entrance Pending - The inspector will in Concrete Washout Removed - Boyer Young cleat Concrete Washout Removed - Boyer Young cleat Inlet Filter Removed - E&A inspector re	Ading of the new area as n accommodate the flow Intersection of Rosewood and Rainwood Road recommend an entrance Lot 20 aned out and removed th Lot 162 aned out and removed th Rosewater Prky and Chicory St.	of 11/9/17. The inspector v coming from the adjacent I Projected Install Date 11/21/2017 if it becomes necessary as e concrete washout prior to concrete washout prior to	vill continue to mon ots. The basin was Status Pending of the 11/21/2017 Removed b the 9/26/15 inspe Removed the 9/26/15 inspe Removed	Maintenance No inspection.
. SB 4 is being partially closed to he surrounding area is primarily is of the 8/13/18 inspection. indings / Corrective Actions (D indings / Corrective Actions (D .) Some maintenance is required Unique Name CE 1 Current Condition: CW 1 Current Condition: CW 2 Current Condition: IF 1 Current Condition: Lot 17	accommodate the dirt from the gra built out so the remaining basin car inte): in the BMP section. Construction Entrance Pending - The inspector will in Concrete Washout Removed - Boyer Young clea Concrete Washout Removed - Boyer Young clea Inlet Filter Removed - E&A inspector re Individual Lot	Location Location Intersection of Rosewood and Rainwood Road recommend an entrance Lot 20 aned out and removed th Lot 162 aned out and removed th Rosewater Prky and Chicory St. moved the inlet filter duri Lot 17	of 11/9/17. The inspector v coming from the adjacent I Projected Install Date 11/21/2017 if it becomes necessary as e concrete washout prior to ne concrete washout prior to ing inspection on 4/15/17.	Status Pending of the 11/21/2017 Removed the 9/26/15 inspe Removed the 9/26/15 inspe	Maintenance No inspection.
. SB 4 is being partially closed to he surrounding area is primarily is of the 8/13/18 inspection. indings / Corrective Actions (D indings / Corrective Actions (D .) Some maintenance is required Unique Name CE 1 Current Condition: CW 1 Current Condition: CW 2 Current Condition: IF 1 Current Condition: Lot 17 Current Condition:	accommodate the dirt from the gra built out so the remaining basin car late): In the BMP section. Construction Entrance Pending - The inspector will I Concrete Washout Removed - Boyer Young clea Concrete Washout Removed - Boyer Young clea Inlet Filter Removed - E&A inspector re Individual Lot Removed - Metro Homes soo	Ading of the new area as n accommodate the flow Location Intersection of Rosewood and Rainwood Road recommend an entrance Lot 20 aned out and removed th Lot 162 aned out and removed th Rosewater Prky and Chicory St. moved the inlet filter dur Lot 17 dded the lot prior to the in	of 11/9/17. The inspector v coming from the adjacent I Projected Install Date 11/21/2017 if it becomes necessary as e concrete washout prior to ne concrete washout prior to ing inspection on 4/15/17.	vill continue to mon ots. The basin was Status of the 11/21/2017 Removed the 9/26/15 inspe Removed the 9/26/15 inspe Removed Removed	Maintenance No inspection.
SB 4 is being partially closed to he surrounding area is primarily is of the 8/13/18 inspection. indings / Corrective Actions (D indings / Corrective Actions (D .) Some maintenance is required Unique Name CE 1 Current Condition: CW 1 Current Condition: CW 2 Current Condition: IF 1 Current Condition: Lot 17	accommodate the dirt from the gra built out so the remaining basin car inte): in the BMP section. Construction Entrance Pending - The inspector will in Concrete Washout Removed - Boyer Young clea Concrete Washout Removed - Boyer Young clea Inlet Filter Removed - E&A inspector re Individual Lot	Ading of the new area as n accommodate the flow Location Intersection of Rosewood and Rainwood Road recommend an entrance Lot 20 aned out and removed th Lot 162 aned out and removed th Chicory St. moved the inlet filter duri Lot 17 dded the lot prior to the in	of 11/9/17. The inspector v coming from the adjacent I Projected Install Date 11/21/2017 if it becomes necessary as e concrete washout prior to ne concrete washout prior to ne concrete washout prior to ne concrete washout prior to	vill continue to mon ots. The basin was Status Pending of the 11/21/2017 Removed b the 9/26/15 inspe Removed the 9/26/15 inspe Removed	Maintenance No inspection.

Lot 22 Current Condition:	Individual Lot Good Condition - Metro Ho	Lot 22	11/24/2020	Active	No No
	wattles along the front of t				omes installe
Lot 24	Individual Lot	Lot 24		Removed	
Current Condition:	Removed - Story Homes so	dded the lot prior to the 1	1/11/21 inspection.		1
Lot 25	Individual Lot	Lot 25		Removed	
Current Condition:	Removed - Metro Homes so		nspection on 6/11/21.		
				1	1
SF 6	Silt Fence	SB 5		Removed	
Current Condition:	Removed - Commercial See	- °	ce prior to the 10/9/18 insp		
SF 7	Silt Fence	SB 3		Removed	
Current Condition:	Removed - SF 7 changed to		6) as of 5/15/18.		1
SF 8	Silt Fence Removed - Boyer Young ins	Rainwood Road	n front of Doinwood Dood r	Removed	Silt Fanaa wa
Current Condition:	repaired prior to the 8/13/18				
05.0	0.11 5	The perimeter of the	1.1/0.1/00.17		
SF 9 Current Condition:	Silt Fence Good Condition - The silt fer	newly graded area	11/21/2017	Active	No No
ourient oonation.	Seeding installed silt fence a				
	corner was repaired prior to				
	lots prior to the 8/13/18 insp				
	inspection. Commercial See	ding backfilled and repair	red the silt fence prior to the	e 6/24/19 inspectior	<ol> <li>E&amp;A inspect</li> </ol>
	retied the silt fence where it				
	the silt fence in multiple loca undermined silt fence prior t				
	inspection on 6/21/21. Com				
	Seeding fixed all silt fence o	•	•		
		1			
		South of Wild Indigo St			
SB 3	Sediment Basin	and Prairie Star St.		Removed	
Current Condition:	Removed - The basin was c		inspection.	•	
SB 4	Sediment Basin	South of 149th Dead End	11/14/2005	Active	No
Current Condition:	Good Condition- 41% Filled				
Current Condition.	southern riser and removed				usun Kourren
		Southwest corner of	 	- 	1
		Rosewater Pkwy and			
		North H.W.S			
SB 5	Sediment Basin	Cleveland Blvd		Removed	
Current Condition:	Removed - The basin was o	losed prior to the 8/24/16	inspection.		
STR	Street Cleaning	Entire Site	2/26/2007	Active	No
Current Condition:	Good Condition - Story Hon				
	cleaned the street in front of	lot 22 prior to the 3/14/22	2 inspection. Minino Home	es cleaned 149th S	treet prior to t
	4/12/22 inspection.	Desile ( 0			
CE 1	Construction Entrance	Replat 6 Southwest corner	5/27/2021	Active	Yes
	Fair Condition - 65% effectiv				
Current Condition:					
Current Condition:					
Current Condition:	Rock should be added to the				
Current Condition:		e entrance.			
Current Condition:	Rock should be added to the Mark Hopkins and Steve Mi	e entrance.		ne as of last inspec	tion.
	Mark Hopkins and Steve Mi	e entrance. nino were informed to con	nplete by 4/12/22. <b>Not dor</b>		
CE 2	Mark Hopkins and Steve Mir	e entrance. nino were informed to con Northeast corner	nplete by 4/12/22. <b>Not dor</b> 5/27/2021	Pending	No
	Mark Hopkins and Steve Mir Construction Entrance Pending- Due to CE 1 being	e entrance. nino were informed to con Northeast corner installed a second const	nplete by 4/12/22. <b>Not dor</b> 5/27/2021 ruction entrance will not be	Pending	No
CE 2 Current Condition:	Mark Hopkins and Steve Mir Construction Entrance Pending- Due to CE 1 being inspector will continue to mo	e entrance. nino were informed to con Northeast corner installed a second const nitor and make recomme	nplete by 4/12/22. <b>Not dor</b> 5/27/2021 ruction entrance will not be endations.	Pending recommended at th	No Nis time. E&A
CE 2 Current Condition: D 1	Mark Hopkins and Steve Mi Construction Entrance Pending- Due to CE 1 being inspector will continue to mo Diversion Ditch	e entrance. nino were informed to con Northeast corner installed a second const nitor and make recomme South of SB 4	nplete by 4/12/22. <b>Not dor</b> 5/27/2021 ruction entrance will not be indations. 6/14/2021	Pending	No
CE 2 Current Condition: D 1 Current Condition:	Mark Hopkins and Steve Mi Construction Entrance Pending- Due to CE 1 being inspector will continue to mo Diversion Ditch Good Condition - JBG insta	e entrance. nino were informed to con Northeast corner installed a second const nitor and make recomme South of SB 4 lled the diversion prior to	nplete by 4/12/22. <b>Not dor</b> 5/27/2021 ruction entrance will not be indations. 6/14/2021	Pending recommended at th Active	No Nis time. E&A
CE 2 Current Condition: D 1 Current Condition: FT 1	Mark Hopkins and Steve Mi Construction Entrance Pending- Due to CE 1 being inspector will continue to mo Diversion Ditch Good Condition - JBG insta Fuel Tank	e entrance. nino were informed to con Northeast corner installed a second const nitor and make recomme South of SB 4 lled the diversion prior to On site	nplete by 4/12/22. Not dor 5/27/2021 ruction entrance will not be indations. 6/14/2021 the inspection on 6/14/21.	Pending recommended at th Active Removed	No nis time. E&A
CE 2 Current Condition: D 1 Current Condition:	Mark Hopkins and Steve Mi Construction Entrance Pending- Due to CE 1 being inspector will continue to mo Diversion Ditch Good Condition - JBG insta Fuel Tank Removed - JBG installed th	e entrance. nino were informed to con Northeast corner installed a second const nitor and make recomme South of SB 4 lled the diversion prior to On site e fuel tank on site prior to	nplete by 4/12/22. Not dor 5/27/2021 ruction entrance will not be indations. 6/14/2021 the inspection on 6/14/21.	Pending recommended at th Active Removed	No nis time. E&A
CE 2 Current Condition: D 1 Current Condition: FT 1 Current Condition:	Mark Hopkins and Steve Mi Construction Entrance Pending- Due to CE 1 being inspector will continue to mo Diversion Ditch Good Condition - JBG insta Fuel Tank Removed - JBG installed th site prior to the inspection of	e entrance. nino were informed to con- installed a second const nitor and make recomme South of SB 4 lled the diversion prior to On site e fuel tank on site prior to n12/6/21.	nplete by 4/12/22. Not dor 5/27/2021 ruction entrance will not be indations. 6/14/2021 the inspection on 6/14/21.	Pending recommended at th Active Removed 1. JBG removed the	No nis time. E&A
CE 2 Current Condition: D 1 Current Condition: FT 1 Current Condition: PT 01	Mark Hopkins and Steve Mi Construction Entrance Pending- Due to CE 1 being inspector will continue to mo Diversion Ditch Good Condition - JBG insta Fuel Tank Removed - JBG installed th site prior to the inspection of Portable Toilet	e entrance. nino were informed to con Northeast corner installed a second const nitor and make recomme South of SB 4 lled the diversion prior to On site e fuel tank on site prior to n12/6/21. Adjacent to CE 2	nplete by 4/12/22. Not dor 5/27/2021 ruction entrance will not be endations. 6/14/2021 the inspection on 6/14/21.	Pending recommended at th Active Removed JBG removed the Removed	No nis time. E&A No tuel tank fron
CE 2 Current Condition: D 1 Current Condition: FT 1 Current Condition:	Mark Hopkins and Steve Mi Construction Entrance Pending- Due to CE 1 being inspector will continue to mo Diversion Ditch Good Condition - JBG insta Fuel Tank Removed - JBG installed th site prior to the inspection of Portable Toilet Removed - Mark Hopkins ir	e entrance. nino were informed to con Northeast corner installed a second const nitor and make recomme South of SB 4 lled the diversion prior to On site e fuel tank on site prior to n12/6/21. Adjacent to CE 2 installed and secured a po	nplete by 4/12/22. Not dor 5/27/2021 ruction entrance will not be endations. 6/14/2021 the inspection on 6/14/21. b the inspection on 11/22/2 othe inspection on 11/22/2	Pending recommended at th Active Removed JBG removed the Removed Removed pection on 9/27/21.	No his time. E&A No fuel tank fron
CE 2 Current Condition: D 1 Current Condition: FT 1 Current Condition: PT 01	Mark Hopkins and Steve Mi Construction Entrance Pending- Due to CE 1 being inspector will continue to mo Diversion Ditch Good Condition - JBG insta Fuel Tank Removed - JBG installed th site prior to the inspection of Portable Toilet	e entrance. nino were informed to con Northeast corner installed a second const installed a second const South of SB 4 lled the diversion prior to On site e fuel tank on site prior to n12/6/21. Adjacent to CE 2 stalled and secured a po E 1 prior to the 11/11/21 i	nplete by 4/12/22. Not dor 5/27/2021 ruction entrance will not be endations. 6/14/2021 the inspection on 6/14/21. b the inspection on 11/22/2 hthe inspection on 11/22/2	Pending recommended at tl Active Removed J.JBG removed the Removed Removed Dection on 9/27/21.	No his time. E&A No fuel tank from
CE 2 Current Condition: D 1 Current Condition: FT 1 Current Condition: PT 01	Mark Hopkins and Steve Mi Construction Entrance Pending- Due to CE 1 being inspector will continue to mo Diversion Ditch Good Condition - JBG insta Fuel Tank Removed - JBG installed th site prior to the inspection of Portable Toilet Removed - Mark Hopkins ir moved to the east side of Cl	e entrance. nino were informed to con Northeast corner installed a second const installed a second const South of SB 4 lled the diversion prior to On site e fuel tank on site prior to n12/6/21. Adjacent to CE 2 stalled and secured a po E 1 prior to the 11/11/21 i	nplete by 4/12/22. Not dor 5/27/2021 ruction entrance will not be endations. 6/14/2021 the inspection on 6/14/21. b the inspection on 11/22/2 hthe inspection on 11/22/2	Pending recommended at tl Active Removed J.JBG removed the Removed Removed Dection on 9/27/21.	No his time. E&A No fuel tank from
CE 2 Current Condition: D 1 Current Condition: FT 1 Current Condition: PT 01 Current Condition:	Mark Hopkins and Steve Mi Construction Entrance Pending- Due to CE 1 being inspector will continue to mo Diversion Ditch Good Condition - JBG insta Fuel Tank Removed - JBG installed th site prior to the inspection of Portable Toilet Removed - Mark Hopkins ir moved to the east side of Cl inspection on 12/6/21. Mark	e entrance.     Northeast corner     installed a second const installed a second const installed a second const installed a second const installed and second const installed the diversion prior to On site e fuel tank on site prior to n12/6/21. Adjacent to CE 2 nstalled and secured a po E 1 prior to the 11/11/21 i Hopkins removed the po On Site	nplete by 4/12/22. Not dor 5/27/2021 ruction entrance will not be indations. 6/14/2021 the inspection on 6/14/21. b the inspection on 11/22/2 intable toilet prior to the insp inspection. Mark Hopkins so rtable toilet prior to the 3/12 4/12/2022	Pending recommended at tl Active Removed I. JBG removed the Removed Removed Course the portable 4/22 inspection. Active	No his time. E&A No fuel tank from Portable toilet toilet prior to th

Current Condition:	Good Condition- Mark Hopkins installed prior to the inspection on 5/27/21. Commercial Seeding extended the silt fence west along the basin prior to the inspection on 9/27/21. Mark Hopkins repaired the silt fence prior to the inspection on 12/6/21.					
SWPPP Sign	Signs	1 sign on site	8/19/2008	Active	No	
Current Condition:	Good Condition: E&A inspector installed the SWPPP sign on 8/19/08 at 156th and Bennington Blvd					
Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."					
nspector Signature:	1			Reviewed By:	Cato Sul	