E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager Engineering Answers

		&A- P2005.030.000 ot 195 P2005.030.02			
Inspector: Alex Brown					Stage
		The Herit	tage		
Project Name:		NER110			3 1
		7/9/202			
For Week Ending:	Fact of 456th Street		ZZ Rainwood Road - Bennir		
Project Location:	East of 156th Stree	68007			
		(Douglas Co	unty)		
	The Heritage	Replat 6			
Grading:	100%	90%			
Sanitary Sewer:	100%	95%			
Storm Sewer:	100%	80%			
Paving:	100%	50%			
Seeding:	100%	15%			
Utilities:	100%	0%			
Overall Development:	98%	20%			
				I	1
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week 1
Sunday:	0.01"				
Monday	0.00"				
Tuesday	0.00"	6/14/2022	Partly Cloudy 94/77	11:35 AM	
Wednesday	1.52"				
Thursday	0.03"				
Friday	0.00"				
Saturday	0.00"				
					Week 2
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"	6/21/2022	Partly Cloudy 90/71	2:10 PM	
Wednesday:	0.00"				
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
					Week 3
Sunday:	0.00"				
Monday:	0.00"	0/00/0000	0 77	40.00 PM	
Tuesday:	0.00"	6/28/2022	Sunny 77	12:00 PM	
Wednesday: Thursday:	0.00"				
Friday:	0.00 [*]				
Saturday:	0.00"				
					Week 4
Sunday:	0.00"				
Monday:	0.33"				
Tuesday:	0.02"	7/5/2022	Partly Cloudy 97/72	2:25 PM	
Wednesday:	0.27"				
Thursday:	0.03"			1	
Friday:	0.05"				
Saturday:	0.04"				
					Week 5
Sunday:	N/A				
Monday	N/A				
Tuesday	N/A				
Wednesday	N/A				
Thursday	N/A				
Friday	N/A				
Saturday	N/A				

Complaints:					
construction Sequencing:					
hich portion(s) (i.e. drainage basins) of th	ne site have had a temporary or perm	nanent cessation of grading	, earthwork, or ground disturba	nce in the last 14 days	\$?
ntire site, grading completed 7/2006			•	(11/9/17). Grading	activity on site idle
0/9/20). Storm and sewer installatior /hich portion(s) (i.e. drainage basins) of th					
		<u> </u>			
ntire site, grading completed 7/2006 9/9/20). Storm and sewer installatior				(11/9/17). Grading	activity on site idle
hat temporary or permanent stabilization			12/22).		
/etlands Mitigation Seeding (5/31/00	3), Slopes Seeded/Matted (8/30/	06), Temp. Seeded (9/5	/06), Re-Seeded 5/21/07, R	e-Seeded ROW or	n 9/5/07 & 11/14/07,
rosion seeded in various areas (4/0	9), Old Basin 5 was seeded and	I matted (5/2/12). The a	reas that were disturbed wh	en SB 3 and 5 wer	e closed has been
eeded (9/10/16/). Area surrounding	SB#4 has been seeded (5/22/18	3). Stub road at the end	of N 149th Street seeded a	nd matted (9/8/20).	Replat 6 was temp
eeded (8/9/21).					
hecklist Questions:					
re receiving waters adjacent to th	e project free of any significa	nt signs of erosion or s	sediment that would be as	sociated with the	construction
ctivity?					
es					
reate Corrective Action?					
lave disturbed areas been seeded	or otherwise stabilized as rec	quired? List inactive po	ortions of the project and i	if stabilization mea	asure are adequate
r needed to prevent erosion.					
reate Corrective Action?					
o - See Findings Section					
	struction motorial borordous	ete) heine menered	nyonoyly?		
re waste materials (concrete, con	struction material, nazardous	, etc.) being managed	properly?		
reate Corrective Action?					
o - See BMP Section					
re construction entrances and ad	liacent streets being maintain	ed adequately?			
lo					
create Corrective Action?					
lo - See BMP section					
s dust associated with the constru	action activity adequately conf	trolled on the site?			
es					
Reate Corrective Action?					
/A Comments: Comments:					
/A comments: comments: . Site was inactive for home building					ita ita offactivacao
A omments: omments: . Site was inactive for home building . SB 4 is being partially closed to ac	commodate the dirt from the gra	ding of the new area as	of 11/9/17. The inspector w	vill continue to moni	
A comments: comments: . Site was inactive for home building . SB 4 is being partially closed to ac he surrounding area is primarily bui	commodate the dirt from the gra	ding of the new area as	of 11/9/17. The inspector w	vill continue to moni	
A omments: omments: Site was inactive for home building SB 4 is being partially closed to ac he surrounding area is primarily bui s of the 8/13/18 inspection.	commodate the dirt from the gra It out so the remaining basin car	ding of the new area as	of 11/9/17. The inspector w	vill continue to moni	
A omments: omments: . Site was inactive for home building . SB 4 is being partially closed to ac he surrounding area is primarily bui s of the 8/13/18 inspection. indings / Corrective Actions (Date	commodate the dirt from the gra It out so the remaining basin car	ding of the new area as	of 11/9/17. The inspector w	vill continue to moni	
A omments: . Site was inactive for home building . SB 4 is being partially closed to ac he surrounding area is primarily bui s of the 8/13/18 inspection. indings / Corrective Actions (Date indings / Corrective Actions (Date .) Some maintenance is required in	commodate the dirt from the gra It out so the remaining basin car (a): (b): (c):	iding of the new area as accommodate the flow	of 11/9/17. The inspector w coming from the adjacent k	vill continue to moni ots. The basin was	working effectively
/A comments: . Site was inactive for home building . SB 4 is being partially closed to ac he surrounding area is primarily bui s of the 8/13/18 inspection. indings / Corrective Actions (Date indings / Corrective Actions (Date .) Some maintenance is required in .) A majority of Replat 6 has been in	commodate the dirt from the gra It out so the remaining basin car (a): (a): (b): (b): (c):	ding of the new area as accommodate the flow Disturbed areas through	of 11/9/17. The inspector w coming from the adjacent k out the site should be tempo	vill continue to moni ots. The basin was prarily stabilized an	working effectively
A comments: . Site was inactive for home building . SB 4 is being partially closed to ac he surrounding area is primarily bui s of the 8/13/18 inspection. indings / Corrective Actions (Date indings / Corrective Actions (Date .) Some maintenance is required in .) A majority of Replat 6 has been in hould be limited to paved / rocked a	commodate the dirt from the gra It out so the remaining basin car (a): (a): (b): (c):	ding of the new area as accommodate the flow Disturbed areas through	of 11/9/17. The inspector w coming from the adjacent k out the site should be tempo	vill continue to moni ots. The basin was prarily stabilized an	working effectively
A omments: Site was inactive for home building . SB 4 is being partially closed to ac he surrounding area is primarily bui s of the 8/13/18 inspection. indings / Corrective Actions (Date indings / Corrective Actions (Date .) Some maintenance is required in .) A majority of Replat 6 has been in hould be limited to paved / rocked a	commodate the dirt from the gra It out so the remaining basin car (a): (a): (b): (c):	ding of the new area as accommodate the flow Disturbed areas through	of 11/9/17. The inspector w coming from the adjacent k out the site should be tempo	vill continue to moni ots. The basin was prarily stabilized an	working effectively
A omments: Site was inactive for home building SB 4 is being partially closed to ac he surrounding area is primarily buil s of the 8/13/18 inspection. indings / Corrective Actions (Date indings / Correct	commodate the dirt from the gra It out so the remaining basin car (a): (b): (c):	ding of the new area as accommodate the flow Disturbed areas through kins and Steve Minino w	of 11/9/17. The inspector w coming from the adjacent k out the site should be temp ere informed to complete by	vill continue to moni ots. The basin was prarily stabilized an γ 5/31/22. Not done	working effectively d construction traffic as of last inspectio
A omments: Site was inactive for home building . SB 4 is being partially closed to ac he surrounding area is primarily bui s of the 8/13/18 inspection. indings / Corrective Actions (Date indings / Corrective Actions (Date .) Some maintenance is required in .) A majority of Replat 6 has been in hould be limited to paved / rocked a	commodate the dirt from the gra It out so the remaining basin car (a): (a): (b): (c):	ding of the new area as accommodate the flow Disturbed areas through	of 11/9/17. The inspector w coming from the adjacent k out the site should be tempo	vill continue to moni ots. The basin was prarily stabilized an	working effectively
A omments: Site was inactive for home building SB 4 is being partially closed to ac he surrounding area is primarily bui s of the 8/13/18 inspection. indings / Corrective Actions (Date indings / Corrective Actions (Date inding	commodate the dirt from the gra It out so the remaining basin car (a): (b): (c):	ding of the new area as accommodate the flow Disturbed areas through kins and Steve Minino w Location	of 11/9/17. The inspector w coming from the adjacent k out the site should be temp ere informed to complete by	vill continue to moni ots. The basin was prarily stabilized an γ 5/31/22. Not done	working effectively d construction traffic as of last inspectio
A omments: Site was inactive for home building SB 4 is being partially closed to ac ne surrounding area is primarily buil s of the 8/13/18 inspection. Indings / Corrective Actions (Date ndings / Corrective Actions (Date	commodate the dirt from the gra It out so the remaining basin car (a): (b): (c):	Disturbed areas through cins and Steve Minino w Location Intersection of Rosewood and Rainwood Road	of 11/9/17. The inspector w coming from the adjacent k out the site should be tempo ere informed to complete by Projected Install Date 11/21/2017	vill continue to moni ots. The basin was prarily stabilized an y 5/31/22. Not done Status Pending	working effectively d construction traffic e as of last inspectio Maintenance No
A comments: comments: Site was inactive for home building SB 4 is being partially closed to ac the surrounding area is primarily building of the 8/13/18 inspection. Indings / Corrective Actions (Date ndings / Correctiv	commodate the dirt from the gra It out so the remaining basin car (): (): (): (): (): (): (): ():	Disturbed areas through cins and Steve Minino w Location Intersection of Rosewood and Rainwood Road	of 11/9/17. The inspector w coming from the adjacent k out the site should be tempo ere informed to complete by Projected Install Date 11/21/2017	vill continue to moni ots. The basin was prarily stabilized an y 5/31/22. Not done Status Pending	working effectively d construction traffic as of last inspectio Maintenance No
A comments: Site was inactive for home building SB 4 is being partially closed to ac the surrounding area is primarily building of the 8/13/18 inspection. Indings / Corrective Actions (Date ndings / Corrective Actions (commodate the dirt from the gra It out so the remaining basin car (t):	Disturbed areas through Location Intersection of Rosewood and Rainwood Road ecommend an entrance Lot 20	of 11/9/17. The inspector w coming from the adjacent k out the site should be tempo ere informed to complete by Projected Install Date 11/21/2017 if it becomes necessary as	vill continue to moni ots. The basin was prarily stabilized an y 5/31/22. Not done Status Pending of the 11/21/2017 Removed	working effectively d construction traffic e as of last inspectio Maintenance No inspection.
A comments: Site was inactive for home building SB 4 is being partially closed to ac the surrounding area is primarily building s of the 8/13/18 inspection. Indings / Corrective Actions (Date indings / Corrective Actions (Date) Some maintenance is required in) A majority of Replat 6 has been in nould be limited to paved / rocked a luffs Paving and Japp Bros were Unique Name CE 1 Current Condition:	commodate the dirt from the gra It out so the remaining basin car a): a): the BMP section. active for longer than 14 days. If reas where possible. Mark Hopk reminded on 6/24/22 Type Construction Entrance Pending - The inspector will r	Disturbed areas through Location Intersection of Rosewood and Rainwood Road ecommend an entrance Lot 20	of 11/9/17. The inspector w coming from the adjacent k out the site should be tempo ere informed to complete by Projected Install Date 11/21/2017 if it becomes necessary as	vill continue to moni ots. The basin was prarily stabilized an y 5/31/22. Not done Status Pending of the 11/21/2017 Removed	working effectively d construction traffi e as of last inspectio Maintenance No inspection.
A omments: Site was inactive for home building SB 4 is being partially closed to ac the surrounding area is primarily building s of the 8/13/18 inspection. Indings / Corrective Actions (Date indings / Corrective Actions (Date) Some maintenance is required in) A majority of Replat 6 has been in nould be limited to paved / rocked a luffs Paving and Japp Bros were Unique Name CE 1 Current Condition: CW 1 Current Condition: CW 2	commodate the dirt from the gra It out so the remaining basin car (t):	Disturbed areas through cins and Steve Minino w Location Intersection of Rosewood and Rainwood Road ecommend an entrance Lot 20 aned out and removed th Lot 162	of 11/9/17. The inspector w coming from the adjacent k out the site should be tempo ere informed to complete by Projected Install Date 11/21/2017 if it becomes necessary as e concrete washout prior to	vill continue to moni ots. The basin was prarily stabilized an y 5/31/22. Not done Status Pending of the 11/21/2017 Removed o the 9/26/15 inspect Removed	working effectively d construction traffi e as of last inspection Maintenance No inspection.
A omments: Site was inactive for home building SB 4 is being partially closed to ac the surrounding area is primarily building s of the 8/13/18 inspection. indings / Corrective Actions (Date indings / Corrective Actions (Date) Some maintenance is required in) A majority of Replat 6 has been in nould be limited to paved / rocked a luffs Paving and Japp Bros were Unique Name CE 1 Current Condition: CW 1 Current Condition:	commodate the dirt from the gra It out so the remaining basin car (t):	Disturbed areas through cins and Steve Minino w Location Intersection of Rosewood and Rainwood Road ecommend an entrance Lot 20 aned out and removed th Lot 162 aned out and removed th	of 11/9/17. The inspector w coming from the adjacent k out the site should be tempo ere informed to complete by Projected Install Date 11/21/2017 if it becomes necessary as e concrete washout prior to	vill continue to moni ots. The basin was prarily stabilized an y 5/31/22. Not done Status Pending of the 11/21/2017 Removed o the 9/26/15 inspect Removed	working effectively d construction traffi e as of last inspection Maintenance No inspection.
A omments: Site was inactive for home building SB 4 is being partially closed to ac ne surrounding area is primarily builts of the 8/13/18 inspection. Indings / Corrective Actions (Date ndings / Corrective Actions (Date Note and the state of the state of the state Note and the state of the state of the state of the 8/13/18 inspection. CE 1 Current Condition: CW 2 Current Condition:	commodate the dirt from the gra It out so the remaining basin car (t):	Disturbed areas through cins and Steve Minino w Location Intersection of Rosewood and Rainwood Road ecommend an entrance Lot 20 aned out and removed th Lot 162 aned out and removed th Rosewater Prky and	of 11/9/17. The inspector w coming from the adjacent k out the site should be tempo ere informed to complete by Projected Install Date 11/21/2017 if it becomes necessary as e concrete washout prior to	vill continue to moni ots. The basin was prarily stabilized an y 5/31/22. Not done Status Pending of the 11/21/2017 Removed of the 9/26/15 inspect p the 9/26/15 inspect	working effectively d construction traffi e as of last inspection Maintenance No inspection.
A omments: Site was inactive for home building SB 4 is being partially closed to ac he surrounding area is primarily build s of the 8/13/18 inspection. indings / Corrective Actions (Date indings / Corrective Actions (Date CE 1 Current Condition: CW 1 Current Condition: CW 2 Current Condition: IF 1	commodate the dirt from the gra It out so the remaining basin car (t): (c):	Disturbed areas through cins and Steve Minino w Location Intersection of Rosewood and Rainwood Road ecommend an entrance Lot 20 Ined out and removed th Lot 162 Ined out and removed th Rosewater Prky and Chicory St.	of 11/9/17. The inspector w coming from the adjacent le out the site should be tempo ere informed to complete by Projected Install Date 11/21/2017 if it becomes necessary as le concrete washout prior to le concrete washout prior to	vill continue to moni ots. The basin was prarily stabilized an y 5/31/22. Not done Status Pending of the 11/21/2017 Removed o the 9/26/15 inspect Removed	working effectively d construction traffi e as of last inspectio Maintenance No inspection.
A omments: Site was inactive for home building SB 4 is being partially closed to ac he surrounding area is primarily buils of the 8/13/18 inspection. indings / Corrective Actions (Date indings / Corrective Actions (Date) Some maintenance is required in) A majority of Replat 6 has been in nould be limited to paved / rocked a luffs Paving and Japp Bros were Unique Name CE 1 Current Condition: CW 1 Current Condition: CW 2 Current Condition: IF 1	commodate the dirt from the gra It out so the remaining basin car (t) the BMP section. (active for longer than 14 days. If reas where possible. Mark Hoph reminded on 6/24/22	Disturbed areas through Commodate the flow Disturbed areas through kins and Steve Minino w Location Intersection of Rosewood and Rainwood Road ecommend an entrance Lot 20 aned out and removed th Lot 162 aned out and removed th Chicory St. moved the inlet filter dur	of 11/9/17. The inspector w coming from the adjacent le out the site should be tempo ere informed to complete by Projected Install Date 11/21/2017 if it becomes necessary as le concrete washout prior to le concrete washout prior to	vill continue to moni ots. The basin was prarily stabilized an y 5/31/22. Not done Status Pending of the 11/21/2017 Removed the 9/26/15 inspect Removed the 9/26/15 inspect	working effectively d construction traffic as of last inspectio Maintenance No inspection.
A omments: omments: Site was inactive for home building SB 4 is being partially closed to ac he surrounding area is primarily bui s of the 8/13/18 inspection. indings / Corrective Actions (Date indings / Corrective Actions (Date indings / Corrective Actions (Date .) Some maintenance is required in .) A majority of Replat 6 has been in hould be limited to paved / rocked a luffs Paving and Japp Bros were Unique Name CE 1 Current Condition: CW 1 Current Condition: IF 1 Current Condition: IF 1 Current Condition: Lot 17	commodate the dirt from the gra It out so the remaining basin car (tout	Disturbed areas through Control of the new area as accommodate the flow Disturbed areas through cins and Steve Minino w Location Intersection of Rosewood and Rainwood Road ecommend an entrance Lot 20 aned out and removed th Lot 162 aned out and removed th Rosewater Prky and Chicory St. moved the inlet filter dur Lot 17	of 11/9/17. The inspector w coming from the adjacent le out the site should be temperer ere informed to complete by Projected Install Date 11/21/2017 if it becomes necessary as e concrete washout prior to ne concrete washout prior to ne concrete washout prior to	vill continue to moni ots. The basin was prarily stabilized an y 5/31/22. Not done Status Pending of the 11/21/2017 Removed of the 9/26/15 inspect p the 9/26/15 inspect	working effectively d construction traffic as of last inspectio Maintenance No inspection.
A comments: comments: comments: Site was inactive for home building SB 4 is being partially closed to ac he surrounding area is primarily bui s of the 8/13/18 inspection. indings / Corrective Actions (Date indings / Corrective Actions (Date indings / Corrective Actions (Date .) Some maintenance is required in .) A majority of Replat 6 has been in hould be limited to paved / rocked a luffs Paving and Japp Bros were Unique Name CE 1 Current Condition: CW 1 Current Condition: CW 2 Current Condition: IF 1 Current Condition:	commodate the dirt from the gra It out so the remaining basin car (t) the BMP section. (active for longer than 14 days. If reas where possible. Mark Hoph reminded on 6/24/22	Disturbed areas through Control of the new area as accommodate the flow Disturbed areas through cins and Steve Minino w Location Intersection of Rosewood and Rainwood Road ecommend an entrance Lot 20 aned out and removed th Lot 162 aned out and removed th Rosewater Prky and Chicory St. moved the inlet filter dur Lot 17	of 11/9/17. The inspector w coming from the adjacent le out the site should be temperer ere informed to complete by Projected Install Date 11/21/2017 if it becomes necessary as e concrete washout prior to ne concrete washout prior to ne concrete washout prior to	vill continue to moni ots. The basin was prarily stabilized an y 5/31/22. Not done Status Pending of the 11/21/2017 Removed the 9/26/15 inspect Removed the 9/26/15 inspect	working effectively d construction traffic as of last inspectio Maintenance No inspection.

	Removed - Story Homes soc	dded the lot prior to the in	nspection on 6/26/21.		
Lot 22	Individual Lot	Lot 22		Removed	
Current Condition:	Removed - Metro Homes so	dded the lot prior to the 6	6/7/22 inspection.		
Lot 24	Individual Lot	Lot 24		Removed	
Current Condition:	Removed - Story Homes so	dded the lot prior to the 1	1/11/21 inspection.		
Lot 25	Individual Lot	Lot 25		Removed	
Current Condition:	Removed - Metro Homes so		Inspection on 6/11/21.		
			1		1
SF 6	Silt Fence	SB 5		Removed	
Current Condition:	Removed - Commercial See	ding removed the silt fer	nce prior to the 10/9/18 insp	ection.	
SF 7	Silt Fence	SB 3		Removed	
Current Condition:	Removed - SF 7 changed to	lot level item (lots 5 and	6) as of 5/15/18.		
SF 8	Silt Fence	Rainwood Road		Removed	
Current Condition:	Removed - Boyer Young ins	talled a silt fence check i	in front of Rainwood Road	prior to 11/23/2016.	Silt Fence was
	repaired prior to the 8/13/18	inspection. Boyer Young	g removed the silt fence pri	or to the 10/23/18 in	spection.
		The perimeter of the		1	
SF 9	Silt Fence	newly graded area	11/21/2017	Active	No
Current Condition:	Good Condition - The silt fer				
	Seeding installed silt fence a				
	corner was repaired prior to				
	lots prior to the 8/13/18 inspe	•	•		
	inspection. Commercial See				
	retied the silt fence where it				
	the silt fence in multiple loca	v v		•	
	undermined silt fence prior to				
	inspection on 6/21/21. Comr	mercial Seeding fixed all	silt fence on site prior to the	e inspection on 7/26	/21. Commercial
	Seeding fixed all silt fence of	n site prior to the inspect	ion on 9/27/21.		
		South of Wild Indigo St			
SB 3	Sediment Basin	and Prairie Star St.		Removed	
Current Condition:	Removed - The basin was c		inspection.	1	
0.5.4		South of 149th Dead	44/44/0005	A 11	
SB 4	Sediment Basin	End	11/14/2005	Active	No
Current Condition:	Good Condition- 41% Filled southern riser and removed				ustin Roth remov
	southern riser and removed	• •		·.	
		Southwest corner of			
		Rosewater Pkwy and North H.W.S			
SB 5	Sediment Basin	Cleveland Blvd		Removed	
Current Condition:	Removed - The basin was c	-	 Sinspection	Removed	
STR	Street Cleaning	Entire Site	inspection.		
31K			2/26/2007	Activo	No
Ourseast One sellting as			2/26/2007	Active	No 1. Matra Llamaa
Current Condition:	Good Condition - Story Hom	es cleaned the street in t	front of lot 24 prior to the in	spection on 11/11/2	1. Metro Homes
Current Condition:	Good Condition - Story Hom cleaned the street in front of	les cleaned the street in t lot 22 prior to the 3/14/2	front of lot 24 prior to the in: 2 inspection. Minino Home:	spection on 11/11/2 s cleaned 149th Stre	1. Metro Homes
Current Condition:	Good Condition - Story Hom	les cleaned the street in t lot 22 prior to the 3/14/2 lomes cleaned 149th Str	front of lot 24 prior to the in: 2 inspection. Minino Home:	spection on 11/11/2 s cleaned 149th Stre	1. Metro Homes
	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H	les cleaned the street in t lot 22 prior to the 3/14/2 lomes cleaned 149th Str Replat 6	front of lot 24 prior to the in- 2 inspection. Minino Homes eet prior to the 6/7/22 inspe	spection on 11/11/2 s cleaned 149th Streection.	1. Metro Homes eet prior to the
CE 1	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance	les cleaned the street in t lot 22 prior to the 3/14/2 lomes cleaned 149th Str Replat 6 Southwest corner	Front of lot 24 prior to the in: 2 inspection. Minino Homes eet prior to the 6/7/22 inspe 5/27/2021	spection on 11/11/2 s cleaned 149th Streection.	1. Metro Homes eet prior to the No
	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec	less cleaned the street in f lot 22 prior to the 3/14/2 lomes cleaned 149th Stru- Replat 6 Southwest corner tive - Mark Hopkins insta	front of lot 24 prior to the in: 2 inspection. Minino Homes eet prior to the 6/7/22 inspe 5/27/2021 alled the construction entrar	spection on 11/11/2 s cleaned 149th Stre sction. Active	1. Metro Homes set prior to the No ection on 10/13/2
CE 1	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance	less cleaned the street in f lot 22 prior to the 3/14/2 lomes cleaned 149th Stru- Replat 6 Southwest corner tive - Mark Hopkins insta	front of lot 24 prior to the in: 2 inspection. Minino Homes eet prior to the 6/7/22 inspe 5/27/2021 alled the construction entrar	spection on 11/11/2 s cleaned 149th Stre sction. Active	1. Metro Homes set prior to the No ection on 10/13/2
CE 1 Current Condition:	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec Due to imminent paving of	les cleaned the street in f lot 22 prior to the 3/14/2 lomes cleaned 149th Stre Replat 6 Southwest corner tive - Mark Hopkins insta the entrance, addition	front of lot 24 prior to the im 2 inspection. Minino Homes eet prior to the 6/7/22 inspe 5/27/2021 alled the construction entrar al rock is no longer recon	Active Active Active	1. Metro Homes bet prior to the No ection on 10/13/2 6/21/22 inspect
CE 1 Current Condition: CE 2	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec Due to imminent paving of Construction Entrance	les cleaned the street in f lot 22 prior to the 3/14/2 lomes cleaned 149th Stru- Replat 6 Southwest corner tive - Mark Hopkins insta the entrance, additional Northeast corner	front of lot 24 prior to the im 2 inspection. Minino Homes eet prior to the 6/7/22 inspec 5/27/2021 alled the construction entrar al rock is no longer recon 5/27/2021	Active Active Active Active Active Active Active Active Active	1. Metro Homes eet prior to the No ection on 10/13/2 6/21/22 inspecti
CE 1 Current Condition:	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec Due to imminent paving of	les cleaned the street in f lot 22 prior to the 3/14/2 lomes cleaned 149th Stru- Replat 6 Southwest corner tive - Mark Hopkins insta the entrance, additional Northeast corner	front of lot 24 prior to the im 2 inspection. Minino Homes eet prior to the 6/7/22 inspec 5/27/2021 alled the construction entrar al rock is no longer recon 5/27/2021	Active Active Active Active Active Active Active Active Active	1. Metro Homes eet prior to the No ection on 10/13/2 6/21/22 inspect No
CE 1 Current Condition: CE 2 Current Condition:	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec Due to imminent paving of Construction Entrance Good Condition - 95% effec	es cleaned the street in f lot 22 prior to the 3/14/2 lomes cleaned 149th Str Replat 6 Southwest corner tive - Mark Hopkins insta the entrance, addition Northeast corner tive - Mark Hopkins insta	front of lot 24 prior to the im 2 inspection. Minino Homes eet prior to the 6/7/22 inspec 5/27/2021 alled the construction entrar al rock is no longer recon 5/27/2021	Active Active Active Active Active Active Active Active Active	1. Metro Homes eet prior to the No ection on 10/13/2 6/21/22 inspecti
CE 1 Current Condition: CE 2 Current Condition: D 1	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec Due to imminent paving of Construction Entrance Good Condition - 95% effec Diversion Ditch	es cleaned the street in f lot 22 prior to the 3/14/2 lomes cleaned 149th Stru- Replat 6 Southwest corner tive - Mark Hopkins insta the entrance, addition Northeast corner tive - Mark Hopkins insta South of SB 4	front of lot 24 prior to the im 2 inspection. Minino Homes eet prior to the 6/7/22 inspection 5/27/2021 alled the construction entrar al rock is no longer recon 5/27/2021 alled a construction entrance	Active Removed	1. Metro Homes eet prior to the No ection on 10/13/2 6/21/22 inspecti
CE 1 Current Condition: CE 2 Current Condition: D 1 Current Condition:	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec Due to imminent paving of Construction Entrance Good Condition - 95% effec Diversion Ditch Removed - Mark Hopkins re	es cleaned the street in f lot 22 prior to the 3/14/2 lomes cleaned 149th Stru- Replat 6 Southwest corner tive - Mark Hopkins insta the entrance, addition Northeast corner tive - Mark Hopkins insta South of SB 4 moved the diversion dur	front of lot 24 prior to the im 2 inspection. Minino Homes eet prior to the 6/7/22 inspection 5/27/2021 alled the construction entrar al rock is no longer recon 5/27/2021 alled a construction entrance ing paving prior to the 5/17.	Active Removed Z2 inspection.	1. Metro Homes eet prior to the No ection on 10/13/2 6/21/22 inspecti No tion on 5/24/22.
CE 1 Current Condition: CE 2 Current Condition: D 1	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec Due to imminent paving of Construction Entrance Good Condition - 95% effec Diversion Ditch	es cleaned the street in f lot 22 prior to the 3/14/2 lomes cleaned 149th Str Replat 6 Southwest corner tive - Mark Hopkins insta the entrance, addition Northeast corner tive - Mark Hopkins insta South of SB 4 moved the diversion dur See Rainwood Rd	front of lot 24 prior to the im 2 inspection. Minino Homes eet prior to the 6/7/22 inspection 5/27/2021 alled the construction entrar al rock is no longer recon 5/27/2021 alled a construction entrance	Active Removed	1. Metro Homes eet prior to the No ection on 10/13/2 6/21/22 inspecti
CE 1 Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec Due to imminent paving of Construction Entrance Good Condition - 95% effec Diversion Ditch Removed - Mark Hopkins re Erosion Control Matting	es cleaned the street in f lot 22 prior to the 3/14/2 lomes cleaned 149th Str Replat 6 Southwest corner tive - Mark Hopkins insta the entrance, addition Northeast corner tive - Mark Hopkins insta South of SB 4 moved the diversion dur See Rainwood Rd SWPPP Map	front of lot 24 prior to the im 2 inspection. Minino Homes eet prior to the 6/7/22 inspection 5/27/2021 alled the construction entrar al rock is no longer recon 5/27/2021 alled a construction entrance billed a constru	Active Active Active Active Active Active Active Active Active Removed Active Removed Active Removed Active Removed	1. Metro Homes set prior to the action on 10/13/2 6/21/22 inspect No tion on 5/24/22.
CE 1 Current Condition: CE 2 Current Condition: D 1 Current Condition:	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec Due to imminent paving of Construction Entrance Good Condition - 95% effec Diversion Ditch Removed - Mark Hopkins re Erosion Control Matting Pending - Erosion matting	es cleaned the street in f lot 22 prior to the 3/14/2 lomes cleaned 149th Str Replat 6 Southwest corner tive - Mark Hopkins insta the entrance, addition Northeast corner tive - Mark Hopkins insta South of SB 4 moved the diversion dur See Rainwood Rd SWPPP Map	front of lot 24 prior to the im 2 inspection. Minino Homes eet prior to the 6/7/22 inspection 5/27/2021 alled the construction entrar al rock is no longer recon 5/27/2021 alled a construction entrance billed a constru	Active Active Active Active Active Active Active Active Active Removed Active Removed Active Removed Active Removed	1. Metro Homes set prior to the action on 10/13/2 6/21/22 inspect No tion on 5/24/22.
CE 1 Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2 Current Condition:	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec Due to imminent paving of Construction Entrance Good Condition - 95% effec Diversion Ditch Removed - Mark Hopkins re Erosion Control Matting Pending - Erosion matting after paving is complete.	es cleaned the street in 1 lot 22 prior to the 3/14/2 lomes cleaned 149th Stru- Southwest corner tive - Mark Hopkins insta the entrance, addition Northeast corner tive - Mark Hopkins insta South of SB 4 moved the diversion dur See Rainwood Rd SWPPP Map will be installed on eith	front of lot 24 prior to the im 2 inspection. Minino Homes eet prior to the 6/7/22 inspection 5/27/2021 alled the construction entrar al rock is no longer recon 5/27/2021 alled a construction entrance big paving prior to the 5/17, 9/6/2022	Active Active Active Active Active Active Active Active Active Removed Active A	1. Metro Homes set prior to the action on 10/13/2 6/21/22 inspect No tion on 5/24/22.
CE 1 Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2 Current Condition: FT 1	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec Due to imminent paving of Construction Entrance Good Condition - 95% effec Diversion Ditch Removed - Mark Hopkins re Erosion Control Matting Pending - Erosion matting after paving is complete. Fuel Tank	es cleaned the street in 1 lot 22 prior to the 3/14/2 lomes cleaned 149th Stru- Southwest corner tive - Mark Hopkins insta the entrance, addition Northeast corner tive - Mark Hopkins insta South of SB 4 moved the diversion dur See Rainwood Rd SWPPP Map will be installed on eith On site	front of lot 24 prior to the im 2 inspection. Minino Homes eet prior to the 6/7/22 inspection. 5/27/2021 alled the construction entrar al rock is no longer recon 5/27/2021 alled a construction entrance 5/27/2021 alled a construction entrance 9/6/2022 her side of Rainwood Roa	Active Prior to the inspect Active Removed Active Active Removed Active Removed Active Removed Removed	1. Metro Homes eet prior to the ection on 10/13/2 6/21/22 inspect No tion on 5/24/22.
CE 1 Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2 Current Condition:	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec Due to imminent paving of Construction Entrance Good Condition - 95% effec Diversion Ditch Removed - Mark Hopkins re Erosion Control Matting Pending - Erosion matting after paving is complete. Fuel Tank Removed - JBG installed th	es cleaned the street in 1 lot 22 prior to the 3/14/2 lomes cleaned 149th Stru- Southwest corner tive - Mark Hopkins insta the entrance, addition Northeast corner tive - Mark Hopkins insta South of SB 4 moved the diversion dur See Rainwood Rd SWPPP Map will be installed on eith On site e fuel tank on site prior to	front of lot 24 prior to the im 2 inspection. Minino Homes eet prior to the 6/7/22 inspection. 5/27/2021 alled the construction entrar al rock is no longer recon 5/27/2021 alled a construction entrance 5/27/2021 alled a construction entrance 9/6/2022 her side of Rainwood Roa	Active Prior to the inspect Active Removed Active Active Removed Active Removed Active Removed Removed	1. Metro Homes eet prior to the ection on 10/13/2 6/21/22 inspect No tion on 5/24/22.
CE 1 Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2 Current Condition: FT 1	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec Due to imminent paving of Construction Entrance Good Condition - 95% effec Diversion Ditch Removed - Mark Hopkins re Erosion Control Matting Pending - Erosion matting after paving is complete. Fuel Tank	es cleaned the street in 1 lot 22 prior to the 3/14/2 lomes cleaned 149th Stru- Southwest corner tive - Mark Hopkins insta the entrance, addition Northeast corner tive - Mark Hopkins insta South of SB 4 moved the diversion dur See Rainwood Rd SWPPP Map will be installed on eith On site e fuel tank on site prior to	front of lot 24 prior to the im 2 inspection. Minino Homes eet prior to the 6/7/22 inspection. 5/27/2021 alled the construction entrar al rock is no longer recon 5/27/2021 alled a construction entrance 5/27/2021 alled a construction entrance 9/6/2022 her side of Rainwood Roa	Active Prior to the inspect Active Removed Active Active Removed Active Removed Active Removed Removed	1. Metro Homes eet prior to the ection on 10/13/2 6/21/22 inspect No tion on 5/24/22.
CE 1 Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2 Current Condition: FT 1	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec Due to imminent paving of Construction Entrance Good Condition - 95% effec Diversion Ditch Removed - Mark Hopkins re Erosion Control Matting Pending - Erosion matting after paving is complete. Fuel Tank Removed - JBG installed th	e fuel tank on site prior to See Rainwood Rd South of SB 4 moved the diversion dur See Rainwood Rd Support to See Rainwood Rd Support to See Rainwood Rd Support to Con site e fuel tank on site prior to 12/6/21. See Rainwood Rd	front of lot 24 prior to the im 2 inspection. Minino Homes eet prior to the 6/7/22 inspection. 5/27/2021 alled the construction entrar al rock is no longer recon 5/27/2021 alled a construction entrance 5/27/2021 alled a construction entrance 9/6/2022 her side of Rainwood Roa	Active Prior to the inspect Active Removed Active Active Removed Active Removed Active Removed Removed	1. Metro Homes eet prior to the ection on 10/13/2 6/21/22 inspect No tion on 5/24/22.
CE 1 Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2 Current Condition: FT 1 Current Condition: IP 1 - 2	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec Due to imminent paving of Construction Entrance Good Condition - 95% effec Diversion Ditch Removed - Mark Hopkins re Erosion Control Matting Pending - Erosion matting after paving is complete. Fuel Tank Removed - JBG installed th site prior to the inspection or Inlet Protection	e fuel tank on site prior to	Tront of lot 24 prior to the im 2 inspection. Minino Homes eet prior to the 6/7/22 inspection 5/27/2021 alled the construction entrare al rock is no longer recon 5/27/2021 alled a construction entrance ing paving prior to the 5/17, 9/6/2022 her side of Rainwood Roa b the inspection on 11/22/2 8/9/2022	Active Removed Active Removed Active Removed Active Active Removed Active Active Active Removed Active Acti	1. Metro Homes eet prior to the No ection on 10/13/2 6/21/22 inspecti No tion on 5/24/22. No window opens fuel tank from th No
CE 1 Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2 Current Condition: FT 1 Current Condition: IP 1 - 2 Current Condition:	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec Due to imminent paving of Construction Entrance Good Condition - 95% effec Diversion Ditch Removed - Mark Hopkins re Erosion Control Matting Pending - Erosion matting after paving is complete. Fuel Tank Removed - JBG installed th site prior to the inspection or Inlet Protection	e fuel tank on site prior to	Tront of lot 24 prior to the im 2 inspection. Minino Homes eet prior to the 6/7/22 inspection 5/27/2021 alled the construction entrare al rock is no longer recon 5/27/2021 alled a construction entrance ing paving prior to the 5/17, 9/6/2022 her side of Rainwood Roa b the inspection on 11/22/2 8/9/2022	Active Removed Active Removed Active Removed Active Active Removed Active Active Active Removed Active Acti	1. Metro Homes eet prior to the No ection on 10/13/2 6/21/22 inspecti No tion on 5/24/22. No window opens fuel tank from th No
CE 1 Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2 Current Condition: FT 1 Current Condition: IP 1 - 2	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec Due to imminent paving of Construction Entrance Good Condition - 95% effec Diversion Ditch Removed - Mark Hopkins re Erosion Control Matting Pending - Erosion matting after paving is complete. Fuel Tank Removed - JBG installed th site prior to the inspection or Inlet Protection	e fuel tank on site prior to	Tront of lot 24 prior to the im 2 inspection. Minino Homes eet prior to the 6/7/22 inspection 5/27/2021 alled the construction entrare al rock is no longer recon 5/27/2021 alled a construction entrance ing paving prior to the 5/17, 9/6/2022 her side of Rainwood Roa b the inspection on 11/22/2 8/9/2022	Active Removed Active Removed Active Removed Active Active Removed Active Active Active Removed Active Acti	1. Metro Homes eet prior to the No ection on 10/13/2 6/21/22 inspecti No tion on 5/24/22. No window opens fuel tank from th No
CE 1 Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2 Current Condition: FT 1 Current Condition: IP 1 - 2 Current Condition:	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec Due to imminent paving of Construction Entrance Good Condition - 95% effec Diversion Ditch Removed - Mark Hopkins re Erosion Control Matting Pending - Erosion matting after paving is complete. Fuel Tank Removed - JBG installed th site prior to the inspection or Inlet Protection	les cleaned the street in f lot 22 prior to the 3/14/2 lomes cleaned 149th Stru- Replat 6 Southwest corner tive - Mark Hopkins insta the entrance, additional Northeast corner tive - Mark Hopkins insta South of SB 4 moved the diversion dur See Rainwood Rd SWPPP Map will be installed on either 12/6/21. See Rainwood Rd SWPPP Map will be installed over the Adjacent to CE 2	Tront of lot 24 prior to the im 2 inspection. Minino Homes eet prior to the 6/7/22 inspection 5/27/2021 alled the construction entrare al rock is no longer recon 5/27/2021 alled a construction entrance ing paving prior to the 5/17, 9/6/2022 per side of Rainwood Roa the inspection on 11/22/2 8/9/2022 e Rainwood Road curb in	Active Removed Active Removed Active Active Pending Active Removed Active Remove	1. Metro Homes eet prior to the No ection on 10/13/2 6/21/22 inspecti No tion on 5/24/22. No window opens fuel tank from th No s are built.
CE 1 Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2 Current Condition: FT 1 Current Condition: IP 1 - 2 Current Condition: IP 1 - 2 Current Condition: IP 1 - 2	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec Due to imminent paving of Construction Entrance Good Condition - 95% effec Diversion Ditch Removed - Mark Hopkins re Erosion Control Matting Pending - Erosion matting after paving is complete. Fuel Tank Removed - JBG installed th site prior to the inspection of Inlet Protection Pending - Inlet protection of Portable Toilet	les cleaned the street in 1 lot 22 prior to the 3/14/2 lomes cleaned 149th Street Southwest corner tive - Mark Hopkins insta the entrance, additional Northeast corner tive - Mark Hopkins insta South of SB 4 moved the diversion dur See Rainwood Rd SWPPP Map will be installed on eith 12/6/21. See Rainwood Rd SWPPP Map will be installed over th Adjacent to CE 2	Tront of lot 24 prior to the im 2 inspection. Minino Homes eet prior to the 6/7/22 inspection. 5/27/2021 alled the construction entrare 5/27/2021 alled a construction entrance 5/27/2021 alled a construction entrance 5/27/2022 alled a construction entrance 5/27/2022 all	Active Removed Active	
CE 1 Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2 Current Condition: FT 1 Current Condition: IP 1 - 2 Current Condition: IP 1 - 2 Current Condition: IP 1 - 2	Good Condition - Story Hom cleaned the street in front of 4/12/22 inspection. Minino H Construction Entrance Good Condition - 75% effec Due to imminent paving of Construction Entrance Good Condition - 95% effec Diversion Ditch Removed - Mark Hopkins re Erosion Control Matting Pending - Erosion matting after paving is complete. Fuel Tank Removed - JBG installed th site prior to the inspection or Inlet Protection Pending - Inlet protection v Portable Toilet Removed - Mark Hopkins in	les cleaned the street in 1 lot 22 prior to the 3/14/2 lomes cleaned 149th Street Southwest corner tive - Mark Hopkins insta the entrance, additional Northeast corner tive - Mark Hopkins insta South of SB 4 moved the diversion dur See Rainwood Rd SWPPP Map will be installed on eith On site e fuel tank on site prior to 12/6/21. See Rainwood Rd SWPPP Map will be installed over the Adjacent to CE 2 stalled and secured a po E 1 prior to the 11/11/21	Tront of lot 24 prior to the im 2 inspection. Minino Homes eet prior to the 6/7/22 inspection. 5/27/2021 alled the construction entrare al rock is no longer recond 5/27/2021 alled a construction entrance 5/27/2021 alled a construction entrance 5/27/2022 alled a construc	Active Removed Active Removed Active Removed I.JBG removed H.JBG removed Removed Removed Removed Removed Active Removed Removed Active Removed Active Removed Remo	

Current Condition:	Fair Condition - Mark Ho	ppkins installed and secured a	a portable toilet prior to the	he 4/12/22 inspection.		
	The portable toilet shou	IId be resecured.				
	Bluffs Paving and Japp Bros were informed to complete by 6/28/22. Not done as of the last inspection.					
RR 1	Riprap	See Rainwood Rd SWPPP Map	8/9/2022	Pending	No	
Current Condition:	Pending - Riprap will be	installed at the east end of	FRainwood Road after	paving is complete.		
SF 1	Silt Fence	East edge of site	5/27/2021	Active	Yes	
	 west along the basin prior to the inspection on 9/27/21. Mark Hopkins repaired the silt fence prior to the inspection 12/6/21. 1.) Silt fence should be reinstalled where removed on the western side of the basin. 2.) Silt fence should be repaired where fallen in multiple locations along the northern perimeter. 3.) Silt fence should be reinstalled around the drainage ditch on the south side of SB 4. 4.) Silt fence should be cleaned out where full south of Outlot B. 1.) Mark Hopkins and Steve Minino were informed to complete by 5/31/22. Not done as of last inspection. Bluffs and Japp Bros were reminded on 6/24/22 3.) Mark Hopkins and Steve Minino were informed to complete by 5/31/22. Not done as of last inspection. Bluffs and Japp Bros were reminded on 6/24/22 3.) Mark Hopkins and Steve Minino were informed to complete by 5/31/22. Not done as of last inspection. Bluffs and Japp Bros were reminded on 6/24/22 					
SF 01 - 05	4.) Bluffs Paving and Ja Silt Fence	pp Bros were informed to c See Rainwood Rd SWPPP Map	complete by 6/28/22. No 6/14/2022	Active	inspection. No	
Current Condition:	Good Condition - Bluffs Paving and Japp Bros installed SF 1, SF 2, and SF 5 around the disturbed area for th Rainwood Road project prior to the 6/14/22 inspection. E&A inspector will monitor for installation of SF 3 and 4.					
SWPPP Sign	Signs	1 sign on site	8/19/2008	Active	No	
Current Condition:	Good Condition: E&A inspector installed the SWPPP sign on 8/19/08 at 156th and Bennington Blvd					
Certification Statement:	direction or supervision in properly gathered and ev persons who manage the the information submitted	f law, that this document and a accordance with a system d aluated the information subm e system or those persons dir l is, to the best of my knowled significant penalties for subm it for knowing violations."	esigned to assure that o itted. Based on my inqui ectly responsible for gat lge and belief, true, accu	ualified personnel iry of the person or hering the information, urate, and complete. I		
AR					Bet S.C.	