E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Complaints:

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

		E&A- P2005.030.000 5 P2005.030.024 (Repla	t 6)			
Inspector: Ethan Anderson		Stage				
Project Name:	The Heritage NER110495					
For Week Ending:	8/12/2023					
Project Location:	East of 156th Street, North and South of Rainwood Road - Bennington, NE (Douglas County)			68007		
_						
	The Heritage	Lot 195/Replat 6				
Grading:	100%	90%				
Sanitary Sewer:	100%	95%				

	The nemaye	Lot 195/Replat 6				
Grading:	100%	90%				
Sanitary Sewer:	100%	95%				
Storm Sewer:	100%	80%				
Paving:	100%	90%				
Seeding:	0%	35%				
Utilities:	2%	80%				
Overall Development:	98%	45%				

RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Duration
					Week
Sunday:	0.00"				
Monday:	0.08"				
Tuesday:	0.00"	7/11/2023	Cloudy 87/67	11:55 AM	
Wednesday:	0.54"	7/12/2023	Sunny 82/62	4:50 PM	6:15 AM - 10:00 AM
Thursday:	0.00"				
Friday:	0.27"				9:30 AM - 4:00 PM
Saturday:	0.00"				
					Week
Sunday:	0.07"				
Monday:	0.16"	7/17/2023	Cloudy 81/61	2:20 PM	
Tuesday:	0.18"	7/18/2023	Sunny 78/60	11:40 AM	
Wednesday:	0.00"				
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.31"				3:55 AM
					Week
Sunday:	0.00"				
Monday:	0.19"	7/24/2023	Sunny 86/70	1:40 PM	
Tuesday:	0.00"	7/25/2023	Sunny 84/73	9:10 AM	
Wednesday:	0.00"				
Thursday:	0.00"				
Friday:	0.03"				
Saturday:	0.00"				
					Week
Sunday:	0.00"				
Monday:	1.16"	7/31/2023	Cloudy 83/67	5:00 PM	4:55 AM - 8:55 AM
Tuesday:	0.01"	8/1/2023	Cloudy 79/69	10:00 AM	
Wednesday:	2.08"	8/2/2023	Cloudy 80/70	3:00 PM	1:55 AM - 9:55 AM
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
					Week
Sunday:	0.08"				
Monday:	0.00"				
Tuesday:	0.02"	8/8/2023	Partly Cloudy 84/65	11:15 AM	
Wednesday:	0.10"				
Thursday:	0.00"				
Friday:	0.07"				
Saturday:	0.00"				

# Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site, grading completed 7/2006 and site seeded 9/5/2006. Grading began on old school site east of Stargrass Road (11/9/2017). Grading activity on site idle (9/9/2020). Storm and sewer installation began in replat 6 (9/27/2021). Street paving in replat 6 (4/12/2022). Street paving in Rainwood Road (8/9/2022).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire site, grading completed 7/2006 and site seeded 9/5/2006. Grading began on old school site east of Stargrass Road (11/9/2017). Grading activity on site idle (9/9/2020). Storm and sewer installation began in replat 6 (9/27/2021). Street paving in replat 6 (4/12/2022). Street paving in Rainwood Road (8/9/2022).

What temporary or permanent stabilization measures listed in this section are being implemented?

Wetlands Mitigation Seeding (5/31/2006), Slopes Seeded/Matted (8/30/2006), Temp. Seeded (9/5/2006), Re-Seeded 5/21/2007, Re-Seeded ROW on 9/5/2007 & 11/14/2007, Erosion seeded in various areas (4/2009), Old Basin 5 was seeded and matted (5/2/2012). The areas that were disturbed when SB 3 and 5 were closed has been seeded (9/10/2016). Area surrounding SB#4 has been seeded (5/22/2018). Stub road at the end of N 149th Street seeded and matted (9/8/2020). Replat 6 was temp seeded (8/9/2021). Rainwood Road ROW and Basin seeded/matted (9/12/2022). Erosion matting was installed along side the riprap under Rainwood road and IP5 (4/17/2023). The entire site was seeded (6/20/23).

#### **Checklist Questions:**

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

# **Create Corrective Action?**

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

#### **Create Corrective Action?**

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

NIo

#### **Create Corrective Action?**

No. Con BMD Continu

Are construction entrances and adjacent streets being maintained adequately?

...

### **Create Corrective Action?**

No, See BMP Section.

Is dust associated with the construction activity adequately controlled on the site?

Yes

### **Create Corrective Action?**

N/A

### Comments:

### Comments:

- 1. Site was inactive for home building during the most recent inspection. Replat 6 was inactive for utility installation during the most recent inspection. The Rainwood Road project was inactive during the most recent inspection.
- 2. SB 4 is being partially closed to accommodate the dirt from the grading of the new area as of 11/9/17. The inspector will continue to monitor its effectiveness. The surrounding area is primarily built out so the remaining basin can accommodate the flow coming from the adjacent lots. The basin was working effectively as of the 8/13/18 inspection.

## Findings / Corrective Actions (Date):

# Findings / Corrective Actions (Date):

- 1.) No maintenance is required in the BMP section.
- 2.) The low-lying area at the southeast end of rainwood road in Outlot G has a large section that is being eroded and undermining the matting. E&A Inspector informed the SID Department and engineers to repair, seed and re-matt the slope by 4/17/2023. E&A inspector will update the report when more information is known. Not done as of last inspection.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance			
		Intersection of Rosewood and						
CE 1	Construction Entrance	Rainwood Road		Removed				
Current Condition:	Removed - A construction e	Removed - A construction entrance is no longer necessary due to paving prior to the inspection on 8/8/23.						
CW 1	Concrete Washout	Lot 20		Removed				
Current Condition:	Removed - Boyer Young clea	aned out and removed the concr	rete washout prior to the 9/2	26/15 inspection.				
CW 2	Concrete Washout	Lot 162		Removed				
Current Condition:	Removed - Boyer Young clea	aned out and removed the concr	ete washout prior to the 9/2	26/15 inspection.				
		Rosewater Prky and Chicory						
IF 1	Inlet Filter	St.		Removed				
Current Condition:	Removed - E&A inspector re	Removed - E&A inspector removed the inlet filter during inspection on 4/15/17.						
Lot 17	Individual Lot	Lot 17		Removed				
Current Condition:	Removed - Metro Homes so	Removed - Metro Homes sodded the lot prior to the inspection on 6/11/21.						
Lot 20	Individual Lot	Lot 20		Removed				
Current Condition:	Removed - Story Homes soc	Removed - Story Homes sodded the lot prior to the inspection on 6/26/21.						
Lot 22	Individual Lot	Lot 22		Removed				
Current Condition:	Removed - Metro Homes so	Removed - Metro Homes sodded the lot prior to the 6/7/22 inspection.						
Lot 24	Individual Lot	Lot 24		Removed				
Current Condition:	Removed - Story Homes soc	ded the lot prior to the 11/11/21	inspection.					

Current Condition:	Removed - Metro Homes sodded the lot prior to the inspection on 6/11/21.					
SF 6	Silt Fence	SB 5		Removed		
Current Condition:	Removed - Commercial See	ding removed the silt fence prior	to the 10/9/18 inspection.	l		
SF 7	Silt Fence	SB 3		Removed		
Current Condition:	Removed - SF 7 changed to	lot level item (lots 5 and 6) as o	f 5/15/18.	ļ.		
SF 8	Silt Fence	Rainwood Road		Removed		
Current Condition:	Removed - Boyer Young inst	alled a silt fence check in front o	of Rainwood Road prior to	11/23/2016. Silt Fe	nce was repaired	
		n. Boyer Young removed the silt			'	
	<del> </del>	The maximum at the manulu	· ·	I		
SF 9	Silt Fence	The perimeter of the newly graded area		Removed		
Current Condition:		s repaired by Commercial Seed	ing prior to the inspection o		rial Seeding installed	
SB 3	silt fence around the existing dirt stock pile prior to the inspection on 3/5/18. The silt fence in the SE corner was repaired prior to inspection on 4/27/18. Silt fence was repaired and sediment was cleaned up from adjacent lots prior to the 8/13/18 inspection. Commercial Seeding repaired and cleaned out the silt fence prior to the 11/6/18 inspection. Commercial Seeding backfilled and repaired the silt fence prior to the 6/24/19 inspection. E&A inspector retied the silt fence where it was damaged during the 8/12/19 inspection. Jerry Banks repaired/cleaned out/trenched in the silt fence in multiple locations prior to the inspection on 6/10/20. Centennial Enterprises trenched in and backfilled the undermined silt fence prior to the inspection on 8/11/20. JBG reinstalled the norther run of silt fence prior to the inspection on 6/21/21. Commercial Seeding fixed all silt fence on site prior to the inspection on 9/27/21. SF 9 is now part of Replat 6 SF 1 and SF 2.  South of Wild Indigo St and Seediment Basin Prairie Star St. Removed					
Current Condition:	Sediment Basin Removed - The basin was cl	osed prior to the 8/24/16 inspect	l tion	Removed		
SB 4	Sediment Basin	South of 149th Dead End	11/14/2005	Active	No	
Current Condition:		- Roth Enterprise cleaned off the				
Garrent Genation.		dirt to restore drainage prior to ir		iopodioni. Budan 14	our romovou	
SB 5	Sediment Basin	Southwest corner of Rosewater Pkwy and North H.W.S Cleveland Blvd		Removed		
Current Condition:	Removed - The basin was cl	osed prior to the 8/24/16 inspect				
STR	Street Cleaning	Entire Site	2/26/2007	Active	No	
Current Condition:	the street in front of Lot 22 pr	es cleaned the street in front of I rior to the 3/14/22 inspection. Mi n Street prior to the 6/7/22 insper Replat 6	nino Homes cleaned 149th			
CE 1	Construction Entrance	Southwest corner		Removed		
Current Condition:		ved the construction entrance p	l rior to the inspection on 8/2			
CE 2	<u> </u>	ved the constitution chitalioc p	nor to the inspection on orz	-2/22.		
Current Condition:		Northeast corner	5/27/2021	Active	No	
Current Condition.	Construction Entrance	Northeast corner	5/27/2021	Active	No 5/24/22	
		Northeast corner ive - Mark Hopkins installed a co				
CW 1						
CW 1 Current Condition:	Good Condition - 85% effecti	ive - Mark Hopkins installed a co	onstruction entrance prior to	o the inspection on	5/24/22.	
	Good Condition - 85% effecti Concrete Washout Pending - A concrete washout should	ve - Mark Hopkins installed a co	onstruction entrance prior to	o the inspection on Pending	5/24/22.	
	Good Condition - 85% effecti Concrete Washout Pending - A concrete washout should	ve - Mark Hopkins installed a co	onstruction entrance prior to	o the inspection on	5/24/22.	
Current Condition:	Good Condition - 85% effecti  Concrete Washout  Pending -  A concrete washout should  Landmark Homes was info  Diversion Ditch  Removed - Mark Hopkins rer	On site  I be installed.  Treed to complete by 8/15/23.  South of SB 4  moved the diversion during pavi	ng prior to the 5/17/22 insp	o the inspection on  Pending  Removed	5/24/22.	
D 1  Current Condition:  EM 1 - 2	Good Condition - 85% effecti  Concrete Washout  Pending -  A concrete washout should  Landmark Homes was info  Diversion Ditch  Removed - Mark Hopkins rer  Erosion Control Matting	On site  On site  I be installed.  Treed to complete by 8/15/23.  South of SB 4  moved the diversion during pavious See Rainwood Rd  SWPPP Map	ng prior to the 5/17/22 insp	Removed ection. Active	5/24/22.  Yes  No	
D 1  Current Condition:  EM 1 - 2  Current Condition:	Good Condition - 85% effection   Concrete Washout   Pending -   A concrete washout should   Landmark Homes was information Diversion Ditch   Removed - Mark Hopkins rerestrosion Control Matting   Good Condition - Bluffs Pavir to the inspection on 9/12/22.	On site  On site  I be installed.  Treed to complete by 8/15/23.  South of SB 4  moved the diversion during pavil  See Rainwood Rd  SWPPP Map  ng seeded and matted the ROW	ng prior to the 5/17/22 insp	Removed ection. Active e basin to the south	5/24/22.  Yes  No	
D 1 Current Condition:  EM 1 - 2 Current Condition:  FT 1	Good Condition - 85% effecti  Concrete Washout  Pending -  A concrete washout should  Landmark Homes was info  Diversion Ditch  Removed - Mark Hopkins rer  Erosion Control Matting  Good Condition - Bluffs Pavir to the inspection on 9/12/22.  Fuel Tank	On site  On site  I be installed.  Treed to complete by 8/15/23.  South of SB 4  moved the diversion during pavirus See Rainwood Rd  SWPPP Map  ng seeded and matted the ROW  On site	ng prior to the 5/17/22 insp 9/12/2022 / of Rainwood Road and th	Removed ection. Active e basin to the south	5/24/22.  Yes  No  No  Rainwood prior	
D 1 Current Condition:  EM 1 - 2 Current Condition:  FT 1 Current Condition:	Good Condition - 85% effecti  Concrete Washout  Pending -  A concrete washout should  Landmark Homes was info Diversion Ditch  Removed - Mark Hopkins rer Erosion Control Matting  Good Condition - Bluffs Pavir to the inspection on 9/12/22.  Fuel Tank  Removed - JBG installed the to the inspection on12/6/21.	On site  I be installed.  I complete by 8/15/23.  South of SB 4  I complete by 8/15/23.  South	ng prior to the 5/17/22 insp 9/12/2022 / of Rainwood Road and th	Removed ection. Active e basin to the south Removed tremoved the fuel tar to the inspection of	No No n of Rainwood prior ank from the site prior on 9/26/22.	
Current Condition:  D 1  Current Condition:  EM 1 - 2  Current Condition:  FT 1  Current Condition:	Good Condition - 85% effecti  Concrete Washout  Pending -  A concrete washout should  Landmark Homes was info  Diversion Ditch  Removed - Mark Hopkins rer  Erosion Control Matting  Good Condition - Bluffs Pavir to the inspection on 9/12/22.  Fuel Tank  Removed - JBG installed the to the inspection on12/6/21. I	On site  I be installed.  I complete by 8/15/23.  South of SB 4  I moved the diversion during paving See Rainwood Rd  SWPPP Map  I on site  I on site  I on site  I fuel tank on site prior to the installed and matted and double-well.  I on site  I see Rainwood Rd  SWPPP Map	ng prior to the 5/17/22 insp 9/12/2022 / of Rainwood Road and th spection on 11/22/21. JBG walled fuel tank on site prio	Removed e basin to the south Removed the fuel tar to the inspection of Pending	No No f Rainwood prior	
D 1 Current Condition:  EM 1 - 2 Current Condition:  FT 1 Current Condition:	Good Condition - 85% effecti  Concrete Washout  Pending -  A concrete washout should  Landmark Homes was info  Diversion Ditch  Removed - Mark Hopkins rer  Erosion Control Matting  Good Condition - Bluffs Pavir to the inspection on 9/12/22.  Fuel Tank  Removed - JBG installed the to the inspection on12/6/21. I	On site  The installed.  The i	ng prior to the 5/17/22 insp 9/12/2022 / of Rainwood Road and th spection on 11/22/21. JBG walled fuel tank on site prio	Removed e basin to the south Removed the fuel tar to the inspection of Pending	No No n of Rainwood prior ank from the site prior on 9/26/22.	
Current Condition:  D 1  Current Condition:  EM 1 - 2  Current Condition:  FT 1  Current Condition:	Good Condition - 85% effecti  Concrete Washout  Pending -  A concrete washout should  Landmark Homes was info  Diversion Ditch  Removed - Mark Hopkins rer  Erosion Control Matting  Good Condition - Bluffs Pavir to the inspection on 9/12/22.  Fuel Tank  Removed - JBG installed the to the inspection on12/6/21. I	On site  I be installed.  I complete by 8/15/23.  South of SB 4  I moved the diversion during paving See Rainwood Rd  SWPPP Map  I on site  I on site  I on site  I fuel tank on site prior to the installed and matted and double-well.  I on site  I see Rainwood Rd  SWPPP Map	ng prior to the 5/17/22 insp 9/12/2022 / of Rainwood Road and th spection on 11/22/21. JBG walled fuel tank on site prio	Removed e basin to the south Removed the fuel tar to the inspection of Pending	No No n of Rainwood prior ank from the site prior on 9/26/22.	
D 1 Current Condition:  EM 1 - 2 Current Condition:  FT 1 Current Condition:  IP 1 - 2 Current Condition:	Good Condition - 85% effection  Concrete Washout  Pending -  A concrete washout should  Landmark Homes was infonction  Diversion Ditch  Removed - Mark Hopkins rerefore Erosion Control Matting  Good Condition - Bluffs Pavinto the inspection on 9/12/22.  Fuel Tank  Removed - JBG installed the to the inspection on 12/6/21. Inlet Protection  Good Condition - Commercial Inlet Protection	On site  I be installed.  I complete by 8/15/23.  South of SB 4  I moved the diversion during paving.  See Rainwood Rd.  SWPPP Map  I complete by 8/15/23.  South of SB 4  I complete by 8/15/23.  South of SB 4  I complete by 8/15/23.  I complete by 8/15/2	ng prior to the 5/17/22 insp 9/12/2022 / of Rainwood Road and th spection on 11/22/21. JBG walled fuel tank on site prio 8/9/2022 lon prior to the inspection of 4/3/2023	Removed ection. Active e basin to the south Removed tremoved the fuel tar to the inspection of Pending Pending Pending Pending	No No n of Rainwood prior ank from the site prior on 9/26/22.	
Current Condition:  D 1  Current Condition:  EM 1 - 2  Current Condition:  FT 1  Current Condition:  IP 1 - 2  Current Condition:  IP 3 - 4	Good Condition - 85% effection  Concrete Washout  Pending -  A concrete washout should  Landmark Homes was infonction  Diversion Ditch  Removed - Mark Hopkins rerefore Erosion Control Matting  Good Condition - Bluffs Pavinto the inspection on 9/12/22.  Fuel Tank  Removed - JBG installed the to the inspection on 12/6/21. Inlet Protection  Good Condition - Commercial Inlet Protection	On site  I be installed.  I complete by 8/15/23.  South of SB 4  I compl	ng prior to the 5/17/22 insp 9/12/2022 / of Rainwood Road and th spection on 11/22/21. JBG walled fuel tank on site prio 8/9/2022 lon prior to the inspection of 4/3/2023	Removed ection. Active e basin to the south Removed tremoved the fuel tar to the inspection of Pending Pending Pending Pending	No No n of Rainwood prior ank from the site prior on 9/26/22.	

Lot 25

Removed

Lot 25

Individual Lot

Current Condition:	Fair Condition - Landmark excavating the lot prior to	Homes installed a silt fence p	rior to the inspection on	7/25/23. Landmar	K Homes was	
	1.) Wattles should be insta					
	2.) Street should be cleaned 3.) Concrete waste should be removed.  1.) Landmark Homes was informed to complete by 8/7/23. Not done as of last inspection.  2.) Landmark Homes was informed to complete by 8/4/23. Not done as of last inspection.					
Lot 12	3.) Landmark Homes was i Individual Lot	nformed to complete by 8/15/2 Lot 12	7/11/2023	Active	No	
Current Condition:		Iders was excavating the lot price				
Lot 25	Individual Lot	Lot 25	7/25/2023	Active	Yes	
Current Condition:	Fair Condition - Landmark excavating the lot prior to  1.) Wattles should be insta 2.) Street should be cleaned	lled at front of lot	rior to the inspection on		k Homes was	
		nformed to complete by 8/15/2				
PT 01	Portable Toilet	Adjacent to CE 2	<u> </u>	Removed		
Current Condition:	Removed - Mark Hopkins in	stalled and secured a portable t		on 9/27/21. Portab		
	·	r to the 11/11/21 inspection. Mai eved the portable toilet prior to th		rtable toilet prior to	the inspection on	
PT X	Portable Toilet	On Site	2/6/2023	Active	No	
Current Condition:	·	nd Steve Minino removed the po ne inspection on 2/06/23. Mark h		•	•	
RR 1	Riprap	See Rainwood Rd SWPPP Map	8/9/2022	Active	No	
Current Condition:	Good Condition - Riprap will	be installed at the east end of F	Rainwood Road after pavin	g is complete.		
RR 2	Riprap	STA 3+19.29	4/17/2023	Active	No	
Current Condition:	Good Condition - Storm Co	ntractor installed riprap at the ou	tfall that is under Rainwoo	d Road prior to insp	pection on 4/17/23.	
RR 3	Riprap	F5	4/17/2023	Active	No	
Current Condition:	Good Condition - Storm Co	ntractor installed riprap at the inl	et outfall prior to inspection	n on 4/17/23.		
SF 1	Silt Fence	East edge of site	5/27/2021	Active	No	
Current Condition:	along the basin prior to the i Hopkins reinstalled the silt for as of the 3/20/23 inspection,	cins installed prior to the inspect inspection on 9/27/21. Mark Hop ence where removed on the wes silt fence reinstallation along the the SF was damaged prior to on 6/13/23.	kins repaired the silt fence tern side of SB 4 prior to tl e drainage ditch is no long	prior to the inspect the inspection on 9/2 per recommended.	ion on 12/6/21. Mai 26/22. Due to pavin An unknown	
SF 2	Silt Fence	Southern Perimeter	5/27/2021	Active	No	
Current Condition:	a part of SF 1. Commercial	kins installed the silt fence prior to Seeding repaired parts of the silt used as an access point for the s	fence prior to the inspecti	on on 6/13/23. Silt	fence is down in an	
SF 01 - 05	Silt Fence	See Rainwood Rd SWPPP Map	6/14/2022	Active	No	
Current Condition:		ing and Japp Bros installed SF 1			or the Rainwood Ro	
STR	Street Cleaning	Entire Site	3/6/2023	Active	No	
Current Condition:	Good Condition - Commerci	al Seeding cleaned the streets p	rior to the inspection on 6/	27/23.	1	
SWPPP Sign	Signs	1 sign on site	8/19/2008	Active	No	
Current Condition:	•	ctor installed the SWPPP sign of	n 8/19/08 at 156th and Be		1	
Certification Statement:	direction or supervision in ac properly gathered and evalu persons who manage the sy the information submitted is,	v, that this document and all atta accordance with a system designated the information submitted. stem or those persons directly r to the best of my knowledge ar nificant penalties for submitting for knowing violations.	ed to assure that qualified Based on my inquiry of the esponsible for gathering th d belief, true, accurate, an	personnel e person or le information, ld complete. I		
nspector Signature:	En Carlon			Reviewed By:	Get Sol	
opostor orginature.		1		I to tion ou by.		