E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com

Zachary A. Jilek, CPESC, CISEC



Environmental Services Dept. Manager E&A- P2017.411.001 Stage Inspector: Patrick Sechser The Villas at Piney Creek OMA-20160711-03678 Project Name: 1 CSW-201600546 11/4/2017 For Week Ending: 68022 Project Location: 202nd Street and Blondo Parkway, Omaha, NE (Douglas County) Grading: 80% Sanitary Sewer: 50% Storm Sewer: 50% 50% Paving: Seeding: 82% Utilities: 50% Overall Development: 20% RAIN FALL AMOUNTS Amount in tenths Date inspected Weather Conditions Sunday: 0.00" Monday 0.00' Tuesday ММ Wednesday 0.00" 11/2/2017 0.00' 55/38 Sunny Thursday Friday 0.00" Saturday 0.00" Complaints: CONSTRUCTION SEQUENCING: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Grading activities began in the Summer/Fall of 2016 by Ruff Grading. Major grading activities have ceased in the Summer of 2017 on site. Minor grading to be completed at a later time in drainage areas A1-A0.2 due to lot level construction (10/2/2017). Drainage basins A0.3, A2, A0.4 and B1 were inactive (10/2/2017). Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? Grading activities began in the Summer/Fall of 2016 by Ruff Grading. Major grading activities have ceased in the Summer of 2017 on site. Minor grading to be completed at a later time in drainage areas A1-A0.2 due to lot level construction (10/2/2017). Drainage basins A0.3, A2, A0.4 and B1 were inactive (10/2/2017). hat temporary or permanent stabilization measures listed in this section are being implemente Existing Vegetation (2016); Both sides of project were seeded and erosion control blanket installed (2017); Right-of Ways were seeded on west side of project (10/2/2017); NW slope was re-matted and seeded due to erosion (10/19/2017). SUMMARY QUESTIONS: Are approved entrances and adjacent streets being maintained adequately? Yes Are i Yes CHECKLIST QUESTIONS: struction material, hazardous, etc.) being managed properly? Are waste materials (concrete, cor

Yes Is dust associated with the construction activity adequately controlled on the site? Yes

		1			1			
Comments:								
Comments:								
East side of the site remains idle.	Home construction is o	continuing on the west	side of the project as of	11/2/2017.				
Findings / Corrective Actions (Date	e):							
Findings / Corrective Actions (Date):								
 Some maintenance is required in Walking trail on the far east end r 		The Developer Steve Ch	ampoux was informed to c	complete maintena	nce by 10/9/2017			
Not done as of the last inspection. D	eveloper Steve Champou	ux was reminded on 10/2	10/2017.		-			
 City Inspection Report #6110 was up of walking trail on 10/20/2017. Set 			ampoux to fix remaining sil	It fence 10, basin it	ems and cleaning			
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance			
CD1-14 Current Condition:	Wattles	Site	9/7/2016 &A will verify other wattles	Active	No Nork prograada			
Current Condition:		not needed based on lo		and necessity as v	vork progresses.			
CE-1	Entrance	Blondo Parkway		Removed				
Current Condition:	Removed- Entrance w	as removed and paved	prior to 10/2/2017 inspection	on.				
CE-2	Entrance	Blondo Parkway-East	9/7/2016	Active	No			
Current Condition:			is installed prior to 10/2/20		-			
CW-1 Current Condition:	Concrete washout	West side of project it was removed prior to 1	0/2/2017	Removed				
Current Condition.	Removed- washout p		0/2/2017.	I	T			
	Concepts weeks at	Fact side of ansist	F/4/0040	Dending	Ne			
CW-2 Current Condition:	Concrete washout Pending- Washout will	East side of project	5/1/2018 ern phase prior to road pav	Pending ing operations.	No			
	i onung it donout in			ng opolationol				
Diversion Ditches 1-24 Current Condition:	Diversion Ditches	Site	9/7/2016	Active	No			
	Good Condition- Diversion Ditches have been installed prior to the inspection on 10/2/2017 by Ruff Grading. E&A will continue to verify ditches once vegetation is mowed back. DD1, part of DD2, DD13-DD24 were noted during the first inspection by E&A. E&A will continue to monitor. Other diversion ditches were removed for lot level construction.							
		202nd Street, 202nd						
Inlet Filters	Inlet Filters	Avenue	10/25/2017	Active	No			
Current Condition:	Good Condition- Inlet filters have been cleaned out prior to 10/25/2017 by Developer Steve Champoux. E&A will continue to monitor inlet filters due to the establishment of vegetation.							
Lot 30	Silt Fence	202nd Street	10/25/2017	Active	No			
Current Condition:			prior to 10/25/2017. Lot is					
		nce installation on the fr		,				
Lot 33	Silt Fence	202nd Avenue	10/9/2017	Pending	Yes			
Current Condition:	Pending- Dirt was rem	oved from the ROW price	or to 10/25/2017 by Legacy	Homes.				
	Silt fence is needed on the front of the lot.							
	Legacy Homes was informed to complete by 10/9/2017. Not done as of the last inspection.							
Lot 43	Silt Fence	Miami Circle	10/9/2017	Pending	Yes			
Current Condition:	Pending- Dirt was re	moved from the ROW p	prior to 11/2/2017 by Lega	acy Homes.				
	Silt fence is needed on the front of the lots.							
	Legacy Homes was informed to complete by 10/9/2017. Not done as of the last inspection.							
Lot 44	Silt Fence	Miami Circle	10/9/2017	Pending	Yes			
Current Condition:	Pending- Dirt was removed from the ROW prior to 11/2/2017 by Legacy Homes.							
	Silt fence is needed on the front of the lots.							
	Legacy Homes was informed to complete by 10/9/2017. Not done as of the last inspection.							
	Legacy nomes was in	ionned to complete by 1	ororzo rr. Not done as of th	ne last inspection.				

Lot 45	Silt Fence	Miami Circle	10/9/2017	Pending	Yes		
Current Condition:	Pending- Dirt was re	moved from the ROW p	prior to 11/2/2017 by Leg	acy Homes.			
	Silt fonce is needed or	the front of the lote					
	Silt fence is needed on the front of the lots.						
	Legacy Homes was informed to complete by 10/9/2017. Not done as of the last inspection.						
	Stream Outlet Rip						
RR-1-2	Rap	Drainage way	9/7/2016	Active	No		
Current Condition:			o 10/2/2017 inspection. E	&A will continue to	monitor. RR 2 is		
		installed from outfall #3					
RW-1-8	Rock Weirs	Site	9/7/2016	Active	No		
Current Condition:			or to 10/2/2017 inspection n 10/2/2017. RW 6-8 will b				
	o have been removed		11 10/2/2017. TWV 0 0 Will C		ie next inspection		
	Erosion Control						
ECB-1-15	Blanket	Site	9/7/2016	Active	No		
Current Condition:			been installed on the site p				
	Champoux.				, ,		
Silt Fence 1-4	Silt Fence	West side of project	9/7/2016	Active	No		
Current Condition:			n the west side & repaired	U			
	-		led to the east of lot 39; S by RR1 was repaired due				
	by the Developer Stev		by ININI was repaired due	to underculling Sr	prior to 10/19/20		
Silt Fence 5-10	Silt Fence	East side of project	9/7/2016	Active	Yes		
Current Condition:			lled by Developer Steve C				
	Silt fence in the farthest SE corner needs repair (SF10).						
	Developer Steve Champeux was informed to complete by 40/44/2017. Not done as of the last increation						
		Developer Steve Champoux was informed to complete by 10/14/2017. Not done as of the last inspection. Developer Steve Champoux was reminded on 10/19/2017.					
Sediment Basin 1							
Sediment Basin I	Sediment Basin	West side-entrance	9/7/2016	Active	No		
Current Condition:			9/7/2016 ex device was installed pri		-		
	Good Condition- 30%		ex device was installed pri		-		
	Good Condition- 30%	full- Basin and Anti-vorte	ex device was installed pri		-		
	Good Condition- 30%	full- Basin and Anti-vorte	ex device was installed pri		-		
Current Condition:	Good Condition- 30% Steve Champoux. SR Sediment Basin Fair Condition- 25% fu	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central II- Basin and Anti-vortex	ex device was installed pri e slopes. 9/7/2016 e device was installed prior	or to 10/2/2017 ins Active	pection by Develo		
Current Condition: Sediment Basin 2	Good Condition- 30% Steve Champoux. SR Sediment Basin Fair Condition- 25% fu	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central	ex device was installed pri e slopes. 9/7/2016 e device was installed prior	or to 10/2/2017 ins Active	pection by Develo		
Current Condition: Sediment Basin 2	Good Condition- 30% Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SR	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central II- Basin and Anti-vortex R 7 & 8 are in place on	ex device was installed pri e slopes. 9/7/2016 device was installed prior the slopes.	or to 10/2/2017 ins Active	pection by Develo		
Current Condition: Sediment Basin 2	Good Condition- 30% Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SR	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central II- Basin and Anti-vortex	ex device was installed pri e slopes. 9/7/2016 device was installed prior the slopes.	or to 10/2/2017 ins Active	pection by Develo		
Current Condition: Sediment Basin 2	Good Condition- 30% Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central III- Basin and Anti-vortex R 7 & 8 are in place on s undermined and repair npoux was informed to o	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed.	Active	Yes		
Current Condition: Sediment Basin 2	Good Condition- 30% Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central III- Basin and Anti-vortex R 7 & 8 are in place on s undermined and repair npoux was informed to o	ex device was installed pri e slopes. 9/7/2016 device was installed prior the slopes. r is needed.	Active	Yes		
Current Condition: Sediment Basin 2 Current Condition:	Good Condition- 30% Steve Champoux. SRI Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central II- Basin and Anti-vortex R 7 & 8 are in place on s undermined and repair npoux was informed to on npoux was reminded on	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed. complete by 10/9/2017.No 10/10/2017, 10/20/2017.	Active	Pection by Develo		
Current Condition: Sediment Basin 2	Good Condition- 30% Steve Champoux. SRI Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central III- Basin and Anti-vortex R 7 & 8 are in place on s undermined and repair npoux was informed to on poux was reminded on East side	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed.	Active to 10/2/2017 insp to 10/2/2017 insp t done as of the las	Pection by Develop Yes ection by Develop st inspection. Yes		
Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3	Good Condition- 30% Steve Champoux. SRI Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central III- Basin and Anti-vortex R 7 & 8 are in place on s undermined and repair npoux was informed to on poux was reminded on East side	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed. 20/10/2017, 10/20/2017.No 9/7/2016	Active to 10/2/2017 insp to 10/2/2017 insp t done as of the las	Pection by Develo Yes ection by Develop st inspection. Yes		
Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3	Good Condition- 30% Steve Champoux. SRI Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin Poor Condition-SRR 1 to 10/2/2017.	full- Basin and Anti-vorte R 4-6 are in place on the Basin and Anti-vortex R 7 & 8 are in place on s undermined and repair npoux was informed to c npoux was reminded on East side 0 & 11 are in place on th	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed. complete by 10/9/2017. No 10/10/2017, 10/20/2017. 9/7/2016 ne slopes, although SRR 1	t done as of the las	Pection by Develop Yes ection by Develop st inspection. Yes has been dug p		
Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3	Good Condition- 30% Steve Champoux. SRI Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin Poor Condition-SRR 1 to 10/2/2017.	full- Basin and Anti-vorte R 4-6 are in place on the Basin and Anti-vortex R 7 & 8 are in place on s undermined and repair npoux was informed to c npoux was reminded on East side 0 & 11 are in place on th	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed. 20/10/2017, 10/20/2017.No 9/7/2016	t done as of the las	Pection by Develop Yes ection by Develop st inspection. Yes has been dug pu		
Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3	Good Condition- 30% Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin Poor Condition-SRR 1 to 10/2/2017. Sediment Basin needs	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central II- Basin and Anti-vortex R 7 & 8 are in place on s undermined and repair npoux was informed to c npoux was reminded on East side 0 & 11 are in place on the sto be installed per plan	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed. complete by 10/9/2017.No 10/10/2017, 10/20/2017. 9/7/2016 ne slopes, although SRR 1 , including riser, anti-vorte	Active Active to 10/2/2017 inspective to 10/2/2017 inspective t done as of the las Active Active Active Active Statistics, outfall an	Pection by Develop Yes ection by Develop st inspection. Yes has been dug pu d rip rap per plan		
Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3	Good Condition- 30% Steve Champoux. SRI Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin Poor Condition-SRR 1 to 10/2/2017. Sediment Basin needs Developer Steve Char	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central III- Basin and Anti-vortex R 7 & 8 are in place on s undermined and repair npoux was informed to on Deast side 0 & 11 are in place on the s to be installed per plan npoux was informed to on	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed. complete by 10/9/2017. No 10/10/2017, 10/20/2017. 9/7/2016 ne slopes, although SRR 1	Active Active to 10/2/2017 inspective to 10/2/2017 inspective t done as of the las Active Active Active Active Statistics, outfall an	Pection by Develop Yes ection by Develop st inspection. Yes has been dug pu d rip rap per plan		
Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3	Good Condition- 30% Steve Champoux. SRI Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin Poor Condition-SRR 1 to 10/2/2017. Sediment Basin needs Developer Steve Char	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central III- Basin and Anti-vortex R 7 & 8 are in place on s undermined and repair npoux was informed to c npoux was reminded on East side 0 & 11 are in place on the s to be installed per plan npoux was informed to c	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed. 20/10/2017, 10/20/2017.No 10/10/2017, 10/20/2017. 9/7/2016 ne slopes, although SRR 1 , including riser, anti-vorte complete by 10/9/2017. No 10/10/2017, 10/20/2017.	Active Active to 10/2/2017 inspective to 10/2/2017 inspective t done as of the las Active Active Active Active Statistics, outfall an	Pection by Develo		
Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3 Current Condition: Sediment Trap 1	Good Condition- 30% Steve Champoux. SRI Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin Poor Condition-SRR 1 to 10/2/2017. Sediment Basin needs Developer Steve Char Developer Steve Char Developer Steve Char Sediment Tap	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central III- Basin and Anti-vortex R 7 & 8 are in place on the sundermined and repair npoux was informed to con East side 0 & 11 are in place on the sto be installed per plan npoux was informed to con poux was reminded on SW corner	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed. 20/10/2017, 10/20/2017. No 10/10/2017, 10/20/2017. 9/7/2016 ne slopes, although SRR 1 including riser, anti-vorte complete by 10/9/2017. No 10/10/2017, 10/20/2017.	Active Active t done as of the las Active Active Active Active Active	Pection by Develop Yes ection by Develop st inspection. Yes has been dug pr d rip rap per plan. st inspection. No		
Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3 Current Condition:	Good Condition- 30% Steve Champoux. SRI Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Developer Steve Char Sediment Basin Poor Condition-SRR 1 to 10/2/2017. Sediment Basin needs Developer Steve Char Developer Steve Char	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central III- Basin and Anti-vortex R 7 & 8 are in place on the s undermined and repair npoux was informed to con- npoux was reminded on East side 0 & 11 are in place on the s to be installed per plan npoux was informed to con- npoux was reminded on SW corner full- Trap was installed per plan	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed. 20/10/2017, 10/20/2017.No 10/10/2017, 10/20/2017. 9/7/2016 ne slopes, although SRR 1 , including riser, anti-vorte complete by 10/9/2017. No 10/10/2017, 10/20/2017.	Active Active t done as of the las Active Active Active Active Active	Pection by Develop Yes ection by Develop st inspection. Yes has been dug pr d rip rap per plan. st inspection. No		
Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3 Current Condition: Sediment Trap 1	Good Condition- 30% Steve Champoux. SRI Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin Poor Condition-SRR 1 to 10/2/2017. Sediment Basin needs Developer Steve Char Developer Steve Char Developer Steve Char Sediment Tap	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central III- Basin and Anti-vortex R 7 & 8 are in place on the s undermined and repair npoux was informed to con- npoux was reminded on East side 0 & 11 are in place on the s to be installed per plan npoux was informed to con- npoux was reminded on SW corner full- Trap was installed per plan	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed. 20/10/2017, 10/20/2017. No 10/10/2017, 10/20/2017. 9/7/2016 ne slopes, although SRR 1 including riser, anti-vorte complete by 10/9/2017. No 10/10/2017, 10/20/2017.	Active Active t done as of the las Active Active Active Active Active	Pection by Develop Yes ection by Develop st inspection. Yes has been dug pr d rip rap per plan. st inspection. No		
Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3 Current Condition: Sediment Trap 1	Good Condition- 30% Steve Champoux. SRI Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin Poor Condition-SRR 1 to 10/2/2017. Sediment Basin needs Developer Steve Char Developer Steve Char Developer Steve Char Developer Steve Char Developer Steve Char Sediment Trap Good Condition-20% f SRR 1 & 2 are in place	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central II- Basin and Anti-vortex R 7 & 8 are in place on the s undermined and repair npoux was informed to con poux was reminded on East side 0 & 11 are in place on the s to be installed per plan npoux was informed to con npoux was informed to con S to be installed per plan npoux was informed to con S to be installed per plan npoux was informed to con poux was informed to con S to be installed per plan npoux was informed to con poux was informed to c	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed. 0/10/2017, 10/20/2017.No 10/10/2017, 10/20/2017. 9/7/2016 ne slopes, although SRR 1 , including riser, anti-vorte complete by 10/9/2017. No 10/10/2017, 10/20/2017. 9/7/2016 prior to 10/2/2017 inspectio 9/7/2016	Active Active t done as of the las Active t done as of the las Active C is missing. Basin Active	Pection by Develop Yes ection by Develop t inspection. Yes has been dug pr d rip rap per plan. st inspection. No eve Champoux. No		
Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3 Current Condition: Sediment Trap 1 Current Condition:	Good Condition- 30% Steve Champoux. SRI Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin Poor Condition-SRR 1 to 10/2/2017. Sediment Basin needs Developer Steve Char Developer Steve Char Developer Steve Char Developer Steve Char Developer Steve Char Sediment Trap Good Condition-20% f SRR 1 & 2 are in place Sediment Trap Good Condition-Sedir	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central III- Basin and Anti-vortex R 7 & 8 are in place on the s undermined and repair npoux was informed to con poux was reminded on East side 0 & 11 are in place on the s to be installed per plan npoux was informed to con npoux was informed to con SW corner UII- Trap was installed per e on the slopes. Site ment Traps 2-5 have been	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed. 20/10/2017, 10/20/2017. No 10/10/2017, 10/20/2017. No 10/10/20/2017. No 10/10/2017. No 10/10/2017. N	Active Active t done as of the las Active t done as of the las Active a device, outfall an ot done as of the la Active Ac	Pection by Develop Yes ection by Develop t inspection. Yes has been dug pr d rip rap per plan. st inspection. No eve Champoux. No e. ST 6-8 have be		
Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3 Current Condition: Sediment Trap 1 Current Condition: Sediment Traps 2-8	Good Condition- 30% Steve Champoux. SRI Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Developer Steve Char Sediment Basin Poor Condition-SRR 1 to 10/2/2017. Sediment Basin needs Developer Steve Char Developer Steve Char Developer Steve Char Developer Steve Char Sediment Trap Good Condition-20% f SRR 1 & 2 are in place Sediment Trap Good Condition-Sedir installed prior by Steve	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central III- Basin and Anti-vortex R 7 & 8 are in place on the s undermined and repair npoux was informed to c npoux was reminded on East side 0 & 11 are in place on the s to be installed per plan npoux was informed to c npoux was informed to c npoux was informed to c SW corner UII- Trap was installed per e on the slopes. Site ment Traps 2-5 have bee	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed. 0/10/2017, 10/20/2017.No 10/10/2017, 10/20/2017. 9/7/2016 ne slopes, although SRR 1 , including riser, anti-vorte complete by 10/9/2017. No 10/10/2017, 10/20/2017. 9/7/2016 prior to 10/2/2017 inspectio 9/7/2016	Active Active t done as of the las Active t done as of the las Active a device, outfall an ot done as of the la Active Ac	Pection by Develop Yes ection by Develop t inspection. Yes has been dug pr d rip rap per plan. st inspection. No eve Champoux. No e. ST 6-8 have be		
Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3 Current Condition: Sediment Trap 1 Current Condition: Sediment Traps 2-8	Good Condition- 30% Steve Champoux. SRI Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin Poor Condition-SRR 1 to 10/2/2017. Sediment Basin needs Developer Steve Char Developer Steve Char Developer Steve Char Developer Steve Char Developer Steve Char Sediment Trap Good Condition-20% f SRR 1 & 2 are in place Sediment Trap Good Condition-Sedir	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central III- Basin and Anti-vortex R 7 & 8 are in place on the s undermined and repair npoux was informed to c npoux was reminded on East side 0 & 11 are in place on the s to be installed per plan npoux was informed to c npoux was informed to c npoux was informed to c SW corner UII- Trap was installed per e on the slopes. Site ment Traps 2-5 have bee	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed. 20/10/2017, 10/20/2017. No 10/10/2017, 10/20/2017. No 10/10/20/2017. No 10/10/2017. No 10/10/2017. N	Active Active t done as of the las Active t done as of the las Active a device, outfall an ot done as of the la Active Ac	Pection by Develop Yes ection by Develop t inspection. Yes has been dug pr d rip rap per plan. st inspection. No eve Champoux. No e. ST 6-8 have be		
Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3 Current Condition: Sediment Trap 1 Current Condition: Sediment Traps 2-8 Current Condition:	Good Condition- 30% Steve Champoux. SRI Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Developer Steve Char Sediment Basin needs Developer Steve Char Developer Steve Char Sediment Trap Good Condition-20% f SRR 1 & 2 are in place Sediment Trap Good Condition-Sedir installed prior by Steve vegetation.	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central III- Basin and Anti-vortex R 7 & 8 are in place on the s undermined and repair npoux was informed to con poux was reminded on East side 0 & 11 are in place on the s to be installed per plan npoux was informed to con npoux was informed to con SW corner ull- Trap was installed per e on the slopes. Site ment Traps 2-5 have bee a Champoux prior to the	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed. 2007/2017, 10/20/2017. No 10/10/2017, 10/20/2017. No 10/10/2017, 10/20/2017. No 9/7/2016 ne slopes, although SRR 1 2007/2017, 10/20/2017. No 10/10/2017, 10/20/2017. No 9/7/2016 prior to 10/2/2017 inspection 9/7/2016 en removed for development inspection on 10/2/2017. I	Active Active t done as of the las Active t done as of the las Active C is missing. Basi Active Acti	Pection by Develop Yes ection by Develop tinspection. Yes has been dug pr d rip rap per plan. st inspection. No eve Champoux. No e. ST 6-8 have be rea due to extensiv		
Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3 Current Condition: Sediment Trap 1 Current Condition: Sediment Traps 2-8 Current Condition:	Good Condition- 30% Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin needs Developer Steve Char Developer Steve	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central II- Basin and Anti-vortex R 7 & 8 are in place on the s undermined and repair npoux was informed to con poux was reminded on East side 0 & 11 are in place on the s to be installed per plan npoux was informed to con poux was reminded on S to be installed per plan npoux was reminded on S W corner UII- Trap was installed per e on the slopes. Site Site Site	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed. complete by 10/9/2017. No 10/10/2017, 10/20/2017. 9/7/2016 ne slopes, although SRR 1 including riser, anti-vorte complete by 10/9/2017. No 10/10/2017, 10/20/2017. No 10/10/2017, 10/20/2017. No 10/10/2017, 10/20/2017. No 10/10/2017, 10/20/2017. No 9/7/2016 en removed for developme inspection on 10/2/2017. I 9/7/2016	Active	Pection by Develo		
Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3 Current Condition: Sediment Trap 1 Current Condition: Sediment Traps 2-8 Current Condition:	Good Condition- 30% Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin needs Developer Steve Char Developer Steve Char Steve Char Deve	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central II- Basin and Anti-vortex R 7 & 8 are in place on the s undermined and repair npoux was informed to con poux was reminded on East side 0 & 11 are in place on the s to be installed per plan npoux was informed to con poux was reminded on S to be installed per plan npoux was reminded on S W corner UII- Trap was installed per e on the slopes. Site Site Site	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed. complete by 10/9/2017. No 10/10/2017, 10/20/2017. 9/7/2016 ne slopes, although SRR including riser, anti-vorte complete by 10/9/2017. No 10/10/2017, 10/20/2017. 9/7/2016 prior to 10/2/2017 inspection 9/7/2016 en removed for development inspection on 10/2/2017. In 9/7/2016 nstalled prior to 10/2/2017.	Active	Pection by Develo		
Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3 Current Condition: Sediment Trap 1 Current Condition: Sediment Traps 2-8 Current Condition:	Good Condition- 30% Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin needs Developer Steve Char Developer Steve Char Steve Char Deve	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central II- Basin and Anti-vortex R 7 & 8 are in place on the s undermined and repair npoux was informed to con poux was reminded on East side 0 & 11 are in place on the s to be installed per plan npoux was informed to con npoux was reminded on SW corner UII- Trap was installed per e on the slopes. Site ment Traps 2-5 have bee e Champoux prior to the Site ap 1,2, 4-8, 10-11 were i	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed. complete by 10/9/2017. No 10/10/2017, 10/20/2017. 9/7/2016 ne slopes, although SRR including riser, anti-vorte complete by 10/9/2017. No 10/10/2017, 10/20/2017. 9/7/2016 prior to 10/2/2017 inspection 9/7/2016 en removed for development inspection on 10/2/2017. In 9/7/2016 nstalled prior to 10/2/2017.	Active	Pection by Develop Yes ection by Develop st inspection. Yes has been dug pr d rip rap per plan. st inspection. No eve Champoux. No e. ST 6-8 have be rea due to extensi No		
Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3 Current Condition: Sediment Trap 1 Current Condition: Sediment Traps 2-8 Current Condition:	Good Condition- 30% Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin needs Developer Steve Char Developer Steve Char Steve Char Deve	full- Basin and Anti-vorte R 4-6 are in place on the East side-Central II- Basin and Anti-vortex R 7 & 8 are in place on the s undermined and repair npoux was informed to con poux was reminded on East side 0 & 11 are in place on the s to be installed per plan npoux was informed to con npoux was reminded on SW corner UII- Trap was installed per e on the slopes. Site ment Traps 2-5 have bee e Champoux prior to the Site ap 1,2, 4-8, 10-11 were i	ex device was installed pri 9/7/2016 device was installed prior the slopes. r is needed. complete by 10/9/2017. No 10/10/2017, 10/20/2017. 9/7/2016 ne slopes, although SRR including riser, anti-vorte complete by 10/9/2017. No 10/10/2017, 10/20/2017. 9/7/2016 prior to 10/2/2017 inspection 9/7/2016 en removed for development inspection on 10/2/2017. In 9/7/2016 nstalled prior to 10/2/2017.	Active	Pection by Develop Yes ection by Develop st inspection. Yes has been dug pr d rip rap per plan. st inspection. No eve Champoux. No e. ST 6-8 have be rea due to extensi No		

Current Condition:	Good Condition- Stree	Good Condition- Streets were scraped up and cleaned by Developer Steve Champoux prior to 10/19/2017.						
SWPPP Sign Current Condition:	Misc/Other Good Condition- 2 SW	Blondo Parkway PPP signs were installe	10/9/2017 d by the entrances prior to	Active 10/19/2017 by E&	No A.			
Inspector Signature:	Porto Sul			Reviewed By:	Hittes Vinn			