E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com

Zachary A. Jilek, CPESC, CISEC



Engineering Answers

Environmental Services Dept. Mana	iger			Engineering Answ	ers
		E&A- P2017.41	1.001		
Inspector: Patrick Sechser					Stage
Project Name:			1		
For Week Ending:					
Project Location:	202nd Stre	las County)	68022		
	•				
Grading:	80%				
Sanitary Sewer:	50%				
Storm Sewer:	50%				
Paving:	50%				
Seeding:	82%				
Utilities:	50%				
Overall Development:	20%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions		
					Week 1
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.02"	11/29/2017	Sunny 52/24		
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
Complaints:					
CONSTRUCTION SEQUENCING:					
Which portion(s) (i.e. drainage basins) of th	e site have had a temporar	y or permanent cessation	on of grading, earthwork, or g	pround disturbance in the	ast 14 days?
Grading activities began in the Summer/Fall of	2016 by Ruff Grading. Major	grading activities have c	eased in the Summer of 2017 o	on site.	
Minor grading to be completed at a later time ir		to lot level construction (10/2/2017).		
Drainage basins A0.3, A2, A0.4 and B1 were ir	nactive (10/2/2017).				
Which portion(s) (i.e. drainage basins) of th	e site do not have grading,	earthwork, or ground d	listurbance scheduled in the	next 14 days?	
Grading activities began in the Summer/Fall of	2016 by Ruff Grading. Maior	arading activities have c	eased in the Summer of 2017 o	on site.	
		33			
Minor grading to be completed at a later time in		to lot level construction (10/2/2017).		
Drainage basins A0.3, A2, A0.4 and B1 were ir	nactive (10/2/2017).				
		1			
		tion one being implement			
What temporary or permanent stabilization Existing Vegetation (2016); Both sides of proje				led on west side of project (1	0/2/2017) [.] NW slope
was re-matted and seeded due to erosion (10/			ion,, ragin or trajo noro cood		0,2,20 m), 111 0,0p0
		1			
		ļ			<u> </u>
SUMMARY QUESTIONS:	to boing maintained ad-	atoly?			
Are approved entrances and adjacent stree Yes	is being maintained adequa	atery f			
Are receiving waters adjacent to the project	t free of any significant sig	ns of erosion or sedime	ent that would be associated	with the construction activ	ritv?
Yes	s and a start of g	, , , , , , , , , , , , , , , , , , ,			· •
CHECKLIST QUESTIONS:					
Are waste materials (concrete, construction	n material, hazardous, etc.)	being managed properl	y?		
Yes					
Is dust associated with the construction ac	tivity adequately controlled	i on the site?			

Comments:							
Comments:							
East side of the site remains idle.	Home construction is o	continuing on the west	side of the project as of	11/29/2017.			
Findings / Corrective Actions (Da Findings / Corrective Actions (Date)	:						
1.) Some maintenance is required in					40/0/0047		
Walking trail on the far east end Not done as of the last inspection. E							
although minor silt residue remai				ing trait was part	lially scraped up,		
3.) City Inspection Report #6110 wa				t fence 10, basin it	ems and cleaning		
up of walking trail on 10/20/2017. S							
Terri Krasne for compliance (See Bl	,		,	•			
sediment basin #3 maintenance, ris silt runoff and issues on the eastern			•				
complete remaining silt fence on the				ercial decuring will	be filled to		
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
CD1-14	Wattles	Site	9/7/2016	Active	No		
Current Condition:		not needed based on lo	&A will verify other wattles t level construction.	and necessity as v	vork progresses.		
CE-1	Entrance	Blondo Parkway		Removed			
Current Condition:			prior to 10/2/2017 inspection				
CE-2	Entrance	Blondo Parkway-East	9/7/2016	Active	No		
Current Condition:	Good Condition-70% f	unctioning- Entrance wa	is installed prior to 10/2/20	17 inspection by R	uff Grading.		
CW-1	Concrete washout	West side of project		Removed			
Current Condition:	Removed- Washout pi	it was removed prior to 1	10/2/2017.				
CW-2	Concrete washout	East side of project	5/1/2018	Pending	No		
Current Condition:			ern phase prior to road pav		110		
			···· • • • • • • • • • • • • • • • • •				
Diversion Ditches 1-24	Diversion Ditches	Site	9/7/2016	Active	No		
Current Condition:			installed prior to the inspec		, ,		
			ation is mowed back. DD1, ntinue to monitor. Other div				
	level construction.	ion by Ear. Ear will co		ersion diteries wer			
					1		
		202nd Street, 202nd					
Inlet Filters	Inlet Filters	Avenue	10/25/2017	Active	No		
Current Condition:			d out prior to 10/25/2017 by stablishment of vegetation		Champoux. E&A		
	will continue to monito						
Lot 30	Silt Fence	202nd Street	10/25/2017	Active	No		
Current Condition:		· · ·	x prior to 10/25/2017. Lot i	s presently flat. Ea	&A will continue to		
	monitor need for silt fe	nce installation on the fr	ont.				
		1	ſ				
Lat 22		202nd Avenue	10/0/2017	Pendina	Vac		
Lot 33 Current Condition:	Silt Fence	202nd Avenue	10/9/2017 or to 10/25/2017 by Legacy	5	Yes		
Sarrent Gondition.	Fonding Dirt was fem		or to to zorzotti by Legacy	Homeo.			
	Silt fence is needed on the front of the lot.						
	Legacy Homes was int was reminded on 11/9	formed to complete by 10/9/2017. Not done as of the last inspection. Steve Champoux					
Lot 43	Silt Fence	Miami Circle	10/9/2017	Pending	Yes		
Current Condition:	Pending- Dirt was rem	oved from the ROW price	or to 11/2/2017 by Legacy I	Homes.			
	Silt fence is needed on the front of the lots.						
	Legacy Homes was informed to complete by 10/9/2017. Not done as of the last inspection. Steve Champoux						
	was reminded on 11/9	was reminded on 11/9/2017, 11/21/2017.					

Lot 44 Current Condition:	Silt Fence	Miami Circle	10/9/2017	Pending	Yes			
ourient oonanton.	Pending- Dirt was removed from the ROW prior to 11/2/2017 by Legacy Homes.							
	Silt fence is needed or	Silt fence is needed on the front of the lots.						
	Legacy Homes was in was reminded on 11/9		0/9/2017. Not done as of	the last inspection.	Steve Champoux			
Lot 45	Silt Fence	Miami Circle	10/9/2017	Pending	Yes			
Current Condition:	Pending- Dirt was rem	oved from the ROW price	or to 11/2/2017 by Legacy	Homes.				
	Silt fence is needed on the front of the lots.							
	Legacy Homes was in was reminded on 11/9		0/9/2017. Not done as of t	the last inspection.	Steve Champoux			
	Stream Outlet Rip	Designed	0/7/0010	A stiller	Ne			
RR-1-2 Current Condition:	Rap Good Condition- Rip ra	Drainage way ap 1 was installed prior t	9/7/2016 to 10/2/2017 inspection. E	Active	No monitor. RR 2 is			
		installed from outfall #3						
RW-1-8	Rock Weirs	Site	9/7/2016	Active	No			
Current Condition:			ior to 10/2/2017 inspectior n 10/2/2017. RW 6-8 will t					
					·			
	Erosion Control	011	0/7/00/0					
ECB-1-15 Current Condition:	Blanket	Site	9/7/2016 been installed on the site	Active	No No Developer Steve			
Current Condition.	Champoux.	on control blanket has			y Developer Steve			
Silt Fence 1-4	Silt Fence	West side of project		Active	No			
Current Condition:			on the west side & repaired					
			lled to the east of lot 39; S					
	by the Developer Stev		by RR1 was repaired due	to undercutting SF	prior to 10/19/2017			
Silt Fence 5-10	Silt Fence	East side of project	0/7/0040	A				
	SILFENCE							
Current Condition:	Good Condition- Silt F		9/7/2016 talled by Developer Steve	Active Champoux prior to	No 10/19/2017. SF 10			
			talled by Developer Steve					
Current Condition: Sediment Basin 1	was repaired by Com Sediment Basin	ence by CE-2 was reins mercial Seeding prior West side-entrance	talled by Developer Steve to 11/29/2017. 9/7/2016	Champoux prior to Active	10/19/2017. SF 10 No			
Current Condition:	was repaired by Com Sediment Basin Good Condition- 30%	ence by CE-2 was reins mercial Seeding prior West side-entrance	talled by Developer Steve to 11/29/2017. 9/7/2016 ex device was installed pri	Champoux prior to Active	10/19/2017. SF 10 No			
Current Condition: Sediment Basin 1 Current Condition: Sediment Basin 2	was repaired by Com Sediment Basin Good Condition- 30% Steve Champoux. SRI Sediment Basin	ence by CE-2 was reins mercial Seeding prior West side-entrance full- Basin and Anti-vort R 4-6 are in place on the East side-Central	talled by Developer Steve to 11/29/2017. 9/7/2016 ex device was installed pri e slopes. 9/7/2016	Champoux prior to Active or to 10/2/2017 insp Active	10/19/2017. SF 10 No bection by Developer Yes			
Current Condition: Sediment Basin 1 Current Condition:	was repaired by Com Sediment Basin Good Condition- 30% Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu	ence by CE-2 was reins imercial Seeding prior West side-entrance full- Basin and Anti-vorto R 4-6 are in place on the East side-Central II- Basin and Anti-vortex	talled by Developer Steve to 11/29/2017. 9/7/2016 ex device was installed prior 9/7/2016 device was installed prior	Champoux prior to Active or to 10/2/2017 insp Active	10/19/2017. SF 10 No bection by Developer Yes			
Current Condition: Sediment Basin 1 Current Condition: Sediment Basin 2	was repaired by Com Sediment Basin Good Condition- 30% Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SR	ence by CE-2 was reins imercial Seeding prior West side-entrance full- Basin and Anti-vort R 4-6 are in place on the East side-Central Basin and Anti-vortex R 7 & 8 are in place on	talled by Developer Steve to 11/29/2017. 9/7/2016 ex device was installed prior slopes. 9/7/2016 device was installed prior the slopes.	Champoux prior to Active or to 10/2/2017 insp Active	10/19/2017. SF 10 No bection by Developer Yes			
Current Condition: Sediment Basin 1 Current Condition: Sediment Basin 2	was repaired by Com Sediment Basin Good Condition- 30% Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SR	ence by CE-2 was reins imercial Seeding prior West side-entrance full- Basin and Anti-vorto R 4-6 are in place on the East side-Central II- Basin and Anti-vortex	talled by Developer Steve to 11/29/2017. 9/7/2016 ex device was installed prior slopes. 9/7/2016 device was installed prior the slopes.	Champoux prior to Active or to 10/2/2017 insp Active	10/19/2017. SF 10 No bection by Developer Yes			
Current Condition: Sediment Basin 1 Current Condition: Sediment Basin 2	was repaired by Com Sediment Basin Good Condition- 30% Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char	ence by CE-2 was reins imercial Seeding prior West side-entrance full- Basin and Anti-vort R 4-6 are in place on the East side-Central II- Basin and Anti-vortex R 7 & 8 are in place on s undermined and repain npoux was informed to d	talled by Developer Steve to 11/29/2017. 9/7/2016 ex device was installed prior slopes. 9/7/2016 device was installed prior the slopes.	Champoux prior to Active or to 10/2/2017 insp Active to 10/2/2017 inspe t done as of the last	10/19/2017. SF 10 No Section by Developer Yes ction by Developer			
Current Condition: Sediment Basin 1 Current Condition: Sediment Basin 2	was repaired by Com Sediment Basin Good Condition- 30% Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char	ence by CE-2 was reins imercial Seeding prior West side-entrance full- Basin and Anti-vort R 4-6 are in place on the East side-Central II- Basin and Anti-vortex R 7 & 8 are in place on s undermined and repain npoux was informed to d	talled by Developer Steve to 11/29/2017. 9/7/2016 ex device was installed prior slopes. 9/7/2016 c device was installed prior the slopes. r is needed. complete by 10/9/2017.No	Champoux prior to Active or to 10/2/2017 insp Active to 10/2/2017 inspe t done as of the last	10/19/2017. SF 10 No Section by Developer Yes ction by Developer			
Current Condition: Sediment Basin 1 Current Condition: Sediment Basin 2 Current Condition:	was repaired by Com Sediment Basin Good Condition- 30% Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin	ence by CE-2 was reins imercial Seeding prior West side-entrance full- Basin and Anti-vorte R 4-6 are in place on the East side-Central II- Basin and Anti-vortes R 7 & 8 are in place on s undermined and repain npoux was informed to on poux was reminded on East side	talled by Developer Steve to 11/29/2017. 9/7/2016 ex device was installed prio slopes. 9/7/2016 device was installed prior the slopes. r is needed. complete by 10/9/2017.No 10/10/2017, 10/20/2017,	Champoux prior to Active or to 10/2/2017 insp Active to 10/2/2017 inspe t done as of the last 11/21/2017. Active	10/19/2017. SF 10 No Dection by Developer Yes ction by Developer			
Current Condition: Sediment Basin 1 Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3	was repaired by Com Sediment Basin Good Condition- 30% Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char	ence by CE-2 was reins imercial Seeding prior West side-entrance full- Basin and Anti-vorte R 4-6 are in place on the East side-Central II- Basin and Anti-vortex R 7 & 8 are in place on s undermined and repai npoux was informed to o npoux was reminded on East side 0 & 11 are in place on the	talled by Developer Steve to 11/29/2017. 9/7/2016 ex device was installed prior solution of the slopes. r is needed. complete by 10/9/2017.No 10/10/2017, 10/20/2017, 9/7/2016	Champoux prior to Active or to 10/2/2017 insp Active to 10/2/2017 inspe t done as of the last 11/21/2017. Active 12 is missing. Basin	10/19/2017. SF 10 No Dection by Developer Yes ction by Developer t inspection.			
Current Condition: Sediment Basin 1 Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3	was repaired by Com Sediment Basin Good Condition- 30% Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SR Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin Poor Condition-SRR 1 to 10/2/2017. Sediment Basin needs	ence by CE-2 was reins imercial Seeding prior West side-entrance full- Basin and Anti-vorte R 4-6 are in place on the East side-Central II- Basin and Anti-vortes R 7 & 8 are in place on s undermined and repai npoux was informed to on npoux was reminded on East side 0 & 11 are in place on the s to be installed per plan	talled by Developer Steve to 11/29/2017. 9/7/2016 ex device was installed prio solopes. 9/7/2016 device was installed prior the slopes. r is needed. complete by 10/9/2017.No 10/10/2017, 10/20/2017, 9/7/2016 he slopes, although SRR , including riser, anti-vorte	Champoux prior to Active or to 10/2/2017 inspe to 10/2/2017 inspe to 10/2/2017 inspe t done as of the last 11/21/2017. Active 12 is missing. Basin x device, outfall and	10/19/2017. SF 10 No Dection by Developer Ves ction by Developer t inspection. <u>Yes</u> has been dug prior d rip rap per plan.			
Current Condition: Sediment Basin 1 Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3 Current Condition:	was repaired by Com Sediment Basin Good Condition- 30% Steve Champoux. SRI Fair Condition- 25% fu Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SRI Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin Poor Condition-SRR 1 to 10/2/2017. Sediment Basin needs Developer Steve Char Developer Steve Char	ence by CE-2 was reins imercial Seeding prior [West side-entrance full- Basin and Anti-vorte R 4-6 are in place on the [East side-Central [II- Basin and Anti-vortes R 7 & 8 are in place on s undermined and repai inpoux was informed to on poux was reminded on [East side 0 & 11 are in place on the to be installed per plan inpoux was informed to on poux was inform	talled by Developer Steve to 11/29/2017. 9/7/2016 ex device was installed prior the slopes. 9/7/2016 device was installed prior the slopes. r is needed. complete by 10/9/2017.No 10/10/2017, 10/20/2017, 9/7/2016 he slopes, although SRR , including riser, anti-vorte complete by 10/9/2017. No 10/10/2017, 10/20/2017, No	Champoux prior to Active or to 10/2/2017 insp Active to 10/2/2017 inspe t done as of the last 11/21/2017. Active 12 is missing. Basin x device, outfall and bt done as of the last 11/21/2017.	10/19/2017. SF 10 No Dection by Developer Yes ction by Developer t inspection. Yes has been dug prior d rip rap per plan.			
Current Condition: Sediment Basin 1 Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3 Current Condition:	was repaired by Com Sediment Basin Good Condition- 30% Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SRI Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin Sediment Basin Sediment Basin Sediment Basin Sediment Basin Sediment Basin Developer Steve Char	ence by CE-2 was reins imercial Seeding prior [West side-entrance full- Basin and Anti-vorte R 4-6 are in place on the [East side-Central [II- Basin and Anti-vortex R 7 & 8 are in place on s undermined and repai inpoux was informed to on [East side 0 & 11 are in place on the code installed per plan inpoux was informed to on inpoux was informed to on poux was informed to on inpoux was informed to on suppoux was informed to on inpoux was informed to on informed to on inpoux was informed to on inpoux was informed to on inpoux was informed to on informed to on inpoux was informed to o	talled by Developer Steve to 11/29/2017. 9/7/2016 ex device was installed prior the slopes. r is needed. complete by 10/9/2017.No 10/10/2017, 10/20/2017, 9/7/2016 he slopes, although SRR r , including riser, anti-vorte complete by 10/9/2017. No 10/10/2017, 10/20/2017, No 10/10/2017, 10/20/2017, No	Champoux prior to Active or to 10/2/2017 insp Active to 10/2/2017 inspe t done as of the lass 11/21/2017. Active 12 is missing. Basin x device, outfall and t done as of the lass 11/21/2017. Active Active	10/19/2017. SF 10 No Dection by Developer Yes ction by Developer t inspection. Yes has been dug prior d rip rap per plan. st inspection.			
Current Condition: Sediment Basin 1 Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3 Current Condition:	was repaired by Com Sediment Basin Good Condition- 30% Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SRI Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin Sediment Basin Sediment Basin Sediment Basin Sediment Basin Sediment Basin Developer Steve Char	ence by CE-2 was reins imercial Seeding prior [West side-entrance full- Basin and Anti-vorte R 4-6 are in place on the [East side-Central [II- Basin and Anti-vortex R 7 & 8 are in place on s undermined and repai inpoux was informed to on proux was reminded on [East side 0 & 11 are in place on the sto be installed per plan inpoux was informed to on proux was reminded on sto be installed per plan proux was reminded on sto be installed per plan inpoux was reminded on [SW corner ull- Trap was installed p	talled by Developer Steve to 11/29/2017. 9/7/2016 ex device was installed prior the slopes. 9/7/2016 (device was installed prior the slopes. r is needed. complete by 10/9/2017.No 10/10/2017, 10/20/2017, 9/7/2016 he slopes, although SRR , including riser, anti-vorte complete by 10/9/2017. No 10/10/2017, 10/20/2017, No	Champoux prior to Active or to 10/2/2017 insp Active to 10/2/2017 inspe t done as of the lass 11/21/2017. Active 12 is missing. Basin x device, outfall and t done as of the lass 11/21/2017. Active Active	10/19/2017. SF 10 No Dection by Developer Yes ction by Developer t inspection. Yes has been dug prior d rip rap per plan. st inspection.			
Current Condition: Sediment Basin 1 Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3 Current Condition: Sediment Trap 1 Current Condition:	was repaired by Com Sediment Basin Good Condition- 30% Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SRI Sediment Basin riser i Developer Steve Char Sediment Basin Poor Condition-SRR 1 to 10/2/2017. Sediment Basin needs Developer Steve Char Developer Steve Char Sediment Basin needs Developer Steve Char Sediment Basin needs Developer Steve Char Sediment Basin needs Developer Steve Char Sediment Trap Good Condition-20% f SRR 1 & 2 are in place	ence by CE-2 was reins imercial Seeding prior West side-entrance full- Basin and Anti-vorte R 4-6 are in place on the East side-Central II- Basin and Anti-vortes R 7 & 8 are in place on s undermined and repai npoux was informed to on poux was reminded on East side 0 & 11 are in place on the to be installed per plan npoux was informed to on SW corner SW corner ull- Trap was installed p e on the slopes.	talled by Developer Steve to 11/29/2017. 9/7/2016 ex device was installed prio solopes. 9/7/2016 device was installed prior the slopes. r is needed. complete by 10/9/2017.No 10/10/2017, 10/20/2017, 9/7/2016 he slopes, although SRR , including riser, anti-vorte complete by 10/9/2017. No 10/10/2017, 10/20/2017, No 10/10/2017, 10/20/2017, No 10/10/2017, 10/20/2017, No 10/10/2017, 10/20/2017, No 9/7/2016 prior to 10/2/2017 inspectio	Champoux prior to Active or to 10/2/2017 insp Active to 10/2/2017 inspe to 10/2/2017 inspe t done as of the last 11/21/2017. Active 12 is missing. Basin x device, outfall and ot done as of the last 11/21/2017. Active on by Developer Ste	10/19/2017. SF 10 No Dection by Developer Ves ction by Developer t inspection. Yes has been dug prior d rip rap per plan. of inspection.			
Current Condition: Sediment Basin 1 Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3 Current Condition:	was repaired by Com Sediment Basin Good Condition- 30% Steve Champoux. SRI Fair Condition- 25% fu Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SRI Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin Poor Condition-SRR 1 to 10/2/2017. Sediment Basin needs Developer Steve Char Developer Steve Char Sediment Basin needs Developer Steve Char Sediment Tapin Good Condition-20% f SRR 1 & 2 are in place Sediment Trap Good Condition-Sedir installed prior by Steve	ence by CE-2 was reins imercial Seeding prior [West side-entrance full- Basin and Anti-vorte R 4-6 are in place on the [East side-Central [II- Basin and Anti-vortes R 7 & 8 are in place on s undermined and repai inpoux was informed to o npoux was reminded on [East side 0 & 11 are in place on the to be installed per plan inpoux was informed to o npoux was informed to o mpoux was informed to o so to be installed per plan inpoux was informed to o mpoux was i	talled by Developer Steve to 11/29/2017. 9/7/2016 ex device was installed prior the slopes. r is needed. complete by 10/9/2017.No 10/10/2017, 10/20/2017, 9/7/2016 he slopes, although SRR r , including riser, anti-vorte complete by 10/9/2017. No 10/10/2017, 10/20/2017, No 10/10/2017, 10/20/2017, No	Champoux prior to Active or to 10/2/2017 insp to 10/2/2017 inspe to 10/2/2017 inspe t done as of the last 11/21/2017. Active 12 is missing. Basin x device, outfall and bt done as of the last 11/21/2017. Active on by Developer Ste Active ent on the west side	10/19/2017. SF 10 No Dection by Developer Yes ction by Developer tinspection. Yes has been dug prior trip rap per plan. st inspection. No exe Champoux. No . ST 6-8 have been			
Current Condition: Sediment Basin 1 Current Condition: Sediment Basin 2 Current Condition: Sediment Basin 3 Current Condition: Sediment Trap 1 Current Condition: Sediment Traps 2-8	was repaired by Com Sediment Basin Good Condition- 30% Steve Champoux. SRI Fair Condition- 25% fu Steve Champoux. SRI Sediment Basin Fair Condition- 25% fu Steve Champoux. SRI Sediment Basin riser i Developer Steve Char Developer Steve Char Sediment Basin Poor Condition-SRR 1 to 10/2/2017. Sediment Basin needs Developer Steve Char Developer Steve Char Sediment Basin needs Developer Steve Char Sediment Tapin Good Condition-20% f SRR 1 & 2 are in place Sediment Trap Good Condition-Sedir	ence by CE-2 was reins imercial Seeding prior [West side-entrance full- Basin and Anti-vorte R 4-6 are in place on the [East side-Central [II- Basin and Anti-vortes R 7 & 8 are in place on s undermined and repai inpoux was informed to o npoux was reminded on [East side 0 & 11 are in place on the to be installed per plan inpoux was informed to o npoux was informed to o mpoux was informed to o so to be installed per plan inpoux was informed to o mpoux was i	talled by Developer Steve to 11/29/2017. 9/7/2016 ex device was installed prior the slopes. 9/7/2016 device was installed prior the slopes. r is needed. complete by 10/9/2017.No 10/10/2017, 10/20/2017, 9/7/2016 he slopes, although SRR , including riser, anti-vorte complete by 10/9/2017. No 10/10/2017, 10/20/2017, 9/7/2016 prior to 10/2/2017 inspection 9/7/2016 en removed for development	Champoux prior to Active or to 10/2/2017 insp to 10/2/2017 inspe to 10/2/2017 inspe t done as of the last 11/21/2017. Active 12 is missing. Basin x device, outfall and bt done as of the last 11/21/2017. Active on by Developer Ste Active ent on the west side	10/19/2017. SF 10 No Dection by Developer Yes ction by Developer tinspection. Yes has been dug prior trip rap per plan. st inspection. No exe Champoux. No . ST 6-8 have been			

Current Condition:	Good Condition- Rip rap 1,2, 4-8, 10-11 were installed prior to 10/2/2017 inspection. Rip rap 3, 9 and 12 are currently missing or need to be verified. E&A will continue to monitor.					
STR	Streets	Site	9/7/2016	Active	No	
Current Condition:	Good Condition- Stree	ts were scraped up and	cleaned by Developer Ste	ve Champoux prio	r to 10/19/2017.	
SWPPP Sign	Misc/Other	Blondo Parkway	10/9/2017	Active	No	
Current Condition:	Good Condition- 2 SW	PPP signs were installe	d by the entrances prior to	10/19/2017 by E&	A.	
nspector Signature:	Cat Sul			Reviewed By:	Hittes Van	