E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Engineering Answers

Zachary A. Jilek, CPESC, CISEC

E & A CONSULTING GROUP, INC.

ENGINEERING · PLANNING · ENVIRONMENTAL & FIELD SERVICES Environmental Services Dept. Manager E&A - P1999.175.0042 Inspector: Mike Jacobson, CISEC Stage Val Vista NER101066 Project Name: 6/8/2013 For Week Ending: 68128 Project Location: 108th & Giles Road - Papillion, NE (Sarpy County) Grading: 100% Sanitary Sewer: 100% Storm Sewer: 100% Paving: 100% 100% Seeding 100% Utilities Overall Development: RAIN FALL AMOUNTS Amount in tenths Sunday: 0.00" Monday 0.00 Tuesday 0.03 Wednesday 0.00" Thursday 0.00 Friday 0.00" Saturday 0.00" Sunday: Monday 0.00" 05/21/13 Tuesday 0.00" Wednesday 0.01" Thursday 0.00" Friday 0.00" Saturday 0.31" Sunday: 0.01" Monday 1.24' 05/27/13 0.00" Tuesday Wednesday).59" Thursday).19" 05/31/13 Friday).12' Saturday 0.03 Sunday: 0.00" Monday 0.00" Tuesday 0.05" Wednesday 0.00 Thursday 0.00 Friday 0.00" Saturday Sunday: N/A N/A Monday N/A N/A Tuesday Wednesday N/A N/A Thursday N/A Friday N/A N/A Saturday N/A N/A Complaints: Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006. As of inspection on 3/25/09 grading was active on lot 241. As of inspection on 4/7/09 grading was completed on this section of lot 241. hich portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005,

and south commercial property grading completed and site seeded Summer 2006.

As of inspection on 3/25/09 grading was active on lot 241. As of inspection on 4/7/09 grading was completed on this section of lot 241.

What temporary or permanent stabilization measures listed in this section are being implemented?								
Paving, dense vegetation and landscaping installed prior to 2005. Paving commercial property (7/2007)								
Comments:								
Comments:								
No activity in the residential or commercial areas.								
Findings / Corrective Actions (Date):								
-								
Findings / Corrective Actions (Date):								
1) No maintenance is required in the BMP section.								

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
	Construction	N41d00m00s			
CE-1 Current Condition:	Entrance Entrance Paved	W96d00m00s		Removed	
Carrent Condition.	Construction	N41d00m00s	T		
CE-2	Entrance	W96d00m00s		Removed	
Current Condition:	Entrance Paved		1		
	Construction	N41d00m00s			
CE 3	Entrance	W96d00m00s		Removed	
Current Condition:	Entrance Paved				
		N41d00m00s			
DD 1	Diversion Ditch	W96d00m00s		Removed	
Current Condition:	Diversion Ditch was remov	ed when the SB 7 was	re-located to the northe	ast, but was not re	moved from the rep
		N144 d00-e00-	1		
CD 1	Sadiment Basin	N41d00m00s		Romayad	
SB 1 Current Condition:	Sediment Basin	W96d00m00s		Removed	
Current Condition:		N41d00m00s	1		
SB 2	Sediment Basin	W96d00m00s		Removed	
Current Condition:	Sediment Basin	W90d00III00S		Removed	
Carrent Condition.		N41d00m00s			
SB 3	Sediment Basin	W96d00m00s		Removed	
Current Condition:	Counter Dasiil	***************************************		Romoved	
Carront Condition.		N41d00m00s	T I		
SB 4	Sediment Basin	W96d00m00s		Removed	
Current Condition:	TTT Buon1		1		
		N41d00m00s			
SB 5	Sediment Basin	W96d00m00s	<u> </u>	Removed	
Current Condition:	Removed due to commerc	ial property developmer	nt		
		N41d00m00s			
SB 6	Sediment Basin	W96d00m00s		Removed	
Current Condition:					
		N/41 d0000	<u> </u>	1	
QD 7	Sediment Basin	N41d00m00s W96d00m00s	In Place	A otivo	No
SB 7 Current Condition:	Good Condition- 32% full.	W 9000011100S	In Place	Active	No
Current Condition.	Outlet Pipe maintenance of	completed 5/2007 Comp	nercial Seeding		
	Oddet i pe maintenance c	ompleted 3/2007 Comin	lercial decuirig.		
		N41d00m00s			
SB 8	Sediment Basin	W96d00m00s		Removed	
Current Condition:	Removed.				
		N41d00m00s			
SF 1	Silt Fence	W96d00m00s		Removed	
Current Condition:	Silt fence was removed pri		09 by CS for Bernie Hed		e will need to be re-
	installed when construction	n is active in the area.			
		N41d00m00s	T 1		
SF 2	Silt Fence	W96d00m00s		Removed	
Current Condition:	Cit i Gilos	***************************************		Romoved	
Carroni Contantoll.		N41d00m00s			
SF 3	Silt Fence	W96d00m00s		Removed	
Current Condition:			ı		
		N41d00m00s			
SF 4	Silt Fence	W96d00m00s		Removed	
Current Condition:					
		N41d00m00s			
SF 5	Silt Fence	W96d00m00s		Removed	
Current Condition:					
		N41d00m00s			
SF 6	Silt Fence	W96d00m00s		Removed	
Current Condition:					-
		N41d00m00s			
SF 7	Silt Fence	W96d00m00s		Removed	
Current Condition:					
		N41d00m00s			
SF 8	Silt Fence	W96d00m00s		Removed	
Current Condition:		1			
05.5	OW =	N41d00m00s			
SF 9	Silt Fence	W96d00m00s		Removed	
Current Condition:		N44-100-00	 	-	
05.40	0 =	N41d00m00s		D	
SF 10	Silt Fence	W96d00m00s		Removed	

Current Condition:							
		N41d00m00s					
SF 11	Silt Fence	W96d00m00s		Removed			
Current Condition:							
		N41d00m00s					
SF 12	Silt Fence	W96d00m00s		Removed			
Current Condition:							
SF 14	Silt Fence	Lot 248		Removed			
Current Condition:	Silt fence run was removed prior to inspection on 7/5/10 by CS due to good vegetation and this area of the lot being builder on already.						
		N41d00m00s					
STR	Street Cleaning	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition- No major	Good Condition- No major signs of track off.					
SWPPP Sign	SWPPP Sign	One sign on site	8/8/2008	Active	No		
Current Condition:	Good Condition On 3/27/08 inspector insta		8th & Brentwood Ave	e. and 108th & Chandle	er Rd entrance. The		
nspector Signature:	had Jawlan			Reviewed By:	Echany L. Jiluk		