E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Engineering Answers

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Ma

E & A CONSULTING GROUP, INC. ENGINEERING • PLANNING • ENVIRONMENTAL & FIELD SERVICES

Environmental Services Dept.	Manager	ENGINE	ERING · PLANNING ·	ENVIRONMENTAL & F	ELD SERVICES		
•	Ŭ	E&A	- P1999.175.04	2			
Inspector: Patrick Sechser						Stage	
			Val Vist	2		3	
						-	
Project Name:			NER1010	66			
For Week Ending:		3/14/2015					
Project Location:	11	108th & Giles Road - Papillion, NE (Sarpy County)					
			68128				
Grading:		100%					
Sanitary Sewer:		100%					
Storm Sewer:		100%					
Paving:		100%					
Seeding:		100%					
Utilities:		100%					
Overall Development:		68%					
					1		
RAIN FALL AMOUNTS	Amount in tenths	Date	e inspected	Weather Conditions			
						Week 1	
Sunday:	0.00"						
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"						
						Week 2	
Sunday:	0.00"						
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.05"						
Thursday	0.00"		2/26/2015	Sunny 12/2			
Friday	0.00"						
Saturday	0.00"						
						Week 3	
Sunday:	0.00"						
Monday	0.01"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"						
						Week 4	
Sunday:	0.00"						
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"						
						Week 5	
Sunday:	N/A	N/A					
Monday	N/A	N/A					
Tuesday	N/A	N/A					
Wednesday	N/A	N/A					
Thursday	N/A	N/A					
Friday	N/A	N/A					
Saturday	N/A	N/A					
Complaints:	None						

Construction Sequencing:						
Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?						
En d'an aite ann aite a tha bhfar ann aite an an	and a first state of the second state of the state	0005				
Entire site; residential site grading con			cial property grading o	completed and site	seeded Summer 2005,	
and south commercial property grading	j completed and site seeded	d Summer 2006.				
		4/7/00		delta a solta a setta de		
As of inspection on 3/25/09 grading wa	as active on lot 241. As of in	spection on 4/7/09 grad	ing was completed on	this section of lot 2	241.	
Which portion(s) (i.e. drainage basins) of the	site do not have grading, earthw	ork, or ground disturbance	scheduled in the next 14	days? :		
Entire site; residential site grading com	pleted and site seeded prior	r to 2005, north comme	rcial property grading of	completed and site	seeded Summer 2005,	
and south commercial property grading	g completed and site seeded	d Summer 2006.				
As of inspection on 3/25/09 grading was active on lot 241. As of inspection on 4/7/09 grading was completed on this section of lot 241.						
What temporary or permanent stabilization measures listed in this section are being implemented?						
Paving, dense vegetation and landscaping installed prior to 2005. Paving commercial property (7/2007)						
SUMMARY QUESTIONS:						
Are approved entrances and adjacent streets being maintained adequately?						
Yes						
Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?						
Yes	T			<u>т </u>	r	
	ļ	ļ			ļ	
CHECKLIST QUESTIONS:						
Are waste materials (concrete, consruction r Yes	naterial, nazardous, etc.) being n	nanaged property?				
Tes	1			T		
Is dust associated with the construction acti	vity adequately controlled on the	site?		<u> </u>		
is dust associated with the construction activity adequately controlled on the site : Yes						
Comments:						
Comments:						
Work is continuing on lot 8, replat 4 and lot 1, replat 2 as of 2/26/2015. However, both lots are over an acre and not included in the current						
SWPPP.						
Findings / Corrective Actions (Date):						
Findings / Corrective Actions (Date):						
1.) No maintenance is required in the BMP section.						

			Projected Install			
Unique Name	Туре	Location	Date	Status	Maintenance	
		N41d00m00s				
SB 7	Sediment Basin	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition- 36% full- Outlet Pipe maintenance completed 5/2007 Commercial Seeding.					
		N41d00m00s				
STR	Street Cleaning	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition- No major signs of track off.					
Inspector Signature:	Parts Sul)			Reviewed By:	Zachany K. Julik	