E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Engineering Answers

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Inspector: Patrick Sechser Stage 3 Val Vista NER101066 Project Name: 12/12/2015 For Week Ending: 108th & Giles Road - Papillion, NE (Sarpy County) Project Location: 68128 Grading: 100% Sanitary Sewer: 100% Storm Sewer: 100% Paving: 100% Seeding: 100% Utilities 100% Overall Development: 68% RAIN FALL AMOUNTS Amount in tenths Date inspected Weather Conditions Sunday: 0.00" Monday 0.03 Tuesday 0.55 11/18/2015 Cloudy 49/35 0.00" Wednesday 0.00" Thursday 0.04" Friday Saturday 0.00" Week Sunday: 0.00" Monday 0.00" Tuesday 0.00" Wednesday 0.00" Thursday).28 Friday 0.00" Saturday **0.0**1" W Sunday: 0.00" Monday 0.35 Tuesday 0.00" Wednesday 0.00' Thursday 0.00" Friday 0.00" Saturday 0.00" Week Sunday: 0.00" 0.00" Monday Tuesday 0.00" Wednesday 0.03" Thursday 0.00' Friday 0.00" Saturday 0.63" Weel Sunday: N/A N/A Monday N/A N/A Tuesday N/A N/A Wednesday N/A N/A Thursday N/A N/A Friday N/A N/A Saturday N/A N/A None Complaints: Construction Sequencing ince in the last 14 days Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006. /hich portion(s) (i.e. d 14 d

E&A - P1999.175.042

Entire site: residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005,									
and south commercial property grading completed and site seeded Summer 2006.									
	- · ·								
What temporary or permanent stabilization n	neasures listed in this section are	e being implemented?							
Paving, dense vegetation and landscaping installed prior to 2005. Paving commercial property (7/2007)									
SUMMARY QUESTIONS:									
Are approved entrances and adjacent streets being maintained adequately?									
Yes									
Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?									
Yes	1								
CHECKLIST OUESTIONS:									
CHECKLIST QUESTIONS: Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?									
· · · ·	naterial, nazardous, etc.) being n	nanaged property?							
Yes	1								
Is dust associated with the construction acti	with adaptately controlled on the	site?							
Yes	vity adequately controlled of the	sile f							
Comments:									
Comments:									
Site is inactive.									
Findings / Corrective Actions (Date):									
Findings / Corrective Actions (Date):									
1.) No maintenance is required in the BMP section.									

			Projected Install				
Unique Name	Туре	Location	Date	Status	Maintenance		
		N41d00m00s					
SB 7	Sediment Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition- 36% full- Outlet Pipe maintenance completed 5/2007 Commercial Seeding.						
		N41d00m00s					
STR	Street Cleaning	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition- No major signs of track off.						
Inspector Signature:	Cato Sul			Reviewed By:	Zachany K. Jiluk		