E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com

Complaints:



Zachary A. Jilek, CPESC, CISEC

	ger Engineering Answers					
E	&A - P1999.175.0	42	ı			
				Stage		
Val Vista NER101066				3		
40046		00400				
108tn 8	Glies Road - Papilli	on, NE (Sarpy Count	y)	68128		
100%						
100%)					
100%)					
68%						
A	L	I				
Amount in tentris	Date inspected	Weather Conditions		Wee		
0.00"				- vve		
0.00"						
				Wee		
0.00"						
0.00"	1/18/2016	Cloudy 17/0				
0.05"						
0.00"						
0.00"						
				Wed		
0.00"						
0.00"				Wee		
		1	+			
			+			
			+			
			+			
0.00			+			
			+			
0.00				We		
0.00"						
0.00"						
0.00"						
0.01"						
0.00"						
	i .	+				
0.00"						
	108th 8 100% 100% 100% 100% 100% 100% 100% 10	Val Vis NER101 2/13/20 108th & Giles Road - Papillion 100% 100% 100% 100% 100% 100% 100% 100% 68% Amount in tenths Date inspected 0.00"	NER101066 2/13/2016 108th & Giles Road - Papillion, NE (Sarpy County 100% 1000"	Val Vista NER101066		

Construction Sequencing: sins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006. Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006. What temporary or permanent stabilization measures listed in this section are being implemented? Paving, dense vegetation and landscaping installed prior to 2005. Paving commercial property (7/2007) SUMMARY QUESTIONS: Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes CHECKLIST QUESTIONS: Are waste materials (concrete, construction material, hazardous, etc.) being managed properly? s dust associated with the construction activity adequately controlled on the site? Yes Comments: Site is inactive. Rain inspections were not completed with in 24 hours of moisture quantities going over .5" on 2/2/2016 due to the moisture

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) No maintenance is required in the BMP section.

			Projected Install			
Unique Name	Туре	Location	Date	Status	Maintenance	
		N41d00m00s				
SB 7	Sediment Basin	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition- 36% full- Outlet Pipe maintenance completed 5/2007 Commercial Seeding.					
		N41d00m00s				
STR	Street Cleaning	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition- No major	signs of track off.				
nspector Signature:	Posts Sul			Reviewed By:	Tachary L. Jilek	

being snow and due to dangerous driving conditions. Inspections will be conducted at normal intervals.