E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept. M	lanager			igincering Answ		
		E&A - P1999.17	75.042			
Inspector: Matthew Vanicek					Stage	
		Val	Vista		3	
Project Name:		NER101066				
For Week Ending:		7/13/2019				
Project Location:	1	108th & Giles Road - Papillion, NE (Sarpy County)				
Grading:		00%				
Sanitary Sewer:	10	00%				
Storm Sewer:		00%				
Paving:		00%				
Seeding:		00%				
Utilities:		00%				
Overall Development:		68%				
	1			Т		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions			
					Week 1	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"			ļļ		
Wednesday	0.28"					
Thursday	0.00"					
Friday	0.00"			+ -		
Saturday	0.00"					
	0.00#				Week 2	
Sunday:	0.00"					
Monday	0.05"					
Tuesday Wednesday	0.43" 0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
outur day	0.00				Week 3	
Sunday:	0.11"				Week	
Monday	0.00"					
Tuesday	0.10"					
Wednesday	0.19"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
					Week 4	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.82"	7/3/2019	91/76 Partly Cloudy			
Thursday	0.00"					
Friday	0.02"	7/5/2019	85/73 Cloudy		<u> </u>	
Saturday	0.00"					
	2.20				Week 5	
Sunday:	0.00"			ļ		
Monday	0.00"					
Tuesday	0.26"			1		
Wednesday Thursday	0.00"			 		
Thursday Friday	0.00"			+		
			+	+ +		
Saturday	0.00"		1			
	ls.					
	None					
Complaints:						
Complaints:						
Complaints: Construction Sequencing:						

Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006.

ent stabilization measures listed in this section are being imp

Paving, dense vegetation and landscaping installed prior to 2005. Paving commercial property (7/2007)

SUMMARY QUESTIONS:

Are approved entrances and adjacent streets being maintained adequately?

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

CHECKLIST QUESTIONS:

s dust associated with the construction activity adequately controlled on the site?

Comments:

Comments:

Inspector Signature:

Site is inactive as of the last inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) See BMP Section for required maintenance.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance		
		N41d00m00s					
SB 7	Sediment Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition- 36% full- Outlet Pipe maintenance completed 5/2007 Commercial Seeding.						
		N41d00m00s					
STR	Street Cleaning	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition- No major signs of track off.						
SWPPP Sign	Sign	S. 108th Street	11/7/2018	Pending	No		
Current Condition:	Pending - A SWPPP Sign will be reinstalled when construction resumes on the site.						
Inspector Signature:			Reviewed By:	Posts Sol			

Reviewed By: