E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Engineering Answers

Environmental Services Dept. N	nager Engineering Answe					
Environmental del vices Dept. N	nanagei	E&A - P199	9.175.042			
Inspector: Shaun McGuire	pector: Shaun McGuire					
пороского спаши постано		Stage				
		Val Vista NER101066				
Project Name:		68128				
For Week Ending:						
Project Location:						
Grading:		100%				
Sanitary Sewer:		100%				
Storm Sewer:		100%				
Paving:		100%				
Seeding:		100%				
Utilities:		100%				
Overall Development:		68%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Inspection Time	Storm Event Duration	
	7 tillount ill tolltilo	Bate moperted	Wodiner Conditions	mopodion rime	Week	
Sunday:	0.00"				- Frook	
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday Saturday	0.21" 0.04"				6:00 AM - 12:00 AM	
Saturday	0.04				12:00 AM - 10:00 AM Week 2	
Sunday:	0.00"				Week 2	
Monday	0.03"	12/18/202	3 Sunny 51/29	8:10 AM		
Tuesday	0.00"	13,10,20				
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
Sunday	0.00"				Week 3	
Sunday: Monday	0.88" 0.24"				5:45 AM - 12:00 AM 12:00 AM - 11:00 AM	
Tuesday	0.08"	12/26/202	23 Overcast 32/27	8:45 AM	12.00 AW - 11.00 AW	
Wednesday	0.00"	12/20/202	010.000.022	0		
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
Company of the compan	0.00"				Week 4	
Sunday: Monday:	0.00"				_	
Tuesday:	0.00"				+	
Wednesday:	0.00"				+	
Thursday:	0.00"					
Friday:	0.00"					
Saturday:	0.00"					
					Week 5	
Sunday:	0.00"				0.00.414.40.00.111	
Monday	0.27"	4/0/2004	0::	10:20 414	6:30 AM - 12:00 AM	
Tuesday Wednesday	0.09"	1/9/2024	Overcast 32/13	10:20 AM	12:00 AM - 4:00 AM	
Thursday	0.00"				+	
Friday	0.07"				+	
Saturday	0.00"					
	None					
Complaints:						
Construction Sequencings						
Construction Sequencing: Which portion(s) (i.e. drainage basins) of	of the cite have had a tomparati	or normanant coccation	of grading parthwork or ground dis	sturbance in the last 4.4	days?	
Trinon portion(s) (i.e. drainage pasins) o	or the site have had a temporary	or permanent cessation (or grading, earniwork, or ground dis	sturbance in the last 14	uayo:	

Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006.

As of inspection on 3/25/09 grading was active on lot 241. As of inspection on 4/7/09 grading was completed on this section of lot 241.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006.

As of inspection on 3/25/09 grading was active on lot 241. As of inspection on 4/7/09 grading was completed on this section of lot 241.

What temporary or permanent stabilization measures listed in this section are being implemented?

Paving, dense vegetation and landscaping installed prior to 2005. Paving commercial property (7/2007)

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to

νΔς

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Vac

Create Corrective Action?

N/A

Are construction entrances and adjacent streets being maintained adequately?

V---

Create Corrective Action?

N/A

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments

Comments:

Site is inactive as of the last inspection.

Lot 1 Val Vista Replat One is under grading permit # LAV-20220831-6588-GP2 and is being inspected by HG Associates as of 12/2/2022.

Lot 5 Val Vista Replat One is under grading permit #LAV-20230926-7113-GP2 and is being inspected by Olsson as of 11/21/23.

Lot 2 Val Vista Replat Seven has been sold as of 11/21/23. Currently no separate grading permit.

Remaining lots include Lot 1 Val Vista Replat Seven, Lot 2 Val Vista Replat One, Lot 6 Val Vista Replat One, Lot 7 Val Vista Replat One, and Lot 234 Val

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) No maintenance is needed at this time.

Unique Name	Туре	Location N41d00m00s	Projected Install Date	Status	Maintenance		
SB 7	Sediment Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - 36% full - Outlet Pipe maintenance completed 5/2007 Commercial Seeding.						
		N41d00m00s					
STR	Street Cleaning	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - No major signs of track off.						
SWPPP Sign	Sign	S. 108th Street	11/7/2018	Pending	No		
Current Condition:	Pending - A SWPPP Sign will be reinstalled when construction resumes on the site.						
Certification Statement:	accordance with a system submitted. Based on my in gathering the information,	designed to assure that quiry of the person or pethe information submitte	nd all attachments were preg qualified personnel properly ersons who manage the syst d is, to the best of my knowl alties for submitting false inf	gathered and eval em or those perso edge and belief, tru	uated the information ns directly responsible ie, accurate, and		

Inspector Signature:

Reviewed By: