E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Zachary A. Jilek, CPESC, CISEC					ing Answers	
Environmental Services Dept. N	nanager	E&A - P1999.17	5.042			
Inspector: Shaun McGuire						
Project Name:		3				
		NER101066				
For Week Ending:						
Project Location:	108th	68128				
Grading:	100%			1		
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	100%					
Seeding:	100%					
Utilities: Overall Development:	100%					
Overall Bevelopment.	0070			I		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Inspection Time	Storm Event Duration	
					Week 1	
Sunday:	0.00"			1		
Monday Tuesday	0.00"					
Wednesday	0.00"		+	<u> </u>		
Thursday	0.00"			<u> </u>		
Friday	0.00"					
Saturday	0.00"					
Sunday:	0.00"				Week 2	
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00				Week 3	
Sunday:	0.00"				Week	
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday Friday	0.00"					
Saturday	0.00"					
outu. uuy	6.66				Week 4	
Sunday:	0.00"					
Monday:	0.00"					
Tuesday: Wednesday:	0.00" 0.02"	2/7/2024	Overcast 56/43	11:45 AM		
Thursday:	0.01"	2/1/2024	Overcast 30/43	11.45 AW		
Friday:	0.00"					
Saturday:	0.00"					
					Week 5	
Sunday:	N/A			1		
Monday Tuesday	N/A N/A			+		
Wednesday	N/A					
Thursday	N/A					
Friday	N/A					
Saturday	N/A					
	News					
Complaints:	None					
- Diames						
Construction Sequencing:			<u> </u>			
Which portion(s) (i.e. drainage basins) of	of the site have had a temporary or peri	manent cessation of grad	ling, earthwork, or ground distur	bance in the last 14 da	ays?	

Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006.

As of inspection on 3/25/09 grading was active on lot 241. As of inspection on 4/7/09 grading was completed on this section of lot 241.

Vhich portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006.

As of inspection on 3/25/09 grading was active on lot 241. As of inspection on 4/7/09 grading was completed on this section of lot 241.

Paving, dense vegetation and landscaping installed prior to 2005. Paving commercial property (7/2007)

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

N/A

lave disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

Are construction entrances and adjacent streets being maintained adequately?

reate Corrective Action?

N/A

s dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Site is inactive as of the last inspection.

Lot 1 Val Vista Replat One is under grading permit # LAV-20220831-6588-GP2 and is being inspected by HG Associates as of 12/2/2022.

Lot 5 Val Vista Replat One is under grading permit #LAV-20230926-7113-GP2 and is being inspected by Olsson as of 11/21/23.

Lot 2 Val Vista Replat Seven has been sold as of 11/21/23. Currently no separate grading permit.

Remaining lots include Lot 1 Val Vista Replat Seven, Lot 2 Val Vista Replat One, Lot 6 Val Vista Replat One, Lot 7 Val Vista Replat One, and Lot 234 Val Vista.

Findings / Corrective Actions (Date):

1.) No maintenance is needed at this time.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance		
		N41d00m00s					
SB 7	Sediment Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - 36% full - Outlet Pipe maintenance completed 5/2007 Commercial Seeding.						
		N41d00m00s					
STR	Street Cleaning	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - No major signs of track off.						
SWPPP Sign	Sign	S. 108th Street	11/7/2018	Pending	No		
Current Condition:	Pending - A SWPPP Sign will be reinstalled when construction resumes on the site.						
Certification Statement:	I certify, under penalty of law	w, that this document a	nd all attachments were prep	pared under my dir	ection or supervisior		
	accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information						
	submitted. Based on my inc	quiry of the person or p	areone who manage the eyet	tem or those person	ne directly responsib		

gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations Got Sie

Inspector Signature:

Reviewed By: