E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept.	Manager	E0.4 B4	000 175 010	2.1.91.1100	illig Allswers	
		E&A - P1	999.175.042		T	
Inspector: Shaun McGuire					Stage	
			Val Vista		3	
		NER101066				
Project Name:						
For Week Ending:			4/13/2024			
Project Location:		108th & Giles Roa	d - Papillion, NE (Sarpy Count	y)	68128	
•	•			-	•	
Grading:		100%				
Sanitary Sewer:		100%				
Storm Sewer:		100%				
Paving:		100%				
Seeding:		100%				
Utilities:		100%				
Overall Development:		68%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Inspection Time	Storm Event Duration	
					Week	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.30"				12:15 AM - 12:15 PM	
Friday	0.00"	3/15/2	024 Sunny 60/41	10:20 AM		
Saturday	0.00"					
					Week 2	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.08"					
Saturday	0.00"					
					Week :	
Sunday:	0.75"				5:30 AM - 7:00 PM	
Monday	0.07"	3/25/2	024 Overcast 53/23	10:00 AM		
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
					Week	
Sunday:	0.00"					
Monday:	0.00"					
Tuesday:	0.00"					
Wednesday:	0.00"					
Thursday:	0.00"				+	
Friday:	0.00"					
Saturday:	0.10"					
					Week 5	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.03"					
Thursday	0.00"				+	
Friday	0.00"					
Saturday	0.00"					
	None					
Complaints:						
Construction Sequencing:						
Which portion(s) (i.e. drainage basins)	of the site have had a temporary	or permanent cessation	on of grading, earthwork, or ground d	isturbance in the last 14 of	days?	

Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006.

As of inspection on 3/25/09 grading was active on lot 241. As of inspection on 4/7/09 grading was completed on this section of lot 241.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006.

As of inspection on 3/25/09 grading was active on lot 241. As of inspection on 4/7/09 grading was completed on this section of lot 241.

What temporary or permanent stabilization measures listed in this section are being implemented?

Paving, dense vegetation and landscaping installed prior to 2005. Paving commercial property (7/2007)

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

N/A

Are construction entrances and adjacent streets being maintained adequately?

Vac

Create Corrective Action?

N/A

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments

Comments:

Site is inactive as of the last inspection.

Lot 1 Val Vista Replat One is under grading permit # LAV-20220831-6588-GP2 and is being inspected by HG Associates as of 12/2/2022.

Lot 5 Val Vista Replat One is under grading permit #LAV-20230926-7113-GP2 and is being inspected by Olsson as of 11/21/23.

and imprisonment for knowing violations

Lot 2 Val Vista Replat Seven has been sold as of 11/21/23. Currently no separate grading permit.

Remaining lots include Lot 1 Val Vista Replat Seven, Lot 2 Val Vista Replat One, Lot 6 Val Vista Replat One, Lot 7 Val Vista Replat One, and Lot 234 Val Vista.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) No maintenance is needed at this time.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance			
•		N41d00m00s						
SB 7	Sediment Basin	W96d00m00s	In Place	Active	No			
Current Condition:	Good Condition - 36% full - Outlet Pipe maintenance completed 5/2007 Commercial Seeding.							
		N41d00m00s						
STR	Street Cleaning	W96d00m00s	In Place	Active	No			
Current Condition:	Good Condition - No major signs of track off.							
SWPPP Sign	Sign	S. 108th Street	11/7/2018	Pending	No			
Current Condition:	Pending - A SWPPP Sign will be reinstalled when construction resumes on the site.							
Certification Statement:	I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in							
	accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information							
	submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible							
	gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and							
	complete. I am aware that there are significant penalties for submitting false information including the possibility of fines							

Inspector Signature:

Reviewed By: