E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC
Environmental Services Dept. Manager

Engineering Answers

100% 100% 100% 100% 100% 100% 68%		/ista 01066		Stage 3 68128
100% 100% 100% 100% 100% 100% 68%	NER10 7/13/ & Giles Road - Pap	01066 2024		3
100% 100% 100% 100% 100% 100% 68%	NER10 7/13/ & Giles Road - Pap	01066 2024		
100% 100% 100% 100% 100% 100% 68%	7/13/ & Giles Road - Pap	2024		68128
100% 100% 100% 100% 100% 100% 68%	& Giles Road - Pap			68128
100% 100% 100% 100% 100% 100% 68%		illion, NE (Sarpy County)		68128
100% 100% 100% 100% 100% 68%				
100% 100% 100% 100% 100% 68%				
100% 100% 100% 100% 100% 68%				
100% 100% 68%				
100% 68%				
68%				
Amount in touth				
Amount in tenths	Date inspected	Weather Conditions	Inspection Time	Storm Event Duration
				Week
0.00"				
				+
				+
				+
0.00"				+
0.72"				6:55 - 12:55
				Week
	2//=/222	4		
	6/17/2024	Cloudy 89/67	1:45 PM	40.54 24.54
	6/19/2024	Cloudy 74/65	10:10 AM	18:54 - 21:54
	0/13/2024	Cloudy 14/03	10.10 AW	
0.00"				+
0.00"				
				Week
				_
				-
0.00"				
				Week
0.00"				7.55 AM 40.55 AM 9
1.31"	7/1/2024	Cloudy 72/60	2:15 PM	7:55 AM - 10:55 AM & 11:15 PM -
3.13"	7/2/2024	Cloudy 80/67	10:50 AM	To 2:55 PN
0.00"				
0.17"				
0.07"				107
0.00"				Week
0.00"				+
0.00"				
0.00"				
0.00"				
J0.00°				
Nono				
INOTIE				
\dashv				
	0.00" 0.00" 0.00" 0.00" 0.00" 0.00" 0.00" 0.72" 0.00"	Amount in tenths Date inspected	Amount in tenths Date inspected Weather Conditions 0.00"	Amount in tenths

Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006.

As of inspection on 3/25/09 grading was active on lot 241. As of inspection on 4/7/09 grading was completed on this section of lot 241.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006.

As of inspection on 3/25/09 grading was active on lot 241. As of inspection on 4/7/09 grading was completed on this section of lot 241.

What temporary or permanent stabilization measures listed in this section are being implemented?

Paving, dense vegetation and landscaping installed prior to 2005. Paving commercial property (7/2007)

Checklist Questions:

1.) Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

2.) Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to

Yes

Create Corrective Action?

N/A

3.) Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

4.) Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

N/A

5.) Is dust associated with the construction activity adequately controlled on the site?

Create Corrective Action?

N/A

Comments:

Comments:

- 1.) Site is inactive as of the last inspection.
- 2.) Lot 1 Val Vista Replat One is under grading permit # LAV-20220831-6588-GP2 and is being inspected by HG Associates as of 12/2/2022. Lot has been closed and removed from Permix as of 5/7/24.
- 3.) Lot 5 Val Vista Replat One is under grading permit #LAV-20230926-7113-GP2 and is being inspected by Olsson as of 11/21/23.
- 4.) Lot 2 Val Vista Replat Seven has been sold as of 11/21/23. Currently no separate grading permit.
- 5.) Lot 2 Val Vista Replat One has been sold to Nacho Properties LLC as of 1/9/24. Currently no separate grading permit. An unknown builder installed a silt fence perimeter and secured a portable toilet on the lot prior to the 4/26/24 inspection.
- 6.) Remaining lots include Lot 1 Val Vista Replat Seven, Lot 6 Val Vista Replat One, Lot 7 Val Vista Replat One, and Lot 234 Val Vista.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) No maintenance is needed at this time.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance	
		N41d00m00s				
SB 7	Sediment Basin	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - 36% full - Outlet Pipe maintenance completed 5/2007 Commercial Seeding.					
		N41d00m00s				
STR	Street Cleaning	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - No major signs of track off.					
SWPPP Sign	Sign	S. 108th Street	11/7/2018	Pending	No	
Current Condition:	Pending - A SWPPP Sign will be reinstalled when construction resumes on the site.					
Certification Statement:	I certify, under penalty of lav	w, that this document ar	nd all attachments were pre	epared under my di	rection or supervision in	

accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations.

Inspector Signature:	En Carlon		Reviewed By:	Put Su
		•		