E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Engineering Answers

108th 100% 100% 100% 100% 100% 68%	Date inspected	/ista 01066	Inspection Time	Stage 3 68128 Storm Event Duration Week
100% 100% 100% 100% 100% 100% 68%	Val V NER10/ 8/10/ & Giles Road - Pap	/ista 01066 2024 iillion, NE (Sarpy County)		Storm Event Duration Week
100% 100% 100% 100% 100% 100% 68%	NER10 8/10/ 8 Giles Road - Pap Date inspected	01066 2024 iillion, NE (Sarpy County)		Storm Event Duration Week
100% 100% 100% 100% 100% 100% 68%	NER10 8/10/ 8 Giles Road - Pap Date inspected	01066 2024 iillion, NE (Sarpy County)		68128 Storm Event Duration Week
100% 100% 100% 100% 100% 100% 68%	8/10/2 & Giles Road - Pap Date inspected	2024 illion, NE (Sarpy County)		Storm Event Duration Week
100% 100% 100% 100% 100% 100% 68%	Date inspected	illion, NE (Sarpy County)		Storm Event Duration Week
100% 100% 100% 100% 100% 100% 68%	Date inspected			Storm Event Duration Week
100% 100% 100% 100% 100% 68%	Date inspected	Weather Conditions	Inspection Time	Week
100% 100% 100% 100% 68%	Date inspected	Weather Conditions	Inspection Time	Week
100% 100% 100% 68%	Date inspected	Weather Conditions	Inspection Time	Week
100% 100% 68%	Date inspected	Weather Conditions	Inspection Time	Week
100% 68%	Date inspected	Weather Conditions	Inspection Time	Week
	Date inspected	Weather Conditions	Inspection Time	Week
in tenths		Weather Conditions	Inspection Time	Week
in tenths		Weather Conditions	Inspection Time	Week
				40.55 40.55
				40.55 40.55
				40.55 40.55
				40.55 40.55
				40.55 40.55
				16:55 - 18:55
				00:15 - 13:55
				Week 2
	7/22/2024	Sunny 83/64	11:40 AM	
	7/26/2024	Sunny 91	2:12 PM	
				Week
				+
				[17:39 to 20:04]
	8/1/2024	Sunny 85	11:35 AM	
				Week 4
				+
				+
				Week
				+
				+
	l		1	

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006.

As of inspection on 3/25/09 grading was active on lot 241. As of inspection on 4/7/09 grading was completed on this section of lot 241.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006.

As of inspection on 3/25/09 grading was active on lot 241. As of inspection on 4/7/09 grading was completed on this section of lot 241.

What temporary or permanent stabilization measures listed in this section are being implemented?

Paving, dense vegetation and landscaping installed prior to 2005. Paving commercial property (7/2007)

Checklist Questions:

1.) Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

2.) Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

11//

3.) Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

IN/A

4.) Are construction entrances and adjacent streets being maintained adequately?

Yes

Create Corrective Action?

N/A

5.) Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Comments:

- 1.) Site is inactive as of the last inspection.
- 2.) Lot 1 Val Vista Replat One is under grading permit # LAV-20220831-6588-GP2 and is being inspected by HG Associates as of 12/2/2022. Lot has been closed and removed from Permix as of 5/7/24.
- 3.) Lot 5 Val Vista Replat One is under grading permit #LAV-20230926-7113-GP2 and is being inspected by Olsson as of 11/21/23.
- 4.) Lot 2 Val Vista Replat Seven has been sold as of 11/21/23. Currently no separate grading permit.
- 5.) Lot 2 Val Vista Replat One has been sold to Nacho Properties LLC as of 1/9/24. Currently no separate grading permit. An unknown builder installed a silt fence perimeter and secured a portable toilet on the lot prior to the 4/26/24 inspection.
- 6.) Remaining lots include Lot 1 Val Vista Replat Seven, Lot 6 Val Vista Replat One, Lot 7 Val Vista Replat One, and Lot 234 Val Vista.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) No maintenance is needed at this time.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance
		N41d00m00s	-		
SB 7	Sediment Basin	W96d00m00s	In Place	Active	No
Current Condition:	Good Condition - 36% full - Outlet Pipe maintenance completed 5/2007 Commercial Seeding.				
		N41d00m00s			
STR	Street Cleaning	W96d00m00s	In Place	Active	No
Current Condition:	Good Condition - No major	Good Condition - No major signs of track off.			
SWPPP Sign	Sign	S. 108th Street	11/7/2018	Pending	No
Current Condition:	Pending - A SWPPP Sign will be reinstalled when construction resumes on the site.				
Certification Statement:	I certify, under penalty of late accordance with a system of submitted. Based on my integrathering the information, the complete. I am aware that it and imprisonment for know	designed to assure that quiry of the person or pe he information submitte here are significant per	ersons who manage the sys d is, to the best of my know	y gathered and eva stem or those perso ledge and belief, tro	luated the information ns directly responsible ue, accurate, and

	Diylin Waegner
nspector Signature:	Jr Jun

Reviewed By:	Get Su