Inspector: Scott Fryant		- 2001.059.000		Stage
Project Name:		S	3	
For Week Ending:		0	68046	
or trees chally.		11/14/2009		1
Grading:		100%		
Sanitary Sewer: Storm Sewer:		100% 100%	_	
Paving:		100%		-
Seeding:		100%		
Utilities:	100%			
Overall Development:		85%		
RAIN FALL AMOUNTS	Amount in inches	Date inspected		
Sunday:	0.00"			We
Monday	0.00"			
Tuesday	0.24"			
Wednesday	0.22"			
Thursday	0.00"			
Friday	0.02"			
Saturday	0.00"			
Sunday:	0.00"			We
Vonday	0.00"			
Tuesday	0.00"			
Wednesday	0.47"			
Thursday	0.84"			
Friday	0.01"	10/23/09		
Saturday	0.06"			
Sunday:	0.01"			We
Monday	0.00"	10/26/09		
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.70"			
Friday	0.01"	10/30/09		
Saturday	0.00"			
Sunday:	0.00";0.00"	11/1/2009; None		Week
Monday	0.00";0.00"			
Tuesday	0.00";0.00"			
Wednesday	0.00";0.00"			
Thursday	0.00";0.00"			
Friday	0.00";0.00"			
Saturday	0.00";0.00"			
	None			
Complaints:				
Construction Sequencing:				
Which portion(s) (i.e. drainage basin last 14 days?	s) of the site have had a tempor	ary or permanent cessation of g	rading, earthwork, or grou	nd disturbance in th
Entire site; grading completed a	and site seeded prior to 2009	5.		
Which portion(s) (i.e. drainage basin	s) of the site do not have gradin	g, earthwork, or ground disturba	ance scheduled in the next	14 days? :
Entire site; grading completed a	and site seeded prior to 200	5.		
What temporary or permanent stabil Paving, dense vegetation and la				
5, · · · · · · · · · · · · · · · · · · ·		-		
Comments:				
Comments:				
Site is currently idle.				

			Projected Install		Maintenance	Description of
Unique Name	Туре	Location	Date	Status	Scheduled	Maintenance/Activity:
		N41d00m00s				
CE 1	Construction Entrance	W96d00m00s		Removed		Repairs Needed/Planned:
Current Condition:	Entrance paved.					
		N41d00m00s				
CE 2	Construction Entrance	W96d00m00s		Removed		
Current Condition:	Entrance paved.					
		N41d00m00s				
SB 1	Sediment Basin	W96d00m00s	In Place	Active	No	

Current Condition:	Good Condition - 30% Full							
		N41d00m00s						
SB 2	Sediment Basin	W96d00m00s		Removed				
Current Condition:	Removed							
		N41d00m00s						
SB 3	Sediment Basin	W96d00m00s		Removed				
Current Condition:	Removed December 2005 by McArdle Grading due to drainage area development.							
		N41d00m00s						
SB 4	Sediment Basin	W96d00m00s	In Place	Active	No			
Current Condition:	Good Condition - 32% Full - Permanent Basin/Pond							
		N41d00m00s						
SB 5	Sediment Basin	W96d00m00s		Removed				
Current Condition:	Removed							
		N41d00m00s						
SF 1	Silt Fence	W96d00m00s		Active				
Current Condition:	Removed; area vegetated.							
		N41d00m00s						
SF 2	Silt Fence	W96d00m00s		Active				
Current Condition:	Removed; area vegetated.	Removed; area vegetated.						
		N41d00m00s						
SF 3	Silt Fence	W96d00m00s		Removed				
Current Condition:	Removed							
		N41d00m00s						
STR	Streets	W96d00m00s	In Place	Active	No			
Current Condition:	Good Condition - No major signs of track off							
SWPPP Sign	Signs	3 Signs	8-19-08	Active	No			
Current Condition:	Good Condition -90th and Fenwick, 90th ar		Gold Coast	•				
pector Signature:	ott Fryant		Reviewed By:	Zachany K. Jil	k			