100% 100% 100% 100% 100%		Stage 3 68046
100% 100% 100% 100%	1/9/2010	3
100% 100% 100% 100%	1/9/2010	68046
100% 100% 100%		i
100% 100% 100%		
100% 100%		
100%		
100%		
100%		
85%		
Amount in inches	Date inspected	
		Week '
	12/17/09	
0.00"		
la aar	T	Week 2
0.05"		
2.00"	1	Week
	40/00/00	
	12/30/09	
0.02"		Week 4//
0.04"		Week 4 / S
		-
		-
		-
		-
		-
0.00		
None		
INOTIE		
 		
	85%	Amount in inches Date inspected 0.00" 0.04" 0.00"

Construction Sequencing:

Thich portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site; grading completed and site seeded prior to 2005.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire site; grading completed and site seeded prior to 2005.

Paving, dense vegetation and landscaping installed prior to 2005.

Comments:

Site is currently idle.

An inspection was not conducted after snow events from 12/23/09 - 12/26/09 due to very dangerous driving and winter conditions even though the perception was over a ½" due to heavy amounts of snow in the metro area. An inspection will be conducted as soon as conditions allow for each site. Please contact Zach Jilek w/ E&A Consulting Group, Inc. with any questions. (402-895-4700).

Inspections on 12/17/09 and 12/30/09 were drive thru inspection. Site was covered with over a foot of snow and all BMP's appeared to be in good working condition.

Findings / Corrective Actions (Date):

1) No required maintenance in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance Scheduled	Description of Maintenance/Activity:
		N41d00m00s		_		
CE 1	Construction Entrance	W96d00m00s		Removed	1	Repairs Needed/Plann
Current Condition:	Entrance paved.		T		1	
		N41d00m00s				
CE 2	Construction Entrance	W96d00m00s		Removed		
Current Condition:	Entrance paved.					
		N41d00m00s				
SB 1	Sediment Basin	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - 30% Full					
		N41d00m00s				
SB 2	Sediment Basin	W96d00m00s		Removed		
Current Condition:	Removed					
		N41d00m00s				
SB 3	Sediment Basin	W96d00m00s		Removed		
Current Condition:	Removed December 2005 b		e to drainage area devel	lopment.		
		N41d00m00s				
SB 4	Sediment Basin	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - 32% Full -		d			
		N41d00m00s				
SB 5	Sediment Basin	W96d00m00s		Removed		
Current Condition:	Removed					
		N41d00m00s				
SF 1	Silt Fence	W96d00m00s		Active		
Current Condition:	Removed; area vegetated.				•	
	-	N41d00m00s				
SF 2	Silt Fence	W96d00m00s		Active		
Current Condition:	Removed; area vegetated.		•		•	
		N41d00m00s				1
SF 3	Silt Fence	W96d00m00s		Removed	1	
Current Condition:	Removed				•	1
		N41d00m00s				1
STR	Streets	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - No major s	signs of track off			•	1
						1
SWPPP Sign	Signs	3 Signs	8-19-08	Active	No	
Current Condition:	Good Condition				•	1
	-90th and Fenwick, 90th and	Gold Coast, 96th and	Gold Coast			