E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com

E & A CONSULTING GROUP, INC.

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

	ΕŁ	&A - P2001.059.00	0			
In an arten Annon Tolling					Ctoro	
Inspector: Aaron Tulley			Stage 3			
Project Name:						
For Week Ending:		11/9/2019 96th and Gold Coast Road- Papillion, NE (Sarpy County)				
Project Location:	96th and	ity)	68046			
Grading:	100%				I	
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	100%					
Seeding: Utilities:	100% 100%			+	1	
Overall Development:	92%					
				1		
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions			
				<u> </u>	Week 1	
Sunday:	0.00"			1		
Monday	0.00"			+		
Tuesday Mednesday	0.00"					
Wednesday Thursday	0.00"			+		
Friday	0.00"					
Saturday	0.09"				1	
Juliu uuy	0100				Weel	
Sunday:	0.05"					
Monday	0.02"					
Гuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
					Weel	
Sunday:	0.00"					
Monday	0.04"					
Tuesday	0.00"				1	
Wednesday Thursday	0.11 " 0.00"			+	1	
Friday	0.04"			+		
Saturday	0.00"				1	
Jataraay	0.00				Wee	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"	11/07/19	Clear 34/18			
Friday	0.00"					
Saturday	0.00"					
2	lavo.				Weel	
Sunday:	N/A			1		
Monday Fuesday	N/A N/A			+		
ruesday Wednesday	N/A N/A			1		
Thursday	N/A			+		
Friday	N/A			1		
Saturday	N/A					
	•				<u>'</u>	
	None					
Complaints:						
			I	1	1	

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site; grading completed and site seeded prior to 2005.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Entire site; grading completed and site seeded prior to 2005.

What temporary or permanent stabilization measures listed in this section are being implemented?

Paving, dense vegetation and landscaping installed prior to 2005. Vacant lots 1, 2, and 3 replat 20 have been seeded (4/27/19).

Summary Questions:

Are approved entrances and adjacent streets being maintained adequately?

Yes

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Checklist Questions:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

LI

Yes

Is dust associated with the construction activity adequately controlled on the site?

Yes

Comments:

Comments:

Grading has begun for Trinity Lutheran Church on vacant Lots 1, 2, and 3 Replat 20. Project and silt fence is being inspected by TD2. E&A will continue to inspect SB 1. Grading for storm sewer in vacant Lots 1, 2, and 3 Replat 20. Trinity Lutheran Church project was active as of the last inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) No required maintenance in the BMP section.
- 2) TD2 will be informed to attempt to prevent sediment going into SB 1 as of 3/19/19. No BMPs installed or stabilization measures as of the last inspection. It appears the vacant Lots 1, 2, and 3 Replat 20 have been seeded prior to inspection on 4/27/19. E&A will continue to monitor.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance Scheduled		
		41°08'23.73"N					
SB 1	Sediment Basin	96°03'19.85"W	In Place	Active	No		
	sediment from the adjacent unstabilized Lots 1, 2, and 3 Replat 20 associated with the Trinity Lutheran Church project being managed by TD2. Due to basin being closed in the near future, E&A will not be recommending cleanout at this time. E&A will continue to monitor.						
		onitor.	n the near future, E&A will no	ot be recommending cle	eanout at this		
			n the near future, E&A will no	ot be recommending cle	eanout at this		
STR		onitor.	n the near future, E&A will no	ot be recommending cle	eanout at this		
STR Current Condition:	time. E&A will continue to me	onitor. 41°08'17.47"N 96°03'13.01"W	,				
****	time. E&A will continue to me	onitor. 41°08'17.47"N 96°03'13.01"W	,				

Inspector Signature:

Reviewed By:

Plette Sam