E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. Manager

Engineering Answers

E&A - P2017.483.001 Bill SID as of 10/27/20 P2017.483.000

Bill SID as of 10/27/20 P2017.483.000						
Inspector: Bryce Wright					Stage	
		Wind	dsor East			
		SAR-2019	1014-5177-GP1		1	
					ı ı	
Project Name:		CSW-	201904190			
For Week Ending:		1/2	22/2022		68136	
Project Location:		180th & Giles Road (NE), Sarpy County, NE				
Grading:	9	0%				
Sanitary Sewer:	9	0%				
Storm Sewer:	9	0%				
Paving:		5%				
Seeding:		5%				
Utilities:	8	5%				
Overall Development:	3	5%				
RAIN FALL AMOUNTS	Amount in tenths	I ₂		I		
RAIN FALL AMOUNTS	Amount in tentris	Date inspected	Weather Conditions	Time		
					Week '	
Sunday:	0.00"					
Monday:	0.00"					
Tuesday:	0.00"	1/18/2022	Sunny 47	11:35 AM		
Wednesday:	0.00"					
Thursday:	0.00"					
Friday:	0.00"				•	
Saturday:	0.00"					
Complaints:	None					

construction Sequencing:

Vhich portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Rough grading began in the eastern portion of the site (4/27/20). Grading began over all portions of the site (7/13/20). Grading on site has ceased due to winter conditions (2/9/21). Paving began all portions of site (4/15/21). Paving completed (6/2/21). Grading and excavation on large western slope (6/24/21). Utility installation began (9/14/21). Home excavation began (12/28/21).

Rough grading began in the eastern portion of the site (4/27/20). Grading began over all portions of the site (7/13/20). Grading on site has ceased due to winter conditions (2/9/21). Paving began all portions of site (4/15/21). Paving completed (6/2/21). Grading and excavation on large western slope (6/24/21). Utility installation began (9/14/21). Home excavation began (12/28/21).

Existing vegetation (4/27/20). EM 1, 2, 3, and 4 installed (9/22/20). Western portion of GN 9 seeded/matted along Giles Road (9/22/20)

No

No, see BMP section

No

No, see BMP and Findings section.

ste materials (concrete, construction material, hazardous, etc.) being managed properly?

N/A

No

No, See BMP section

dust associated with the construction activity adequately controlled

Yes	
Create Corrective Action?	
N/A	
Commonts	

Site was active for home construction during the most recent inspection.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):

- 1) Some maintenance is recommended in the BMP section of this report.
- 2) Areas of the site that will be inactive for 14 days or more need to be stabilized. JC Excavation/Gene Graves were informed to complete by 3/18/21. Not done as of the last inspection. JC Excavation/Gene Graves were reminded on 3/16/21, 5/20/21, 6/10/21, 7/9/21, 8/19/21, 9/16/21, 9/27/21 (Per CIR#15091), 10/20/21, 12/2/21
- Nebraska Hydroseeding was met on site on 7/22/21 to plan for seeding of entire site. Western portion of the site is ready for seeding. Rest of site still
- needs approval to start from Caleb B. of E&A. Nebraska Hydroseeding completed mowing on site on 7/28/21.

 3) SF-1 for SAR-20200507-5452-GP2 (Giles Road/180th Street Improvements) was installed along the east side of EM 3 prior to the 8/2/21 inspection. The SF will not be included in this report and is part of the road improvement project. The SF has been marked on the SWPPP map to indicate its location within

	Туре	Location	Projected Install Date	Status	Maintenan
CE 1	Construction Entrance	Giles Road (Q14)		Removed	
Current Condition:	Removed - Hawkins Cons	struction paved the entra	ance prior to the inspection or	9/8/21.	
CE 2	Construction Entrance	Giles Road (BB14)		Removed	
Current Condition:	Removed - Hawkins Cons	struction paved the entra	ance prior to the inspection or	9/8/21.	I
D 1	Diversion	E of SB A	9/22/2020	Active	Yes
Current Condition:	Fair Condition - JC Excav	ation installed the divers	sion prior to the 9/22/20 inspe	ction.	
	2.) The diversion needs to1.) JC Excavation was infewere reminded on 1/13/2*2.) JC Excavation/Gene G	ormed to complete by 10 1, 3/5/21, 3/16/21, 4/23/2 Graves were informed to	ven over when work allows. d in multiple locations. 0/13/20. Not done as of the la 21, 5/20/21, 6/10/21, 7/9/21, 8 complete by 3/11/21. Not dor (21, 4/23/21, 5/20/21, 6/10/21)	1/19/21, 9/16/21, 10/2 The as of the last inspe	0/21, 12/2/21 ection. JC
D 2	Diversion	SE of SB A	9/22/2020	Active	Yes
Current Condition:			he diversion prior to the 8/10/2		cavation installed t
			mplete by 3/11/21. Not done a 21, 6/10/21, 7/9/21, 8/19/21, 9		
D 3 Current Condition:	the need of additional dive	ersions from GN 8. The	9/22/2020 here possible prior to the 9/22 diversion was removed prior		
	Pending - JC Excavation the need of additional diversion/swale need JC Excavation was inform	installed the diversion wersions from GN 8. The less to be reinstalled when the to complete by 10/13	here possible prior to the 9/22 diversion was removed prior works allows. 3/20. Not done as of the last	2/20 inspection, the into the 10/7/20 inspection. JC Excav	spector will monitorion. ation/Gene Grave
Current Condition: D 4	Pending - JC Excavation the need of additional diversion/swale need JC Excavation was information the diversion of 1/13/21, 3/5/Diversion	installed the diversion wersions from GN 8. The stobe reinstalled when need to complete by 10/13/21, 3/16/21, 4/23/21, 5/3 W of SB A	here possible prior to the 9/22 diversion was removed prior works allows. 3/20. Not done as of the last 20/21, 6/10/21, 7/9/21, 8/19/2 9/22/2020	2/20 inspection, the into the 10/7/20 inspection. JC Excavinspection. JC Excavinspection. JC Excaving / 1, 9/16/21, 10/20/21, Active	spector will monitorion. ation/Gene Grave 12/2/21 Yes
Current Condition:	Pending - JC Excavation the need of additional diversion/swale need JC Excavation was inform reminded on 1/13/21, 3/5/Diversion Fair Condition - JC Excava section of the diversion diversion was partially renumber the roadway work is Hawkins will be informed	installed the diversion wersions from GN 8. The sto be reinstalled when the sto be reinstalled when the sto complete by 10/13/21, 3/16/21, 4/23/21, 5/2 W of SB A ration installed the easte pes not appear necessal moved as part of SAR-20/20 edefined when work allowed as complete.	here possible prior to the 9/22 diversion was removed prior works allows. 3/20. Not done as of the last i 20/21, 6/10/21, 7/9/21, 8/19/2	inspection, the into the 10/7/20 inspection. JC Excav. 1, 9/16/21, 10/20/21, Active or to the 9/22/20 inspector will country the inspector will country the inspector will make spector will mak	ration/Gene Grave 12/2/21 Yes ection. The weste intinue to monitor.
Current Condition: D 4 Current Condition:	Pending - JC Excavation the need of additional diversion/swale need JC Excavation was information of the diversion was information of the diversion of the diversion of the diversion was partially renumber o	installed the diversion wersions from GN 8. The stobe reinstalled when the document of the stobe reinstalled when the document of the stobe reinstalled when the document of the stobe reinstalled the easten oved as part of SAR-20 edefined when work allows complete.	here possible prior to the 9/22 diversion was removed prior works allows. 3/20. Not done as of the last 20/21, 6/10/21, 7/9/21, 8/19/2 9/22/2020 rn section of the diversion prior y as of the 9/22/20 inspectior 2000507-5452-GP2 for the 18 was in applicable areas. The inspection of the diversion prior 2000507-5452-GP2 for the 18 was in applicable areas.	inspection. JC Excavante in Market i	ration/Gene Grave 12/2/21 Yes ection. The weste intinue to monitor.
Current Condition: D 4	Pending - JC Excavation the need of additional diversion/swale need JC Excavation was information in the diversion was information in the diversion of the diversion of the diversion was partially rendered in the readway work is the diversion was partially rendered inspection.	installed the diversion wersions from GN 8. The sto be reinstalled when need to complete by 10/13/21, 3/16/21, 4/23/21, 5/3 W of SB A ation installed the easted be not appear necessal noved as part of SAR-20 edefined when work allows complete.	here possible prior to the 9/22 diversion was removed prior works allows. 3/20. Not done as of the last 20/21, 6/10/21, 7/9/21, 8/19/2 9/22/2020 rn section of the diversion prior y as of the 9/22/20 inspectior 2000507-5452-GP2 for the 18 was in applicable areas. The inspection of the diversion prior 2000507-5452-GP2 for the 18 was in applicable areas.	inspection, the into the 10/7/20 inspection. JC Excav. 1, 9/16/21, 10/20/21, Active or to the 9/22/20 inspect, the inspector will color St. improvements inspector will make sp. 8/2/21 inspection. No	ration/Gene Grave 12/2/21 Yes ection. The weste ontinue to monitor. Secific recommence of done as of the la
D 4 Current Condition:	Pending - JC Excavation the need of additional diversion/swale need JC Excavation was inform reminded on 1/13/21, 3/5/Diversion Fair Condition - JC Excavation was partially reminded on the diversion of the diversion of diversion was partially reminded inspection. Diversion Removed - Due to the control Terrace	installed the diversion wersions from GN 8. The sto be reinstalled when the sto be reinstalled when the sto complete by 10/13/21, 3/16/21, 4/23/21, 5/10 W of SB A reation installed the eastences not appear necessan to appear necessan to appear necessan to appear necessan to complete. It is complete when work allows complete when the reating to see SWPPP Map	here possible prior to the 9/22 diversion was removed prior works allows. 3/20. Not done as of the last to 20/21, 6/10/21, 7/9/21, 8/19/2 9/22/2020 rn section of the diversion prior as of the 9/22/20 inspection 200507-5452-GP2 for the 18 was in applicable areas. The interaction of the diversion prior as of the 9/22/20 inspection 200507-5452-GP2 for the 18 was in applicable areas. The interaction of the 18/2/21 development as of the 8/2/21	inspection, the into the 10/7/20 inspection. JC Excaval, 9/16/21, 10/20/21, Active or to the 9/22/20 inspection, the inspector will color St. improvements inspector will make spector will make	ration/Gene Grave 12/2/21 Yes ection. The weste intinue to monitor. Secific recommend of done as of the la
D 4 Current Condition: D 5 Current Condition:	Pending - JC Excavation the need of additional diversion/swale need JC Excavation was inform reminded on 1/13/21, 3/5/Diversion Fair Condition - JC Excavation was partially reminded on the diversion of the diversion of diversion was partially reminded inspection. Diversion Removed - Due to the control Terrace	installed the diversion wersions from GN 8. The sto be reinstalled when the sto be reinstalled when the sto complete by 10/13/21, 3/16/21, 4/23/21, 5/10 W of SB A reation installed the eastences not appear necessan to appear necessan to appear necessan to appear necessan to complete. It is complete when work allows complete when the reating to see SWPPP Map	here possible prior to the 9/22 diversion was removed prior works allows. 3/20. Not done as of the last is 20/21, 6/10/21, 7/9/21, 8/19/2 9/22/2020 rn section of the diversion prior yas of the 9/22/20 inspection 2000507-5452-GP2 for the 18 lows in applicable areas. The interaction of the diversion prior and the section of the section	inspection, the into the 10/7/20 inspection. JC Excaval, 9/16/21, 10/20/21, Active or to the 9/22/20 inspection, the inspector will color St. improvements inspector will make spector will make	ration/Gene Grave 12/2/21 Yes ection. The weste intinue to monitor. Secific recommend of done as of the la
D 4 Current Condition: D 5 Current Condition: ET 1	Pending - JC Excavation the need of additional diversion/swale need JC Excavation was informed and 1/13/21, 3/5/Diversion Fair Condition - JC Excavasection of the diversion diversion was partially renumber of the diversion when the roadway work is Hawkins will be informed inspection. Diversion Removed - Due to the control Terrace Removed - Due to the control Control Matting	installed the diversion wersions from GN 8. The sto be reinstalled when need to complete by 10/13 (21, 3/16/21, 4/23/21, 5/2). Wo of SB A action installed the easte personate appear necessal anoved as part of SAR-20 edefined when work allows complete. East side of site impletion of primary civil See SWPPP Map	here possible prior to the 9/22 diversion was removed prior works allows. 3/20. Not done as of the last to 20/21, 6/10/21, 7/9/21, 8/19/2 9/22/2020 rn section of the diversion prior as of the 9/22/20 inspection 200507-5452-GP2 for the 18 was in applicable areas. The interaction of the diversion prior as of the 9/22/20 inspection 200507-5452-GP2 for the 18 was in applicable areas. The interaction of the 18/2/21 development as of the 8/2/21	Inspection, the into the 10/7/20 inspection. JC Excavent 1, 9/16/21, 10/20/21, Active for to the 9/22/20 inspection, the inspector will country to the section of the section. Not the section of the section of the diversity of the section, the terrace of the section of the sec	spector will monitorition. ration/Gene Grave 12/2/21 Yes ection. The westerntinue to monitor. S. pecific recommendate done as of the label sion will not be install the will

	Te : a : 114 I	0 00000000	0/00/0000		
EM 2	Erosion Control Matting	See SWPPP Map	9/22/2020	Pending	Yes Yes
Current Condition:	O .	stalled the matting prio	r to the 9/22/20 inspection. T	ne matting was remov	ed prior to the 10/7/20
	inspection.				
	The seeding/matting needs	to be reinstalled with t	he diversion.		
			/20. Not done as of the last i		
		1, 3/16/21, 4/23/21, 5/2	20/21, 6/10/21, 7/9/21, 8/19/2	1, 9/16/21, 9/27/21 (Pe	er CIR#15091),
514.0	10/20/21, 12/2/21	0 014/000 14	0/00/0000	A 11	
EM 3	Erosion Control Matting	See SWPPP Map	9/22/2020	Active	Yes
Current Condition:			g prior to the 9/22/20 inspect		
			wkins installed silt fence at th	ie base of the hill wher	e matting was removed
	prior to the inspection on 7/	27/21 (see findings sec	ction).		
	Matting should be reinstalle	ed where removed from	storm installation.		
			one as of the last inspection.		
	be contacted when info is for	ound on their project. M	litch C. of E&A contacted Ha	wkins and informed the	em of the maintenance
	on 7/22/21. As of the 8/2/2	1 inspection, maintena	nce will be completed as part	t of SAR-20200507-54	52-GP2.
EM 4	Erosion Control Matting	See SWPPP Map	9/22/2020	Active	No
Current Condition:			ing prior to the 9/22/20 inspe		
EM 5	Erosion Control Matting	See SWPPP Map		Removed	
Current Condition:			ppear to be necessary as of		I
FT 1	Fuel Tank	On Site	spear to be more and a cr	Removed	
Current Condition:			e prior to the 10/28/20 inspec		
FT 2	Fuel Tank	On Site	5 prior to the 10/20/20 mopos	Removed	
Current Condition:			site prior to the 11/4/20 inspe		
FT 3	Fuel Tank	Adjacent to CE 1	3.00 p. 101 to 1.10 1.17 1/20 11.10 p.	Removed	
Current Condition:			ank prior to the inspection on		L
FT 4	Fuel Tank	western section of site		Removed	
Current Condition:	Removed - Swain construc	tion removed the fuel to	ank prior to the inspection on	6/29/21.	
Lot 68 - 69	Individual Lot	Lot 68 - 69	12/21/2021	Active	No
Current Condition:	Active - Legacy Homes beg	gan excavation on the le	ot prior to the inspection on 1	2/21/21. A dirt pile was	s observed in the ROW
	but due to the lot being acti	vely excavated no reco	mmendations will be made a	t this time. The E&A ir	spector will continue to
	monitor for dirt pile remova	l and BMP installation.		110	
Lot 70 - 71	Individual Lot	Lot 70 - 71	12/28/2021	Active	No
Current Condition:	Active - Legacy Homes beg	gan excavation on the le	ot prior to the inspection on 1	2/28/21. A dirt pile was	s observed in the ROW
	but due to the lot being acti	vely excavated no reco	mmendations will be made a	t this time. The E&A ir	spector will continue to
	monitor for dirt pile remova	l and BMP installation.			•
Lot 72 - 73	Individual Lot	Lot 72 - 73	12/28/2021	Active	No
Current Condition:	Active - Legacy Homes beg	gan excavation on the le	ot prior to the inspection on 1	2/28/21. A dirt pile was	s observed in the ROW
	but due to the lot being acti	vely excavated no reco	mmendations will be made a	t this time. The E&A ir	spector will continue to
	monitor for dirt pile remova	and BMP installation.			
Lot 74 - 75	Individual Lot	Lot 74 - 75	12/28/2021	Active	No
Current Condition:	Active - Legacy Homes beg	an excavation on the le	ot prior to the inspection on 1	2/28/21. A dirt pile was	s observed in the ROW
	but due to the lot being acti	velv excavated no reco	mmendations will be made a	t this time. The E&A ir	spector will continue to
	monitor for dirt pile remova				
Lot 76 - 77	Individual Lot	Lot 76 - 77	1/4/2022	Active	No
Current Condition:	Active - Legacy Homes bed	an excavation on the lo	ot prior to the inspection on 1	/4/22. A dirt pile was o	bserved in the ROW but
			endations will be made at thi	·	
	monitor for dirt pile remova				
MS 1	Material Storage	On Site		Removed	
Current Condition:			as of the 8/2/21 inspection.		e is attributed to
	SAR20200507-5452-GP2		•	2.3.090 0.1 010	
PB X	Portable Bathroom	On Site		Removed	
Current Condition:			te under Windsor East. Both		Her the Giles Road and
Current Condition:	180th street project as of 6	•	io unuci vviilusui Last. DUIII	portable tollets are unit	aci ale Olles Noau allu
			10/05/		,
SB A	Sediment Basin	04	10/20/2020	Active	No
Current Condition:			y dug out prior to the 6/10/20		
	the baffle installed by JC Excavation prior to the 9/22/20 inspection. JC Excavation finished installed the riser prior to the				
	10/20/20 inspection. The E&A inspector painted the cleanout mark on the riser during the 11/4/20 inspection. Minor erosion				
		•	21 inspection. Damage to the	baffle was observed of	n 6/2/21. No
	recommendations at this tir			_	
SF 1	Silt fence	S6-X7	5/6/2020	Active	Yes

Current Condition:	Fair Condition - JC Excavation installed the silt fence prior to the 5/6/20 inspection. The SB A berm is built up adjacent to the drainage ditch as of the 6/19/20 inspection, extending the silt fence is no longer recommended. JC Excavation partially cleaned out, trenched in, and repaired the silt fence prior to the 7/6/20 inspection, further maintenance is recommended. JC Excavation cleaned out and repaired the silt fence at V7 prior to the 7/13/20 inspection. The silt fence was partially removed at T6 for utility work prior to the 9/22/20 inspection, the inspector will recommend reinstallation when work in the area is complete. JC Excavation patched some of the silt fence prior to the 10/9/20 inspection. 1.) The silt fence should be extended around the disturbance behind the basin until the area is stabilized. 2.) Silt fence needs to be reinstalled where removed for infrastructure work. 1.) JC Excavation was informed to complete by 8/25/20. Not done as of the last inspection. JC Excavation/Gene Graves were reminded on 9/11/20, 10/9/20, 1/13/21, 3/5/21, 3/16/21, 4/23/21, 5/20/21, 6/10/21, 7/9/21, 8/19/21, 9/16/21, 10/20/21, 12/2/21 2.) JC Excavation/Gene Graves were informed to complete by 3/11/21. Not done as of the last inspection. JC				
SF 2	Excavation/Gene Graves were reminded on 3/16/21, 4/23/21, 5/20/21, 6/10/21, 7/9/21, 8/19/21, 9/16/21, 10/20/21, 12/2/21 Silt fence D13-D7-J4 5/6/2020 Active Yes				
Current Condition:	Fair Condition - JC Excavation installed the silt fence prior to the 5/6/20 inspection. Hawkins Construction removed a section				
	of the silt fence north of EM 4 prior to the inspection on 8/9/21. Due to vegetation in the area reinstallation will not be recommended at this time. E&A inspector will continue to monitor. 1.) The silt fence is undermined in multiple locations and needs to be backfilled and trenched in. 2.) The silt fence is down in multiple locations and needs repaired/retied. 3.) The silt fence is full west of SB A and needs to be cleaned out. 4.) The silt fence in the northwest corner of the site needs to be repaired/cleaned out and fugitive sediment needs to be				
	cleaned up. 5.) The silt fence on the west side of the run should be repaired/cleaned out and fugitive sediment needs to be cleaned up.				
	1.) JC Excavation was informed to complete by 5/13/20. Not done as of the last inspection. JC Excavation/Gene Graves were reminded on 5/19/20, 5/28/20, 8/6/20, 8/19/20, 9/11/20, 10/9/20, 1/13/21, 3/5/21, 3/16/21, 4/23/21, 5/20/21, 6/10/21, 7/9/21, 8/19/21, 9/16/21, 10/20/21, 12/2/21				
	2.) JC Excavation was informed to complete by 8/10/20. Not done as of the last inspection. JC Excavation/Gene Graves were reminded on 8/12/20, 8/19/20, 9/11/20, 10/9/20, 1/13/21, 3/5/21, 3/16/21, 4/23/21, 5/20/21, 6/10/21, 7/9/21, 8/19/21, 9/16/21, 10/20/21, 12/2/21				
	3.) JC Excavation was informed to complete by 8/10/20. Not done as of the last inspection. JC Excavation/Gene Graves were reminded on 8/12/20, 8/19/20, 9/11/20, 10/9/20, 1/13/21, 3/5/21, 3/16/21, 4/23/21, 5/20/21, 6/10/21, 7/9/21, 8/19/21, 9/16/21, 10/20/21, 12/2/21 4.) JC Excavation/Gene Graves were informed to complete by 3/22/21. Not done as of the last inspection. JC Excavation/Gene Graves was reminded on 4/23/21, 5/20/21, 6/10/21, 7/9/21, 8/19/21, 9/16/21, 10/20/21, 12/2/21				
	5.) JC Excavation/Gene Graves were informed to complete by 8/24/21. Not done as of the last inspection. JC				
SF 3	Excavation/Gene Graves was reminded on 9/16/21, 10/20/21, 12/2/21 Silt fence CC9-X7 5/6/2020 Active Yes				
Current Condition:	Fair Condition - JC Excavation installed the silt fence prior to the 5/6/20 inspection. The silt fence was partially cleaned out prior to the 3/31/21 inspection. The remaining accumulated sediment along the silt fence needs to be removed to allow water to filter through the silt fence. The maintenance recommendation will remain until proper maintenance is completed. Minor damage was observed to the south end of the silt fence run during the 4/15/21 inspection, no maintenance is required at this time, the inspector will monitor. 1.) The silt fence needs to be cleaned out where full. 2.) Erosion outside of the silt fence should be repaired where silt fence is full. 3.) The silt fence should be repaired on the east side of the run. 1.) JC was informed to complete by 9/16/20. Not done as of the last inspection. JC Excavation/Gene Graves were reminded on 10/9/20, 1/13/21, 3/5/21, 3/16/21, 4/23/21, 5/20/21, 6/10/21, 7/9/21, 8/19/21, 9/16/21, 10/20/21, 12/2/21 2.) JC was informed to complete by 8/24/21. Not done as of the last inspection. JC Excavation/Gene Graves was reminded on 9/16/21, 10/20/21, 12/2/21 3.) JC was informed to complete by 10/26/21. Not done as of the last inspection. JC Excavation/Gene Graves was reminded Streets Giles Road 4/27/2020 Active Yes				
Current Condition:	Fair Condition - No sign of track out Per CIR #15091 all interior streets should be cleaned. JC Excavation/Gene Graves was informed to complete by 10/4/21. Not done as of the last inspection. JC Excavation/Gene Graves was reminded on 10/20/21, 12/2/21				
SWPPP Sign	Misc./Other Giles Road 7/13/2020 Pending No				
Current Condition:	Good Condition - E&A inspector installed the SWPPP sign at Q13 during the 7/13/20 inspection. The E&A inspector reinstalled the SWPPP sign at Q13 during the 10/28/20 inspection. SWPPP sign was removed by unknown source prior to the inspection on 6/15/21. E&A inspector reinstalled the SWPPP sign on 8/20/21.				
WO 1	Concrete Washout On Site Removed				
Current Condition:	Removed - Swain Construction removed the washout prior to the inspection on 5/25/21.				
WO 2	Concrete Washout On Site Removed				
Current Condition:	Removed - Swain Construction removed the washout prior to the inspection on 6/8/21.				
WS 1	Waste Storage On Site Removed				
Current Condition:	Removed - Primary civil development is complete as of the 8/2/21 inspection, the inspector will monitor waste storage on a lot by lot basis.				

Certification Statement:	direction or supervision in properly gathered and eva persons who manage the the information submitted	aw, that this document and all attachments were prepaccordance with a system designed to assure that queliated the information submitted. Based on my inquing system or those persons directly responsible for gathers, to the best of my knowledge and belief, true, accur gnificant penalties for submitting false information incommon for knowing violations."	palified personnel y of the person or ering the information, rate, and complete. I	
Inspector Signature:	Brya M Zhapht		Reviewed By:	But Sul