E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402A6863:F7009.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Environmental Services Dept	. Manager			Lingineering	Answers
		E&A - P2017	.483.002		
		Bill SID - P20	17.483.010		
Inspector: Bryce Wright			or West		Stage
		GRE-201908	812-5114-GP1		1
Project Name:		CSW-20	01903993		
		68136			
For Week Ending:		00130			
Project Location:		Touth & Glies Road (SW), Sarpy County, NE		
Grading:	90%	[1	1	
Sanitary Sewer:	75%				
Storm Sewer:	75%				
Paving:	70%				
Seeding: Utilities:	75% 60%				
Overall Development:	30%				
	0070				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time
					Week 1
Sunday:	0.06"				HCCK
Monday:	0.05"		1		
Tuesday:	0.13"				
Wednesday:	0.00"	7/19/2023	Sunny 80	12:40 PM	
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.19"				
Complaints: Construction Sequencing: Which portion(s) (i.e. drainage basis	rs) of the site have had a tempo	rary or permanent cessatio	n of grading, earthwork, or ground	disturbance in the last 14	days?
Rough grading began in draina Grading on site has ceased due Paving began on site (9/21/21). (2/22/23). All grading on site ce Which portion(s) (i.e. drainage basin Rough grading began in draina Grading on site has ceased due Paving began on site (9/21/21).	e to winter conditions (2/9/21 Grading in the southern sea ased (3/8/23). Sidewalk pav hs) of the site do not have grading ge area DEV C (7/28/20). G e to winter conditions (2/9/21	 Grading resumed in ction began (11/30/21). ring on all interior streets ng, earthwork, or ground di rading began in drainag Grading resumed in 	all drainage areas (4/5/21). St Grading in southern section re s (3/15/23). sturbance scheduled in the next 1 e area DEV C and DEV B (8/3 all drainage areas (4/5/21). St	orm and sanitary began sumed (06/01/22). Elec 4 days? V/20). Grading began in orm and sanitary began	installation (7/26/21). tric installation began DEV A (10/28/20). installation (7/26/21).
(2/22/23). All grading on site ce	. ,	0	× ,		
What temporary or permanent stabi					
Existing vegetation (7/28/20). E site was beginning to be seede					oueet (12/20/21). Enure
Checklist Questioner					
Checklist Questions: Are receiving waters adjacent to the	project free of any significant s	signs of erosion or sedimen	t that would be associated with th	e construction activity?	
No	joet nee et any eighneant e				
Create Corrective Action?					
No, See BMP section					
Have disturbed areas been seeded areas	or otherwise stabilized as requir	ed? List inactive portions o	of the project and if stabilization m	easure are adequate or nee	ded to prevent erosion.
Create Corrective Action?					
N/A					
Ann ann an A	Amonthe a manufacture of the second second		<u></u>		
Are waste materials (concrete, cons Yes	struction material, hazardous, et	c.) being managed properly	14		
Create Corrective Action?					
N/A					

Are construction entrances and adjacent streets being maintained adequately?	
No	
Create Corrective Action?	
No, See BMP section	
Is dust associated with the construction activity adequately controlled on the site?	
Yes	
Create Corrective Action?	
N/A	
Comments:	
Comments:	
Site was in active during the current inspection.	

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):

Some maintenance is required in the BMP section of this report.
 SF-1 for SAR-20200507-5452-GP2 (Giles Road/180th Street Improvements) was installed along Giles Road on the west end of the site prior to the 8/9/21

inspection. The SF will not be included in this report and is part of the road improvement project. The SF has been marked on the SWPPP map to indicate its location within the temporary road project. Also applies to silt fence east of river on north side of Giles Rd and the fuel tank located near CE 1. The fuel tank was removed prior to the inspection on 9/19/22. Silt fence checks were installed as part of the road project along Giles Rd. prior to the inspection on 9/19/22.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
CE 1	Construction Entrance	Giles Road (BB3)		Removed	
Current Condition:	Removed - Hawkins Const	truction paved the Const	ruction entrance prior to the ins	spection on 5/3/23.	
CE 2	Construction Entrance	180th Street (DD9)		Removed	
Current Condition:	Removed - All entrances a	. ,	e of the site as of 5/18/22	rtoniovou	
		•	I	Demond	
CE 3 Current Condition:	Construction Entrance	L3		Removed	
Current Condition.		Construction entrance w	struction entrance, graded the ill not be recommended to be r		
D 1	Diversion	N17-E17	8/14/2020	Active	No
Current Condition:	Good Condition - Gene Gr	aves installed the diversi	on prior to the 7/18/22 inspecti	on.	
D 2	Diversion	N17-U17	8/14/2020	Active	No
Current Condition:	Good Condition - Gene Gr	aves installed the diversi	on prior to the 7/13/22 inspecti	on.	
D 3	Diversion	West of SB A	1/13/2021	Active	No
Current Condition:			the 1/13/21 inspection. JC pa		
	4/5/21 inspection, the inspe	ector will monitor as the	diversion is redefined. JC Exca	avation/Gene Graves re	einstalled the divers
D 4	Diversion	East of SB A	10/13/2022	Active	No
Current Condition:	Good Condition - Gene Gr	aves reinstalled the dive	rsion prior to the inspection on	10/13/22. An unknowr	n contractor remove
			Graves reinstalled the diversio		
D 5	Diversion	West of SB B	10/13/2022	Active	No
Current Condition:			rsion prior to the inspection on Graves reinstalled the diversion		
D 6	Diversion	SW of SB C		Removed	
Current Condition:			as of the 10/6/2020 revision.		
D 7	Diversion	S of SB A		Removed	
	Diversion	S of SB A	as of the 10/6/2020 revision. ated the diversion is no longer	Removed	26/22 inspection.
D 7	Diversion	S of SB A		Removed	26/22 inspection.
D 7 Current Condition:	Diversion Removed - Due to paving	S of SB A and the site being vegeta M25-N17	ated the diversion is no longer	Removed necessary as of the 7/2	
D 7 Current Condition: D 8	Diversion Removed - Due to paving a Diversion	S of SB A and the site being vegeta M25-N17	ated the diversion is no longer	Removed necessary as of the 7/2	
D 7 Current Condition: D 8 Current Condition:	Diversion Removed - Due to paving a Diversion Good Condition - JC instal Diversion	S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B	ated the diversion is no longer	Removed necessary as of the 7/2 Active Removed	No
D 7 Current Condition: D 8 Current Condition: D 9	Diversion Removed - Due to paving - Diversion Good Condition - JC instal Diversion Removed - Due to paving - Diversion Diversion Diversion Diversion Diversion Diversion Diversion Diversion	S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9	ated the diversion is no longer 1/20/2021 the 7/26/22 inspection. ated the diversion is no longer	Removed necessary as of the 7/2 Active Removed necessary as of the 7/2 Removed	No
D 7 Current Condition: D 8 Current Condition: D 9 Current Condition:	Diversion Removed - Due to paving - Diversion Good Condition - JC instal Diversion Removed - Due to paving - Diversion Removed - Due to paving - Diversion Removed - D10 has been	S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPF	1/20/2021 the 7/26/22 inspection.	Removed necessary as of the 7/2 Active Removed necessary as of the 7/2 Removed	No
D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition: D 11	Diversion Removed - Due to paving - Diversion Good Condition - JC instal Diversion Removed - Due to paving - Diversion Removed - D10 has been Diversion	S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPF S of SB C	ted the diversion is no longer 1/20/2021 the 7/26/22 inspection. ted the diversion is no longer PP as of the 10/6/2020 revision	Removed necessary as of the 7/2 Active Removed necessary as of the 7/2 Removed Removed Removed	No
D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition: D 11 Current Condition:	Diversion Removed - Due to paving Diversion Good Condition - JC instal Diversion Removed - Due to paving : Diversion Removed - D10 has been Diversion Removed - D11 has been	S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPF S of SB C removed from the SWPF	ated the diversion is no longer 1/20/2021 the 7/26/22 inspection. ated the diversion is no longer	Removed necessary as of the 7/2 Active Removed necessary as of the 7/2 Removed Removed Removed	No
D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition: D 11 Current Condition: D 12	Diversion Removed - Due to paving a Diversion Good Condition - JC instal Diversion Removed - Due to paving a Diversion Removed - D10 has been Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - D11 has been Diversion	S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPF S of SB C removed from the SWPF E of SB B	1/20/2021 the diversion is no longer 1/20/2021 the 7/26/22 inspection. 1 ted the diversion is no longer PP as of the 10/6/2020 revision PP as of the 10/6/2020 revision	Removed necessary as of the 7/2 Active Removed necessary as of the 7/2 Removed Removed Removed Removed Removed	No
D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition: D 11 Current Condition: D 12 Current Condition:	Diversion Removed - Due to paving a Diversion Good Condition - JC instal Diversion Removed - Due to paving a Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - D11 has been Diversion Removed - Gene Graves r	S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPF S of SB C removed from the SWPF E of SB B emoved the diversion for	ted the diversion is no longer 1/20/2021 the 7/26/22 inspection. ted the diversion is no longer PP as of the 10/6/2020 revision	Removed necessary as of the 7/2 Active Removed necessary as of the 7/2 Removed Removed Removed Removed Removed Removed Spection.	No
D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition: D 11 Current Condition: D 12 Current Condition: ET 1	Diversion Removed - Due to paving - Diversion Good Condition - JC instal Diversion Removed - Due to paving - Diversion Removed - Due to paving - Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - Gene Graves r Erosion Control Terrace	S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPF S of SB C removed from the SWPF E of SB B emoved the diversion for See SWPPP Map	1/20/2021 the diversion is no longer 1/26/22 inspection. ated the diversion is no longer P as of the 10/6/2020 revision P as of the 10/6/2020 revision	Removed necessary as of the 7/2 Active Removed necessary as of the 7/2 Removed Removed Removed Removed Removed	No
D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition: D 11 Current Condition: D 12 Current Condition:	Diversion Removed - Due to paving a Diversion Good Condition - JC instal Diversion Removed - Due to paving a Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - D11 has been Diversion Removed - Gene Graves r	S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPF S of SB C removed from the SWPF E of SB B emoved the diversion for See SWPPP Map	1/20/2021 the diversion is no longer 1/26/22 inspection. ated the diversion is no longer P as of the 10/6/2020 revision P as of the 10/6/2020 revision	Removed necessary as of the 7/2 Active Removed necessary as of the 7/2 Removed Removed Removed Removed Removed Removed Spection.	No
D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition: D 11 Current Condition: D 12 Current Condition: ET 1	Diversion Removed - Due to paving - Diversion Good Condition - JC instal Diversion Removed - Due to paving - Diversion Removed - Due to paving - Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - Gene Graves r Erosion Control Terrace	S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPF S of SB C removed from the SWPF E of SB B emoved the diversion for See SWPPP Map	1/20/2021 the diversion is no longer 1/26/22 inspection. ated the diversion is no longer P as of the 10/6/2020 revision P as of the 10/6/2020 revision	Removed necessary as of the 7/2 Active Removed necessary as of the 7/2 Removed Removed Removed Removed Removed Removed Spection.	No
D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition: D 11 Current Condition: D 12 Current Condition: ET 1 Current Condition: ET 2 Current Condition:	Diversion Removed - Due to paving a Diversion Good Condition - JC instal Diversion Removed - Due to paving a Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - Gene Graves r Erosion Control Terrace Removed - Due to paving a Erosion Control Terrace Removed - Due to paving a	S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPF S of SB C removed from the SWPF E of SB B emoved the diversion for See SWPPP Map the terrace is no longer r See SWPPP Map		Removed necessary as of the 7/2 Active Removed necessary as of the 7/2 Removed Removed Removed Removed Removed	No
D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition: D 11 Current Condition: D 12 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 2 Current Condition:	Diversion Removed - Due to paving a Diversion Good Condition - JC instal Diversion Removed - Due to paving a Diversion Removed - Due to paving a Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - Gene Graves r Frosion Control Terrace Removed - Due to paving a Erosion Control Terrace Removed - Due to paving a Erosion Control Terrace Removed - Due to paving a	S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPF S of SB C removed from the SWPF E of SB B emoved the diversion for See SWPPP Map the terrace is no longer r See SWPPP Map the terrace is no longer r		Removed necessary as of the 7/2 Active Removed necessary as of the 7/2 Removed necessary as of the 7/2	No
D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition: D 11 Current Condition: D 12 Current Condition: ET 1 Current Condition: ET 2 Current Condition:	Diversion Removed - Due to paving a Diversion Good Condition - JC instal Diversion Removed - Due to paving a Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - Gene Graves r Erosion Control Terrace Removed - Due to paving a Erosion Control Terrace Removed - Due to paving a	S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPF S of SB C removed from the SWPF E of SB B emoved the diversion for See SWPPP Map the terrace is no longer r See SWPPP Map the terrace is no longer r		Removed necessary as of the 7/2 Active Removed necessary as of the 7/2 Removed Removed Removed Removed Removed	No N
D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition: D 11 Current Condition: D 12 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 2 Current Condition:	Diversion Removed - Due to paving a Diversion Good Condition - JC instal Diversion Removed - Due to paving a Diversion Removed - Due to paving a Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - Gene Graves r Frosion Control Terrace Removed - Due to paving a Erosion Control Terrace Removed - Due to paving a Erosion Control Terrace Removed - Due to paving a	S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPF S of SB C removed from the SWPF E of SB B emoved the diversion for See SWPPP Map the terrace is no longer r See SWPPP Map the terrace is no longer r		Removed necessary as of the 7/2 Active Removed necessary as of the 7/2 Removed Removed Removed Removed Removed	No N
D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition: D 11 Current Condition: D 12 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 2 Current Condition: ET 3 Current Condition:	Diversion Removed - Due to paving a Diversion Good Condition - JC instal Diversion Removed - Due to paving a Diversion Removed - Due to paving a Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - Gene Graves r Frosion Control Terrace Removed - Due to paving a Erosion Control Terrace Removed - Due to paving a Erosion Control Terrace Good Condition - JC instal Erosion Control Terrace Good Condition - JC instal	S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPF S of SB C removed from the SWPF E of SB B emoved the diversion for See SWPPP Map the terrace is no longer r See SWPPP Map the terrace prior to th See SWPPP Map		Removed necessary as of the 7/2 Active Removed necessary as of the 7/2 Removed necessary as of the 7/2 Removed necessary as of the 7/2 Removed Removed Removed Removed Removed Active Pending	No 26/22 inspection.

Current Condition:	Pending - The erosion con				
EM 3	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No
Current Condition:	Pending - The erosion con	trol matting will be install	ed within the seeding window	when the associated a	rea reaches final g
EM 4	Erosion Control Matting	See SWPPP Map	3/5/2021	Pendina	No
Current Condition:			ed within the seeding window		
EM 5	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No
Current Condition:	Pending - The erosion con	trol matting will be install	ed within the seeding window	when the associated a	rea reaches final g
EM 6	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No
Current Condition:	Pending - The erosion con	trol matting will be install	ed within the seeding window	when the associated a	rea reaches final g
EM 7	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No
Current Condition:	Pending - The erosion con	trol matting will be install	ed within the seeding window	when the associated a	rea reaches final g
FT X	Fuel Tank	On Site		Removed	
Current Condition:			ink from site prior to the inspec		•
FT Y	Fuel Tank	On Site		Removed	
Current Condition:			ed from the site prior to the ins		•
IF 1-32	Inlet Filters	Interior Streets curb	5/17/2023	Active	No
Current Condition:		inlets cial Seeding installed inl	I et filters in all interior street cur	l b inlets prior to the ins	pection on 5/17/23
MS 1	Material Storage	On Site	8/14/2020	Active	No
Current Condition:	Good condition - Sewer pi		4/05/0000	A -41	
PB X Current Condition:	Portable Bathroom	On Site	1/25/2023 toilet on site prior to the 6/8/2	Active	No
			removed the portable toilet fro le toilet on site prior to the insp		nspection on 9/19
SB A					
	dewatering prior to the insp on 5/18/22. Kersten Const	pection on 9/8/21. Kerste ruction installed the riser	1/20/2021 and installed the baffle prior to n Construction was in the proc prior to the inspection on 6/1/2 ainted the cleanout mark during	ess of installing the ris 2. Hausman cleaned o	er during the insp out a portion of the
Current Condition:	Fair Condition - 50% filled dewatering prior to the insp on 5/18/22. Kersten Const prior to the inspection on 7 The basin is more than 50 E&A inspector is in the pro	JC excavated the basin pection on 9/8/21. Kerste ruction installed the riser 1/26/22. E&A inspector pa % full and needs to be cl	and installed the baffle prior to n Construction was in the proc prior to the inspection on 6/1/2 ainted the cleanout mark during	o the 1/13/21 inspectio less of installing the ris 22. Hausman cleaned o g the 8/10/22 inspectio	n. JC Excavation er during the insp out a portion of the n.
	Fair Condition - 50% filled dewatering prior to the ins on 5/18/22. Kersten Const prior to the inspection on 7 The basin is more than 50	JC excavated the basin pection on 9/8/21. Kerste ruction installed the riser 1/26/22. E&A inspector pa % full and needs to be cl	and installed the baffle prior to n Construction was in the proc prior to the inspection on 6/1/2 ainted the cleanout mark during eaned out.	o the 1/13/21 inspectio less of installing the ris 22. Hausman cleaned o g the 8/10/22 inspectio	n. JC Excavation er during the insp out a portion of the n.
Current Condition: SB B	Fair Condition - 50% filled dewatering prior to the insp on 5/18/22. Kersten Const prior to the inspection on 7 The basin is more than 50 E&A inspector is in the pro inspection. Sediment Basin	- JC excavated the basir pection on 9/8/21. Kerste ruction installed the riser //26/22. E&A inspector pa % full and needs to be cl pecess of lining up a contra	and installed the baffle prior to n Construction was in the proc prior to the inspection on 6/1/2 ainted the cleanout mark during eaned out. actor to complete maintenance 10/28/2020	o the 1/13/21 inspectio ess of installing the ris 22. Hausman cleaned o g the 8/10/22 inspectio with the SID on 6/1/22 Active	n. JC Excavation er during the insp out a portion of the n. 2. Not done as of t Yes
Current Condition:	Fair Condition - 50% filled dewatering prior to the inspon 5/18/22. Kersten Const prior to the inspection on 7 The basin is more than 50 E&A inspector is in the pro- inspection. Sediment Basin Fair Condition - 10% Filleor mark during the 11/4/20 in will be made at this time a inspection. JC repaired the basin during the inspectior	- JC excavated the basin pection on 9/8/21. Kerste ruction installed the riser r/26/22. E&A inspector pa % full and needs to be cl becess of lining up a contra votes of lining up a contra votes of lining up a contra votes of lining up a contra becess of lining up a contra votes of	and installed the baffle prior to n Construction was in the proc prior to the inspection on 6/1/2 ainted the cleanout mark during eaned out. actor to complete maintenance	o the 1/13/21 inspectio ess of installing the ris 22. Hausman cleaned of g the 8/10/22 inspectio with the SID on 6/1/22 Active 1. The E&A inspector p g the 7/20/21 inspector filled around the riser p 5/21. CDS Enterprise b	n. JC Excavation er during the inspo out a portion of the n. 2. Not done as of t <u>Yes</u> painted the cleand on. No recommen prior to the 8/2/21 egan cleaning out
Current Condition: SB B	Fair Condition - 50% filled dewatering prior to the insponsion of 5/18/22. Kersten Const prior to the inspection on 7 The basin is more than 50 E&A inspector is in the provins pection. Sediment Basin Fair Condition - 10% Filled mark during the 11/4/20 in will be made at this time a inspection. JC repaired the basin during the inspectior inspector repainted the clear the baffle needs to be instructed. The baffle needs to be instructed.	- JC excavated the basir pection on 9/8/21. Kerste ruction installed the riser r/26/22. E&A inspector part % full and needs to be cl becess of lining up a contra void the teasin spection. JC Excavation nd the E&A inspector will e erosion around the riser on 4/6/22. CDS Enterpre- tanout mark on the riser of talled per the SWPPP. es were informed to com 3/26/21, 4/16/21, 5/20/2 ⁻¹	and installed the baffle prior to n Construction was in the proc prior to the inspection on 6/1/2 ainted the cleanout mark during eaned out. actor to complete maintenance <u>10/28/2020</u> prior to the 10/28/20 inspectior is doing work on the riser during continue to monitor. JC back prior to the inspection on 9/15 ise completed cleanout of the during the 8/10/22 inspection. plete by 3/22/21. Not done as 1, 6/10/21, 6/25/21, 7/17/21, 8/	o the 1/13/21 inspectio ess of installing the ris 22. Hausman cleaned of g the 8/10/22 inspectio with the SID on 6/1/22 <u>Active</u> 1. The E&A inspector p ing the 7/20/21 inspectio filled around the riser p /21. CDS Enterprise b basin prior to the inspection.	n. JC Excavation er during the insp out a portion of the n. 2. Not done as of t <u>Yes</u> painted the cleance on. No recommen rior to the 8/2/21 egan cleaning out ction on 6/29/22. JC Excavation/Ge
Current Condition: SB B	Fair Condition - 50% filled dewatering prior to the inspon 5/18/22. Kersten Const prior to the inspection on 7 The basin is more than 50 E&A inspector is in the pro- inspection. Sediment Basin Fair Condition - 10% Filled mark during the 11/4/20 in will be made at this time a inspection. JC repaired the basin during the inspectior inspector repainted the clean The baffle needs to be inst JC Excavation/Gene Grav	- JC excavated the basir pection on 9/8/21. Kerste ruction installed the riser r/26/22. E&A inspector part % full and needs to be cl becess of lining up a contra void the teasin spection. JC Excavation nd the E&A inspector will e erosion around the riser on 4/6/22. CDS Enterpre- tanout mark on the riser of talled per the SWPPP. es were informed to com 3/26/21, 4/16/21, 5/20/2 ⁻¹	and installed the baffle prior to n Construction was in the proc prior to the inspection on 6/1/2 ainted the cleanout mark during eaned out. actor to complete maintenance <u>10/28/2020</u> prior to the 10/28/20 inspectior is doing work on the riser during continue to monitor. JC back prior to the inspection on 9/15 ise completed cleanout of the during the 8/10/22 inspection. plete by 3/22/21. Not done as 1, 6/10/21, 6/25/21, 7/17/21, 8/	o the 1/13/21 inspectio ess of installing the ris 22. Hausman cleaned of g the 8/10/22 inspectio with the SID on 6/1/22 <u>Active</u> 1. The E&A inspector p ing the 7/20/21 inspectio filled around the riser p /21. CDS Enterprise b basin prior to the inspection.	n. JC Excavation er during the insp out a portion of the n. 2. Not done as of t <u>Yes</u> painted the cleance on. No recommen rior to the 8/2/21 egan cleaning out ction on 6/29/22. JC Excavation/Ge
SB B Current Condition: SB C	Fair Condition - 50% filled dewatering prior to the inspon 5/18/22. Kersten Const prior to the inspection on 7 The basin is more than 50 E&A inspector is in the proving section. Sediment Basin Fair Condition - 10% Fillec mark during the 11/4/20 in will be made at this time a inspection. JC repaired the basin during the inspectior inspector repainted the cle The baffle needs to be instant during the inspection inspector repainted the cle The baffle needs to be instant during the inspection inspector repainted the cle The baffle needs to be instant during the inspection inspector repainted the cle The baffle needs to be instant during the inspection inspector repainted the cle The baffle needs to be instant during the inspection inspector repainted the cle The baffle needs to be instant during the inspection inspector repainted the cle The baffle needs to be instant during the inspection inspector repainted the cle The baffle needs to be instant during the inspection inspector repainted the cle The baffle needs to be instant during the inspection inspector repainted the cle The baffle needs to be instant during the inspection during the during the inspection during the inspection during the inspection during the i	- JC excavated the basin pection on 9/8/21. Kerste ruction installed the riser 1/26/22. E&A inspector pe % full and needs to be cl bocess of lining up a contra voide the basin spection. JC Excavation nd the E&A inspector will e erosion around the riser on 4/6/22. CDS Enterpr canout mark on the riser talled per the SWPPP. es were informed to com 3/26/21, 4/16/21, 5/20/2 ^o 2/1/22, 1/4/23 (CIR #182 Z4	and installed the baffle prior to n Construction was in the proc prior to the inspection on 6/1/2 ainted the cleanout mark during eaned out. actor to complete maintenance <u>10/28/2020</u> prior to the 10/28/20 inspectior is doing work on the riser during continue to monitor. JC back prior to the inspection on 9/15 ise completed cleanout of the during the 8/10/22 inspection. plete by 3/22/21. Not done as 1, 6/10/21, 6/25/21, 7/17/21, 8/ 52)	o the 1/13/21 inspectio ress of installing the ris 22. Hausman cleaned of g the 8/10/22 inspectio with the SID on 6/1/22 Active h. The E&A inspector r g the 7/20/21 inspection filled around the riser p s/21. CDS Enterprise b basin prior to the inspection. 19/21, 9/2/21, 10/15/21 Active	n. JC Excavation er during the insp put a portion of the n. 2. Not done as of t yes painted the cleano on. No recommen rior to the 8/2/21 egan cleaning out ction on 6/29/22. JC Excavation/G 1, 11/17/21, 12/2/2 No
SB B Current Condition: Current Condition: SB C Current Condition:	Fair Condition - 50% filled dewatering prior to the inspon 5/18/22. Kersten Const prior to the inspection on 7 The basin is more than 50 E&A inspector is in the province of the inspection. Sediment Basin Fair Condition - 10% Filled mark during the 11/4/20 in will be made at this time at inspection. JC repaired the basin during the inspectior inspector repainted the clear the baffle needs to be instructed on 2/10/22, 3/31/22, 6/7/22, 1 Sediment Basin Good Condition - 30% Filled mark during the inspector inspector repainted the clear the baffle needs to be instructed on 2/10/22, 3/31/22, 6/7/22, 1 Sediment Basin Good Condition - 30% Filled mark during the 11/4/20 in the inspection on 6/22/2	- JC excavated the basin pection on 9/8/21. Kerste ruction installed the riser //26/22. E&A inspector pe % full and needs to be cl bases of lining up a contra votice of the basin pection. JC Excavation nd the E&A inspector will e erosion around the riser is on 4/6/22. CDS Enterpri- anout mark on the riser anout mark on the riser talled per the SWPPP. es were informed to com 3/26/21, 4/16/21, 5/20/2 ⁻ 2/1/22, 1/4/23 (CIR #182 24 ed - JC installed the basin spection. CDS Enterprise the basin into silt fence 12.	and installed the baffle prior to n Construction was in the proc prior to the inspection on 6/1/2 ainted the cleanout mark during eaned out. actor to complete maintenance 10/28/2020 prior to the 10/28/20 inspectior is doing work on the riser during continue to monitor. JC back prior to the inspection on 9/15 ise completed cleanout of the during the 8/10/22 inspection. plete by 3/22/21. Not done as 1, 6/10/21, 6/25/21, 7/17/21, 8/ 52) 10/28/2020 n prior to the 10/28/20 inspection began cleaning out the basind during the inspection on 5/10/2	o the 1/13/21 inspectio ess of installing the ris 22. Hausman cleaned of g the 8/10/22 inspectio with the SID on 6/1/22 Active 1. The E&A inspector r 13/21. CDS Enterprise b basin prior to the inspection. 19/21, 9/2/21, 10/15/27 Active on. The E&A inspection during the inspection	n. JC Excavation er during the insp put a portion of the n. 2. Not done as of the painted the cleance on. No recommen prior to the 8/2/21 egan cleaning out ction on 6/29/22. JC Excavation/Ge 1, 11/17/21, 12/2/2 No r painted the clean on 4/6/22. CDS
SB B Current Condition: SB C Current Condition: SF 1	Fair Condition - 50% filled dewatering prior to the inspon 5/18/22. Kersten Const prior to the inspection on 7 The basin is more than 50 E&A inspector is in the proving prior to the inspection. Sediment Basin Fair Condition - 10% Filled mark during the 11/4/20 in will be made at this time at inspection. JC repaired the basin during the inspector inspector repainted the clean during the inspector repainted the clean during the inspector for the baffle needs to be instructed on 2/10/22, 3/31/22, 6/7/22, 1 Sediment Basin Good Condition - 30% Fillemark during the 11/4/20 in spector mark during the 11/4/20 in the provide the spector repainted the clean during the the spector inspector repainted the clean during the inspector for the spector mark during the spector mark during the 11/2, 3/31/22, 6/7/22, 1 Sediment Basin Good Condition - 30% Fillemark during the 11/4/20 in the inspection on 6/22/2 Silt fence	- JC excavated the basin pection on 9/8/21. Kerste ruction installed the riser //26/22. E&A inspector per % full and needs to be cl pecess of lining up a contra vocument pecess of lining up a contra vocument spection. JC Excavation nd the E&A inspector will e erosion around the riser on 4/6/22. CDS Enterpri- anout mark on the riser of the basin formed to com 3/26/21, 4/16/21, 5/20/2- 2/1/22, 1/4/23 (CIR #182 24 ed - JC installed the basin spection. CDS Enterprise the basin into silt fence vocument vocum	and installed the baffle prior to n Construction was in the proc prior to the inspection on 6/1/2 ainted the cleanout mark during eaned out. actor to complete maintenance 10/28/2020 prior to the 10/28/20 inspectior is doing work on the riser during continue to monitor. JC back r prior to the inspection on 9/15 ise completed cleanout of the sturing the 8/10/22 inspection. plete by 3/22/21. Not done as 1, 6/10/21, 6/25/21, 7/17/21, 8/ 52) 10/28/2020 n prior to the 10/28/20 inspection began cleaning out the basind during the inspection on 5/10/2 10/20/2020	o the 1/13/21 inspectio ess of installing the ris 22. Hausman cleaned of g the 8/10/22 inspectio with the SID on 6/1/22 Active h. The E&A inspector r ing the 7/20/21 inspectio filled around the riser p 5/21. CDS Enterprise b basin prior to the inspection. 19/21, 9/2/21, 10/15/2 Active on. The E&A inspection during the inspection of 22. CDS completed cle Active	n. JC Excavation er during the insp put a portion of the n. 2. Not done as of t <u>Yes</u> painted the cleane on. No recommen rior to the 8/2/21 egan cleaning out ction on 6/29/22. JC Excavation/Ge 1, 11/17/21, 12/2/2 No r painted the clean on 4/6/22. CDS anout of the basin
SB B Current Condition: Current Condition: SB C Current Condition:	Fair Condition - 50% filled dewatering prior to the inspon 5/18/22. Kersten Const prior to the inspection on 7 The basin is more than 50 E&A inspector is in the pro- inspection. Sediment Basin Fair Condition - 10% Fillec mark during the 11/4/20 in will be made at this time at inspection. JC repaired the basin during the inspection inspector repainted the cle The baffle needs to be inst JC Excavation/Gene Grav Graves were reminded on 2/10/22, 3/31/22, 6/7/22, 1 Sediment Basin Good Condition - 30% Fille mark during the 11/4/20 in Enterprise was dewatering to the inspection on 6/22/2 Silt fence Good Condition - JC instal B to install storm. E&A ins 4/19/22. Great Plains reins Graves extended the silt fence prior to the in	- JC excavated the basin pection on 9/8/21. Kerste ruction installed the riser r/26/22. E&A inspector pe % full and needs to be cl bases of lining up a contra votess of lining up a contra votes votess of lining up a contra votes votes of lining up a contra votes of lining up a contra votes votes of lining up a contra votes votes votes of lining up a contra votes votes votes votes of lining up a contra votes votes votes votes votes of lining up a contra votes votes vote	and installed the baffle prior to n Construction was in the proc prior to the inspection on 6/1/2 ainted the cleanout mark during eaned out. actor to complete maintenance 10/28/2020 prior to the 10/28/20 inspectior is doing work on the riser during continue to monitor. JC back prior to the inspection on 9/15 ise completed cleanout of the during the 8/10/22 inspection. plete by 3/22/21. Not done as 1, 6/10/21, 6/25/21, 7/17/21, 8/ 52) 10/28/2020 n prior to the 10/28/20 inspection began cleaning out the basind during the inspection on 5/10/2	o the 1/13/21 inspection is so f installing the ris 22. Hausman cleaned of g the 8/10/22 inspection with the SID on 6/1/22 Active 1. The E&A inspector r 19 the 7/20/21 inspection filled around the riser p 5/21. CDS Enterprise b basin prior to the inspection. 19/21, 9/2/21, 10/15/2 Active of the last inspection of the E&A inspector of the last inspection of 22. CDS completed clean Active cavation took down a berm along the creek r prior to the inspection of the malong the creek r prior to the inspection of the malong the creek r prior to the inspection of an unknown contractor aired the silt fence prior	n. JC Excavation er during the insp put a portion of the n. 2. Not done as of the painted the clean or to the 8/2/21 egan cleaning out ction on 6/29/22. JC Excavation/Go 1, 11/17/21, 12/2/2 DC Excavation/Go 1, 11/17/21, 12/2/2 No r painted the clean on 4/6/22. CDS anout of the basin mout of the basin or 4/6/22. Gene small section nort prior to the inspect on 0 4/19/22. Gene r removed a portion or to the inspection

Current Condition:	Removed - Crops are out SF 1.	of the ground as of the 10/	20/20 inspection, silt fence	e below grading activities v	will be included und	
SF 3	Silt fence	N of Giles Road	10/20/2020	Active	No	
Current Condition:	Good Condition - JC installed the silt fence prior to the 10/20/20 inspection. Hawkins Construction removed a portion of this fence, graded the area, and installed their own silt fence prior to the inspection on 8/17/21. E&A inspector will continue to monitor. Great Plains repaired the entire run of silt fence prior to the inspection on 4/19/22.					
SF 4	Silt fence	NE Corner Across RR	1/28/2021	Active	No	
Current Condition:	Good Condition - Dave Doll installed some of the silt fence prior to the 1/28/2021 inspection. The undermined portion of the fence was backfilled prior to the 3/31/21 inspection. West end of drainage is fully vegetated so silt fence is no longer recommended on 6/8/21. Hawkins Construction removed the northern run of silt fence, graded the area, and installed their o silt fence prior to the inspection on 8/17/21. Gene Graves cleaned out the silt fence and extended the silt fence around the w end of the dirt piles prior to the inspection on 4/26/22.					
SF 5	Silt fence	Interior streets aves installed silt fence alon	6/13/2022	Active	Yes	
	of silt fence prior to the in to monitor. Gene Graves Interior street silt fence sh	noved for utility installation spection on 11/22/22. Reins repaired the silt fence prior nould be reinstalled and rep ed to complete by 5/3/23. N	stallation will not be recom to the inspection on 4/5/2 aired once site is oversee	mended at this time. E&A 3. ded.	inspector will cont	
STR	Streets	Giles Road/180th Street	7/28/2020	Active	Yes	
	street prior to the inspection on 5/3/23. Interior streets should be cleaned.					
	Peter Katt was informed t	so complete by 7/6/23. Not c	ione as of the last inspecti	on. I		
SWPPP Sign	Misc./Other	St.	8/10/2020	Active	No	
Current Condition:	SWPPP sign during the induring the inspection on 2	spector installed the SWPP nspection on 2/22/22. E&A 10/19/22. E&A inspector rein to the entrance on 182nd ar	inspector reinstalled the S nstalled the SWPPP sign	WPPP sign at S 148th Av during the inspection on 1	e and Meridian St.	
WO 1	Concrete Washout	On Site	3/5/2021	Pending	No	
Current Condition:		shout will be installed when				
WS 1	Waste Storage	On Site	3/5/2021	Pending	No	
Current Condition:	0	contained on site and in prop				
ertification Statement:	direction or supervision ir properly gathered and ev persons who manage the the information submitted	I law, that this document and accordance with a system aluated the information sub system or those persons d l is, to the best of my knowle significant penalties for subr t for knowing violations."	designed to assure that q mitted. Based on my inqui irectly responsible for gath edge and belief, true, accu	ualified personnel ry of the person or ering the information, rate, and complete. I		
	Braga M Wayt			1		